

Available from
National Technical Information Service
Springfield, Virginia 22161

Title List of Documents made Publicly Available

June 1 - 30, 1979

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



CONTENTS

Preface	v
Arrangements of Items by Docket Number	ix
Arrangement of Docket 50 Facility Name	xix
Docketed Items	1
Low Level Radwaste Disposal Sites - Docket 27	1
Domestic Licensing of Source Material - Docket 40	1
Domestic Licensing of Production and Utilization Facilities - Docket 50	3
Domestic Licensing of Special Nuclear Material - Docket 70	231
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions - Docket 71	241
Nondocketed Items	251
10CFR - Commission Meeting Records	251
ACRS - Advisory Committee on Reactor Safeguards	253
COMMISSION - NRC Commissioners	254
CONTRACT - NRC Contracts and Modifications	256
FOIA - Freedom of Information Act Requests and Releases	257
GEN TECH IS - Generic Technical Issues	260
I&E - Inspection and Enforcement	260
NUREG - NUREG Reports and Related Correspondence	261
ORG - Correspondence with other organizations	264
PR - Proposed Rule	264
PRM - Petition for Rulemaking	268
PROJ - Projects-Pre-docket Licensing	269
PT21 - Noncompliance Reports and Related Correspondence	270
QA999 - Quality Assurance Inspections	270
REGGD - Regulatory Guides	275
RES - Research and Technical Assistance Reports	277
REVIEW GRP - NRC Research Review Groups	278
RM - Rulemakings	278
SECY - Position Papers Before the Commission	278
TOPREP - Vendor Reports and Related Correspondence	281
WASTE MGT - Nuclear Waste Management	283
XPORLIC - Export and Import Licenses	284
Personal Author Index	293
Corporate Source Index - By Corporate Types	335
Citizen Group/Individual/Media	335
Engineering/Construction/Consultants/Services	355
Educational Institutions	336

CONTENTS (Cont'd.)

Foreign Governments and Agencies	337
Legal/Law Firms/Insurance Companies	337
Local Government and Agencies	339
Medical Institutions and Laboratories	339
Manufacturers/Equipment and Supplies	339
Professional/Industrial Institutions, Societies	341
State Governments and Agencies	341
U.S. Federal Government and Agencies	342
Utilities, Holding Companies, Investor Associations	343
Research Institutions and Laboratories	356
U.S. Nuclear Regulatory Commission Organizational Source Index	359
Report Number Index	385
Appendix A - Definitions of Docket 50 Categories	387
Appendix B - Definitions of Non-docketed Categories	395

PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information includes the information formerly issued through the Department of Energy's Technical Information Center under the title *Power Reactor Docket Information* (PRDI) and, in addition, information received or generated on other uses of radioactive materials. The last issue of PRDI, published in January 1979, was an annual cumulation of the information for 1978. The *Title List* series initiated by this document replaces PRDI, which will no longer be prepared. Plans for providing microfiche of the docketed material will be announced in a future issue of the *Title List* and in other mailings and announcements.

We are making the monthly issues produced in 1979 available free to all who subscribed to PRDI in Calendar Year 1978. We are doing this to encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material. Near the end of 1979, subscriptions will be solicited for Calendar Year 1980 at a fee yet to be established.

DOCKETED ITEMS


Beginning with Vol. 1, No. 4, the listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence

- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:



1. NRC/PDR Document category (see Appendix A).
2. NRC Accession Number
3. Description of information contained in the document
4. Personal author. An asterisk in this position indicates that there is no personal author.
5. Corporate, agency or nonindividual source
6. Date of document described
7. Pages in document
8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS


Beginning with Vol. 1, No. 6, the nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

- 10CFR – Commission Meeting Records
- ACRS – Advisory Committee on Reactor Safeguards
- AGREEMENT – State Agreements and Programs
- COMMISSION – NRC Commissioners
- CONTRACT – NRC Contracts and Modifications
- FOIA – Freedom of Information Act Requests and Releases
- GEN TECH IS – Generic Technical Issues
- I&E – Inspection and Enforcement
- NUREG – NUREG Reports and Related Correspondence
- ORG – Correspondence with other organizations
- PR – Proposed Rule
- PRM – Petition for Rulemaking
- PROJ – Projects-Predocket Licensing
- PT21 – Noncompliance Reports and Related Correspondence

QA999 – Quality Assurance Inspections
 REGGD – Regulatory Guides
 RES – Research and Technical Assistance Reports
 REVIEW GRP – NRC Research Review Groups
 RM – Rulemakings
 SECY – Position Papers Before the Commission
 TOPREP – Vendor Reports and Related Correspondence
 WASTE MGT – Nuclear Waste Management
 XPORTLIC – Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



1. Nondocketed category
2. NRC Accession Number
3. NRC Report Number
4. Title and description of information contained in the document
5. Personal author(s). An asterisk in this position indicates that there is no personal author
6. Corporate, agency or other nonindividual source
7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
8. Date of document described
9. Pages in document
10. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or Available at GPO."

The Nondocketed Items list is arranged sequentially by Accession Number. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NTIS is
National Technical Information Service
Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

2. The address for GPO is:
Superintendent of Documents
Government Printing Office
Washington, D.C. 20402

To place orders for or to obtain price information about NRC publications at GPO, either write to GPO or call the Inquiry Desk at (202) 783-3238. Publications can be charged to VISA or MasterCard credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:
1717 H Street, N.W.
Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
27-039	Sheffield, IL., Nuclear Engineering Co., Inc.	1	50-2	Univ. of Michigan Research Reactor	3
27-047	Baynwell, SC., Chem-Nuclear Systems, Inc.	1	50-3	Indian Point Station, Unit 1	4
27-048	Richland, WA., Nuclear Engineering Co.	1	50-5	Pennsylvania State Univ. Research Reactor	4
40-0299	Union Carbide Corp.	1	50-10	Deesden Nuclear Power Station, Unit 1	4
40-1162	Western Nuclear	1	50-13	Babcock & Wilcox Co. Critical Facility	5
40-1341	Ford, Bacon and Davis, Inc.	1	50-18	Vallecitos Boiling Water Reactor	5
40-2259	Pathfinder Mines Corp.	1	50-20	Massachusetts Institute of Technology Research Reactor	6
40-3392	Allied Chemical Corp.	1	50-22	Westinghouse Test Reactor	6
40-3453	Athen Minerals	1	50-27	Washington State Univ. Research Reactor	6
40-4492	Federal American Partners	1	50-29	Yankee-Rowe Nuclear Power Station	6
40-6659	Petrochemicals Co.	2	50-47	Army Materials Research Reactor	7
40-7455	Desco Marine	2	50-54	Union Carbide Research Reactor	7
40-7860	Plateau Resources, Ltd.	2	50-57	State Univ. of New York Research Reactor	7
40-8027	Kerr-McGee Corp.	2	50-59	Texas A & M Univ. Research Reactor	7
40-8032	Gulf Research and Development Co.	2	50-62	Univ. of Virginia Research Reactor	7
40-8194	Army, Dept. of	2	50-70	General Electric Test Reactor	8
40-8452	Bear Creek Mining Co.	2	50-72	Univ. of Utah Research Reactor	8
40-8502	Wyoming Mining Corp., Irigary Mine	2	50-73	General Electric Nuclear Test Reactor	8
40-8584	Union 76 Exploration Co.	3	50-77	Catholic Univ. of America Research Reactor	8
40-8602	United Nuclear Corp.	3	50-83	Univ. of Florida Training Reactor	9
40-8681	Energy Fuels Nuclear	3	50-84	Univ. of California Research Reactor	
40-8692	Cottier Corp.	3	50-87	Westinghouse Critical Experiment	
40-8693	Ogle Petroleum, Inc.	3	50-89	General Atomic Co.	
40-8698	Plateau Resources, Ltd.	3			
40-8714	Cleveland Cliffs Iron Co.	3			
40-8722	Brush-Wellman, Inc.	3			

Docket	Name	Page	Docket	Name	Page
50-94	Rockwell International Research Reactor	9	50-166	Univ. of Maryland Research Reactor	13
50-97	Cornell Univ. Zero Power Reactor	9	50-170	National Naval Medical Center	13
50-99	Babcock & Wilcox Test Reactor	9	50-171	Peach Bottom Atomic Power Station, Unit 1	13
50-106	Oregon State Univ.	9	50-182	Purdue Univ. Research Reactor	14
50-111	North Carolina State Univ. Research Reactor	9	50-184	National Bureau of Standards Reactor	14
50-112	Univ. of Oklahoma Research Reactor	10	50-186	Univ. of Missouri Research Reactor	14
50-113	Univ. of Arizona Research Reactor	10	50-187	Space Radiation Research Reactor	14
50-116	Iowa State Univ. Research Reactor	10	50-188	Kansas State Univ. Research Reactor	14
50-123	Univ. of Missouri Research Reactor	10	50-192	Univ. of Texas Research Reactor	14
50-124	Virginia Polytech Inst. Training Reactor	10	50-193	Rhode Island & Providence Plantations AEC	14
50-128	Texas A & M Univ. Research Reactor	10	50-199	Manhattan College Research Reactor	14
50-129	Texas A & M Univ. Research Reactor	10	50-201	West Valley Reprocessing Plant	14
50-130	Pathfinder Atomic Plant	11	50-206	San Onofre Nuclear Station, Unit 1	15
50-131	Omaha Veterans Administration Hospital Research Reactor	11	50-208	Columbia Univ. Research Reactor	16
50-133	Humboldt Bay Power Plant, Unit 3	11	50-213	Haddam Neck Plant	16
50-134	Worcester Polytech Inst. Research Reactor	11	50-219	Oyster Creek Nuclear Power Plant	17
50-139	Univ. of Washington Research Reactor	11	50-220	Nine Mile Point Nuclear Station, Unit 1	18
50-141	Stanford Univ. Research Reactor	11	50-223	Univ. of Lowell Research Reactor	19
50-142	UCLA Training Reactor	12	50-224	Univ. of California Research Reactor	19
50-146	Saxton Nuclear Experimental Facility	12	50-225	RPI Critical Experiment	19
50-148	Univ. of Kansas Research Reactor	12	50-228	Aerotest Radiography & Research Reactor	20
50-150	Ohio State Univ. Research Reactor	12	50-237	Dresden Nuclear Power Station, Unit 2	20
50-151	Univ. of Illinois Research Reactor	12	50-241	Mississippi State Univ. Research Reactor	21
50-155	Big Rock Point Nuclear Power Plant	12	50-243	Oregon State Univ. Research Reactor	22
50-156	Univ. of Wisconsin Research Reactor	13	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	22
50-157	Cornell Univ. Research Reactor	13	50-245	Millstone Nuclear Power Station, Unit 1	23
50-160	Georgia Institute of Technology Research Reactor	13	50-247	Indian Point Station, Unit 2	24
50-163	General Atomic Co.	13	50-249	Dresden Nuclear Power Station, Unit 3	25

50-250	Turkey Point Plant, Unit 3	26	50-286	Indian Point Station, Unit 3	63
50-251	Turkey Point Plant, Unit 4	28	50-287	Oconee Nuclear Station, Unit 3	65
50-252	Univ. of New Mexico Research Reactor	30	50-288	Reed College Research Reactor	66
50-254	Quad-Cities Station, Unit 1	30	50-289	Three Mile Island Nuclear Station, Unit 1	66
50-255	Palmodes Nuclear Plant	31	50-290	Proof Test Facility	67
50-259	Browns Ferry Nuclear Power Station, Unit 1	33	50-293	Pilgrim Nuclear Power Station, Unit 1	67
50-260	Browns Ferry Nuclear Power Station, Unit 2	34	50-294	Michigan State Univ. Research Reactor	68
50-261	H.B. Robinson Plant, Unit 2	35	50-295	Zion Nuclear Power Station, Unit 1	69
50-262	Belgium Young Univ. Research Reactor	36	50-296	Browns Ferry Nuclear Power Station, Unit 3	70
50-263	Monticello Nuclear Generating Plant	36	50-297	North Carolina State Univ. PULSTAR Reactor	71
50-264	Dow Chemical Co.	37	50-298	Cooper Nuclear Station	71
50-265	Quad-Cities Station, Unit 2	37	50-301	Point Beach Nuclear Plant, Unit 2	73
50-266	Point Beach Nuclear Plant, Unit 1	38	50-302	Crystal River Nuclear Plant, Unit 3	73
50-267	Fort St. Vrain Nuclear Generating Station	39	50-304	Zion Nuclear Power Station, Unit 2	76
50-269	Oconee Nuclear Station, Unit 1	40	50-305	Kewaunee Nuclear Power Plant	77
50-270	Oconee Nuclear Station, Unit 2	42	50-306	Prairie Island Nuclear Station, Unit 2	78
50-271	Vermont Yankee Nuclear Power Station	44	50-309	Maine Yankee Atomic Power Plant	80
50-272	Salem Nuclear Generating Station, Unit 1	45	50-311	Salem Nuclear Generating Station, Unit 2	83
50-274	U.S. Geological Survey Research Reactor	47	50-312	Rancho Seco Nuclear Generating Station	84
50-275	Diablo Canyon Nuclear Power Plant, Unit 1	47	50-313	Arkansas Nuclear One, Unit 1	86
50-276	Georgia Tech Research Reactor	49	50-315	Donald C. Cook Nuclear Power Plant, Unit 1	88
50-277	Peach Bottom Atomic Power Station, Unit 2	49	50-316	Donald C. Cook Nuclear Power Plant, Unit 2	89
50-278	Peach Bottom Atomic Power Station, Unit 3	51	50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	90
50-280	Surry Power Station, Unit 1	52	50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	91
50-281	Surry Power Station, Unit 2	56	50-320	Three Mile Island Nuclear Station, Unit 2	92
50-282	Prairie Island Nuclear Station, Unit 1	60	50-321		
50-284	Idaho State Univ. Research Reactor	62			
50-285	Fort Calhoun Station, Unit 1	62			

Docket	Name	Page	Docket	Name	Page
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	113	50-363	Forked River Nuclear Station, Unit 1	154
50-324	Brunswick Steam Electric Plant, Unit 2	115	50-364	Joseph M. Farley Nuclear Plant, Unit 2	154
50-325	Brunswick Steam Electric Plant, Unit 1	117	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	155
50-326	Univ. of California at Irvine Research Reactor	120	50-367	Baldy Generating Station	156
50-327	Sequoyah Nuclear Plant, Unit 1	120	50-368	Arkansas Nuclear One, Unit 2	157
50-328	Sequoyah Nuclear Plant, Unit 2	121	50-369	William B. McGuire Nuclear Station, Unit 1	158
50-329	Midland Plant, Unit 1	122	50-370	William B. McGuire Nuclear Station, Unit 2	159
50-330	Midland Plant, Unit 2	124	50-373	LaSalle County Station, Unit 1	160
50-331	Duane Arnold Energy Center	126	50-374	LaSalle County Station, Unit 2	161
50-332	Barnwell Reprocessing Plant	127	50-375	Nuclear Examination Reactor	161
50-333	James A. Fitzpatrick Nuclear Power Plant	127	50-382	Waterford Generating Station, Unit 3	161
50-334	Beaver Valley Power Station, Unit 1	130	50-387	Susquehanna Steam Electric Station, Unit 1	162
50-335	St. Lucie Plant, Unit 1	133	50-388	Susquehanna Steam Electric Station, Unit 2	163
50-336	Millstone Nuclear Power Station, Unit 2	134	50-389	St. Lucie Plant, Unit 2	163
50-338	North Anna Power Station, Unit 1	135	50-390	Watts Bar Nuclear Plant, Unit 1	165
50-339	North Anna Power Station, Unit 2	138	50-391	Watts Bar Nuclear Plant, Unit 2	167
50-341	Enrico Fermi Atomic Power Plant, Unit 2	140	50-394	California State Polytech College Research Reactor	168
50-344	Trojan Nuclear Plant, Unit 1	141	50-395	Virgil C. Summer Nuclear Station, Unit 1	169
50-346	Davy-Besse Nuclear Power Station, Unit 1	143	50-396	Univ. of Virginia Cavalier Reactor	169
50-348	Joseph M. Farley Nuclear Plant, Unit 1	146	50-397	WPPSS Nuclear Project, Unit 2	169
50-352	Limerick Generating Station, Unit 1	147	50-400	Shearon Harris Nuclear Power Plant, Unit 1	170
50-353	Limerick Generating Station, Unit 2	148	50-401	Shearon Harris Nuclear Power Plant, Unit 2	171
50-354	Hope Creek Nuclear Station, Unit 1	148	50-402	Shearon Harris Nuclear Power Plant, Unit 3	172
50-355	Hope Creek Nuclear Station, Unit 2	149	50-403	Shearon Harris Nuclear Power Plant, Unit 4	172
50-356	Univ. of Illinois Lopez Research Reactor	149	50-404	North Anna Power Station, Unit 3	173
50-358	William H. Zimmer Nuclear Station, Unit 1	149	50-405	North Anna Power Station, Unit 4	173
50-360	Battelle Memorial Inst. Critical Facility	151	50-406	Tuskegee Inst. Research Reactor	174
50-361	San Onofre Nuclear Station, Unit 2	151	50-407	Univ. of Utah Research Reactor	174
50-362	San Onofre Nuclear Station, Unit 3	153	50-409	La Crosse Boiling Water Reactor	174

Docket	Name	Page	Docket	Name	Page
50-410	Nine Mile Point Nuclear Station, Unit 2	175	50-463	Fulton Generating Station, Unit 1	195
50-412	Beaver Valley Power Station, Unit 2	176	50-464	Fulton Generating Station, Unit 2	195
50-413	Catawba Nuclear Station, Unit 1	176	50-466	Allens Creek Nuclear Station, Unit 1	195
50-414	Catawba Nuclear Station, Unit 2	176	50-470	CESSAR System 80	197
50-416	Grand Gulf Nuclear Station, Unit 1	177	50-471	Pilgrim Nuclear Power Station, Unit 2	197
50-417	Grand Gulf Nuclear Station, Unit 2	178	STN-50-482	Wolf Creek Generating Station	198
50-423	Millstone Nuclear Power Station, Unit 3	179	STN-50-483	Calloway Plant, Unit 1	199
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	179	STN-50-484	Tyrone Energy Park, Unit 1	200
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	179	STN-50-485	Sterling Power Project, Nuclear, Unit 1	200
50-433	UC-Santa Barbara Research Reactor	180	STN-50-486	Calloway Plant, Unit 2	201
50-434	Surry Power Station, Unit 3	180	STN-50-488	Perkins Nuclear Station, Unit 1	201
50-435	Surry Power Station, Unit 4	180	STN-50-489	Perkins Nuclear Station, Unit 2	201
STN-50-437	Floating Nuclear Plant	181	STN-50-490	Perkins Nuclear Station, Unit 3	202
50-438	Bellefonte Nuclear Plant, Unit 1	181	STN-50-491	Cherokee Nuclear Station, Unit 1	202
50-439	Bellefonte Nuclear Plant, Unit 2	182	STN-50-492	Cherokee Nuclear Station, Unit 2	203
50-440	Perry Nuclear Power Plant, Unit 1	183	STN-50-493	Cherokee Nuclear Station, Unit 3	203
50-441	Perry Nuclear Power Plant, Unit 2	183	STN-50-495	SWESSAR-F1	204
50-443	Seabrook Nuclear Station, Unit 1	184	STN-50-498	South Texas Project, Unit 1	204
50-444	Seabrook Nuclear Station, Unit 2	185	STN-50-499	South Texas Project, Unit 2	206
50-445	Comanche Peak Steam Electric Station, Unit 1	186	50-500	Davis-Besse Nuclear Power Station, Unit 2	209
50-446	Comanche Peak Steam Electric Station, Unit 2	189	50-501	Davis-Besse Nuclear Power Station, Unit 3	210
50-452	Greenwood Energy Center, Unit 2	191	STN-50-502	Haven Nuclear Plant, Unit 1	210
50-453	Greenwood Energy Center, Unit 3	191	STN-50-503	Haven Nuclear Plant, Unit 2	211
50-454	Byron Station, Unit 1	191	50-504	Koshkonong Nuclear Plant, Unit 1	211
50-455	Byron Station, Unit 2	192	50-505	Koshkonong Nuclear Plant, Unit 2	211
50-456	Baldwood Station, Unit 1	192	50-506		
50-457	Baldwood Station, Unit 2	193	50-507		
50-458	River Bend Station, Unit 1	193	STN-50-508		
50-459	River Bend Station, Unit 2	194	STN-50-509		
50-460	WPPSS Nuclear Project, Unit 1	194	50-510		
50-461	Clinton Power Station, Unit 1	195	50-511		
50-462	Clinton Power Station, Unit 2	195	50-513		
			50-514		

Docket	Name	Page	Docket	Name	Page
50-515	Pebble Springs Nuclear Plant, Unit 2	214	50-597	New Haven, Unit 2	228
STN-50-516	Jamestown Nuclear Station, Unit 1	214	50-599	Carroll Facility I	229
STN-50-517	Jamestown Nuclear Station, Unit 2	214	50-600	Carroll Facility II	230
STN-50-518	Hartsville Nuclear Plant, Unit 1	215	70-0008	Hotel Columbus Laboratories	231
STN-50-519	Hartsville Nuclear Plant, Unit 2	215	70-0025	Rockwell International Corp.	231
STN-50-520	Hartsville Nuclear Plant, Unit 3	215	70-0027	Habcock & Wilcox Co.	231
STN-50-521	Hartsville Nuclear Plant, Unit 4	216	70-0033	Texas Instruments, Inc.	231
STN-50-522	Skagit Nuclear Power Project, Unit 1	216	70-0036	Combustion Engineering, Inc.	232
STN-50-523	Skagit Nuclear Power Project, Unit 2	217	70-0041	North Carolina State Univ.	232
STN-50-528	Palo Verde Nuclear Station, Unit 1	217	70-0135	Habcock & Wilcox Co.	232
STN-50-529	Palo Verde Nuclear Station, Unit 2	217	70-0143	Nuclear Fuel Services, Inc.	232
STN-50-530	Palo Verde Nuclear Station, Unit 3	218	70-0152	Purdue University	233
50-537	Clinch River Breeder Reactor	218	70-0364	Parks Township Site, Habcock & Wilcox Co.	233
50-538	Memphis State Univ. Research Reactor	218	70-0371	United Nuclear Corp.	234
STN-50-546	Marble Hill Nuclear Station, Unit 1	218	70-0510	U.S. Coast Guard Academy	234
STN-50-547	Marble Hill Nuclear Station, Unit 2	219	70-0597	Central Michigan Univ.	234
50-549	Greene County Nuclear Power Plant	220	70-0687	Union Carbide Corp.	234
STN-50-553	Philips Bend Nuclear Plant, Unit 1	220	70-0698	Walter Mill Site, General Electric Corp.	234
STN-50-554	Philips Bend Nuclear Plant, Unit 2	221	70-0708	HG&G, Inc.	234
STN-50-556	Black Fox Station, Unit 1	221	70-0734	General Atomic Co.	235
STN-50-557	Black Fox Station, Unit 2	222	70-0754	Vallecitos Nuclear Center, General Electric Co.	235
50-561	B-SAR-205	223	70-0820	United Nuclear Corp.	235
STN-50-566	Yellow Creek Nuclear Plant, Unit 1	223	70-0824	Habcock & Wilcox Co.	236
STN-50-567	Yellow Creek Nuclear Plant, Unit 2	223	70-0895	Arkansas, Univ. of	236
STN-50-568	NEP Nuclear, Unit 1	224	70-0925	Cimarron Facility, Kerr-McGee Corp.	236
STN-50-569	NEP Nuclear, Unit 2	224	70-0959	Nuclear Fuel Services, Inc.	236
STN-50-574	Bagnasco Nuclear Power Project	225	70-0984	Pacific Northwest Laboratory	236
STN-50-580	Erie Nuclear Plant, Unit 1	225	70-1007	General Electric Co.	236
STN-50-581	Erie Nuclear Plant, Unit 2	226	70-1100	Combustion Engineering, Inc.	236
50-586	Rogersville Nuclear Power Station	226	70-1113	General Electric Co.	236
50-589	Asco Fescon I Nuclear Power Plant	226	70-1143	Westinghouse Electric Corp.	237
STN-50-592	Palo Verde Nuclear Station, Unit 4	226	70-1151	Westinghouse Electric Corp.	237
STN-50-593	Palo Verde Nuclear Station, Unit 5	227	70-1193	Cimarron Facility, Kerr-McGee Corp.	237
50-596	New Haven, Unit 1	227			

Docket	Name	Page	Docket	Name	Page
70-1200	Princeton Gamma-Tech	237	71-0028	Borg-Warner Corp.	242
70-1201	UFG Conversion Facility, Babcock & Wilcox Co.	237	71-0034	Babcock & Wilcox Co.	242
70-1220	General Electric Co.	238	71-0036	ITT Grinnell Corp.	242
70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	238	71-0037	Navy, Dept. of	242
70-1308	Morris Operations, General Electric Co.	238	71-0039	Walworth Co.	242
70-1309	Morris Operations, Sources & Standards, General	238	71-0047	Capital International Airways, Inc.	242
70-1319	U.S. Nuclear, Inc.	238	71-0056	Philadelphia Electric Co.	242
70-1351	Army, Dept. of	238	71-0059	General Electric Co.	242
70-1359	IRT Corp.	239	71-0061	Navy, Dept. of	242
70-1426	Transnuclear, Inc.	239	71-0068	Yankee Atomic Electric	242
70-1432	Recycle Fuels Plant, Westinghouse Electric Corp.	239	71-0070	General Motors Corp.	242
70-1489	Goodyear Aerospace Corp.	239	71-0072	Babcock & Wilcox Co.	242
70-1510	Nuclear Assurance Corp.	239	71-0074	Nuclear Welding, Inc.	242
70-1621	Conover and Associates, Inc.	239	71-0077	Midstate Testing Laboratory	242
70-1710	St. Mary's Hospital, Waterbury, CT	239	71-0085	Navy, Dept. of	242
70-1717	Noewalk Hospital	239	71-0089	Navy, Dept. of	242
70-1729	Fuel Receiving and Storage Station, Allied General Nuclear Services	239	71-0090	Combustion Engineering Co., Inc.	242
70-1738	Pacific Gas & Electric Co.	239	71-0096	Pan American World Airways	243
70-2090	Mt. Sinai Hospital, Hartford, CT.	239	71-0099	Foster Wheeler Energy Corp.	243
70-2217	General Atomic Co.	239	71-0103	Twin City Testing & Engineering Laboratory	243
70-2443	Tennessee Valley Authority	239	71-0110	Buckeye Steel Castings	243
70-2623	McGuire Spent Fuel Pool, Duke Power Co.	239	71-0115	Babcock & Wilcox Co.	243
70-2684	Transnuclear, Inc.	241	71-0119	Ingersoll-Rand Co.	243
70-2809	Marubeni America Corp.	241	71-0120	Daniel International Corp.	243
70-2838	Cincinnati Gas & Electric Co.	241	71-0135	Babcock & Wilcox Co.	243
70-2880	Mersey Hospital, Springfield, MA	241	71-0137	Metals Testing Co., Inc.	243
70-2884	Long Island Lighting Co.	241	71-0145	Thayer Inspection Service, Inc.	243
71-0003	Exxon Nuclear, Inc.	241	71-0146	Globe X-Ray Services, Inc.	243
71-0006	United Nuclear Corp.	241	71-0150	Peabody Testing Service	243
71-0010	Gamma Industries	241	71-0154	General Dynamics	243
71-0018	Nuclear Assurance Corp.	242	71-0157	Froehling & Robertson, Inc.	243
			71-0162	Elaseco Services, Inc.	243
			71-0169	Florida Power & Light Co.	243
			71-0174	Southern California Edison Co.	243

Docket	Name	Page	Docket	Name	Page
71-0188	Maynard Steel Casting Co.	243	71-0314	Smith-Emery Co.	245
71-0190	Texas Instruments, Inc.	244	71-0315	Radiography Inspection, Inc.	246
71-0195	Toledo Edison Co.	244	71-0316	Mason & Hanger-Silas Mason Co., Inc.	246
71-0202	Pacific Gas & Electric Co.	244	71-0318	Marathon Oil Co.	246
71-0207	Connecticut Yankee Atomic Power Co.	244	71-0319	General Testing and Inspection Co.	246
71-0208	Northeast Nuclear Energy Co.	244	71-0320	Pittsburgh-Des Moines Steel Co.	246
71-0213	Intermountain Testing Co.	244	71-0321	Exxon Co.	246
71-0220	General Dynamics Corp.	244	71-0322	Control Components International	246
71-0223	B.F. Shaw, Inc.	244	71-0324	Allied Chemical	246
71-0225	Navy, Dept. of	244	71-0325	Consumers Power Co.	246
71-0229	Wood Industries Pipe Fabricating, Inc.	244	71-0326	Industrial Heat Treating & Metallurgical Co., Inc.	246
71-0230	Babcock & Wilcox Co.	244	71-0327	Portland General Electric Co.	246
71-0233	O'Neill Tank Co., Inc.	244	71-4834	Model: HA-10, Babcock & Wilcox Co.	246
71-0240	Power Authority of the State of New York	244	71-4894	Model: NPD-1-528, Kerr-McGee Nuclear Corp.	246
71-0258	Nuclear Engineering Co., Inc.	244	71-4949	Model: UMC-1484, Combustion Engineering Co., Inc.	246
71-0260	Astrotech, Inc.	244	71-4986	Model: RA-2, Exxon Nuclear Co., Inc.	246
71-0275	Duquesne Light	244	71-5364	Model: NPI-67-0442 Neutron Products, Inc.	246
71-0279	Universal Testing, Inc.	245	71-5442	Model: LA-36, Babcock & Wilcox Co.	246
71-0284	Ultrasonic Specialists, Inc.	245	71-5450	Model: RCC-1, -2, -3, Westinghouse Electric Corp.	246
71-0285	Bell Geophysics	245	71-5595	Model: L & M ORNL Uranium Shielded Cask, Energy, Dept. of	246
71-0287	Casson Non-Destructive Testing	245	71-5768	Model: BB-250-2, Combustion Engineering Co., Inc.	247
71-0289	Terradata Geophysical, Inc.	245	71-5790	Model: A1-M3, Energy, Dept. of	247
71-0291	DJ Inspection Services, Inc.	245	71-5791	Model: A1-M6, Energy, Dept. of	247
71-0292	Industrial Gamma Inspection	245	71-5805	Model: Atcor VNUB Cask, Atcor, Inc.	247
71-0294	Applied Engineering Co.	245	71-5908	Model: DOT-GM Type B, Babcock & Wilcox Co.	247
71-0295	Acurex Corp.	245	71-5926	Model: 100, General Electric Co.	247
71-0296	Acurex Construction Co.	245	71-5942	Model: GE-700, General Electric Co.	247
71-0297	Acurex Construction Co.	245			
71-0303	Memphis Testing Services, Inc.	245			
71-0306	Snyder Drilling-Well Servicing Co.	245			
71-0308	Alaska Industrial X-Ray	245			
71-0310	Bacynas-Erie Co.	245			
71-0313	Precision Inspection, Ltd.	245			

Docket	Name	Page	Docket	Name	Page
71-6058	Model: B3-1, Nuclear Engineering Co.	247	71-9019	Model: BU-7, General Electric Co.	248
71-6244	Model: 6244, Chem-Nuclear Systems, Inc.	247	71-9022	Model CE-250-2, Combustion Engineering Co., Inc.	248
71-6272	Model Poly Panther, Nuclear Engineering Co.	247	71-9033	Model: 660 & 660E, Technical Operations, Inc.	248
71-6294	Model: UNC-2501, Combustion Engineering, Inc.	247	71-9044	Model: GE-1600, General Electric Co.	248
71-6375	Model PD-1, Chem-Nuclear Systems, Inc.	247	71-9065	Model: BU-4, General Electric Co.	248
71-6387	Model: 60, Battelle Memorial Institute	247	71-9070	Model: N 55, Energy, Dept. of	248
71-6400	Model: Super Tiger, Westinghouse Electric Corp.	247	71-9079	Model: HN-100 Series 2, Hittman Nuclear & Development Corp.	248
71-6574	Model: HN-200, Hittman Nuclear & Development Corp.	248	71-9080	Model: HN-600, Hittman Nuclear & Development Corp.	248
71-6601	Model: LL-50-100, Kern-Nuclear Systems, Inc.	248	71-9081	Model: CSNI-1600, Chem-Nuclear Systems, Inc.	249
71-6639	Model: MJ-1A, Army, Dept. of	248	71-9086	Model: HN-100, Series 1, Hittman Nuclear & Development Corp.	249
71-6679	Model: 1/2 Super Tiger, Nuclear Engineering Co.	248	71-9108	Model: AL-33-90, Atcor, Inc.	249
71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	248	71-9117	Model: RC-TBRTG-1000, Army, Dept. of, Ft. Belvoir	249
71-6717	Model: 6717 B	248	71-9126	Model: 20, 20A, 50, 50A, Gamma Industries	249
71-9002	Model: U-10-CL, Babcock & Wilcox Co.	248	71-9128	Model: C-8, Gamma Industries	249
71-9009	Model: FL-10-L, General Electric Co.	248	71-9132	Model: T-3, Nuclear Packaging, Inc.	249
71-9010	Model: NLI-1/2, NL Industries, Inc.	248	71-9506	Model: MS27684-2, Energy, Dept. of	249

ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Aerotest Radiography & Research Reactor	50-228	20	Browes Ferry Nuclear Power Station, Unit 2	50-260	34
Allens Creek Nuclear Station, Unit 1	50-466	195	Browes Ferry Nuclear Power Station, Unit 3	50-296	70
Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	179	Brunswick Steam Electric Plant, Unit 1	50-325	117
Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	179	Brunswick Steam Electric Plant, Unit 2	50-324	115
Arkansas Nuclear One, Unit 1	50-313	86	B-SAR-205	50-561	223
Arkansas Nuclear One, Unit 2	50-368	157	Byron Station, Unit 1	50-454	191
Army Materials Research Reactor	50-47	7	Byron Station, Unit 2	50-455	192
Asco Fesca I Nuclear Power Plant	50-589	226	California State Polytech College Research Reactor	50-394	168
Babcock & Wilcox Co. Critical Facility	50-13	5	Calloway Plant, Unit 1	STN-50-483	199
Babcock & Wilcox Test Reactor	50-99	9	Calloway Plant, Unit 2	STN-50-486	201
Bagnac Nuclear Power Project	STN-50-574	225	Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	90
Bully Generating Station	50-367	156	Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	91
Burnwell Reprocessing Plant	50-352	127	Carroll Facility I	50-599	229
Battelle Memorial Inst. Critical Facility	50-360	151	Carroll Facility II	50-600	230
Beaver Valley Power Station, Unit 1	50-334	130	Catawba Nuclear Station, Unit 1	50-413	176
Beaver Valley Power Station, Unit 2	50-412	176	Catawba Nuclear Station, Unit 2	50-414	176
Bellefonte Nuclear Plant, Unit 1	50-438	181	Catholic Univ. of America Research Reactor	50-77	8
Bellefonte Nuclear Plant, Unit 2	50-439	182	CESSAR System 80	50-470	197
Big Rock Point Nuclear Power Plant	50-155	12	Cherokee Nuclear Station, Unit 1	STN-50-491	202
Black Fox Station, Unit 1	STN-50-556	221	Cherokee Nuclear Station, Unit 2	STN-50-492	203
Black Fox Station, Unit 2	STN-50-557	222	Cherokee Nuclear Station, Unit 3	STN-50-493	203
Blue Hills Station, Unit 1	50-510	212	Clinch River Breeder Reactor	50-537	218
Blue Hills Station, Unit 2	50-511	213	Clinton Power Station, Unit 1	50-461	195
Braidwood Station, Unit 1	50-456	192	Clinton Power Station, Unit 2	50-462	195
Braidwood Station, Unit 2	50-457	193	Columbia Univ. Research Reactor	50-208	16
Brigham Young Univ. Research Reactor	50-262	36	Comanche Peak Steam Electric Station, Unit 1	50-445	186
Browns Ferry Nuclear Power Station, Unit 1	50-259	33			

Name	Docket	Page	Name	Docket	Page
Comanche Peak Steam Electric Station, Unit 2	50-446	189	General Atomic Co.	50-163	13
Cooper Nuclear Station	50-298	71	General Electric Test Reactor	50-70	8
Cornell Univ. Research Reactor	50-157	13	General Electric Nuclear Test Reactor	50-73	8
Cornell Univ. Zero Power Reactor	50-97	9	Georgia Institute of Technology Research Reactor	50-160	13
Crystal River Nuclear Plant, Unit 3	50-302	73	Georgia Institute of Technology Research Reactor	50-276	49
Davis-Besse Nuclear Power Station, Unit 1	50-346	143	Grand Gulf Nuclear Station, Unit 1	50-416	177
Davis-Besse Nuclear Power Station, Unit 2	50-500	209	Grand Gulf Nuclear Station, Unit 2	50-417	178
Davis-Besse Nuclear Power Station, Unit 3	50-501	210	Greene County Nuclear Power Plant	50-549	220
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	47	Greenwood Energy Center, Unit 2	50-452	191
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	113	Greenwood Energy Center, Unit 3	50-453	191
Donald C. Cook Nuclear Power Plant, Unit 1	50-315	88	H.B. Robinson Plant, Unit 2	50-261	35
Donald C. Cook Nuclear Power Plant, Unit 2	50-316	89	Haddam Neck Plant	50-213	16
Dow Chemical Co.	50-264	37	Hartsville Nuclear Plant, Unit 1	STN-50-518	215
Dresden Nuclear Power Station, Unit 1	50-10	4	Hartsville Nuclear Plant, Unit 2	STN-50-519	215
Dresden Nuclear Power Station, Unit 2	50-237	20	Hartsville Nuclear Plant, Unit 3	STN-50-520	215
Dresden Nuclear Power Station, Unit 3	50-249	25	Hartsville Nuclear Plant, Unit 4	STN-50-521	216
Duane Arnold Energy Center	50-331	126	Haven Nuclear Plant, Unit 1	STN-50-502	210
Edwin E. Hatch Nuclear Plant, Unit 1	50-321	111	Haven Nuclear Plant, Unit 2	STN-50-503	211
Edwin E. Hatch Nuclear Plant, Unit 2	50-366	155	Hope Creek Nuclear Station, Unit 1	50-354	148
Enrico Fermi Atomic Power Plant, Unit 2	50-341	140	Hope Creek Nuclear Station, Unit 2	50-355	149
Erie Nuclear Plant, Unit 1	STN-50-580	225	Humboldt Bay Power Plant, Unit 3	50-133	11
Erie Nuclear Plant, Unit 2	STN-50-581	226	Idaho State Univ. Research Reactor	50-284	62
Flaming Nuclear Plant	STN-50-437	181	Indian Point Station, Unit 1	50-3	4
Forked River Nuclear Station, Unit 1	50-363	154	Indian Point Station, Unit 2	50-247	24
Fort Calhoun Station, Unit 1	50-285	62	Indian Point Station, Unit 3	50-286	63
Fort St. Vrain Nuclear Generating Station	50-267	39	Iowa State Univ. Research Reactor	50-116	10
Fulton Generating Station, Unit 1	50-463	195	James A. Fitzpatrick Nuclear Power Plant	50-333	127
Fulton Generating Station, Unit 2	50-464	195	Jamesport Nuclear Station, Unit 1	STN-50-516	214
General Atomic Co.	50-89	9	Jamesport Nuclear Station, Unit 2	STN-50-517	214
			Joseph M. Farley Nuclear Plant, Unit 1	50-348	146
			Joseph M. Farley Nuclear Plant, Unit 2	50-364	154
			Kansas State Univ. Research Reactor	50-188	14

Name	Docket	Page	Name	Docket	Page
Kewaunee Nuclear Power Plant	50-305	77	Nine Mile Point Nuclear Station, Unit 2	50-410	175
Koshkonong Nuclear Plant, Unit 1	50-504	211	North Anna Power Station, Unit 1	50-338	135
Koshkonong Nuclear Plant, Unit 2	50-505	211	North Anna Power Station, Unit 2	50-339	138
Koshkonong Nuclear Plant, Unit 3	50-506	211	North Anna Power Station, Unit 3	50-404	173
Koshkonong Nuclear Plant, Unit 4	50-507	211	North Anna Power Station, Unit 4	50-405	173
LaCrosse Boiling Water Reactor	50-409	174	North Carolina State Univ. PULSTAR Reactor	50-297	71
LaSalle County Station, Unit 1	50-373	160	North Carolina State Univ. Research Reactor	50-111	9
LaSalle County Station, Unit 2	50-374	161	Nuclear Examination Reactor	50-375	161
Limerick Generating Station, Unit 1	50-352	147	Oconee Nuclear Station, Unit 1	50-269	40
Limerick Generating Station, Unit 2	50-353	148	Oconee Nuclear Station, Unit 2	50-270	42
Maine Yankee Atomic Power Plant	50-309	80	Oconee Nuclear Station, Unit 3	50-287	65
Manhattan College Research Reactor	50-199	14	Ohio State Univ. Research Reactor	50-150	12
Marble Hill Nuclear Station, Unit 1	STN-50-546	218	Omaha Veterans Administration Hospital Research Reactor	50-131	11
Marble Hill Nuclear Station, Unit 2	STN-50-547	219	Oregon State Univ.	50-106	9
Massachusetts Institute of Technology Research Reactor	50-20	6	Oregon State Univ. Research Reactor	50-243	22
Memphis State Univ. Research Reactor	50-538	218	Oyster Creek Nuclear Power Plant	50-219	17
Michigan State Univ. Research Reactor	50-294	68	Palisades Nuclear Plant	50-255	31
Midland Plant, Unit 1	50-319	122	Palo Verde Nuclear Station, Unit 1	STN-50-528	217
Midland Plant, Unit 2	50-330	124	Palo Verde Nuclear Station, Unit 2	STN-50-529	217
Millstone Nuclear Power Station, Unit 1	50-245	23	Palo Verde Nuclear Station, Unit 3	STN-50-530	218
Millstone Nuclear Power Station, Unit 2	50-336	134	Palo Verde Nuclear Station, Unit 4	STN-50-592	226
Millstone Nuclear Power Station, Unit 3	50-423	179	Palo Verde Nuclear Station, Unit 5	STN-50-593	227
Mississippi State Univ. Research Reactor	50-241	21	Pathfinder Atomic Plant	50-130	11
Monticello Nuclear Generating Plant	50-263	36	Peach Bottom Atomic Power Station, Unit 1	50-171	13
National Bureau of Standards Reactor	50-184	14			
National Naval Medical Center	50-170	13			
NEP Nuclear, Unit 1	STN-50-568	224			
NEP Nuclear, Unit 2	STN-50-569	224			
New Haven, Unit 1	50-596	227			
New Haven, Unit 2	50-597	228			
Nine Mile Point Nuclear Station, Unit 1	50-220	18			

Name	Docket	Page	Name	Docket	Page
Perkins Nuclear Station, Unit 2	STN-50-489	201	Seabrook Nuclear Station, Unit 2	50-444	185
Perkins Nuclear Station, Unit 3	STN-50-490	202	Sequoiah Nuclear Plant, Unit 1	50-327	120
Perry Nuclear Power Plant, Unit 1	50-440	183	Sequoiah Nuclear Plant, Unit 2	50-328	121
Perry Nuclear Power Plant, Unit 2	50-441	183	Shearon Harris Nuclear Power Plant, Unit 1	50-400	170
Phipps Bend Nuclear Plant, Unit 1	50-553	220	Shearon Harris Nuclear Power Plant, Unit 2	50-401	171
Phipps Bend Nuclear Plant, Unit 2	50-554	221	Shearon Harris Nuclear Power Plant, Unit 3	50-402	172
Pilgrim Nuclear Power Station, Unit 1	50-293	67	Shearon Harris Nuclear Power Plant, Unit 4	50-403	172
Pilgrim Nuclear Power Station, Unit 2	50-471	197	Shoshone Nuclear Power Station	50-322	113
Point Beach Nuclear Plant, Unit 1	50-266	38	Skagit Nuclear Power Project, Unit 1	STN-50-522	216
Point Beach Nuclear Plant, Unit 2	50-301	73	Skagit Nuclear Power Project, Unit 2	STN-50-523	217
Prairie Island Nuclear Station, Unit 1	50-282	60	South Texas Project, Unit 1	STN-50-498	204
Prairie Island Nuclear Station, Unit 2	50-306	78	South Texas Project, Unit 2	STN-50-499	206
Proof Test Facility	50-290	67	Space Radiation Research Reactor	50-187	14
Purdue Univ. Research Reactor	50-182	14	Stanford Univ. Research Reactor	50-141	11
Quad-Cities Station, Unit 1	50-254	30	State Univ. of New York Research Reactor	50-57	7
Quad-Cities Station, Unit 2	50-265	37	Sterling Power Project, Nuclear, Unit 1	STN-50-485	200
Rancho Seco Nuclear Generating Station	50-312	84	St. Lucie Plant, Unit 1	50-335	133
Reed College Research Reactor	50-288	66	St. Lucie Plant, Unit 2	50-389	165
Regatta Nuclear Power Station	50-588	226	Surry Power Station, Unit 1	50-280	52
Rhode Island & Providence Plantations ABC	50-193	14	Surry Power Station, Unit 2	50-281	56
River Bend Station, Unit 1	50-458	193	Surry Power Station, Unit 3	50-434	180
River Bend Station, Unit 2	50-459	194	Surry Power Station, Unit 4	50-435	180
Rockwell International Research Reactor	50-94	9	Susquehanna Steam Electric Station, Unit 1	50-387	162
Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	22	Susquehanna Steam Electric Station, Unit 2	50-388	163
RPI Critical Experiment	50-225	19	SWESSAR-P1	STN-50-495	204
Salem Nuclear Generating Station, Unit 1	50-272	45	Texas A & M Univ. Research Reactor	50-59	7
Salem Nuclear Generating Station, Unit 2	50-511	83	Texas A & M Univ. Research Reactor	50-128	10
	50-206	15	Texas A & M Univ. Research Reactor	50-129	10
	50-361	151	Three Mile Island Nuclear Station, Unit 1	50-289	66
	50-362	153			
	50-146	12			
	50-443	184			

Name	Docket	Page	Name	Docket	Page
Three Mile Island Nuclear Station, Unit 2	50-320	93	U.S. Geological Survey Research Reactor	50-274	47
Trojan Nuclear Plant, Unit 1	50-344	141	Vallecitos Boiling Water Reactor	50-18	5
Turkey Point Plant, Unit 3	50-250	26	Vermont Yankee Nuclear Power Station	50-271	44
Turkey Point Plant, Unit 4	50-251	28	Virgil C. Summer Nuclear Station, Unit 1	50-395	169
Tuskegee Inst. Research Reactor	50-406	174	Virginia Polytech Inst. Training Reactor	50-124	10
Tyrone Energy Pack, Unit 1	STN-50-484	200	Washington State Univ. Research Reactor	50-27	6
UCLA Training Reactor	50-142	12	Waterford Generating Station, Unit 3	50-382	161
UC-Santa Barbara Research Reactor	50-433	180	Watts Bar Nuclear Plant, Unit 1	50-390	165
Union Carbide Research Reactor	50-54	7	Watts Bar Nuclear Plant, Unit 2	50-391	167
Univ. of Arizona Research Reactor	50-113	10	Westinghouse Critical Experiment	50-87	9
Univ. of California at Irvine Research Reactor	50-326	120	Westinghouse Test Reactor	50-22	6
Univ. of California Research Reactor	50-84	9	West Valley Reprocessing Plant	50-201	14
Univ. of California Research Reactor	50-224	19	William B. McGuire Nuclear Station, Unit 1	50-369	158
Univ. of Florida Training Reactor	50-83	9	William B. McGuire Nuclear Station, Unit 2	50-370	159
Univ. of Illinois Research Reactor	50-151	12	William H. Zimmer Nuclear Station, Unit 1	50-358	149
Univ. of Illinois Research Reactor	50-356	149	Wolf Creek Generating Station	STN-50-482	198
Univ. of Kansas Research Reactor	50-148	12	Worcester Polytech Inst. Research Reactor	50-134	11
Univ. of Lowell Research Reactor	50-223	19	WPPSS Nuclear Project, Unit 1	50-460	194
Univ. of Maryland Research Reactor	50-166	13	WPPSS Nuclear Project, Unit 2	50-397	169
Univ. of Michigan Research Reactor	50-2	3	WPPSS Nuclear Project, Unit 3	STN-50-508	211
Univ. of Missouri Research Reactor	50-123	10	WPPSS Nuclear Project, Unit 4	50-513	213
Univ. of Missouri Research Reactor	50-186	14	WPPSS Nuclear Project, Unit 5	STN-50-509	212
Univ. of New Mexico Research Reactor	50-252	30	Yankee-Rowe Nuclear Power Station	50-29	6
Univ. of Oklahoma Research Reactor	50-112	10	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	223
Univ. of Texas Research Reactor	50-192	14	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	223
Univ. of Utah Research Reactor	50-72	8	Zion Nuclear Power Station, Unit 1	50-293	69
Univ. of Utah Research Reactor	50-407	174	Zion Nuclear Power Station, Unit 2	50-304	76
Univ. of Virginia Cavalier Reactor	50-396	169			
Univ. of Virginia Research Reactor	50-62	7			
Univ. of Washington Research Reactor	50-139	11			
Univ. of Wisconsin Research Reactor	50-156	13			

DOCKETED ITEMS

LDW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-559 SHEFFIELD, IL - NUCLEAR ENGINEERING CO

7906010288 Forwards attachments to "Licensees' Post-Hearing Brief on Issues Arising During Oral Argument Before Licensing Board re 790327," which were inadvertently omitted from original submission
SHEFFIELD, IL J. Conner, Moore & Carter 79/04/04 13pp

7906070240 Re: reply to Nuclear Engineering Co 790403 post-hearing brief on issues arising during 790327 oral argument before ARLB Certificate of Rev. Encl.
SHEFFIELD, IL J. Conner, Moore & Carter 79/04/11 3pp

7904070184 Reaffirms NRC 790325 order to show cause Licensee must resume responsibility for Sheffield site. Order will remain in effect until issues have been resolved by ARLB.
CHILK, B. J. Office of the Secretary of the Commission 79/04/04 7pp

7904070191 Hearing will be held before ARLB to determine whether Licensee can satisfactorily terminate license & application to renew license. Delegates review authority to ARLB.
CHILK, B. J. Office of the Secretary of the Commission 79/04/04 3pp

DOCKET 27-547 BARNHILL, BC - CHEM-NUCLEAR SYSTEMS

7904070187 Submits answers to NRC questions re license application for receipt of boxes of waste containing up to 250 g U-235
BARNHILL, BC K. Westinghouse Electric Corp 79/03/25 3pp

7906070254 State of BC denial of Chem-Nuclear Sys. Inc request for receipt & burial of low power range monitors
BARNHILL, BC K. Westinghouse Electric Corp 79/04/10 1p

7906020172 Submits add info to support request for amend to permit burial of large boxes of U-235 wastes in response to NRC 790325 ltr
BARNHILL, BC K. Westinghouse Electric Corp 79/04/11 4pp

DOCKET 27-548 RICHLAND, WA - NUCLEAR ENGINEERING CO

7906070252 Forwards final response to Question 4 of Bell 790523 ltr
BARNHILL, BC K. Westinghouse Electric Corp 79/04/11 3pp

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0299 UNION CARBIDE CORP

7906020179 Provides info requested in 790409 Union Carbide item which do not affect license issuance
KENDRICK, P. C. Union Carbide Corp 79/04/09 3pp

7904050140 Summary of 790415 meeting re issues that must be resolved prior to NRC decision on Union Carbide Corp request for authorization to operate heap leach at East Gas Hills site.
LINDHOLM, J. Fuel Process & Fab Branch 79/05/08 2pp

DOCKET 40-1142 NORTHERN NUCLEAR, INC

7906140547 Outlines topics for discussion at 790358 meeting topics include meeting date prior to 790715 to avoid violation of 10-cf. preaction condition & cost details of strip test.
NORTHERN NUCLEAR, INC. (subs. of Phelps Dodge Corp.) 79/05/03 2pp

DOCKET 40-1341 FORD, BACON & BAVER, INC

7906020224 Responds to 790358 ltr expressing concern re possible health hazards from tailings piles at inactive Equipment Unit mill. Piles will be stabilized until they are removed & buried per decontamination plan.
FORD, BACON & BAVER, INC. Division of Fuel Cycle & Material Safety 79/04/04 1p

DOCKET 40-0299 PATHFINDER MINES CORP

7906020232 Responds to NRC 790409 ltr requesting addl info re Tailings Pond A & Tailings Reservoir 2. Forwards "Peak Flow Estimates for Spillway of Tailings Reservoir 2".
PATHFINDER MINES CORP 79/04/23 3pp

7906020246 "Peak Flow Estimates for Spillway of Tailings Reservoir 2".
PATHFINDER MINES CORP 79/04/23 3pp

7906020256 Responds to NRC 790410 request for addl info to complete radiological assessment of proposed tailings area and forwards detailed info.
PATHFINDER MINES CORP 79/05/04 7pp

DOCKET 40-0392 ALTEC CHEMICAL CORP

7906100037 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assembly".
ALTEC CHEMICAL CORP Region 3, Chicago, Office of the Director 79/05/11 1p

7906020343 Requests addl ref mat to enhance incident response ctr info included with emergency plan & implementing procedures & form sets of site maps showing various monitoring stations.
ALTEC CHEMICAL CORP Region 3, Chicago, Office of the Director 79/05/17 1p

7906020313 Forwards DC Circular 79-08, "Attempted Extension - Low Enriched U".
ALTEC CHEMICAL CORP Region 3, Chicago, Office of the Director 79/05/18 1p

7906020377 Requests addl info re plant emissions.
ALTEC CHEMICAL CORP Fuel Process & Fab Branch 79/05/22 1p

DOCKET 40-0403 ATLAS MINERALS

7904050209 Responds to ltr re FCC of heap U mill operation. Station is located from U area during milling. Diffusion of radon from U tailings particles is insignificant.
ATLAS MINERALS Uranium Recovery Licensing Branch 79/04/23 3pp

7906020387 Submits addl detailed comments re RBG license must comply with 10-cf. buffer zone required by 10-cf. Div of Health.
ATLAS MINERALS, Utah, State of 79/05/03 2pp

DOCKET 40-0492 FEDERAL AMERICAN PARTNERS

7904020332 "Stock Extensions Survey, Federal American Partners, Gas Hills Mill," Jul 1978.
FEDERAL AMERICAN PARTNERS (Mining) 78/07/31 44pp

7906020352 "Stock Extensions Survey, Federal American Partners, Gas Hills Mill," Aug 1978.
FEDERAL AMERICAN PARTNERS (Mining) 78/08/31 44pp

7906020380 "Stock Extensions Survey, Federal American Partners, Gas Hills Mill," Sept 1978.
FEDERAL AMERICAN PARTNERS (Mining) 78/09/30 46pp

DOCKETED ITEMS

7906200314 "Stack Emissions Survey-Federal American Partners-Das Hill
Hill," Dec 1979
* Federal American Partners (Mining) 79/01/31 50pp

7906200312 "Stack Emissions Survey-Federal American Partners-Das Hill
Hill," Nov 1979
* Federal American Partners (Mining) 79/11/30 40pp

7906200343 "Stack Emissions Survey-Federal American Partners-Das Hill
Hill," Dec 1979
* Federal American Partners (Mining) 79/12/31 53pp

7906200323 "Stack Emissions Survey-Federal American Partners-Das Hill
Hill," Jan 1979
* Federal American Partners (Mining) 79/01/31 30pp

7906200322 "Stack Emissions Survey-Federal American Partners-Das Hill
Hill," Feb 1979
* Federal American Partners (Mining) 79/02/28 50pp

7906140123 Forwards requests for info identified during geotechnical
engineering review of subsurface re tailing of Tailings Dam
2 Requests requested by 790605
SCHWAB, R A Radiological Licensing Branch (Pne 790605)
79/02/28 7pp

7906200600 "Stack Emissions Survey-Federal American Partners-Das Hill
Hill," Mar 1979
* Federal American Partners (Mining) 79/03/31 50pp

7906100579 Forwards request for add info re hydrological inputs
of anticipated mill expansion in order to complete
radiological assessment for license renewal application
SCARANO, R A Uranium Recovery Licensing Branch 79/04/13 7pp

7906180671 Forwards corrected Revision 2 to area-capacity curve for
tailings pond
MOSHER, R A For Consulting Engineers & Geologists, P H Fox &
Associates 79/04/28 5pp

7906200123 Requests for 790412 request for info re license renewal
application submit operating & revision data for Copper
after complete data on Das Hill area is not yet available
Unauthorized drawing re air quality permit added
JACKSON, F B Federal American Partners 79/03/02 4pp

7906200079 Submit summary of TLD gamma survey conducted during
previous briefs and to be used in preparation of
previously submitted info regarding scheduled 790618
meeting
JACKSON, F B Federal American Partners (Mining) 79/05/04 4pp

7906200779 Requests add info re hydrologic engineering
LITTMAN, J J Uranium Recovery Licensing Branch 79/05/17 5pp

DOCKET 40-8457 PETROBRON CO. & BETTY OIL

7906200432 Requests formalization of review for cont mat of tailings dam
releases Petrobrone Co has withdrawn and request
withdrawn, R A Uranium Recovery Licensing Branch 79/05/08 1p

TCSD MARINE

commissioning
final status of
= Sublease
is
501 79/05/00 5pp

7906200519 Discusses decommissioning plan All contaminated equipment to
be transferred to proposed processing facility
Decommissioning radiation surveys sent
SCHWAB, R A Radiological Resources Ltd 79/05/00 27pp

DOCKET 40-8627 MERR-MCONE CORP.

7906200388 Safety evaluation of Amend 6 to application is authorize
test distribution of treated spent attraction raffinate as
fertilizer used in license renewal and feed chain testing
of raffinate fertilized pasture. Recommended license
9029, A L Fuel Process & Fab, Branch 79/06/12 3pp

7906200581 Forwards Hatt Pollution Discharge Elimination Act permits
for 150-acre & 270-acre areas say conditions outlined in
amend
SHELLEY, W J Hatt-McCone Corp 79/05/09 20pp

7906200707 Advices of 40,560 refund for fee accompanying 790632
application for Amend 4 to License 808-1040
KILLER, W O License Fee Management Branch 79/05/23 1p

DOCKET 40-8632 GULF PETROBRON & BETTY OIL CO.

7906140023 Requests amend to License 808-1058 to permit simulated
in-situ U leaching tests in lab
LITTMAN, J A Gulf Research & Development Co 79/04/05 1p

DOCKET 40-8694 ARMY, DEPT OF

7906140477 Ack receipt of 790611 for informing ARE of steps taken to
correct violations noted in IE Insp Repts 30-5268/79-01,
40-8194/79-01 & 70-1251/79-01
RELLINTON, R O Region 1, Philadelphia, Office of the Director
79/03/08 1p

--7906140509 Response to ARE 790630 for re violations noted in IE Insp
Repts 30-5268/79-01, 40-8194/79-01 & 70-1251/79-01
Corrective actions Installation of fence excluding radiation
area & storage of licensed mail in locked cabinet
BOHANNAN, L Army, Dept of Electronics Research & Development
Command 79/04/11 1p

--7906180506 Forwards advice of violation from IE Insp Repts
30-5268/79-01, 40-8194/79-01 & 70-1251/79-01 as 790604
RELLINTON, R O Region 1, Philadelphia, Office of the Director
79/03/20 2pp

--7906140916 Notice of violation from Insp re 790608 Metropolitan noted
radiation safety facility exceeded limits
& licensed mail stored in unlocked cabinet
RELLINTON, R O Region 1, Philadelphia, Office of the Director
79/03/26 2pp

DOCKET 40-8458 BEAR CREEK URANIUM CO.

7906200102 Forwards responses to questions re amend of license to
expand mill production capacity Overland drilling and
ANDRUS, R D Rocky Mountain Energy Co 79/05/10 50pp

7906100779 Forwards request for add info to complete Review of
tailings dam plan Request in add of draft given to Facility
personnel during ARE 790630 site visit
LITTMAN, J J Uranium Recovery Licensing Branch 79/04/09 2pp

7906100786 Issues Amend 6 to License 808-1310-authorizing add of
emission monitoring program by revising Condition 10
Meteorological monitoring station may be moved to any onsite
location
SCARANO, R A Uranium Recovery Licensing Branch 79/04/20 1p

7906100922 Forwards request for add info identified during hydrologic
engineering review of Sept 1978 Submittal Requests response
by 790611
LITTMAN, J J Uranium Recovery Licensing Branch 79/04/26 4pp

7906180586 Forwards responses to Questions 1-6 submitted by ARE 790426
for Amend 6 revision to proposed tailings pit &
reclamation plan Site permitted draft only
ANDRUS, R D Rocky Mountain Energy Co 79/05/17 20pp

7906200747 Forwards revision to Question 5 of license 790609 package
of questions & answers Overland drilling and
ANDRUS, R D Rocky Mountain Energy Co 79/05/17 14pp

DOCKET 40-8502 IRIDIARY NINE, HYDROMINING CORP.

7906200604 Amend 1 to License 808-104-authorizing use of
calcium-magnesium carbonate/bicarbonate lithium/sulph
to specified conditions
SCARANO, R A Assistant Director for Waste Management (Pne 790605)
79/04/10 2pp

7906200523 Submits report concerning results of bioassay analyses of
samples taken from monitor units 79061 & 79067 which
have been upper control limit values for radon parameters
measured. Corrective action: overpumping
SCHWAB, R A Wyoming Mineral Corp 79/04/27 4pp

DOCKETED ITEMS

3

DOCKET 40-1804 UNION 75 MINERALS EXPLORATION CO

790420008 Responds to 790216 request for additional preliminary monitoring data. Licensee will continue obtaining additional info until made noted, unless otherwise advised.
NANBMLL J A Union Minerals 79/03/27 1p

790420044 Forwards report on testing of foundation matls & specs for License 804-1230. Requests review of report.
ECARAND R A Uranium Recovery Licensing Branch 79/03/08 4pp

790420121 Forwards report of 790327 work on Sweetwater U project in WY to inspect initial cost operations on Cell C of mine. Requests retention basin work is satisfactory.
DOPHILIPP K A Ariz. Dept. of 79/03/10 3pp

DOCKET 40-8402 UNITED NUCLEAR CORP

790420044 Comments on NUREG-0552 license should be required to fence & flag or cover acid tailings pond to prevent use of pond by wildlife, especially waterfowl. All surface runoff from overburden piles should be contained by dikes.
DISTRUB H E Hearing, State of 79/03/10 1p

DOCKET 40-8481 ENERGY FUELS NUCLEAR, INC

7904180474 Forwards FES for facility (NUREG-0556).
ECARAND R A Uranium Recovery Licensing Branch 79/03/10 1p

7904180477 Forwards FES for facility (NUREG-0556). Distribution list encl.
ECARAND R A Uranium Recovery Licensing Branch 79/03/10 13pp

790420038 Requests determination as to whether area south of Bladensburg is eligible for designation as archeological district in Md. Register.
ECARAND R A Redesignation Licensing Branch (Pm 790501) 79/03/28 3pp

790420035 Forwards archeological survey site forms for sites 6782 & 6750 in San Juan County, UT.
CABERNH C Utah, State of 79/04/23 3pp

7904180494 Forwards preliminary case report for lands to be impacted by White Mesa U mill. Also forwards proposal for conditions of mine of agreement w/ mitigation of adverse effects at mill site.
ECARAND R A Uranium Recovery Licensing Branch 79/04/30 10pp

7904180414 Believe memo of agreement will satisfy necessary mitigation under requirements of 106 review procedures.
KEENE J P Utah, State of 79/03/03 1p

7904200138 FES for facility
* Office of Nuclear Material Safety & Safeguards NUREG-0556
79/03/31, 320pp Available at NTIS, 11.00

DOCKET 40-8492 COTTER CORP

790420037 Forwards revisions to pilot plant license application. Envir & radiological monitoring section encl.
SMITH T Cotter Corp. 79/03/20 7pp

DOCKET 40-8493 OGLE PETROLEUM, INC

7904200104 Requests administrative amend to License 804-1230 reducing extent of aviation air particulate sampling & deleting ground water sampling program in supportive info document.
GATCHELLE G J Ogle Petroleum, Inc 79/03/22 4pp

DOCKET 40-8494 PLATEAU RESOURCES, LTD

7904200138 Forwards "Contract Drawings for Stage 1 Tailings Segregation & Dam/Booster Canyon U Project" & "Stage 1 Tailings Segregation & Dam Final Design Rep. Boaster Canyon U Project" encl 790331.
BENJELLS R B Plateau Resources, Ltd 79/03/24 3pp

7904200137 "Stage 1 Tailings Segregation & Dam Final Design Rep. Boaster Canyon U Project"
* Plateau Resources, Ltd. 79/03/31 100pp

7904270201 Protests proposed U project because of strain on public svc from increased population, threat to endangered species, adequacy of monitoring procedures, tailings containment & safeguards.
HOLKHAHN B Concerned Citizens Against Proliferation of Uranium Waste 79/03/30 18pp

7904200108 Requests timely authorization for cost of proposed facility following and of 42-day public comment period an DSS.
HATCH D O Senate 79/04/23 1p

7904200126 Forwards applicant response to DSI comments on DRE.
BENJELLS R B Plateau Resources, Ltd 79/03/04 36pp

7904190121 Forwards responses to draft comments from EPA on Boaster Canyon DSS. DSS changed changes encl.
DOWELL R B Plateau Resources, Ltd 79/03/07 42pp

DOCKET 40-8714 CLEVELAND CLIFFS IRON CO

7904200237 Forwards "Radiation Handbook for Collins Draw Solution Extraction Recovery Plant".
SHERWILLER O V Cleveland-Cliffs Iron Co 79/04/26 1p

7904200238 "Radiation Handbook for Collins Draw Solution Extraction Recovery Plant".
* Cleveland-Cliffs Iron Co 79/04/23 13pp

7904200239 Requests invoice for license fee for source mat license to be issued to Cleveland Cliffs Iron Co.
HILLER W U License Fee Management Branch 79/03/10 1p

DOCKET 40-8722 BRUSH-MILLMAN, INC

7904200237 Forwards request for add info in order to complete review of Dec 1978 application for source mat license & supporting environ rep. Requests response by 790331.
ECARAND R A Uranium Recovery Licensing Branch 79/04/16 3pp

7904200221 Forwards responses to questions re source mat license application. Unrevised drawings encl.
BENJELLS R Brush-Millman, Inc 79/04/30 7pp

7904200220 Forwards 790504 ltr from A Richters of UT Air Conservation Committee notifying that state will publish notice of intent to issue approval order for renew of U recovery circuit at Delta, UT. Also forwards notice from 790509 Salt Lake Tribune.
BENJELLS R Brush-Millman, Inc 79/03/11 3pp

7904200281 Forwards Delta of UT notice of intent to approve count of U recovery plant in Delta, UT.
FOMERIS H R Brush-Millman, Inc 79/03/14 2pp

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 30-2 UNIV OF ILLINOIS RESEARCH REACTOR

Q Inspection reports: IE Bulletins & correspondence

790416083 Forwards IE Insp Rpt 30-052/79-01 on 790404-04. No noncompliance noted.
HEND J A Region D, Chicago, Safeguards Branch 79/03/02 3pp

790416083 IE Insp Rpt 30-052/79-01 on 790404-04. No noncompliance noted. Major areas inspected licensee's approved security program. Details withheld (ref 10092 7903).
CHRISTOPHER S R SCHWENK J C HEND J A Region D, Chicago, Safeguards Branch 79/04/30 1p

790416083 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Enriched U".
HEFFLER J O Region D, Chicago, Office of the Director 79/03/11 1p

790416084 Forwards IE Circular 79-06, "Attempted Extortion - Lew Enriched U".
HEFFLER J O Region D, Chicago, Office of the Director 79/03/10 1p

DOCKETED ITEMS

DOCKET 30-3 INDIAN POINT STATION, UNIT 1

Security, medical, emergency & fire protection plans

790502008 Ack receipt of 790307 revised emergency plan Requests Class 3
MILLER, H O License Fee Management Branch 79/05/08 1p

790502007 Requests to 790508 for forwarding \$4,400 filing fee for revised emergency plan Payment made under protest Unit reserves right to challenge validity of fees
CAHILL, W J Consolidated Edison Co of New York 79/06/11 1p

Insurance & indemnity information

790502006 Notice of receipt of complaint served on Westinghouse re alleged bodily injury to unit employee J O'Mallinwald was assigned unproductive worker to 790912 Bush under way
MILLER, H O American Nuclear Insurers 79/06/14 1p

790502003 Forwards Amend 25 to Indemnity Agreement B-15
CAHILL, W J Consolidated Edison Co of New York 79/06/18 3pp

Operating license stage documents & correspondence

790502004 Requests facility participate in vital area analysis & schedule site visit during week of 790504
MILLER, H O Operating Reactors Branch 1 (Pre 790623) 79/04/12 2pp

790502005 Forwards info re PWR feedwater license response to NRC
790503 request WTR overrated drawings
CAHILL, W J Consolidated Edison Co of New York 79/04/18 40pp

Inspection Reports: IE Bulletin & correspondence

790502006 Forwards IE Bulletin 79-056, "Nuclear Incident at TPC-0001" No written response received
GRUBB, R H Region 1, Philadelphia, Office of the Director 79/04/22 1p

790502008 Requests to IE Bulletin 79-07 Discusses actions taken re verification approach for UGR-A&B/FRC-D program
CAHILL, W J Consolidated Edison Co of New York 79/04/24 7pp

790502009 Requests to IE Bulletin 79-054 Facility is presently in defueling condition awaiting decision re EGCS installation
Further investigation initiated; response expected 790508
CAHILL, W J Consolidated Edison Co of New York 79/04/24 1p

790502010 Requests to IE Bulletin 79-04, "Incorrect Weights for Dosing Check Valves" by Union Engineering Corp - Effect of weight discrepancy negligible on every case investigated
Further investigation initiated; response expected 790508
CAHILL, W J Consolidated Edison Co of New York 79/05/01 2pp

790502012 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required
GRUBB, R H Region 1, Philadelphia, Office of the Director 79/05/07 2pp

790502013 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics" - Licensee action required.
GRUBB, R H Region 1, Philadelphia, Office of the Director 79/05/11 1p

790502009 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
GRUBB, R H Region 1, Philadelphia, Office of the Director 79/05/11 1p

790502007 Requests to IE Bulletin 79-020 Unit 1 was shut down at 790501 & is in deferred condition. Pending decision re installation of EGCS Reactor design is substantially different from current B&B design
CAHILL, W J Consolidated Edison Co of New York 79/05/14 1p

790502004 Requests to IE Bulletin 79-09 Unit 1 currently shut down, awaiting decision re EGCS No GE type AN-2 circuit breakers installed in safety-related area in Unit 2
CAHILL, W J Consolidated Edison Co of New York 79/05/17 1p

790502009 Forwards IE Circular 79-08, "Attempted Extension - Low Enriched U"
GRUBB, R H Region 1, Philadelphia, Office of the Director 79/05/18 1p

Periodic operating reports & related correspondence

790502009 Annual Environ Operating Rept 1978 Part A & Part B radiological rept, vols 1 & 2
Consolidated Edison Co of New York 78/12/31 223pp

790502006 Forwards "Seismic Monitoring Network." Quarterly Rept 13 for Dec 1978 - Feb 1979
CAHILL, W J Consolidated Edison Co of New York 79/04/04 1p

790502006 "Seismic Monitoring Network." Quarterly Rept 12 for Dec 1977 - Feb 1978 Prepared by Westinghouse Consultants, Inc
Consolidated Edison Co of New York 78/05/30 35pp

790502008 Submits Reg monitor data specified in Section 401 certification
MILLER, H O Consolidated Edison Co of New York 79/04/18 11pp

790502004 Forwards monthly operating rept for May 1979
CAHILL, W J Consolidated Edison Co of New York 79/06/14 1p

790502006 Monthly operating rept for May 1979
MILLER, H O Consolidated Edison Co of New York 79/06/08 7pp

790502007 Forwards May 1979 daily tabulation of fish collection & species breakdown
CAHILL, W J Consolidated Edison Co of New York 79/06/14 3pp

DOCKET 30-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

Insurance & indemnity information

790502007 Forwards executed Amend 14 to Indemnity Agreement B-10
LUNDIN/HAHN, R O Pennsylvania State Univ 79/05/11 2pp

Inspection reports: IE Bulletin & correspondence

790502006 Forwards IE Info Notice 79-13, "Attempted Damage to New Fuel Assemblies"
GRUBB, R H Region 1, Philadelphia, Office of the Director 79/05/11 1p

790502007 Forwards IE Circular 79-08, "Attempted Extension - Low Enriched U"
GRUBB, R H Region 1, Philadelphia, Office of the Director 79/05/18 1p

Reportable occurrences, LCRs & related correspondence

790502007 SD on 790408 percent power meter stuck at 98% full scale & could not have occurred if power had exceeded 98% Caused by dust inside meter movement Movement cleaned & checked for proper operation
LUNDIN/HAHN, R O Pennsylvania State Univ 79/06/25 1p

790502006 SD 790408 during routine daily reactor instrumentation checks, discovered percent power meter stuck at 98% full scale Caused by dust inside meter movement Movement cleaned.
LUNDIN/HAHN, R O Pennsylvania State Univ 79/06/25 1p

790502014 Notice for 790408 during routine daily checkout of reactor instrumentation, percent power meter stuck at 98% full scale Caused by dust in meter movement Movement cleaned, checked for proper operation & returned to use
LUNDIN/HAHN, R O Pennsylvania State Univ 79/06/25 1p

790502009 Advice of incident reported to Region 1 on 790408 percent power meter stuck at 98% full scale & could have failed to perform safety function caused by dust inside meter Meter cleaned, checked & returned to use
LUNDIN/HAHN, R O Pennsylvania State Univ 79/06/25 1p

DOCKET 30-10 SREBEN NUCLEAR POWER STATION, UNIT 1

Security, medical, emergency & fire protection plans

790502008 Forwards request for add info re 790417 fire protection
EIDHAM, D L Operating Reactors Branch 2 (Pre 790623) 79/05/01 4pp

790502006 Response to NRC 790301 request for add info re fire protection
JAMMICK, R F Commonwealth Edison Co 79/05/30 38pp

DOCKETED ITEMS

5

J Insurance & Indemnity Information

7906200187 Forwards executed Amends 21.15.9 & 1 to Indemnity Agreements 8-10-82, 8-29 & 8-24, respectively
HALL, E. B. Commonwealth Edison Co. 79/05/29 App

7906200250 Forwards Endorsements 118 & 119 to NELA Policy NP-43
GUTER, J. Commonwealth Edison Co. 79/05/30 App

7906100260 Forwards Endorsements 150 & 151 to NELA Policy NP-22 & Endorsements 48 & 50 to NELA Policy NP-54
GUTER, J. Commonwealth Edison Co. 79/05/27 App

P. Operating license stage documents & correspondence

7906200158 Forwards draft evaluation of systematic evaluation program Topics 20-17 Requests review & response within 30 days
TODMAN, D. L. Operating Reactors Branch 2 (Pw 790525) 79/05/09 App

7906200046 Forwards request for info re chemical decontamination of facility Three questions relate to actions taken by DOE
VOLLMER, R. H. Assistant Director for Systems Engineering 79/05/10 App

7906200047 Requests info re proposed decontamination of facility in red to petition to produce EIS
HARRILL, S. Illinois State of 79/04/18 App

7906200039 Requests two controlled copies of site emergency plans & implementing procedures, site maps showing location & grid station number of units & offsite monitor monitoring stations & site maps for off site decontamination
KOPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/17 App

7906200016 Forwards OR reph HSCC-04139, "Long-Term Evaluation of Effects of Exposure to SOH H8-H Solvent on Stress Corrosion Cracking of Simulated Type 304 Stainless Steel in Simulated BWR Environments" dtd Nov 1978
JANECER, R. F. Commonwealth Edison Co. 79/05/23 App

7906200015 "Long-Term Evaluation of Effects of Exposure to SOH H8-H Solvent on Stress Corrosion Cracking of Simulated Type 304 Stainless Steel in Simulated BWR Environments"
JANECER, R. F. Commonwealth Edison Co. 79/05/23 App

7906200026 Sites add systematic evaluation program topics that should be deleted from review re failure of Underdmin app 5
JANECER, R. F. Commonwealth Edison Co. 79/04/22 App

A Inspection reports, IE Bulletins & correspondence

7906200147 Forwards IE Insp Repts 30-010/79-10, 30-037/79-10 & 30-038/79-08 on 790514-30 H8-H solvent release noted
HARRILL, S. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/04/28 App

7906200153 IE Insp Repts 30-010/79-10, 30-037/79-10 & 30-044/79-08 on 790514-30 H8-H solvent release noted, BWR area inspected
JANECER, R. F. MCH, M. K. REVEN, L. A. Region 3, Chicago, Office of the Director 79/04/25 App

7906200492 Responds to IE Bulletin 79-08 Forwards info re review of NRI incident, existing line isolation not important to EECB
HARRILL, S. Commonwealth Edison Co. 79/04/27, 28pp

7906100083 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Penetration Support Problem." No action required
KOPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/07 App

7906101010 Forwards IE Bulletin 79-10, "Recertification Training Program Statistics." Written response required
KOPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/11 App

7906100078 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies."
KOPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/11 App

7906200195 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
KOPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/18 App

7906200282 Forwards IE Bulletin 79-11, "Penalty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required
KOPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/22 App

7906200090 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Beaver Creek Reactor"
KOPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/24 App

R Periodic operating reports & related correspondence

7906100026 Forward monthly operating rept for May 1979
STODOLSKA, R. B. Commonwealth Edison Co. 79/05/11 App

7906100338 Monthly operating rept for May 1979
STODOLSKA, R. B. Commonwealth Edison Co. 79/05/04 App

S Reportable occurrences, LERs & related correspondence

7906100229 Forwards LER 79-001/03L-0
STODOLSKA, R. B. Commonwealth Edison Co. 79/05/13 App

7906100248 LER 79-001/03L-0 on 790510 while digging ditch for new pipe, control personnel observed water running into trench from proximity of reheats 79070-2e storage line caused by return line to IA storage tank from aluminum line
HARRILL, S. Commonwealth Edison Co. 79/05/19 App

U Congressional/Executive Correspondence

7906200093 Responds to 790404 request to review R Bray lit on proposed chemical decontamination of facility. Action will be taken as requested for action per 10CFR 200 & action will be taken on petition within reasonable time period
STODOLSKA, L. V. Office of the Executive Director for Operations 79/05/08 App

7906200050 Act receipt of 790514 petition requesting EIS on proposed decontamination experiments designed to flush radioactive corrosion products from portions of piping. Petition is being treated per 10CFR 200 FR notice and
STODOLSKA, R. Office of Nuclear Reactor Regulation 79/04/09 App

7906200008 Request for preparation of EIS re proposed decontamination experiments designed to flush radioactive corrosion products from portions of piping
STODOLSKA, R. Division of Project Management 79/04/09 App

7906200004 Forwards petition requesting that prior to use of New Chemical solvent to flush and piping
STODOLSKA, R. House of Rep 79/04/04 App

7906200002 Petition for preparation of EIS prior to use of New Chemical solvent to flush out radioactive products from piping
STODOLSKA, R. Affiliates Unknown 79/03/19 App

SECRET 50-10 BARCOCK & WILSON CO CRITICAL FACILITY

7906200434 Forwards IE Info Notice 79-10, "Attempted Damage to New Fuel Assemblies"
KOPPLER, J. G. Region 2, Atlanta, Office of the Director 79/05/10 App

SECRET 50-10 VALLEYVIEW BOLLARD WATER REACTOR

7906200419 Forwards Endorsements 106, 110 & 111 to NELA Policy NP-1
CHARRA, C. Marsh & McLennan, M & M Nuclear Consultants, Inc. Div 79/05/13 App

DOCKETED ITEMS

DOCKET 50-20 MASSACHUSETTS INST OF TECH AND REACTOR

J. Insurance & indemnity information

7904010011 Forwards executed Amend 15 to Indemnity Agreement 6-29
VALENTINE, R. Massachusetts Institute of Technology 79/04/04 1p

0 Inspection reports, IE Bulletins & correspondence

7904060027 Forwards IE Insp Mast 50-020/79 on 790326-1A re
noncompliance noted
BRUNDEL, C. J. Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 79/04/16 2pp

7904060041 IE Insp Mast 50-020/79-01 on 790318-1A re noncompliance
noted Reactor Area inspected logs & records, LDR assignments,
operator licenses, design mode, licensee notices & action of
previous insp findings
CRISTO, J. F. Region 1, Philadelphia, Office of the Director
RCASB, E. C. Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 79/04/13 7pp

7904060059 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
CRISTO, J. F. Region 1, Philadelphia, Office of the Director
79/03/11 1p

7904080024 Forwards IE Circular 79-08, "Attempted Extortion - Low
Enriched U"
CRISTO, J. F. Region 1, Philadelphia, Office of the Director
79/03/18 1p

DOCKET 50-22 WASHINGTON STATE REACTOR

0 Inspection reports, IE Bulletins & correspondence

7904060051 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
CRISTO, J. F. Region 1, Philadelphia, Office of the Director
79/03/11 1p

7904080053 Forwards IE Circular 79-08, "Attempted Extortion - Low
Enriched U"
CRISTO, J. F. Region 1, Philadelphia, Office of the Director
79/03/18 1p

DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR

B NRC Draft/Final Environmental Statements, update & correspondence

7904070049 Forwards corrected version of page 10 to EIO Original
contained typographical errors in appendix
MILTON, W. E. Washington State Univ 79/05/29 2pp

USNRC Final Safety Analysis Report (FSAR) & Amend

7904070183 Forwards revised SAR as part of renewal application for
license R-75 Submit 790315 ltr forwarding application for
renewal of license & info re application for renewal
MILTON, W. E. Washington State Univ 79/04/25 1pp

7904070184 Revised SAR
MILTON, W. E. Washington State Univ 79/05/21 20pp

Operating license stage documents & correspondence

9043040402 Forwards two pages re application for renewal of License
R-76, erroneously omitted from 790510 submission
MILBORN, H. E. Washington State Univ 79/04/04 1p

7904030413 Submits two pages erroneously omitted from application for
renewal of License R-76, per NRC 790504 ltr.
MILBORN, H. E., MILBORN, H. E. Washington State Univ
79/05/18 2pp

0 Inspection reports, IE Bulletins & correspondence

9043040403 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
MILBORN, H. E. Region 1, San Francisco, Office of the Director
79/05/10 1p

7904080029 Forwards IE Circular 79-08, "Attempted Extortion - Low
Enriched U"
MILBORN, H. E. Region 1, San Francisco, Office of the Director
79/05/18 1p

DOCKET 50-29 YANKEE-ROSE NUCLEAR POWER STATION

F Security, medical, emergency & fire protection plans

7904090027 Submits add info re fire protection sys re alternatives to
increase saving capacity of fire water supply Diesel-driven
fire pump of sufficient capacity will be provided re meet
NRC concerns
RODNEY, D. E. Yankee Atomic Electric Co 79/04/10 1p

I Financial information

7904050047 Forwards Annual cash flow info for 1979 re meet
retroactive premium guarantee requirements under
Price-Anderson Act
RODNEY, D. E. Yankee Atomic Electric Co 79/03/19 4pp

F Operating license stage documents & correspondence

7904070039 Response to 790412 request re SN program suggests revision
number of YDAP-1-A not be designated
MILBORN, H. E. Yankee Atomic Electric Co 79/04/24 1p

7904050076 Resubmits w/790318 ltr supporting position that Class III
license amend fee is inappropriate for 790405 Proposed
Change 163 re Low Temp overpressure protection sys Requests
payment of Class III Fee within 15 days
MILBORN, H. E. License Fee Management Branch 79/05/17 2pp

7904070070 Requests add info re 790328 contingency plan
MILBORN, D. L. Operating Reactors Branch 2 (Pw 790405) 79/05/17

7904050076 Forwards Exxon Nuclear Co 790418 ltr which provides add
info re Nov 1978 Core X211 Fuel examinations
GRICE, E. H. Yankee Atomic Electric Co 79/05/24 20pp

7904090024 Forwards draft evaluation of systematic evaluation program
Topic II-2 re onsite meteorological measurements program
MILBORN, D. L. Operating Reactors Branch 2 (Pw 790429) 79/05/29

7904060271 Submits add info for development of input for review of
systematic evaluation program Topic III-5 re high energy
line break vessel containment
GRICE, E. H. Yankee Atomic Electric Co 79/05/01 4pp

7904030259 Notifies that licensed operator recertification program may
not be completed by 79/03/31 due to cancellation of license
data for present reactor operator class
MILBORN, H. E. Yankee Atomic Electric Co 79/05/01 1p

7904030268 Notifies that until 6/14/79 packages are being penalized for
obvious NRC review deficiencies Forwards license amend fee
under protest
MILBORN, H. E. Yankee Atomic Electric Co 79/04/03 2pp

7904030276 Submits \$4,000 license fee under protest & w/o waiver of
right to claim. License data papers are being penalized for
NRC review deficiencies
MILBORN, H. E. Yankee Atomic Electric Co 79/04/03 2pp

7904030278 Submits add info re steam generator feedwater lines in
response to 790523 request. Four overvoltage breakers in
Control Plant only. Add info will be forwarded
GRICE, E. H. Yankee Atomic Electric Co 79/05/19 1p

7904020408 Response to NRC 790529 ltr requesting verification of basis
on which evaluation of systematic evaluation program Topic
II-2 is based. Data recorded on Eddy's dist rather than
negative RPP
GRICE, E. H. Yankee Atomic Electric Co 79/06/25 1p

0 Inspection reports, IE Bulletins & correspondence

7904030404 Forwards IE Bulletin 79-028, "Nuclear Incident at
Boysen Station"
CRISTO, J. F. Region 1, Philadelphia, Office of the Director
79/04/20 1p

DOCKETED ITEMS

7904140143 Act receipt of 790328 1hr informing NRC of steps taken to correct violations noted in IE Insp Rpt 50-009779-02
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/28 1p

--7904140144 Response to NRC 790328 1hr re violations noted in IE Insp Rpt 50-009779-02 Corrective actions procedure for testing valves has been included in "Surveillance Procedure Follow Up"
HODDY, D. E. Yankee Atomic Electric Co 79/03/28 3pp

--7904140151 Forwards IE Insp Rpt 50-009779-02 on 790213-1a & notice of violation
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/08 2pp

--7904140159 Notice of violation from Insp on 790213-1A
Region 1, Philadelphia, Office of the Director 79/03/07 1p

--7904140164 IE Insp Rpt 50-026779-02 on 790213-1a Noncompliance noted failure to exercise valves within required time period
HODDY, D. E. Region 1, Philadelphia, Office of the Director CAPWOLD, L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, 79/03/07 9pp

7904150104 Responds to IE Bulletin 79-04, "Incorrect Weights for Relief Check Valves Affected by Velen Engineering Corp." Velen valves are used in EDS Use of corrected weights is compensated for by design code inherent conservatism.
HODDY, D. E. Yankee Atomic Electric Co 79/03/02 2pp

7904150141 Forwards summary of 790304 mtg meeting info presented during meeting resulted in withdrawal of item 8 of 790328 notice of violation
HODDY, D. E. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/03/02 2pp

--7904150171 Summary of 790304 mtg meeting until 11 in King of Prussia, PA re computerized personnel desimetry record app & withdrawal of apparent item of noncompliance
HODDY, D. E. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/03/02 2pp

7904150204 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Installation Support Function" No action required
HODDY, D. E. Region 1, Philadelphia, Office of the Director 79/05/07 3pp

7904150153 Forwards IE Bulletin 79-10, "Regualification Training Program Matriculation" Written response required
HODDY, D. E. Region 1, Philadelphia, Office of the Director 79/05/11 1p

7904200144 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
HODDY, D. E. Region 1, Philadelphia, Office of the Director 79/05/11 1p

7904290137 Supplements 790423 response to IE Bulletin 79-06A Mid to Tech Specs & design changes are unnecessary
HODDY, D. E. Yankee Atomic Electric Co 79/05/16 3pp

7904300112 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
HODDY, D. E. Region 1, Philadelphia, Office of the Director 79/05/18 1p

8. Periodic operating reports & related correspondence

7904190312 Forwards monthly operating rpt for May 1979
HODDY, D. E. Yankee Atomic Electric Co 79/06/12 1p

--7904190314 Monthly operating rpt for May 1979
HODDY, D. E. Yankee Atomic Electric Co 79/06/12 3pp

DOCKET 50-47 ARMY MATERIALS RESEARCH REACTOR

8. Inspection reports, IE Bulletins & correspondence

7904200429 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
HODDY, D. E. Region 1, Philadelphia, Office of the Director 79/05/11 1p

7904200012 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
HODDY, D. E. Region 1, Philadelphia, Office of the Director 79/05/18 1p

DOCKET 50-84 UNION CARBIDE RESEARCH REACTOR

P. Operating license stage documents & correspondence

7904200276 Act receipt of Amend 14 to License R-61 Request clarification of environ considerations in Section C of safety evaluation
KOSKINEN, C. J. Union Carbide Corp 79/06/03 2pp

8. Inspection reports, IE Bulletins & correspondence

7904260046 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
HODDY, D. E. Region 1, Philadelphia, Office of the Director 79/05/11 1p

7904260046 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
HODDY, D. E. Region 1, Philadelphia, Office of the Director 79/05/18 1p

DOCKET 50-37 STATE UNIV OF NEW YORK RESEARCH REACTOR

P. Operating license stage documents & correspondence

7904260019 Requests renewal of License R-77 until Jan 1, 2000
FODDY, D. E. New York State Univ of Buffalo 79/06/14 3pp

8. Inspection reports, IE Bulletins & correspondence

7904260046 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
HODDY, D. E. Region 1, Philadelphia, Office of the Director 79/05/11 1p

DOCKET 50-89 TEXAS A&M UNIV RESEARCH REACTOR

P. Operating license stage documents & correspondence

7904260146 Forwards Amend 12 to License R-23, safety evaluation & notice of issuance & availability
HODDY, D. E. Operating Reactors Branch 4 (Pw 790425) 79/04/25 3pp

--7904260146 Amend 12 to License R-23 extending duration of license
HODDY, D. E. Operating Reactors Branch 4 (Pw 790425) 79/04/25 3pp

--7904260181 Safety evaluation supporting Amend 12 to License R-23
HODDY, D. E. Office of Nuclear Reactor Regulation 79/04/25 10pp

--7904260182 Notice of issuance & availability & negative declaratory Amend 12 to License R-23
HODDY, D. E. Operating Reactors Branch 4 (Pw 790425) 79/04/25 3pp

8. Inspection reports, IE Bulletins & correspondence

7904260183 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
HODDY, D. E. Region 1, Dallas, Office of the Director 79/05/11 1p

DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR

8. Inspection reports, IE Bulletins & correspondence

7904260424 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
HODDY, D. E. Region 1, Atlanta, Office of the Director 79/05/10 1p

DOCKETED ITEMS

B Reportable occurrences, LERs & related correspondence

7904000200 Forwarded RD on 790413 Fuel element AM-22 was releasing low levels of fission products in reactor coolant element was removed from core. No measurable release of fission products to environment seen
SRI/VER, J. L. Virginia Univ. of 79/04/18 3pg

DOCKET 80-70 GENERAL ELECTRIC TEST REACTOR

F Security, medical, emergency & fire protection plans

7904000200 Forwarded revised physical security plan. Plan withheld (red IDCFR 7903) summarizes changes to plan
GENERAL ELECTRIC CO. Nuclear Energy Products Div 79/04/27 2pg

J Insurance & indemnity information

7904000200 Forwarded Endorsements 19-20 & 21 to MAELU Policy #7-95
COMMER, C Marsh & McLennan, M & M Nuclear Consultants, Inc Div 79/04/30 2pg

B Inspection reports, IE Bulletins & correspondence

7904190200 Forwarded IE Info Notice 79-12, "Attempted Damage to New Fuel Assembly"
SRI/VER, J. L. Region 3, San Francisco, Office of the Director 79/05/10 1p

7904000200 Forwarded GE Circular 79-06, "Attempted Extortion - Low Enriched U"
SRI/VER, J. L. Region 3, San Francisco, Office of the Director 79/05/10 1p

DOCKET 80-72 UNIV OF UTAH RESEARCH REACTOR

P Operating license stage documents & correspondence

7904000200 Forwarded Amend 10 to License R-25, safety evaluation/revision impact approval & notice of issuance/negative declaration
SRI/VER, J. L. Operating Reactors Branch 4 (Pre 790203) 79/05/09 3pg

7904000200 Amend 10 to License R-25, extending DL duration until 799912
SRI/VER, J. L. Assistant Director for Engineers & Projects (Pre 790425) 79/05/02 2pg

7904000200 Safety evaluation & CIA supporting Amend 10 to License R-25 & Office of Nuclear Reactor Regulation 79/05/02 13pg

7904000200 Notice of issuance & availability of Amend 10 to License R-25 & negative declaration
SRI/VER, J. L. Operating Reactors Branch 4 (Pre 790203) 79/05/02 2pg

B Inspection reports, IE Bulletins & correspondence

7904000200 Forwarded IE Info Notice 79-12, "Attempted Damage to New Fuel Assembly"
SRI/VER, J. L. Region 4, Dallas, Office of the Director 79/05/11 1p

DOCKET 80-70 GENERAL ELECTRIC NUCLEAR TEST REACTOR

E Safety Evaluation Report (SER), maps & correspondence

7904000200 Forwarded responses to questions re SER Phase II geological investigations.
GENERAL ELECTRIC CO. Nuclear Energy Products Div 79/05/02 3pg

F Security, medical, emergency & fire protection plans

7904190200 Forwarded revised physical security plan. Plan withheld (red IDCFR 7903) summarizes changes to plan
GENERAL ELECTRIC CO. Nuclear Energy Products Div 79/04/07 2pg

P Operating license stage documents & correspondence

7904000200 Forwarded NEDD-12724, "Regulification Program for GE Nuclear Test Reactor"
GENERAL ELECTRIC CO. General Electric Co 79/04/02 1p

7904000200 "Regulification Program for GE Nuclear Test Reactor"
GENERAL ELECTRIC CO. NEDD-12724 79/03/31 1pg

7904000200 Forwarded renewal application info for License R-25
GENERAL ELECTRIC CO. Nuclear Energy Products Div 79/05/10 2pg

7904000200 "Transportation of Radioactive Materials Nuclear Ctr"
GENERAL ELECTRIC CO. Nuclear Energy Products Div NEDD-12610 79/05/31 2pg

7904000200 "Fire Protection Plan, Vallecitos Nuclear Ctr"
GENERAL ELECTRIC CO. Nuclear Energy Products Div NEDD-12610 79/04/27 2pg

7904000200 "Criticality Emergency Plan, Vallecitos Nuclear Ctr"
GENERAL ELECTRIC CO. Nuclear Energy Products Div NEDD-12610 79/03/31 1pg

7904000200 "Radiation Emergency Plan, Vallecitos Nuclear Ctr"
GENERAL ELECTRIC CO. Nuclear Energy Products Div NEDD-12610 79/03/31 1pg

7904000200 "Emergency Control Plan, General, Vallecitos Nuclear Ctr"
GENERAL ELECTRIC CO. Nuclear Energy Products Div NEDD-12610 79/03/31 1pg

7904000200 Submit schedule for completion of financial & environ info & SAR Task Book re new model for natural circulation mode info submitted for NEDD12 renewal application for License R-25
GENERAL ELECTRIC CO. Nuclear Energy Products Div 79/04/19 1p

7904000200 Provides financial info to demonstrate that Vallecitos Nuclear Ctr has resources necessary to operate & shut down decommissioning facility
GENERAL ELECTRIC CO. Nuclear Energy Products Div 79/04/19 2pg

B Inspection reports, IE Bulletins & correspondence

7904190200 Forwarded IE Info Notice 79-12, "Attempted Damage to New Fuel Assembly"
SRI/VER, J. L. Region 3, San Francisco, Office of the Director 79/05/10 1p

7904000200 Forwarded IE Insp Rept 50-073/79-01 on 790327-09, No noncompliance noted
SRI/VER, J. L. Region 3, San Francisco, Reactor Operations Nuclear Support Branch 79/05/17 2pg

7904000200 IE Insp Rept 50-073/79-01 on 790327-09 No noncompliance noted. Major areas inspected: facility operations, unit 3 surveillance for previous year's activities, operator qualification program, procedures, logs & records
SRI/VER, J. L. REGION 3, SAN FRANCISCO, REACTOR OPERATIONS NUCLEAR SUPPORT BRANCH 79/05/16 7pg

7904000200 Forwarded IE Circular 79-06, "Attempted Extortion - Low Enriched U"
SRI/VER, J. L. Region 3, San Francisco, Office of the Director 79/05/10 1p

DOCKET 80-77 FATECHIC UNIV OF AMERICA RESEARCH REACTOR

B Inspection reports, IE Bulletins & correspondence

7904000200 Forwarded IE Info Notice 79-12, "Attempted Damage to New Fuel Assembly"
SRI/VER, J. L. Region 1, Philadelphia, Office of the Director 79/05/11 1p

7904000200 Forwarded IE Circular 79-06, "Attempted Extortion - Low Enriched U"
SRI/VER, J. L. Region 1, Philadelphia, Office of the Director 79/05/10 1p

DOCKETED ITEMS

9

DOCKET 50-03 UNIV. OF FLORIDA TRAINING REACTOR

J. Insurance & indemnity information

7904070142 Forwards Amend 3 to Indemnity Agreement E-10
MCARTHUR, R. J. Florida, Univ. of, Gainesville 79/03/23 1p

P. Operating license status documents & correspondence

7904190286 Forwards operator requalification & recertification program
DIANE, R. J. GORDON, R. J. Florida, Univ. of, Gainesville 79/04/08 1p

7904190287 Operator requalification & recertification program for
790701190300
Florida, Univ. of, Gainesville 79/04/08 3pp

G. Inspection reports, IE Bulletins & correspondence

7904200422 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies -"
GRIFFIN, J. P. Region 3, Atlanta, Office of the Director 79/05/10 1p

DOCKET 50-04 UNIV. OF CALIFORNIA RESEARCH REACTOR

J. Insurance & indemnity information

7904260395 Forwards executed Amend 8 to Indemnity Agreement E-10-Amend
8 to Indemnity Agreement E-10-Amend 8 to Indemnity Agreement
E-10 & Amend 13 to Indemnity Agreement E-10
GRIFFIN, J. P. California, Univ. of, Berkeley 79/04/21 3pp

DOCKET 50-07 MONTICLOMERE CRITICAL EXPERIMENT

G. Inspection reports, IE Bulletins & correspondence

7904190286 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies -"
GRIFFIN, J. P. Region 3, Chicago, Office of the Director 79/05/11 1p

7904200422 Forwards IE Circular 79-06, "Attempted Extortion - Low
Enriched U -"
GRIFFIN, J. P. Region 3, Chicago, Office of the Director 79/05/10 1p

7904260395 Forwards IE Insp Rept 50-007/79-02 on 790309-10 No
non-compliance noted
GRIFFIN, J. P. Region 3, Chicago, Safeguards Branch 79/05/24 3pp

7904260395 IE Insp Rept 50-007/79-02 on 790309-10 No non-compliance
noted Major areas inspected security organization, access
control, alarm sys, surveillance & sabotage protection details
unshielded area (IDPFS 7901)
CHRISTOFFER, G. SCHWARTZ, J. P. GRIFFIN, J. P. Region 3, Chicago,
Safeguards Branch 79/05/24 1p

DOCKET 50-09 GENERAL ATOMIC CO.

J. Insurance & indemnity information

7904190415 Forwards Endorsement 29 & 30 to HACL Policy HP-59
GORDON, R. J. MARKS & McLENNAN, R. H. Nuclear Consultants, Inc. Div
79/04/14 3pp

G. Inspection reports, IE Bulletins & correspondence

7904190286 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies -"
GRIFFIN, J. P. Region 3, San Francisco, Office of the Director 79/05/10 1p

7904200422 Forwards IE Circular 79-06, "Attempted Extortion - Low
Enriched U -"
GRIFFIN, J. P. Region 3, San Francisco, Office of the Director 79/05/10 1p

DOCKET 50-04 ROCKWELL INTERNATIONAL RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

7904190415 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies -" No written response necessary
GRIFFIN, J. P. Region 3, San Francisco, Office of the Director 79/05/10 1p

7904200422 Forwards IE Circular 79-06, "Attempted Extortion - Low
Enriched U -"
GRIFFIN, J. P. Region 3, San Francisco, Office of the Director 79/05/10 1p

DOCKET 50-07 CORNELL UNIV. ZERO POWER REACTOR

G. Inspection reports, IE Bulletins & correspondence

7904200422 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies -"
GRIFFIN, J. P. Region 1, Philadelphia, Office of the Director 79/05/10 1p

7904200422 Forwards IE Circular 79-06, "Attempted Extortion - Low
Enriched U -"
GRIFFIN, J. P. Region 1, Philadelphia, Office of the Director 79/05/10 1p

DOCKET 50-09 SAFEGUARD & WILCOX TEST REACTOR

G. Inspection reports, IE Bulletins & correspondence

7904200422 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies -"
GRIFFIN, J. P. Region 3, Atlanta, Office of the Director 79/05/10 1p

DOCKET 50-106 OHIO STATE UNIV.

G. Inspection reports, IE Bulletins & correspondence

7904190415 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies -"
GRIFFIN, J. P. Region 3, San Francisco, Office of the Director 79/05/10 1p

7904200422 Forwards IE Circular 79-06, "Attempted Extortion - Low
Enriched U -"
GRIFFIN, J. P. Region 3, San Francisco, Office of the Director 79/05/10 1p

DOCKET 50-111 NORTH CAROLINA STATE UNIV. RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

DOCKETED ITEMS

7904210081 Ask receipt of 790418 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpts 79-111/79-01
79-097/79-01 & 79-004/79-01
RECEIVED M 8 Region 2, Atlanta, Safeguards Branch 79/05/03 1p

79040810394 Requests to NRC 790507 ltr re violations noted in IE Insp Rpts 79-111/79-01, 79-097/79-01 & 79-004/79-01 corrective actions from 742 answered properly & copy for per-lm Oct 1979 - Mar 1979 forwarded to Region II
SULLIVAN, T B North Carolina State Univ 79/04/19 3p

7904203389 Forwards IE Insp Rpts 79-111/79-01, 79-097/79-01 & 79-004/79-01 on 790320-28 Notice of violations withheld (ref 10CFR2 7901)
SULLIVAN, T B Region 2, Atlanta, Safeguards Branch 79/03/27 2pp

79042610395 IE Insp Rpts 79-111/79-01, 79-097/79-01 & 79-004/79-01 on 790320-28 Noncompliance noted. Failure to measure & report accountability values re production & consumption of SRM
Details withheld (ref 10CFR2 7901)
SULLIVAN, T B Region 2, Atlanta, Office of the Director 79/03/28 1p

7904260414 Forwards IE Info Notice 79-12: "Attempted Damage to New Fuel Assemblies"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/10 1p

SECRET 79-112 UNIV OF OKLAHOMA RESEARCH REACTOR
I Insurance & indemnity information

7904103043 Executed Amend 9 to Indemnity Agreement E-24
SULLIVAN, J Antitrust & Indemnity Group 79/04/11 1p

I Inspection reports, IE Bulletins & correspondence

7904260254 Forwards IE Info Notice 79-12: "Attempted Damage to New Fuel Assemblies"
O'REILLY, J P Region 4, Dallas, Office of the Director 79/05/11 1p

SECRET 79-113 UNIV OF ARIZONA RESEARCH REACTOR
I Insurance & indemnity information

7904180556 Forwards IE Info Notice 79-12: "Attempted Damage to New Fuel Assemblies"
O'REILLY, J P Region 3, San Francisco, Office of the Director 79/05/10 1p

7904090232 Forwards IE Circular 79-08: "Attempted Extortion - Law Enforced U"
O'REILLY, J P Region 3, San Francisco, Office of the Director 79/05/10 1p

SECRET 79-114 IOWA STATE UNIV RESEARCH REACTOR
I Insurance & indemnity information

7904100346 Requests confirmation of understanding of effect of indemnity coverage under Agreement E-3 of Price-Anderson Act re decommissioning activities of Major Engineering-Inc
Hagen & Hartman 79/04/07 3p

7904080106 Forwards IE Circular 79-08: "Attempted Extortion - Law Enforced U"
O'REILLY, J P Region 3, Chicago, Office of the Director 79/05/10 1p

7904080662 Ask receipt of IE Circular 79-08 Will review security procedures for all law enforcement units presently on hand
FLANKE, T J Research, Univ. of 79/05/20 1p

SECRET 79-126 VIRGINIA PD-FRECH INET TRAINING REACTOR
I Inspection reports, IE Bulletins & correspondence

7904020124 ask receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpts 79-126/79-02
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 2pp

7904050176 Requests to NRC 790320 ltr re violations noted in IE Insp Rpts 79-126/79-02 Corrective actions all procedures being rewritten & monthly reactor operator meetings held
WAGNER, T F Virginia Polytechnic Institute & State Univ 79/04/18 3pp

7904030183 Forwards IE Insp Rpts 79-126/79-02 on 790320-0002 & notice of violations
LUMIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 3pp

7904030167 Notice of violation from Insp on 790320-0002
Region 2, Atlanta, Office of the Director 79/03/23 3pp

7904030216 IE Insp Rpts 79-126/79-02 on 790320-0002 Noncompliance noted. Failure to document licensed reactor operator re qualification records & failure to provide & maintain procedures in conducting operations
ALLAN, C A, WAGNER, T F Region 2, Atlanta, Office of the Director, REACTOR, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 11pp

7904203021 Forwards IE Info Notice 79-12: "Attempted Damage to New Fuel Assemblies"
O'REILLY, J P Region 3, Atlanta, Office of the Director 79/05/10 1p

SECRET 79-120 TEXAS A&M UNIV RESEARCH REACTOR
I Operating license stage documents & correspondence

7904100270 Submit add'l info re Tech Spec change request to allow radiography of expensive metal in response to NRC 790407
SULLIVAN, J B Texas A & M Univ 79/04/13 2pp

I Inspection reports, IE Bulletins & correspondence

7904260213 Forwards IE Info Notice 79-12: "Attempted Damage to New Fuel Assemblies"
O'REILLY, J P Region 4, Dallas, Office of the Director 79/05/11 1p

SECRET 79-124 WEST VIRGINIA UNIV RESEARCH REACTOR
I Insurance & indemnity information

7904090271 Executed Amend 9 to Indemnity Agreement E-27
SULLIVAN, J Antitrust & Indemnity Group 79/05/13 1p

I Operating license stage documents & correspondence

7904070240 Requests temporary extension of License R-92 to allow time for decommissioning & amending of License C 4 to permit transfer of fuel to suitably licensed party
BLACK, E T, KOPPELMAN, R West Virginia Univ 79/05/30 1p

7905100251 Requests that License R-90 be extended temporarily for 12 months to allow time for decommissioning. Also requests that Condition C 4 be amended to allow transfer of fuel to suitably party
BLACK, E T, KOPPELMAN, R West Virginia Univ 79/05/30 1p

I Inspection reports, IE Bulletins & correspondence

7904260414 Forwards IE Info Notice 79-12: "Attempted Damage to New Fuel Assemblies"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 1p

DOCKETED ITEMS

11

DOCKET 70-130 PASSENDER ATOMIC PLANT

0 Inspection reports, IC Bulletin & correspondence

7002701023 Responds to IC Bulletin 70-08 re events relevant to SUE identified during TMI incident
CRANE, P A Pacific Gas & Electric Co 70/05/01 5pp

DOCKET 70-131 DRAVA WET ADMIN HOSP RESEARCH REACTOR

0 Inspection reports, IC Bulletin & correspondence

7002580033 Forwards SE Info Notice 70-12, "Attempted Damage to New Fuel Assemblies"
SEYFRIT, R V Region 4, Dallas, Office of the Director 70/05/11

DOCKET 70-132 HARBOLDT BAY POWER PLANT, UNIT 3

0 Administrative correspondence

7004002005 Holds proceedings in absence until 701001 Licensee shall furnish report re status of geologic investigation within ten days after receipt of order & every 45 days thereafter
LUTON, E Atomic Safety and Licensing Board Panel 70/05/07 1p

0 Inspection reports, IC Bulletin & correspondence

7006140099 Schedule for responses to IC Bulletin 70-02 & 70-03 will be submitted after resolution of seismic issues currently being studied
CRANE, P A Pacific Gas & Electric Co 70/04/23 1p

7006130123 Forwards IC Circular 70-07, "Unspecified Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase" No written response required
CHIDELSON, R H Region 5, San Francisco, Office of the Director 70/05/02 1p

7006120047 Forwards IC Info Notice 70-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required
CHIDELSON, R H Region 5, San Francisco, Office of the Director 70/05/07 1p

7006110079 Forwards IC Info Notice 70-12, "Attempted Damage to New Fuel Assemblies" No written response necessary
CHIDELSON, R H Region 5, San Francisco, Office of the Director 70/05/10 1p

7006110079 Forwards IC Bulletin 70-10, "Requalification Training Program Statistics" Written response required
CHIDELSON, R H Region 5, San Francisco, Office of the Director 70/05/11 1p

7006100061 Forwards IC Circular 70-08, "Attempted Extortion - Low Enriched U"
CHIDELSON, R H Region 5, San Francisco, Office of the Director, 70/05/10, 1p

7006130042 Forwards IC Bulletin 70-11, "Partial Overcurrent Trip Device in Electric Breakers for Engineered Safety Sys" License action required
CHIDELSON, R H Region 5, San Francisco, Office of the Director 70/05/22 1p

7006110073 Forwards IC Bulletin 70-12, "Short Period Seism at BWR Facilities" License action required
CHIDELSON, R H Region 5, San Francisco, Office of the Director 70/05/31, 1p

R Periodic operating reports & related correspondence

7006110028 Forwards monthly operating report for May 1977
MEERS, E B Pacific Gas & Electric Co 70/06/07 1p

--7006100070 Monthly operating report for May 1977.
GUFFR, E G Pacific Gas & Electric Co. 70/05/31 App.

0 Reportable occurrences, LCRs & related correspondence

7005002040 FWD-70-ATAS summary of info re nuclear incident as of 700428 description plant & environs status
0 Office of Inspection & Enforcement 70/04/28 3pp

7006100219 Forwards FWD-70-ATAS
CHIDELSON, R H Region 5, San Francisco, Office of the Director 70/05/14 1p

7006100215 Forwards FWD-70-ATAS
CHIDELSON, R H Region 5, San Francisco, Office of the Director 70/05/21 1p

7006100208 Forwards FWD-70-ATAS
CHIDELSON, R H Region 5, San Francisco, Office of the Director 70/05/22 1p

7006100214 Forwards FWD-70-ATAS
CHIDELSON, R H Region 5, San Francisco, Office of the Director 70/05/20 1p

7006170019 Forwards LCR 70-021/03L-0
CRANE, P A Pacific Gas & Electric Co 70/06/12 1p

--7006100223 LCR 70-023/03L-0 on 700312 fire water egg header low pressure switch APR-12 started fire pumps at 41 gpm instead of 45 gpm caused by drift & close differential setting
Defect not adjusted Switch will be replaced
CHIDELSON, R H Pacific Gas & Electric Co 70/06/12 1p

7006170021 Forwards LCR 70-004/03L-0
CRANE, P A Pacific Gas & Electric Co 70/06/12 1p

--7006170023 LCR 70-004/03L-0 on 700316 refueling bldg ventilation when valve failed closed caused by poor attachment of pivot arm to butterfly valve stem Procedures approved for attachment of arm to stem
REDEMAN, S J Pacific Gas & Electric Co 70/06/15 App

DOCKET 70-134 WORCESTER POLYTECH INST RESEARCH REACTOR

P Operating license stage documents & correspondence

7006120004 Responds to LC Wilbur 700423 Request for renewal of License R-61 which will expire 701123 Submits specific items that will be reviewed prior to license renewal
REID, S H Operating Reactors Branch 4 (Pw 700625) 70/05/14 10pp

0 Inspection reports, IC Bulletin & correspondence

7006260043 Forwards IC Info Notice 70-12, "Attempted Damage to New Fuel Assemblies"
ORLER, D H Region 1, Philadelphia, Office of the Director 70/05/11 1p

7006260007 Forwards IC Circular 70-09, "Attempted Extortion - Low Enriched U"
ORLER, D H Region 1, Philadelphia, Office of the Director 70/05/10 1p

DOCKET 70-139 UNIV OF WASHINGTON RESEARCH REACTOR

0 Inspection reports, IC Bulletin & correspondence

7006120442 Forwards IC Info Notice 70-12, "Attempted Damage to New Fuel Assemblies" No written response necessary
CHIDELSON, R H Region 5, San Francisco, Office of the Director 70/05/10, 1p

7006080028 Forwards IC Circular 70-08, "Attempted Extortion - Low Enriched U"
CHIDELSON, R H Region 5, San Francisco, Office of the Director 70/05/10, 1p

DOCKET 70-141 STANFORD UNIV RESEARCH REACTOR

0 Inspection reports, IC Bulletin & correspondence

7006100229 Forwards IC Insp Rept 50-141/79-01 on 700331 & 0313 Re noncompliance noted
BOKR, W E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 70/03/27 2pp

--7006100237 IC Insp Rept 50-141/79-01 on 700331 & 0313 Re noncompliance noted Major areas inspected, facility that previously housed pool type research reactor
CHIDELSON, R H Region 5, San Francisco, Office of the Director 70/03/27 3pp

DOCKETED ITEMS

DOCKET 90-142 UCLA TRAINING REACTOR

J Insurance & indemnity information

7906260390 Forwards executed Amend 8 to Indemnity Agreement E-14 Amend 8 to Indemnity Agreement E-38 Amend 8 to Indemnity Agreement E-33 & Amend 10 to Indemnity Agreement E-10
 WENDESS G J California Univ of Berkeley 79/06/20 App

P Operating license stage documents & correspondence

7906104002 Requests renewal of License R-71 due to expire on 8/30/81
 CARTTON L California Univ of Los Angeles 79/06/20 Ip

S Inspection reports, IE Bulletins & correspondence

7906100484 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies - No written responses necessary
 BERNARD R H Region 3, San Francisco, Office of the Director 79/05/10 App

7906080206 Forwards IE Circular 79-08, "Attempted Extortion - Low Extortion U"
 BERNARD R H Region 3, San Francisco, Office of the Director 79/05/10 App

DOCKET 90-146 BAITON NUCLEAR EXPERIMENTAL FACILITY

H General correspondence

7906210000 Ack receipt of 790611 request to witness Facility Inop Licensee test NRC has authority to allow spectators to be present Protocol/Inop agreement for accompaniment of NRC Inop team
 BERNARD R H Region 1, Philadelphia, Office of the Director 79/06/19 App

J Insurance & indemnity information

7906102977 Forwards Endorsement 71 to ANS Policy NF-107
 HOFFMEYER C R Baiton Nuclear Experimental Corp 79/06/07 App

DOCKET 90-148 UNIV OF KANSAS RESEARCH REACTOR

J Insurance & indemnity information

7906270210 Forwards Amend 9 to Indemnity Agreement E-21
 HALLERENSON C A Kansas Univ of 79/06/20 App

G Inspection reports, IE Bulletins & correspondence

7906250007 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
 BEFFREY K V Region 4, Dallas, Office of the Director 79/05/11 Ip

DOCKET 90-150 OHIO STATE UNIV RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7906190048 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
 KIEFFLER J O Region 3, Chicago, Office of the Director 79/05/11 Ip

7906090174 Forwards IE Circular 79-08, "Attempted Extortion - Low Extortion U"
 KIEFFLER J O Region 3, Chicago, Office of the Director 79/05/10 Ip

DOCKET 90-151 UNIV OF ILLINOIS RESEARCH REACTOR

J Insurance & indemnity information

7906100455 Executed Amend 12 to Indemnity Agreement E-20
 BARNETT J H Antitrust & Indemnity Group 79/06/14 Ip

G Inspection reports, IE Bulletins & correspondence

7906100602 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
 KIEFFLER J O Region 3, Chicago, Office of the Director 79/05/11 Ip

7906080181 Forwards IE Circular 79-08, "Attempted Extortion - Low Extortion U"
 KIEFFLER J O Region 3, Chicago, Office of the Director 79/05/10 Ip

DOCKET 90-155 BIG ROCK POINT NUCLEAR PLANT

P Operating license stage documents & correspondence

7906080206 Requests add info re fire prevention insulation on cabling in recirculating pump area Evaluation of need for protective insulation on recirculating pump area cabling & associated valve operators to be completed by 79/05/15
 BIEHL D A Consumers Power Co 79/05/20 Ip

7906080172 Discusses need for fire protective insulation on cables & valve operators in recirculating pump room Insulation not necessary
 HOFFMAN W P Consumers Power Co 79/06/13 App

P Operating license stage documents & correspondence

7906101824 Requests two xerocoded copies of site emergency plans & implementing procedures, site maps showing location & grid station numbers of drains & effluents and/or monitoring stations & maps used for effluent dose determination
 KIEFFLER J O Region 3, Chicago, Office of the Director 79/05/17 Ip

7906101774 Submits response to 790607 rapid response questions re effluent monitoring eqs
 HOFFMAN W P Consumers Power Co 79/06/14 App

7906080188 Corrects 790614 response to questions re effluent monitoring eqs
 BIEHL D A Consumers Power Co 79/05/22 Ip

7906080194 Forwards comments re systematic evaluation program details prepared in NRC 790616 17
 BIEHL D A Consumers Power Co 79/05/22 App

7906080163 Forwards request for change to Tech Spec-permitting mod of spent fuel storage shed by addition of storage racks
 BIEHL D A Consumers Power Co 79/06/26 App

S Inspection reports, IE Bulletins & correspondence

7906140511 Forwards IE Insp Rept 33-135/79-06 on 790603-06 No noncompliance noted
 KIEFFLER J O Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/14 App

7906140546 IE Insp Rept 33-135/79-06 on 790603-06 No noncompliance noted Major areas inspected preparation for refueling process/pre-fuel handling activities, fuel handling activities & mod of containment supply ventilation valve
 KIEFFLER J O Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/15 App

7906101029 Forwards IE Insp Rept 33-135/79-06 on 790614-16 & 0483 No noncompliance noted
 FIORELLI O Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/18 App

7906101024 IE Insp Rept 33-135/79-06 on 790614-16 & 0483 No noncompliance noted Major areas inspected safety-related barriers & mechanical systems, observation of installation conditions & review of previous license surveillance
 VIN, J J, BARNETT J H Region 3, Chicago, Office of the Director 79/06/14 App

7906020547 Responds to IE Bulletin 79-09 re seismic analysis Dynamic analyses of piping were performed by reactor vendor & A/E
 Requested info will be submitted in one month
 BIEHL D A Consumers Power Co 79/06/24 Ip

7906050450 Notifies that preliminary review of 790301 description of inactive test program for pumps & valves & request for relief from specific ASME Code requirements is complete
 Forwards questions & comments
 ZICHANOW S L Operating Reactors Branch 2 (Re 790625) 79/06/22 App

7906080143 Responds to IE Bulletin 79-04 re inspect weights for well check valves eqs by Valves Engineering Corp Inspect valves not in use
 BIEHL D A Consumers Power Co 79/05/01 Ip

DOCKETED ITEMS

13

7706140246 Forwards response to IE Bulletin 79-08 Previous procedures for dealing with TMS incident circumstances
SIXEL, B.A. Consumers Power Co 79/05/01 1pp

7706120098 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Report Problem" No action required
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/05/07 1p

7706100093 Forwards IE Insp Rept 50-155/79-05 on 770326-30 Notice of Violation issued (ref 100790 790)
HENS, J.A. Region 3, Chicago, Referees Branch 79/05/09 2pp

7706100021 IE Insp Rept 50-155/79-03 on 790326-30 Noncompliance noted maintenance in lighting-access control-vital areas & access control research details violation (ref 100790 790)
HENS, J.A.; HENS, J.C.; HENS, J.A. Region 1, Philadelphia, Referees Branch 79/05/04 2pp

7706110066 Forwards IE Bulletin 79-10, "Regualification Training Program Statistics" Written response required
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/05/11 1p

7706170008 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/05/11 1p

7706100030 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/05/10 1p

7706230045 Response to IE Bulletin 79-09 re IE Type AM-2 circuit breakers Describes preventative maint program
SIXEL, B.A. Consumers Power Co 79/05/01 2pp

7706120094 Forwards IE Bulletin 79-11, "Facility Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Licensee action required
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/05/22 1p

7706200103 Forwards IE Info Notice 79-13, "Indication of Low Meter Level in Oyster Creek Reactor"
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/05/29 1p

B Reportable occurrences, LERs & related correspondence

7706120100 Bulletin info re control rod drive housing penetration design per leakage discovered during 770620 hydraulic testing & reported in LER 79-18 on 770302 Describes add testing to be performed Overvalued drawing
SIXEL, B.A. Consumers Power Co 79/05/07 3pp

7706240033 Forwards LER 79-020/017-0
SIXEL, B.A. Consumers Power Co 79/05/22 1p

7706250077 LER 79-020/017-0 on 770609 vibration found in primary sys oil circulation pump in and discovered diffuser dislodged in pump 1 inlet & loose diffuser in pump 2 inlet Caused by failure of bolts holding diffuser for reasons unknown
Consumers Power Co 79/05/22 2pp

DOCKET 50-156 UNIV OF MICHIGAN RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7706190054 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/05/11 1p

7706100191 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/05/10 1p

DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7706240075 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
GRUBER, S.H. Region 1, Philadelphia, Office of the Director 79/05/11 1p

7706100021 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
GRUBER, S.H. Region 1, Philadelphia, Office of the Director 79/05/10 1p

DOCKET 50-160 GEORGIA INST OF TECH RESEARCH REACTOR

J Insurance & indemnity information

7706270009 Forwards Award 12 to Indemnity Agreement 5-30
WILSON, J.W. Georgia Institute of Technology 79/05/22 2pp

G Inspection reports, IE Bulletins & correspondence

7706100012 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
GRUBER, S.H. Region 2, Atlanta, Office of the Director 79/05/10 1p

DOCKET 50-163 GENERAL ATOMIC COMPANY

J Insurance & indemnity information

7706190415 Forwards Endorsement 24 & 30 to R&AU Policy #7-89
COHEN, M.A. Marsh & McLennan, M & H Nuclear Consultants, Inc. Div 79/05/14 3pp

G Inspection reports, IE Bulletins & correspondence

7706190016 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
HENSEN, R.H. Region 3, San Francisco, Office of the Director 79/05/10 1p

7706100019 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
HENSEN, R.H. Region 3, San Francisco, Office of the Director 79/05/10 1p

DOCKET 50-166 UNIV. OF MARYLAND RESEARCH REACTOR

J Insurance & indemnity information

7706120317 Forwards Awarded Award 9 to Indemnity Agreement 6-22
TOLL, J.G. Maryland, Univ. of 79/06/07 2pp

G Inspection reports, IE Bulletins & correspondence

7706200062 Forwards IE Info Notice 79-13, "Attempted Damage to New Fuel Assemblies"
GRUBER, S.H. Region 1, Philadelphia, Office of the Director 79/05/11 1p

7706100024 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
GRUBER, S.H. Region 1, Philadelphia, Office of the Director 79/05/10 1p

DOCKETED ITEMS

9 Reportable occurrences, EERs & related correspondence

7906040341 Forwards EER 79-0117447-0
GOSSEL, H J Philadelphia Electric Co 79/03/07 2pp

--7906040348 EER 79-0117447-0 an 7902239 appear 40 gallons light diesel
fuel oil drained into discharge canal caused by valve left
open after valve stopped open discovery: cleanup
initiated & valve locked in control unit
GOSSEL, H J Philadelphia Electric Co 79/03/07 1p

DOCKET 30-102 PURDUE UNIV RESEARCH REACTORF Security, medical, emergency & fire protection plans

7906103180 Forwards modified physical security plan Plan withheld
Intr 100792 7901
CLINEBAUM, F M Purdue Univ 79/05/05 1p

0 Inspection reports, IE Bulletins & correspondence

7906080135 Ack receipt of 7904419 ltr informing NRC of steps taken to
correct violations noted in IE insp repts
HIND, J A Region 3, Chicago, Safeguards Branch 79/05/08 1p

--7906080130 Response to NRC 790326 ltr re violations noted in IE insp
repts Corrective actions withheld (ref 100792 7901)
CLINEBAUM, F M Purdue Univ 79/04/19 2pp

7906190058 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
NEPPLER, J O Region 3, Chicago, Office of the Director 79/05/11 1p

7906190059 Forwards IE Circular 79-08, "Attempted Exhortion - Low
Enriched U"
NEPPLER, J O Region 3, Chicago, Office of the Director 79/05/10 1p

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR0 Inspection reports, IE Bulletins & correspondence

7906210024 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
GILES, D H Region 1, Philadelphia, Office of the Director 79/05/11 1p

7906080141 Forwards IE Circular 79-08, "Attempted Exhortion - Low
Enriched U"
GILES, D H Region 1, Philadelphia, Office of the Director 79/05/08 1p

DOCKET 30-186 UNIV OF MISSOURI RESEARCH REACTOR0 Inspection reports, IE Bulletins & correspondence

18 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
J O Region 3, Chicago, Office of the Director 79/05/11

DOCKET 50-188 KANSAS STATE UNIV RESEARCH REACTOR0 Inspection reports, IE Bulletins & correspondence

7906210006 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
SOMMER, K W Region 4, Dallas, Office of the Director 79/05/11 1p

DOCKET 30-192 UNIV OF TEXAS RESEARCH REACTOR0 Inspection reports, IE Bulletins & correspondence

7906250012 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
SEYFRIED, K V Region 4, Dallas, Office of the Director 79/05/11 1p

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS ACO0 Inspection reports, IE Bulletins & correspondence

7906200029 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
SHULER, B H Region 1, Philadelphia, Office of the Director 79/05/11 1p

DOCKET 30-194 MANHATTAN COLLEGE RESEARCH REACTOR0 Inspection reports, IE Bulletins & correspondence

7906200030 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
CRITEN, B W Region 1, Philadelphia, Office of the Director 79/05/11 1p

7906080022 Forwards IE Circular 79-08, "Attempted Exhortion - Low
Enriched U"
SEITZ, B H Region 1, Philadelphia, Office of the Director 79/05/08 1p

DOCKET 30-291 WEST VALLEY REPROCESSING PLANTH General correspondence

7906210241 Responses to 790124 ltr re effects of radioactive waste on
bedion of water surrounding Mt State & effects of stored
wastes on animals
ROUSELLE, C Fuel Reprocess & Recycle Branch 79/04/03 4pp

--7906210260 Requests info re serious effects of radioactive wastes at
plant site
SCHERMAN, R Affiliation Unknown 79/01/24 1p

7906290101 Ack receipt of 790339 ltr & 790506 telcon suggests use of
local PM to obtain info on serious effects of radioactive waste on
bedion of water surrounding Mt State & effects of stored
wastes on animals
ROUSELLE, C Fuel Reprocess & Recycle Branch 79/05/04 3pp

7906200471 Forwards requested info re discovery of pen defect at
Nuclear Fuel Svcs. Inc. summary of NRC 790103 meeting re pen
defect & summary of NRC 790329 meeting re investigation &
evaluation of defect by pen
HUGHES, C J Fuel Reprocess & Recycle Branch 79/05/08 3pp

0 Operating license stage documents & correspondence

7906200032 Responses to 790329 telegram requesting NRC presence at
790404 hearing since last safety investigation is
concluding final conclusions about safety margins for tanks
cannot be made.
STROCK, H J Office of Nuclear Material Safety & Safeguards 79/04/02 2pp

--7906090070 Requests NRC appear before 790404 legislative committee
energy ap hearing is discuss safety questions re high level
radioactive waste tanks operated by license
HUTV, B New York State at 79/03/21 1p

7906090080 Ack receipt of documents re condition of high level ltr
waste storage age at West Valley/RT facility.
HUTV, B New York State at 79/04/16 1p

DOCKETED ITEMS

7906250049 Summary of 790215 meeting w/WR in Silver Spring,MD re efforts to provide biological data useful for future contamination & decommissioning & present efforts to investigate SS-2 core defect

7908253069 Notification of 790516 meeting w/ NY State Energy R&D Authority & NED to discuss progress of efforts re technical info for future decontamination & to investigate M22 pan defect.
NAUGHNEY, C J Fuel Reprocess & Recycle Branch 79/05/01

7904200179 Summary of 790501-82 meeting w/HFB at West Valley, NY facility to obtain site data on safety of high level waste storage
CLARK, A T Fuel Process & Fab Branch 79/05/82 Gps

1942504485 Forwarded URL-82579, "Structural Analyses of Fuel Reducing Station Fuel at NPS Reprocessing Plant-West Valley, NY" & typical rpt evaluation H790307 comments from GW Hall of NM Nuclear Consulting Engineering Univ
ROUSE, L. C Fuel Reprocess & Recycle Branch 79/03/14 3pp

---7904250487 "Structural Analysis of Fuel Receiving Station Pool at
NPS Reprocessing Plant, West Valley, NY."
DONS, R & Lawrence Livermore Laboratory ARC-03-78-150
ORNL-32575 7904250487 42pp Available as NTIS

7905250489 Typical post evaluation of UOCL-SQB05. "Structural Analyses of Fuel Receiving Station Pool at NPB Reprocessing Plant, West Valley, NY"

7904210129 Discusses NRC 790329 & 0623 memos re defect in pan under high level liquid waste tank at reprocessing plant, in response to Jan 1979 request
 HQUSC, L C Paul Hargreaves & Sacula Beach 29/05/81 Rm

□ Inspection reports, IE Bulletin & correspondence

770260040 Forwards IE Info Notice 77-12, "Attempted Damage to New Fuel Assemblies"
ORDER, G M Region I, Philadelphia, Office of the Director
7/20/57 1a

SECRET 89-206 SAN GABRIEL NUCLEAR STATION, UNIT 1

P Operating license stage documents & correspondence

7905040924 Forward draft evaluation of systematic evaluation program
Topic: 2V-19 re LCCA resulting from spectrum of postulated
piping breaks within reactor coolant pressure boundary
Requests input within 30 days
ZIEHAKK D L Operating Reactors Branch 2 (Pre 790525) 79/03/15
Jpp

1996080223 Forwards draft evaluation of systematic evaluation program
Topic IV-1 A: "Operation W-Test: Thus All Loops in Bv"
Request Review & Response within 30 days
ZIERMAN, D L Operating Reactors Branch 2 (Pre 199623) 79/04/00
12pg

PG06040333 Forwards comments on systematic evaluation program Topic
VI-10 3. "Shared Engineered Safety Features/Onsite Emergency
Power & Gas Sys for Multiple Unit Stations"
HAYNES, J S Southern California Edison Co 79/03/17 2pg

7906060271 Offers no comments on NRC redraft evaluation of systematic evaluation program Topic IV-1 A Proposed Tech Spec changes to be submitted by 790608
HAYNEQ.J @ Southern California Edison Co 79/05/25 ca

7906040167 Forwards corrections to Figures 4 2 2 4 5 2-2 re
reorganization changes Figures appended corresponding
Figures of Proposed Change 77
BARRIN, K. P. Southern California Edison Co. 28/03/01 3w

790619068 Forwards Amend 80 to License 89B-13, consisting of proposed
Tech Specs Change 80
DRANE, J H Southern California Edison Co 79/06/11 tp

--7906140472 Amend 80 to Licensee GPR-9D, consisting of proposed Tech Specs
Change 80 to restrict operation w/less than all reader
emulated loops in sxc Certificate of Svc sent
* Southern California Edison Co. 7/9/06/9D 10pp

Precedence: Forward info requested in 68C 701000 ltr re systematic evaluation of foreign Tech. Unit-4 re electrical penetrations of reactor containment
 04/06/70 J O Southern California Edison Co 79/01/16 1300

④ Inspection reports, IE Bulletins & correspondence

790200134 Responds to NRC 790411 for re-visitations noted in DE Insp Rept 99-036/79-04 Corrective actions three design changes have been reviewed by all licensed operators
HSCWEL J B Southern California Edison Co 79/05/01 See

CRD/S: J L Region 5, San Francisco, Office of the Director
7/19/04/jll gas

--79062003144 Notice of violation from insp on 790216 & 0013-15
+ Region 5, San Francisco, Office of the Director 79/04/31
is

--7905293149 IC Insp Rept 90-206/79-24 on 790326 3 0312-13
Macconscience noted failure of reactor operator retraining
program to review facility design changes
CHARTER, H. L., JOHN DOLY Region 3, San Francisco; Office of the
Director FAULKENBERG, S Region 3, San Francisco; Reactor
Operations Nuclear Support Branch 79/04/31 Sus

7905210345 Response to IE Bulletin 79-06A & Revision 3 Operating personnel have been instructed that precursor level indications may not provide reliable transient or accident conditions IE bulletins on THs are distributed for review (SWAN). J H Southern California Edison Co 790503 15pp

7906120051 Forwarded SE Info Notice 79-81, "Lower Reactor Vessel Head Insulation Support Problem" - No action required
RMG:LRH:JH:R - Region 5, San Francisco; Office of the Director
79/06/02 Lm

TP04270126 Herremans What MEC study potential use of nuclear instrumentation source & intermediate to determine existence of voids in IE Bulletin 79-056, Revision 1 WILLIAMS, F J Revision of Project Management 79/05/09 1a

P0561034MI Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel
 Assemblies - No written response necessary
 DISCLOSED to Region 5, San Francisco, Office of the Director
 79/05/10 ss

790610075 Forwards IE Bulletin 79-10. "Requalification Training Program Statistics." Written response required.
ENOCLEAK,R H Region 5, San Francisco, Office of the Director
79/05/11 1a

7902250403 Forwards DE Insp Regt 50-236/79-06 on 790400-11 No
noncompliance noted
CHDS: J L Reiter S. San Francisco, Reorder Operations Nuclei
Support Branch 7903A/11 Don

79-066250472 IE Insp Rept 80-206/79-06 on 79040-01 No noncompliance noted Major areas inspected verification of IE Bulletin 79-038, examination of licensee plant review of features similar to TRI design
CANYON, H L, FAULKNER, G Region 5, San Francisco, Reaction Dynamics Nuclear Research Branch 79/05/10 3as

7906080943 Forwards IE Circular 79-09, "Attempted Extortion - Low
Suspected U" b6
CNSL/KSOFH Region 3, San Francisco, Office of the Director
2005/10 1a

7905135047 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device
in Circuit Breakers for Engineered Safety Sys - Licensee
action required
ENCLOSURE 8 H Reges S, San Francisco, Office of the Director
79/05/02 1p

790620300A Forwards IE Info Helix 79-13. "Inflation of Low Water Level in Oyster Creek Reactor"

EM06LKH:R H. Region 3, San Francisco. Office of the Director

79/03/29 1a

R. Periodic operating reports & related correspondence

7906130009 Forwards monthly operating rept for May 1979
CURRAM J H Southern California Edison Co 79/06/04 to

--7906100491 Monthly operating report for May 1979
EDELMEIER, J. P. Southern California Edison Co 79/06/06 App

G Reportable occurrences, LERs and related correspondence

7906100228 Forwards PNO-79-0749
EDELMEIER, J. P. Region 5, San Francisco, Office of the Director
79/05/14 Sp

7906100223 Forwards PNO-79-0749
EDELMEIER, J. P. Region 5, San Francisco, Office of the Director
79/05/21 Sp

7906100341 Forwards PNO-79-0749
EDELMEIER, J. P. Region 5, San Francisco, Office of the Director
79/05/22 Sp

7906100348 Forwards PNO-79-0749
EDELMEIER, J. P. Region 5, San Francisco, Office of the Director
79/05/30 Sp

7906100314 Forwards LER 79-018/017-D
KORNE, J. B. Southern California Edison Co 79/06/10 Sp

--7906100320 LER 79-018/017-D as 790605 radiography revealed stress
indications in steam generator feedwater nozzle during water
outage. Caused by stress assisted corrosion. Nozzle repaired
in water reactor.
CURRAN, J. M. Southern California Edison Co 79/06/10 Sp

7906100349 Response to NRC 790525 request Forwards three covered
drawings, "Steam Generator Nozzle to Piping Isop &
Corrective Action," & "Detectability to Steam Generator
Feedwater Line Water Hammer Events."
MAYHEW, J. C. Southern California Edison Co 79/06/10 3pp

--7906100347 Interim report "Steam Generator Nozzle to Piping Isop &
Corrective Action"
* Southern California Edison Co 79/06/13 21pp

--7906100336 "Detectability to Steam Generator Feedwater Line Water
Hammer Events"
* Southern California Edison Co 77/12/31 Sp

7906100240 Forwards LER 79-008/017-D
KORNE, J. B. Southern California Edison Co 79/06/10 App

--7906100404 LER 79-018/017-D as 790604 during main outage ID defective
tube discovered in steam generator A. Caused by corrosion of
area of tube sheet. Defective tubes plugged.
CURRAN, J. M. Southern California Edison Co 79/06/10 App

7906100325 Forwards LER 79-009/017-D
KORNE, J. B. Southern California Edison Co 79/06/19 App

--7906100346 LER 79-009/017-D as 790605 rubber failure discovered during
functional testing. Caused by water hammer from misadjustment
of feedwater regulating valve control circuit. Control
circuit repaired & retested.
CURRAN, J. M. Southern California Edison Co 79/06/19 Sp

SECRET 80-208 COLUMBIA UNIV. RESEARCH REACTION

H Inspection reports, IE Bulletins and correspondence

Re Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Can"
* Electric, Office of the President

J Insurance and indemnity information

7906100242 Forwards Endorsements 35 & 36 to NAAJUL Policy No-09
EDELMEIER, J. P. Connecticut Yankee Atomic Power Co 79/05/10 App

7906100240 Forwards Endorsements 60 & 61 to NAAJUL Policy No-151
EDELMEIER, J. P. Connecticut Yankee Atomic Power Co 79/05/10 App

P Operating license steps documents and correspondence

7906100224 Forwards draft evaluation of systematic evaluation program
Topic 20-1-A, "Operation No/Less Than All Loads in Rev."
Requests review & response within 30 days.
EDELMEIER, J. P. Operating Reactors Branch 2 (PNO 790625) 79/05/07 App

7906100205 Notification of 790516 meeting w/with in Bethesda, MD to
discuss Hudson Area geologic issues.
EDELMEIER, J. P. Operating Reactors Branch 2 (PNO 790625) 79/05/04 App

7906100212 Notification of 790522 meeting w/with in Silver Spring, MD
to discuss App 1 Tech Specs.
EDELMEIER, J. P. Operating Reactors Branch 2 (PNO 790625) 79/05/17 App

7906100213 Proposed m/c of two licensed reactor operators by statement
in main control rooms at all times-one of whom has direct
responsibility for feedwater system.
EDELMEIER, J. P. Connecticut Yankee Atomic Power Co 79/05/20 App

7906100242 Requests amend to License DPE-61-revising Tech Specs
Sections 3.0 & 3.1 & 3.2-adding conditions for operation &
surveillance requirements for auxiliary feedwater system.
EDELMEIER, J. P. Connecticut Yankee Atomic Power Co 79/05/01 App

7906100204 Submitte info requested by V. H. H. 790525 in re design.
Refrigeration history & snap of feedwater lines. Response
includes all info available until has no plans to provide
AC-day report.
EDELMEIER, J. P. Connecticut Yankee Atomic Power Co 79/05/10 54pp

S Inspection reports, IE Bulletins and correspondence

7906100310 Forwards IE Bulletin 79-005, "Nuclear Incident at
TMI-2" Report. No written response required.
EDELMEIER, J. P. Region 1, Philadelphia, Office of the Director
79/04/23 Sp

7906100328 Forwards response to IE Bulletin 79-07 re seismic stress
analysis of water/gated piping. Dynamic analyses were not
used.
EDELMEIER, J. P. Connecticut Yankee Atomic Power Co 79/04/24 App

7906100329 Ask receipt of 790604 in re informing NRC of steps taken to
correct violations noted in IE Insp Rept 80-213/79-04
EDELMEIER, J. P. Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 79/05/03, Sp

--7906100300 Response to NRC 790507 in re violations noted in IE Insp
Rept 80-213/79-04 Corrective action. Meeting notes will be
distributed to include revision page in core refueling
procedure.
EDELMEIER, J. P. Connecticut Yankee Atomic Power Co 79/04/04 App

--7906100308 Forwards IE Insp Rept 80-213/79-04 as 790512-14 & notice
violation.
EDELMEIER, J. P. Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 79/03/07, App

--7906100304 Notice of violation from Insp on 790512-14.
* Region 1, Philadelphia, Reactor Operations Nuclear Support
Branch 79/03/06, Sp

--7906100306 IE Insp Rept 80-213/79-04 as 790512-14. Noncompliance note
failure to maintain typed revised refueling procedure
EP 376.08.
EDELMEIER, J. P. Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 79/03/06, App

7906100304 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Support Problem." No action required.
EDELMEIER, J. P. Region 1, Philadelphia, Office of the Director
79/05/07, App

DOCKETED ITEMS

790410119 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics" - Written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/05/11 1p

790405099 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assembly"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/05/10 1p

790420732 Response to IE Bulletin 79-04, Revision 1 Plans to prepare Test Spec and limiting conditions of operation re Simbala Cycle Change will specify operability requirements for both auxiliary feedwater pumps
COUNTELL, W D Connecticut Yankee Atomic Power Co 79/05/10 2pp

790420035 Discusses licensee response to IE Bulletin 79-04, Revision 1 Recommendations and consider extending current licensee operator understanding of TMI incident
MULLIGAN, F J Division of Project Management 79/05/11 1p

790408077 Forwards IE Circular 79-08, "Attempted Extrusion - Low Enriched U"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/05/10 1p

790420012 Submits add info to 790404 response to IE Bulletin 79-04, Revision 1 Discusses valid parameters in RCR review of containment isolation design & overpressure protection system
MULLIGAN, F J Connecticut Yankee Atomic Power Co 79/05/10 1p

790420742 Response to IE Bulletin 79-10, "Requalification Training Program Statistics" - Forwards util requalification training program statistics
COUNTELL, W D Connecticut Yankee Atomic Power Co 79/05/04 3pp

790420010 Forwards "Intersect Insp Rept" submitted by Westinghouse in Feb-Mar 1-79
GRIER, B H Connecticut Yankee Atomic Power Co 79/05/12 1p

--790420010 "Intersect Insp Rept"
Connecticut Yankee Atomic Power Co 79/03/10 32pp

R Periodic operating reports & related correspondence

790410035 Forwards monthly operating report for May 1979
GRIER, B H Connecticut Yankee Atomic Power Co 79/06/12 1p

--790410035 Monthly operating report for May 1979
Connecticut Yankee Atomic Power Co 79/06/12 1pp

DOCKET 30-018 CYBER CREEK NUCLEAR POWER PLANT

J Insurance & indemnity information

790410035 Forwards Endorsements 63 & 66 to AHS Policy NP-644
GRIER, B H GNP Service Corp 79/06/11 3pp

P Operating license stage documents & correspondence

790420012 Discusses actions agreed to in 790420 & 25 telcons between IE, Piedmont of U.S. & JH Allen of NRC Region 1 Topics include status & rate of improvement of facility radiation protection program
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/20 3pp

790410093 Confirms 790303 release w/JH Allen re 790302 event & presents status of Facility Reactor will remain in cold shutdown condition until NRC examines safety limits
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/03 1p

790401023 Notification of 790509 meeting w/Util, OE & Ecom in Bethesda, MD to resolve NRC concerns about returning facility to power following 790302 event that allowed water in vessel to decrease below LOELC limit
HODGKIN, B J Operating Reactors Branch 2 (Ppe 790425) 79/05/09 1p

790405040 Chart of radiological tests performed on water samples on 790303
Region 1, Philadelphia, Office of the Director 79/05/06 1pp

790405020 Summary of 790509 meeting w/Util & consultants re 790302 events resulting in low low low water level alarm Attendance list & agenda sent
HODGKIN, B J Operating Reactors Branch 2 (Ppe 790501) 79/05/17 32pp

790404074 Response to 790410 ltr requesting comments on NRC evaluation of systematic evaluation program licensing requirements for station battery banks
FIMMERICK, I R Jersey Central Power & Light Co 79/05/20 1p

790405029 Forwards OL Change Request 31, adding info to IER for fire protection program w/supporting documentation
FIMMERICK, I R Jersey Central Power & Light Co 79/06/01 14pp

790405029 Forwards Tech Spec Change Request #9 for App A to provisional license 09F-16, for section 31.3.2.4.4 & 6
Requests incorporation of Tech Spec changes one year after approval, appropriate fee & Certificate of Approval
FIMMERICK, I R Jersey Central Power & Light Co 79/06/01 2pp

--790405029 Tech Spec Change Request #9 re protective instrumentation requirements, radioactive effluents & radiological emission monitoring program
FIMMERICK, I R Jersey Central Power & Light Co 79/06/01 36pp

790420009 Submits Tech Spec Change Request #6, Revision 1, covering high radiation area info submitted 790412
FIMMERICK, I R Jersey Central Power & Light Co 79/06/10 7pp

G Inspection reports, IE Bulletin 4 & correspondence

790410014 Forwards IE Bulletin 79-08, "Nuclear Incident at TMI-Buy" - No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/23 1p

790420076 Response to IE Bulletin 79-08 re END-related events identified during SM-1 event Schedule of completion dates for all corrective actions will be available by 790511
FIMMERICK, I R Jersey Central Power & Light Co 79/04/20 10pp

790420026 Response to IE Bulletin 79-04, "Intersect Weights for Spring Check Valves Hg by Valen Engineering Corp." Util has 4-inch valves w/class 150 pressure rating installed on fuel post casing top
GRIER, B H Region 1, Philadelphia, Office of the Director
79/05/01 1pp

790420012 Forwards IE Circular 79-07, "Unaccepted Speed Increase of Reactor Water Separator Resulting in Reactor Power Increase" - No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/05/02 1p

790410012 Forwards IE Info Notice 79-13, "Lower Reactor Vessel Head Insulation Support Problem" - No action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/05/07 1pp

790420013 Ack receipt of 790423 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-219/79-05
GRIER, B H Region 1, Philadelphia, Reactor Operations Nuclear Report Branch 79/05/09 1p

--

Support Branch 79/04/01 1pp

--790420023 Notice of violation from Insp on 790327-0302 & 0309-04
Region 1, Philadelphia, Office of the Director 79/04/02 2pp

--790420023 IE Insp Rept 30-219/79-05 on 790327-0302 & 0309-04 Noncompliance noted elsewhere did not meet requirements of HSB 2.2 & station procedures
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/02 14pp

790410122 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics" - Written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/05/11 1p

790405012 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assembly"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/05/11 1p

7904290004 Forwarders IE Circular 79-03. "Assumed Eruption - Low Enriched U"
 0812B, R. H. Region 1, Philadelphia. Office of the Director
 79/03/10 1p

7904290007 Response to IE Bulletin 79-10 Forwarder statistical info re operator requalification training program
 FIAF0004, R. H. Jersey Central Power & Light Co 79/03/24 3pp

7904290019 Advances that revision of insurance loss program will be submitted for approval by 790406 Review indicates no conflict between program & Tech Spec requirements
 FIAF0004, R. H. Jersey Central Power & Light Co 79/04/06 1p

R Periodic operating reports & related correspondence

7904290055 Forwarder monthly operating report for May 1979
 R088B, D. A. Jersey Central Power & Light Co 79/06/14 1p

7904290156 Monthly operating report for May 1979
 R088B, D. A. Jersey Central Power & Light Co 79/06/12 14pp

B Reportable occurrences, LERs & related correspondence

7904290251 Forwarder LER 79-021/021-0
 R088B, D. A. Jersey Central Power & Light Co 79/06/30 1p

7904290252 LER 79-023/021-0 on 790310 while performing interlock inspection discovered through wall crack on sparger pipe caused by methods used to install sparger pipe. Corrective action will be determined after full investigation
 R088B, D. A. Jersey Central Power & Light Co 79/06/30 2pp

7904290256 Forwarder LER 79-016/021-0
 FIAF0004, R. H. Jersey Central Power & Light Co 79/06/05 1p

7904290257 LER 79-016/021-0 on 790306 during surveillance test. Insulator condenser isolation resistor output A measured low. Voltage of source water caused by instrument drift in excess of design accuracy. Switch was recalibrated & put back in svc
 R088B, D. A. Jersey Central Power & Light Co 79/06/03 2pp

7904290258 Forwarder RD 29-016/79-20-1P
 CVA0004, J. T. Jersey Central Power & Light Co 79/06/14 1p

7904290259 RD 29-016/79-20-1P on 790412 second containment integrity was not maintained for 13 minutes caused by simultaneous opening of both reactor bldg radiation doors. Door components repaired
 R088B, D. A. Jersey Central Power & Light Co 79/06/14 2pp

7904290267 Forwarder LER 79-020/021-0
 R088B, D. A. Jersey Central Power & Light Co 79/06/15 1p

7904290268 LER 79-020/021-0 on 790317 smaller 50/20000 spray was ill. had signs of grease on assembly fitting on accumulator. Cause unknown but appears related to rigorous test conditions. Bushing replaced
 R088B, D. A. Jersey Central Power & Light Co 79/06/15 2pp

7904290269 Forwarder LER 79-027/021-0
 R088B, D. A. Jersey Central Power & Light Co 79/06/15 1p

7904290269 LER 79-017/021-0 on 790317 during routine surveillance of core spray was ill. parallel isolation valve 79-20-21 failed to operate. Caused by circuit breaker contacts making poor contact in "B" phase. creating overcurrent. Part replaced
 R088B, D. A. Jersey Central Power & Light Co 79/06/15 2pp

7904290269 Forwarder LER 79-019/021-0
 R088B, D. A. Jersey Central Power & Light Co 79/06/21 1p

7904290272 LER 79-019/021-0 on 790326 reactor high pressure isolation condenser isolation switch RD-2A tripped at 2 gpa greater than specified. Caused by instrument repeatability. RE-170 reset to trip at 1.050 gpa
 R088B, D. A. Jersey Central Power & Light Co 79/06/21 2pp

SECRET 50-520 NINE MILE POINT NUCLEAR STATION, UNIT 1

1 General correspondence

7904290303 Response to 790319 ltr to JN Windsor Facility was shot down by NRC 790313 order. due to questions re ability of piping system to withstand earthquake. Revision will be reviewed & plant returned to operation as soon as possible
 D07004, R. H. Office of Nuclear Reactor Regulation 79/05/06 1p

7904290304 Expresses concerns re shutdown of facility. Prolonged impact of plant employees could have adverse effect on town of Oswego, NY
 FIAF0004, J. E. Oswego, NY 79/03/15 1p

F Operating license stage documents & correspondence

7904290327 Forwarder Amend 20 to License 098-62, safety evaluation & notice of issuance & availability
 0812B, R. H. Operating Reactors Branch 3 (PRA 790625)
 79/03/25 2pp

7904290328 Amend 20 to License 098-62 revising Tech Specs to delete stress-corrosion cracking surveillance program
 39042, D. A. Operating Reactors Branch 3 (PRA 790625)
 79/03/25 4pp

7904290329 Safety evaluation supporting Amend 20 to License 098-62
 "Operating Reactors Branch 3 (PRA 790625) 79/03/26 1p

7904290400 Notice of issuance & availability of Amend 20 to License 098-62
 0812B, R. H. Operating Reactors Branch 3 (PRA 790625)
 79/03/26 2pp

7904290584 Response application to amend License 098-62
 39042, D. A. Lehigh, Lehigh & Harris 79/04/20 3pp

7904290590 Requests amend to License 098-62 re Tech Specs for fuel cladding & fuel rod. Forwarders proposed Tech Specs changes
 1. 098-24/098
 2. 098-24/098
 3. 098-24/098
 4. 098-24/098
 5. 098-24/098
 6. 098-24/098
 7. 098-24/098
 8. 098-24/098
 9. 098-24/098
 10. 098-24/098
 11. 098-24/098
 12. 098-24/098
 13. 098-24/098
 14. 098-24/098
 15. 098-24/098
 16. 098-24/098
 17. 098-24/098
 18. 098-24/098
 19. 098-24/098
 20. 098-24/098
 21. 098-24/098
 22. 098-24/098
 23. 098-24/098
 24. 098-24/098
 25. 098-24/098
 26. 098-24/098
 27. 098-24/098
 28. 098-24/098
 29. 098-24/098
 30. 098-24/098
 31. 098-24/098
 32. 098-24/098
 33. 098-24/098
 34. 098-24/098
 35. 098-24/098
 36. 098-24/098
 37. 098-24/098
 38. 098-24/098
 39. 098-24/098
 40. 098-24/098
 41. 098-24/098
 42. 098-24/098
 43. 098-24/098
 44. 098-24/098
 45. 098-24/098
 46. 098-24/098
 47. 098-24/098
 48. 098-24/098
 49. 098-24/098
 50. 098-24/098
 51. 098-24/098
 52. 098-24/098
 53. 098-24/098
 54. 098-24/098
 55. 098-24/098
 56. 098-24/098
 57. 098-24/098
 58. 098-24/098
 59. 098-24/098
 60. 098-24/098
 61. 098-24/098
 62. 098-24/098
 63. 098-24/098
 64. 098-24/098
 65. 098-24/098
 66. 098-24/098
 67. 098-24/098
 68. 098-24/098
 69. 098-24/098
 70. 098-24/098
 71. 098-24/098
 72. 098-24/098
 73. 098-24/098
 74. 098-24/098
 75. 098-24/098
 76. 098-24/098
 77. 098-24/098
 78. 098-24/098
 79. 098-24/098
 80. 098-24/098
 81. 098-24/098
 82. 098-24/098
 83. 098-24/098
 84. 098-24/098
 85. 098-24/098
 86. 098-24/098
 87. 098-24/098
 88. 098-24/098
 89. 098-24/098
 90. 098-24/098
 91. 098-24/098
 92. 098-24/098
 93. 098-24/098
 94. 098-24/098
 95. 098-24/098
 96. 098-24/098
 97. 098-24/098
 98. 098-24/098
 99. 098-24/098
 100. 098-24/098
 101. 098-24/098
 102. 098-24/098
 103. 098-24/098
 104. 098-24/098
 105. 098-24/098
 106. 098-24/098
 107. 098-24/098
 108. 098-24/098
 109. 098-24/098
 110. 098-24/098
 111. 098-24/098
 112. 098-24/098
 113. 098-24/098
 114. 098-24/098
 115. 098-24/098
 116. 098-24/098
 117. 098-24/098
 118. 098-24/098
 119. 098-24/098
 120. 098-24/098
 121. 098-24/098
 122. 098-24/098
 123. 098-24/098
 124. 098-24/098
 125. 098-24/098
 126. 098-24/098
 127. 098-24/098
 128. 098-24/098
 129. 098-24/098
 130. 098-24/098
 131. 098-24/098
 132. 098-24/098
 133. 098-24/098
 134. 098-24/098
 135. 098-24/098
 136. 098-24/098
 137. 098-24/098
 138. 098-24/098
 139. 098-24/098
 140. 098-24/098
 141. 098-24/098
 142. 098-24/098
 143. 098-24/098
 144. 098-24/098
 145. 098-24/098
 146. 098-24/098
 147. 098-24/098
 148. 098-24/098
 149. 098-24/098
 150. 098-24/098
 151. 098-24/098
 152. 098-24/098
 153. 098-24/098
 154. 098-24/098
 155. 098-24/098
 156. 098-24/098
 157. 098-24/098
 158. 098-24/098
 159. 098-24/098
 160. 098-24/098
 161. 098-24/098
 162. 098-24/098
 163. 098-24/098
 164. 098-24/098
 165. 098-24/098
 166. 098-24/098
 167. 098-24/098
 168. 098-24/098
 169. 098-24/098
 170. 098-24/098
 171. 098-24/098
 172. 098-24/098
 173. 098-24/098
 174. 098-24/098
 175. 098-24/098
 176. 098-24/098
 177. 098-24/098
 178. 098-24/098
 179. 098-24/098
 180. 098-24/098
 181. 098-24/098
 182. 098-24/098
 183. 098-24/098
 184. 098-24/098
 185. 098-24/098
 186. 098-24/098
 187. 098-24/098
 188. 098-24/098
 189. 098-24/098
 190. 098-24/098
 191. 098-24/098
 192. 098-24/098
 193. 098-24/098
 194. 098-24/098
 195. 098-24/098
 196. 098-24/098
 197. 098-24/098
 198. 098-24/098
 199. 098-24/098
 200. 098-24/098
 201. 098-24/098
 202. 098-24/098
 203. 098-24/098
 204. 098-24/098
 205. 098-24/098
 206. 098-24/098
 207. 098-24/098
 208. 098-24/098
 209. 098-24/098
 210. 098-24/098
 211. 098-24/098
 212. 098-24/098
 213. 098-24/098
 214. 098-24/098
 215. 098-24/098
 216. 098-24/098
 217. 098-24/098
 218. 098-24/098
 219. 098-24/098
 220. 098-24/098
 221. 098-24/098
 222. 098-24/098
 223. 098-24/098
 224. 098-24/098
 225. 098-24/098
 226. 098-24/098
 227. 098-24/098
 228. 098-24/098
 229. 098-24/098
 230. 098-24/098
 231. 098-24/098
 232. 098-24/098
 233. 098-24/098
 234. 098-24/098
 235. 098-24/098
 236. 098-24/098
 237. 098-24/098
 238. 098-24/098
 239. 098-24/098
 240. 098-24/098
 241. 098-24/098
 242. 098-24/098
 243. 098-24/098
 244. 098-24/098
 245. 098-24/098
 246. 098-24/098
 247. 098-24/098
 248. 098-24/098
 249. 098-24/098
 250. 098-24/098
 251. 098-24/098
 252. 098-24/098
 253. 098-24/098
 254. 098-24/098
 255. 098-24/098
 256. 098-24/098
 257. 098-24/098
 258. 098-24/098
 259. 098-24/098
 260. 098-24/098
 261. 098-24/098
 262. 098-24/098
 263. 098-24/098
 264. 098-24/098
 265. 098-24/098
 266. 098-24/098
 267. 098-24/098
 268. 098-24/098
 269. 098-24/098
 270. 098-24/098
 271. 098-24/098
 272. 098-24/098
 273. 098-24/098
 274. 098-24/098
 275. 098-24/098
 276. 098-24/098
 277. 098-24/098
 278. 098-24/098
 279. 098-24/098
 280. 098-24/098
 281. 098-24/098
 282. 098-24/098
 283. 098-24/098
 284. 098-24/098
 285. 098-24/098
 286. 098-24/098
 287. 098-24/098
 288. 098-24/098
 289. 098-24/098
 290. 098-24/098
 291. 098-24/098
 292. 098-24/098
 293. 098-24/098
 294. 098-24/098
 295. 098-24/098
 296. 098-24/098
 297. 098-24/098
 298. 098-24/098
 299. 098-24/098
 300. 098-24/098
 301. 098-24/098
 302. 098-24/098
 303. 098-24/098
 304. 098-24/098
 305. 098-24/098
 306. 098-24/098
 307. 098-24/098
 308. 098-24/098
 309. 098-24/098
 310. 098-24/098
 311. 098-24/098
 312. 098-24/098
 313. 098-24/098
 314. 098-24/098
 315. 098-24/098
 316. 098-24/098
 317. 098-24/098
 318. 098-24/098
 319. 098-24/098
 320. 098-24/098
 321. 098-24/098
 322. 098-24/098
 323. 098-24/098
 324. 098-24/098
 325. 098-24/098
 326. 098-24/098
 327. 098-24/098
 328. 098-24/098
 329. 098-24/098
 330. 098-24/098
 331. 098-24/098
 332. 098-24/098
 333. 098-24/098
 334. 098-24/098
 335. 098-24/098
 336. 098-24/098
 337. 098-24/098
 338. 098-24/098
 339. 098-24/098
 340. 098-24/098
 341. 098-24/098
 342. 098-24/098
 343. 098-24/098
 344. 098-24/098
 345. 098-24/098
 346. 098-24/098
 347. 098-24/098
 348. 098-24/098
 349. 098-24/098
 350. 098-24/098
 351. 098-24/098
 352. 098-24/098
 353. 098-24/098
 354. 098-24/098
 355. 098-24/098
 356. 098-24/098
 357. 098-24/098
 358. 098-24/098
 359. 098-24/098
 360. 098-24/098
 361. 098-24/098
 362. 098-24/098
 363. 098-24/098
 364. 098-24/098
 365. 098-24/098
 366. 098-24/098
 367. 098-24/098
 368. 098-24/098
 369. 098-24/098
 370. 098-24/098
 371. 098-24/098
 372. 098-24/098
 373. 098-24/098
 374. 098-24/098
 375. 098-24/098
 376. 098-24/098
 377. 098-24/098
 378. 098-24/098
 379. 098-24/098
 380. 098-24/098
 381. 098-24/098
 382. 098-24/098
 383. 098-24/098
 384. 098-24/098
 385. 098-24/098
 386. 098-24/098
 387. 098-24/098
 388. 098-24/098
 389. 098-24/098
 390. 098-24/098
 391. 098-24/098
 392. 098-24/098
 393. 098-24/098
 394. 098-24/098
 395. 098-24/098
 396. 098-24/098
 397. 098-24/098
 398. 098-24/098
 399. 098-24/098
 400. 098-24/098
 401. 098-24/098
 402. 098-24/098
 403. 098-24/098
 404. 098-24/098
 405. 098-24/098
 406. 098-24/098
 407. 098-24/098
 408. 098-24/098
 409. 098-24/098
 410. 098-24/098
 411. 098-24/098
 412. 098-24/098
 413. 098-24/098
 414. 098-24/098
 415. 098-24/098
 416. 098-24/098
 417. 098-24/098
 418. 098-24/098
 419. 098-24/098
 420. 098-24/098
 421. 098-24/098
 422. 098-24/098
 423. 098-24/098
 424. 098-24/098
 425. 098-24/098
 426. 098-24/098
 427. 098-24/098
 428. 098-24/098
 429. 098-24/098
 430. 098-24/098
 431. 098-24/098
 432. 098-24/098
 433. 098-24/098
 434. 098-24/098
 435. 098-24/098
 436. 098-24/098
 437. 098-24/098
 438. 098-24/098
 439. 098-24/098
 440. 098-24/098
 441. 098-24/098
 442. 098-24/098
 443. 098-24/098
 444. 098-24/098
 445. 098-24/098
 446. 098-24/098
 447. 098-24/098
 448. 098-24/098
 449. 098-24/098
 450. 098-24/098
 451. 098-24/098
 452. 098-24/098
 453. 098-24/098
 454. 098-24/098
 455. 098-24/098
 456. 098-24/098
 457. 098-24/098
 458. 098-24/098
 459. 098-24/098
 460. 098-24/098
 461. 098-24/098
 462. 098-24/098
 463. 098-24/098
 464. 098-24/098
 465. 098-24/098
 466. 098-24/098
 467. 098-24/098
 468. 098-24/098

DOCKETED ITEMS

790129067 Ack receipt of 790502 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-020/79-06
BONNEILLER, J. Region I, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/17 1p

790129268 Responds to NRC 790412 ltr re violations noted in IE Insp Rept 50-020/79-06. Corrective actions are individual.
performing task to assure Compliance. Individual advised that quality-related items should be reviewed by another.
BONNEILLER, J. Niagara Mohawk Power Corp 79/05/02 1p

790129342 Forwards IE Insp Rept 50-020/79-06 on 790305-08 & notice of violation.
BONNEILLER, J. Region I, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/12 3pp

790129347 Notice of violation from Insp on 790305-08
BONNEILLER, J. Region I, Philadelphia, Office of the Director 79/04/04 1p

790129354 IE Insp Rept 50-020/79-06 on 790305-08 Noncompliance noted failure to follow insps procedures.
KALMAN, D. SMITH, T. CAPTAIN, G. Region I, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/04 3pp

790129394 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
BONNEILLER, J. Region I, Philadelphia, Office of the Director 79/05/18 1p

790129408 Responds to IE Bulletin 79-07 Forwards add info on analysis of seven safety-related piping sys. Telephone Engineering Serv. re: "Identification & Specifications of TRIPTE Computer Program" & printouts and
DISE, D. P. Niagara Mohawk Power Corp 79/05/12 3pp

790129409 Notice Insp of pump & valve has been added to intervene insps program implementation date is Dec 1979. Available piping & instrument drawing will be available at site on 7905/20
BONNEILLER, J. Niagara Mohawk Power Corp 79/04/20 1p

8 Periodic operating reports & related correspondence

790129527 Forwards "1970 Nine Mile Point Aquatic Ecology Studies Report" in response to HQ 790505 ltr & Tech Spec reporting requirements.
BONNEILLER, J. Niagara Mohawk Power Corp 79/05/29 1p

790129531 "1978 Nine Mile Point Aquatic Ecology Studies Rept"
BONNEILLER, J. Niagara Mohawk Power Corp 79/05/31 30pp

9 Reportable occurrences, LERs & related correspondence

790130214 SO 79-12 on 790323 during Insp concrete anchor bolts discovered to be loose 5/37 improperly installed Bolt test program implemented & deficient bolts to be repaired or replaced.
BONNEILLER, J. Niagara Mohawk Power Corp 79/05/23 1p

790130179 Forwards LERs 79-008/03L-0 & 79-009/03L-0
BONNEILLER, J. Niagara Mohawk Power Corp 79/06/05 1p

790130181 LER 79-008/03L-0 on 790510 during refueling outage, containment spray heat exchangers 112 & 121 failed leak rate test caused by tube leak tests plugged.
BONNEILLER, J. Niagara Mohawk Power Corp 79/05/31 1p

790130184 LER 79-009/03L-0 on 790510 during refueling outage, NRC Operations Review Committee failed to review temporary change to test procedure 80-007-7 it within 7-day limit. Change subsequently reviewed.
BONNEILLER, J. Niagara Mohawk Power Corp 79/05/31 1p

790130205 Forwards LER 79-012/01T-0
BONNEILLER, J. Niagara Mohawk Power Corp 79/06/06 1p

790130206 LER 79-012/01T-0 on 790520 concrete anchor bolt deficiencies & missing seismic restraints were discovered on Class I seismic piping sys. Caused by incorrect installation. Concrete anchor bolt repair program will be completed by 79/05/31.
BONNEILLER, J. Niagara Mohawk Power Corp 79/05/31 1pp

790130247 Forwards LER 79-013/03L-0
BONNEILLER, J. Niagara Mohawk Power Corp 79/04/12 1p

790130247 LER 79-013/03L-0 on 790325 NRC Operations Review Committee failed to review temporary changes to three instruments. Compliance procedure while required 7-day period review has since taken place & approval received.
BONNEILLER, J. Niagara Mohawk Power Corp 79/04/12 1p

790130249 Forwards LER 79-04/03L-0
BONNEILLER, J. Niagara Mohawk Power Corp 79/04/18 1p

790130249 LER 79-014/03L-0 on 790319 during refueling outage, tube spray sys. snubber 40-18-10 found inoperable caused by design defect results on new sys. required resulting in loss of fluid from snubber. Reels replaced & snubber reinstalled.
BONNEILLER, J. Niagara Mohawk Power Corp 79/04/14 1p

7901302412 Forwards LER 79-011/03L-0
BONNEILLER, J. Niagara Mohawk Power Corp 79/04/15 1p

7901302417 LER 79-011/03L-0 on 790317 during refueling outage, discovered that radiographer received overexposure of 2,750 millirem for second quarter 1979 Cause unknown & under investigation. Discussed further in 790518 ltr to NRC.
BONNEILLER, J. Niagara Mohawk Power Corp 79/04/14 1p

7901302424 Submits repts of individual employee overexposure to radiation. General inability to adhere to radiation work permit may have contributed to overexposure. Personnel & film data incl case reported in LER 79-011/03L-0.
BONNEILLER, J. Niagara Mohawk Power Corp 79/04/15 3pp

DOCKET 50-020 UNIV. OF LOWELL RESEARCH REACTOR

8 Inspection reports, IE Bulletins & correspondence

790129070 Forwards IE Info Notice 79-12, "Attempted Extortion - Low Enriched U"
BONNEILLER, J. Region I, Philadelphia, Office of the Director 79/05/11 1p

790129083 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
BONNEILLER, J. Region I, Philadelphia, Office of the Director 79/05/18 1p

DOCKET 50-024 UNIV. OF CALIFORNIA RESEARCH REACTOR

9 Insurance & indemnity information

790129079 Forwards executed Amend 2 to Indemnity Agreement C-14, Amend 4 to Indemnity Agreement C-55, Amend 10 to Indemnity Agreement C-53 & Amend 12 to Indemnity Agreement C-15.
BONNEILLER, J. California, Univ. of Berkeley 79/05/24 3pp

8 Inspection reports, IE Bulletins & correspondence

790129074 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" RE written response necessary.
BONNEILLER, J. Region I, San Francisco, Office of the Director 79/05/10 1p

790129083 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
BONNEILLER, J. Region I, San Francisco, Office of the Director 79/05/18 1p

8 Periodic operating reports & related correspondence

790129083 Forwards Annual Operating Rept 1978
BONNEILLER, J. California, Univ. of Berkeley 79/05/25 1p

790129083 Annual Operating Rept 1978
BONNEILLER, J. California, Univ. of Berkeley 79/05/27 13pp

DOCKET 50-025 RPI CRITICAL EXPERIMENT

8 Inspection reports, IE Bulletins & correspondence

790129083 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
BONNEILLER, J. Region I, Philadelphia, Office of the Director 79/05/11 1p

790129089 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
BONNEILLER, J. Region I, Philadelphia, Office of the Director 79/05/18 1p

DOCKETED ITEMS

DOCKET 50-326 ADJUTANT RADIOGRAPHY & RESEARCH REACTOR0 Separation reports, IE Bulletin & correspondence

7904010445 Forwards IE info Notice 79-10, "Accepted Change to New Fuel Assembly" to written response necessary
ENGELSEN, R H Region 3, San Francisco, Office of the Director
7/9/81/10 1p

7904050413 Forwards IE Circular 79-08, "Accepted Extension - Low Enriched U"
ENGELSEN, R H Region 3, San Francisco, Office of the Director
7/9/81/10 1p

DOCKET 50-337 GREENH NUCLEAR POWER STATION, UNIT 20 Administrative correspondence

7904010131 Forwards 790316 order re shipment of spent fuel, admitting contamination similar to those at issue on present processing
ROTHMAN, A J Natural Resources Defense Council 7/9/81/05 1p

7904070346 Re: re standing & contentions of intervenors State of IL, AMEC & Citizens for Better Environments following 790301 special proceeding conference on spent fuel storage
MILHOLLAND, G L Atomic Safety and Licensing Board Panel 7/9/81/17 3pp

7904010387 Forwards representative mail prepared by Citizens for Better Environments & NRDC to disclose interest in issue of nuclear power
ROTHMAN, A J Natural Resources Defense Council 7/9/81/05 40pp

7904010387 Forwards representative mail prepared by Citizens for Better Environments & NRDC to disclose interest in issue of nuclear power
ROTHMAN, A J Natural Resources Defense Council 7/9/81/05 40pp

7904010327 Motion for reconsideration of 790419 memo & order following special proceeding conference Objects to admission of Contention & re specific threats to irradiated fuel in transit Certificate of Doc. no. 0030480, R J Branch 2 7/9/81/04 3pp

7904050329 Would not oppose admission of Contention & if revised to conform w/Contention & as admitted in Site Power proceeding re security of spent fuel in transit
0030480, R J Branch 2 7/9/81/04 3pp

7904050329 Would not oppose admission of Contention & if revised to conform w/Contention & as admitted in Site Power proceeding re security of spent fuel in transit
0030480, R J Branch 2 7/9/81/04 3pp

7904010329 Applicant motion for reconsideration of 790419 memo & order of Clarification of 790419 order re physical security of SNR supporting documentation & Certificate of Doc. no. 0030480, R J Branch 2 7/9/81/07 14pp

7904050302 Grants NRC 790504 motion suggesting alternative language for Contention & Denies intervenor motion to reconsider availability of Contention 8 & 11
MILHOLLAND, G L Atomic Safety and Licensing Board Panel 7/9/81/16 4pp

7904050465 Concludes NRC & Citizens for Better Environments have standing based on criteria of 42 USC 5332 But have established interest in nuclear power issues & are authorized to represent members in proceedings
MILHOLLAND, G L Atomic Safety and Licensing Board Panel 7/9/81/29 4pp

J Insurance & Intensity Information

7904060187 Forwards executed Amends 21, 11-V & 1 to Intensity Agreements 3-10, 8-07, 8-08 & 8-04, respectively
ROSE, R D Commonwealth Edison Co. 7/9/81/29 8pp.

P. Operating license stage documents & correspondence

7904070331 Requests to 790311 lit Requests sent info re review of proposed spent fuel pool and UOI should provide info within 90 days of receipt of lit.
EIDMAN, D L Operating Reactors Branch 2 (Prc 790623) 7/9/81/23 9pp

7904060188 Forwards Amend 43 to provisional License 098-19, safety evaluation & notice of issuance
EIDMAN, D L Operating Reactors Branch 2 (Prc 790623) 7/9/81/24 3pp

7904070310 Amend 43 to provisional License 098-19 authorizing operation w/1600 BWR R fuel assembly, incorporating revised operating limits to reflect plant specific analyses for Reload & 4 modifying License Condition 3
EIDMAN, D L Assistant Director for System Engineering 7/9/81/24 3pp

7904070310 Safety evaluation supporting Amend 43 to provisional License 098-19
Office of Nuclear Reactor Regulation 7/9/81/24 13pp

7904070313 Notice of Issuance & availability of Amend 43 to provisional License 098-19
EIDMAN, D L Operating Reactors Branch 2 (Prc 790623) 7/9/81/24 3pp

7904050309 Response to 790318 lit requesting add info re spent fuel storage at site nuclear power plants near Lake MI & forwards
15041 FBE letter for status briefing on Lake MI
OCHTAL, H J Office of Nuclear Reactor Regulation 7/9/81/25 7pp

7904050343 Requests to be notified when current requests for license amend to store add quantities of spent fuel at Rossmore
Point Beach Coal & Silo are granted
SOMMER, J Lake Michigan Federation 7/9/81/18 3pp

7904050329 Requests two controlled copies of site emergency plans & implementing procedures, site maps showing location & precise station number of onsite & offsite source monitoring stations & site maps used for dose determinations
EIDMAN, D L Region 3, Chicago, Office of the Director 7/9/81/17 1p

7904050363 Forwards draft evaluation of systematic evaluation program Topic 11-10 C re surveillance requirements on SNR recirculation pump discharge valves
EIDMAN, D L Operating Reactors Branch 2 (Prc 790623) 7/9/81/22 3pp

7904050371 Requests to NRC 790483 request for add info re spent fuel pool and Forwards spent fuel storage module suitability study (incl drawing available in Central Files only)
JANSEN, R F Commonwealth Edison Co 7/9/81/20 40pp

7904050320 Forwards "Reactor Containment Rld Integrated Leak Rate Test"
EIDMAN, D L Commonwealth Edison Co 7/9/81/12 1p

7904050320 "Reactor Containment Rld Integrated Leak Rate Test"
EIDMAN, D L Commonwealth Edison Co 7/9/81/21 30pp

7904050190 Requests inclusion in docket of NRC-21944-P, "One-Quarter Scale Pressure Expression Pool Swell Test Program Plant Union Tests."
JANSEN, R F Commonwealth Edison Co 7/9/81/15 1p

7904070326 Litte add systematic evaluation program topics that should be deleted from review re failure of underdrain sgs & internal requirements
JANSEN, R F Commonwealth Edison Co 7/9/81/22 1p

0 Inspection reports, IE Bulletin & correspondence

7904050147 Forwards IE Insp Repts 50-010/79-10, 50-237/79-10 & 30-249/79-08 on 790214-05 Re noncompliance noted
EIDMAN, D L Region 3, Chicago, Reactor Operations Nuclear Support Branch 7/9/81/25 8pp

7904050153 Re Insp Repts 50-010/79-10, 50-237/79-10 & 30-249/79-08 on 790214-05 Re noncompliance noted Major areas inspected
major activities, plant operations & physical protection & security organization
EIDMAN, D L, HOPKINS, M R, REYES, L A Region 3, Chicago, Office of the Director 7/9/81/22 9pp.

7904050165 Forwards IE Insp Repts 50-237/79-08 on 790214-05 & 0411-13 Re noncompliance noted.
EIDMAN, D L Region 3, Chicago, Reactor Construction & Engineering Support Branch 7/9/81/23 3pp.

DOCKETED ITEMS

--7904250172 IE Insp Repts 90-237/79-08 on 790329-03 & 0401-13 No noncompliance noted Major areas inspected: licensees surveillance of safety-related signage & standards including applicable procedures
VINI D T - DANIELSON, B Region 3, Chicago, Office of the Director 79/04/23 App

7904290470 Response to IE Bulletin 79-06 Forwarded info re review of IMI including existing line isolation not important to ECCC inspection
HILLMAN, P Commonwealth Edison Co 79/04/27 20pp

7904290620 Forwarded IE Insp Repts 90-237/79-11 & 90-249/79-09 on 790413.21-23 & 27 No noncompliance noted
HILLMAN, P Region 3, Chicago, Reactor Operations Nuclear Regulator Branch 79/05/02 2pp

--7904290623 IE Insp Repts 90-237/79-11 & 90-249/79-09 on 790413.21-23 & 27 No noncompliance noted Major areas inspected: integrated test test & license action on previously identified item of noncompliance
REYES, L A - BUTTENHEIMER, R - BIRKNER, J F Region 3, Chicago, Office of the Director 79/05/03 App

7904300302 Forwarded IE Info Notice 79-11, "Lower Reactor Vessel Head Isolation Report Problem" No action required
HILLMAN, P Region 3, Chicago, Office of the Director 79/05/07 1p

7904310101 Forwarded IE Bulletin 79-10, "Recertification Training Program Statistics" Written response required
HILLMAN, P Region 3, Chicago, Office of the Director 79/05/11 1p

7904320078 Forwarded IE Info Notice 79-12, "Attempted Damage to New Post Assemblies"
HILLMAN, P Region 3, Chicago, Office of the Director 79/05/11 1p

7904320018 Forwarded IE Circular 79-08, "Attempted Extension - Low Enriched U"
HILLMAN, P Region 3, Chicago, Office of the Director 79/05/18 1p

7904330032 Forwarded IE Bulletin 79-11, "Facility Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys - Licensee action required"
HILLMAN, P Region 3, Chicago, Office of the Director 79/05/22 1p

7904330075 Submit corrected copy of page 6 of Insp Repts 90-273/79-11 & 90-249/79-24
HILLMAN, P Region 3, Chicago, Reactor Operations Nuclear Regulator Branch 79/05/23 2pp

7904330082 Forwarded IE Info Notice 79-12, "Indication of Low Water Level in Outer Crank Reactor"
HILLMAN, P Region 3, Chicago, Office of the Director 79/05/29 1p

R Periodic operating reports & related correspondence

7904330206 Forward monthly operating report for May 1979
STEPHENSON, B Commonwealth Edison Co 79/06/11 1p

--7904330338 Monthly operating report for May 1979
OUREKHEVIC, S Commonwealth Edison Co 79/06/06 20pp

R Reportable occurrences, LEDs & related correspondence

7904330330 Forwarded IE Insp Repts 79-032/03L-0
STEPHENSON, B Commonwealth Edison Co 79/05/24, 1p

--7904330333 LER 79-032/03L-0 on 790506.02 line low temp alarm received & frost found on insulating line, 40-2-1001 & insulating line failed leak rate test Caused by failure of temp recorder at NG vaporizer
PARCELL Commonwealth Edison Co 79/05/28 1p

7904330343 Forwarded LER 79-032/03L-0
STEPHENSON, B Commonwealth Edison Co 79/05/30 1p

--7904330348 LER 79-032/03L-0 on 790501 intermediate range monitors in trip app found domains during red trip to backing power, resulting in manual half-power. Caused by faulty connector & loose input connector
HILLMAN, P Commonwealth Edison Co 79/05/30 1p

7904330348 Forwarded LER 79-032/03L-0
STEPHENSON, B Commonwealth Edison Co 79/05/30 1p

--7904330349 LER 79-032/03L-0 on 790502 during startup, main turbine isolation on high turbine level caused by jamming leak on isolation valve for 79-263-000 Parking adjusted, tested & app lines returned to normal
HILLMAN, P Commonwealth Edison Co 79/05/30 2pp

7904330378 LER 79-032 has been voided
Commonwealth Edison Co 79/06/01 1p

7904330393 LER 79-031 has been voided
Commonwealth Edison Co 79/06/01 1p

7904330397 LER 79-037 has been voided
Commonwealth Edison Co 79/06/01 1p

7904330401 LER 79-038 has been voided
Commonwealth Edison Co 79/06/01 1p

7904330410 Forwarded LER 79-039/03L-0
STEPHENSON, B Commonwealth Edison Co 79/06/03 1p

--7904330413 LER 79-039/03L-0 on 790508 200 1405-3 pressure switch 2-143D-14400 failed to trip Caused by wiring problem in pressure switch Switch removed, cleaned & reset to trip at 94.5 psig increasing
BOTH, D L Commonwealth Edison Co 79/06/03 1p

7904330440 Forwarded LER 79-039/03L-1
STEPHENSON, B Commonwealth Edison Co 79/06/03 1p

--7904330447 LER 79-039/03L-1 on 790503 during normal operation, HPCI turbine failed to start during quarterly flow test Caused by partial engagement of interlock dump valve operating lever Lever adjusted HPCI started to verify operability
PARCELL Commonwealth Edison Co 79/06/03 2pp

7904330474 Forwarded LER 79-031/03L-0
STEPHENSON, B Commonwealth Edison Co 79/06/07 1p

--7904330488 LER 79-031/03L-0 on 790509 crack found on 201 feedwater emergency spill to condenser line & crack located on pipe to condenser weld Caused by mechanical failure Cracked portion removed & resealed
JAMES, T Commonwealth Edison Co 79/06/07 1p

7904330475 Forwarded LER 79-034/03L-0
STEPHENSON, B Commonwealth Edison Co 79/06/12 1p

--7904330493 LER 79-034/03L-0 on 790503 diesel generator failed to start during operability test Caused by failure to engage of inner air start handle gear Over alignment will be checked after diesel generator starts
QUAM, J Commonwealth Edison Co 79/06/12 2pp

7904330498 Forwarded LER 79-041/03L-0
STEPHENSON, B Commonwealth Edison Co 79/06/15 1p

--7904330501 LER 79-041/03L-0 on 790506 200 rectification motor severe wet field circuit breaker tripped open Caused by failure of potential transformer in voltage regulator circuit
Transformer replaced
DUNHAM, J Commonwealth Edison Co 79/06/15 1p

7904330518 Forwarded LER 79-039/03L-0
STEPHENSON, B Commonwealth Edison Co 79/06/15 1p

--7904330530 LER 79-039/03L-0 on 790508 180 volt dc switch 2 reserve bus 22, was opened causing trip of 200 rectification motor generator wet oil pump Caused by inadvertent opening of switch Switch marked to caution against opening
ANNE, A Commonwealth Edison Co 79/06/15 1p

DOCKET NO-041 MISSISSIPPI STATE UNIV RESEARCH REACTOR

J Insurance & Indemnity Information

7904330574 Forwarded executed demand by re Indemnity Agreement E-46
PRICE, R Mississippi State Univ 79/05/27 2pp

DOCKETED ITEMS

DOCKET 50-243 SREDD STATE UNIV RESEARCH REACTOR

Q Inspection reports, IE Bulletin & correspondence

7704190431 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies - No written response necessary."
 ERNEST, R. H. Region 3, San Francisco, Office of the Director
 79/05/10 1p

7704090528 Forwards IE Circular 79-06, "Attempted Escalation - Low Enriched U"
 ERNEST, R. H. Region 3, San Francisco, Office of the Director
 79/05/18 1p

B Reportable occurrences, LERs & related correspondence

7704280532 FO on 770407 shutdown margin of TRIGA reactor was 40 CM, also 40% less than Tech Spec limitation of 40 27 Upon discovery, two fuel elements were moved to shutdown margin went up to 80 74
 MORGAN, C. H. Oregon State Univ. 79/04/19 7pp

DOCKET 50-244 ROBERT ERNET DUMA NUCLEAR PLANT, UNIT 3

P Security, medical, emergency & fire protection plans

7704080505 Forwards replacement page to security plan evaluation report supporting issuance of Amend 25 to license DPR-18 on 770502 Pages withheld (ref 50CFR 2361)
 ERNEST, R. H. Operating Reactors Branch 2 (PR 770428) 79/05/14 5pp

7704050272 Notifies replacement of temporary room ceiling is delayed until 770501
 WHITE, L. D. Rochester Gas & Electric Corp 79/06/14 1p

J Insurance & indemnity information

7704190306 Forwards Endorsements 49, 50 & 51 to MARU Policy 89-47 & Endorsements 50 & 51 of HD-18 Policy 89-170
 WHITE, L. D. Rochester Gas & Electric Corp 79/06/14 4pp

P Operating license shape documents & correspondence

7704260587 Summary of 770410-11 meeting w/ staff at site re systematic evaluation program Topic 11-4, seismic design
 SMITH, J. J. Operating Reactors Branch 2 (PR 770428) 79/04/20, 5pp

7704050339 Forwards Offsite Dose Calculation Manual
 WHITE, L. D. Rochester Gas & Electric Corp 79/05/29 1p

--7704050336 Offsite Dose Calculating Manual
 Rochester Gas & Electric Corp 79/05/28, 30pp

7704280404 Response to item 111-1 of NRC questions re design & construction for systematic evaluation program seismic review Discusses details of flood walls throughout plant, two overland drawings encl.
 WHITE, L. D. Rochester Gas & Electric Corp. 79/06/06, 2pp.

7704130593 Forwards application for amend to license DPR-18.
 FARRAR, R. A. Lathrop, Lamb, Leiby & MacLean. 79/05/11 4pp

7704290404 Notifies Revision 5 to Suppl IV of full-term license application will be submitted in early July as requested by NRC 770405 1p Revision & will include Reg Guide 1.74 New listing of ANSI code
 WHITE, L. D. Rochester Gas & Electric Corp 79/04/25 1p

Q Inspection reports, IE Bulletin & correspondence

7704280804 Forwards IE Insp Reps 50-244/79-05 on 770310-12 No nonconformities noted
 ERNEST, R. H. Region 3, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/20 5pp

--7704040309 IE Insp Reps 50-244/79-04 on 770310-12 No nonconformities noted. Major areas inspected: witness of core related activities, witness of refueling activities & review of pipe support & restraint surveillance program
 ERNEST, R. H. Region 3, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/20 11pp

7704110404 Forwards IE Bulletin 79-08, "Nuclear Incident at 501-Suppl." No written response required
 ERNEST, R. H. Region 3, Philadelphia, Office of the Director 79/04/20 1p

7704280404 Responds to IE Bulletin 79-07 re seismic stress analysis of safety-related piping. Confirms capability of plant to withstand seismic event
 WHITE, L. D. Rochester Gas & Electric Corp 79/04/20 4pp

7704050207 Responds to IE Bulletin 79-06A & 79-06A, Revision 1, "Review of Operational Groups & Key Missions Identified During 10-2 Incident." Plant procedures are being reviewed & updated
 WHITE, L. D. Rochester Gas & Electric Corp 79/04/28 17pp

7704070201 Forwards response to IE Bulletin 79-04, "Incorrect Heights for Relief Valves NRC by Valves Engineering Corp." Valves used in safety-related app are in close proximity to pipe supports. No mods planned
 WHITE, L. D. Rochester Gas & Electric Corp 79/04/30 5pp.

7704130201 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Examination Support Problem." No action required
 ERNEST, R. H. Region 3, Philadelphia, Office of the Director 79/05/07, 2pp

7704110149 Forwards IE Bulletin 79-09, "Regulification Training Program Disturbances." Written response required
 ERNEST, R. H. Region 3, Philadelphia, Office of the Director 79/05/11 1p

7704050101 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
 ERNEST, R. H. Region 3, Philadelphia, Office of the Director 79/05/11 1p.

7704050104 Forwards IE Circular 79-06, "Attempted Escalation - Low Enriched U"
 ERNEST, R. H. Region 3, Philadelphia, Office of the Director 79/05/18 1p

7704070203 Responds to IE Bulletin 79-06A & 79-06A, Revision 1. No Tech Spec changes required at Unit 150. Change will be requested when design & safety evaluations are prepared.
 WHITE, L. D. Rochester Gas & Electric Corp 79/05/10 1p

B Reportable occurrences, LERs & related correspondence

7704050403 Confirms 770428 action to M. Raymond regarding LER-79-09, borate acid storage tanks out of spec per vol & weight of borate acid. Orderly load reduction & backing operations commenced tanks within specs.
 ERNEST, R. A. Rochester Gas & Electric Corp 79/04/16 1p

7704050501 Confirms 770428 action w/ Lathrop re LER 79-10, borate acid storage tanks out-of-spec per vol & weight. Orderly load reduction initiated by refueling tanks to required specs.
 ERNEST, R. A. Rochester Gas & Electric Corp. 79/04/20, 1p

7704290505 Confirms 770510 discussion w/ D. Becker re LER 79-011. New valve internals being mfg to correct problem will be available in June
 ERNEST, R. A. Rochester Gas & Electric Corp. 79/05/11, 1p.

7704280523 Forwards LER 79-010/017-0.
 WHITE, L. D. Rochester Gas & Electric Corp 79/04/20 1p.

DOCKETED ITEMS

23

--7904290293 LER 79-02/011-0 Rev. 790406 during inservice insp. identified piping supports for safety equipment not built per Tech Spec 3.4.2.1. Cause: by inadequate control on test installation. Support corrected.
BODINE, J. C. Rochester Gas & Electric Corp. 79/04/20 App

DOCKET 50-045 HOLISTONE NUCLEAR POWER STATION, UNIT 1

I. Financial Information

7904050374 Forwards annual financial report for semi-licensed
O'CONNOR, L. A. Northeast Utilities 79/04/19 App

--7904290373 Annual Financial Report 1978
* Western Massachusetts Electric Co. 79/12/21 12pp

--7904290374 Annual Financial Report 1978
* Hartford Electric Light Co. 79/12/21 21pp

--7904290375 Annual Financial Report 1978
* Connecticut Light & Power Co. 79/12/21 21pp

J. Insurance & Indemnity Information

7904190292 Forwards Endorsements 54 & 55 to RWGLU Policy 79-32
COMBELL, T. Northeast Nuclear Energy Co. (Northeast Utilities)
79/04/12 App

7904270241 Forwards Endorsements 59 & 60 to HDL&A Policy 79-173
SEIGER, R. H. Northeast Nuclear Energy Co. (Northeast Utilities)
79/04/21 App

7904290291 Forwards Endorsements 79 & 80 to AHC Policy 79-172
SEIGER, R. H. Northeast Utilities 79/04/21 App

P. Operating license stage documents & correspondence

7904290308 Forwards Mar 1979 "Thermal Flume Study"
COMBELL, T. G. Northeast Utilities 79/04/19 App

--7904290306 "Thermal Flume Study," Mar 1979
* Northeast Utilities 79/03/21 25pp

7904290366 Notification of 790317-18 meeting w/Unit 1 to discuss
systematic evaluation program Topic 112-0, A. "Effects of
Pipe Break on Structures, Piping & Components Inside
Containment"
BODINE, J. C. Operating Reactors Branch 2 (Pir 790425) 79/04/20
App

7904290254 Requests HSB-21878-P, "Mark II Containment Program," be
included in docket Regs transmitted by GE on 790426
COMBELL, T. G. Northeast Utilities 79/04/20 App

7904290302 Forwards Amend 61 to License 50-045 safety evaluation &
notice of issuance & availability
1189990, D. L. Operating Reactors Branch 2 (Pir 790425) 79/03/29
App

--7904290308 Amend 61 to License 50-045 authorizing use of 148 Rb88 kgps
Test Assembly, changing safety limit min critical power
ratio to 1.07 & changing max average planar linear heat
generation limits
VELLIER, R. H. Assistant Director for System Engineering
79/03/29 App

--7904290309 Safety evaluation supporting Amend 61 to License 50-045
* Operating Reactors Branch 2 (Pir 790425) 79/03/29 11pp

--7904290301 Notice of issuance & availability of Amend 61 to License
50-045
1189990, D. L. Operating Reactors Branch 2 (Pir 790425)
79/03/29 App

7904290312 Submittal agenda & other info re 790609-09 meeting as
systematic evaluation program Topic 112-0, "Reactor Design"
Forwards draft "Reactor Design of Unit for Systematic
Evaluation Program"
1189990, D. L. Operating Reactors Branch 2 (Pir 790425) 79/03/20
11pp

--7904290314 Draft "Reactor Design of Unit for Systematic Evaluation
Program Phase 1 Report"
* Office of Nuclear Reactor Regulation 79/03/13 180pp

7904190337 Response to NRC 790410 ltr re systematic evaluation program
Topic 112-0 A, station testing testing Draft assessment of
plant surveillance requirements is substantially correct
COMBELL, T. G. Northeast Utilities 79/04/20 App

D. Inspection reports, IE Bulletins & correspondence

7904190403 Forwards 2E Insp Repts 50-045/79-01 & 50-034/79-02 on
791105-1207 No noncompliance noted
BODINE, J. C. Region 1, Philadelphia, Office of the Director
79/03/21 App

--7904290407 IE Insp Repts 50-045/79-01 & 50-034/79-02 on 791106-1207 No
noncompliance noted Major areas inspected accessible
portions of Unit 1 reactor-turbine & reactor bldg, Unit 2
auxiliary & turbine bldg & radiation protection
BODINE, J. C. Region 1, Philadelphia, Office of the Director
MOORE, E. C. Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 79/03/20 25pp

7904040371 Response to IE Bulletin 79-02 re AHC 50-045 stainless steel
pipe mfg by Towner-Helding & Engineering Co. Piping mfg
in use or planned for use
COMBELL, T. G. Northeast Utilities 79/04/19 App

7904290504 Forwards IE Insp Repts 50-045/79-04 & 50-036/79-02 on
790210-0314 No noncompliance noted
BODINE, J. C. Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 79/04/19 App

--7904290501 IE Insp Repts 50-045/79-04 & 50-036/79-02 on 790210-0314 No
noncompliance noted Major areas inspected accessible
portions of Unit 1 reactor, turbine & reactor bldg, Unit 2
auxiliary & turbine bldg & radiation protection
BODINE, J. C. Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 79/04/19 App

7904190411 Forwards IE Bulletin 79-05, "Nuclear Incident at
TMI-Beggs" No written response required
BODINE, J. C. Region 1, Philadelphia, Office of the Director
79/04/20 App

7904290402 Response to IE Bulletin 79-07 re seismic stress analyses of
seismic-related piping. Seismic design methods will be
verified by NRC within framework of systematic evaluation
program.
COMBELL, T. G. Northeast Utilities 79/04/24 App

7904290481 Response to IE Bulletin 79-08, "Review of Operational
Errors & Size Mismatches Identified During The Incident"
Reactor vessel water in BWR is continuously monitored by
seven indicators on recorders
COMBELL, T. G. Northeast Utilities 79/04/24 App

7904140222 Response to IE Bulletin 79-09, "Intermittent Heights Per Rising
Check Valves Mfg by Velan Engineering Corp." Three seismic
Category I piping app. test valves. No obvious
discrepancies exist re valve weights
COMBELL, T. G. Northeast Utilities 79/04/20 App

7904290484 Forwards IE Circular 79-09, "Unrecognized Rapid Increase of
Reactor Power Generator Set Resulted in Reactor Power
Increase" No written response required
BODINE, J. C. Region 1, Philadelphia, Office of the Director
79/04/20 App

7904190302 Ack receipt of 790412 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-045/79-03 &
50-034/79-03
BODINE, J. C. Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch 79/05/03 App

--7904190302 Response to NRC 790320 ltr re violations noted in IE Insp
Repts 50-045/79-03 & 50-034/79-03 re Corroductive actions 2M-P1,
2M-P2, 2M-P3, 2M-P4, 2M-P5, 2M-P6, 2M-P7, 2M-P8, 2M-P9, 2M-P10,
2M-P11, 2M-P12, 2M-P13, 2M-P14, 2M-P15, 2M-P16, 2M-P17,
2M-P18, 2M-P19, 2M-P20, 2M-P21, 2M-P22, 2M-P23, 2M-P24,
2M-P25, 2M-P26, 2M-P27, 2M-P28, 2M-P29, 2M-P30, 2M-P31,
2M-P32, 2M-P33, 2M-P34, 2M-P35, 2M-P36, 2M-P37, 2M-P38,
2M-P39, 2M-P40, 2M-P41, 2M-P42, 2M-P43, 2M-P44, 2M-P45,
2M-P46, 2M-P47, 2M-P48, 2M-P49, 2M-P50, 2M-P51, 2M-P52,
2M-P53, 2M-P54, 2M-P55, 2M-P56, 2M-P57, 2M-P58, 2M-P59,
2M-P60, 2M-P61, 2M-P62, 2M-P63, 2M-P64, 2M-P65, 2M-P66,
2M-P67, 2M-P68, 2M-P69, 2M-P70, 2M-P71, 2M-P72, 2M-P73,
2M-P74, 2M-P75, 2M-P76, 2M-P77, 2M-P78, 2M-P79, 2M-P80,
2M-P81, 2M-P82, 2M-P83, 2M-P84, 2M-P85, 2M-P86, 2M-P87,
2M-P88, 2M-P89, 2M-P90, 2M-P91, 2M-P92, 2M-P93, 2M-P94,
2M-P95, 2M-P96, 2M-P97, 2M-P98, 2M-P99, 2M-P100, 2M-P101,
2M-P102, 2M-P103, 2M-P104, 2M-P105, 2M-P106, 2M-P107,
2M-P108, 2M-P109, 2M-P110, 2M-P111, 2M-P112, 2M-P113,
2M-P114, 2M-P115, 2M-P116, 2M-P117, 2M-P118, 2M-P119,
2M-P120, 2M-P121, 2M-P122, 2M-P123, 2M-P124, 2M-P125,
2M-P126, 2M-P127, 2M-P128, 2M-P129, 2M-P130, 2M-P131,
2M-P132, 2M-P133, 2M-P134, 2M-P135, 2M-P136, 2M-P137,
2M-P138, 2M-P139, 2M-P140, 2M-P141, 2M-P142, 2M-P143,
2M-P144, 2M-P145, 2M-P146, 2M-P147, 2M-P148, 2M-P149,
2M-P150, 2M-P151, 2M-P152, 2M-P153, 2M-P154, 2M-P155,
2M-P156, 2M-P157, 2M-P158, 2M-P159, 2M-P160, 2M-P161,
2M-P162, 2M-P163, 2M-P164, 2M-P165, 2M-P166, 2M-P167,
2M-P168, 2M-P169, 2M-P170, 2M-P171, 2M-P172, 2M-P173,
2M-P174, 2M-P175, 2M-P176, 2M-P177, 2M-P178, 2M-P179,
2M-P180, 2M-P181, 2M-P182, 2M-P183, 2M-P184, 2M-P185,
2M-P186, 2M-P187, 2M-P188, 2M-P189, 2M-P190, 2M-P191,
2M-P192, 2M-P193, 2M-P194, 2M-P195, 2M-P196, 2M-P197,
2M-P198, 2M-P199, 2M-P200, 2M-P201, 2M-P202, 2M-P203,
2M-P204, 2M-P205, 2M-P206, 2M-P207, 2M-P208, 2M-P209,
2M-P210, 2M-P211, 2M-P212, 2M-P213, 2M-P214, 2M-P215,
2M-P216, 2M-P217, 2M-P218, 2M-P219, 2M-P220, 2M-P221,
2M-P222, 2M-P223, 2M-P224, 2M-P225, 2M-P226, 2M-P227,
2M-P228, 2M-P229, 2M-P230, 2M-P231, 2M-P232, 2M-P233,
2M-P234, 2M-P235, 2M-P236, 2M-P237, 2M-P238, 2M-P239,
2M-P240, 2M-P241, 2M-P242, 2M-P243, 2M-P244, 2M-P245,
2M-P246, 2M-P247, 2M-P248, 2M-P249, 2M-P250, 2M-P251,
2M-P252, 2M-P253, 2M-P254, 2M-P255, 2M-P256, 2M-P257,
2M-P258, 2M-P259, 2M-P260, 2M-P261, 2M-P262, 2M-P263,
2M-P264, 2M-P265, 2M-P266, 2M-P267, 2M-P268, 2M-P269,
2M-P270, 2M-P271, 2M-P272, 2M-P273, 2M-P274, 2M-P275,
2M-P276, 2M-P277, 2M-P278, 2M-P279, 2M-P280, 2M-P281,
2M-P282, 2M-P283, 2M-P284, 2M-P285, 2M-P286, 2M-P287,
2M-P288, 2M-P289, 2M-P290, 2M-P291, 2M-P292, 2M-P293,
2M-P294, 2M-P295, 2M-P296, 2M-P297, 2M-P298, 2M-P299,
2M-P300, 2M-P301, 2M-P302, 2M-P303, 2M-P304, 2M-P305,
2M-P306, 2M-P307, 2M-P308, 2M-P309, 2M-P310, 2M-P311,
2M-P312, 2M-P313, 2M-P314, 2M-P315, 2M-P316, 2M-P317,
2M-P318, 2M-P319, 2M-P320, 2M-P321, 2M-P322, 2M-P323,
2M-P324, 2M-P325, 2M-P326, 2M-P327, 2M-P328, 2M-P329,
2M-P330, 2M-P331, 2M-P332, 2M-P333, 2M-P334, 2M-P335,
2M-P336, 2M-P337, 2M-P338, 2M-P339, 2M-P340, 2M-P341,
2M-P342, 2M-P343, 2M-P344, 2M-P345, 2M-P346, 2M-P347,
2M-P348, 2M-P349, 2M-P350, 2M-P351, 2M-P352, 2M-P353,
2M-P354, 2M-P355, 2M-P356, 2M-P357, 2M-P358, 2M-P359,
2M-P360, 2M-P361, 2M-P362, 2M-P363, 2M-P364, 2M-P365,
2M-P366, 2M-P367, 2M-P368, 2M-P369, 2M-P370, 2M-P371,
2M-P372, 2M-P373, 2M-P374, 2M-P375, 2M-P376, 2M-P377,
2M-P378, 2M-P379, 2M-P380, 2M-P381, 2M-P382, 2M-P383,
2M-P384, 2M-P385, 2M-P386, 2M-P387, 2M-P388, 2M-P389,
2M-P390, 2M-P391, 2M-P392, 2M-P393, 2M-P394, 2M-P395,
2M-P396, 2M-P397, 2M-P398, 2M-P399, 2M-P400, 2M-P401,
2M-P402, 2M-P403, 2M-P404, 2M-P405, 2M-P406, 2M-P407,
2M-P408, 2M-P409, 2M-P410, 2M-P411, 2M-P412, 2M-P413,
2M-P414, 2M-P415, 2M-P416, 2M-P417, 2M-P418, 2M-P419,
2M-P420, 2M-P421, 2M-P422, 2M-P423, 2M-P424, 2M-P425,
2M-P426, 2M-P427, 2M-P428, 2M-P429, 2M-P430, 2M-P431,
2M-P432, 2M-P433, 2M-P434, 2M-P435, 2M-P436, 2M-P437,
2M-P438, 2M-P439, 2M-P440, 2M-P441, 2M-P442, 2M-P443,
2M-P444, 2M-P445, 2M-P446, 2M-P447, 2M-P448, 2M-P449,
2M-P450, 2M-P451, 2M-P452, 2M-P453, 2M-P454, 2M-P455,
2M-P456, 2M-P457, 2M-P458, 2M-P459, 2M-P460, 2M-P461,
2M-P462, 2M-P463, 2M-P464, 2M-P465, 2M-P466, 2M-P467,
2M-P468, 2M-P469, 2M-P470, 2M-P471, 2M-P472, 2M-P473,
2M-P474, 2M-P475, 2M-P476, 2M-P477, 2M-P478, 2M-P479,
2M-P480, 2M-P481, 2M-P482, 2M-P483, 2M-P484, 2M-P485,
2M-P486, 2M-P487, 2M-P488, 2M-P489, 2M-P490, 2M-P491,
2M-P492, 2M-P493, 2M-P494, 2M-P495, 2M-P496, 2M-P497,
2M-P498, 2M-P499, 2M-P500, 2M-P501, 2M-P502, 2M-P503,
2M-P504, 2M-P505, 2M-P506, 2M-P507, 2M-P508, 2M-P509,
2M-P510, 2M-P511, 2M-P512, 2M-P513, 2M-P514, 2M-P515,
2M-P516, 2M-P517, 2M-P518, 2M-P519, 2M-P520, 2M-P521,
2M-P522, 2M-P523, 2M-P524, 2M-P525, 2M-P526, 2M-P527,
2M-P528, 2M-P529, 2M-P530, 2M-P531, 2M-P532, 2M-P533,
2M-P534, 2M-P535, 2M-P536, 2M-P537, 2M-P538, 2M-P539,
2M-P540, 2M-P541, 2M-P542, 2M-P543, 2M-P544, 2M-P545,
2M-P546, 2M-P547, 2M-P548, 2M-P549, 2M-P550, 2M-P551,
2M-P552, 2M-P553, 2M-P554, 2M-P555, 2M-P556, 2M-P557,
2M-P558, 2M-P559, 2M-P560, 2M-P561, 2M-P562, 2M-P563,
2M-P564, 2M-P565, 2M-P566, 2M-P567, 2M-P568, 2M-P569,
2M-P570, 2M-P571, 2M-P572, 2M-P573, 2M-P574, 2M-P575,
2M-P576, 2M-P577, 2M-P578, 2M-P579, 2M-P580, 2M-P581,
2M-P582, 2M-P583, 2M-P584, 2M-P585, 2M-P586, 2M-P587,
2M-P588, 2M-P589, 2M-P590, 2M-P591, 2M-P592, 2M-P593,
2M-P594, 2M-P595, 2M-P596, 2M-P597, 2M-P598, 2M-P599,
2M-P600, 2M-P601, 2M-P602, 2M-P603, 2M-P604, 2M-P605,
2M-P606, 2M-P607, 2M-P608, 2M-P609, 2M-P610, 2M-P611,
2M-P612, 2M-P613, 2M-P614, 2M-P615, 2M-P616, 2M-P617,
2M-P618, 2M-P619, 2M-P620, 2M-P621, 2M-P622, 2M-P623,
2M-P624, 2M-P625, 2M-P626, 2M-P627, 2M-P628, 2M-P629,
2M-P630, 2M-P631, 2M-P632, 2M-P633, 2M-P634, 2M-P635,
2M-P636, 2M-P637, 2M-P638, 2M-P639, 2M-P640, 2M-P641,
2M-P642, 2M-P643, 2M-P644, 2M-P645, 2M-P646, 2M-P647,
2M-P648, 2M-P649, 2M-P650, 2M-P651, 2M-P652, 2M-P653,
2M-P654, 2M-P655, 2M-P656, 2M-P657, 2M-P658, 2M-P659,
2M-P660, 2M-P661, 2M-P662, 2M-P663, 2M-P664, 2M-P665,
2M-P666, 2M-P667, 2M-P668, 2M-P669, 2M-P670, 2M-P671,
2M-P672, 2M-P673, 2M-P674, 2M-P675, 2M-P676, 2M-P677,
2M-P678, 2M-P679, 2M-P680, 2M-P681, 2M-P682, 2M-P683,
2M-P684, 2M-P685, 2M-P686, 2M-P687, 2M-P688, 2M-P689,
2M-P690, 2M-P691, 2M-P692, 2M-P693, 2M-P694, 2M-P695,
2M-P696, 2M-P697, 2M-P698, 2M-P699, 2M-P700, 2M-P701,
2M-P702, 2M-P703, 2M-P704, 2M-P705, 2M-P706, 2M-P707,
2M-P708, 2M-P709, 2M-P710, 2M-P711, 2M-P712, 2M-P713,
2M-P714, 2M-P715, 2M-P716, 2M-P717, 2M-P718, 2M-P719,
2M-P720, 2M-P721, 2M-P722, 2M-P723, 2M-P724, 2M-P725,
2M-P726, 2M-P727, 2M-P728, 2M-P729, 2M-P730, 2M-P731,
2M-P732, 2M-P733, 2M-P734, 2M-P735, 2M-P736, 2M-P737,
2M-P738, 2M-P739, 2M-P740, 2M-P741, 2M-P742, 2M-P743,
2M-P744, 2M-P745, 2M-P746, 2M-P747, 2M-P748, 2M-P749,
2M-P750, 2M-P751, 2M-P752, 2M-P753, 2M-P754, 2M-P755,
2M-P756, 2M-P757, 2M-P758, 2M-P759, 2M-P760, 2M-P761,
2M-P762, 2M-P763, 2M-P764, 2M-P765, 2M-P766, 2M-P767,
2M-P768, 2M-P769, 2M-P770, 2M-P771, 2M-P772, 2M-P773,
2M-P774, 2M-P775, 2M-P776, 2M-P777, 2M-P778, 2M-P779,
2M-P780, 2M-P781, 2M-P782, 2M-P783, 2M-P784, 2M-P785,
2M-P786, 2M-P787, 2M-P788, 2M-P789, 2M-P790, 2M-P791,
2M-P792, 2M-P793, 2M-P794, 2M-P795, 2M-P796, 2M-P797,
2M-P798, 2M-P799, 2M-P800, 2M-P801, 2M-P802, 2M-P803,
2M-P804, 2M-P805, 2M-P806, 2M-P807, 2M-P808, 2M-P809,
2M-P810, 2M-P811, 2M-P812, 2M-P813, 2M-P814, 2M-P815,
2M-P816, 2M-P817, 2M-P818, 2M-P819, 2M-P820, 2M-P821,
2M-P822, 2M-P823, 2M-P824, 2M-P825, 2M-P826, 2M-P827,
2M-P828, 2M-P829, 2M-P830, 2M-P831, 2M-P832, 2M-P833,
2M-P834, 2M-P835, 2M-P836, 2M-P837, 2M-P838, 2M-P839,
2M-P840, 2M-P841, 2M-P842, 2M-P843, 2M-P844, 2M-P845,
2M-P846, 2M-P847, 2M-P848, 2M-P849, 2M-P850, 2M-P851,
2M-P852, 2M-P853, 2M-P854, 2M-P855, 2M-P856, 2M-P857,
2M-P858, 2M-P859, 2M-P860, 2M-P861, 2M-P862, 2M-P863,
2M-P864, 2M-P865, 2M-P866, 2M-P867, 2M-P868, 2M-P869,
2M-P870, 2M-P871, 2M-P872, 2M-P873, 2M-P874, 2M-P875,
2M-P876, 2M-P877, 2M-P878, 2M-P879, 2M-P880, 2M-P881,
2M-P882, 2M-P883, 2M-P884, 2M-P885, 2M-P886, 2M-P887,
2M-P888, 2M-P889, 2M-P890, 2M-P891, 2M-P892, 2M-P893,
2M-P894, 2M-P895, 2M-P896, 2M-P897, 2M-P898, 2M-P899,
2M-P900, 2M-P901, 2M-P902, 2M-P903, 2M-P904, 2M-P905,
2M-P906, 2M-P907, 2M-P908, 2M-P909, 2M-P910, 2M-P911,
2M-P912, 2M-P913, 2M-P914, 2M-P915, 2M-P916, 2M-P917,
2M-P918, 2M-P919, 2M-P920, 2M-P921, 2M-P922, 2M-P923,
2M-P924, 2M-P925, 2M-P926, 2M-P927, 2M-P928, 2M-P929,
2M-P930, 2M-P931, 2M-P932, 2M-P933, 2M-P934, 2M-P935,
2M-P936, 2M-P937, 2M-P938, 2M-P939, 2M-P940, 2M-P941,
2M-P942, 2M-P943, 2M-P944, 2M-P945, 2M-P946, 2M-P947,
2M-P948, 2M-P949, 2M-P950, 2M-P951, 2M-P952, 2M-P953,
2M-P954, 2M-P955, 2M-P956, 2M-P957, 2M-P958, 2M-P959,
2M-P960, 2M-P961, 2M-P962, 2M-P963, 2M-P964, 2M-P965,
2M-P966, 2M-P967, 2M-P968, 2M-P969, 2M-P970, 2M-P971,
2M-P972, 2M-P973, 2M-P974, 2M-P975, 2M-P976, 2M-P977,
2M-P978, 2M-P979, 2M-P980, 2M-P981, 2M-P982, 2M-P983,
2M-P984, 2M-P985, 2M-P986, 2M-P987, 2M-P988, 2M-P989,
2M-P990, 2M-P991, 2M-P992, 2M-P993, 2M-P994, 2M-P995,
2M-P996, 2M-P997, 2M-P998, 2M-P999, 2M-P1000, 2M-P1001,
2M-P1002, 2M-P1003, 2M-P1004, 2M-P1005, 2M-P1006, 2M-P1007,
2M-P1008, 2M-P1009, 2M-P1010, 2M-P1011, 2M-P1012, 2M-P1013,
2M-P1014, 2M-P1015, 2M-P1016, 2M-P1017, 2M-P1018, 2M-P1019,
2M-P1020, 2M-P1021, 2M-P1022, 2M-P1023, 2M-P1024, 2M-P1025,
2M-P1026, 2M-P1027, 2M-P1028, 2M-P1029, 2M-P1030, 2M-P1031,
2M-P1032, 2M-P1033, 2M-P1034, 2M-P1035, 2M-P1036, 2M-P1037,
2M-P1038, 2M-P1039, 2M-P1040, 2M-P1041, 2M-P1042, 2M-P1043,
2M-P1044, 2M-P1045, 2M-P1046, 2M-P1047, 2M-P1048, 2M-P1049,
2M-P1050, 2M

DOCKETED ITEMS

--7906150210 IE Insp Repts 30-045/79-03 & 50-034/79-03 on 790312-13
Noncompliance noted failure to post radioactive waste
storage signs as required
YAMAS, R. H. CROCKFORD, M. W. Region 1, Philadelphia: Fuel Facility
& Materials Safety Branch 79/03/16 App

7906102470 Forwarded IE Info Notice 79-10, "Lower Reactor Vessel Head
Insulation Support Problem - No action required"
OHLER, B. H. Region 1, Philadelphia: Office of the Director
79/03/07 App

7906102520 Forwarded IE Bulletin 77-10, "Regelification Training
Program Evaluation - Written response required"
OHLER, B. H. Region 1, Philadelphia: Office of the Director
79/03/11 App

7906102624 Forwarded IE Info Notice 79-10, "Attempted Damage to New Fuel
Assemblies"
OHLER, B. H. Region 1, Philadelphia: Office of the Director
79/03/11 App

7906102697 Forwarded IE Circular 79-08, "Attempted Embrittlement - Low
Enriched U"
OHLER, B. H. Region 1, Philadelphia: Office of the Director
79/03/08 App

7906103008 Forwarded addl response to IE Bulletin 79-02 re seismic
stress analysis of safety-related piping arrangements
performance for max calculation stresses & restraint loading
of safety-related piping
COUNELL, M. O. Northeast Utilities 79/04/04 App

7906103082 Forwarded addl response to IE Bulletin 79-02 re note to
control rod drive exhaust line & 1-CSD bypass line
gaging data found acceptable for combined use
COUNELL, M. O. Northeast Utilities 79/04/15 App

R. Periodic operating reports & related correspondence

7906103552 Forwarded monthly operating report for May 1979
OHLER, B. H. Northeast Utilities 79/05/01 App

--7906103557 Monthly operating report for May 1979
OHLER, B. H. Northeast Utilities 79/05/08 App

R. Reportable occurrences, LERs & related correspondence

7906104010 Forwarded 80-78-7/25.
PERLA, M. J. Northeast Nuclear Energy Co. (Northeast Utilities)
78/04/23 App

--7906104034 80-78-7/25, on 790403 while performing surveillance system
tunnel high temp functions & callout on steam tunnel temp
switches; one switch tripped at setpoint higher than that
specified in Tech Spec. Caused by signal drift
PROMBER, P. J. Northeast Nuclear Energy Co. (Northeast Utilities)
78/04/25 App

7906104035 80-78-20/1P on 790504 during normal plant operation; unused
chloride capacity of one full flow on line demineralizer
was less than 30 lb min
OHLER, B. H. Northeast Utilities 78/10/10 App

7906104034 Canister 80-78-20/1P submitted on 78/01/10 Unused chloride
capacity of full flow demineralizer meets Tech Spec
requirements
OHLER, B. H. Northeast Utilities 78/10/11 App

7906104037 Forwarded LER 79-082/03L-0
OHLER, B. H. Northeast Utilities 79/04/08 App

--7906104062 LER 79-013/03L-0 on 790508 oxygen pressure 403 B check for
source range monitors not completed for 24-h period
Surveillance overwatched Checklist added to indicate
requirement of procedure
YOUNG, R. H. Northeast Utilities 79/04/03 App

7906104058 Forwarded LER 79-084/03L-0
OHLER, B. H. Northeast Utilities 79/04/07 App

--7906104041 LER 79-014/03L-0 on 790311 during audit of refuel outage
surveillance; source range monitor functional surveillance
was inadequately monitored Caused by failure of monitor
functional to be listed in refueling checklist.
YOUNG, R. H. Northeast Utilities 79/04/07 App

7906104038 Submit addl info to LER 79-04/03L Control rod 22-07
calculated inoperable on 79/03/28 fragments of broken
source holder were retrieved All fragments have been
removed
OHLER, B. H. Northeast Utilities 79/04/14 App

7906104042 Forwarded LER 79-013/03L-0
OHLER, B. H. Northeast Utilities 79/04/23 App

--7906104053 LER 79-013/03L-0 on 790328 during refueling; no control rod
autolock occurred when refuel bridge was never done without
assembly loaded people caused by worn track limit switch
Switch replaced & surveillance procedure changed
YOUNG, R. H. Northeast Utilities 79/04/22 App

DOCKET 50-247 INDIAN POINT STATION UNIT 2

C. Utility Environmental Report (ER): amend & correspondence

7906104055 Forwarded 1976 Year-Class Report for Multistage Impact Study of
Hudson River Estuary - Affidavit of Doc. ent
ZAMKAS, P. Consolidated Edison Co. of New York 79/04/15 App

--7906104057 1976 Year-Class Report for Multistage Impact Study of H. R.
River Estuary - prepared by 15 Instruments
P. Consolidated Edison Co. of New York 79/05/31 500pp

F. Security, medical, emergency & fire protection plans

7906104059 Act receipt of 790327 revised emergency plan Requests Class
115 Rev
MILNER, M. C. License Fee Management Branch 79/05/03 App

7906104287 Response to 790508 for forwarding \$4,400 filing fee for
revised emergency plan Payment made under protest Utility
reserves right to challenge validity of fees
COUNELL, M. O. Consolidated Edison Co. of New York 79/04/31 App

J. Insurance & indemnity information

7906104054 Notification of receipt of complaint served on Westinghouse
alleging bodily injury to utility employee J. O'Halloran, who was
injured while working under a 790512 flag under way
ALTMAN, L. American Nuclear Insurance 79/04/14 App

7906104053 Forwarded Amend 25 to Indemnity Agreement B-15
OHLER, B. H. Consolidated Edison Co. of New York 79/04/18 App

F. Operating license stage documents & correspondence

7906104045 Requester facility participate in vital area analysis &
schedule site visit during unit of 790504
OHLER, B. H. Operating Reactors Branch 1 (Pro 790425) 79/04/18
App

7906104035 Summary of 790508 meeting w/Consolidated Edison Co. of NY &
Power Authority of State of NY re auxiliary feedwater sys &
related status issues
ALTMAN, L. Operating Reactors Branch 1 (Pro 790425) 79/04/18
App

7906104041 Notification of 790502 meeting w/Consolidated Edison Co. of
NY & Power Authority of NY to discuss seismic analysis &
callout by 790507
ALTMAN, L. Operating Reactors Branch 1 (Pro 790425) 79/05/17
App

7906104043 Summary actions taken as result of 790325 conference call
re support adequacy for piping sys. Analysis of 48 supports
indicated acceptability; w/units well within allowable
limits
OHLER, B. H. Consolidated Edison Co. of New York 79/05/28 App

7906104055 Forwarded Westinghouse report, "Fracture Toughness & Design
Considerations for Addressing Lamellar Tearing of Steam
Generator & Reactor Coolant Support Head" - Report withheld
(ref 10CFR2 790)
OHLER, B. H. Consolidated Edison Co. of New York 79/05/28 App

--7906104051 Requester withholding from public disclosure of UT28 system
to NRC request for info re fracture toughness & potential
for tearing of steam generator & reactor coolant pipe
support metal
MILNER, M. A. Westinghouse Electric Corp. 79/04/24 App

7904000129 Forwards application for amend to License OPR-26
24WAKAD.P Consolidated Edison Co of New York 79/06/04 App

7904000133 Application for amend to License OPR-26 changing Test Space
to permit saving turbine stop & control rod lifetime test
during and after start-up operation
* Consolidated Edison Co of New York 79/04/04 App

7904000145 Forwards "Efficiency of One Square Meter Epithelial Aired
for Collecting Young-of-the-Year Striped Bass, White Perch &
Atlantic Tomcod in Hudson River Estuary, 1978"
W.H. Jannas 790406 affidavit Certificate of Doc mcl
CANILL.M.J Consolidated Edison Co of New York 79/06/06 App

7904000150 Forwards info re P&B feedwater lines in response to NRC
790525 request W/IS corrected drawings
CANILL.M.J Consolidated Edison Co of New York 79/04/18 App

7904000255 "Efficiency of One Square Meter Epithelial Aired for
Collecting Young-of-the-Year Striped Bass, White Perch &
Atlantic Tomcod in Hudson River Estuary, 1978"
* Texas Instruments, Inc 79/06/25 1App

D Inspection reports, IE Bulletin & correspondence

7904000308 Forwards IE Bulletin 79-036, "Nuclear Incident at
TRI-Bugli" No written response required
GRIER.S.H Region 1, Philadelphia, Office of the Director
79/04/22 App

7904000342 Response to IE Bulletin 79-037 Discusses action taken re
verification approach for USRC-ASLIPR-2 program
CANILL.M.J Consolidated Edison Co of New York 79/04/24 App

7904000318 Forwards response to Revision 1 to IE Bulletin 79-044 re
TRI incident
CANILL.M.J Consolidated Edison Co of New York 79/04/26 App

7904000340 Response to IE Bulletin 79-04, "Incorrect Heights for During
Direct Valve NIS by Velox Engineering Corp" Effect of
weight discrepancies negligible in direct valve investigated
Further investigation initiated; response expected 790408
CANILL.M.J Consolidated Edison Co of New York 79/05/01 App

7904000350 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Support Problem" No action required
GRIER.S.H Region 1, Philadelphia, Office of the Director
79/05/07 App

7904000318 Forwards IE Bulletin 79-10, "Regualarization Training
Program Statistics" Licenses action required
GRIER.S.H Region 1, Philadelphia, Office of the Director
79/05/11 App

7904000398 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
GRIER.S.H Region 1, Philadelphia, Office of the Director
79/05/11 App

7904000342 Response to IE Bulletin 79-09 Unit 1 currently shut down,
awaiting decision re EGSS No GE Type AA-2 circuit breakers
used in safety-related app in Unit 2
CANILL.M.J Consolidated Edison Co of New York 79/05/17 App

7904000349 Forwards IE Circular 79-08, "Attempted Extinction - Low
Enriched U"
GRIER.S.H Region 1, Philadelphia, Office of the Director
79/05/19, App

7904000390 Summary of 790517 meeting w/Consolidated Edison Co of NY,
Power Authority of State of NY & United Engineers &
Constructors, Inc. to discuss licensed response to IE Bulletin
79-07, "Dynamic Stress Analysis of Safety-Related Piping"
OLSHAN.M.H Operating Reactors Branch 1 (Pia 790428) 79/05/18
App

7904000367 Forwards supplemental response to IE Bulletin 79-07 re
confirming analysis of pressurizer relief line 70, using
USRC-ASLIPR-2 dynamic stresser removal code
24WAKAD.P Consolidated Edison Co of New York 79/05/28 App

R Periodic operating reports & related correspondence

7904000359 Annual Environ Operating Rpt 1978, Part A & Part B:
radiological rpt, vols 1 & 2
* Consolidated Edison Co of New York 78/12/31, 223pp

7904000442 Forwards "Seismic Monitoring Network," Quarterly Rpt
13 for Dec 1978 - Feb 1979
CANILL.M.J Consolidated Edison Co of New York 79/06/04 1p

7904000444 "Seismic Monitoring Network," Quarterly Rpt 13 for
Feb 1979 - Apr 1979 Prepared by Geo-Logic Consultants, Inc
* Consolidated Edison Co of New York 79/05/20 App

7904000470 Releas Mgr environ data specified in Section 401
certification
SEID.M.A Consolidated Edison Co of New York 79/06/10 1pp

7904000504 Forwards monthly operating rpt for May 1979
CANILL.M.J Consolidated Edison Co of New York 79/06/14 1p

7904000504 Monthly operating rpt for May 1979
CANILL.M.J Consolidated Edison Co of New York 79/06/08 7pp

7904000507 Forwards May 1979 daily tabulation of fish collection &
species breakdown
CANILL.M.J Consolidated Edison Co of New York 79/06/14 App

S Reportable occurrences, LERs & related correspondence

7904000534 Forwards LER 79-035/047-0
CANILL.M.J Consolidated Edison Co of New York 78/06/14 1p

7904000591 LER 79-020/048-0 on 780428 activity of water sample taken
from Camp Field Reservoir on 780327 exceeded ten times
the critical level. Caused by non-representative sampling
technique & adverse meteorological conditions
MAGILL.L.J Consolidated Edison Co of New York 79/06/09 1p

7904000598 Discusses erroneous measurement of radioactivity at environ
water sampling location. Problem caused by failure from
chemical waste test & other factors yielding
non-representative sample. Techniques to be changed
CANILL.M.J Consolidated Edison Co of New York 78/06/09 App

DOCKET NO. 249 DREBORN NUCLEAR POWER STATION, UNIT 3

C Adjudicatory correspondence

7904000135 Forwards 790316 order re shipment of spent fuel, admitting
contentions similar to those at issue in present proceeding
as matters in controversy
SEIDMAN.A.2 Natural Resources Defense Council 79/03/26 1p

7904000346 Memo re standing & commitments of intervenors State of IL,
NRDC & Citizens for Better Environ following 790201 special
prehearing conference on spent fuel storage
MILHOLLIN.G.L Atomic Safety and Licensing Board Panel 79/04/19
12pp

7904000387 Forwards representative mail prepared by Citizens for Better
Environ & NRDC to disclose interest in issue of nuclear
power.
SEIDMAN.A.2 Natural Resources Defense Council 79/05/03 60pp

7904000337 Motion for reconsideration of 790419 memo & order following
special prehearing conference. Objects to admission of
Contention 4 re specific threats to irradiated fuel
in bonded Certificate of Res mcl
SEIDMAN.A.2 Branch 2 79/05/24 App

7904000359 Would not oppose admission of Contention 4 as revised to
conform w/Contention 4 as admitted in Civil Power proceeding
re security of spent fuel in Transit
SEIDMAN.A.2 Branch 2 79/04/26 App

7904000339 Applicant motion for reconsideration of 790419 memo & order
of admission of 790419 order re physical security of
SME Supporting documentation & Certificate of Doc mcl
SEIDMAN.A.2 Branch 2 79/05/07 14pp

7904000502 Grants NRDC 790504 motion suggesting alternative language
for Contentions & States license motion to reconsider
admissibility of Contentions 4 & 11
MILHOLLIN.G.L Atomic Safety and Licensing Board Panel, 79/05/16
4pp

7904000445 Concludes NRDC & Citizens for Better Environ have standing
based on criteria of ALAB-325 Both have established interest
in nuclear power issues & are authorized to represent
members in proceedings.
MILHOLLIN.G.L Atomic Safety and Licensing Board Panel, 79/05/20
4pp

J Insurance and indemnity information

7906040087 Forwards executed bonds \$5.0, 4 & 1 to Indemnity Agreement
8-10, 8-47, 8-29 & 8-24 respectively
RHEB, R. D. Commonwealth Edition Co 79/08/29 3pp

F Operating license stage documents & correspondence

7906050081 Responds to 79050119 Request add info re review of
proposed spent fuel pool and UOI should provide info within
30 days of receipt of info
ZIGLER, D. L. Operating Reactors Branch 2 (Pm 790605) 79/04/23
4pp

7906100229 Requests two controlled copies of site emergency plans &
implementing procedures, site maps showing location & grid
station number of outside & offsite emission monitoring
stations & site maps used for dose determinations.
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/05/17
1p

7906100371 Responds to NRC 790423 request for add info re spent fuel
pool and Forwards spent fuel storage module availability
study final findings available in Central Files only
JAWORSKI, R. F. Commonwealth Edition Co 79/05/26 43pp

7906100338 Responds to IE Bulletin 79-01 Forwards info re emission
qualification of Class IE equipment required by function
under accident conditions & info re use & status of AGCS
solenoid valves.
REED, C. Commonwealth Edition Co 79/05/14 5pp

7906100490 Requests inclusion in details of NDE-21946-P, "On-Quarter
Dose Pressure Suppression Pool Sump Test Program, Plant
Unique Tests"
JAWORSKI, R. F. Commonwealth Edition Co 79/06/02 1p

G Inspection reports, IE Bulletins & correspondence

7906290147 Forwards SE Insp Repts 50-035/79-10, 50-037/79-10 &
50-049/79-08 on 790504-20, 05 noncompliance noted
NEPFLER, J. O. Region 3, Chicago, Reactor Operations Nuclear
Support Branch 79/04/25 3pp

7906300123 IE Insp Repts 50-010/79-10, 50-022/79-10 & 50-049/79-08
on 790504-20 Noncompliance noted Major areas inspected
major activation plant operations & physical protection &
security organization.
REED, C. L., MORSE, R. K., REVER, L. A. Region 3, Chicago, Office
of the Director 79/04/25 3pp

7906300409 Responds to IE Bulletin 79-06 Forwards info re review of the
incident Existing line isolation not important to RCS
injection
REED, C. Commonwealth Edition Co 79/04/27 22pp

7906300436 Forwards IE Insp Repts 50-037/79-10 & 50-049/79-08 on
790413, 21-22 & 27 Noncompliance noted
NEPFLER, J. O. Region 3, Chicago, Reactor Operations Nuclear
Support Branch 79/03/02 3pp

7906300439 IE Insp Repts 50-037/79-10 & 50-049/79-08 on 790413, 21-22 &
27 Noncompliance noted Major areas inspected Integrated
test test & license action on previously identified item of
noncompliance.
REVER, L. A., DETEMMEIER, R., DETEMMEIER, J. F. Region 3, Chicago,
Office of the Director 79/05/03 4pp

7906120039 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Support Problem" No action required
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/05/27
1p

7906110101 Forwards IE Bulletin 79-10, "Recalibration Training
Program Statistics" Written response required
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/05/11
1p

7906300578 Forwards IE Info Notice 79-12, "Accepted Damage to New Fuel
Assemblies"
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/05/11,
1p

7906050106 Forwards SE Circular 79-06, "Accepted Extension - Low
Enriched U"
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/05/18
1p

7906100084 Forwards IE Bulletin 79-11, "Monthly Overcurrent Trip Device
in Circuit Breakers for Engineered Safety Sys." License
action required
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/05/22
1p

7906300679 Submits corrected copy of page 4 of Insp Repts 50-035/79-10
& 50-049/79-08
NEPFLER, J. O. Region 3, Chicago, Reactor Operations Nuclear
Support Branch 79/05/23 2pp

7906300690 Forwards IE Info Notice 79-13, "Indication of Low Water
Level in Reactor Coolant System"
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/05/29
1p

R Periodic operating reports & related correspondence

7906100334 Forward monthly operating report for May 1979
STEPHENSON, S. B. Commonwealth Edition Co 79/06/11 1p

7906100338 Monthly operating report for May 1979
STEPHENSON, S. B. Commonwealth Edition Co 79/06/04 20pp

S Reportable occurrences, LERs & related correspondence

7906100311 LER 79-030 has been voided
A. Commonwealth Edition Co 79/06/01 1p

7906100313 Forwards LER 79-013/030-0
STEPHENSON, S. B. Commonwealth Edition Co 79/06/07 1p

7906100313 LER 79-013/030-0 on 790601 during half-core steam testing,
control rod withdrawal 0-5 (20-17) became uncontrolled from
control rod when withdrawn beyond position 48 caused by
lower filter becoming detached
NEPFLER, J. O. Commonwealth Edition Co 79/06/07 1p

7906100418 Forwards LER 79-010/030-0
STEPHENSON, S. B. Commonwealth Edition Co 79/06/12 1p

7906100432 LER 79-010/030-0 on 790505 effluent log read monitor 1705 3A
drifted high & tripped on HI HI effluent activity caused by
exhauster of junction controller (effluent correct on log
feedback) data monitor repaired & will be tested monthly
NEPFLER, J. O. Commonwealth Edition Co 79/06/12 1p

7906100437 Forwards LER 79-011/030-0
STEPHENSON, S. B. Commonwealth Edition Co 79/06/12 1p

7906100447 LER 79-011/030-0 on 790507 intermediate range monitor 17
tripped above Tech Spec set, caused by instrument drift
Monitor readjusted
NEPFLER, J. O. Commonwealth Edition Co 79/06/12 1p

7906201012 Forwards LER 79-012/030-0
STEPHENSON, S. B. Commonwealth Edition Co 79/06/18 1p

7906201018 LER 79-012/030-0 on 790504 downstream read block tripped at
4/125 of full scale rather than at 2/125 as per Tech Spec
caused by electronic instrument drift Intermediate range
monitor readjusted to 4/125 decreasing
NEPFLER, J. O. Commonwealth Edition Co 79/06/18 1p

DOCKET 50-230 TURNER POINT PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

7906060205 Informa that Compensatory measures are acceptable & will
remain in effect until modified annual security plan is
fully implemented. IE should be notified when compensatory
measures are discontinued.
NEPFLER, J. O. Operating Reactors Branch 1 (Pm 790605), 79/04/30
3pp

G Administrative correspondence

7906070028 Request by bill that NRC deny HP Chicago 790509 petition
for hearing on proposed reactor to steam generators, notice
of appearance of SA Bauer & SA Dell on basis of still need
affidavits of GE Whittier & GE South W. Certificate of Rev.
DAUBER, M. A. Loveston/Neuman, Reins, Avirel & Toll COLLIN, A.
Basil, Becker & Davis 79/05/07 20pp

DOCKETED ITEMS

27

7906070026 Urges repair of steam generator tube plugging Alternate methods of repair to be considered are lower section replacement in place retubing NRC to make early deterioration of repair service by 7906070010 R E Florida Power & Light Co 7/7/09/20 App

H General correspondence

7906060007 Requests that H Ocasuga petition to Intervene be granted
SEEDMAN, T. OATES, R. & 01/06/07/09/20 Affiliation Unknown
79/06/01 App

7906070007 Requests that NRC grant NP Ocasuga petition for hearing & intervention in steam generator repair program
NOLAN, T. & SCHNEIDER, S. 06/01/07/09/20 Affiliation Unknown 79/06/27 App

M Amicitia correspondence

7906040418 Response of utility in opposition to FL Citizens' motion for arbitrator hearing & motion for consolidated hearings
Certificate of Doc 06/01/07/09/20 Affiliation Unknown & Tell 79/06/13 App

P Operating license stage documents & correspondence

7906060019 Responds to 79060611R requesting ref to specific OR program used to meet requirements of 10CFR71.31 Revision 2 to topical OR ref is in effect for Turkey Point & PRISM OR program is in effect for St Lucie
06/01/07/09/20 R E Florida Power & Light Co 79/06/23 App

7906060266 Forwards Amends 47 & 39 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability
SCHNEIDER, A. Operating Reactors Branch 1 (Pre 7906025) 79/06/24 App

7906060267 Amends 47 & 39 to Licenses DPR-31 & DPR-41, respectively, changing control rod group insertion limits
SCHNEIDER, A. Operating Reactors Branch 1 (Pre 7906025) 79/06/24 App

7906060268 Safety evaluation supporting Amends 47 & 39 to Licenses DPR-31 & DPR-41, respectively
Office of Nuclear Reactor Regulation 79/06/24 App

7906060269 Notice of issuance & availability of Amends 47 & 39 to Licenses DPR-31 & DPR-41, respectively
SCHNEIDER, A. Operating Reactors Branch 1 (Pre 7906025) 79/06/24 App

7906060271 Forwards Amends 40 & 40 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability
SCHNEIDER, A. Operating Reactors Branch 1 (Pre 7906025) 79/06/04 App

7906060272 Amends 40 & 40 to Licenses DPR-31 & DPR-41, respectively, revising Tech Specs to require activation of safety injection based on two of three channels of low pressure pressure
SCHNEIDER, A. Operating Reactors Branch 1 (Pre 7906025) 79/06/04 App

7906060273 Safety evaluation supporting Amends 40 & 40 to Licenses DPR-31 & DPR-41, respectively
SCHNEIDER, A. Operating Reactors Branch 1 (Pre 7906025) 79/06/04 App

7906060403 Notice of issuance & availability of Amends 40 & 40 to Licenses DPR-31 & DPR-41, respectively
SCHNEIDER, A. Operating Reactors Branch 1 (Pre 7906025) 79/06/04 App

7906060404 Forwards safety evaluation for steam generator repair program
SCHNEIDER, A. Operating Reactors Branch 1 (Pre 7906025) 79/06/14 App

7906060405 Safety evaluation for steam generator repair program
Office of Nuclear Reactor Regulation 79/06/14 App

7906060406 Requests Clauses I & III amend fees within 14 days, in connection with 79060611R application for Tech Spec changes re: operability & surveillance of overpressure mitigation
MILLER, M. D. License Fee Management Branch 79/06/17 App

7906060407 Notification of 7906060266 meeting w/ utility in Orlando, FL to discuss containment gaps & related equipment
06/01/07/09/20 Operating Reactors Branch 1 (Pre 7906025) 79/06/22 App

7906060424 Forwards requested fee for 7906060266 license amend
06/01/07/09/20 R E Florida Power & Light Co 79/06/29 App

7906060427 Forwards requested fee for 7906060266 license amend
06/01/07/09/20 R E Florida Power & Light Co 79/06/29 App

7906060439 Submits figure of max predicted heat flux (P) for Cycle A based on 18°C analysis of ECCS
06/01/07/09/20 R E Florida Power & Light Co 79/06/08 App

7906060445 Provides addl info re costs of limiting containment purge during high power operations Util attempting to resolve issues raised in NRC 7906060266 request
06/01/07/09/20 R E Florida Power & Light Co 79/06/08 App

7906060446 Submits addl info re proposed radiological effluent Tech Specs in response to 7906060266 request
06/01/07/09/20 R E Florida Power & Light Co 79/06/18 App

7906060448 Submits info re Feedwater line design & fabrication history requested by 7906060266 for remaining 1840 will be forwarded by 7906060266
06/01/07/09/20 R E Florida Power & Light Co 79/06/18 App

7906060449 Forwards "Reactor Containment Bldg Integrated Leak Rate Test Rpt"
06/01/07/09/20 R E Florida Power & Light Co 79/06/20 App

7906060450 "Reactor Containment Bldg Integrated Leak Rate Test Rpt"
Florida Power & Light Co 79/06/20 170pp

0 Inspection reports, IE Bulletins & correspondence

7906060487 Forwards IE Insp Repts 50-250/79-09 & 50-251/79-09 on 7906060449 No noncompliance noted
LENNIN, C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/13 App

7906060490 IE Insp Repts 50-250/79-09 & 50-251/79-09 on 7906060449 No noncompliance noted Major areas inspected safety-related piping support/restraint surveillance program & containment integrated leakage rate testing
06/01/07/09/20 R E Florida Power & Light Co 79/06/18 App

7906060494 Responds to IE Bulletin 79-02 Status re: 7906060449 Holding & Engineering Co pipe will be sent no later than 7906060449
06/01/07/09/20 R E Florida Power & Light Co 79/06/17 App

7906060495 Forwards response to IE Bulletin 79-06 & 79-06A Personnel operational responsibilities have completed relevant instructional sessions Operational surveillance level database updated is undetectable
06/01/07/09/20 R E Florida Power & Light Co 79/06/18 App

7906060496 Responds to IE Bulletin 79-06 & 79-06A Personnel operational responsibilities have completed relevant instructional sessions Operational surveillance level database updated is undetectable
06/01/07/09/20 R E Florida Power & Light Co 79/06/18 App

7906060497 Responds to IE Bulletin 79-06 & 79-06A Personnel operational responsibilities have completed relevant instructional sessions Operational surveillance level database updated is undetectable
06/01/07/09/20 R E Florida Power & Light Co 79/06/18 App

7906060498 Forwards IE Insp Repts 50-250/79-04 & 50-251/79-04 on 7906060449 & notice of violation
06/01/07/09/20 R E Region 2, Atlanta, Office of the Director 79/06/18 App

7906060499 Notice of violation from Insp on 7906060449
Region 2, Atlanta, Office of the Director, 79/06/18 App

7906060500 IE Insp Repts 50-250/79-04 & 50-251/79-04 on 7906060449 No noncompliance noted, no fracture in welding joint control
06/01/07/09/20 R E Region 2, Atlanta, Office of the Director 79/06/18 App

DOCKETED ITEMS

7906203452 Forwards IE Info Notice 79-12. "Accepted Damage to New Fuel Assembly"
O'DELL, V. P. Region 2, Atlanta, Office of the Director
7/6/5/11 1p

7906203453 Forwards IE Bulletin 79-10. "Qualification Training Program Schedule"
O'DELL, V. P. Region 2, Atlanta, Office of the Director
7/6/5/11 1p

7906203454 Responds to IE Bulletin 79-09 re IE Model AM-2 circuit breakers
Shatters No such circuit breakers currently installed in units
WHEAT, R. E. Florida Power & Light Co. 7/6/5/12 1p

7906203455 Ack receipt of 790510 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/79-10 & 50-251/79-10
BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 7/6/5/12 1p

7906203456 Responds to NRC 790422 ltr re violations noted in IE Insp Repts 50-250/79-10 & 50-251/79-10 corrective actions will
Health physics shift supervisors instructed to ensure respirator decontamination
WHEAT, R. E. Florida Power & Light Co. 7/6/5/10 3pp

7906203457 Forwards IE Insp Repts 50-250/79-10 & 50-251/79-10 re 790334-12 & notice of violation
BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 7/6/4/23 2pp

7906203458 Notice of violation from Insp re 790319-23
Region 2, Atlanta, Office of the Director 7/6/4/20 1p

7906203459 IE Insp Repts 50-250/79-10 & 50-251/79-10 re 790319-23
Noncompliance noted failure to post airborne radioactivity area & leave contamination on respirators
WHEAT, R. E. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 7/6/4/20 11pp

7906203462 Ack receipt of 790514 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/79-10 & 50-251/79-10
WHEAT, R. E. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 7/6/5/12 1p

7906203464 Responds to NRC 790422 ltr re violations noted in IE Insp Repts 50-250/79-10 & 50-251/79-10 corrective actions
appropriate level channels will be placed in tripped condition when deviation acceptance criteria is exceeded
Florida Power & Light Co. 7/6/5/14 2pp

7906203465 Forwards IE Insp Repts 50-250/79-10 & 50-251/79-10 re 790312-10 & notice of violation
LESTER, M. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 7/6/4/20 2pp

7906203466 Notice of violation from Insp re 790312-10
Region 2, Atlanta, Office of the Director 7/6/4/20 1p

7906203468 IE Insp Repts 50-250/79-10 & 50-251/79-10 re 790312-01
Noncompliance noted failure to take corrective action re vessel/factory instrumentation channel check
WHEAT, R. E. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 7/6/4/19 4pp

5 Periodic operating reports & related correspondence

7906203469 Bulletin supplementing report to Annual Nonradiological Environ Monitoring Rept 1978
WHEAT, R. E. Florida Power & Light Co. 7/6/5/11 2pp

6 Reportable occurrences, LERs & related correspondence

7906203470 Forwards LER 79-014/03L-0
SCHNEIDER, A. B. Florida Power & Light Co. 7/6/5/24 1p

7906203471 LER 79-014/03L-0 re 790424 "ready to start" light on B emergency diesel generator master control panel failed
Caused by vibration of jump switch Tests under way to determine if new unit would be better suited
JAMES, D. K. Florida Power & Light Co. 7/6/5/24 2pp

7906203472 Forwards LER 79-015/03L-0
SCHNEIDER, A. B. Florida Power & Light Co. 7/6/5/24 1p

7906203473 LER 79-015/03L-0 re 790424 B emergency diesel generator failed loading acceptance criteria caused by cracked half-inch nipple in fuel pump assembly resulted in partial fuel starvation Nipple replaced & old nipple reassembled
JAMES, D. K. Florida Power & Light Co. 7/6/5/24 1p

7906203474 Forwards LER 79-016/03L-0
SCHNEIDER, A. B. Florida Power & Light Co. 7/6/5/24 1p

7906203475 LER 79-016/03L-0 re 790424 high level alarm annunciated
Caused by instrument drift of Tech Spec min & high level alarms & digital level indication transducer instruments replaced
SCHNEIDER, A. B. Florida Power & Light Co. 7/6/5/24 2pp

7906203476 50-250-79-20 re 790331 emergency diesel generator tripped as result of lockout relay operation caused by failed exciter gear transformer
WHEAT, R. E. Florida Power & Light Co. 7/6/4/21 1p

7906203477 Forwards LER 79-020/01T-0
SCHNEIDER, A. B. Florida Power & Light Co. 7/6/6/11 1p

7906203478 LER 79-020/01T-0 re 790324 during load test, emergency diesel generator tripped caused by design error which led to overloading of exciter gear transformer Transformer replaced & plant changed-out implemented
SCHNEIDER, A. B. Florida Power & Light Co. 7/6/4/21 1pp

9 Congressional/Executive Correspondence

7906203479 Inform of attempt to reschedule review of typical report re NRC approved use of Fox Industries metal coupling for reinforcing steel bars Assures that review is not premature for NRC product use
SCHNEIDER, A. B. Office of Nuclear Reactor Regulation 7/6/3/28 2pp

7906203480 Requests response to complaint re NRC regulations & TVA contract award for reinforcing steel bars replacing matl at TVA
FOLK, C. J. Forsboro Ga. 7/6/2/05 1p

7906203481 Forwards ltr written to TVA re violation of NRC regulations in granting award of contract for rebar splicing matl to TVA
FOLK, C. J. Forsboro Ga. 7/6/2/02 2pp

7906203482 Discusses constituent's support of HP discharge request for NRC to hold public hearings on planned steam generator repairs
FOLK, C. J. House of Rep. 7/6/5/01 1p

7906203483 Provides add info re Browning info request re FL nuclear power situation Discusses issues produced by FL plants, efforts released & consequences of possible accident
SCHNEIDER, A. B. Office of the Executive Director for Operations 7/6/5/17 3pp

7906203484 Forwards 0 Browning 790424 questions re FL nuclear power & situation Requests necessary info for reply
NICA, D. A. House of Rep. 7/6/4/05 2pp

7906203485 Ack receipt of 790405 ltr re 0 Browning info request re FL nuclear power situation Discusses instructions to operators re steps to prevent occurrence like TSC & JH Hendrie 790410 testimony to Subcommittee on Nuclear Regulation WVC and
SCHNEIDER, A. B. Office of Congressional Affairs 7/6/4/18 1p

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

F. Security, medical, emergency & fire protection plans

7906203486 Inform that Compensatory measures are acceptable & will remain in effect until modified amended security plan is fully implemented IE should be notified when compensatory measures are discontinued
SCHNEIDER, A. B. Operating Reactors Branch 1 Ofc 790620 7/6/4/20 3pp

0 Adjudicatory correspondence

7906203487 Request by atty that NRC deny HP discharge 790509 petition for hearing on proposed repairs to steam generators Notice of appearance of RA Reaser & RA Cell on behalf of unit and affidavit of OD Nasser & OD Nasser Affidavit of OD KAUBER, M. A. Louisiana; Nasser, R. H.; Reaser & Cell. CELL, M. A. Stew. Hinkle & Davis 7/6/3/19 2pp.

--790607002A Urges repair of steam generator tube plugging Alternate methods of repair to be considered are lower section replacement & place including NRC to date early determinations of repair review by 791018
 WRI010.R E Florida Power & Light Co 77/09/20 App

General correspondence

790606007 Requests that NRC Deny petition to inform be granted
 BEFFMAN, T. GATES, R. E. DILLON, D. Affiliation Unknown
 79/05/01 App

7906070037 Requests that NRC grant HP Deny petition for hearing & information in steam generator repair program
 NOLLE, T. S. GRIFFIN, S. Affiliation Unknown 79/04/27 App

Antitrust correspondence

7906060018 Response of NRC in opposition to PL Citings' motion for antitrust hearing & action for consolidated hearings
 Certificate of Rev and
 SCURHAM, J. A. Lowenstein, Neuman-Rose, Arnold & Toll 79/04/13 App

Operating license stage documents & correspondence

7906060019 Responds to 790337 1P requesting ref 54 Specific QA program used to meet requirements of 10CFR71 55 Revision 3 to Technical QA part is to effect for Turkey Point & FWR QA program is in effect for St. Lucie
 WRI010.R E Florida Power & Light Co 79/04/23 1p

7906060046 Forwards Amends 47 & 39 to Licensee DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability
 SCHEMEL, A Operating Reactors Branch 1 (Pre 790625) 79/04/24 App

--7906060047 Amends 47 & 39 to Licensee DPR-31 & DPR-41, respectively, changing control and group interlock limits
 SCHEMEL, A Operating Reactors Branch 1 (Pre 790625) 79/04/24 App

--7906060048 Safety evaluation supporting Amends 47 & 39 to Licensee DPR-31 & DPR-41, respectively
 Office of Nuclear Reactor Regulation 79/04/24 App

--7906060049 Notice of issuance & availability of Amends 47 & 39 to Licensee DPR-31 & DPR-41, respectively
 SCHEMEL, A Operating Reactors Branch 1 (Pre 790625) 79/04/24 App

7906060049 Forwards Amends 48 & 40 to Licensee DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability
 SCHEMEL, A Operating Reactors Branch 1 (Pre 790625) 79/05/04 App

--7906060050 Amends 48 & 40 to Licensee DPR-31 & DPR-41, respectively, revising Tech Specs to require activation of safety injection based on low of three channels of low pressure pressure
 SCHEMEL, A Operating Reactors Branch 1 (Pre 790625) 79/05/04 App

--7906060051 Safety evaluation supporting Amends 48 & 40 to Licensee DPR-31 & DPR-41, respectively
 SCHEMEL, A Operating Reactors Branch 1 (Pre 790625) 79/05/04 App

--7906060052 Notice of issuance & availability of Amends 48 & 40 to Licensee DPR-31 & DPR-41, respectively
 SCHEMEL, A Operating Reactors Branch 1 (Pre 790625) 79/05/04 App

7906060056 Forwards safety evaluation for steam generator repair program
 SCHEMEL, A Operating Reactors Branch 1 (Pre 790625) 79/05/14 App

--7906060058 Safety evaluation for steam generator repair program, Program found acceptable
 Office of Nuclear Reactor Regulation 79/05/14 App

7906060076 Requests Class 1 & II amend fees within 14 days, in connection with 791011 application for Tech Spec changes re operability & surveillance of overpressure mitigating sys, NPL&R, WRI License Fee Management Branch, 79/05/17, 1p

7906060066 Notification of 790529 meeting w/utill in Bethesda, MD to discuss containment purge & related equipment
 SCHEMEL, A Operating Reactors Branch 1 (Pre 790625) 79/05/23 App

7906060125 Responds to NRC review of 790510 license amend & forwards copy of amend proposed by generated for Cycle 6 based on 15-week analysis
 WRI010.R E Florida Power & Light Co 79/05/29 App

7906060274 Forwards requested fee for 790526 license amend
 WRI010.R E Florida Power & Light Co 79/05/29 1p

7906060277 Forwards requested fee for 790521 license amend
 WRI010.R E Florida Power & Light Co 79/05/29 1p

7906060293 Forwards \$4,000 fee for approval of 790510 request
 WRI010.R E Florida Power & Light Co 79/05/29 App

7906060335 Provides add info re costs of limiting containment purges during high power operations until attempting to resolve issues related to NRC 790120 1P Combined containment purges in interim to be limited to 200+1/2 year
 WRI010.R E Florida Power & Light Co 79/06/05 App

7906060356 Submits add info re proposed radiological effluent Tech Spec in response to 790525 request
 WRI010.R E Florida Power & Light Co 79/06/13 1p

7906060358 Submits info re Feedwater line design & fabrication history requested by 790525 1P Remaining info will be forwarded by 790720
 WRI010.R E Florida Power & Light Co 79/06/19 App

Inspection reports, IE Bulletins & correspondence

7906060487 Forwards IE Insp Rpts 50-250/79-09 & 50-251/79-09 on 790213-1P re noncompliance noted
 LOVIN, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/12 App

--7906060490 IE Insp Rpts 50-250/79-09 & 50-251/79-09 on 790213-1P re noncompliance noted Major areas inspected safety-related piping, support, restraint, support, reactor, piping & containment integrated leakage rate testing
 WRI010.R E Region 2, Atlanta, Office of the Director, NUTTING, R. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/12 App

7906130434 Responds to IE Bulletin 79-03 Status report re Yungstung Welding & Engineering Co pipe will be sent no later than 790521
 WRI010.R E Florida Power & Light Co 79/04/17 1p

7906060518 Forwards response to IE Bulletin 79-04 & 79-05A Personnel w/operational responsibilities have completed relevant instructional sessions Operation w/personnel file histories triggered is undesirable
 WRI010.R E Florida Power & Light Co 79/04/28 App

7906070033 Add remark of 790511 re informing MFC of steps taken to correct violations noted in IE Insp Rpts 50-250/79-04 & 50-251/79-04
 HUMPHRY, C E Region 2, Atlanta, Reactor Construction & Engineering Branch 79/05/03 1p

--7906070034 Responds to NRC 790214 1P re violations noted in IE Insp Rpts 50-250/79-04 & 50-251/79-04
 WRI010.R E Florida Power & Light Co 79/04/11 App

--7906070035 Forwards IE Insp Rpts 50-250/79-04 & 50-251/79-04 on 790214-1P re notice of violation
 HUMPHRY, C E Region 2, Atlanta, Office of the Director 79/05/10 App

--7906070037 Notice of violation from Insp on 790206-09
 Region 2, Atlanta, Office of the Director 79/05/10 App

--7906070079 IE Insp Rpt 50-250/79-04 & 50-251/79-04 on 790206-09 Noncompliance noted, infraction in welding metal control, KLM&R, J. J. GONZALEZ E Region 2, Atlanta, Office of the Director 79/04/18 App

7906070082 Forwards IE info Notice 79-12: "Attempted Damage to New Fuel Assemblies - Ongoing" re
 Region 2, Atlanta, Office of the Director, 79/05/10, 1p

DOCKETED ITEMS

790610043 Forwards IE Bulletin 79-10, "Requalification Training Program Overview." Written response required.
GREGORY, J. P. Region 2, Atlanta, Office of the Director.
79/03/11, 1p.

790604090 Responds to IE Bulletin 79-09 re GC Model AM-2 circuit breakers. He such circuit breakers currently installed in units.
LW10, R. E. Florida Power & Light Co. 79/03/22 1p

790606004 Act receipt of 790503 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 79-230/79-10 & 79-231/79-12.
LW10, R. E. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/05/22 1p

7906040358 Responds to NRC 7904023 ltr re violations noted in IE Insp Repts 79-230/79-10 & 79-231/79-12. Corrective actions all health physics shift supervisors instructed to ensure respirator decontamination.
LW10, R. E. Florida Power & Light Co. 79/05/10 2pp

790604043 Forwards IE Insp Repts 79-230/79-10 & 79-231/79-12 on WUTHRELAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/04/23 2pp

790604049 Notice of violation from Insp on 790319-23.
Region 2, Atlanta, Office of the Director. 79/04/20 1p

7906040391 IE Insp Repts 79-230/79-10 & 79-231/79-12 on 790319-23. Noncompliance noted failure to post airborne radioactivity areas & loose contamination on respirators.
ZAWADZKI, R. M. - NRC, J. H. - OHS&A, C. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/04/20 11pp

790604062 Act receipt of 790314 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 79-230/79-12 & 79-231/79-12.
LW10, R. E. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/05/22 1p

7906040409 Responds to NRC 790425 ltr re violations noted in IE Insp Repts 79-230/79-12 & 79-231/79-12. Corrective actions appropriate level chemicals will be placed in tagged condition when deviation acceptance criteria is accepted.
Florida Power & Light Co. 79/03/14 2pp

7906040411 Forwards IE Insp Repts 79-230/79-12 & 79-231/79-12 on 790312-18 & notice of violation.
LW10, R. E. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/04/20 2pp

790604042 Notice of violation from Insp on 790312-15.
Region 2, Atlanta, Office of the Director. 79/04/20 1p

7906040414 IE Insp Repts 79-230/79-12 & 79-231/79-12 on 790312-21. Noncompliance noted failure to take corrective action on unsatisfactory instrumentation channel check.
WORTHEN, C. H. - OHS&A, J. H. - OHS&A, C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/04/19 4pp.

B. Periodic operating reports & related correspondence

7906010248 Submits supplementing report to Annual Neurobiological Environments Monitoring Report 1978.
LW10, R. E. Florida Power & Light Co. 79/03/11 3pp.

B. Reproducible accuracies, LRA & related correspondence

7906140284 RD 231-79-07 on 790519 pipe support in charging pump room (Inoperable fuel post & corrective action to be submitted in response to IE Bulletin 79-08. Pipe Support Base Plate Design using Concrete Expansion Anchor Bolt).
FABER, H. K. Florida Power & Light Co. 79/05/21, 1p.

790608010 Forwards LRA 79-007-017-0.
GREGORY, J. P. Florida Power & Light Co. 79/06/04 1p

7906180015 LRA 79-007-017-0 on 790519 inoperable pipe support 4-VH-108 reported by Insp team. Cause unknown. Pipe support to be restored per approved procedures.
GREGORY, H. K. Florida Power & Light Co. 79/06/04 1p

U. Congressional/Executive Correspondence

7903000226 Inform of attempt to schedule review of typical report re NRC approved use of Pex Industrial half-pipe couplers for reinforcing steel bars. Assures that review is not prerequisite for NRC product use.
GREGORY, H. K. Office of Nuclear Reactor Regulation. 79/03/28 3pp

7903000233 Requests response to complaint re NRC regulations & TVA contract award for reinforcing steel bars applying mail at Yellow Creek plant.
FOSK, J. F. Fisk Co. 79/02/03 1p

7903000243 Forwards ltr written to TVA re violation of NRC regulations in granting award of contract for repair replacing mail to TVA.
FOSK, J. F. Fisk Co. 79/02/02 3pp

7904070048 Discusses constituent's support of NP Overage request for NRC to hold public hearings on planned steam generator repairs.
FOSK, J. F. House of Rep. 79/05/01 1p

7904060046 Provides add'l info re B Browning info request re FL nuclear power situation. Discusses issues produced by FL plants. Affirmative response to consequences of possible accident.
GREGORY, J. P. Office of the Executive Director for Operations. 79/05/17 3pp

7904060099 Forwards B Browning 790404 questions re FL nuclear power situation. Requests necessary info for reply.
NRC, D. A. House of Rep. 79/04/02 2pp

7904060093 Act receipt of 790403 ltr re B Browning info request re FL nuclear power situation. Forwards instructions to operators re steps to prevent occurrence like TMI & JM Hendrie 790410. Testimony to Subcommittee on Nuclear Regulation. HHS and. KAMMERER, C. Office of Congressional Affairs. 79/04/16 1p

DOCKET 79-052 UNIV. OF NEW MEXICO RESEARCH REACTOR

J. Insurance & indemnity information

790604043 Forwards Amend 10 to Indemnity Agreement C-47.
FOSK, J. F. New Mexico Univ. of 79/04/18 3pp

K. Inspection reports: IE Bulletins & correspondence

7906120009 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies."
GREGORY, J. P. Region 2, Atlanta, Office of the Director. 79/03/11 1p

DOCKET 79-054 MAAS-CITRER STATION, UNIT 1

D. Advisory correspondence

790610101 Forwards 790314 order re shipment of spent fuel. Submitting conditions similar to those at issue in present proceeding. As follows in correspondence.
GREGORY, J. P. Natural Resources Defense Council. 79/03/20 1p.

7906070344 Memo re standing & termination of Interim State of IL, NRC & Citizens for Better Environments following 790503 special prehearing conference on spent fuel storage.
HARRIS, D. L. Atomic Safety and Licensing Board Panel. 79/04/19 1pp.

7906100327 Forwards representative mail prepared by Citizens for Better Environments & NRC to discuss interest in issue of nuclear power.
GREGORY, J. P. Natural Resources Defense Council. 79/03/23 40pp

7906100337 Rebuttal for reconsideration of 790419 memo & order following special prehearing conference. Objects to admission of Contention 2 re specific issues re irradiated fuel. In Transit Certificate of Rev. and.
GREGORY, J. P. Branch 2. 79/05/04, 2pp

7906100339 Would not oppose admission of Contention 1 if revised to conform w/Contention 2 as admitted in Duke Power proceeding re safety of spent fuel in transit.
GREGORY, J. P. Branch 2. 79/04/06, 2pp.

DOCKETED ITEMS

7904210252 Applicant action for reconsideration of 790419 memo & order of clarification of 790409 order re physical security of
 BSM Supporting documentation & Certificate of Due care
 STEPHOE-F John, Lincoln & Balle 79/CM/07 100

790506082 Grants AMI 790504 motion suggesting alternative language
for Convention & Ordinance 110000 motion to reconsider
admissibility of Conventions 6 & 81
MINDLELLIN, C.L. Atomic Safety and Licensing Board Panel 79/05/1A
4a

7906200468 Concludes NRC & Citizens for Better Environ have standing based on criteria of ALAB-339 Both have established interest in nuclear power issues & are authorized to represent members in proceedings
MILKOLLIN, G. L. Atomic Safety and Licensing Board Panel 79/05/29/dua

J. Insurance & Indemnity Information

7906040187 Forwards executed Amends 21-21.9 & 1 to Indemnity Agreements
9-10, 9-47.3-59 & 9-86, respectively
FOIA, R D Commonwealth Edison Co 79/05/29 Eca

7906120860 Forwards Endorsements 100 & 101 to HADLV Policy HF-22 &
Endorsements 49 & 50 to HADLV Policy HF-54
00185.J Commonwealth Edison Co. 79/06/03 Sas

F. Querying license stage documents & correspondence

7706200239 Requests two controlled copies of site emergency plans & implementing procedures, site maps showing location & grid station number of onsite & offsite environ. monitoring stations & site maps used for dose determinations
NEFFLER:J G Region D, Chicago, Office of the Director 79/05/17
18

7906200035 Responds to IE Bulletin 79-03 Forwards info re environ
qualification of Class IE equipment required to function
under accident conditions & info re use & maint of ABCO
solenoid valves
RSCD.C Commonwealth Edison Co 79/06/14 09ac

7906210190 Requests inclusion in drafts of NEDE-21944-F, "One-Quarter
Scale Pressure Suppression Pool Swell Test Program Plant
Unique Tests"
JANECOK,B F Commonwealth Edison Co 79/06/13 1p

9. Inspection reports, IE Bulletins & correspondence

790220017 Forwards IE Insp Regis 20-234/79-03 & 20-263/79-03 on
790207-08; 10-16, 21-22, 28 & 0301-02 & notice of violation
HLSHMAN, R Regis 3, Chicago, Reactor Operations Nuclear
Support Branch 79/03/12 Sus

--7906290020 Notice of violation from Insp on 790607-09:15-19:21-22:20 &
0301:02
* Region Q, Chicago, Reactor Operations Nuclear Support Branch
79/03/07 19

--793425002A IE Insp Rpts 20-254/79-05 & 20-265/79-05 on 790207-00.
[1-18,2]-22,23 & 0301-02 Noncompliance noted inadequate
positive control over high radiation area
0401220T1H00.H Region 3: Chrgs. Reactor Operations Nuclear
Support Branch RIDGM.H.D. GFESEARD.H.L. Region 3: Chicago.
Office of the Director 79/03/07 app

7903030048 Verwarda, H insp Repts 50-254/78-10 & 50-265/79-98 on
781101-03-07-08 & 790302 No noncompliance noted
HHSO, J A Region 3, Chicago, Office of the Director 79/04/00

--7906020056 IE Insp Repts 80-25479-10 & 80-262779-08 on 791016-03-07-00
 & 7906020056 IE Insp Repts 80-25479-10 & 80-262779-08 on 791016-03-07-00
 Firms qualifications for securing personnel
 POSTER, J.E., MADSEN, T.J., OSMAIER, J.S. Region 3, Chicago, Office
 of the Director 79/03/29 1800

790302001 Act receipt of 790405 ltr informing HRC of steps taken to correct violations noted in EE Insp Rept 50-23479-00
HETTINGER, R P Region 3, Chicago, Office of the Director
79/04/27 1a.

--790020014 Responds to HRC 790022 [tr re violations noted in IE Insp
Rept 50-294/79-08 Corrective actions special test written
to secure drywall cover dangers in open position
REED C. Commonwealth Edison Co, 79/04/03 3pp

7906200493 Response to IE Bulletin 79-08 Forwards info re review of TH3
incident Existing line isolation not important to EOCs
Injection
REED,C Commercial Edison Co 3806409 000

7906120002 Forwards IE Info Notice 79-15, "Lower Reactor Vessel Head
Insulation Supports Problem" - No action required
REPLER:J D Region 3, Chicago, Office of the Director 79/05/97

7904180009 Forwarded IE Insp Regis 80-284/79-11 & 80-263/79-09 on 3/10/81-20 Notice of violations withheld (ref 100FAG 7901 31000 1 & 2) Section 2 Chinese Redwood Forest 34000100

--7904180045 DE Insp Repts 80-284/79-11 & 80-265/79-09 on 790418-20
Details withheld (ref 10CFR2 770)
DELANOR, J L, CHRISTOFFER, S Region 3, Chicago, Office of the
Director HAD, J A Region 3, Chicago, Safeguards Branch
79/02/08 Jm

790610001 Forward 1E Bulletin 79-10, "Regualification Training
Program Statistics - Written response required
KEPLER, J D Region 3- Chicago, Office of the Director 79/05/1
1a

7906100079 Forward: IE Info Notice 79-12: "Attempted Damage to New Fuel
Assemblies"
REPLER, J O Region 3, Chicago Office of the Director 79/05/11
1a

7906000194; Forwarded IE Circular 79-08, "Attempted Extortion - Law
Enforced U"
REFFLER, J O Region 3, Chicago, Office of the Director 79/05/
18

7906130082 Forwarded IE Bulletin 79-11. "Faulty Overcurrent Trip Device
in Circuit Breakers for Engineered Safety Sys - Licensee
action required
REFFLER, J G Region 3, Chicago, Office of the Director 79/05/22
in

790620080 Forwards IE Info Notebook 79-13, "Indication of Low Water Level in Oyster Creek Reactor"
RSPFLER, J B Region 3, Chicago, Office of the Director 79/03/24

• Periodic operating reports & related correspondence

7906190246 Monthly operating report for May 1979
 000015 0 Compucon/Edison Co 29/06/79 28p

Q Reportable occurrences, LERs & related correspondence

7706060280 Forwarded LHM 79-009/00L-0
R&I INSTRUCTIONS: 10 COMMUNALITE ELLISON CA 79/05/11 is

--7706060245 LER 79-029/0GL-0 on 790429 while measuring HSBV 16m1 switch
ing positions. 10 of 12 switches were set greater than 10X
of HSBV closure. Caused by lack of precise field callist of
exact limit switch trip point. Special procedure developed
1406040400.0. Commonwealth Edison Co. 79/05/11. Dan

7906270202 Forwards LER 79-019/003-0
KAI INDIANAPOLIS, IN Commonwealth Edison Co 79/06/118 16

--PW0270205 LER 79-087/SOL-9 on 790820 vacuum breaker 1-fail-029 fa
to give closed indication Caused by binding on valve stem
not allowing disk to shut Defective bushing & end pecking on
valve stem replaced
LNECHLN Commonwealth Edison Co 790810 3pp

ROSEB 50-255 PALISADES NUCLEAR PLANT

0 Adjudicatory correspondence

7906260049 Requests opportunity to testify at 790309 replacement
hearing in SA Joseph. NE
0000.01 Affiliation Unknown 79/05/00 1a

790602047 Applicant answer opposing Great Lakes Energy Alliance 790
response Response does not cure defects found in marilee
substantive Alliance petition to intervene should be denied
Certificate of Evc encl
COLLEEN M I Iahan, Lincoln & Beale, 79/05/04 ffp

--790613003 Monthly operating report for May 1979
BOSTON, P. J. Consumers Power Co 7/9/05/03 App

Reportable occurrences, ISRs & related correspondence

790610329 Forwarders LER 79-025/03L-0 & 79-021/03L-0
BOSTON, P. J. Consumers Power Co 7/9/05/02 App

--790610398 LER 79-023/03L-0 on 790604 during routine surveillance of safety-related shutdown-R-W (main steam line) had no visible oil level. Oil leakage from nozzle caused by failed O-ring, attributed to old age being replaced.
* Consumers Power Co 7/9/05/02 App

--790610352 LER 79-021/03L-0 on 790607 during routine surveillance of safety-related shutdown-R-W (main steam line) had no visible oil level. Oil leakage from nozzle caused by failed O-ring, attributed to old age being replaced.
* Consumers Power Co 7/9/05/02 App

790610030 Forwarders 790511 Heat Pollution Discharge Elimination By noncompliance notification re excessive neutralizer tank discharge
BOSTON, P. J. Consumers Power Co 7/9/05/01 App

--790609010 Heat Pollution Discharge Elimination By 790507 noncompliance notification re excessive neutralizer tank discharge caused by operating errors. Discharge procedures discussed w/operators
BOSTON, P. J. Consumers Power Co 7/9/05/01 App

790610025 Forwarders LER 79-025/03L-0
BOSTON, P. J. Consumers Power Co 7/9/05/01 App

--790610059 LER 79-023/03L-0 on 790610 leak in regenerative heat exchanger (RHX) shell side vent line resulted in degradation of chemical & vol control age caused by high porosity in weld. Weld ground out & repaired.
* Consumers Power Co 7/9/05/01 App

DOCKET 79-029 000498 FURNY NUCLEAR POWER STATION, UNIT 1

Insurance & liability information

790610078 Forwarders executed Amends 12 & 3 to Indemnity Agreements 8-32 & 8-02, respectively
BOSTON, P. J. Consumers Power Co 7/9/05/01 App

790610029 Forwarders Endorsements 40 & 41 to PMEL Policy HP-66
FELLSBORO, J. Marsh & McLennan, R. H. Nuclear Consultants, Inc. Div 7/9/05/04 App

Operating license stage documents & correspondence

790610018 Forwarders Amends 30, 44, 22 to License DPR-33, DPR-52 & DPR-68, respectively, safety evaluation & notice of issuance & availability re main to standby gas treatment age
SPRDLTGT, T. A. Operating Reactors Branch 3 (Pfr 790625) 7/9/05/04 App

--790610019 Amends 50, 44 & 22 to License DPR-33, DPR-52 & DPR-68, respectively, modifying electrical controls & instrumentation for standby gas treatment age
SPRDLTGT, T. A. Operating Reactors Branch 3 (Pfr 790625) 7/9/05/04 App

--790610018 Safety evaluation supporting Amends 30, 44 & 22 to License DPR-33 & DPR-52 & DPR-68, respectively
* Operating Reactors Branch 3 (Pfr 790625) 7/9/05/04 App

--790610018 Notice of issuance of Amends 50, 44 & 22 to License DPR-33, DPR-52 & DPR-68, respectively
SPRDLTGT, T. A. Operating Reactors Branch 3 (Pfr 790625) 7/9/05/04 App

790610075 Safety review of proposed hydrostatic pressure testing program & relief from testing requirements of ASME code. Section III of ASME code. Licensee has been granted
D1006, R. H. Office of Administration 7/9/05/01 App

790609070 Act receipt of 790418 request re proposed pump & valve testing program & relief from testing requirements of ASME code. Section III of ASME code. Licensee has been granted
D1006, R. H. Office of Administration 7/9/05/01 App

790610008 Forwarders Amends 51, 45 & 22 to License DPR-33, DPR-52 & DPR-68, respectively, safety evaluation & notice of issuance & availability
SPRDLTGT, T. A. Operating Reactors Branch 3 (Pfr 790625) 7/9/05/11 App

--790610014 Amends 51, 45 & 22 to License DPR-33, DPR-52 & DPR-68, respectively, authorizing change of power supply for certain low pressure coolant injection valves
SPRDLTGT, T. A. Operating Reactors Branch 3 (Pfr 790625) 7/9/05/11 App

--790610019 Safety evaluation supporting Amends 51, 45 & 22 to License DPR-33, DPR-52 & DPR-68, respectively
* Operating Reactors Branch 3 (Pfr 790625) 7/9/05/11 App

--790610018 Notice of issuance & availability of Amends 51, 45 & 22 to License DPR-33, DPR-52 & DPR-68, respectively
SPRDLTGT, T. A. Operating Reactors Branch 3 (Pfr 790625) 7/9/05/11 App

790610031 Forwarders general info re purge operations & analysis of purge valve operability
GILLESBAND, J. E. Tennessee Valley Authority 7/9/05/12 App

790610195 Forwarders "Secondary Containment Leak Rate Test-90-Day Rept"
GILLESBAND, J. E. Tennessee Valley Authority 7/9/05/12 App

--790610199 "Secondary Containment Leak Rate Test-90-Day Rept"
* Tennessee Valley Authority 7/9/05/12 App

6 Inspection reports, 18 Bulletins & correspondence

790610070 Forwarders IE Insp Repts 79-029/79-06, 30-260/79-06 & 30-264/79-06 on 790625-0082 IE Insp Repts Reactor Construction & Engineering Support Branch 7/9/05/20 App

--790610074 IE Insp Repts 30-269/79-06, 30-260/79-06 & 30-264/79-06 on 790625-0082 IE Insp Repts Reactor Construction & Engineering Support Branch 7/9/05/20 App

790610078 Responds to IE Bulletin 79-07 Forwarders results of seismic stress analysis of safety-related piping
GILLESBAND, J. E. Tennessee Valley Authority 7/9/05/26 App

790610020 Responds to IE Bulletin 79-08 Forwarders results of investigation re operational errors & age misalignments identified during TMI incident
GILLESBAND, J. E. Tennessee Valley Authority 7/9/05/24 App

790610013 Forwarders IE Circular 79-07, "Unexpected Speed Increase Reactor Motor Generator Set Resulted in Reactor Power Increase." No written response required
O'BRIEN, V. J. Region 2, Atlanta, Office of the Director 7/9/05/11 App

790610099 Act receipt of 790418 IE Insp Repts 30-260/79-06, 30-269/79-06 & 30-264/79-06
LEHMAN, R. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 7/9/05/07 App

790610064 Forwarders IE Bulletin 79-10, "Regulification Training Program Statistics." Written response required
O'BRIEN, V. J. Region 2, Atlanta, Office of the Director 7/9/05/11 App

790610018 Forwarders add'l response to IE Bulletin 79-08 re incorrect valve weights, reactor core isolation cooling piping
GILLESBAND, J. E. Tennessee Valley Authority 7/9/05/11 App

790610075 Responds to IE Bulletin 79-09 re GE Type AM-B breakers
GILLESBAND, J. E. Tennessee Valley Authority 7/9/05/21 App

8 Periodic operating reports & related correspondence

790610029 Forwarders monthly operating report for May 1979
BOSTON, P. J. Tennessee Valley Authority 7/9/05/11 App

DOCKETED ITEMS

--7706150083 Monthly operating report for May 1979
DEMARCO, J. D. Tennessee Valley Authority 7/9/81 34pp

7706250349 Forward revision to "Environ Radioactivity Levels, Annual Report 1978" to supersede report issued 770625 Revision corrects some radioactive levels. Conclusions in original report are still valid
GILLESPIE, J. E. Tennessee Valley Authority 7/9/81 1p

--7706250374 "Environ Radioactivity Levels, Annual Report 1978," revised version
Tennessee Valley Authority 8/4/79-3-872 7/8/81 31 48pp

DOCKET 33-260 BROWN FERRY NUCLEAR POWER STATION, UNIT 2
J Insurance & Indemnity Information

7706160230 Forwarded executed Amends 12 & 13 to Indemnity Agreements 8-82 & 8-82, respectively
PARISH, H. D. Tennessee Valley Authority 7/9/81 2pp

7706080229 Forwarded Endorsements 40 & 41 to 770610 Policy 7/7-06
FIELDMAN, J. March & Nolen, H. & Nuclear Consultants, Inc. Div 7/16/81 3pp

F Operating license change documents & correspondence

7706140053 Requests add info to complete review of changes to Tech Specs re startup test program
7706170, T. A. Operating Reactors Branch 3 (Pw 770625)
7/14/81 3pp

7706170134 Forwarded Amends 30, 44, 52 to License 8PR-33, 8PR-32 & 8PR-48, respectively, safety evaluation & notice of issuance & availability re need to standby gas treatment unit
7706170, T. A. Operating Reactors Branch 3 (Pw 770625)
7/19/81 3pp

--7706170139 Amends 30, 44 & 52 to License 8PR-33, 8PR-32 & 8PR-48, respectively, modifying electrical controls & instrumentation for standby gas treatment unit
7706170, T. A. Operating Reactors Branch 3 (Pw 770625)
7/19/81 3pp

--7706170145 Safety evaluation supporting Amends 30, 44 & 52 to License 8PR-33 & 8PR-32 & 8PR-48, respectively
Operating Reactors Branch 3 (Pw 770625) 7/19/81 3pp

--7706170146 Notice of Issuance of Amends 30, 44 & 52 to License 8PR-33, 8PR-32 & 8PR-48, respectively
7706170, T. A. Operating Reactors Branch 3 (Pw 770625)
7/19/81 3pp

7706250070 Ack receipt of 770614 request re proposed pump & valve testing program & relief from testing requirements of ASME code, Action Item in Fee Class II (single safety issue involved)
GILLESPIE, R. M. Office of Administration 7/9/81 1p

7706250080 Forwarded Amends 31, 45 & 52 to License 8PR-33, 8PR-32 & 8PR-48, respectively, safety evaluation & notice of issuance & availability
7706170, T. A. Operating Reactors Branch 3 (Pw 770625)
7/19/81 3pp

--7706250094 Amends 31, 45 & 52 to License 8PR-33, 8PR-32 & 8PR-48, respectively, authorizing change of power supply for certain low pressure coolant injection valves
7706170, T. A. Operating Reactors Branch 3 (Pw 770625)
7/19/81 3pp

--7706250099 Safety evaluation supporting Amends 31, 45 & 52 to License 8PR-33, 8PR-32 & 8PR-48, respectively
Operating Reactors Branch 3 (Pw 770625) 7/19/81 3pp

G Notice of Issuance & availability of Amends 31, 45 & 52 to 8PR-33, 8PR-32 & 8PR-48, respectively
G. T. A. Operating Reactors Branch 3 (Pw 770625)
1 3pp

de general safe re pump operations & analysis of reliability
Tennessee Valley Authority 7/19/81 12 3pp

de "Secondary Containment Leak Rate Test, 70-Day Report"
Tennessee Valley Authority 7/19/81 1p

--7706101049 "Secondary Containment Leak Rate Test, 70-Day Report"
Tennessee Valley Authority 7/19/81 35pp

G Inspection reports, IE Guidelines & correspondence

7706100710 Forwarded IE Insp Repts 30-259/79-08, 30-260/79-08 & 30-261/79-08 on 770625-0332 No noncompliance noted
LENNER, H. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 7/9/81 2p

--7706100714 IE Insp Repts 30-259/79-08, 30-260/79-08 & 30-261/79-08 on 770625-0332 No noncompliance noted Major areas inspected: Reactor shutdown & fire protection area & plant physical protection
BULLIVANT, F. W. H. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 7/9/81 2pp

7706170378 Response to IE Bulletin 79-07 Forwarded results of seismic stress analysis of safety-related piping
GILLESPIE, J. E. Tennessee Valley Authority 7/9/81 2pp

7706250053 Response to IE Bulletin 79-08 Forwarded results of investigation re operational errors & sign intelligibility identified during TMI incident
GILLESPIE, J. E. Tennessee Valley Authority 7/9/81 14pp

7706120013 Forwarded IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase" No written response required
GILLESPIE, J. E. Region 2, Atlanta, Office of the Director 7/9/81 1p

7706100849 Ack receipt of 770618 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-260/79-08, 30-261/79-08 & 30-262/79-08
LENNER, H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 7/9/81 1p

7706100666 Forwarded IE Bulletin 79-08, "Regulification Training Program Statistics" Written response required
GILLESPIE, J. E. Region 2, Atlanta, Office of the Director 7/9/81 1p

7706140150 Forwarded add response to IE Bulletin 79-04 re incorrect valve weights Reactor core isolation testing piping realized using correct weight of valves using check valves
GILLESPIE, J. E. Tennessee Valley Authority 7/9/81 3pp

7706250078 Response to IE Bulletin 79-08 re OE Type AR-2 breakers Breakers used in safety-related area at plant site found equipped w/undervoltage trip device
GILLESPIE, J. E. Tennessee Valley Authority 7/9/81 2pp

H Periodic operating reports & related correspondence

7706150079 Monthly operating report for May 1979
DEMARCO, J. D. Tennessee Valley Authority 7/9/81 1p

--7706150083 Monthly operating report for May 1979
DEMARCO, J. D. Tennessee Valley Authority 7/9/81 34pp

7706250084 Forward revision to "Environ Radioactivity Levels, Annual Report 1978" to supersede report issued 770625 Revision corrects some radioactive levels. Conclusions in original report are still valid
GILLESPIE, J. E. Tennessee Valley Authority 7/9/81 1p

--7706250074 "Environ Radioactivity Levels, Annual Report 1978," revised version
Tennessee Valley Authority 8/4/79-3-872 7/8/81 31 48pp

B Reportable occurrences, LERs & related correspondence

7706101029 Forwarded LER 79-034/03L-0
FOX, H. B. Tennessee Valley Authority 7/9/81 2pp

--7706101029 LER 79-034/03L-0 on 770627 prior to refueling shutdown, drydown pressure buildup report not taken caused by lack of understanding between operational & lab personnel Operating instructions amended to prevent recurrence
Tennessee Valley Authority 7/9/81 2pp

7706140322 30-260/79-08 on 770626 not inadvertently pulled three notches during attempt to reach criticality Cause not established Operator intervened
DEMARCO, J. D. Tennessee Valley Authority 7/9/81 3pp

DOCKETED ITEMS

35

7904120029 Forwards LER 79-01/017-0
FOL, H B Tennessee Valley Authority 79/06/06 1p

--790420035 LER 79-01/017-0 on 790504 while pulling control rods first rod 24-37 in group 3 was inadvertently withdrawn three notches Caused by unexplained factors Procedures were reviewed
Tennessee Valley Authority 79/06/06 2pp

7904120049 Forwards LER 79-00/031-0
FOL, H B Tennessee Valley Authority 79/06/06 1p

--790420039 LER 79-00/031-0 on 790510 scram accumulator level switch LS-2-05-04 for control rod drivelines 26-29 & 30-17 failed to give accumulation for high accumulator level Caused by switch failure
Tennessee Valley Authority 79/06/06 2pp

7904120064 Forwards LER 79-01/031-0
FOL, H B Tennessee Valley Authority 79/06/07 1p

--790420049 LER 79-01/031-0 on 790510 residual heat removal sys shutdown came apart upon manual for testing Caused by piston unsealing from rod after locking sys vibrated loose Subbar replaced & other knobbar tested
Tennessee Valley Authority 79/06/07 2pp

7904120142 Forwards LER 79-01/031-0
FOL, H B Tennessee Valley Authority 79/06/06 1p

--790420052 LER 79-01/031-0 on 790509 during post-refueling startup testing of RCIC Surpines: electronic overamped device could not be reset Caused by failure of electronic overamped device Airpas Model FSD 400 Overamped device replaced
Tennessee Valley Authority 79/06/06 2pp

7904200109 Forwards LER 79-01/017-0
FOL, H B Tennessee Valley Authority 79/06/06 1p

--790420057 LER 79-01/017-0 on 790506 during cold shutdown for refueling Local leak rate was found to exceed Tech Spec Levels Caused by deterioration of valve seats in main steam ventilation, Feedwater & RCIC sys Valves repaired
Tennessee Valley Authority 79/06/06 4pp

DECRET NO-201 H O ROBINSON PLANT, UNIT 2
F. Security, medical, emergency & fire protection plans

7904120201 Forwards amend to 790517 request to revise fire protection Tech Spec Encl revised pages correct typographical & numbering errors & change space re reactor containment
UTLEY, E E Carolina Power & Light Co 79/06/07 4pp

Q. Adjudicatory correspondence

7904200186 Forwards 791017 Amend 13, 791203 Amend 13, 791203 Amend 20 & 791207 & 790211 wire to clarify BOR Regl 2 w/ie wml
LAWREN, S H Branch 2 79/05/02 2pp

7904120274 Applicant motion to dismiss preexisting Disposition of power increase safety aspects should be governed by 10CFR 760.760 Upon that data is set for NRC response to amend Issue Certificate of Sys wml
TSMARR, D S F Shaw, Pittman, Potts, & Trowbridge 79/05/06 4pp

7904200482 Grant extension until 790930 for NRC to respond to 790522 applicant motion to dismiss proceedings re DC amend modification
MOL, J. P. Atomic Safety and Licensing Board Panel 79/06/08 1p

J. Insurance & indemnity information

7904080177 Forwards executed Endorsements 36, 39 & 40 to NELA Policy
M-LBO
GAWMAN, M E Carolina Power & Light Co 79/06/01 4pp

P. Operating license stage documents & correspondence

7904200499 Discuss review of 790515 submittal re acceptability of proposed isolation valve seal water sys Proposed sys is acceptable & can be used in future Type C Neut Safety evolution encl
SCHWABER, A. Operating Reactors Branch 1 (Pre 790625) 79/04/23 2pp

--790420030 Safety evaluation of isolation valve seal water sys Dye acceptable
Operating Reactors Branch 1 (Pre 790625) 79/04/23 2pp

7904040124 Forwards Amend 37 to License 07N-03 & notice of issuance & availability
SCHWABER, A. Operating Reactors Branch 1 (Pre 790625) 79/04/23 2pp

--7904040130 Amend 37 to License 07N-03, changing Tech Specs to incorporate NRC-requested changes re qualifications of sealwater & radiation control equipment
SCHWABER, A. Operating Reactors Branch 1 (Pre 790625) 79/04/23 4pp

--7904040132 Notice of issuance & availability of Amend 37 to License 07N-03
SCHWABER, A. Operating Reactors Branch 1 (Pre 790625) 79/04/23 2pp

7904120137 Forwards safety evaluation for Amend 36 to License 07N-03
SCHWABER, A. Operating Reactors Branch 1 (Pre 790625) 79/05/01 2pp

7904200190 Summary of 790510 meeting w/utley re auxiliary feedwater sys & amendments required of non-BOR plants in light of TMI-2
THARRELL, C H Operating Reactors Branch 1 (Pre 790625) 79/05/10 2pp

7904080294 Forwards license amend for radiological effluent Tech Specs
UTLEY, E E Carolina Power & Light Co 79/05/21 1p

--7904080295 License amend for radiological effluent Tech Specs
Carolina Power & Light Co 79/05/21 2pp

7904200306 Forwards add info requested on 790521 info to be used to prepare basis for continued plant operation in light of TMI-2 event
UTLEY, E E Carolina Power & Light Co 79/05/18 13pp

7904200308 Response to 790520 data request re feedwater lines Preliminary examination shows cracks exist in inlet lines Planned mode to sys will delay useful response to further info requests until completion
UTLEY, E E Carolina Power & Light Co 79/05/20 1p

B. Inspection reports, EE Bulletin & correspondence

7904200194 Forwards response to EE Bulletin 79-04A, "Operational Errors & Sys Readjustments Identified During TMI Incident" Detailed procedure changes will be developed to address problem of overriding of automatic actuation
PARR, S J Carolina Power & Light Co 79/04/24 2pp

7904200446 Forwards DE Info Notice 79-12, "Attempted Damage to New Fuel Assembly"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 1p

7904100894 Forwards EE Bulletin 79-10, "Regulation Training Program Statistics" Written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/11 1p

7904200511 Updates info re admitting add NRC inspector to facility Forwards vital area access list Requests site orientation re badge issuance, escort duties & emergency procedures for individuals listed
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 2pp

B. Periodic operating reports & related correspondence

7904101044 Forwards monthly operating report for May 1979
BANKS, H R Carolina Power & Light Co 79/06/08 1p

--7904101047 Monthly operating report for May 1979
BANKS, H R Carolina Power & Light Co 79/06/08 4pp

E. Reportable occurrences, LERs & related correspondence

7904070194 Forwards LER 79-01/031-0
BANKS, H R Carolina Power & Light Co 79/06/04 1p

DOCKETED ITEMS

--7904270200 LER 79-04/02L-0 on 790509 during fuel shuffle operation, detector voltage was lost on M-50 source range detector. Covered by power supply switchover of instrument bus from RCS-B to Inverter A. Operations personnel to be instructed. STANLEY, R. B. Carolina Power & Light Co. 79/06/04 App

7904270201 Forwards LER 79-01/02L-0
STANLEY, R. B. Carolina Power & Light Co. 79/06/04 App

--7904270205 LER 79-01/02L-0 on 790509 during refueling-high leakage detected in penetration pressurization air caused by failure of purge valve to seat properly. Seat adjusted. STANLEY, R. B. Carolina Power & Light Co. 79/06/04 App

790448494 Notification that reactor containment bldg integrity was breached when employee opened inner air lock when outdoor door was not sealed due to faulty mechanism. No release was made since containment purge was in progress. STANLEY, R. B. & ROBINSON, H. B. Carolina Power & Light Co. 79/06/04 App

790450501 Forwards LER 79-01/01T-0
STANLEY, R. B. Carolina Power & Light Co. 79/06/03 App

--790450505 LER 79-01/01T-0 on 790409 w/plant in hot shutdown-reactor containment integrity was breached. Covered by shroud belt in personnel air lock door. Locking mechanism shroud belt released & shroud belt returned to use. STANLEY, R. B. Carolina Power & Light Co. 79/06/03 App

7904570114 Forwards LER 79-01/01T-0
STANLEY, R. B. Carolina Power & Light Co. 79/06/03 App

--7904570118 LER 79-01/01T-0 on 790411 leak suspected to be in excess of 0.30 gallons/minute identified in one tube of C when generator No. 4 house identified. Lost repaired by explosive tube plugging. STANLEY, R. B. Carolina Power & Light Co. 79/06/03 App

DOCKET 50-042 BRIGHAM YOUNG UNIV. RESEARCH REACTOR

J Security & Safeguards Information

790459303 Forwards executed copy of Award # to Indemnity Agreement
B-20
VICKS, H. H. Brigham Young Univ. 79/06/13 App

6 Inspection reports, IE Bulletin & correspondence

790459303B Forwards IE Info Notice 79-1B, "Attempted Damage to New Fuel Assemblies"
BEPFLER, J. D. Region 3, Chicago, Office of the Director 79/05/11 App

DOCKET 50-043 MONTICELLO NUCLEAR GENERATING PLANT

F Security, medical, emergency & fire protection plans

790459302B Forwards supplemental info re physical security plan re implementation status info withheld (ref. 10CFR27.70)
HAYES, L. D. Northern States Power Co. 79/06/03 App

Applies to safety evaluation. Details review of
at Laboratory 79/06/20 App

Remaining issue does

7904570302 Forwards BAW77-1527, "Transport of Radioisotopes in Urban Environment: Safety Assessment." BAW77-74-21, cld 780614-4 & BAW77-74-21, cld 781010-4. W/see and
LEWIS, R. H. Branch 2 79/03/30, App.

F Operating license stage documents & correspondence

790459301 Requests site emergency plan & implementing procedures, site map showing location & grid numbers of units & offsite monitor monitoring stations & site maps used for offsite dose determinations or evacuation.
BEPFLER, J. D. Region 3, Chicago, Office of the Director 79/05/17 App.

7904593017 Discusses results of 790507-11 Insps re implementation of parts of approved security plan. Plan should be implemented in accordance with its LER withheld (ref. 10CFR27.70)
HAYES, L. D. Region 3, Chicago, Office of the Director 79/05/18 App

7904593018 Provides supplemental info re containment gassing during normal plant operation in further response to NRC 781129 LER
HAYES, L. D. Northern States Power Co. 79/06/07 App

G Inspection reports, IE Bulletin & correspondence

790459304 Forwards IE Insp Rpt 90-043/79-21 on 791024-05 & 790327-08. No noncompliance noted.
STANLEY, R. B. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/02 App

--790459305 IE Insp Rpt 90-043/79-23 on 791024-05 & 790327-08. No noncompliance noted. Major areas inspected: Inservice Insp & Main steam equalizer piping and
STANLEY, R. B. & ROBINSON, H. B. Region 3, Chicago, Office of the Director 79/05/20 App

7904593018B Forwards IE Bulletin 79-06, "Events Relevant to BAW77 Identified During THX Incident." Licensee action required.
BEPFLER, J. D. Region 3, Chicago, Office of the Director 79/04/14 App

7904593012 Forwards IE Insp Rpt 90-043/79-03 on 790327-09. No noncompliance noted.
STANLEY, R. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/26 App

--7904593013 IE Insp Rpt 90-043/79-02 on 790327-09. No noncompliance noted. Major areas inspected: Administrative & Mgt Control, sig. CM & Control in sampling & analytical measurements & license internal audits.
STANLEY, R. B. & ROBINSON, H. B. Region 3, Chicago, Office of the Director 79/04/24 App

7904593017 Responds to IE Bulletin 79-01 Switches similar to WNEC Model 610204 are used at facility but do not perform safety function. Service qualification data not
HAYES, L. D. Northern States Power Co. 79/04/30 App

7904593015 Responds to IE Bulletin 79-04 Valves using check valves are installed on offgas sys. Valve Engineering Corp. will determine weights & dynamic info to investigate in approx two weeks.
HAYES, L. D. Northern States Power Co. 79/05/01 App

--7904593016 Responds to IE Bulletin 79-04 Valve valve weights were incorrect but have been reanalyzed in compliance w/bulletin. No net required. Evaluation of valve use end.
HAYES, L. D. Northern States Power Co. 79/05/01 App

7904593018 Responds to IE Bulletin 79-04 Actions have been initiated re review of THX containment isolation design, auxiliary heat removal sys, reactor vessel outlet & plant operating procedures.
HAYES, L. D. Northern States Power Co. 79/05/01 App

7904593016B Forwards IE Circular 79-20, "Unexpected Speed Increase of Reactor Motor Controller Not Resulted in Reactor Power Increase." No written response required.
BEPFLER, J. D. Region 3, Chicago, Office of the Director 79/05/02 App

7904593019 Forwards IE Info Notice 79-11, "Loss of Reactor Vessel Head Inservice Support Problem." No action required.
BEPFLER, J. D. Region 3, Chicago, Office of the Director 79/05/07 App

7904593016 Forwards IE Bulletin 79-14, "Regulational Training Program Statistics." Written response required.
BEPFLER, J. D. Region 3, Chicago, Office of the Director 79/05/11 App

7904593019 Forwards IE Info Notice 79-02, "Attempted Damage to New Fuel Assemblies"
BEPFLER, J. D. Region 3, Chicago, Office of the Director 79/05/11 App

7904593015 Forwards IE Insp Rpt 90-043/79-04 on 790423-07 & notice of violation.
HAYES, L. D. Region 3, Chicago, Safeguards Branch 79/05/14 App

DOCKETED ITEMS

37

7904000004 Notice of violation from Insp on 790425-27
Region 3, Chicago, Office of the Director 79/03/29 1p

7904000012 IE Insp Rept 80-263/79-04 on 790425-27 Noncompliance noted
reporting unregulated BBN as irradiated in casing under
composition of ending inventory details withheld
100928 7901
FIRLEY, J. P., PATTERSON, J. P., HIND, J. A. Region 3, Chicago,
Befeguards Branch 79/05/16 1p

7904000018 Forwards IE Circular 79-08, "Attempted Extortion - Low
Enriched U"
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/05/18
1p

7904000019 Forwards IE Bulletin 79-15, "Facility Overcurrent Trip Device
on Circuit Breakers for Engineered Safety Sys" - Licensee
action required
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/05/22
1p

7904000021 Forwards IE Info Notice 79-13, "Indication of Low Water
Level in Outer Core Reactor"
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/05/29
1p

8 Periodic operating reports & related correspondence

7904000079 Forwards monthly operating report for May 1979
MYER, L. D. Northern States Power Co 79/06/07 1p

7904000078 Monthly operating report for May 1979
MYER, L. D. Northern States Power Co 79/06/04 App

SECRET 80-264 BOW CHEMICAL CO

8 Inspection reports, IE Bulletins & correspondence

7904000074 Forwards IE Insp Rept 80-264/79-01 on 790411-12 No
noncompliance noted
HIND, J. A. Region 3, Chicago, Befeguards Branch 79/05/04 App

7904000080 IE Insp Rept 80-264/79-01 on 790411-12 No noncompliance
noted Major areas inspected security plan details withheld
(see 100928 7901)
MACDONALD, T. J. Region 3, Chicago, Office of the Director
HIND, J. A., HIND, J. A. Region 3, Chicago, Befeguards Branch
79/05/02 1p

7904000082 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/05/11
1p

7904000084 Forwards IE Circular 79-08, "Attempted Extortion - Low
Enriched U"
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/05/18
1p

SECRET 80-265 SUMMIT-STATION, UNIT 2

8 Administrative correspondence

7904000121 Forwards 790316 order re shipment of spent fuel, admitting an
attorney in controversy contentious similar to those at issue
in present proceeding
ROBINSON, A. Z. Natural Resources Defense Council 79/03/20 1p

7904000346 Memo re standing & contentions of intervenors State of IL,
NRDC & Citizens for Better Environ following 790201 special
prehearing conference on spent fuel storage
HIND, J. A., Atomic Safety and Licensing Board Panel 79/04/19
10pp

7904000357 Forwards representative mail prepared by Citizens for Better
Environ & NRDC to disclose interest in issue of nuclear
power
ROBINSON, A. Z. Natural Resources Defense Council 79/03/29 App

7904000357 Motion for reconsideration of 790419 memo & order following
special prehearing conference. Objects to admission of
evidence & re specific breaches to irradiated fuel
in breach Certificate of RUC encl
OCCAMER, J. Branch 2 79/05/04 App

7904000359 Would not oppose admission of Contentment & if revised Co
contentment Co Contentment & as admitted in Duke Power proceeding
re security of spent fuel in transit
OCCAMER, J. Branch 2 79/04/06 App

7904000352 Applicant motion for reconsideration of 790419 memo & order
of clarification of 790417 order re physical security of
BNM Supporting documentation & Certificate of RUC encl
OCCAMER, J. Branch 2 79/05/07 10pp

7904000352 Grants HRC 790304 motion suggesting alternative language
for Contentment & Contentment motion to reconsider
admissibility of Contentment & & IL
HIND, J. A., Atomic Safety and Licensing Board Panel 79/05/16
App

7904000465 Concludes NRDC & Citizens for Better Envir have standing
based on criteria of ALAD-033 Both have established interest
in nuclear power issues, both are authorized to represent
their members in proceedings
HIND, J. A., Atomic Safety and Licensing Board Panel 79/05/22,
App

8 Insurance & indemnity information

7904000407 Forwards executed Amended St. 11.9 & 1 to Indemnity Agreements
B-10, B-47, B-59 & B-60, respectively
FOOLE, R. D. Commonwealth Edison Co 79/05/29 App

8 Operating license stage documents & correspondence

7904000329 Requester has controlled copies of site emergency plans &
implementing procedures, site maps showing location & grid
station number of analy & effluents environ monitoring
stations & site maps used for dose determinations
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/05/17
1p

7904000335 Response to IE Bulletin 79-01 Forwards info re environ
qualification of Class II equipment required to function
under accident conditions & info re use & status of AECB
collected valves
HIND, J. A., Commonwealth Edison Co 79/05/14 App

7904000100 Requests inclusion in schedule of NEED-21460-P, "On-Quarter
Scale Pressure Suppression Pool Swirl Test Program Plant
Design Tests"
HIND, J. A., Commonwealth Edison Co 79/06/15 1p

8 Inspection reports, IE Bulletins & correspondence

7904000507 Forwards IE Insp Repts 80-254/79-05 & 80-263/79-03 on
790207-03, 15-16, 21-22, 28 & 2301-02 & notice of violation
80-264/79-01 Region 3, Chicago, Reactor Operations Nuclear
Support Branch 79/03/13 App

7904000506 Notice of violation from Insp on 790207-03, 15-16, 21-22, 28 &
2301-02
Region 3, Chicago, Reactor Operations Nuclear Support Branch
79/03/07 1p

7904000506 IE Insp Repts 80-254/79-05 & 80-263/79-03 on 790207-03,
15-16, 21-22, 28 & 2301-02 Noncompliance noted Inadequate
positive control over high radiation area
CH188071038, H. Region 3, Chicago, Reactor Operations Nuclear
Support Branch 80-264/79-01, Region 3, Chicago,
Office of the Director 79/03/07 App

7904000504 Forwards IE Insp Repts 80-254/79-05 & 80-263/79-03 on
790207-03, 15-16, 21-22 & 790202 No noncompliance noted
HIND, J. A. Region 3, Chicago, Office of the Director 79/04/03
App

7904000504 IE Insp Repts 80-254/79-05 & 80-263/79-03 on 790207-03, 15-16,
21-22 & 790202 No noncompliance noted Major areas inspected
fireman qualifications for security personnel
FOOTER, J. E., HIND, J. A., OCHS, J. P. Region 3, Chicago, Office
of the Director 79/03/29 10pp

7904000503 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Support Problem"
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/05/07
1p

7904000509 Forwards IE Insp Repts 80-254/79-05 & 80-263/79-03 on
790207-03 Notice of violation withheld (see 100928 7901)
HIND, J. A. Region 3, Chicago, Befeguards Branch 79/05/16 App

DOCKETED ITEMS

7704180043 IE Insp Report 50-25479-11 & 50-26379-09 re 790416-20
Details withheld (ref 100292 790)
SALAMON, J. C. CHRISTOFFER, D. Region 3, Chicago, Office of the
Director 79/05/00
Region 3, Chicago, Safeguards Branch

7904121041 Forwards IE Bulletin 79-10, "Recertification Training
Program Statistics" Written response required
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/05/11
ip

7904190028 Forwards IE Info Notice 79-12, "Attenuated Damage to New Fuel
Assemblies"
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/05/11
ip

7904090196 Forwards IE Circular 79-08, "Attempted Sabotage - Low
Enriched U"
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/05/10
ip

7904100002 Forwards IE Bulletin 79-10, "Faulty Overcurrent Trip Device
in Circuit Breakers for Enriched Reactor" Licensee
Action Required
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/05/02
ip

7904060380 Forwards IE Info Notice 79-13, "Indication of Low Water
Level in Reactor Core Reactor"
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/05/09
ip

R Periodic operating reports & related correspondence

7904190046 Monthly operating report for May 1979
KAPPLER, J. D. Commonwealth Edison Co 79/04/02 35pp

S Reportable occurrences, LERs & related correspondence

7904020101 Forwards LER 79-010/02L-0
KALIVANAKIS, N. Commonwealth Edison Co 79/04/12 3p

7904020036 LER 79-040/03-0 re 790416 2A fuel pool radiation monitor
detected anomaly & failed again on 790502 & 03 Caused by
Failure of CR tube in sensor connector with tube finally
replaced w/Amperex 1020V
KAPPLER, J. D. Commonwealth Edison Co 79/06/12 3p

7904020037 Forwards LER 79-040/03-0 Corrects packet number of
original forwarding letter
KALIVANAKIS, N. Commonwealth Edison Co 79/04/13 3p

7904020015 Forwards LER 79-011/03L-0
KALIVANAKIS, N. Commonwealth Edison Co 79/04/14 3p

7904020017 LER 79-011/03L-0 re 790501 three cables not installed in
enclosure w/connections caused by error in cable routing
during initial coast shutdown of cables will take place
during Nov 1979 refueling outage
KALIVANAKIS, N. Commonwealth Edison Co 79/04/14 3pp

SECRET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

7904020104 Documents of Rev 790508 tables w/US Berggren re unit
security plan, Encl withheld (ref 100292 790)
KAPPLER, J. D. Wisconsin Electric Power Co 79/05/10 3p

H General correspondence

7904040197 Responds to 790202 letter transmitting petition on NRC-impeded
gatehouse security processing of reactor plant employees
Documents meant of dealing w/specific concerns Codes of
Federal Regulation except w/Encl
KALIVANAKIS, N. Division of Rules and Records 79/04/10 3pp

7904040002 Returns 790202 petition, re gatehouse security for plant
employees & proposed response Advise treatment as petition
for rulemaking under 100292 20A
KALIVANAKIS, N. Branch 3 79/04/02 3p

J Insurance & indemnity information

7904020192 Forwards executed Undertakings 37.08 & 39 to NELA Policy
177B & Undertakings 48.49 & 50 to NELA Policy 17F-03
KAPPLER, J. D. Wisconsin Electric Power Co 79/05/01 7pp

P Operating license stage documents & correspondence

7904020012 Summary of 790408 meeting w/Unit 1 Westinghouse in Bethesda,
MD re dash pot and air cracks on Westinghouse 2B-10 & 2B-25
air circuit breakers List of attendees, schematic design &
tripping characteristics encl
KAPPLER, J. D. Operating Reactors Branch 1 (Pw 790429)
79/05/02 7pp

7904020035 Forwards Amends 30 & 43 to Licenses 09F-24 & 09F-27,
respectively, safety evaluation & notice of issuance &
availability
KAPPLER, J. D. Operating Reactors Branch 1 (Pw 790429) 79/05/11
3pp

7904020036 Amends 30 & 43 to Licenses 09F-24 & 09F-27, respectively,
inspecting activation of safety injection, revving opening
loop for prewarmer power operated relief valves &
modifying power supplies
KAPPLER, J. D. Operating Reactors Branch 1 (Pw 790429)
79/05/11 14pp

7904020037 Safety evaluation supporting Amends 30 & 43 to Licenses
09F-24 & 09F-27, respectively
KAPPLER, J. D. Operating Reactors Branch 1 (Pw 790429)
79/05/11 3pp

7904020038 Notice of issuance & availability of Amends 30 & 43 to
Licenses 09F-24 & 09F-27, respectively
KAPPLER, J. D. Operating Reactors Branch 1 (Pw 790429)
79/05/11 3pp

7904020039 Summary of 790511 meeting w/Unit 1 Bethesda MD re auxiliary
feedwater sys List of attendees & main discussion encl
KAPPLER, J. D. Operating Reactors Branch 1 (Pw 790429)
79/05/16 4pp

7904020056 Summary of 790512 meeting w/Northern States Power Co re
auxiliary feedwater sys & related areas
KAPPLER, J. D. Operating Reactors Branch 1 (Pw 790429)
79/05/16 6pp

7904010224 Requests two controlled copies of site emergency plan &
implementing procedures, site maps showing location & grid
station numbers of onsite & offsite environs monitoring
stations & maps used for offsite dose determinations
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/05/17
3p

7904190018 Submits response to 790407 questionnaire re monitoring cable
gases offsite
KAPPLER, J. D. Wisconsin Electric Power Co 79/04/12 3pp

7904020101 Submits info re feedwater lines to steam generator in
response to 790508 request Feedwater pipe to Feedwater
control valve to be examined for cracking during first week
of Jul 1979
KAPPLER, J. D. Wisconsin Electric Power Co 79/04/30 3pp

7904020057 Submits responses to 790419 telcon inquiries re reactor
vessel support structure the controlled drawing encl
KAPPLER, J. D. Wisconsin Electric Power Co 79/04/20 3pp

O Inspection reports, IE Bulletins & correspondence

7904020103 Responds to IE Bulletin 79-07 Four cases associated
w/gases & liquid redwells vis at plant have been
examined All pipe structures & support & constraint loads
are within acceptable limits
KAPPLER, J. D. Wisconsin Electric Power Co 79/05/02 3p

7904040027 Responds to IE Bulletin 79-04 re weights of swing check
valves Forwards list of piping sys where valves are
installed, Review of review to be provided when available
KAPPLER, J. D. Wisconsin Electric Power Co 79/05/05 3pp

7904100132 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Support Problem" no action required
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/05/02
3p

7904020100 Act receipt of 790222 letter informing NRC of steps taken to
correct violations noted in IE Insp Report 50-044779-03 &
50-01/79-01
KAPPLER, J. D. Region 3, Chicago, Safeguards Branch 79/05/06 3p

DOCKETED ITEMS

7904200475 Forwarded application for amend to App A of Tech Spec 4.4.1 re voltage sensing delay
MILLEN, C. K. Public Service Co. of Colorado 7/9/81/19 1p

---7904200426 Application for amend to App A of License DPM-34 changing Tech Spec re voltage sensing delay
MILLEN, C. K. Public Service Co. of Colorado 7/9/81/19 4pp

G Inspection reports, IR Bulletins and correspondence

7904200132 Forwarded IE Insp Rept 50-247/79-04 on 790318-23 No noncompliance noted
HARRIS, D. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 7/9/81/05 2pp

---7904188107 IE Insp Rept 50-247/79-04 on 790318-03 No noncompliance noted Major upset inspected Refueling & main procedures
HARRIS, D. L. Region 4, Dallas, Office of the Director 7/9/81/05 4pp

7904100075 Forwarded IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" no action required
SEYFERT, K. V. Region 4, Dallas, Office of the Director 7/9/81/07 1p

7904100088 Forwarded IE Bulletin 79-10, "Regaladication Training Program Modification" no action required
SEYFERT, K. V. Region 4, Dallas, Office of the Director 7/9/81/11 1p

7904200029 Forwarded IE Info Notice 79-12, "Attempted Damage to Hot Fuel Assemblies"
SEYFERT, K. V. Region 4, Dallas, Office of the Director 7/9/81/11 1p

7904200040 Forwarded IE Info Notice 79-13, "Indication of Low Water Level in Operator Crash Bucket"
SEYFERT, K. V. Region 4, Dallas, Office of the Director 7/9/81/09 1p

7904200182 Forwarded "Incense Insp Region 3B & Region 10 Core Support Binch"
SMITH, F. E. Public Service Co. of Colorado 7/9/81/05 1p

7904100084 Forwarded addl info to JK Fuller 790318 Ibr Disturbance BCL-tended program re tube corrosion monitoring data
FULLER, J. K. Public Service Co. of Colorado 7/9/81/05 4pp

H Periodic operating reports & related correspondence

7904010217 Forwarded Interim Rept 1B, "Initial Approach to Power Tests (B-Series)" 791122-790922
HARRIS, D. L. Public Service Co. of Colorado 7/9/81/01 1p

---7904010223 Interim Rept 1B, "Initial Approach to Power Tests (B-Series)" 791122-790922
Public Service Co. of Colorado 7/9/81/01 4pp

7904100155 Forwarded monthly operating rept for May 1979
HARRIS, D. L. Public Service Co. of Colorado 7/9/81/05 1p

---7904100145 Monthly operating rept for May 1979
SMITH, F. E. Public Service Co. of Colorado 7/9/81/05 4pp

7904100299 Forwarded monthly operating rept for Apr 1979
HARRIS, D. L. Public Service Co. of Colorado 7/9/81/05 1p

---7904100302 Monthly operating rept for Apr 1979
SMITH, F. E. Public Service Co. of Colorado 7/9/81/05 7pp

I Reportable occurrences, LERs & related correspondence

7904180140 Forwarded PHO-79-679R
HARRIS, D. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 7/9/81/05 1p

7904180202 Forwarded PHO-79-679R
HARRIS, D. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 7/9/81/05 1p

7904180201 Forwarded PHO-79-679R & AP
HARRIS, D. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 7/9/81/05 1p

7904180409 Forwarded LER 79-054/017-0
HARRIS, D. L. Public Service Co. of Colorado 7/9/81/01 1p

---7904120408 LER 79-014/017-0 on 790220 punch gap of PCMV rupture disc
AP-17082 found out of tolerance w/under spec located by undocumented change of punch gap spec Tolerances returned to original spec
SMITH, F. E. Public Service Co. of Colorado 7/9/81/01 5pp

7904180410 Forwarded LER 79-013/021-0
HARRIS, D. L. Public Service Co. of Colorado 7/9/81/05 1p

---7904180418 LER 79-013/021-0 on 790207 during turbine surveillance testing-witness of RCR turbine disc #11702 found to be 820 psiG caused by earlier drift disc reactor
SMITH, F. E. Public Service Co. of Colorado 7/9/81/05 4pp

7904100001 Interim Rept 11, "Initial Approach to Power Tests (B-Series)"
Public Service Co. of Colorado 7/9/81/05 2pp

7904200430 Forwarded LER 79-004/023-1
HARRIS, D. L. Public Service Co. of Colorado 7/9/81/19 1p

---7904060437 LER 79-004/023-1 on 790201 during normal operation, cooling tower knockout activated 3.7 million gal./hour. Cause by failure to properly tag events due to incorrect completion of surveillance forms. Tubes changed & personnel instructed
SMITH, F. E. Public Service Co. of Colorado 7/9/81/19 4pp

SECRET 50-406 OSCEM: MAXWELL STATION, UNIT 1

D Regulatory correspondence

7904060224 Orders licensee to take immediate action to modify feedwater system & operating procedures to avoid down turbine units & completion of tests & to undertake long-term action as specified
CHILKOT, J. Office of the Secretary of the Commission 7/9/81/07 1pp

7904060144 Forwarded petition for reconsideration of 790207 order permitting Units 1 & 2 to remain in operation after Forwarded "Effect of Closing Oconee Nuclear Plant on Ability to Meet Summer Peak Demands"
HARRIS, D. L. Union of Concerned Scientists 7/9/81/01 1p

---7904060148 USC petition for immediate reconsideration of orders of 790209 order & for immediate shutdown of Units 1 & 2
HARRIS, D. L. Union of Concerned Scientists 7/9/81/01 4pp

---7904060170 "Review of Closing Oconee Nuclear Plant on Ability to Meet Summer Peak Demands"
HARRIS, D. L. Union of Concerned Scientists 7/9/81/01 10pp

7904060225 Forwarded Attachment A to B Taylor statement which was appended to USC petition for immediate reconsideration of orders of 790209 order for immediate shutdown of feeding
HARRIS, D. L. Dallas, Street & Bulfinch 7/9/81/01 1p

---7904200254 Details analysis of DOE info on reactor margins for summer 1979 estimated to be affected by shutdown of DOE plants
HARRIS, D. L. Office of Policy Evaluation 7/9/81/01 1p

J Insurance & insuring information

7904100331 Forwarded Attachment 34 & 35 to AVE Policy No-102 & Endorsements 92 & 93 to 198005 Policy Operator has 20 policies of 79-040601-0, State Power Co. 7/9/81/05 4pp

D Advisory Committee on Reactor Safeguards reports & correspondence

7904180289 Forwarded DOE analysis of small breaks in conjunction w/ emergency feedwater line failure Operator has 20 policies of 79-040601-0, State Power Co. 7/9/81/05 4pp

F Operating license stage documents & correspondence

7904200405 Forwarded 790418 Inspector findings re changes to plant procedures resulting from MC 790207 order. Procedures of order & operator understanding deemed adequate.
HARRIS, D. L. Office of Inspection & Enforcement 7/9/81/17 1p

DOCKETED ITEMS

41

--7904270068 Confirms procedural changes resulting from NRC 790307 order to reactor understanding of changes
JAFPE.F Region 2, Atlanta, Office of the Director 79/03/14 1p

7904270038 Reactor proposed Tech Specs revisions re surveillance mode to meet 1761001 & 790305 Submittals
FARMER.W O Duke Power Co 79/03/00 13pp

79042900327 Responds to 790518 request Forwards emergency feedwater flow test procedure
FARMER.W O Duke Power Co 79/04/01 1p

--7904300029 Emergency feedwater flow test procedure
Duke Power Co 79/03/31 12pp

7904300047 Advice that hydrostatic test required by 1936 ASME Boiler & Pressure Vessel Code is impractical until will follow 1977 edition requirement Request Notification if unacceptable
FARMER.W O Duke Power Co 79/04/11 2pp

7904300061 Responds to NRC 790318 for requesting schedule by 790410 completion of long-term mode described in Section 2 of 1962
790307 under AIB efforts satisfactorily executed
FARMER.W O Duke Power Co 79/04/14 1p

7904300093 Forwards responses to NRC 790325 ltr re feedwater lines Diagrams encl
FARMER.W O Duke Power Co 79/04/18 45pp

3 Inspection reports, IE Bulletins & correspondence

7904290088 BAW site inspector daily report on 790407 Plant status reactor at full power for repairs re condenser tubes
Testing continues to determine leak source
COTTELL.H ASHENDEN.J Region 2, Atlanta, Office of the Director 79/04/07 3pp

7904290134 BAW site inspector daily report on 790408 Plant status units 1 & 3 operating at 100% Unit 2 at 95% Hunting condenser tube leak on Unit 2 reported
COTTELL.H Region 2, Atlanta, Office of the Director 79/04/08 2pp

7904290148 BAW site inspector daily report on 790409 Plant status all reactors at full power Condenser leak has been corrected on Unit 3
COTTELL.H ASHENDEN.H C Region 2, Atlanta, Office of the Director 79/04/09 2pp

7904290219 BAW site inspector daily report on 790410 Plant status all reactors at full power w/all engineering safety feature age in svc.
COTTELL.H ASHENDEN.H C FORD.E P Region 2, Atlanta, Office of the Director 79/04/10 2pp

7904290287 BAW site inspector daily report on 790411 Plant status reactor at full power w/all training instructors scheduled for BAW simulator training on 790418
JAFPE.F Region 2, Atlanta, Office of the Director 79/04/11 2pp

7904290288 BAW site inspector daily report on 790412 Plant status all units running at full power Bax alignment verified for accessible components on emergency feedwater age
COTTELL.H FORD Region 2, Atlanta, Office of the Director 79/04/12 2pp

7904290318 BAW site inspector daily report on 790413 Plant status all reactors at full power w/o engineering safety feature equipment out of svc & no major fault
COTTELL.H BELLE.C A HOSM.M T Region 2, Atlanta, Office of the Director 79/04/13 2pp

7904290429 BAW site inspector daily report on 790414 Plant status Unit 2 operating at 92% power, Units 1 & 3 at full power No major plant scheduled & all major equipment is operational
BELLE.C A HOSM.M T Region 2, Atlanta, Office of the Director 79/04/14 2pp

7904290540 BAW site inspector daily report on 790415 Plant status all units at 100% power w/o engineering safety feature equipment out of svc & no major plant scheduled
BELLE.C A HOSM.M T Region 2, Atlanta, Office of the Director 79/04/15 1p

7904290578 BAW site inspector daily report on 790417 Plant status all units at 100% power No major engineering safety feature age equipment out of svc
JAFPE.F Region 2, Atlanta, Office of the Director 79/04/17 1p

7904100062 Responds to IE Bulletin 79-008 Reactor protective age high BSC pressure signal not been lowered to not greater than 0.500 psi/pressure power operated relief valve signal raised to 2.450 psig
FARMER.W O Duke Power Co 79/04/21 1p

7904290354 BAW site inspector daily report on 790420 Plant status Units 1 & 3 at 100% power Unit 2 reduced to 95% due to water leak in turbine condenser line
JAFPE.F Region 2, Atlanta, Office of the Director 79/04/20 1p

7904100391 Admits that response to IE Bulletin 79-04 re Velen check valves will be submitted no later than 790505
FARMER.W O Duke Power Co 79/05/02 1p

7904240421 Supplemental response to item 3 of IE Bulletin 79-05 & 79-06 re licensed shift operators completing BAW simulator training
FARMER.W O Duke Power Co 79/05/06 1p

7904290065 Act receipt of IE Insp Repts 50-249/79-11, 50-270/79-11 & 50-287/79-11 re 790321-29 re engineering info
FARMER.W O Duke Power Co 79/05/09 1p

--7904290270 Forwards IE Insp Repts 50-249/79-11, 50-270/79-11 & 50-287/79-11 re 790321-29 re engineering info
LEWIS.E S Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/01 2pp

--7904290329 IE Insp Repts 50-249/79-11, 50-270/79-11 & 50-287/79-11 re 790321-29 re noncompliance noted Major areas inspected plant operations, followup of info notices, physical security & licensee event report
JAFPE.F Region 2, Atlanta, Office of the Director 79/04/28 2pp

--7904290329 IE Insp Repts 50-249/79-11, 50-270/79-11 & 50-287/79-11 re 790321-29 re noncompliance noted Major areas inspected plant operations, followup of info notices, physical security & licensee event report
JAFPE.F Region 2, Atlanta, Office of the Director 79/04/28 2pp

7904290483 Forwards IE Info Notice 79-12, "Adopted Damage to New Fuel Assemblies"
O'NEILL.J P Region 2, Atlanta, Office of the Director 79/05/10 1p

7904100040 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics" Written response required
O'NEILL.J P Region 2, Atlanta, Office of the Director 79/05/11 1p

7904290283 Act receipt of 790322 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-249/79-01, 50-270/79-01 & 50-287/79-01
O'NEILL.J P Region 2, Atlanta, Office of the Director 79/05/11 1p

--7904290284 Supplemental act 790322 ltr responding to item of noncompliance noted in IE Insp Repts 50-249/79-01, 50-270/79-01 & 50-287/79-01 will submit BAW within 30 days of discovery of event
FARMER.W O Duke Power Co 79/05/05 1p

--7904290350 Responds to NRC 790327 ltr re violations noted in IE Insp Repts 50-249/79-01, 50-270/79-01 & 50-287/79-01 Disputes item of noncompliance re late submittal of RO data fall on holiday
FARMER.W O Duke Power Co 79/05/05 2pp

--7904290359 Forwards IE Insp Repts 50-249/79-01, 50-270/79-01 & 50-287/79-01 re 790131-0201 & notice of violation
LEWIS.E S Region 2, Atlanta, Office of the Director 79/05/07 2pp

--7904290364 Notice of violation from Insp on 790131-0201
Region 2, Atlanta, Office of the Director 79/05/24 1p

--7904290371 IE Insp Repts 50-249/79-01, 50-270/79-01 & 50-287/79-01 re 790131-0201 Noncompliance noted failure to submit written repts within 30 days of discovery of event
COTTELL.H C O'NEILL.J P Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/24 4pp

DOCKETED ITEMS

7904200809 Forwards response to IE Bulletin 79-09 re OE Type AX-2/BA circuit breakers in safety-related systems are used as control rod drive and primary trip breakers & four are used in dc holding power supplies
PARKER, W D Duke Power Co 79/09/14 3pp

7904200920 Requests info re manual trap on low pressure level as stated in item 4P of IE Bulletin 79-088
WILLIAMS, F J Division of Project Management 79/09/18 3pp

7904200925 Informs of 3M 790328 notification that operator for valve 26P-80 inside Unit 2 containment bldg did not meet minimum qualification requirements Unit 1 continues to operate; Unit 2 valve repaired
PARKER, W D Duke Power Co 79/09/08 3pp

8 Periodic operating reports & related correspondence

7904201017 Forwards monthly operating report for May 1979
PARKER, W D Duke Power Co 79/05/15 1p

7904201073 Monthly operating report for May 1979
SEAWIG, J A Duke Power Co 79/06/10 17pp

7904201018 Forwards correction sheets to monthly operating report for May 1979
PARKER, W D Duke Power Co 79/06/25 1p

7904201019 Correction sheets to monthly operating report for May 1979
Duke Power Co 79/05/21 1pp

9 Repairable occurrences, LERs & related correspondence

7904200923 ED 26P/79-12 on 790507 quadrupole power trip was legend error; steady state limit caused by power increase after emergency feedwater pump flow capability test; power reduced to maintain trip
VITTO, D J Duke Power Co 79/05/07 1p

7904200930 ED 26A/79-18 on 790504 2,025 gallons uncollected water discharged from laundry & hot shower tank caused by incorrect valve lineup; Retained water sampled & proper pumping resumed
VITTO, D J Duke Power Co 79/05/24 1p

7904200920 Forwards LER 79-015/091-0
PARKER, W D Duke Power Co 79/06/07 1p

7904200934 LER 79-015/091-0 on 790504 laundry & hot shower tank A vent discharged air being sampled; caused by personnel error; Responsible parties identified
LEWIS, S R Duke Power Co 79/06/07 3pp

7904200934 Forwards LER 79-015/091-1
PARKER, W D Duke Power Co 79/06/25 1p

7904200923 LER 79-015/091-1 on 790504 laundry & hot shower tank A discharged prior to sampling; caused by personnel error; Personnel contacted; tank & related equipment marked & procedures revised
LEWIS, S R Duke Power Co 79/06/25 3pp

Y Hearing transcripts on non-safety matters

7904201023 Transcripts of 790518 meeting in Washington, DC re briefing on license under Pg 1-88 hearing exhibit 101
HEWITT, C H, J. OIL, HENRY, V, HORNED, S T Councilman 79/05/18 10pp

7904200940 Transcript of 790510 public meeting in Washington, DC re briefing by NRC on license under Pg 1-88
Office of the Executive Legal Director 79/05/18 80pp

U Congressional/Executive Correspondence

7904200941 Response to 790503 letter re B Anson inquiry about radiological impact of nuclear power plant cooling on drinking water; Response available PER 140-001
GOSSELINK, V, Office of the Executive Director for Operations 79/05/15 3pp

7904200944 Requests info re radiological impact of nuclear power plant cooling on drinking water in ref to BL Anson inquiry
LEWIS, S R House of Rep. 79/04/25 3pp

DOCKET 99-270 OGDNE NUCLEAR STATION, UNIT 2

3 Adjudicatory correspondence

7904200921 Orders litigants to take immediate action to modify feedwater system operating procedures to shut down certain units until completion of audit & to undertake long-term mode on specified
OHLIS, J J Office of the Secretary of the Commission 79/05/07 14pp

7904200944 Forwards petition for reconsideration of 790507 order permitting Units 1 & 2 to remain in operation; Also forwards "Effect of Closing Certain Nuclear Plants on Ability to Meet Summer Peak Demands"
HEISS, E H Union of Concerned Scientists 79/05/10 1p

7904200948 USC petition for immediate reconsideration of errors of 790506 order & for immediate shutdown of Units 1 & 2
HEISS, E H Union of Concerned Scientists 79/05/10 3pp

7904200970 "Effect of Closing Certain Nuclear Plants on Ability to Meet Summer Peak Demands"
TALBOT, V Union of Concerned Scientists 79/05/09 10pp

7904201024 Forwards Attachment A to V Taylor statement which was appended to USC petition for immediate reconsideration of errors of 790506 order for immediate shutdown of facility
HEISS, E H Sullivan, Herman & Sullivan 79/05/15 1p

7904201024 Details analysis of RCE info on reserve margins for summer 1979 estimated to be affected by shutdown of 356 plants
HEISS, E H Office of Policy Evaluations 79/04/24 1p

4 Insurance & indemnity information

7904200931 Forwards Endorsements 54 & 55 to ARI Policy NF-162 & Endorsements 40 & 41 to P&U Policy TP-41
SHAW, T D Duke Power Co 79/06/08 3pp

5 Advisory Committee on Reactor Safeguards reports & correspondence

7904200924 Forwards GDS analysis of small breaks in conjunction w/ emergency feedwater flow failures; Operator has 30 minutes to react; Initial feedwater flow prior to core recovery
BATES, A HSG Advisory Committee on Reactor Safeguards 79/05/23 1p

F Operating license stage documents & correspondence

7904200945 Forwards 790516 inspector findings re changes to plant procedures resulting from NRC 790507 order; Procedures of order & operator understanding deemed adequate
HEWITT, C H Office of Inspection & Enforcement 79/05/17 1p

7904200946 Confirms procedural changes resulting from NRC 790507 order & operator understanding of changes
JAMES, F Region 2, Atlanta, Office of the Director 79/05/14 1p

7904200923 Babbitt presented Tech Report revisions re surveillance tests to staff 790505 & 790506 submittals
PARKER, W D Duke Power Co 79/05/20 12pp

7904200927 Response to 790518 request forwards emergency feedwater flow test procedure
PARKER, W D Duke Power Co 79/06/01 1p

7904200927 Emergency feedwater flow test procedure
Duke Power Co 79/05/21 12pp

7904200947 Advises that hydrostatic test required by 1974 ASME Boiler & Pressure Vessel Code is impractical; Unit will follow 1977 edition requirements; Requests notification if unacceptable
PARKER, W D Duke Power Co 79/06/01 2pp

7904200948 Response re NRC 790518 letter requesting schedule for 790510 completion of long-term mode described in Section 2 of NRC 790507 order; All efforts satisfactorily executed
PARKER, W D Duke Power Co 79/05/11 1p

7904200928 Forwards responses to NRC 790507 letter re feedwater lines Diagrams and
PARKER, W D Duke Power Co 79/06/18 40pp

3 Inspection reports, IE Bulletins & correspondence

- 7904290288 BSW site inspector daily rept on 790407 Plant status reactor operating at 100 power for repairs to condenser tubes
Testing continues to determine leak source
COTTELL, W. A. Region 2, Atlanta, Office of the Director
79/04/07 App
- 7904290174 BSW site inspector daily rept on 790408 Plant status units 1 & 3 operating at 100% power Unit 2 at 100% power condenser leak has been corrected on Unit 2
COTTELL, W. A. Region 2, Atlanta, Office of the Director
79/04/08 App
- 7904290289 BSW site inspector daily rept on 790409 Plant status all reactors at full power Condenser leak has been corrected on Unit 2
COTTELL, W. A. Region 2, Atlanta, Office of the Director
79/04/09 App
- 7904290319 BSW site inspector daily rept on 790410 Plant status all reactors at full power all engineering safety features are in OK
JAMES, F. A. Region 2, Atlanta, Office of the Director
79/04/10 App
- 7904290387 BSW site inspector daily rept on 790411 Plant status reactor at full power w/ no known problems Training instructors scheduled for BSW simulator training on 790412
JAMES, F. A. Region 2, Atlanta, Office of the Director
79/04/11 App
- 7904290343 BSW site inspector daily rept on 790412 Plant status all units running at full power Sgs alignment verified for available components on emergency fanoutler sgs
COTTELL, W. A. Region 2, Atlanta, Office of the Director
79/04/12 App
- 7904290139 BSW site inspector daily rept on 790413 Plant status all reactors at full power w/ no engineering safety features equipment out of svc & no major malis
COTTELL, W. A. Region 2, Atlanta, Office of the Director
79/04/13 App
- 7904290388 BSW site inspector daily rept on 790414 Plant status Unit 2 operating at 100% power Units 1 & 3 at full power No major malis scheduled & all major equipment is operational
COTTELL, W. A. Region 2, Atlanta, Office of the Director
79/04/14 App
- 7904290400 BSW site inspector daily rept on 790415 Plant status all units at 100% power w/ no engineering safety features equipment out of svc & no major malis scheduled
COTTELL, W. A. Region 2, Atlanta, Office of the Director
79/04/15 App
- 7904290398 BSW site inspector daily rept on 790417 Plant status all units at 100% power No major engineering safety features equipment out of svc
JAMES, F. A. Region 2, Atlanta, Office of the Director
79/04/17 App
- 7904100342 Response to IE Bulletin 79-038 Reactor protective sgs high RCS pressure setpoint has been lowered to not greater than 3,200 psig emergency power operated relief valve setpoint raised to 2,450 psig
PARKER, W. O. Duke Power Co
79/04/21 App
- 7904290456 BSW site inspector daily rept on 790420 Plant status Units 1 & 3 at 100% power Unit 2 reduced to 92% due to water leak in turbine condenser sgs
JAMES, F. A. Region 2, Atlanta, Office of the Director
79/04/20 App
- 7904100325 Clarifies that response to IE Bulletin 79-04 re Valen check valves will be submitted no later than 790326.
PARKER, W. O. Duke Power Co
79/05/02 App
- 7904040421 Supplemental response to item 3 of IE Bulletin 79-05 & 79-05A re licensed shift operators completing BSW simulator training
PARKER, W. O. Duke Power Co
79/05/04 App
- 7904020243 Ack receipt of IE Insp Repts 30-269/79-11, 30-270/79-11 & 30-267/79-11 on 790321-28. No proprietary info.
PARKER, W. O. Duke Power Co
79/05/09 App
- 7904290379 IE Insp Repts 30-269/79-11, 30-270/79-11 & 30-267/79-11 on 790321-28. No noncompliance noted plant operations. Followup of info notices, physical security & LES JAMES, F. A. Region 2, Atlanta, Office of the Director
Support Branch 79/04/28 App
- 7904290443 IE Info notice 79-12, "Attempted Damage to New Fuel Assemblies"
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director
79/05/10 App
- 7904100400 Forward IE Bulletin 79-10, "Regualification Training Program Statistics." Written response required
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director
79/05/11 App
- 7904290282 Ack receipt of 790328 ltr informing AEC of steps taken to correct violations noted in IE Insp Repts 30-269/79-01, 30-270/79-01 & 30-267/79-01
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director
79/05/11 App
- 7904290384 Supplemental to 790329 ltr responding to item of noncompliance noted in IE Insp Repts 30-269/79-01, 30-270/79-01 & 30-267/79-01. Will submit RCR within 30 days of discovery of event.
PARKER, W. O. Duke Power Co
79/05/20 App
- 7904290390 Response to IE 790327 ltr re violations noted in IE Insp Repts 30-269/79-01, 30-270/79-01 & 30-267/79-01. Disputes item of noncompliance re late submittal of RCR due date fell on holiday.
PARKER, W. O. Duke Power Co
79/05/22 App
- 7904290299 Forward IE Insp Repts 30-269/79-01, 30-270/79-01 & 30-267/79-01 on 790321-0201 & notice of violation
LEHMAN, N. C. Region 2, Atlanta, Office of the Director
79/05/27 App
- 7904290344 Notice of violation from Insp on 790321-0201
LEHMAN, N. C. Region 2, Atlanta, Office of the Director
79/05/28 App
- 7904290371 IE Insp Repts 30-269/79-01, 30-270/79-01 & 30-267/79-01 on 790321-0201 Noncompliance noted failure to submit written report within 30 days of discovery of event.
COTTELL, W. A. Region 2, Atlanta, Office of the Director
Operations Nuclear Support Branch 79/05/28 App
- 7904290329 Forward response to IE Bulletin 79-04 re GE Type AA-2/2A circuit breakers in safety-related sgs. Two are used as control Rod drive at primary trip breakers & four are used in dc feeding power supplies
PARKER, W. O. Duke Power Co
79/05/16 App
- 7904290420 Request info re manual trip at low pressure stated in item 4 of IE Bulletin 79-03.
WILLIAMS, P. J. Division of Project New

DOCKETED ITEMS

790429024 Forwards response to IE Bulletin 79-07 re OE Type AM-2/2A circuit breakers for safety-related app. Two are used as control mod drive as primary trip breakers & four are used in tie holding power trip lines
PARKER, M O Duke Power Co 79/05/15 App

790429020 Requests info re manual trip on low pressure level as stated in item 4F of IE Bulletin 79-030
MELISSA, P J Division of Project Management 79/05/18 App

790429022 Informs of BSW 790322 notification that operator for valve 200-20 inside Unit 2 containment bldg did not meet environ. qualification requirements Unit 1 continued to operate. Unit 2 valve replaced
PARKER, M O Duke Power Co 79/04/09 App

B Periodic operating reports & related correspondence

790429024 Forwards monthly operating report for May 1979
PARKER, M O Duke Power Co 79/04/15 App

--790429023 Monthly operating report for May 1979
SEAWIS, J A Duke Power Co 79/04/15 17p

790429024 Forwards correction sheets to monthly operating report for May 1979
PARKER, M O Duke Power Co 79/04/25 App

--790429023 Correction sheets to monthly operating report for May 1979
Duke Power Co 79/05/24 App

C Repairable occurrences, LERs & related correspondence

790429020 RD 04/17/79-12 on 790307 quadruplex power tilt was beyond error-adjusted steady state limit caused by power increases after emergency feedwater pump flow stability test. Power reduced to evaluate tilt
VITTO, D J Duke Power Co 79/05/07 App

790429020 RD 04/17/79-14 on 790324 2,338 gallons steam/water released from laundry & hot shower tank caused by incorrect valve lineup. Released water sampled & proper pumping resumed
VITTO, D J Duke Power Co 79/05/24 App

790429020 Forwards LER 79-015/017-0
PARKER, M O Duke Power Co 79/04/07 App

--790429024 LER 79-015/017-0 on 790324 laundry & hot shower tank discharged w/o being sampled. Caused by personnel error. Responsible parties counseled
LEWIS, S R Duke Power Co 79/04/07 App

790429024 Forwards LER 79-015/017-1
PARKER, M O Duke Power Co 79/04/25 App

--790429022 LER 79-015/017-1 on 790324 laundry & hot shower tank A discharged prior to sampling. Caused by personnel error. Personnel counseled. Tanks & related equipment marked & procedures revised
LEWIS, S R Duke Power Co 79/04/25 App

DOCKET 30-270 CONNIE NUCLEAR STATION, UNIT 2

D Application correspondence

790429024 Orders licensee to take immediate action to modify feedwater system & operating procedures, to shut down certain units until completion of tests & to undertake long-term work as specified
CHILDS, J J Office of the Secretary of the Commission 79/05/17 14p

790429024 Forwards petition for reconsideration of 790507 order permitting Units 1 & 2 to remain in operation. Also forwards "Effect of Closing Connie Nuclear Plants on Ability to Meet Summer Peak Demands"
KELSO, E R Union of Concerned Scientists 79/05/10 App

--790429024 USR petition for immediate reconsideration of errors of 790507 order & for immediate shutdown of Units 1 & 2
KELSO, E R Union of Concerned Scientists 79/05/10 App

--790429024 "Effect of Closing Connie Nuclear Plants on Ability to Meet Summer Peak Demands"
TAYLOR, V Union of Concerned Scientists 79/05/09 10p

790429024 Forwards Attachment A to V Region statement which was appended to USR petition for immediate reconsideration of errors of 790507 order for immediate shutdown of facilities
KELSO, E R Sheffield, Hansen & Pollock 79/05/10 App

--790429024 Details analysis of DOE info on reserve margin for summer 1979 estimated to be affected by shutdown of BSW plants
KELSO, E R Office of Policy Evaluations 79/04/24 App

J Inverness & Inverness Information

790429023 Forwards Endorsements 24 & 25 to ARE Policy AF-052 & Endorsements 40 & 41 to NADU Policy AF-01
SANDERS, P D Duke Power Co 79/04/25 App

G Advisory Committee on Reactor Safeguards reports & correspondence

790429020 Forwards RCSS analysis of small breaks in conjunction w/ emergency feedwater flow failures. Operator has 120 seconds to re-establish feedwater flow prior to core uncovering
SANDERS, P D Advisory Committee on Reactor Safeguards 79/05/03 App

P Operating license stage documents & correspondence

790429025 Forwards 790314 Inspector findings re changes to plant procedures resulting from NRC 790507 order. Procedures of order & operator understanding of changes
MULLER, N C Office of Inspection & Enforcement 79/05/17 App

--790429026 Confirms procedural changes resulting from NRC 790507 order & operator understanding of changes
JONES, P Region 2, Atlanta, Office of the Director 79/05/14 App

790429020 Submits proposed Tech Spec revision re surveillance slide to appx 791001 & 790708 submittals

1 matters

DOCKETED ITEMS

43

C Inspection reports, IE Bulletins & correspondence

790403008 BMW site Inspector daily rept on 790402 Plant status reactor operating at 90% power for repairs to condenser tubes Testing continued to determine leak source
COTTELL, W. ARNOLD, H. C. Region 2, Atlanta, Office of the Director 79/04/07 3pp

790403074 BMW site Inspector daily rept on 790408 Plant status units 1 & 2 operating at 100% unit 2 at VCC Hunting condenser tube leak on Unit 2 repaired
COTTELL, W. Region 2, Atlanta, Office of the Director 79/04/08 2pp

790403008 BMW site Inspector daily rept on 790409 Plant status all reactors at full power Condenser leak has been corrected on Unit 2
COTTELL, W. ARNOLD, H. C. Region 2, Atlanta, Office of the Director 79/04/09 2pp

790403067 BMW site Inspector daily rept on 790410 Plant status all reactors at full power w/ell engineering safety features set in vcc
WOLF, P. ARNOLD, H. C. FORD, R. P. Region 2, Atlanta, Office of the Director 79/04/10 2pp

790403087 BMW site Inspector daily rept on 790411 Plant status reactor at full power w/ell training problems Training instructors scheduled for BMW simulator training on 790418
WOLF, P. Region 2, Atlanta, Office of the Director 79/04/11 2pp

790403082 BMW site Inspector daily rept on 790412 Plant status all units running at full power Sp alignment verified for accessibility components on emergency feeder unit
COTTELL, W. FORD, R. P. Region 2, Atlanta, Office of the Director 79/04/12 2pp

790403038 BMW site Inspector daily rept on 790413 Plant status all reactors at full power w/ell engineering safety features set in vcc & no major maint
COTTELL, W. ARNOLD, H. C. FORD, R. P. Region 2, Atlanta, Office of the Director 79/04/13 2pp

790403029 BMW site Inspector daily rept on 790414 Plant status Unit 2 operating at 90% power, Units 1 & 3 at full power No major maint scheduled & all major equipment is operational.
BELLORE, S. A. FORD, R. P. Region 2, Atlanta, Office of the Director 79/04/14 2pp

790403048 BMW site Inspector daily rept on 790415 Plant status all units at 100% power w/ell engineering safety features equipment set off vcc & no major maint scheduled
BELLORE, S. A. FORD, R. P. Region 2, Atlanta, Office of the Director 79/04/15 1p

790403050 BMW site Inspector daily rept on 790417 Plant status all units at 100% power No major engineering safety features equipment set off vcc
WOLF, P. Region 2, Atlanta, Office of the Director 79/04/17 1p

790403062 Response to IE Bulletin 79-08 Reactor protective system high pressure setpoint has been lowered to not greater than 2.450 psig
FARMER, W. G. Duke Power Co 79/04/21 1p

790403056 BMW site Inspector daily rept on 790420 Plant status Units 1 & 3 at 100% power Unit 2 reduced to 92% due to water leak in turbine condenser box
WOLF, P. Region 2, Atlanta, Office of the Director 79/04/20 1p

790403071 Notification that response to IE Bulletin 79-04 re Valves check valves will be submitted no later than 790503
FARMER, W. G. Duke Power Co. 79/05/03 1p

790404041 Movement response to Item 5 of IE Bulletin 79-03 & 79-04 re licensed shift operators completing BMW simulator training
FARMER, W. G. Duke Power Co. 79/05/04 1p

790403063 Ack receipt of IE Regs 50-249/79-11, 50-270/79-11 & 50-277/79-11 on 790501-09 No noncompliance noted
FARMER, W. G. Duke Power Co. 79/05/09 1p

790403070 Forwarded IE Regs 50-249/79-11, 50-270/79-11 & 50-277/79-11 on 790501-09 No noncompliance noted
LOAN, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/05/01 2pp

790403079 IE Regs 50-249/79-11, 50-270/79-11 & 50-277/79-11 on 790501-09 No noncompliance noted Major areas inspected: plant operations, followup of info notices, physical security & LER
JAN, P. Region 2, Atlanta, Office of the Director
CANTRELL, P. F. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/28 2pp

790403043 Forwarded IE Info Notice 79-10. "Attempted Damage to New Fuel Assembly"
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director 79/05/10 1p

790403060 Forwarded IE Bulletin 79-10, "Qualification Training Program Statistics" written response required
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director 79/05/11 1p

790403085 Ack receipt of 790328 ltr informing NRC of steps taken to correct violations noted in IE Regs 50-249/79-01 & 50-270/79-01
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director 79/05/11 1p

790403084 Supplements to 790328 ltr responding to them of noncompliance noted in IE Regs 50-249/79-01, 50-270/79-01 & 50-287/79-01 Unit will submit RCR within 30 days of discovery of event
FARMER, W. G. Duke Power Co 79/05/20 1p

790403083 Response to NRC 790327 ltr re violations noted in IE Regs 50-249/79-01, 50-270/79-01 & 50-287/79-01 Disputes claim of noncompliance re late submission of RC One date fell on holiday
FARMER, W. G. Duke Power Co 79/05/22 2pp

790403039 Forwarded IE Regs 50-249/79-01, 50-270/79-01 & 50-287/79-01 on 790501-0201 & notice of violation
LEWIS, R. C. Region 2, Atlanta, Office of the Director 79/05/27 2pp

790403064 Notice of violation from Reg on 790501-0201
* Region 2, Atlanta, Office of the Director 79/05/26 1p

790403071 IE Regs 50-249/79-01, 50-270/79-01 & 50-287/79-01 on 790501-0201 Noncompliance noted Failure to submit written rept within 30 days of discovery of event
COTTELL, W. T. CANTRELL, P. F. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/28 2pp

790403082 Forwarded response to IE Bulletin 79-07 re GE Type AB-2/2A circuit breakers in safety-related area Two are used as control rod drive on primary trip breakers & four are used in de holding power supplies
FARMER, W. G. Duke Power Co 79/05/16 2pp

790403020 Request info re manual trip on low pressurizer level as stated in Item 4F of IE Bulletin 79-03
WILLIAMS, F. J. Division of Project Management 79/05/18 2pp

790403023 Inform of BMW 790502 notification that operator for valve 39B-05 Inactive Unit 2 containment flag did not meet required qualification requirements Unit 2 continued to operate Unit 2 valve replaced
FARMER, W. G. Duke Power Co 79/05/05 2pp

R Periodic operating reports & related correspondence

790403049 Forwarded monthly operating rept for May 1979
FARMER, W. G. Duke Power Co 79/04/13 1p

790403083 Monthly operating rept for May 1979
FARMER, W. G. Duke Power Co 79/04/19 12pp

790403048 Forwarded correction sheets to monthly operating rept for May 1979.
FARMER, W. G. Duke Power Co 79/05/23 1p

790403051 Correction sheets to monthly operating rept for May 1979
* Duke Power Co 79/05/23 2pp

S Reportable occurrences, LERs & related correspondence

790403080 Reg 50-249/79-11 on 790501-0201 223 gallons unaccounted water released from laundry & hot shower basins, caused by incorrect valve closing Released water sampled & proper pumping returned
VITTO, J. J. Duke Power Co 79/05/24 1p

DOCKETED ITEMS

- 7906133000 Forwards LER 79-015/017-3
PARKER, W D Duke Power Co 79/06/27 1p
- 7906130024 LER 79-015/017-0 on 790524 laundry & hot shower A tank discharged w/le being vented caused by personnel error
Responsible parties contained
LEWIS, S R Duke Power Co 79/06/07 3pp
- 7906120009 Forwards LER 79-006/002-0
PARKER, W D Duke Power Co 79/06/28 1p
- 7906130020 LER 79-006/002-0 on 790522 reactor protection sys channel 0 determined to be above specified limit of 4 pps caused by selected drifts. Switches recall for setpoint of 3.3 pps will be verified at 6-month intervals
LEWIS, S R Duke Power Co 79/06/28 3pp
- 7906120014 Forwards LER 79-015/017-3
PARKER, W D Duke Power Co 79/06/28 1p
- 7906130023 LER 79-015/017-1 on 790524 laundry & hot shower tank A discharged prior to sampling caused by personnel error
Personnel counseled, tanks & related equipment marked & procedures revised
LEWIS, S R Duke Power Co 79/06/28 3pp
- T Hearing transcript as non-identifiable matter
- 7906130005 Transcripts of 790518 meeting in Washington, DC re briefing on Dennee order Pg 1-88 meeting exhibits and
HENDERSON, J A - OLSINGER, V - HENDERSON, S T Commission 79/05/18 10pp
- 7906200050 Transcript of 790518 public meeting in Washington, DC re briefing by NRC on Dennee order Pg 1-88
A - Office of the Executive Legal Director 79/05/18 6pp
- U Congressional/Executive Correspondence
- 7906200091 Responds to 790422 ltr re 5 April inquiry about radiological impact of nuclear power plant cooling on drinking water. Forwards applicable PSD ltr and
OBERMAYER, L V Office of the Executive Director for Operations 79/05/15 2pp
- 7906200094 Responds info re radiological impact of nuclear power plant cooling on drinking water in ref to Re. health inquiry
WITT, M F House of Rep 79/05/20 2pp
- 7906010005 Summary of 790420 meeting w/rel in Bethesda, MD re modified radiological effluent Tech Specs
HODGSON, V L Operating Reactors Branch 3 ltr 79/06/25 79/06/27 2pp
- 7906200079 Ack receipt of 790428 ltr objecting to Class III fee requested in NRC 790614 ltr. Fee is due within 15 days after receipt of ltr
HODGSON, V L License Fee Management Branch 79/05/25 2pp
- 7906200070 Responds to 790392 request for exemption from Type A test frequency as required by 10CFR50.42, Section 115.4 (a)(3)
Request device test needed to verify completeness of corrective action plan
GRUBBS, S R Assistant Director for Engineers & Projects (Pro 79/05/25 2pp
- 7906150043 Defers submission of requested Class III fee for proposed License Change 74. Support ltr matter 4533 under legal review. Request to be filed by 790627
WABER, D. J. Vermont Yankee Nuclear Power Corp 79/06/12 1p
- B Inspection reports, IE Bulletin & correspondence
- 7906200171 Forwards IE Insp Rept 79-271/79-06 on 790320-20 No noncompliance noted
BRUNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/20 2pp
- 7906200173 IE Insp Rept 79-271/79-06 on 790320-20 No noncompliance noted. Major areas inspected: fuel shuffling program & activation, plant operation, planned startup testing program & station personnel change
MCAGUE, E C - STECH, T F Region 1, Philadelphia, Office of the Director 79/04/19 2pp
- 7906150044 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-2" - No written response required
STECH, T F Region 1, Philadelphia, Office of the Director 79/04/22 1p
- 7906000281 Responds to IE Bulletin 79-05 re items identified during TMI-2 event. All vessel level instrumentation was reviewed. Applicable procedures are being revised & containment air filtration sys installed
HODGSON, S E Vermont Yankee Nuclear Power Corp 79/04/27 2pp
- 7906140030 Responds to IE Bulletin 79-07 re seismic stress analysis of safety-related piping. No analysis using method listed in item 1 has been identified. Investigation continuing
HODGSON, S E Vermont Yankee Nuclear Power Corp 79/04/27 2pp
- 7906120014 Responds to IE Bulletin 79-04, "Incorrect Heights for Diving Check Valves Mfg by Valzer Engineering Corp." No such valves are in use in seismic Category 3 piping sys
GRUBBS, S R Vermont Yankee Nuclear Power Corp 79/05/03 1p
- 7906130077 Forwards IE Circular 79-07, "Unspecified Speed Increase of Reactor MFCG Generator Not Resulted in Reactor Power Increase." No written response required
GRUBBS, S R Region 1, Philadelphia, Office of the Director 79/05/02 1p
- 7906180141 Forwards summary of 790306 mgt meeting info presented during meeting revealed in withdrawal of item 3 of 791232 notice of violation
WITTEN, S R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/02 2pp
- 7906180171 Summary of 790306 mgt meeting w/rel in King of Prussia, PA re computerized personnel continuity return sys & withdrawal of apparent item of noncompliance
WITTEN, S R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/02 2pp
- 7906140030 Forwards vessel level indication drawing as add'l info to 790429 response to IE Bulletin 79-08
GRUBBS, S R Vermont Yankee Nuclear Power Corp 79/05/04 2pp
- 7906120005 Forwards IE info re 79-11, "Lower Reactor Vessel Head Inspection Support Problem." No action required
GRUBBS, S R Region 1, Philadelphia, Office of the Director 79/05/07 2pp
- 7906101030 Forwards IE Bulletin 79-10, "Regulification Training Program Mathematics." Written response required
GRUBBS, S R Region 1, Philadelphia, Office of the Director 79/05/11 1p

7904020142 Forwards IE Info Notice 79-02, "Attempted Range to New Fuel Assembly"
Region 1, Philadelphia, Office of the Director
08080, J H
79/05/11 1p

7904020305 Responds to IE Bulletin 79-07 GE Type AB-2 circuit breakers
are used on 400 volt safety-related buschangers
08080, J H Vermont Yankee Nuclear Power Corp 79/05/17 3pp

7904020311 Forwards IE Circular 79-06, "Attempted Extinction - Low
Enriched U"
Region 1, Philadelphia, Office of the Director
79/05/08 1p

7904020344 Responds to IE Bulletin 79-12, 12A & 12B Submits results of
search for spec of used mail used for fabrication of
reactor pressure vessel
08080, J H Vermont Yankee Nuclear Power Corp 79/05/25 2pp

7904020356 Requests relief from certain programmatic requirements of
AEC Section 16 re licensee inspec program until 08080
Request revised changes & table of contents for program
Tech Specs & relief request basis
08080, J H Vermont Yankee Nuclear Power Corp 79/05/20 3pp

8 Periodic operating 790315 & related correspondence

7904020355 Forwards monthly operating rep for May 1979
08080, J H Vermont Yankee Nuclear Power Corp 79/06/10 1p

7904020356 Monthly operating rep for May 1979
08080, J H Vermont Yankee Nuclear Power Corp 79/06/10 3pp

9 Reportable occurrences, LTRs & related correspondence

7904020355 Forwards LTR 79-007/031-0
COMNAV, N P Vermont Yankee Nuclear Power Corp 79/04/20 1p

7904020356 LTR 79-007/031-0 on 08080 during control rod testing,
red switch monitor A was bypassed several times caused by
supervisory misunderstanding. Misunderstanding clarified &
precautionary procedures added
COMNAV, N P Vermont Yankee Nuclear Power Corp 79/04/20 3pp

DOCKET 83-272 BARN NUCLEAR GENERATING STATION, UNIT 1

8 Adjudicatory correspondence

7904020348 Opposes licensee's motion for summary judgment. Licensee has
not carried burden of proof nor shown that contentions are
unconvincing. Affidavit & Certificate of Due and
08080, J H Belvedere, State of 79/03/20 3pp

7904020399 Item by interveners Coleman in opposition to licensee's
motion for summary judgment. Statement by interveners of
mail facts to dispute re interveners' Certificate 2
Affidavit of DC Minor & Certificate of Due and
08080, J H Belvedere, State of 79/03/29 3pp

7904020345 Confirms 790320 order outlining schedule of 790320
evidentiary hearing. Affix three questions re incident at TMI
for discussion at hearing
08080, J H Belvedere, State of 79/04/10 3pp

7904020352 Outline of intended cross-examination by still continuing
under denial of will 790423 objections to intervenor's
proffered testimony. Certificate of Due and
08080, J H Belvedere, State of 79/04/25 10pp

7904040368 Outline of areas of cross-examination submitted per 790329
pretrial order. Certificate of Due and
08080, J H Belvedere, State of 79/04/25 3pp

7904040441 Responds to ASLB 790418 order. Forwards ASLB 790427
testimony re accident hazards of spent fuel storage on
validity of intervenor Leuer Alloways Creek Township, PA
Certificate of Due and
08080, J H Belvedere, State of 79/04/25 3pp

7904040455 Testimony re ASLB 790418 order. Question 3 spent fuel storage
is unsafe, accidents are possible & potential harm is
extreme. Reactor must be closed down. Proof qualifications
and
08080, J H Belvedere, State of 79/05/27 27pp

7904050411 Outline of cross-examination of Coleman on Contentions 2 &
3 re spent fuel assemblies testing of barrel melt in environ
& section of cross-examination of Lower Alloways Creek on
Contention 1 re spent fuel pool. Certificate of Due
08080, J H Belvedere, State of 79/04/25 3pp

7904050572 Advises that NG Nechols on Exxon Nuclear Corp will replace
JH Nechols on licensee's witness panel. Proof qualification of
NG Nechols and
08080, J H Belvedere, State of 79/04/26 3pp

7904050572 Responds to request made during limited appearance in
proceeding 790329. 10298 & regulations defining procedures
for document requests. W/A and
08080, J H Belvedere, State of 79/04/27 1p

7904050616 Responds to request made during limited appearance in
proceeding 790329. 10298 & regulations defining procedures
for document requests. W/A and
08080, J H Belvedere, State of 79/04/27 3pp

7904050624 Notifies that evidentiary hearing recesses on 790710 in
Belmont NJ. Testimony to be offered at hearing shall be filed by
790507
08080, J H Belvedere, State of 79/05/14 3pp

7904050655 Revises to 790314 notice of hearing
08080, J H Belvedere, State of 79/05/17 1p

10 Insurance & indemnity information

7904050621 Forwards Endorsements 07-28 & 29 to NADU Policy 79-03
08080, J H Belvedere, State of 79/05/17 3pp

7904050628 Forwards executed Amendment to Indemnity Agreement 0-74
08080, J H Belvedere, State of 79/05/20 3pp

11 Operating license stops documents & correspondence

7904050670 Forwards requested info re main feedwater events, pressurizer
boiler & steam generator schematic diagram
LIR12312, P Public Service Electric & Gas Co of New Jersey
79/05/20 3pp

7904050676 Notification of 790325 meeting. Whitehouse & still in
Belmont NJ to discuss surface damage observed at fuel
assemblies
LIR12312, P Public Service Electric & Gas Co of New Jersey
79/05/20 3pp

7904050681 Forwards request for Amend to License 079-70 to change Tech
Specs for diesel generator breaker trip protection
Certificate of Due and
LIR12312, P Public Service Electric & Gas Co of New Jersey
79/06/14 3pp

7904050682 Requests amend to License 079-70 to change Tech Specs re
diesel generator breaker trip protection
LIR12312, P Public Service Electric & Gas Co of New Jersey
79/06/14 3pp

7904050684 Submits info requested by 790325 for re power feedwater
line design & fabrication history
LIR12312, P Public Service Electric & Gas Co of New Jersey
79/06/14 3pp

12 Inspection reports, IE Bulletins & correspondence

7904050629 Forwards IE Bulletin 79-05B, "Nuclear Incident at
TRI-Bogal." No written response required
08080, J H Belvedere, State of 79/04/23 1p

7904050681 Requests extension until 790504 to respond to IE Bulletin
79-07
LIR12312, P Public Service Electric & Gas Co of New Jersey
79/06/14 1p

7904050692 Responds to IE Bulletin 79-06A. Partial task force
established to conduct review & understanding of TRI-Bogal
events. Appropriate procedural revisions being prepared.
Supplemental response will be made prior to 790504.
LIR12312, P Public Service Electric & Gas Co of New Jersey
79/06/25 2pp

DOCKETED ITEMS

- 7906040098 Ack receipt of 790320 3tr informing NRC of steps taken to correct violations noted in IE Insp Rpt 50-272-79-03
CARROLL, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/23 1p
- 7906040079 Responds to NRC 790320 3tr re violations noted in IE Insp Rpt 50-272-79-03 Corrective actions fire watch posted at open penetration, penetrations sealed & cables refueled properly
SCHNEIDER, F. M. Public Service Electric & Gas Co. of New Jersey 79/03/28 3pp
- 7906040058 Forwards IE Insp Rpt 50-272-79-03 re 790320-0201 & 05 & notice of violation
CARROLL, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/28 2pp
- 7906040093 Notice of violation from Insp on 790320-0201 & 05
+ Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/28 3pp
- 7906040099 IE Insp Rpt 50-272-79-03 on 790320-0201 & 05 Noncompliance noted unsealed penetrations & failure to meet standards & verification for associated circuits
GALLINA, C. D. Region 1, Philadelphia, Office of the Director
SEDLER, J. M. Region 1, Philadelphia, Regulatory Branch
CARROLL, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/28 14pp
- 7906070209 Responds to IE Bulletin 79-04 re seismic Category 1 piping size W/D & 6-inch diameter valves Weights for A-inch valves have been corresponding confirmation of 3 & 6-inch weights from Vello
SCHNEIDER, F. M. Public Service Electric & Gas Co. of New Jersey 79/04/20 3pp
- 7906120197 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem." No action required
SHIBB, R. H. Region 1, Philadelphia, Office of the Director 79/05/07 2pp
- 7906101440 Forwards IE Bulletin 79-10, "Regulification Training Program Qualifiers." Written response required
SHIBB, R. H. Region 1, Philadelphia, Office of the Director 79/05/11 1p
- 7906060149 Forwards IE Info Notice 79-12, "Assumed Damage to New Fuel Assembly Lin." No action required
SHIBB, R. H. Region 1, Philadelphia, Office of the Director 79/05/11 1p
- 7906070206 Responds to IE Bulletin 79-12, "Atypical Weld Heli in Reactor Pressure Vessel Welds." Requests extension of response due date to 79/05/20
SCHNEIDER, F. M. Public Service Electric & Gas Co. of New Jersey 79/05/14 1p
- 7906090304 Forwards IE Circular 79-08, "Assumed Elevation - Low Elevation of"
SHIBB, R. H. Region 1, Philadelphia, Office of the Director 79/05/14 1p
- 7906060408 Forwards operating rpt for industrial waste treatment plant for May 1979
MILICH, M. J. Public Service Electric & Gas Co. of New Jersey 79/06/12 2pp
- 7906060309 Forwards discharge monitoring reports for May 1979
MILICH, M. J. Public Service Electric & Gas Co. of New Jersey 79/06/19 18pp
- 5 Reportable occurrences, LERs & related correspondence
- 7906040334 Forwards RD 79-03/04L
LIBRIEII, F. P. Public Service Electric & Gas Co. of New Jersey 79/04/04 1p
- 7906040300 RD 79-03/04L on 790317 required weekly river water samples for chloride determinations not taken during June, Sept or Dec 1979 Caused by personnel error Personnel re-instructed
COHEN, S. E. & MILICH, M. J. Public Service Electric & Gas Co. of New Jersey 79/04/04 2pp
- 7906040308 Forwards RD 79-03/04L
LIBRIEII, F. P. Public Service Electric & Gas Co. of New Jersey 79/04/17 1p
- 7906040371 RD 79-23/04L on 790416 with sample had 1-120 concentration which exceeded ten times control station concentration. Probably caused by Chinese weapon test, rather than disintegration of fuel rods
MILICH, M. J. Public Service Electric & Gas Co. of New Jersey 79/07/10 2pp
- 7906040375 Forwards LER 79-022/037-0
LIBRIEII, F. P. Public Service Electric & Gas Co. of New Jersey 79/04/17 1p
- 7906040377 LER 79-022/037-0 on 790404 Flucker & Porter 1002890 Transmitters for coolant flow monitoring had high output deviation during seismic test caused by vibration of mounting plate design change initiated
FRANCO, L. C. Public Service Electric & Gas Co. of New Jersey 79/04/17 3pp
- 7906040470 Confirms 790405 letter advising of RD instrument panels containing reactor coolant flow transmitters could fail during design base seismic event Corrective action will be required
MILICH, M. J. Public Service Electric & Gas Co. of New Jersey 79/04/04 1p
- 7906050303 Forwards RD 79-40/04L
LIBRIEII, F. P. Public Service Electric & Gas Co. of New Jersey 79/05/24 1p
- 7906050294 RD 79-40/04L on 790420 liquid waste disposal SWS monitor channel IR18 failed remote channel calibrator check Caused by failed tube in channel detector causing detector output to increase by factor of 2 Detector repaired
MILICH, M. J. Public Service Electric & Gas Co. of New Jersey 79/05/24 1p
- 7906040323 LER 79-04L number not used
+ Public Service Electric & Gas Co. of New Jersey 79/05/29 1p
- 7906050299 Forwards LER 79-027/013-1
LIBRIEII, F. P. Public Service Electric & Gas Co. of New Jersey 79/05/01 1p
- 7906050291 LER 79-027/013-1 on 790325 while providing backup protection in Hope Creek facility fresh water tanks were below Tech Spec required levels Caused by poor communications between facilities water level monitor
MILICH, M. J. Public Service Electric & Gas Co. of New Jersey 79/06/01 1p
- 7906050301 Forwards LER 79-025/013-1
LIBRIEII, F. P. Public Service Electric & Gas Co. of New Jersey 79/06/01 1p
- 7906050304 LER 79-025/013-1 on 790405 during cold shutdown w/irre pump 1 out of four flow pump 2 did not start when header pressure dropped to 75 psig pump started manually Caused by unit coil in A & B batteries
MILICH, M. J. Public Service Electric & Gas Co. of New Jersey 79/06/01 1p
- 7906050325 Forwards LER 79-044/031-0
LIBRIEII, F. P. Public Service Electric & Gas Co. of New Jersey 79/06/01 1p

DOCKETED ITEMS

47

--790400340 LER 79-04-032-L on 790304 during refueling operations. 28
Fuel assemblies were identified as having cracked, dented or
been dented. Corrective action will be taken after
evaluation complete. Cause not known at present time
HAPPEL, A. W. Public Service Electric & Gas Co. of New Jersey
79/04/01 2pp

7903070250 Confirms 790301 verbal report to E. Brunner, advising of
potential 30 linear cracking observed on pump impeller spurs
which were tested & also showed cracks. Impellers being
sent to vendor for testing
HEDURA, H. J. Public Service Electric & Gas Co. of New Jersey
79/04/01 1p

790313024 Forwards LER 79-04-011-0
LER11221, P. Public Service Electric & Gas Co. of New Jersey
79/04/03 1p

--790310231 LER 79-04-013-0 on 790302 auxiliary feedwater pumps
discharge valves demand reduction to 0% caused by deficient
surveillance procedure. Immediate change intended to leave
demand signal at normal value
HAPPEL, A. W. Public Service Electric & Gas Co. of New Jersey
79/04/03 2pp

790309025 Forwards LER 79-04-011-0
LER11221, P. Public Service Electric & Gas Co. of New Jersey
79/04/04 1p

--790316093 LER 79-04-011-0 on 790303 component cooling pump impellers
contained liner tears & presently in vane connection to
water. Primary Cause being misaligned. Defective impellers
will be replaced w/stainless steel components
HAPPEL, A. W. Public Service Electric & Gas Co. of New Jersey
79/04/04 2pp

790304027 Forwards LER 79-04-031-0
LER11221, P. Public Service Electric & Gas Co. of New Jersey
79/04/05 2pp

--790304044 LER 79-04-032-L on 790317 during refueling operations four
non-functional flow barriers were identified. Caused by
inertial error in shaft deficient penetrations were not
used during Nov 1978 Insp Penetrations properly sealed
HAPPEL, A. W. Public Service Electric & Gas Co. of New Jersey
79/04/05 1p

F. Hearing transcripts on non-confidential matters

7904000420 Errata to hearing transcript on facility application
RULHOLLEN, G. L. Atomic Safety and Licensing Board Panel 79/03/03
1p

DOCKET 90-274 U S GEOLOGICAL SURVEY RESEARCH REACTOR

B. Inspection reports, SE Bulletin & correspondence

790400028 Forwards IE Insp Rpt 90-274/79-02 on 790319-0202 Re
noncompliance noted
HARRIS, D. L. Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/10 2pp

--790301091 IE Insp Rpt 90-274/79-02 on 790319-0319 Re noncompliance
noted. Major areas inspected: organization, safety committee
reviews & audits, operations & maintenance records & new
superintendents re reactor operation
HARRIS, D. L., EVANETT, R. J. Region 4, Dallas, Reactor Operations
Nuclear Support Branch 79/04/12 7pp

790400004 Forwards IE Info Notice 79-12, "Attempted Damage to New Paul
Assembly"
SEVIER, K. V. Region 4, Dallas, Office of the Director 79/05/11
1p

DOCKET 90-275 DABLO CANYON NUCLEAR POWER PLANT, UNIT 2

A. Application/construction stage documents & correspondence

790400021 Summary of 790302 meeting w/USNR re radiological effluent
Tech. Branch
MUCHIN, E. C. Light Water Reactors Branch 1 79/05/06 2pp

790400013 Requests add info for review re environ qualification of
balance of plant equipment, facility CORRESPONDENCE protection for
containment penetrations, ventilation & auxiliary feedwater
w/ps, fire protection & inservice testing
GOLD, J. F. Light Water Reactors Branch 1 79/05/16 7pp

790309010 Requests add info re instrumentation qualification of
Barium transmitters
GOLD, J. F. Light Water Reactors Branch 1 79/04/20 2pp

790313016 Forwards repts re ventilation sys electromechanical devices
auxiliary feedwater valve motor operators, valves
qualification of conduits & fuel transfer tubes, re response
to 790301 request
CRANE, P. A. Pacific Gas & Electric Co. 79/04/11 20pp

--790310040 "Qualification Type Test Rpt Limiting Valve Actuators For
Class 1E Non Safety Primary Equipment"
HEEST, T., OENNEKE, W. L., FORHEDE, C. Limiting Valve Corp. 79/03/02
44pp

--790310022 "Rpt of Seismic Test on SRC-04 Valve Control (CSD) "
Pacific Gas & Electric Co. 79/03/20 72pp

--790310040 "Qualification Rpt for Conductor Modules for AM Nuclear One
Unit 2"
FEEDERICH, W. C. Limiting Valve Corp. 198-409 79/03/04 23pp

790310053 Requests add info re environ qualification of Barium
pressure & differential pressure TRANSMITTERS
CRANE, P. A. Pacific Gas & Electric Co. 79/04/14 1p

790302044 Forwards response to 790314 request for add info re main
steam line break inside containment w/proprietary &
nonproprietary versions of "Equipment Qualification" &
applications for withholding proprietary info
CRANE, P. A. Pacific Gas & Electric Co. 79/04/14 1p

--790302042 Application for withholding proprietary info from public
disclosure. Forwards proprietary & nonproprietary versions
of "Equipment Qualification"
CRANE, P. A. Pacific Gas & Electric Co. 79/04/14 2pp

--790304040 Nonproprietary version of "Equipment Qualification"
Winninghouse Electric Corp. 79/04/20 20pp

790305001 Forwards changes to input parameters to correct logic error
reported in Westinghouse App B EES model. Change accounts
for heating effect of auxiliary water injection
CRANE, P. A. Pacific Gas & Electric Co. 79/04/15 2pp

G. Administrative correspondence

790400043 Requests status of CL
RICH, J. P. Northridge California Ecumenical Council 79/03/21 1p

--790402046 Requests alternate power sources & conservation measures in
Ch. 12 of rev. of CP
RICH, J. P. Northridge California Ecumenical Council 79/03/14 1p

790400023 Requests halt re nuclear plant test
Affiliation Unknown 79/04/02 1p

--790402029 Recommends postponement of CL issuance until earth
safety factor is quantified
BATES, T. H., RAPILOFF, L., SAGAN, H. California State of 31
79/04/01 1p

--790403043 Forwards constituent ltr re facility cost near \$1
fault. Requests any info dealing w/matter
ANNUNZIO, R. House of Rep. 79/03/20 1p

--790403024 Expresses concern re reactor cost near active 94
fault
ANNUNZIO, R. D. Affiliation Unknown 79/03/18 1p

790400004 Opposes nuclear facility cost
PETERLIN, H. Affiliation Unknown 79/04/02 1p

--790403023 Opposes cost of facility near active seismologic fault
GILSON, A. Affiliation Unknown 79/04/02 1p

--790403009 Requests facility cost cease due to possible sea
hazard
REINHOLD, J., REINHOLD, P. Affiliation Unknown 79/03/31

--790403017 Requests facility cost cease
HEEST, T. Affiliation Unknown 79/04/02 1p

- 7906180028 Requests facility cost costs due to radiation hazards
HARRISON, D. J. Affiliation Unknown 79/04/03 1p
- 7906180029 Expresses concern over cost of facility
HARRISON, D. J. Affiliation Unknown 79/04/02 2pp
- 7906180028 Board notification semicircle experiment D-47-6 Unanticipated results re cladding temp require further study to determine safety significance Certificate of Env and
Nuclear Division 79/04/05 2pp
- 7906170027 Motion by joint interveners Elmer Barakine Preservation Conference San Luis Obispo Mothers for Peace Silver
League Action Club & J. Parfater for withdrawal of CP Certificate of Env and
FLEISCHNER, D. S. Fleischner, D. S. PHILLIPS, J. R. WILSON, D. S. Center for Law in the Public Interest 79/04/12 2pp
- 7906101059 Responds to 790331 re concerning unresolved questions about low level radiation & nuclear waste disposal Unit will submit plans for increasing spent fuel pool storage capacity in near future
WASSER, L. D. D. Assistant Director for Light Water Reactors 79/03/02 2pp
- 7906100310 Responds to re expressing opposition to plant operation because of proximity to active earthquake fault & problem of disposal of wastes stored in process of preparing decision re plant licensing
BORD, R. S. Division of Project Management 79/03/04 2pp
- 7906100341 Request by joint interveners that NRC reopen evidentiary hearings to address Class D accidents & emergency planning in alternative, non-directed certification on related questions Certificate of Env and
FLEISCHNER, D. S. Fleischner, D. S. PHILLIPS, J. R. WILSON, D. S. Center for Law in the Public Interest 79/03/09 11pp
- 7906100313 Forwards attachments & arrange sheet to joint interveners 790509 request to reopen is alternative request for directed certification Certificate of Env and
FLEISCHNER, D. S. Fleischner, D. S. 79/03/12 10pp
- 7906100315 Arrange sheet to joint interveners 790509 request to reopen is alternative request for directed certification
FLEISCHNER, D. S. Fleischner, D. S. 79/03/10 2pp
- 7906100338 Comments on Governor GE Brown 790804 ltr to JN Hendrix Request for extraordinary action of singling out plant for suspension of licensing proceedings to unanticipated
BORD, R. S. Pacific Gas & Electric Co 79/03/11 2pp
- 7906100491 Responds to 790405 & 86 ltr re opposition to facility costs over 8000; fault No evidence generated in NRC hearings for earthquakes at 8000 greater than 2.5
BORD, R. S. Office of Nuclear Reactor Regulation 79/03/14 2pp
- 7906100507 Defers ruling on reopening evidentiary hearings until NRC completes rule on effects of the on proceeding Other parties will be provided opportunity to request to rule
BORD, R. S. Nuclear Safety and Licensing Board Panel 79/04/05 2pp
- I. General correspondence
- 7906180027 Requests that earthquake potential be considered before granting CP
BORD, R. S. Affiliation Unknown 79/03/13 2pp
- 7906100297 Discusses reasons for delays in facility cost completion. re response to 790320 ltr of concern re indication of ability of plant to withstand possible earthquake in main dome of delay
BORD, R. S. Office of Nuclear Reactor Regulation 79/04/20 2pp
- 7906100297 Requests info re delays in completion of cost of facility Continued delay may preclude use of alternate energy sources to conserve oil
HARRISON, D. J. Affiliation Unknown 79/03/08 1p
- 7906100101 Objects to Rules 790405 ltr supporting postponement of CL. Intervenor supports development of nuclear power
CASTALDO, V. F. Affiliation Unknown 79/04/26 1p
- 7906100111 Requests CL be denied due to proximity to earthquake zone, ELSE, J. D. WATERHOUSE, E. Affiliation Unknown 79/04/26 2pp
- 7906170401 Responds to 790328 ltr re potential for delays in issuance of CL decision in order to satisfy antineutrino monitoring program concerned re plant ability to withstand effect of earthquakes
BORD, R. S. Division of Project Management 79/04/27 2pp
- 7906170403 Comments on granting of CL operation of plant should not be further postponed to satisfy anti-neutrino monitoring
HARRISON, D. J. Affiliation Unknown 79/03/28 1p
- 7906150220 Requests that CA Public Utility Commission withhold issuance of "certificate of necessity" for plant until Santa Barbara County can devise emergency evacuation plan
HARRISON, D. J. Affiliation Unknown 79/03/01 1p
- 7906170209 Ack receipt of 790323 ltr re S. Lashburn correspondence Forwards info giving brief history & status of licensing process N/A and
HARRISON, D. J. Office of Congressional Affairs 79/03/02 1p
- 7906140209 Discusses potential for delays in issuance of decision to CL in order to satisfy antineutrino monitoring program
BORD, R. S. Division of Project Management 79/03/04 2pp
- 7906180172 Responds to 790412 ltr re safety considerations involved in CL issuance
WASSER, L. D. D. Assistant Director for Light Water Reactors 79/03/10 2pp
- 7906100323 Responds to 790317 ltr re issuance of CP Forwards info re structural design, fuel element allowance for decommissioning, combustible storage, low level radiation effluents & transport of spent fuel
BORD, R. S. Division of Project Management 79/03/15 2pp
- D. Inspection reports, IE Bulletin & correspondence
- 7906100342 Forwards IE Insp Rpt 50-275/79-02 to 790328-0404 no compliance noted Rpt withheld ITR 100K 7901
BORD, R. S. Region 3, San Francisco, Safeguards Branch 79/03/02 2pp
- 7906100347 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required
BORD, R. S. Region 3, San Francisco, Office of the Director 79/03/07 1p
- 7906100349 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" No written response necessary
BORD, R. S. Region 3, San Francisco, Office of the Director 79/03/10 1p
- 7906100341 Forwards IE Circular 79-08, "Attempted Entarion - Low Enriched U"
BORD, R. S. Region 3, San Francisco, Office of the Director 79/03/16 1p
- 7906100401 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Licensee action required
BORD, R. S. Region 3, San Francisco, Office of the Director 79/03/22 1p
- 7906100374 Forwards IE Bulletin 79-12, "Recent Partial Burn at BWR Facilities" No written response necessary
BORD, R. S. Region 3, San Francisco, Office of the Director 79/03/31 1p
- B. Reportable occurrences, LERs & related correspondence
- 7906180219 Forwards 7907-79-0704
BORD, R. S. Region 3, San Francisco, Office of the Director 79/03/14 1p
- 7906180223 Forwards 7907-79-0703
BORD, R. S. Region 3, San Francisco, Office of the Director 79/03/21 1p
- 7906180038 Forwards 7907-79-0706
BORD, R. S. Region 3, San Francisco, Office of the Director 79/03/22 1p
- 7906180034 Forwards 7907-79-0705
BORD, R. S. Region 3, San Francisco, Office of the Director 79/03/20 1p

DOCKETED ITEMS

49

7904130482 Responds to 790501 ltr Details corrective actions for two items of non-compliance re testing of unit-bus safety checks & non-Class I conduct crawling over Class I equipment
CNAME:P A Pacific Gas & Electric Co 79/04/04 App

U Congressional/Executive Correspondence

7904130499 Forwards ltr from constituent containing Santa Barbara, CA Board of Supervisors resolution that NRC defer final action re license application until adequate safety checks have been completed
CAGOR:R1ND,R J House of Rep 79/04/24 App

7904130508 Responds to 790426 ltr Forwarding J Schatzinger 790418 ltr re Santa Barbara, CA Board of Supervisors resolution urging NRC to defer final licensing action on facility until safety can be assured
C0883CN,L V Office of the Executive Director for Operations 79/05/25 App

DOCKET 90-27A GEORGIA TECH RESEARCH REACTOR

7904130509 Forwards Amend 12 to Indemnity Agreement 8-30
WILSON:J H Georgia Institute of Technology 79/04/22 App

Q Inspection reports, IE Bulletins & correspondence

7904130513 Forwards IE Info Notice 79-12, "Attempted Damage to Hot Fuel Assemblies"
O'DRISCOLL:P Region 2, Atlanta, Office of the Director 79/05/10 App

DOCKET 90-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

7904130523 "Fire Protection in Operating Nuclear Power Stations, Peach Bottom Units 2 & 3 DER Review"
WILSON:J H, WHEATON:R A, F A Brookhaven National Laboratory 79/04/06 App

Q Administrators correspondence

7904130547 Action for extension until 790411 to prepare response to ALAB-509
SCINTO:J F Hearings Division 79/04/02 App

7904130540 Responds to 790322 request for info re status of evaluating proceeding to develop value for re-use in Table C-3 Dept & proposed rule will be sent to NRC by 790426
CIRIEN:RUBIN,E Hearings Division 79/05/26 App

7904130546 Action for reconsideration of ALAB-540 & severance from consideration established by ALAB-540 Admins issues not raised by any party & reports from "last case" procedure previously adopted Certificate of Rev and
CONNER:T B Conner, Moore & Conner 79/05/02 App

7904130559 NRC action for summary disposition re re-use issue was in error, ALAB-500 cancelled only 3 of 10 cases
WILSON:J H, WHEATON:R A, F A Brookhaven National Laboratory 79/05/25 App

7904130567 Request by utility that AEAAC grant summary disposition of all issues in consolidated notice proceeding until such decision as matter of license renewal issue as to null facts
WILSON:J H, WHEATON:R A, F A Brookhaven National Laboratory 79/05/25 App

7904130510 Statement of null facts re re-use proceedings, for which there is no genuine issue to be heard Dismissed
Defendants 1-7, 9-10, 20-24 & 26 Affidavit of RE Golden & supporting documentation and
WILSON:J H, WHEATON:R A, F A Brookhaven National Laboratory 79/05/25 App

7904130512 Supplemental RE Golden 790525 affidavit & utility 790409 memo re re-use notices & de novo approach Dismissed
Defendants 2, 9-10, & 25 Draft motion for summary disposition Certificate of Rev and
WILSON:J H, WHEATON:R A, F A Brookhaven National Laboratory 79/05/25 App

P Operating license stage documents & correspondence

7904130574 Forwards Amends 32 & 33 to Licenses 090-44 & 090-56 respectively, & notice of issuance & availability
IPFOL:ITO,T A Operating Reactors Branch 3 (Prc 790425) 79/05/23 App

7904130575 Amends 32 & 33 to Licenses 090-44 & 090-56 respectively, substituting two new conditions re shared discharge
IPFOL:ITO,T A Operating Reactors Branch 3 (Prc 790425) 79/05/23 App

7904130583 Notice of issuance & availability of Amends 52 & 53 to Licenses 090-44 & 090-56 respectively
IPFOL:ITO,T A Operating Reactors Branch 3 (Prc 790425) 79/05/23 App

7904130585 Forwards Amends 33 to Licenses 090-44 & 090-56, safety evaluation & notice of issuance & availability
IPFOL:ITO,T A Operating Reactors Branch 3 (Prc 790425) 79/05/23 App

7904130586 Amends 33 to Licenses 090-44 & 090-56
IPFOL:ITO,T A Operating Reactors Branch 3 (Prc 790425) 79/05/23 App

7904130587 Safety evaluation supporting Amends 33 to Licenses 090-44 & 090-56
Operating Reactors Branch 3 (Prc 790425) 79/05/23 App

7904130588 Discusses safety evaluation report review re facility fire protection Proposed mode represents significant increase in level of protection
NBL:R E Brookhaven National Laboratory 79/04/06 App

7904130590 Notice of issuance & availability of Amends 52 to Licenses 090-44 & 090-56
IPFOL:ITO,T A Operating Reactors Branch 3 (Prc 790425) 79/05/23 App

Q Inspection reports, IE Bulletins & correspondence

7904130599 Forwards IE Bulletin 79-02B, "Nuclear Incident at TMI-2" & written response received
O'DRISCOLL:P Region 1, Philadelphia, Office of the Director 79/04/22 App

7904130626 Responds to IE Bulletin 79-07 re seismic stress analysis & safety-related piping Plant did not use specified computer code for seismic stress analysis
DALLMEYER:L L Philadelphia Electric Co 79/04/24 App

7904130641 Bulletin info in response to IE Bulletin 79-08 Discusses work done in seismic analysis of safety-related piping program listing & program verification
DALLMEYER:L L Philadelphia Electric Co 79/04/25 App

7904130612 Responds to IE Bulletin 79-04, "Increased Risks for Spring Check Valves" by New Engineering Corp & others
also used in re-use & outboard containment isolation valves
Complete response will be forwarded by 790521
DALLMEYER:L L Philadelphia Electric Co 79/05/01 App

7904130670 Forwards IE Circular 79-07, "Unspecified Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase" & written response forwarded
O'DRISCOLL:P Region 1, Philadelphia, Office of the Director 79/05/02 App

7904130688 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Isolation System Problem" & written response received
O'DRISCOLL:P Region 1, Philadelphia, Office of the Director 79/05/02 App

7904130694 Forwards IE Bulletin 79-10, "Qualification Training Program Statistics" & written response received
O'DRISCOLL:P Region 1, Philadelphia, Office of the Director 79/05/11 App

7904130697 Forwards IE Info Notice 79-12, "Attempted Damage to Hot Fuel Assemblies"
O'DRISCOLL:P Region 1, Philadelphia, Office of the Director 79/05/11 App

7904130698 Responds to IE Bulletin 79-07 re SE Type AN-2 circuit breakers in use or planned for use in safety-related apps
DALLMEYER:L L Philadelphia Electric Co 79/05/14 App

DOCKETED ITEMS

7906080102 Forwards IE Circular 79-08. "Attempted Escalation - Low Enriched U."
SHELDON, H. Region 3, Philadelphia, Office of the Director
79/05/18 1p

B Periodic operating reports & related correspondence

7906100303 "Post-Operational Report 1 on Ecology of Cummings Pond" for July-Dec 1978
* Philadelphia Electric Co 79/03/31 25pp

7906100330 Forwards second surveillance & special study program rept. "PSMR-Postoperational Report 1 on Ecology of Cummings Pond for July-Dec 1978," prepared by RMC-Geological Div (M/S and) MILLER, H. B. Philadelphia Electric Co 79/04/07 1p

7906140021 Forwards "Environ Radiation Monitoring Program" for 1978 Rept 3a & "Radiological Regional Environ Monitoring Program" for 1978 Rept 4
MILLER, H. B. Philadelphia Electric Co 79/04/08 1p

7906140028 "Environ Radiation Monitoring Program" for 1978 Rept 3b, prepared by Intech Corp
* Philadelphia Electric Co 79/05/30 11pp

7906140023 "Radiological Regional Environ Monitoring Program," 1978 Rept 4 (prepared by Radiation Mgt Corp)
* Philadelphia Electric Co 79/05/31 13pp

7906140035 Forwards "Thermal & Biological Monitoring Program" Monthly Repts 07, 08 & 09 for Jan-Feb & Mar 1979, respectively
MILLER, H. B. Philadelphia Electric Co 79/04/08 1p

7906140457 "Thermal & Biological Monitoring Program," Monthly Rept 07, Jan 1979
* Philadelphia Electric Co 79/04/08 3pp

7906140463 "Thermal & Biological Monitoring Program," Monthly Rept 08, Feb 1979
* Philadelphia Electric Co 79/04/08 3pp

7906140466 "Thermal & Biological Monitoring Program," Monthly Rept 09, Mar 1979
* Philadelphia Electric Co 79/04/08 3pp

7906140483 Forwards "Thermal & Biological Monitoring Program," Monthly Rept 70, Apr 1979
MILLER, H. B. Philadelphia Electric Co 79/05/11 1p

7906140487 "Thermal & Biological Monitoring Program," Monthly Rept 70, Apr 1979
* Philadelphia Electric Co 79/04/30 10pp

7906190039 Forwards monthly operating rept for May 1979
ALDER, H. R. Philadelphia Electric Co 79/05/10 10pp

7906190321 Monthly operating rept for May 1979
ALDER, H. R. Philadelphia Electric Co 79/05/10 10pp

C Reportable occurrences, LERs & related correspondence

7906040341 Forwards LER 78-011/017-0
COONEY, H. J. Philadelphia Electric Co 78/03/07 3pp

7906040345 LER 78-011/047-0 on 790323 approx 80 gallons light diesel fuel oil drained into discharge canal caused by valve left open after use. Bypass stopped upon discovery; cleanup initiated & valve locked to control use
COONEY, H. J. Philadelphia Electric Co 78/03/07 1p

7906040346 RD 3-78-28/1P on 790328 uncorrected calculations show excessive accelerations on inboard reactor water cleanup app. elevation valve RD-15 during DSE caused by use of incorrect acceleration rate on valve
ULRICH, W. T. Philadelphia Electric Co 78/05/11 2pp

7906040356 RD 3-78-28/1P on 790328 analysis by A/E on reactor water cleanup piping in A/E resulted in reduction in acceleration values and restraint will be installed on valve 2 during present A/E refueling outage.
ULRICH, W. T. Philadelphia Electric Co 78/05/12 3p

7906040367 Forwards LER 78-028/017-0
COONEY, H. J. Philadelphia Electric Co 78/05/22 3pp

7906040368 LER 78-028/017-0 on 790328 one point on piping outdoors RD-12 RD-13 had above code allowable restraint to be added to code
COONEY, H. J. Philadelphia Electric Co 78/05/22 3p

7906040300 Forwards LER 78-043/032-0
COONEY, H. J. Philadelphia Electric Co 78/11/17 3pp

7906040304 LER 78-043/032-0 on 790329 another 23885-00 found unacceptable bleed rates & locking velocities caused by clogged bleed restrictors & low ambient temp during tests. Safety-related problems tested, repaired & results
COONEY, H. J. Philadelphia Electric Co 78/11/17 1p

7906070700 RD 3-78-12/1P on 790326 gaseous methane rate exceeded allowable Tech Specs limits for instantaneous release rate. Cause had lack of proper procedure lead to valve errors. Procedures will be revised & valves clearly identified
ULRICH, W. T. Philadelphia Electric Co 79/02/27 3pp

7906070710 Forwards LER 79-011/017-0
COONEY, H. J. Philadelphia Electric Co 79/02/29 3pp

7906070815 LER 79-011/017-0 on 790308 engineering review determined certain containment isolation valves incapable of closing against LCH pressure caused by design oversight. Failure and to assume "valve open" alarm to include seal jam pressure
COONEY, H. J. Philadelphia Electric Co 79/02/29 1p

7906080304 RD 3-79-16/1P on 790411 engineering review of plant valve closures indicated automatically qualified emergency use water app connected to heat exchanger in nonfunctionally qualified app caused by personnel error
ULRICH, W. T. Philadelphia Electric Co 79/04/12 2pp

7906070044 RD 3-79-24/1P control rod drive line return line outside containment support beam support calculations in response to IE Bulletin 79-04 indicates support for piping unsatisfactory
ULRICH, W. T. Philadelphia Electric Co 79/03/17 3pp

7906040300 Forwards LER 79-033/047-0
COONEY, H. J. Philadelphia Electric Co 79/03/25 2pp

7906040316 LER 79-033/047-0 on 790315 routine pH analysis of sewage plant effluents showed pH of 3.0 which exceeded Tech Specs caused by air blower failure which allowed dissolved oxygen to drop. Air O₂ saturation limit to become automatic
COONEY, H. J. Philadelphia Electric Co 79/03/25 1p

7906070302 LER 79-019/038-0 on 790301 during surveillance testing of normally open primary containment isolation valves, fire oxygen analyzer app isolation valves failed to close caused by binding of pistons in valve bodies. Valve parts replaced
COONEY, H. J. Philadelphia Electric Co 79/03/30 1p

7906070313 LER 79-028/038-0 on 790313 fire hose nozzles were missing from bus hose stations in turbine bldg. Cause not noted. Nozzles replaced & warning light added to inhibit removal
COONEY, H. J. Philadelphia Electric Co 79/03/31 1p

7906080367 Forwards LER 79-038/017-0
COONEY, H. J. Philadelphia Electric Co 79/04/05 3pp

7906080369 LER 79-038/017-0 on 790327 support for control rod drive line return line outside containment does not meet seismic requirements. Seismically qualified pipe support design completed. RDC to design included in Rept 790601
COONEY, H. J. Philadelphia Electric Co 79/04/05 1p

7906080390 LER 79-038/038-0 on 790323 solution temp in standby liquid control app found to be 2 P less than Tech Spec requirement for avoiding boron concentration caused by incorrect acceptable temp controller setpoint range
COONEY, H. J. Philadelphia Electric Co 79/04/05 1p

7906101019 Forwards LER 79-025/017-0
COONEY, H. J. Philadelphia Electric Co 79/04/04 3pp

7906101019 LER 79-025/017-0 on 790328 8 D classed tripped causing half-acram & half-isolation on Unit 3 caused by loss of control oil from diesel governor. Cracked pipe fitting was replaced
COONEY, H. J. Philadelphia Electric Co 79/04/04 1p

7906090422 Forwards LER 79-026/017-0
COONEY, H. J. Philadelphia Electric Co 79/04/08 3pp

DOCKETED ITEMS

- 79040042B LER 79-028/011-0 on 790324 during startup, offgas stack ventilation monitors were inoperable for 0.5-1.0 hr. due to failure of separating sample pump caused by broken belt. Belt replaced
CORMEY, H. J. Philadelphia Electric Co. 7/9/64/20 1p
- 79040042B LER 79-028/011-0 on 790324 reactor under cleanup, insular insulation system failed to automatically isolate in test
Controlled by misaligned limit switch on valve. Switch adjusted & test procedure streamlined
CORMEY, H. J. Philadelphia Electric Co. 7/9/64/20 1p
- 79040042B LER 79-028/011-0 on 790324 firewatch patrol was not conducted while fire detection was out of service for control
Cause by failure in communication. Procedure changed
CORMEY, H. J. Philadelphia Electric Co. 7/9/64/22 1p
- 79040041A Forwarded LER 79-028/011-0
CORMEY, H. J. Philadelphia Electric Co. 7/9/64/22 2pp
- 79040041B LER 79-028/011-0 on 790324 redundant low level NPL start signal from LIL-0-2-70C found inoperable. Caused by human error. Field wiring & connection drawing were corrected & investigation of event is being performed by engineering QA
CORMEY, H. J. Philadelphia Electric Co. 7/9/64/22 1p
- DOCKET 50-478 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2
F. Security, medical, emergency & fire protection plans
- 79040040C "Fire Protection in Operating Nuclear Power Stations, Peach Bottom Units 2 & 3 EER Review"
HALL, R. E., MACDONALD, C. A. Brookhaven National Laboratory
79040040C 7/9/64/04 4pp
- G Adjudicatory correspondence**
- 7904010047 Motion for extension until 790411 to prepare response to ALAB-504
SCHEIDT, J. F. Hearings Division 7/9/64/02 2pp
- 7904010040 Responds to 790322 request for info re status of rehearing proceeding to develop value for radar in Table G-0 Rept & proposed value will be sent to NRC by 790404
CHRISTENBURG, E. Hearings Division 7/9/64/26 34pp
- 7904010046 Motion for reconsideration of ALAB-540 & severance from continuation established by ALAB-540 Admits review not waived by any party & reports from "lead case" procedure previously adopted. Certificate of NRC will
CORMEY, T. B. Conner, Moore & Conner 7/9/64/20 15pp
- 7904010079 NRC motion for summary disposition re radar usage in error ALAB-540 considered only 5 of 16 cases. NRC motion re parties in other proceedings. NRC Certificate of NRC
SCHEIDT, J. F. Atomic Safety and Licensing Appeal Panel 7/9/64/20 3pp
- 79040200107 Request by title that ALAB grant summary disposition of all issues in consolidated radar proceeding. Until such decision is made by the court, parties agree to not file motions for summary disposition. Certificate of NRC will
SCHEIDT, J. F., Shaw, Pittman, Potter, & Troubridge, VORHOUT, H. H. LeBoeuf, Lamb, Leiby & MacIsaac CORMEY, T. B. Conner, Moore & Conner 7/9/64/25 4pp
- 7904020110 Statement of all parties re radar proceedings for which there is no genuine issue to be heard. Discussion alleged
Deficiencies (-7-9-58, 22-24 & 26 Affidavit of H. J. Goldman & supporting documentation will
SCHEIDT, J. F., Shaw, Pittman, Potter, & Troubridge, VORHOUT, H. H. LeBoeuf, Lamb, Leiby & MacIsaac CORMEY, T. B. Conner, Moore & Conner 7/9/64/25 34pp
- 7904020112 Supplemental H. J. Goldman 790322 affidavit & title 790404 memo re radar evidence & de minimus approach. Discussion alleged
Deficiencies (-7-9-58, 22-24 & 26 Affidavit of H. J. Goldman & supporting documentation will
SCHEIDT, J. F., Shaw, Pittman, Potter, & Troubridge, VORHOUT, H. H. LeBoeuf, Lamb, Leiby & MacIsaac CORMEY, T. B. Conner, Moore & Conner 7/9/64/25 19pp
- F Operating license stage documents & correspondence**
- 7904020074 Forwarded Amends 52 & 52 to Licenses DFR-44 & DFR-54 respectively, & notice of issuance & availability.
IPPL, LTD. T. A. Operating Reactors Branch 3 (Pre 790425) 7/9/64/02 3pp
- 7904020075 Notice of issuance & availability of Amends 52 & 52 to Licenses DFR-44 & DFR-54 respectively.
IPPL, LTD. T. A. Operating Reactors Branch 3 (Pre 790425) 7/9/64/02 2pp
- 7904020069 Forwarded Amends 53 to Licenses DFR-44 & DFR-54, safety evaluation & notice of issuance & availability.
IPPL, LTD. T. A. Operating Reactors Branch 3 (Pre 790425) 7/9/64/02 3pp
- 7904020070 Amends 53 to Licenses DFR-44 & DFR-54.
IPPL, LTD. T. A. Operating Reactors Branch 3 (Pre 790425) 7/9/64/02 4pp
- 7904020077 Safety evaluation supporting Amends 53 to Licenses DFR-44 & DFR-54.
Operating Reactors Branch 3 (Pre 790425) 7/9/64/23 18pp
- 7904020080 Discusses safety evaluation report review re Facility fire protection. Proposed mode represent significant increase in level of protection.
HALL, R. E. Brookhaven National Laboratory 7/9/64/04 3pp
- 7904020080 Notice of issuance & availability of Amends 53 to Licenses DFR-44 & DFR-54.
IPPL, LTD. T. A. Operating Reactors Branch 3 (Pre 790425) 7/9/64/02 2pp
- 7904020084 Forwarded proposed insp program for feedwater heaters & mod program for control rod drive line return line. To be implemented during Fall 1979 refueling outage.
DALLAMER, J. W. Philadelphia Electric Co. 7/9/64/02 2pp
- 7904020085 Proposed insp program for feedwater heaters & Philadelphia Electric Co. DFR-44 & DFR-54 7/9/64/25 10pp
- G Inspection reports, IE Bulletins & correspondence**
- 7904100029 Amends IE Bulletin 79-028 "Nuclear Incident at TMI-Suppl. 1" No written response required.
CORMEY, H. J. Region 1, Philadelphia, Office of the Director 7/9/64/23 1p
- 7904100026 Responds to IE Bulletin 79-07 re seismic stress analysis of safety-related piping. Plans did not use specified computer codes for seismic stress analysis.
SCHEIDT, J. F. Philadelphia Electric Co. 7/9/64/02 4pp
- 7904020084 Submits info in response to IE Bulletin methods used in seismic analysis of safety-related program including & program verification.
DALLAMER, J. W. Philadelphia Electric Co.

DOCKETED ITEMS

7906080108 Forwarded EE Circular 79-09: "Attempted Extension - Low Enriched U"
 OREGON, R. H. Region 1, Philadelphia: Office of the Director
 79/02/10 1p

B. Periodic operating reports & related correspondence

7906100530 "Post-Operational Report on an Ecology of Sewing Pond" for
 J. Edgar 1978
 Philadelphia Electric Co 79/03/26 25pp

7906100328 Forwarded nuclear surveillance & special study program report.
 "Post-Operational Report II on Behavior of Concomitant Pond
 for July-Dec 1978," prepared by RMC/Environmental Dev. & Eval.
 WILLIAMS, W. B. Philadelphia Electric Co 79/05/07 1p

7906100501 Forwarded "Environ Radiation Monitoring Program" for 1978
 Rept 36 & "Radiological Regional Environ Monitoring Program"
 for 1978, Rept 4
 WILLIAMS, W. B. Philadelphia Electric Co 79/05/08 1p

7906100528 Forwarded "Environ Radiation Monitoring Program" for 1978, Rept 36.
 Prepared by Johnson, C.
 Philadelphia Electric Co 79/05/09 11pp

7906100528 "Radiological Regional Environ Monitoring Program," 1978
 Rept 14, prepared by Radiation Mkt. Ctr.
 Philadelphia Electric Co 79/05/09 120pp

7906100455 Forwarded "Thermal & Biological Monitoring Program" Monthly
 Rept 57, 68 & 69 for Jan-Feb & Mar 1979, respectively
 WILLIAMS, W. B. Philadelphia Electric Co 79/06/08 1p

7906100494 "Thermal & Biological Monitoring Program," Monthly Rept 67,
 Jan 1979
 Philadelphia Electric Co 79/06/08 2pp

7906100462 "Thermal & Biological Monitoring Program," Monthly Rept 68,
 Feb 1979
 Philadelphia Electric Co 79/06/08 2pp

7906100466 "Thermal & Biological Monitoring Program," Monthly Rept 69,
 Mar 1979
 Philadelphia Electric Co 79/06/08 31pp

7906100463 Forwarded "Thermal & Biological Monitoring Program," Monthly
 Rept 70, Apr 1979
 WILLIAMS, W. B. Philadelphia Electric Co 79/06/11 1p

7906100467 "Thermal & Biological Monitoring Program," Monthly Rept 70,
 Apr 1979
 Philadelphia Electric Co 79/06/10 10pp

7906100509 Forwarded monthly operating report for May 1979
 COONEY, H. J. Philadelphia Electric Co 79/06/11 1p

7906100531 Monthly operating report for May 1979
 ALDEN, W. H. Philadelphia Electric Co 79/06/10 10pp

B. Reportable occurrences, LERs & related correspondence

7906080246 SD 2-79-08/1P on 790608 unconfirmed calculations show
 excessive accelerations on inboard reactor water cleanup sys
 isolation valve SD-15 during OOE caused by use of erroneous
 acceleration data on valve
 ULLRICH, W. F. Philadelphia Electric Co 79/06/11 2pp

7906040256 RD 1-79-08/1P on 790608 analysis by A/E on reactor water
 cleanup piping in #2011 resulted in reduction in
 acceleration values. AERs restraints will be installed on
 Unit 2 during present refueling outage.
 ULLRICH, W. F. Philadelphia Electric Co 79/06/12 1p

7906040367 Forwarded LER 79-036/047-0
 COONEY, H. J. Philadelphia Electric Co 79/06/22 2pp.

7906040368 LER 79-036/047-0 on 790608 one point on piping outdoors
 RD-12-15 had stress during OOE above safe allowable
 Reinsiting to be added to code
 COONEY, H. J. Philadelphia Electric Co 79/06/22 1p

7906020370 RD 3-79-16/1P on 790326 gaseous release rate exceeded
 allowable Tech Repts limits for instantaneous release rate
 caused by lack of proper procedure lead to violating errors
 Procedures will be revised & valves clearly identified
 ULLRICH, W. F. Philadelphia Electric Co 79/03/27 2pp.

7906020316 Forwarded LER 79-011/017-0
 COONEY, H. J. Philadelphia Electric Co 79/02/29 4pp

7906020316 LER 79-011/017-0 on 790328 engineering review determined
 certain containment isolation valves incapable of closing
 against LERs pressure caused by design oversight. Future work
 to expand "valve open" alarm to LERs and low pressure
 COONEY, H. J. Philadelphia Electric Co 79/02/29 1p

7906040304 RD 3-79-16/1P on 790411 engineering review of plant
 valve linings indicated unqualified qualified welding rvc
 water sys connected to heat exchanger in noncompliance
 qualified sys caused by personnel error
 ULLRICH, W. F. Philadelphia Electric Co 79/04/12 2pp

7906070564 RD 3-79-04/13 control rod drive-line failure line outside
 containment support. Dynamic support calculations in
 response to 2E Bulletin 79-04 indicate support for
 piping unsatisfactory
 ULLRICH, W. F. Philadelphia Electric Co 79/05/17 2pp

7906080287 Forwarded LER 79-028/017-0
 COONEY, H. J. Philadelphia Electric Co 79/06/01 2pp

7906080389 LER 79-038/017-0 on 790817 support for control rod drive
 line return line outside containment does not meet seismic
 requirements. Seismically qualified pipe support design
 completed. Plans to design scheduled to begin 790801
 COONEY, H. J. Philadelphia Electric Co 79/06/01 1p

7906100172 Forwarded LER 79-023/017-0
 COONEY, H. J. Philadelphia Electric Co 79/06/04 2pp

7906100174 LER 79-023/017-0 on 790818 S-E diesel tripped causing
 half-trip of half-trip of Unit 3 caused by loss of
 control oil from diesel governor. Checked pipe filling was
 replaced
 COONEY, H. J. Philadelphia Electric Co 79/06/04 1p

7906020422 Forwarded LER 79-024/017-0
 COONEY, H. J. Philadelphia Electric Co 79/06/03 2pp

7906020425 LER 79-024/017-0 on 790224 starting start-up/offen stop
 isolation valve was inoperable for 7-1/2 hrs due to failure of
 operating sample pump. Caused by broken belt. Belt replaced
 COONEY, H. J. Philadelphia Electric Co 79/06/03 1p

7906020275 LER 79-015/015-0 on 790323 automatic depressurization sys A
 actuation. Steam trap setting found 130° less than Tech
 Repts. Cause by setpoint drift of time delay relay. Relay
 reprogrammed, tested & returned to use
 COONEY, H. J. Philadelphia Electric Co 79/06/03 1p

7906020294 LER 79-014/021-0 on 790328 effluent source breaker 0293
 tripped on low air pressure. Caused by short circuit in light
 switch & circuit conductors on voltage relay. Relay contacts
 cleaned & switch removed pending replacement.
 COONEY, H. J. Philadelphia Electric Co 79/06/03 1p

DOCKET 90-280 BARRY POWER STATION, UNIT 1

Q. Adjudicatory correspondence

7906040415 Orders extension, until 790515, for NRC to review
 790201 denial of enforcement action
 OHLER, E. J. Office of the Secretary of the Commission 79/04/12
 1p.

7906040436 Grants NRC extension until 790424, for review of
 790201 denial of enforcement action
 OHLER, E. J. Office of the Secretary of the Commission 79/05/15
 1p.

H. General correspondence

7906020347 Responds to 790312 re shutdown of five nuclear power
 plants because of seismic concerns. Seismic design was not in
 accord w/accepted engineering practice. Failed piping could
 cause rupture during refueling shutdown. Benefits of nuclear
 power outweigh seismic risks
 BIRNBAUM, E. E. Affiliation Unknown, 79/02/15 2pp

7906020350 Expresses concern re shutdown of five nuclear power
 stations. Action requires energy crisis. Plant overhaul is more
 appropriate during refueling shutdown. Benefits of nuclear
 power outweigh seismic risks
 BIRNBAUM, E. E. Affiliation Unknown, 79/02/15 2pp

DOCKETED ITEMS

63

- 7903210418 Responds to 790319 ltr re 790313 orders to shut down five nuclear power plants NRC prefers to review situation in expedited & disciplined manner, to return plants to operation as soon as possible to public benefit & safety concerns
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/16 App
- 7903210424 Comments on NRC capitulations & cavalier acts Requests immediate reversal of undue decision to shut down five plants Requests more rational approach to legitimate safety concerns in future
FIMBIS, S. H. Affiliation Unknown 79/03/17 App
- 7903210509 Responds to 790314 ltr re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210513 Comments on 790313 orders shutting down five northeastern US nuclear power plants Requests investigation into actual probability of major seismic activity in region
BENTON, H. R. Affiliation Unknown 79/03/16 App
- 7903210520 Responds to 790313 ltr re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210528 Comments on 790313 orders shutting down five northeastern US nuclear power plants Requests investigation into actual probability of major seismic activity in this region
BENTON, H. R. Affiliation Unknown 79/03/16 App
- 7903210538 Responds to 790303 ltr re 790313 orders shutting down five nuclear plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210542 Comments on 790313 orders shutting down five northeastern US nuclear power plants Actions poorly reasoned
FULLER, W. S. Affiliation Unknown 79/04/02 App
- 7903210550 Responds to 790321 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210556 Comments on 790313 orders shutting down five northeastern US nuclear power plants Economic consequences for Maine as well as power shortages, override with prospect of earthquakes Plants should be reopened
GILLMAN, S. F. Affiliation Unknown 79/03/21 App
- 7903210560 Responds to 790307 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210566 Comments on 790313 orders shutting down five northeastern US nuclear power plants NRC should re-evaluate its antismelter attitudes
OFFICER, L. Affiliation Unknown 79/03/27 App
- 7903210569 Responds to 790303 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210573 Comments on 790313 orders shutting down five northeastern US nuclear power plants Plants should be reopened immediately, due to economic prospects of plant closing
WILSON, J. B. Affiliation Unknown 79/03/22 App
- 7903210576 Responds to 790322 ltr re President re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210580 Responds to 790328 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210586 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-conceived, considering current energy crisis
BENTON, H. R. Affiliation Unknown 79/03/22 App
- 7903210582 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-conceived
LISINSKY, P. F. Affiliation Unknown 79/03/28 App
- 7903210587 Responds to 790313 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210591 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-conceived
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210595 Responds to 790317 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210599 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-conceived
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210609 Responds to 790314 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210614 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-conceived
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210619 Responds to 790322 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210622 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-conceived & represents flagrant Federal govt Overreaction through regulatory process
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/22 App
- 7903210624 Responds to 790324 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210627 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-conceived
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/22 App
- 7903210632 Responds to 790317 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210638 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was poorly timed & economically ill-conceived
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/22 App
- 7903210643 Responds to 790313 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210644 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-conceived Requests date of last recorded earthquake
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/22 App
- 7903210651 Responds to 790322 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 App
- 7903210656 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-conceived, considering current energy crisis
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/22 App

DOCKETED ITEMS

- 7906270263 Responds to 790323 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7906270264 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-conceived
DEHARLE E H Affiliation Unknown 79/05/22 4pp
- 7906270265 Responds to 790313 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7906270266 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was unrepresentative act
RAFFINOS E L Affiliation Unknown 79/05/18 2pp
- 7906270267 Responds to 790323 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7906270268 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-conceived
ELLIS R C Affiliation Unknown 79/05/25 1p
- 7906270433 Responds to 790314 ltr re NRC 790303 orders to shut down five nuclear power plants NRC prefers to remove situation as expedited & discontinued matter. To return plants to operation w/o threat to public health & safety
BENTON H R Office of Nuclear Reactor Regulation 79/05/21 3pp
- 7906270448 States that NRC overreacted in closing five nuclear plants. Comments on impact of NRC action 79/05/25 forwarding ltr to NRC re shutdown of plants
HENSEY T P Affiliation Unknown 79/05/24 2pp
- 7906270501 Responds to Wilson re NRC order to shut down five nuclear plants because of seismic concern. Analysis techniques used in seismic design were inappropriate. Piping age failure could cause LOCA
BENTON H R Office of Nuclear Reactor Regulation 79/05/24 1p
- I. Insurance & indemnity information
- 7906102328 Endorsement 41 to NOLIA Policy NF-37
GIBSON T Mutual Atomic Energy Liability Underwriters 1p 79/05/10 1p
- 7906102331 Endorsement 42 to NOLIA Policy NF-37
GIBSON T Mutual Atomic Energy Liability Underwriters 1p 79/05/10 1p
- 7906102304 Requests replacement copy of signed originals of Amended B-45, which will be executed & returned to NRC as requested
STALLINGS C R Virginia Electric & Power Co 79/05/31 1p
- P. Operating license stage documents & correspondence
- 7906102379 PDIA request for all records & communications re shutdown of five nuclear plants
CASHMAN V J Power Authority State of New York 79/05/16 2pp
- 7906102326 Solicitors criterion to develop plant-specific info packages on site visits
RUTHERFORD T Office of Nuclear Reactor Regulation 79/04/11 2pp
- 7906102325 Forwards 790409 ltr from J. Allen of North Anna Environ Coalition requesting review of site. Also includes request for action per 10CFR30.303. Also forwards FR notice, Ltr not encl
BENTON H R Office of Nuclear Reactor Regulation 79/05/04 1p
- 7906102330 Notice of 790428 North Anna Environ Coalition request for NRC to revise B-45 due to lack of concurrence of estimated peak fuel cladding temp w/voids of 10CFR30.303
BENTON H R Office of Nuclear Reactor Regulation 79/05/04 2pp
- 7906270503 Forwards Amended 49 & 48 to Licenses EPR-32 & BWR-37, respectively. Revising Tech Spec limits for total nuclear peaking factor
VILLARIN E H Assistant Director for Systems Engineering 79/05/09 10pp
- 7906270505 Safety evaluation supporting Amended 49 & 48 to Licenses EPR-32 & BWR-37, respectively
Assistant Director for Systems Engineering 79/05/09 4pp
- 7906270506 Notice of issuance & availability of Amended 49 & 48 to Licenses EPR-32 & BWR-37, respectively
Operating Reactors Branch 1 (Pfr 790425) 79/05/09 2pp
- 7906270510 Summary of 790502 meeting w/utl in Bethesda, MD re need & testing for emergency buses
Operating Reactors Branch 1 (Pfr 790425) 79/05/09 2pp
- 7906270514 Summary of 790502 meeting w/utl in Bethesda, MD re proposal to start up facility while pipe stress analysis are being completed
Operating Reactors Branch 1 (Pfr 790425) 79/05/11 2pp
- 7906270507 Summary of 790502 meeting w/utl re steam generator & reactor coolant pump supports 10pp
Operating Reactors Branch 1 (Pfr 790425) 79/05/11 4pp
- 7906250591 Forwards memo discussing B. McDermott concerns re shutdown of BSW plants
Division of Project Management 79/05/17 2p
- 7906250501 Requests assessment of safety of continued operation of BSW reactor based on performance of relief & safety valves. Performance of HP1 pumps, reliability of nuclear feedwater & core cooling in natural circulation
Division of Project Management 79/05/08 2pp
- 7906250506 Discusses safety assessment of BSW plants, in response to 790508 memo. BSW plants should be shut down until reactants have been completed re core cooling in natural circulation, small break LSCAs & SCOs
Quality Assurance Branch 79/05/14 7pp
- 7906250512 Discusses B. McDermott 790504 memo re safety of BSW plants
Division of Project Management 79/05/15 2pp
- 7906250514 Discusses B. McDermott 790504 memo re safety of BSW plants
Division of Project Management 79/05/15 2pp
- 7906102446 Notification of 790502 meeting w/utl & BSW to discuss pipe stress analysis & review w/utl structure interaction analysis
Operating Reactors Branch 1 (Pfr 790425) 79/05/18 1p
- 7906270709 Lists sub. of 790504 & 18 info requests re amplified response spectra using soil structure interaction. Response should be completed by 790623
Division of Operating Reactors 79/05/18 2pp
- 7906102773 Denies PDIA request for Gibson 790404 & Thompson 790310 memos to Commissioner Bradford, which contain NRC opinions & recommendations re five shutdown plants info withheld (ref PDIA Exemption D)
Division of Rules and Records 79/05/21 4pp
- 7906270559 Notification of 790504 meeting w/utl in Bethesda, MD to discuss pipe stress analysis for facility
Operating Reactors Branch 1 (Pfr 790425) 79/05/21 2pp
- 7906270542 Discusses containment depressurization
Plant System Branch 79/05/22 2pp
- 7906250509 Discusses position re use of soil structure interaction data. Seismic input/output analysis being performed. Approves methodology, provided that relevant stresses calculated are increased by factor of 1.5
Assistant Director for Systems Engineering 79/05/25 2pp

DOCKETED ITEMS

- 7904150234 Forwards "Verification of NUPURE-1 for Analysis of Nuclear Piping Sys. HSC" & "Quadra-NUPURE Response Spectral Analysis Methods & Computer Listing." in response to NRC 790402 ltr. Requests withholding Review (ref 100792 7901)
STALLINGS, C. H. Virginia Electric & Power Co. 79/05/30 4pp
- 7904050302 Requests 790110 reph "QA Program Operations Phase" Request exception from ANSI para 2.4 & 4.45 2 d paragraphs re relief control & equipment test. Discusses proposed alternative.
BARKER, A. Virginia Electric & Power Co. 79/05/30 2pp
- 7906050303 Forwards results of steam generator & preventative plugging program. Unit operation can be safely extended for seven months per unit 790406 request
STALLINGS, C. H. Virginia Electric & Power Co. 79/05/31 1p
- 7904050307 Steam generator tube insp & preventative plugging program
Virginia Electric & Power Co. 79/04/30 3pp
- 7906070295 Forwards "Rep on Reanalysis of safety-related Piping Sys. Unit 1." in response to NRC 790313 order to show cause. Piping sys only slightly impacted by reanalysis. Requests immediate startup of Unit 1.
SPENCER, W. C. Virginia Electric & Power Co. 79/06/03 4pp
- 7906070298 "Rep on Reanalysis of Safety-Related Piping Sys. Unit 1"
Virginia Electric & Power Co. 79/06/03 10pp
- 7906101019 Forwards "Bell Structure Interaction Rep."
SPENCER, W. C. Virginia Electric & Power Co. 79/06/08 1p
- 7905101017 "Bell Structure Interaction Rep."
Virginia Electric & Power Co. 79/06/08 20pp
- 7906130302 Forwards add info re 790405 rep on reanalysis of safety-related piping sys. Appreciable break location changes are not anticipated.
SPENCER, W. C. Virginia Electric & Power Co. 79/06/20 10pp
- 7906150145 Provides add info to suppl 790605 rep on reanalysis of safety-related piping sys. Details stress problems which require hardware and Mod to be completed by 790620
SPENCER, W. C. Virginia Electric & Power Co. 79/06/16 2pp
- 7906201012 Submits response to 790613 request for add info re pipe stress reanalysis effort, including functional description of support system, schedule for info & reactor coolant pressure boundary support info.
SPENCER, W. C. Virginia Electric & Power Co. 79/06/16 8pp
- 7906200219 Submits add info re facility emergency power sys electrical load analysis, vis mod & testing procedures. Forwards "Addl info for 480 Volt Emergency Power Sys Mod" & "Electrical Load Analysis for 480 Volt Emergency Power Sys"
STALLINGS, C. H. Virginia Electric & Power Co. 79/06/18 21pp
- 7906210214 "Addl info for 480 Volt Emergency Power Sys Mod"
Virginia Electric & Power Co. 79/06/03 21pp
- 7906210216 "Electrical Load Analysis for 480 Volt Emergency Power Sys"
Virginia Electric & Power Co. 79/05/17 42pp
- 7906200419 Submits updated Table 1 to 790615 submission delineating status of supports associated with reactor coolant pressure boundary. Discusses addl needs presently required.
SPENCER, W. C. Virginia Electric & Power Co. 79/06/19 3pp
- 7906200213 Forwards addl info re FWB feedwater lines in response to NRC 790502 request unit 771802 ltr re feedwater lines and
STALLINGS, C. H. Virginia Electric & Power Co. 79/06/20 4pp
- 7906200307 Discusses status of unit study of plant feedwater sys water hammer potential.
STALLINGS, C. H. Virginia Electric & Power Co. 77/12/02 9pp
- 7906200308 Accepts unit provisions for minimizing possibility of water hammer events due to rapid steam condensation in feedwater sys.
SPENCER, W. C. Operating Reactors Branch 1 (Pw 790620) 79/06/07 7pp
- 7906200307 Clarifies causes for hardware nodes identified in earlier submittals of 790605, 12 & 19 in response to NRC 790601-02
SPENCER, W. C. Virginia Electric & Power Co. 79/06/20 4pp
- 9 Inspection reports, IE Bulletin & correspondence
- 7905070032 Forwards IE Insp Repts 50-280/79-11 & 50-281/79-13 on 790226-0302 No noncompliance noted.
BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 2pp
- 7904070036 IE Insp Repts 50-280/79-11 & 50-281/79-13 on 790226-0302 noncompliance noted. Major areas inspected respiratory protection, AAR program & training.
BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 7pp
- 7904100073 Forwards IE Insp Repts 50-280/79-12 & 50-281/79-13 on 790226-0302 No noncompliance noted.
BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 2pp
- 7904180480 IE Insp Repts 50-280/79-12 & 50-281/79-15 on 750306-09 No noncompliance noted. Major areas inspected occupational exposure, personal dosimetry, use of temporary containers & training.
BUTHERLAND, J. T. Region 2, Atlanta, Office of the Director 61800N, A. F. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 4pp
- 7904100048 Forwards IE Bulletin 79-10, "Requalification Training Program Objectives." Written response requested.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/31 1p
- 7904030328 Ack receipt of 790420 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/79-09 & 50-281/79-10.
BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/15 1p
- 7904200340 Responds to NRC 790328 ltr re violations noted in IE Insp Repts 50-280/79-09 & 50-281/79-10. Corrective actions taken: containment screen installed; all radiation area barricades locked & lead removed from RRT van.
STALLINGS, C. H. Virginia Electric & Power Co. 79/04/20 7pp
- 7904100044 Forwards IE Insp Repts 50-280/79-09 & 50-281/79-10 on 790328 ltr & notice of violation.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/28 2pp
- 7904200192 Notice of violation from Insp on 790312-14
Region 2, Atlanta, Office of the Director 79/03/28 3pp
- 7904200140 IE Insp Repts 50-280/79-09 & 50-281/79-10 on 790312-14. Noncompliance noted: containment sump breach screens not installed; failure to post b/w barricade high radiation areas & failure to label contaminated waste drum.
BUTHERLAND, J. T. Region 2, Atlanta, Office of the Director 61800N, A. F. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/28 11pp
- 7904050191 Ack receipt of 790504 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/79-15 & 50-281/79-21.
LEWIS, S. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/17 3p
- 7904100194 Responds to NRC 790406 ltr re violations noted in IE Insp Repts 50-280/79-15 & 50-281/79-21. Corrective actions: annunciation procedure changed; operators instructed to report events & fire watch posted.
STALLINGS, C. H. Virginia Electric & Power Co. 79/05/04 2pp
- 7904100190 Forwards IE Insp Repts 50-280/79-15 & 50-281/79-21 on 790328-0314 & notice of violation.
LEWIS, S. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/06 2pp
- 7904100209 Notice of violation from Insp on 790305-0314
Region 2, Atlanta, Office of the Director, 79/04/06 1p
- 7904100213 IE Insp Repts 50-280/79-15 & 50-281/79-21 on 790305-0314. Noncompliance noted: failure to follow annunciation procedure & failure to establish fire watch on nonfunctional electric penetration fire barriers.
BUTHERLAND, J. T. Region 2, Atlanta, Office of the Director, CENTER, A. F. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/01 8pp
- 7904030124 Responds to NRC 790310 ltr re violations noted in IE Insp Repts 50-280/79-10 & 50-281/79-10. Corrective actions taken: inspected & acceptance label affixed & copy of procedure 10-2000-10 placed in reading file.
STALLINGS, C. H. Virginia Electric & Power Co. 79/03/31 4pp

DOCKETED ITEMS

7906200307 Ack receipt of 790529 ltr informing NRC of steps taken to correct violations noted in IE Insp Regs 30-260/79-09 & 30-261/79-09
 BETHLEHEM, J T Eugene D. Atlanta, For: Facilities & Materials
 Safety Branch 79/06/07 3p

7906200302 Response to NRC 790518 ltr re violations noted in IE Insp Regs 30-260/79-09 & 30-261/79-09 Corrective actions
 labeling of containers of radioactive material
 STALLINGS, C M Virginia Electric & Power Co 79/06/29 2pp

7906200303 Response to IE Bulletin 79-01 Forward: Failure of Solenoid Operated Valves to Meet IE Bulletin 79-01 Nuclear
 Qualification Requirements
 STALLINGS, C M Virginia Electric & Power Co 79/06/14 1p

7906200308 Failure of Solenoid Operated Valves to Meet IE Bulletin 79-01 Nuclear Qualification Requirements Environmental
 unqualified valves from South or will be replaced
 Virginia Electric & Power Co 79/06/14 2pp

7906200421 Response to IE Bulletin 79-01: "Nuclear Qualification of Class IE Equipment - Suspected solenoid valves will be upgraded or replaced as soon as possible"
 STALLINGS, C M Virginia Electric & Power Co 79/06/25 2pp

R Periodic operating reports & related correspondence

7906200307 Forward monthly operating report for May 1979
 STALLINGS, C M Virginia Electric & Power Co 79/06/13 1p

7906200308 Monthly operating report for May 1979
 STALLINGS, C M Virginia Electric & Power Co 79/06/26 2pp

S Reportable occurrences, LERs & related correspondence

7906200309 Forward LER 79-019/03L-3
 STALLINGS, C M Virginia Electric & Power Co 79/05/31 1p

7906200312 LER 79-019/03L-0 on 790510 while securing purging operations, valve H2V-8200 did not close closed by bearing failure
 STALLINGS, C M Virginia Electric & Power Co 79/06/03 2pp

7906200329 RD on 790605 abnormal degradation of cable insulation in emergency power supply battery charger
 STALLINGS, C M Virginia Electric & Power Co 79/06/06 1p

7906200339 Forward LER 79-020/03L-0
 STALLINGS, C M Virginia Electric & Power Co 79/06/16 1p

7906200408 LER 79-020/03L-0 on 790605 abnormal degradation of cable insulation in emergency power supply battery charger discovered at cold shutdown caused by contact high pressure arcing
 STALLINGS, C M Virginia Electric & Power Co 79/06/16 2pp

U Congressional/Executive Correspondence

7906200307 Ack receipt of VA congressional delegation 790319 ltr re shutdown of Facilities Steps have been taken re review of pipe stress analyses Discusses site-specific considerations for seismic events
 HENRIE, J R Commission 79/05/21 2pp

7906200308 Ack receipt of VA congressional delegation 790319 ltr re shutdown of Facilities Steps have been taken re review of pipe stress analyses Discusses site-specific considerations for seismic events
 HENRIE, J R Commission 79/05/21 2pp

7906200309 Ack receipt of VA congressional delegation 790319 ltr re shutdown of Facilities Steps have been taken re review of pipe stress analyses Discusses site-specific considerations for seismic events
 HENRIE, J R Commission 79/05/21 2pp

7906200310 Ack receipt of VA congressional delegation 790319 ltr re shutdown of Facilities Steps have been taken re review of pipe stress analyses Discusses site-specific considerations for seismic events
 HENRIE, J R Commission 79/05/21 2pp

7906200305 Ack receipt of VA congressional delegation 790319 ltr re shutdown of Facilities Steps have been taken re review of pipe stress analyses Discusses site-specific considerations for seismic events
 HENRIE, J R Commission 79/05/21 2pp

7906200307 Ack receipt of VA congressional delegation 790319 ltr re shutdown of Facilities Steps have been taken re review of pipe stress analyses Discusses site-specific considerations for seismic events
 HENRIE, J R Commission 79/05/21 2pp

7906200308 Ack receipt of VA congressional delegation 790319 ltr re shutdown of Facilities Steps have been taken re review of pipe stress analyses Discusses site-specific considerations for seismic events
 HENRIE, J R Commission 79/05/21 2pp

7906200309 Ack receipt of VA congressional delegation 790319 ltr re shutdown of Facilities Steps have been taken re review of pipe stress analyses Discusses site-specific considerations for seismic events
 HENRIE, J R Commission 79/05/21 2pp

7906200307 Ack receipt of VA congressional delegation 790319 ltr re shutdown of Facilities Steps have been taken re review of pipe stress analyses Discusses site-specific considerations for seismic events
 HENRIE, J R Commission 79/05/21 2pp

7906200308 Ack receipt of VA congressional delegation 790319 ltr re shutdown of Facilities Steps have been taken re review of pipe stress analyses Discusses site-specific considerations for seismic events
 HENRIE, J R Commission 79/05/21 2pp

7906200309 Forward draft of proposed responses to 790219 ltr from VA congressional delegation re pipe stress analysis of facility
 STALLINGS, C M Office of Nuclear Reactor Regulation 79/05/01 5p

7906200311 Request expedited review of piping stress analyses independent from review of other three plants shut down for seismic-related issues
 BUTLER, C M - DANIEL, E W - HARRIS, E H House of Rep 79/03/19 2pp

DOCKET 50-061 GURRY POWER STATION, UNIT 2

G Adjudicatory correspondence

7906200413 Order extension until 790513 for NRC to review 790503 denial of enforcement action
 CHILDS, D J Office of the Secretary of the Commission 79/05/12 1p

7906200434 Growth NRC extension until 790604 for review of 790503 denial of enforcement action
 CHILDS, D J Office of the Secretary of the Commission 79/05/15 1p

H General correspondence

7906200407 Response to 790312 ltr re shutdown of five nuclear power plants because of seismic concerns Seismic design was not in accord with accepted engineering practice. Factors of piping stress tests LSCA Plant review is being expedited
 GENTON, H R Office of Nuclear Reactor Regulation 79/05/09 3p

7906200408 Expresses concern re shutdown of five reactors for seismic reasons Action assured energy crisis Plant overriden is done appropriate during refueling shutdown Benefits of nuclear power outweigh seismic risks
 STALLINGS, C M Affiliation Unknown 79/05/15 2pp

7906200410 Response to 790319 ltr re NRC 790312 orders to shut down five nuclear power plants NRC prefers to review situation on site
 GENTON, H R Office of Nuclear Reactor Regulation 79/05/06 2pp

7906200409 Comments on NRC seismic & evaluation acts Request immediate removal of seismic decision to shut down five plants suggests more rational approach to irreparable safety concerns in future
 STALLINGS, C M Affiliation Unknown 79/05/19 2pp

DOCKETED ITEMS

87

- 7906270608 Responds to 790314 ltr re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. E. Office of Nuclear Reactor Regulation 79/03/17 App
- 7906270610 Comments on 790313 orders shutting down five northeastern US nuclear power plants Requests investigation into actual probability of major seismic activity in region
SMITH, B. N. Affiliation Unknown 79/03/14 Ip
- 7906270620 Responds to 790331 ltr re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. E. Office of Nuclear Reactor Regulation 79/03/17 App
- 7906270628 Comments on 790313 orders shutting down five northeastern US nuclear power plants Requests investigation into actual probability of major seismic activity in this region
BERNARD, C. F. Affiliation Unknown 79/03/31 App
- 7906270633 Responds to 790322 ltr re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. E. Office of Nuclear Reactor Regulation 79/03/17 App
- 7906270648 Comments on 790313 orders shutting down five northeastern US nuclear power plants Actions poorly reasoned
FULLER, W. R. Affiliation Unknown 79/04/03 App
- 7906270653 Responds to 790321 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. E. Office of Nuclear Reactor Regulation 79/03/17 App
- 7906270656 Comments on 790313 orders shutting down five northeastern US nuclear power plants Economic consequences for Maine as well as power shortages override slim prospect of earthquakes
SULLIVAN, J. F. Affiliation Unknown 79/03/21 Ip
- 7906270660 Responds to 790327 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. E. Office of Nuclear Reactor Regulation 79/03/17 App
- 7906270668 Comments on 790313 orders shutting down five northeastern US nuclear power plants HED should reevaluate its antinuclear attitudes
GUSKEY, J. Affiliation Unknown 79/03/27 Ip
- 7906270669 Responds to 790323 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. E. Office of Nuclear Reactor Regulation 79/03/17 App
- 7906270673 Comments on 790313 orders shutting down five northeastern US nuclear power plants Plants should be removed immediately due to seismic prospects of plant closings
BARBERS, J. A. Affiliation Unknown 79/03/23 Ip
- 7906270676 Responds to 790322 ltr re President re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. E. Office of Nuclear Reactor Regulation 79/03/17 App
- 7906270680 Responds to 790326 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. E. Office of Nuclear Reactor Regulation 79/03/17 App
- 7906270682 Comments on 790313 orders shutting down five northeastern US nuclear power plants Chance of earthquake is too low to risk economic upheaval caused by closing of plants
LEWIS, P. F. Affiliation Unknown 79/03/28 Ip
- 7906270687 Responds to 790315 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. E. Office of Nuclear Reactor Regulation 79/03/17 App
- 7906270691 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was extremely ill-conceived
ROSENBERG, W. F. Affiliation Unknown 79/03/15 Ip
- 7906270693 Responds to 790317 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. E. Office of Nuclear Reactor Regulation 79/03/17 App
- 7906270698 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was extremely ill-conceived
HARRIS, W. M. Affiliation Unknown 79/03/17 Ip
- 7906270709 Responds to 790314 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. E. Office of Nuclear Reactor Regulation 79/03/17 App
- 7906270719 Responds to 790322 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. E. Office of Nuclear Reactor Regulation 79/03/17 App
- 7906270724 Responds to 790324 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. E. Office of Nuclear Reactor Regulation 79/03/17 App
- 7906270732 Responds to 790317 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. E. Office of Nuclear Reactor Regulation 79/03/17 App
- 7906270735 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was poorly timed & economically ill-considered
ROSENBERG, W. F. Affiliation Unknown 79/03/17 Ip
- 7906270745 Responds to 790313 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. E. Office of Nuclear Reactor Regulation 79/03/17 App
- 7906270751 Responds to 790322 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. E. Office of Nuclear Reactor Regulation 79/03/17 App
- 7906270755 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was ill-considered considering current energy prices
HRETZSCHMAN, M. Affiliation Unknown 79/03/22 Ip

DOCKETED ITEMS

- 790607008 Comments re 790313 orders shutting down five northeastern US nuclear power plants. Decision was economically ill-considered.
ALLISON C Affiliation Unknown 79/03/28 1p
- 790605043 Responds to 790314 Ltr re NRC 790323 orders to shut down five nuclear power plants. NRC prefers to review situation in expedited & disciplined manner, to return plants to operation w/o threat to public health & safety.
DENTON H R Office of Nuclear Reactor Regulation 79/05/21 3pp
- 790601041 States that NRC overreacted in shutting five nuclear plants. Comments on impact of NRC action 5/790313 forwarding ltr to J. McHenry re shutdown of plants.
HEMPF, T P Affiliation Unknown 79/03/14 2pp
- 790605002 Responds to 790314 re NRC order to shut down five nuclear plants because of seismic concerns. Analysis techniques used in plant design were inappropriate. Piping also failure could cause LOCA.
DENTON H R Office of Nuclear Reactor Regulation 79/05/24 1p
- J Insurance & indemnity information
- 790612024 Endorsement 42 to NELA Policy NF-37
CHAS, T Mutual Atomic Energy Liability Underwriters 79/03/18 1p
- 790612021 Endorsement 42 to NELA Policy NF-37
CHAS, T Mutual Atomic Energy Liability Underwriters 79/05/10 1p
- 790607026 Requests replacement sets of signed originals of Amendment 1 to Bedeaford Agreement D-45, which will be executed & returned to NRC as requested.
STALLINGS, C H Virginia Electric & Power Co 79/03/21 1p
- P Operating license state documents & correspondence
- 790610079 FOIA request for all records & communications re shutdown of five nuclear plants
GABRIANO, V J Plant Authority State of New York 79/03/16 2pp
- 790610026 Solicits criteria to develop plant-specific info packages on site visits.
HUBBELL, L T Office of Nuclear Reactor Regulation 79/04/11 2pp
- 7906050125 Forward 790609 ltr from J. Allen of North Anna Extension Coalition requesting revocation of D-45 Ltr. is being treated as request for action per 10CFR 228.31a forwards FR notice Ltr not sent.
DENTON H R Office of Nuclear Reactor Regulation 79/05/04 1p
- 790602026 Notice of 790303 North Anna Extension Coalition request for NRC to revoke D-45 due to alleged noncompliance of estimated peak fuel loading temp. w/limit of 10CFR 228.31a.
DENTON H R Office of Nuclear Reactor Regulation 79/05/04 2pp
- 790607036 Forward Amends 49 & 48 to License 098-32 & 098-27, respectively, safety evaluation & notice of issuance & availability.
SCHAEFER, S A Operating Reactors Branch 1 (Fr 790625) 79/05/09 2pp
- 790603032 Amends 40 & 48 to License 098-32 & 098-27, respectively, revising Tech Spec limits for total nuclear peaking factor.
VALLI, H R Assistant Director for Systems Engineering 79/05/09 18pp
- 790625033 Safety evaluation supporting Amends 49 & 48 to License 098-32 & 098-27, respectively.
Assistant Director for Systems Engineering 79/05/09 4pp
- 790625034 Notice of issuance & availability of Amends 49 & 48 to License 098-32 & 098-27, respectively.
SCHAEFER, S A Operating Reactors Branch 1 (Fr 790625) 79/05/09 2pp
- 790606010 Summary of 790520 meeting w/with Bethesda. NS re mad & testing for emergency buses.
NEIDHARDT, J D Operating Reactors Branch 1 (Fr 790625) 79/05/04 2pp
- 790606017 Summary of 790503 meeting w/with re steam generator & reactor coolant pump supports issue.
NEIDHARDT, J D Operating Reactors Branch 1 (Fr 790625) 79/05/11 2pp
- 790625001 Forward memo discussing D. McHenry's concerns re shutdown of 354 plants.
KIDDER, D P Division of Project Management 79/05/17 1p
- 790625010 Requests assessment of safety of continued operation of 354 reactor based on performance of relief & safety valves, performance of RPS pumps, reliability of auxiliary feedwater & core cooling in natural circulation.
KIDDER, D P Division of Project Management 79/05/10 2pp
- 790625016 Discusses safety assessment of 354 plants, in response to 790520 memo. 354 plants should be shut down until reassessment has been completed re core cooling in natural circulation, small break LOCA & ECCS.
KIDDER, D P Quality Assurance Branch 79/05/14 2pp
- 790625012 Discusses D. McHenry's 790514 memo re safety of 354 plants. Reassess w/with McHenry position. Forwarding shutdown.
KIDDER, D P Quality Assurance Branch 79/05/12 2pp
- 790625014 Discusses D. McHenry's 790514 memo re safety of 354 plants. Reassess w/with McHenry position. Forwarding shutdown.
KIDDER, D P Quality Assurance Branch 79/05/12 2pp
- 790610046 Notification of 790520 meeting w/with & NS re discuss pipe stress analysis & review soil structure interaction analysis.
NEIDHARDT, J D Operating Reactors Branch 1 (Fr 790625) 79/05/18 1p
- 790607029 Ltr to 790314 & 10 info requests re amplified response spectra using soil structure interaction. Response should be completed by 790523.
STALLINGS, C H Division of Operating Reactors 79/05/18 2pp
- 790610073 Denies FOIA request for 790314 & Thompson 790318 memo to Commissioner. Prefers which contain NRC opinions & recommendations re five shutdown plants info withheld.
ZELDON, J H Division of Rules and Records 79/05/21 2pp
- 790621042 Discusses containment degradation.
LAWRENCE, G Plant Systems Branch 79/05/22 2pp
- 790625027 Discusses position re use of soil structure interaction for seismic plant stress analysis. Includes discussion of methodology, provided that seismic stresses calculated are increased by factor of 1.5.
KIDDER, D P Assistant Director for Systems Engineering 79/05/25 2pp
- 790610025 Forward "Verification of NUP-15 for Analysis of Nuclear Piping (NUP-15)" & "Quadrant-NUP-15 Response Spectrum Analysis Method & Computer Listing." in response to NRC 790602 ltr. Requests withholding. Quoted: (ref 10CFR 228.31a).
STALLINGS, C H Virginia Electric & Power Co 79/05/30 2pp
- 790610018 Requests amend to DL in form of proposed Tech Spec Change 78. Forwarding required LOCA-ECCS analysis results supporting full-rated pump operation after replacement of steam generator.
STALLINGS, C H Virginia Electric & Power Co 79/05/21 4pp
- 790625023 Discusses 790510 report "QA Program, Operations Phase." Requests exception from ANSI N4.2 & 4.3 & 4.3.2 & 4.3.3 re paragraphs re valve control & equipment test. Discusses proposed alternative.
KIDDER, D P Virginia Electric & Power Co 79/05/31 2pp
- 790607029 Forward "Report on Reanalysis of safety-related Piping Sys. Unit 1." in response to NRC 790513 order to show cause. Report was only slightly impacted by reanalysis. Requests immediate startup of Unit 1.
SPENCER, M C Virginia Electric & Power Co 79/06/05 4pp
- 790607029 "Report on Reanalysis of Safety-Related Piping Sys. Unit 1." Virginia Electric & Power Co 79/06/05 10pp
- 790610014 Forward "Soil Structure Interaction Report".
SPENCER, M C Virginia Electric & Power Co 79/06/08 1p
- 790611027 "Soil Structure Interaction Report".
SPENCER, M C Virginia Electric & Power Co 79/06/08 20pp
- 790610058 Forward add info to 790520 report on reanalysis of safety-related piping & equipment test. Discusses changes not anticipated.
SPENCER, M C Virginia Electric & Power Co 79/06/08 1pp

DOCKETED ITEMS

59

7904132663 Provides addl info re suppl 790408 rept re feasibility of safety-related piping w/ details stress problems which require hardware mod mod to be completed by 790408
EPFNER, M C Virginia Electric & Power Co 79/04/28 App

7904132663 Submits response to 790413 request for addl info re pipe stress analysis effort including functional description of support apparatus schedule for info re reactor coolant pressure boundary support info
EPFNER, M C Virginia Electric & Power Co 79/04/18 App

7904132663 Submits addl info re facility emergency power sys electrical load analysis, rev mod & testing procedures Forwarded "Addl info for 480 Volt Emergency Power Sys Mod" to Electrical Load Analysis for 480 Volt Emergency Power Sys
STALLINGS, C H Virginia Electric & Power Co 79/04/18 App

7904132624 "Addl info for 480 Volt Emergency Power Sys Mod" to Virginia Electric & Power Co 79/04/08 App

7904132624 "Electrical Load Analysis for 480 Volt Emergency Power Sys" to Virginia Electric & Power Co 79/04/17 App

7904220269 Submits updated Table 1 to 790415 submission delineating status of supports associated w/ reactor coolant pressure boundary discussion addl mod presently required
EPFNER, M C Virginia Electric & Power Co 79/04/19 App

7904220269 Forwarded addl info re PWR feedwater lines, in response to NRC 790328 request Unit 77002 IIR & NRC 790407 IIR re feedwater lines and
STALLINGS, C H Virginia Electric & Power Co 79/04/20 App

7904220269 Discusses status of whil studs of plant feedwater sys water hammer potential
STALLINGS, C H Virginia Electric & Power Co 79/04/02 App

7904220331 Accepts unit provisions for minimizing possibility of water hammer events due to rapid steam condensation in feedwater sys
BROWN, M E Operating Reactors Branch 1 (Per 790425)
79/04/07 App

7904220327 Clarifies cases for hardware mods identified in earlier unit 77002 IIR & NRC 790407 IIR in response to NRC 790328 request of pipe stress analysis
EPFNER, M C Virginia Electric & Power Co 79/04/25 App

0 Inspection Reports, IE Bulletins & Correspondence

7904270079 Forwarded IE Insp Rept 90-282/79-11 & 90-281/79-13 on 790304-1302 No noncompliance noted
BUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 App

7904270079 IE Insp Repts 90-282/79-11 & 90-281/79-13 on 790304-1302 No noncompliance noted Major areas inspected respirators protection/ALNA program & training
BROWN, M E Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 App

7904270079 Forwarded IE Insp Repts 90-282/79-12 & 90-281/79-13 on 790304-1302 No noncompliance noted
BUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 App

7904106680 IE Insp Repts 90-282/79-12 & 90-281/79-15 on 790304-09 No noncompliance noted Major areas inspected occupational exposure areas, special decontamination, use of temporary containment & training
BROWN, M E Region 2, Atlanta, Office of the Director
BROWN, M E Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 App

7904200629 Forwarded IE Insp Rept 90-281/79-14 on 790303-16 No noncompliance noted
BUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/09 App

7904200617 IE Insp Rept 90-281/79-14 on 790303-16 No noncompliance noted Major areas inspected radiological controls & radiation detection associated w/ steam generator replacement project
BROWN, M E Region 2, Atlanta, Office of the Director
BROWN, M E Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/09 App

7904201138 Forwarded IE Insp Rept 90-282/79-15 on 790303-16 No noncompliance noted
BUTHERLAND, J T Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/10 App

7904201138 IE Insp Rept 90-282/79-15 on 790303-16 No noncompliance noted Major areas inspected steam generator repair procedures, work activities, records & general containment work activities
BUTHERLAND, J T Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/10 App

7904201138 Forwarded IE Insp Rept 90-281/79-17 on 790303-16 No noncompliance noted
BUTHERLAND, J T Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/11 App

7904201138 IE Insp Rept 90-281/79-17 on 790303-16 No noncompliance noted Major areas inspected containment status, DR audits, licensee action on previous insp findings & observation of safety-related work activities
BUTHERLAND, J T Region 2, Atlanta, Office of the Director
BUTHERLAND, J T Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/10 App

7904201138 Forwarded IE Insp Rept 90-281/79-23 on 790402-03 No noncompliance noted
BUTHERLAND, J T Region 2, Atlanta, Office of the Director 79/04/23 App

7904201138 IE Insp Rept 90-281/79-23 on 790402-05 No noncompliance noted Major areas inspected containment status re steam generator replacement
BUTHERLAND, J T Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/23 App

7904201138 Forwarded IE Insp Rept 90-281/79-23 on 790402-05 No noncompliance noted
BUTHERLAND, J T Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/26 App

7904201138 IE Insp Rept 90-281/79-23 on 790402-08 No noncompliance noted Major areas inspected steam generator replacement welding activities
BUTHERLAND, J T Region 2, Atlanta, Office of the Director
BUTHERLAND, J T Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/25 App

7904102648 Forwarded IE Bulletin 79-10, "Qualification Training Program Statistics" Written responses required
BUTHERLAND, J T Region 2, Atlanta, Office of the Director 79/05/11 App

7904200120 Act receipt of 790420 IIR informing NRC of steps taken to correct violations noted in IE Insp Repts 90-282/79-09 & 90-281/79-10
BUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/10 App

7904200120 Response to NRC 790328 IIR re violations noted in IE Insp Repts 90-282/79-09 & 90-281/79-10 Corrective actions less containment screen installed; all radiation area barricades locked & lead removed
STALLINGS, C H

DOCKETED ITEMS

7906050127 Forwards IC Insp Reps 50-281/79-14 on 790603-09 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 79/03/29 2pp

7906050142 Notice of violation from Insp on 790524-09
Region 2, Atlanta, Office of the Director 79/03/29 1p

7906050146 IC Insp Reps 50-281/79-14 on 790604-09 Noncompliance noted
inadequate records for nitrogen purge when generator heater
automatically MCGO, T O Region 2, Atlanta, Office of the Director
HERND, A R Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 79/03/29 4pp

7906100071 Act receipt of 790504 ltr informing NRC of steps taken to
correct violations noted in IC Insp Reps 50-280/79-15 &
50-281/79-21
LEWIS, B C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 79/05/17 1p

7906100198 Response to NRC 790504 ltr re violations noted in IC Insp
Reps 50-280/79-15 & 50-281/79-21 Corrective actions
automation procedure changed; operators instructed to
report events & flow watch closed
STALLINGS, C H Virginia Electric & Power Co 79/05/04 3pp

7906100198 Forwards IC Insp Reps 50-280/79-15 & 50-281/79-21 on
790503-0316 & notice of violation
LEWIS, B C Region 2, Atlanta, Reactor Operations Nuclear
Support Branch 79/04/26 2pp

7906100208 Notice of violation from Insp on 790508-0316
Region 2, Atlanta, Office of the Director 79/04/26 1p

7906100213 IC Insp Reps 50-280/79-15 & 50-281/79-21 on 790508-0316
Noncompliance noted failures to follow manufacturer procedure
& failure to establish fire watch on nonfunctional
electric penetration fire barriers
BURSE, D J Region 2, Atlanta, Office of the Director
CARTELLA, J P Region 2, Atlanta, Reactor Operations Nuclear
Support Branch 79/04/01 3pp

7906060124 Response to NRC 790510 ltr re violations noted in IC Insp
Reps 50-280/79-15 & 50-281/79-21 Corrective actions taken
inspected & acceptance label affixed 2 copy of procedure
79-03-0010 placed in reading file
STALLINGS, C H Virginia Electric & Power Co 79/03/31 4pp

7906050337 Act receipt of 790529 ltr informing NRC of steps taken to
correct violations noted in IC Insp Reps 50-280/79-09 &
50-281/79-08
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials
Support Branch 79/06/07 1p

7906050582 Response to NRC 790518 ltr re violations noted in IC Insp
Reps 50-280/79-09 & 50-281/79-08 Corrective actions
labeling of containers of radioactive mat.
STALLINGS, C H Virginia Electric & Power Co 79/05/29 2pp

7906060536 Response to IC Bulletin 79-01 Forwards Failures of Solenoid
Operated Valves to Meet IE Bulletin 79-01 Review
Qualification Requirements
STALLINGS, C H Virginia Electric & Power Co 79/06/14 1p

7906100538 "Failure of Solenoid Operated Valves to Meet IE Bulletin
79-01: Environ Qualification Requirements" Environmentally
unsatisfactory valves have been or will be replaced
Virginia Electric & Power Co 79/06/14 3pp

7906090128 Response to IC Bulletin 79-01, "Environ Qualification of
Class B Equipment" Suspended solenoid valves u will be
upgraded or replaced as soon as possible
STALLINGS, C H Virginia Electric & Power Co 79/06/20 2pp

5. Periodic operating reports & related correspondence

7906100817 Forwards monthly operating report for May 1979
STALLINGS, C H Virginia Electric & Power Co 79/06/10 1p

7906100828 Monthly operating report for May 1979
CARTELLA, D J Virginia Electric & Power Co 79/06/06 40pp

6. Reportable occurrences, LBNs & related correspondence

7906100815 Provides info on potential significant deficiency reported
on 790625 re missing threads in bolt hole on pad of Steam
Generator 2973 All steam generator fast heli coils replaced
STALLINGS, C H Virginia Electric & Power Co 79/06/31 2pp

7906050298 Forwards LCR 79-020/017-0
STALLINGS, C H Virginia Electric & Power Co 79/06/10 1p

7906050405 LCR 79-020/017-0 on 790606 abnormal degradation of cable
isolation on emergency power tie battery charger discovered
at cold shutdown caused by constant high pressure air
Cable will be replaced with cables of higher tolerance
STALLINGS, C H Virginia Electric & Power Co 79/06/18 2pp

7. Congressional/Executive Correspondence

7906100267 Act receipt of VA congressional delegation 790319 ltr re
shutdown of Facilities Steps have been taken re review of
pipe stress analyses Discusses site-specific
considerations for seismic events
HERND, A R Commission 79/05/21 2pp

7906100308 Act receipt of VA congressional delegation 790319 ltr re
shutdown of Facilities Steps have been taken re review of
pipe stress analyses Discusses site-specific
considerations for seismic events
HERND, A R Commission 79/05/21 2pp

7906100380 Act receipt of VA congressional delegation 790319 ltr re
shutdown of Facilities Steps have been taken re review of
pipe stress analyses Discusses site-specific
considerations for seismic events
HERND, A R Commission 79/05/21 2pp

7906100382 Act receipt of VA congressional delegation 790319 ltr re
shutdown of Facilities Steps have been taken re review of
pipe stress analyses Discusses site-specific
considerations for seismic events
HERND, A R Commission 79/05/21 2pp

7906100383 Act receipt of VA congressional delegation 790319 ltr re
shutdown of Facilities Steps have been taken re review of
pipe stress analyses Discusses site-specific
considerations for seismic events
HERND, A R Commission 79/05/21 2pp

7906100387 Act receipt of VA congressional delegation 790319 ltr re
shutdown of Facilities Steps have been taken re review of
pipe stress analyses Discusses site-specific
considerations for seismic events
HERND, A R Commission 79/05/21 2pp

7906100390 Act receipt of VA congressional delegation 790319 ltr re
shutdown of Facilities Steps have been taken re review of
pipe stress analyses Discusses site-specific
considerations for seismic events
HERND, A R Commission 79/05/21 2pp

7906100394 Act receipt of VA congressional delegation 790319 ltr re
shutdown of Facilities Steps have been taken re review of
pipe stress analyses Discusses site-specific
considerations for seismic events
HERND, A R Commission 79/05/21 2pp

7906100397 Act receipt of VA congressional delegation 790319 ltr re
shutdown of Facilities Steps have been taken re review of
pipe stress analyses Discusses site-specific
considerations for seismic events
HERND, A R Commission 79/05/21 2pp

7906100402 Act receipt of VA congressional delegation 790319 ltr re
shutdown of Facilities Steps have been taken re review of
pipe stress analyses Discusses site-specific
considerations for seismic events
HERND, A R Commission 79/05/21 2pp

7906100408 Forwards draft of proposed response to 790319 ltr from 10
VA congressional delegates re pipe stress analysis at
facility
GENTON, R R Office of Nuclear Reactor Regulation 79/06/01 2pp

7906100411 Requests expedited review of piping stress analyses
independent from review of other three plants shut down for
seismic-related issues
BUTLER, C H, SMITH, R W, HARTMAN, E Review of Rep 79/05/29
2pp

DOCKET 50-280 PRADISE ISLAND NUCLEAR STATION, UNIT 1

J Insurance & indemnity information

7906100312 Forwards Endorsements 42 & 43 to MLI-14 Policy W-197
STALLINGS, C H Northern States Power Co 79/06/07 3pp

DOCKETED ITEMS

67

790610023 Forwarded Endorsements DB & DV to NRELU Policy NF-08
KCHWENR, G Northern States Power Co 79/06/15 3pp

P Operating license stage documents & correspondence

790610007 Forwarded Amends DB & DV to Licenses DFR-42 & DFR-60,
respectively, safety evaluation & notice of issuance &
availability
SCHWENR, A Operating Reactors Branch 1 (Pfr 790620) 79/05/01
2pp

790610061 Amends DB & DV to Licenses DFR-42 & DFR-60, respectively,
revolving Tech Specs to require activation of safety injection
based on 3 out of 3 channels of low pressure pressure
SCHWENR, A Operating Reactors Branch 1 (Pfr 790620) 79/05/01
2pp

790610062 Safety evaluation supporting Amends DB & DV to Licenses
DFR-42 & DFR-60, respectively
* Office of Nuclear Reactor Regulation 79/05/01 4pp

790610066 Notice of issuance & availability of Amends DB & DV to
Licenses DFR-42 & DFR-60, respectively
SCHWENR, A Operating Reactors Branch 1 (Pfr 790620) 79/05/01 2pp

790610074 Forwarded safety evaluation for need to safety injection
activation sys
LAINAB, D Plant Systems Branch 79/05/03 2pp

790610201 Safety evaluation supporting need to safety injection
activation sys
Plant Systems Branch 79/05/03 2pp

790610038 Discusses review of info re rod bank exchange method to
verify shutdown margin for two loop Westinghouse NGRs
Approach is alternative to burn exchange, provided
certain conditions are met
SCHWENR, A Operating Reactors Branch 1 (Pfr 790620) 79/05/15
2pp

790610041 Requests site emergency plan & implementing procedures, site
map, routing details & grid numbers of onsite & offsite
emergency monitoring stations & site maps used for offsite
dose determinations at evacuation
KCHWENR, J Region 3, Chicago, Office of the Director 79/05/17
1p

790610060 Forwarded amend application for Licenses DFR-42 & DFR-60, in
response to NRC 790113 ltr
KCHWENR, L Northern States Power Co 79/06/01 1p

790610082 Application for amend to Licenses DFR-42 & DFR-60
KCHWENR, L Northern States Power Co 79/06/01 4pp

790610443 Forwarded "Process Control Program for Waste Solidification"
& Waste Dose Calculation Manual
KCHWENR, L Northern States Power Co 79/06/07 1p

790610446 "Process Control Program for Waste Solidification"
* Northern States Power Co 79/06/01 11pp

790610451 Offsite Dose Calculation Manual
* Northern States Power Co 79/06/01 11pp

790610032 Forwarded Revision 2 to "ABNE Code Section XI Inservice Insp
& Testing Program & Info Required for NRC Review of Request
for Relief from ABNE Code Section XI Requirements"
KCHWENR, L Northern States Power Co 79/06/06 2pp

790610089 Revision 2 to "ABNE Code Section XI Inservice Insp &
Testing Program & Info Required for NRC Review of Request
for Relief from ABNE Code Section XI Requirements"
* Northern States Power Co 79/06/06 2pp

790610037 Submits info re facility feedwater line design, fabrication,
insp & operating history
KCHWENR, L Northern States Power Co 79/06/19 2pp

G Inspection reports, IE Bulletins & correspondence

790610093 Responds to NRC 790218 ltr re violations noted in IE Insp
Rept 90-003/79-01 & 90-004/79-01. Corrective action design
change has been implemented to assure problems are quickly
identified & corrected
KCHWENR, L Northern States Power Co 79/03/08 3pp

790610038 Responds to IE Bulletin 79-07 ASSEPIPE computer code used by
Fluxor Sys. Int. for seismic analysis of one safety injection
line analysis repeated using PIPESTRESS design found
satisfactory
KCHWENR, L Northern States Power Co 79/04/24 3pp

790610021 Forwarded IE Insp Repts 90-002/79-08 & 90-004/79-07 as
790218-1A & 0314-1A & notice of violation
KCHWENR, R Region 3, Chicago, Reactor Operations Nuclear
Support Branch 79/04/20 2pp

790610026 Notice of violation from Insp on 790218-1A & 0314-1A
* Region 3, Chicago, Office of the Director 79/04/19 1p

790610030 IE Insp Repts 90-002/79-08 & 90-004/79-07 on 790218-1A &
0314-1A noncompliance noted delayed conduct of fire eye
surveillance
KCHWENR, R & SMITH, J D, STREET, J F Region 3, Chicago,
Office of the Director 79/04/19 2pp

790610093 Forwarded IE Insp Repts 90-002/79-09 & 90-006/79-09 as
790218-1A noncompliance noted
KCHWENR, R Region 3, Chicago, Reactor Operations Nuclear
Support Branch 79/04/20 2pp

790610055 IE Insp Repts 90-002/79-04 & 90-004/79-08 on 790218-1A
noncompliance noted Major areas inspected plant operations,
radiation protection, ascent, security, insp of new fuel &
contingency planning
KCHWENR, R & SMITH, J D, STREET, J F Region 3, Chicago,
Office of the Director 79/04/20 3pp

790610061 Forwarded IE Insp Repts 90-002/79-10 on 79011-12 No
noncompliance noted
KCHWENR, R Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/04/20 2pp

790610034 IE Insp Repts 90-002/79-10 on 79011-12 No noncompliance
noted Major areas inspected 60/60 program, implementing
procedures, observation of work activities & nondestructive
examination data
KCHWENR, R & SMITH, J D, STREET, J F Region 3, Chicago, Office of the
Director 79/04/20 2pp

790610013 Responds to IE Bulletin 79-04 Valve weights were
incorrect but have been analyzed in compliance with
NRC and required tabulation of valve use ends
KCHWENR, J Northern States Power Co 79/05/01 4pp

790610021 Forwarded IE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Support Problem" No action required
KCHWENR, J Region 3, Chicago, Office of the Director 79/05/02
1p

790610108 Forwarded IE Bulletin 79-10, "Regulification Training
Program Statistics" - Written response required
KCHWENR, J Region 3, Chicago, Office of the Director 79/05/13
1p

DOCKETED ITEMS

7904000133 Forwards SE Info Notice 79-13, "Inspection of Low Water Level in Dyster Creek Reactor"
ANDERSON, J C Region 3, Chicago, Office of the Director 79/03/29 1p

7904000449 Ack receipt of 790318 for informing NRC of steps taken to correct equipment noted in IE Insp Rept 50-032/79-08 L
50-036/79-07
HEIDENHAIN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/03/29 1p

7904000479 Responds to NRC 790425 ltr re violations noted in IE Insp Rept 50-032/79-08 L 50-036/79-07
Connective actions detector testing begun 7/11/00 & completed 7/11/24
WACHNER, L J Northern States Power Co 79/03/18 2pp

7904000471 Forwards "Inservice Insp Examination Summary," 790407-25
HAYES, L O Northern States Power Co 79/04/22 1p

7904000474 "Inservice Insp Examination Summary," 790407-25
HAYES, L O & ANDERSON, R W Northern States Power Co 79/04/08 1p

B Periodic operating reports & related correspondence

7904000324 Submits May 1979 Environ Event Rept 79-04 re cooling tower operations
WARD, E C Northern States Power Co 79/04/01 1p

7904000329 Forwards monthly operating repts for May 1979
HAYES, L O Northern States Power Co 79/04/11 1p

7904000324 Monthly operating repts for May 1979
HAYES, L O Northern States Power Co 79/04/26 4pp

7904000329 Monthly operating repts for May 1979
HAYES, L O Northern States Power Co 79/04/26 4pp

B Reportable occurrences, LERs & related correspondence

7904000322 LER 79-001 has been voided
Northern States Power Co 79/04/01 1p

7904000324 Environ Event Rept 79-04 in May 1979 plant circulating water sys in partial recycle mode had excessive average daily blowdown flow for 17 days caused by accumulation of cooling tower mist & proper cooling water temps
WARD, E C Northern States Power Co 79/04/01 1p

7904000329 79-19 dynamic loading during post-LOCA flow before valve closure was not included in original stress analysis of Westinghouse containment purge valves. All purge valves administratively controlled to ensure closure
TIERNEY, P P Northern States Power Co 79/04/07 1p

7904000326 Forwards LER 79-019/01-0
HAYES, L O Northern States Power Co 79/04/20 1p

7904000326 LER 79-019/01-0 on 790406 containment purge & inservice purge station valves had not been dynamically analyzed for post-LOCA flow induced stresses caused by design valves put under strict administrative control
HAYES, L O Northern States Power Co 79/04/20 1p

7904000324 Forwards LER 79-019/01-0
HAYES, L O Northern States Power Co 79/04/22 1p

7904000324 LER 79-017/03L-0 on 790325 both source range channels lost for three minutes when all power range channel control power from source pulling. Caused by procedure error. Power restored & procedure changed
HAYES, L O Northern States Power Co 79/04/22 1p

DOCKET 20-284 IDAHO STATE UNIV RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7904000910 Forwards SE Info Notice 79-12, "Accepted Damage to New Fuel Assemblies"
BENNETT, R V Region 4, Dallas, Office of the Director 79/05/11 1p

DOCKET 20-289 FORT CALHOUN REACTOR, UNIT 1

F Security, medical, emergency & fire protection plans

7904000173 Forwards modified physical security plan in response to NRC 790311 request plan withdrawn (ref 100P42 790)
BENNETT, R V Omaha Public Power District 79/04/19 1p

I Financial information

7904000214 Forwards info re vital area access control info deemed "recessed" or financial info," per 100P42 51a141 info withheld (ref 100P42 790)
BENNETT, R V Omaha Public Power District 79/04/04 1p

F Operating license stage documents & correspondence

7904000213 Forwards safety evaluation of postulated fuel handling accident in reactor containment bldg
ECO, R W Operating Reactors Branch 4 (P4 790423) 79/04/27 3pp

7904000210 Summary of 790425 meeting w/E re natural circulation capability for E-C plants
HAYES, L O Reactor Systems Branch 79/05/02 43pp

7904000210 Forwards summary of 790301 meeting w/E re natural circulation conditions in E-C operating reactors
HAYES, L O Reactor Systems Branch 79/05/09 1p

7904000210 Notification of 790525 meeting w/utl in Bethesda, MD to discuss surveillance capsule test results which indicate integrated flow in reactor vessel of 2.8 times flow initially calculated
BENNETT, R V Operating Reactors Branch 4 (P4 790423) 79/05/22 2pp

7904000210 Forwards revised design description for mod re steel fence near diesel fire pump fuel storage tank
BENNETT, R V Omaha Public Power District 79/05/23 10pp

7904000214 Forwards addl info re technical basis for calculations, ability of unit to achieve safety injection pump rate ventilation as engineered safety feature & effect upon turbine cooling in event of ventilation sys failure
BENNETT, R V Omaha Public Power District 79/05/24 24pp

7904000210 Responds to 790505 ltr re failure of safety-related electrical equipment to meet emission qualification criteria
Forwards documentation demonstrating that wdg solved valves do not jeopardize public safety
BENNETT, R V Omaha Public Power District 79/05/29 5pp

7904000210 Forwards responses to questions re plant instrumentation & controls
BENNETT, R V Omaha Public Power District 79/06/03 13pp

7904000211 Forwards responses to NRC 790510 questions Loss of main feedwater pumps occurred twice in past three years. Unit has automatic isolation activation sys. Appropriate pumps used to remove liquid waste
BENNETT, R V Omaha Public Power District 79/06/03 5pp

7904000210 Forwards design description for review of fire protection safety evaluation. Proposes mod to reduce probability of tube oil fire in containment bldg floor surrounded openings and
BENNETT, R V Omaha Public Power District 79/06/05 12pp

7904000213 Forwards info re gas effluent monitoring sys in response to 790407 telcon
BENNETT, R V Omaha Public Power District 79/06/08 2pp

7904000210 Forwards info re radiation doses from equipment hatch during normal operation & after LOCA in response to 790404 request
BENNETT, R V Omaha Public Power District 79/06/14 22pp

7904000210 Ack receipt of NRC 790525 request for info re main feedwater at facility. Forwards responses to questions & drawings
BENNETT, R V Omaha Public Power District 79/06/18 25pp

G Inspection reports, IE Bulletins & correspondence

7904000210 Forwards SE Info Notice 79-12, "Accepted Damage to New Fuel Assemblies"
BENNETT, R V Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/11 2pp

DOCKETED ITEMS

63

--790436018 IE Insp Rept 50-285/79-06 on 790405 No noncompliance noted
Neger Areas impacted previously identified area Findings 5
LER 79-040
WALSH, J. L. Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/17 2pp

--790436002 Forwards corrected pages of IE Insp Rept 50-285/79-06
Successes errors made
WALSH, J. L. Region 4, Dallas, Reactor Construction &
Engineering Support Branch 79/04/26 3p

790436002 Forwards IE Info Notice 79-12, "Laser Reactor Vessel Head
Inspection Support Problem." No action required
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/07
1p

790436006 Forwards IE Bulletin 79-10, "Requalification Training
Program Statistics." Written response required
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/11
1p

790436024 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/11
1p

790436037 Responds to NRC 790517 request Forwards add info re
unqualified limit switches supporting 790513 response to IE
Bulletin 79-01
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/15 2pp

790436041 Responds to IE Bulletin 79-01 re environ qualification of
safety-related electrical equipment Forwards relevant info
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/15 2pp

790436046 Notifies that as of 790517 at least two operators per shift
will be designated to initiate & verify auxiliary feedwater
flow to steam generators during transients or accidents
Forwards previous response to IE Bulletin 79-06 & 79-040
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/15 2pp

B. Periodic operating reports & related correspondence

790436035 Forwards monthly operating report for May 1979
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/07 1p

--790436034 Monthly operating report for May 1979
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/07 1p

C. Reportable occurrences, LERs & related correspondence

790436046 Forwards FWD-79-0746
WALSH, J. L. Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/05/15 1p

790436045 Forwards report on potentially hazardous condition discovered
during performance check of analysis performed on feedwater
piping system
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/15 1p

790436048 Forwards FWD-79-0746
WALSH, J. L. Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/05/15 1p

790436077 Forwards FWD-79-0746 2 pp
WALSH, J. L. Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/05/15 1p

790436083 Forwards LER 79-014/017-0
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/25 1p

--790436084 LER 79-014/017-0 on 790515 AECG selected valves locked
sufficient environ qualification data caused by inadequate
space during design & installation period Valves will be
replaced following 1980 refueling outage
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/16 7pp

790436084 Forwards LER 79-002/032-1
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/29 1p

--790436083 LER 79-002/032-1 on 790527 during containment pressure
release containment air monitor readings were abnormally
low. Caused by closed isolation valves. Containment
isolation valves were closed & pressure valves opened.
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/29 1p

790436083 Forwards LER 79-014/017-0
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/25 1p

--790436081 LER 79-014/017-0 on 790517 testing on first removed
irradiated surveillance capsule showed higher than predicted
oil ductility transition temp min pressure temp limitation
curves have been developed
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/25 4pp

SECRET 79-026 INDIAN POINT STATION, UNIT 3
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/25 1p

790436025 Forwards "1976 Year-Class Rept for Multiplant Impact Study
of Hudson River Estuary." Affidavit of Doc sent
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/15 5pp

--790436025 "1976 Year-Class Rept for Multiplant Impact Study of Hudson
River Estuary." prepared by TE Instruments
Consolidated Edison Co. of New York 79/05/31 550pp

F. Security, medical, emergency & fire protection plans

790436044 Forwards revised responses on request for add info re fire
protection program administrative controls
EARLY, F. J. Region 4, Dallas, Office of the Director 79/05/12 4pp

790436045 Forwards revised response to NRC 790523 request re site
boundary dose determination from radioactive releases due to
fire in drumming station
EARLY, F. J. Region 4, Dallas, Office of the Director 79/05/12 4pp

G. Administrative correspondence

790436021 Requests NRC update distribution list WJ Cannon replaces
LR Bennett as counsel for AEC
EARLY, F. J. Region 4, Dallas, Office of the Director 79/05/12 1p

J. Insurance & indemnity information

790436045 Notifies receipt of receipt of complaint served on Westinghouse
alleging bodily injury to still employee of O'Brien & Gere
planned w/ radioactive water on 790512 but under way
ALTON, C. E. American Nuclear Insurance 79/05/14 1p

790436043 Forwards Amend 21 to Indemnity Agreement E-11
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/10 3pp

K. Operating license stage documents & correspondence

790436027 Forwards listing of docketed info describing GA program
EARLY, F. J. Region 4, Dallas, Office of the Director 79/04/30 3pp

790436044 Add request of 790327 emergency plan submittal Requests
Class III fee
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/10 1p

790436043 Summary of 790508 meeting w/Consolidated Edison Co
Power Authority of State of NY re auxiliary feedwater was
related station area
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/17
1p

790436043 Amendment of 790520 meeting w/Consolidated Edison Co of
NY re Power Authority of State of NY to discuss seismic analyses &
follow up 790517 meeting
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/17
1p

790436048 Forwards "Efficiency of one Square Meter Epithermal Mixed
for Collecting Young-of-the-Year Striped Bass While Perch &
Atlantic Tomcod in Hudson River Estuary, 1976."
WALSH, J. L. Region 4, Dallas, Office of the Director 79/05/16 1p

790436043 Forwards "Cycle 3 Refueling Outage Work List."
EARLY, F. J. Region 4, Dallas, Office of the Director 79/05/13 3pp

--790436043 "Cycle 3 Refueling Outage Work List."
Power Authority of State of New York 79/05/13 103pp

DOCKETED ITEMS

- 7904190504 States that analysis performed to demonstrate uninitiated pumping & continuous pressure relief will not interfere with proper operation of ECCS
EARLY, P. J. Power Authority State of New York 79/04/14 App
- 7904200142 Forwards "Post-Accident Reactor Instrumentation - Status/Performance by April in 790103 for in survey existing ICS fixed & portable instrumentation
EARLY, P. J. Power Authority State of New York 79/04/01 App
- 7904180025 "Efficiency of One Square Meter Epithelial Sheet for Collecting Young-of-the-Year Striped Bass, White Perch & Atlantic Tomcod in Hudson River Estuary 1978 -
* Texas Instruments, Inc 79/04/20 App
- 0 Inspection reports, IE Bulletin & correspondence
- 7904180028 Forwards IE Bulletin 79-028, "Nuclear Incident at TMI-2" - No written response required
GRIER, B. H. Region I, Philadelphia, Office of the Director 79/04/23 Ip
- 7904200034 Forwards responses to IE Bulletin 79-07. Discusses methods used for seismic analysis & design of reactor coolant loop
SCHWABER, J. R. Power Authority State of New York 79/04/24 App
- 7904180026 Responds to IE Bulletin 79-03 re use of ASME Sec III Type 304 or other welded pipe made by Youngstown Welding & Engineering Co. No Youngstown plants has been used in safety-related app
BAYNE, J. P. Power Authority State of New York 79/04/04 Ip
- 7904200034 Forwards responses to IE Bulletin 79-04, Items 1-12. As result of TMI incident, procedures have been tightened, personnel restricted & safety checks performed
BAYNE, J. P. Power Authority State of New York 79/04/06 App
- 7904180102 Forwards computer code listing as add response to IE Bulletin 79-07 Request automating TMI 100002 7900 W0
SCHWABER, J. R. Power Authority State of New York 79/04/26 App
- 7904200034 Notices that response to IE Bulletin 79-04 will be submitted by 790420, due to extensive work required
EARLY, P. J. Power Authority State of New York 79/05/02 Ip
- 7904200107 Forwards IE Info Notice 79-01, "Lower Reactor Vessel Head Inspection Report Problem - No action required
GRIER, B. H. Region I, Philadelphia, Office of the Director 79/05/07 App
- 7904180028 Responds to IE Bulletin 79-09 re GE Type 40-2 circuit breaker breakers not utilized in safety-related app
BAYNE, J. P. Power Authority State of New York 79/05/07 Ip
- 7904180444 Forwards IE Bulletin 79-10, "Refueling Training Program Evaluation - Written Response required
GRIER, B. H. Region I, Philadelphia, Office of the Director 79/05/11 Ip
- 7904200039 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies -
GRIER, B. H. Region I, Philadelphia, Office of the Director 79/05/11 Ip
- 7904200077 Forwards IE Circular 79-05, "Attempted Exemption - Low Enriched U -
GRIER, B. H. Region I, Philadelphia, Office of the Director 79/05/18 Ip
- 7904200070 Summary of 790317 meeting w/Consolidated Edison Co of NY, Power Authority of States of NY & United Engineers & Constructors, Inc in discuss licensing response to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping"
GLORIAN, L. M. Operating Reactors Branch I (Pw 790525) 79/05/18 App
- 7904201018 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping - All piping supports evaluated & found within allowable limits
EARLY, P. J. Power Authority State of New York 79/05/27 App
- 7904200284 Provides supplemental response to IE Bulletin 79-07 Provides info to support continued operation during analysis of existing piping stresses. Response to be completed by 790501
EARLY, P. J. Power Authority State of New York 79/05/31 App
- 7904180056 Responds to IE Bulletin 79-05 re pipe stress rationale. Forwards weekly status rept as of 790404
EARLY, P. J. Power Authority State of New York 79/04/05 App
- 7904200274 President revised responses to IE Bulletin 79-04a-Revision 1. Responses result from 790320 meeting w/Westinghouse & NRC in Bethesda, MD to discuss operating procedures for coping with accidents & accidents
BAYNE, J. P. Power Authority State of New York 79/04/05 App
- 7904200272 Responds to IE Bulletin 79-05 re pipe stress rationale. Forwards weekly status rept as of 790407
EARLY, P. J. Power Authority State of New York 79/04/11 App
- 7904200430 Submits revised responses to IE Bulletin 79-04a-Revision 1. Original responses to bulletin encl
BAYNE, J. P. Power Authority State of New York 79/04/20 App
- 7904200461 Forwards weekly status reports of 790404 on pipe stress rationale, in response to IE Bulletin 79-07
EARLY, P. J. Power Authority State of New York 79/04/20 App
- 7904200502 Forwards weekly status of work as of 790402 per IE Bulletin 79-07 re pipe stress rationale
EARLY, P. J. Power Authority State of New York 79/04/20 App
- 0 Periodic operating reports & related correspondence
- 7904180079 Annual Environ Operating Rpt 1978, Part A & Part B radiological, non-radiological & environmental
* Consolidated Edison Co of New York 78/12/31 App
- 7904180448 "Seismic Monitoring Network - Quarterly Report 13 for Dec 1978 - Feb 1979
GRIER, B. H. Consolidated Edison Co of New York 79/05/01 Ip
- 7904180448 "Seismic Monitoring Network - Quarterly Report 13 for Dec 1978 - Feb 1979 Prepared by Woodward-Clyde Consultants, Inc - Consolidated Edison Co of New York 79/05/03 App
- 7904180478 Submits May environ data specified in Section 901 certification
GRIER, B. H. Consolidated Edison Co of New York 79/05/10 App
- 7904200048 Forwards monthly operating rept for May 1979
BAYNE, J. P. Power Authority State of New York 79/05/14 Ip
- 7904200048 Monthly operating rept for May 1979
GRIER, B. H. Power Authority State of New York 79/05/14 App
- 7904200407 Forwards May 1979 daily tabulations of fish collection & species breakdown
GRIER, B. H. Consolidated Edison Co of New York 79/05/14 App
- 0 Repeatable observations, USRs & related correspondence
- 7904200420 Forwards LER 78-025/03L-0
BAYNE, J. P. Power Authority State of New York 78/05/26 Ip
- 7904200438 LER 78-025/03L-0 on 780601 excessive noise from wet water pump 35 observed at 900 power main pump shaft broken. Shutting one of three header pumps. Caused by bearing failure. Pump returned & header realigned.
GRIER, B. H. Power Authority State of New York 78/07/28 Ip
- 7904200404 LER 78-025/03L-0 on 780607 increase in plant vent radio gas 35 Pileup & packaging for Union Pump GS-350 Gaslifts replaced Pileup returned to operable status
GRIER, B. H. Power Authority State of New York 78/11/17 App
- 7904200403 LER 78-026-number not used.
* Power Authority State of New York 79/05/27 Ip
- 7904180064 Forwards LER 79-005/03L-1
BAYNE, J. P. Power Authority State of New York 79/06/15 Ip
- 7904180027 LER 79-005/03L-1 on 790405 wet water pump 34 was removed from svc due to low discharge pressure caused by broken drive shaft which disintegrated. 1 of 3 essential header pumps dry water pump was replaced & new bearings installed.
GRIER, B. H. Power Authority State of New York 79/06/18 App

7904000110 Describes LER 79-004/017-0 on 790403 error found in analysis of high energy line break inside containment change in reactor trip setpoint in effect
DOWNE, J. P. Power Authority State of New York 79/04/02 App

SECRET 30-367 SCENE NUCLEAR STATION, UNIT 2

G Adjudicatory correspondence

7904000203 Orders licensee to take immediate action to modify Feedwater system operating procedures to shut down certain units until completion of tests & to undertake long-term work as specified
COTTELL, E. J. Office of the Secretary of the Commission 79/05/07 App

J Insurance & liability information

7904000301 Forwards Enforcement 54 & 55 to ANR Policy NP-182 & Enforcement 50 & 51 to NRC Policy NP-181
SANDERS, F. B. Duke Power Co 79/04/08 App

D Advisory Committee on Reactor Safeguards reports & correspondence

7904000403 Forwards ECSS analysis of small break in conjunction of emergency Feedwater Flow Failure Operator has 20 minutes to reestablish Feedwater Flow prior to core uncovering
BATES, A. ACSS - Advisory Committee on Reactor Safeguards 79/05/03 App

P Operating license stage documents & correspondence

7904000503 Forwards 790514 Inspector's findings re changes to plant procedures resulting from 790507 order Procedures of 790507 order & operator's understanding of procedures are deemed to be adequate
ROSELEY, N. C. Office of Inspection & Enforcement 79/05/17 App

--7904000608 Confirms procedural changes resulting from NRC 790507 order & operators' again understanding of those changes
JAMES, F. Region 2, Atlanta, Office of the Director 79/05/14 App

7904000709 Confirms info submitted 790503 re OL amend requested to support operation through Cycle 5 Physics test will be conducted according to guidelines submitted on 790503 & 790504
PARKE, M. Q. Duke Power Co 79/05/29 App

7904000803 Delays proposed Tech Specs revisions re surveillance side to support 790101 & 790701 submittals
PARKE, M. Q. Duke Power Co 79/05/30 App

7904000907 Responds to 790518 request Forwards emergency feedwater flow test procedures
PARKE, M. Q. Duke Power Co 79/06/06 App

--7904001027 Emergency feedwater flow test procedure
J. Duke Power Co 79/05/31 App

7904001107 Advises that hydrostatic test required by 1974 ASME Boiler & Pressure Vessel Code is impractical until fall 1977 edition requirement Requests modification if acceptable
PARKE, M. Q. Duke Power Co 79/06/11 App

7904001201 Responds to NRC 790518 1st requesting schedule by 790608 completion of long-term work described in Section 2 of NRC 790507 order All efforts satisfactorily executed
PARKE, M. Q. Duke Power Co 79/06/14 App

7904001303 Forwards responses to NRC 790503 1st re Feedwater lines Diagrams and
PARKE, M. Q. Duke Power Co 79/06/18 App

G Inspection reports, IE Bulletins & correspondence

7904001403 BAW site inspector daily report on 790407 Plant status reactor operating at 90% power for repairs to condenser tubes testing to determine leak where continues
COTTELL, E. J. Region 2, Atlanta, Office of the Director 79/04/07 App

7904001504 BAW site inspector daily report on 790408 Plant status units 1 & 2 operating at 100%Unit 2 at 90% Hotting condenser tube leak on Unit-2 repaired
COTTELL, E. J. Region 2, Atlanta, Office of the Director 79/04/08 App

7904001608 BAW site inspector daily report on 790409 Plant status all reactors at full power Condenser leak has been corrected on
COTTELL, E. J. Region 2, Atlanta, Office of the Director 79/04/09 App

7904001709 BAW site inspector daily report on 790410 Plant status all reactors at full power all engineering safety feature up in svc
JAMES, F. Region 2, Atlanta, Office of the Director 79/04/10 App

7904001807 BAW site inspector daily report on 790411 Plant status reactor at full power w/no known problems Training instructors scheduled for BAW simulator training 790411
JAMES, F. Region 2, Atlanta, Office of the Director 79/04/11 App

7904001902 BAW site inspector daily report on 790412 Plant status all units running at full power BAW alignment verified for accessible components in Emergency Feedwater Bus
COTTELL, E. J. Region 2, Atlanta, Office of the Director 79/04/12 App

7904002003 BAW site inspector daily report on 790413 Plant status 74V power/water reactor coolant pump assumed to prevent seal degradation damage scheduled for 790420
HOLMES, T. J. Region 2, Atlanta, Office of the Director 79/04/13 App

--7904002103 BAW site inspector daily report on 790413 Plant status all reactors at full power w/no engineering safety feature equipment out of svc & no major errors
COTTELL, E. J. Region 2, Atlanta, Office of the Director 79/04/13 App

7904002209 BAW site inspector daily report on 790414 Plant status Unit 2 operating at 100% power Unit 1 & 2 at full power No major equipment scheduled for all major equipment is operational
BELLER, A. Region 2, Atlanta, Office of the Director 79/04/14 App

7904002303 BAW site inspector daily report on 790415 Plant status all units at 100% power w/no engineering safety feature equipment out of svc & no major errors
BELLER, A. Region 2, Atlanta, Office of the Director 79/04/15 App

7904002408 BAW site inspector daily report on 790417 Plant status all units at 100% power No major engineering safety feature eq equipment out of svc
JAMES, F. Region 2, Atlanta, Office of the Director 79/04/17 App

7904002502 Responds to IE Bulletin 79-050 Reactor protective syst high RCS pressure tripout has been lowered to not greater than 2.350 psid pressure power lowered relief valve setpoint raised to 2.400 psid
PARKE, M. Q. Duke Power Co 79/04/21 App

7904002604 BAW site inspector daily report on 790420 Plant status Units 1 & 2 at 100% power Unit 2 reduced to 92% due to water leak in turbine condenser bus
JAMES, F. Region 2, Atlanta, Office of the Director 79/04/20 App

7904002701 Notifies that responses to IE Bulletin 79-050 re Valve chest valves will be submitted by later than 790501
PARKE, M. Q. Duke Power Co 79/05/02 App

7904002801 Supplements response to Item 3 of IE Bulletin 79-05 & 79-05A re licensed shift operators completing BAW simulator training
PARKE, M. Q. Duke Power Co 79/05/04 App

7904002905 Ack receipt of IE Insp Repts 79-049/79-11, 79-050/79-11 & 79-050/79-11 on 790501-BW No proprietary info
PARKE, M. Q. Duke Power Co 79/05/05 App

--7904003007 Forwards IE Insp Repts 79-049/79-11, 79-050/79-11 & 79-050/79-11 on 790501-BW No proprietary info
LEWIS, J. C. Region 2, Atlanta, Office of the Director Nuclear Support Branch 79/05/01 App

--7904003107 IE Insp Repts 79-049/79-11, 79-050/79-11 & 79-050/79-11 on 790501-BW No noncompliance noted Major areas inspected plant operations; followup of info notices; physical security & LER.
JAMES, F. Region 2, Atlanta, Office of the Director
COTTELL, E. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/20 App

7904003205 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assembly."
O'NEILL, V. J. Region 2, Atlanta, Office of the Director 79/05/10 App

DOCKETED ITEMS

790410060 Forwards IE Bulletin 79-10, "Recertification Training Program Schedule" - written response required
O'REILLY, J P Region 2, Atlanta: Office of the Director
79/05/11 1p

790406242 Act receipt of 790322 ltr referring NRC of steps taken to correct violations noted in IE Insp Repts 80-288/79-01, 80-270/79-01 & 80-267/79-01
O'REILLY, J P Region 2, Atlanta: Office of the Director
79/05/11 1p

790406244 Responses to 790322 ltr regarding to state of noncompliance noted in IE Insp Repts 80-288/79-01, 80-270/79-01 & 80-267/79-01 that will submit RDR within 30 days of discovery of event
PARKER, M D Duke Power Co 79/05/05 3p

790406250 Response to NRC 790327 ltr re violations noted in IE Insp Repts 80-288/79-01, 80-270/79-01 & 80-267/79-01. Disputes item of noncompliance re late submittal of RDR due date fall as follows
PARKER, M D Duke Power Co 79/05/02 3pp

790406259 Forwards IE Insp Repts 80-288/79-01, 80-270/79-01 & 80-267/79-01 re 790311-0201 & notice of violation
LEWIS, E C Region 2, Atlanta: Office of the Director 79/05/02 2pp

790406284 Notice of violation from Insp on 790311-0201
Region 2, Atlanta: Office of the Director 79/05/06 1p

790406291 IE Insp Repts 80-288/79-01, 80-270/79-01 & 80-267/79-01 on 790311-0201 Noncompliance noted failure to submit written repts within 30 days of discovery of event
COFFIN, W T, CHATFIELD, P S Region 2, Atlanta: Reactor Operations Nuclear Support Branch 79/05/06 4pp

790406294 Forwards response to IE Bulletin 79-09 re SE Type AM-2/2M circuit breakers in safety-related systems are used as control trip drive as primary trip breakers & four are used in de loading power supplies
PARKER, M D Duke Power Co 79/05/16 3pp

790407010 Request info re manual trip on low pressure level as stated in Item 4 of IE Bulletin 79-08
MILLANS, J J Division of Project Management 79/05/18 3pp

A Periodic operating reports & related correspondence

790410149 Forwards monthly operating report for May 1979
PARKER, M D Duke Power Co 79/06/15 1p

790410152 Monthly operating report for May 1979
REAVEN, J A Duke Power Co 79/06/12 17pp

7904200140 Forwards correction sheets to monthly operating report for May 1979
PARKER, M D Duke Power Co 79/06/25 1p

7904200155 Correction sheets to monthly operating report for May 1979
Duke Power Co 79/06/21 4pp

Y Hearing transcripts on noncontingent matters

790410025 Transcripts of 790518 meeting in Washington, DC re briefing on Quince order for 1-18 meeting within next
HARRIS, J M, O'LINEAR, V, KOSHER, P T Commission 79/05/18 100pg

DOCKET 80-288 THREE ISLANDS NUCLEAR REACTOR

Inspection reports, IE Bulletins & correspondence

790410047 Forwards IE Info Article 79-12, "Attempted Damage to Raw Fuel Assembly" The utility response necessary
ENGELBORN, R H Region 3, San Francisco: Office of the Director
79/05/19 1p

790406230 Forwards IE Circular 79-06, "Attempted Exterior - Low Voltage" J
ENGELBORN, R H Region 3, San Francisco: Office of the Director
79/05/18 1p

DOCKET 80-289 THREE ISLANDS NUCLEAR STATION, UNIT 1

Security, medical, emergency & fire protection plans

790406212 Forwards description of tests to be performed on asbestos board fire barriers protecting cable trays & conduits to comply w/ fire protection NRC item 3 & 2 cable separation
Results will be submitted by 790712
HARRIS, J M Metropolitan Edison Co 79/05/18 3pp

790406204 Response to 790518 ltr re extra precautionary measures for area transmission app Adequate sources of power are available for operation of unit
WOLLERS, R H Assistant Director for Risk Analysis 79/05/19 1p

790406208 Requests end of extra precautionary measures taken to ensure adequate power to plants
HARRIS, J M General Public Utilities 79/05/19 1p

790406211 Notice that precautionary measures taken to maintain power supply are no longer necessary Personnel on standby at switching station are needed elsewhere Forwards update of electrical sys
WELLER, R M General Public Utilities 79/05/03 3pp

790406244 Response to 790320 ltr re fire protection program of cable separation list requested was submitted in 790318 ltr Fire barriers to be modified per test results
HARRIS, J M Metropolitan Edison Co 79/05/24 1p

790410072 Conveys results of field survey to determine fire resistance rating of unlabeled fire doors Forwards 790208 consultant report Requests concurrence re replacement & labeling of fire doors
HARRIS, J M Metropolitan Edison Co 79/06/07 4pp

I Financial Information

790410072 Forwards "Annual Financial Rept 1978"
HARRIS, J M Metropolitan Edison Co 79/06/07 1p

7904200130 "Annual Financial Rept 1978"
Metropolitan Edison Co & CPU Service Corp 79/06/21 119pp

J Insurance & indemnity information

790410024 Forwards Endorsement 34 to NRELU Policy NF-70
OBERLY, H F CPU Service Corp 79/06/12 3pp

790420024 Forwards supplemental limit of liability endorsement to Policy NF-220 effective 790501 Supplemental limit does not apply to events re 790228 CNS incident
BARRON, C & American Nuclear Insurers 79/06/18 3pp

P Operating license stage documents & correspondence

790310243 Amend 49 to License 898-50 & Amend V to DFW-72 Incorporating modified amended physical structures plan into license
REID, S W Operating Reactors Branch 4 (PFA 790285) 79/06/23 4pp

790427004 Forwards info on TNE incident followup actions by NRC in response to 790412 memo
MILLER, G C License Fee Management Branch 79/06/12 3pp

790429022 Describes major drawbacks to locating sampling sinks for both units in same room Unit 2 sink must be moved & all existing lines flushed before Unit 5 can be supported
BURELL, R H Metropolitan Edison Co 79/05/04 3pp

7904250184 Forwards update of health physics status of facility info sent to IV Search for use in memo to NRC
WINTER, V W Region 1, Philadelphia, Office of the Director
79/05/07 App

7905070180 Confirms 790315 taken w/ J Holman & M Beers RMI training kept intact as future licensed operator requalification program on 790321
MILBER, G P Metropolitan Edison Co 79/03/15 Ip

7905080204 Discusses 790320 until response to NRC 701016 ltr re handling of heavy lead within fuel handling bldg till response inadequate Definition of special areas re lead handling requires analysis & back Spec changes
REID, R H Operating Reactors Branch 4 (Pw 790425) 79/05/17 App

7905100308 Discusses operational-related problem re startup Shortly after 1976 unit startup, lead developed in decay heat removal sys which was apparently never permanently repaired
WAGG, D P Region 1, Philadelphia, Office of the Director
79/05/17 Ip

7905100150 Advises that proposed reduction in frequency of core flow rate verification is acceptable
REID, R H Operating Reactors Branch 4 (Pw 790425) 79/05/17 App

7905100212 Forwards "BSM 177 Fuel Assembly Control Group Asymmetric LOCA Loads Evaluation Program, Phase 2" & "BSM 177 Control Group Test for Asymmetric LOCA Loads Evaluation, Phase 2" -
HERSCHEIN, J D Metropolitan Edison Co 79/05/10 Ip

7905100218 "BSM 177 Fuel Assembly Control Group Asymmetric LOCA Loads Evaluations Program, Phase 2" & "BSM 177 Control Group Test for Asymmetric LOCA Loads Evaluation, Phase 2" -
HERSCHEIN, J D Metropolitan Edison Co 79/05/10 App

7905100324 "BSM 177 Fuel Assembly Control Group Asymmetric LOCA Loads Evaluations, Phase 2" & "BSM 177 Control Group Test for Asymmetric LOCA Loads Evaluation, Phase 2" -
HERSCHEIN, J D Metropolitan Edison Co 79/05/10 App

7905100325 Notices of discharge of 7,000 gallons of water on 790514 & 7,150 gallons of water on 790515 Meter released to influent of mechanical draft cooling tower discharge, sparking waste treatment sys
HERSCHEIN, J D Metropolitan Edison Co 79/05/24 App

7905100327 Notifies info requested by 790506 ltr re adequacy of station electric distribution sys voltage will be provided by 790501
HERSCHEIN, J D Metropolitan Edison Co 79/05/25 Ip

7905100408 Forwards info in response to 790320 ltr re freshwater line cracking Add info will be submitted by 790527
HERSCHEIN, J D Metropolitan Edison Co 79/05/26 lisp

② Inspection reports, IE Bulletins & correspondence

7905250334 Forwards IE Insp Rpts 50-289/79-08 & 50-320/79-07 on 790319-25 & 26 Re noncompliance noted in inspected previous Insp findings, selected licensee events & licensee following to prompt RD
BENNETT, E W Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/26 App

7905250339 IE Insp Rpts 50-289/79-08 & 50-320/79-07 on 790319-25 & 26 Re noncompliance noted Major areas inspected previous Insp findings, selected licensee events & licensee following to prompt RD
BENNETT, E W Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/26 App

7906110014 Forwards IE Bulletin 79-255, "Nuclear Incident at BRL-8995" No written response required
CRISP, R H Region 1, Philadelphia, Office of the Director
79/04/20, Ip

7906070237 Responds to IE Bulletin 79-04 requesting review to determine if Valve status check valves are installed in valve Category I piping sys Valves not installed or scheduled to be installed at facility
HERSCHEIN, J D Metropolitan Edison Co 79/03/03 Ip

7905250349 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Inspection Support Problem" No action required
CRISP, R H Region 1, Philadelphia, Office of the Director
79/05/07, App

7906110338 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics" Written response required
CRISP, R H Region 1, Philadelphia, Office of the Director
79/02/11 Ip

7906200119 Forwards IE Info Notice 79-12, "Attempted Damage to Steam Fuel Assembly" -
CRISP, R H Region 1, Philadelphia, Office of the Director
79/05/11 Ip

7906200307 Forwards IE Circular 79-05, "Attempted Extinction - Low Enrichment" -
CRISP, R H Region 1, Philadelphia, Office of the Director
79/05/10 Ip

7906270120 Discusses info re actual trip on low pressure (level 1) as stated in Item 42 of IE Bulletin 79-028
WILLIAMS, P J Division of Project Management 79/05/10 App

7906150324 Forwards results of steam generator edge current tube (1100) performed 790325-0326 during 1979 refueling outage
HERSCHEIN, J D Metropolitan Edison Co 79/06/02 App

7906270011 Lists IE Bulletin issued since 791 incident which have been withheld due to lack of available utility resources
CRISP, R H Region 1, Philadelphia, Office of the Director
79/06/09 App

② Reperable occurrences, LERs & related correspondence

7906280326 Forwards LER 70-09/03L-0
HERSCHEIN, J D Metropolitan Edison Co 79/04/02 Ip

7906280328 LER 70-09/03L-0 on 790318 Ac breaker CB failed to trip on one of several tests caused by apparent binding of breaker operating linkage Binding may have been due to insufficient exercise of breaker prior lack of maintenance
HITCHELL, D C Metropolitan Edison Co 79/04/03 App

7906280324 Forwards LER 70-01/03L-0
HERSCHEIN, J D Metropolitan Edison Co 79/04/17 Ip

7906280324 LER 70-01/03L-0 on 790318 During visual testing, one snubber had no fluid in reservoir caused by pinched lead after seal snubber will be replaced & refilled
HITCHELL, D C Metropolitan Edison Co 79/04/17 App

7906270326 AC 79-09/19 on 790327 during surveillance of turbine driven emergency feed pump pressure regulating valve HD-9-4 was found manually closed Unit was in hot shutdown Valve was opened & pump successfully tested
SEDLINGER, J D Metropolitan Edison Co 79/06/11 Ip

DOCKETED ITEMS

790610040 Forwards IE Bulletin 79-06, "Requalification Training Program Statistics - Written responses required"
O'DELL, J. P. Region 2, Atlanta, Office of the Director
79/05/11 1p

790626042 Act receipt of 790322 ltr informing ABC of steps taken to correct violations noted in IE Insp Reps 58-269/79-01;
80-216/79-01 & 80-267/79-01
O'DELL, J. P. Region 2, Atlanta, Office of the Director
79/05/11 1p

--790626044 Supplements until 790322 ltr responding to item of noncompliance noted in IE Insp Reps 58-269/79-01;
80-216/79-01 & 80-267/79-01 until will submit RDA within 30 days of discovery of event
PARER, H. C. Duke Power Co
79/05/05 1p

--790626050 Response to RRC 790227 ltr re violations noted in IE Insp Reps 58-269/79-01, 80-216/79-01 & 80-267/79-01. Dispute item of noncompliance re late submittal of RDA due date felt as being
PARER, H. C. Duke Power Co
79/05/22 2pp

--790626059 Forwards IE Insp Reps 30-266/79-01, 30-216/79-01 & 80-216/79-01 on 790313-0201 & notice of violation.
LEWIS, H. T. Region 2, Atlanta, Office of the Director
79/05/27 2pp

--790626064 Notice of violation from Insp on 790313-0201
Region 2, Atlanta, Office of the Director
79/05/26 1p

--790626075 IE Insp Reps 30-269/79-01, 30-216/79-01 & 80-216/79-01 on 790313-0201. Noncompliance noted failure to submit written reply within 30 days of discovery of event.
LEWIS, H. T. GAMBRELL, F. S. Region 2, Atlanta, Reactor Operations Nuclear Support Branch
79/05/26 4pp

790629029 Forwards response in IE Bulletin 79-09 re OE Type AM-2/24 circuit breakers in safety-related systems are used as control load drive AM primary trip breakers & have not used in re loading power supplies
PARER, H. C. Duke Power Co
79/05/16 2pp

790629030 Requests info re manual trip on low pressure level as exists in item of IE Bulletin 79-09
MILLARS, F. J. Division of Project Management
79/05/16 4pp

II Periodic operating reports & related correspondence

790629034 Forwards monthly operating report for May 1979
PARER, H. C. Duke Power Co
79/06/15 1p

--790629035 Monthly operating report for May 1979
REAVIS, J. A. Duke Power Co
79/06/15 17pp

790629048 Forwards correction sheets to monthly operating report for May 1979
PARER, H. C. Duke Power Co
79/06/25 4p

--790629050 Correction sheets to monthly operating report for May 1979
Duke Power Co
79/05/23 4pp

T Hearing transcripts on non-ambulatory matters

790610025 Transcripts of 790508 meeting in Washington, DC re briefing on charges under Pp 1-88 Hearing exhibits incl
BENNER, J. R. OLSINSKY, V. MENDENHALL, T. Commission
79/05/10 104pp

790620060 Transcript of 790518 public meeting in Washington, DC re briefing by NRC on license order Pp 1-88
Office of the Executive Legal Director
79/05/18 69pp

U Congressional/Executive Correspondence

790626054 Response to 790422 ltr re S Austin inquiry about radiological impact of nuclear power plant cooling on drinking water. Records available. Pp 1-88
O'DELL, J. P. Office of the Executive Director for Operations
79/05/15 2pp

--790626054 Requests info re radiological impact of nuclear power plant cooling on drinking water in re to S Austin inquiry
LEWIS, H. T. House of Rep.
79/05/23 2pp

DOCKET 30-266 NEED COLLOE RESEARCH REACTOR
Inspection reports: IE Bulletins & correspondence

790610047 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assembly" RRC written response required
ENGLEMAN, R. H. Region 5, San Francisco, Office of the Director
79/05/10 1p

790608039 Forwards IE Circular 79-08, "Attempted Extension - Low Enriched U"
ENGLEMAN, R. H. Region 5, San Francisco, Office of the Director
79/05/10 1p

DOCKET 30-209 THREE HILL ISLAND NUCLEAR STATION, UNIT 1
F Security, medical, emergency & fire protection plans

790610012 Forwards description of test to be performed on embosco board fire barriers protecting cable trays & conduits to comply w/ fire protection RRC item 3 & 2, cable separation
Results will be submitted by 790710
HERBERT, J. D. Metropolitan Edison Co
79/05/10 7pp

790626054 Response to 790518 ltr re extra precautionary measures for area transmission line. Adequate sources of power are available for operation of unit.
VOLLMER, R. H. Assistant Director for Site Analysis
79/05/19 1p

--790626058 Requests end of extra precautionary measures taken to ensure adequate power to plants
VOLLMER, R. H. General Public Utilities
79/05/18 1p

--790626061 Notifies that precautionary measures taken to maintain power supply are no longer necessary. Personnel on standby at switching station are needed elsewhere. Forwards outline of electrical sys.
MORTIS, R. H. General Public Utilities
79/05/02 3pp

790606024 Response to 790330 ltr re fire protection program of cable separation info requested was submitted in 790318 ltr. Fire barriers to be modified per test results
HERBERT, J. D. Metropolitan Edison Co
79/05/24 1p

790610023 Conveys results of field survey to determine fire resistance rating of unlabeled fire doors. Forwards 790338 consultant report. Requests concurrence re replacement & labeling of fire doors
HERBERT, J. D. Metropolitan Edison Co
79/05/07 4pp

I Financial Information

790610029 Forwards "Annual Financial Report 1978"
HERBERT, J. D. Metropolitan Edison Co
79/05/07 1p

--790610038 "Annual Financial Report 1978"
Metropolitan Edison Co & GPU Service Corp
78/12/31 319pp

J Insurance & Liability Information

790610024 Forwards Undermarket 24 to NRELU Policy IF-73
GIBNEY, H. F. GPU Service Corp
79/05/18 2pp

790626029 Forwards supplemental limit of liability endorsement to Policy IF-73 effective 790501. Supplemental limit does not apply to events re 790508 THE incident.
DUBEN, C. R. American Nuclear Insurers
79/05/18 2pp

P Operating license stage documents & correspondence

790321060 Amend 49 to License 398-50 & Amend 9 to 398-73, incorporating modified amended physical security plan into license
REED, R. W. Operating Reactors Branch 4 (79-79028)
79/05/20 4pp

790629064 Forwards info on THE incident followup actions by NRC in response to 790518 memo
MILLARS, F. J. License Fee Management Branch
79/06/17 3pp

790626062 Describes major drawbacks to locating sampling sinks for leak until in sink room Unit 2 sink must be moved & installed after flooded before unit 1 can be supported
DUBEN, C. R. Metropolitan Edison Co
79/05/24 2pp

DOCKETED ITEMS

67

7904020100 Forwards update of health physics status of Facility Info
also sent to LV Council for use in memo to NRC
KIMBERLY M Region I, Philadelphia, Office of the Director
7/9/05/07 2pp

7904030100 Confirms 790515 Notice w/ J. Holman & M. Burns The training
dept intends to resume licensed operator requalification
program as 790521
MILLER, D P Metropolitan Edison Co 7/9/05/15 1p

7904030200 Discusses 790100 will response to NRC 790104 re re handling
of fuel load within fuel handling 50g Unit response
Inadequate definition of special areas re lead handling
requires analysis 5 Tech Spec changes
MILLER, D P Operating Reactors Branch 4 (Pm 790402) 7/9/05/17
2pp

7904030300 Discusses operational-related problem re starting Shorter
after 1979 unit outage; leak developed in decay heat removal
sys which has apparently never permanently repaired
YAMAS, D P Region I, Philadelphia, Office of the Director
7/9/05/17 1p

7904030300 Advises that proposed reduction in frequency of core flow
rate verifications is acceptable
MILLER, D P Operating Reactors Branch 4 (Pm 790402) 7/9/05/17
2pp

7904030310 Forwards "BSU 177 Fuel Assembly Owners' Group Asymmetric
LOCA Loads Evaluation Program-Phase 2" & "BSU 177 Owners'
Group Report for Asymmetric LOCA Loads Evaluation-Phase 2"
MILLER, D P Metropolitan Edison Co 7/9/05/18 1p

7904030310 "BSU 177 Fuel Assembly Owners Group Asymmetric LOCA Loads
Evaluations Program-Phase 2" & "BSU 177
Metropolitan Edison Co 7/9/04/10 2pp

7904030320 "BSU 177 Fuel Assembly Owners Group Asymmetric LOCA Loads
& Acceptance Criteria Report for Asymmetric LOCA Loads
Evaluation-Phase 2"
Metropolitan Edison Co 844-1508 7/9/04/30 2pp

7904040200 Notifies of discharge of 7,400 gallons of water on 790514 &
7,120 gallons of water on 790515 Water released as sufficient
of mechanical draft cooling tower discharge, expelling waste
MILLER, D P Metropolitan Edison Co 7/9/05/26 2pp

7904050077 Notifies info requested by 790502 re re adequacy of station
electric distribution sys voltage will be provided by 790501
MILLER, D P Metropolitan Edison Co 7/9/04/20 1p

7904050400 Forwards info in response to 790525 re re feedwater line
checking AGL info will be submitted by 790527
MILLER, D P Metropolitan Edison Co 7/9/05/26 1pp

0 Investigation reports: IE Bulletin & correspondence

7904050324 Forwards IE Insp Rpts 50-025/79-08 & 50-025/79-07 on
790319-22 & 25 Re noncompliance noted
MILLER, D P Region I, Philadelphia, Reactor Operations Nuclear
Support Branch 7/9/04/20 2pp

7904050320 IE Insp Rpts 50-025/79-08 & 50-025/79-07 on 790319-22 & 25
Re noncompliance noted Major areas inspected previous 108
Findings reflected licensee events & licensee follow-up
prompt RO
MILLER, D P Region I, Philadelphia, Reactor
Operations Nuclear Support Branch 7/9/04/19 10pp

7904050400 Forwards IE Bulletin 79-026, "Nuclear Incident at
TMI-Suppl" & No written response required
MILLER, D P Region I, Philadelphia, Office of the Director
7/9/04/23 1p

7904070237 Responds to IE Bulletin 79-01 requesting review to determine
if Yelan swing check valves are installed in seismic
Category 3 piping sys Valves not installed or scheduled to
be installed at facility
MILLER, D P Metropolitan Edison Co 7/9/08/01 1p

7904080149 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Support Problem" & No action required
MILLER, D P Region I, Philadelphia, Office of the Director
7/9/05/07 2pp,

7904100308 Forwards IE Bulletin 79-10, "Requalification Training
Program Statistics" & Written response required
MILLER, D P Region I, Philadelphia, Office of the Director
7/9/05/11 1p

7904080119 Forwards IE Info Notice 79-02, "Attempted Damage to New Fuel
Assembly"
MILLER, D P Region I, Philadelphia, Office of the Director
7/9/05/11 1p

7904080207 Forwards IE Circular 79-06, "Attempted Extortion - Lew
Carbide"
MILLER, D P Region I, Philadelphia, Office of the Director
7/9/05/10 1p

7904070120 Requests info re manual trip on low pressure level as
stated in item 4f of IE Bulletin 79-03B
MILLER, D P Division of Project Management 7/9/05/08 2pp

7904050324 Forwards results of steam generator eddy current tube insp.
performed 790505-0308 during 1979 refueling outage
MILLER, D P Metropolitan Edison Co 7/9/05/08 2pp

7904070011 Lists IE Bulletin issued since TMI incident which have
been withheld due to lack of available technical resources
MILLER, D P Region I, Philadelphia, Office of the Director
7/9/04/08 2pp

0 Reportable occurrences, LERs & related correspondence

7904040308 Forwards LER 79-009/03L-0
MILLER, D P Metropolitan Edison Co 7/9/04/03 1p

7904040323 LER 79-009/03L-0 on 790315 dc breaker CB3 failed to trip on
one of several tests Caused by apparent binding of breaker
operating linkage Binding may have been due to insufficient
service of breaker prior fact of maintenance
MILLER, D P Metropolitan Edison Co 7/9/04/03 2pp

7904040304 Forwards LER 79-011/03L-0
MILLER, D P Metropolitan Edison Co 7/9/04/17 1p

7904040304 LER 79-011/03L-0 on 790318 during visual testing, one snubber
did not fluid in reservoir Caused by pinched rod upper seal
Snubber will be replaced & refilled
MILLER, D P Metropolitan Edison Co 7/9/04/17 2pp

7904070354 RD 79-09/1p on 790327 during surveillance of turbine driven
emergency steam pump, pressure regulating valve RS-V46 was
found manually closed Unit was in hot shutdown Valve was
opened & pump successfully tested
MILLER, D P Metropolitan Edison Co 7/9/04/11 1p

DOCKETED ITEMS

F Operating license shape documents & correspondence

790620293 Notification of 790618 meeting w/utls re status of seismic reanalysis per IE Bulletin 79-07
HANSBRO, J M Operating Reactors Branch 3 (Re 790623) 79/03/17
1p

7906120426 Notification that current plans do not call for installation of containment atmospheric control systems to submit summary description of proposed and 6 proposed schedule of implementation by 790915
ANDERSON, D C Boston Edison Co 79/06/06 1p

G Inspection reports, IE Bulletins & correspondence

7906140096 Forwards IE Insp Rpt 50-293/79-03 on 790213-16 No noncompliance noted
HANSBRO, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/26 2pp

7906140112 IE Insp Rpt 50-293/79-03 on 790213-16 No noncompliance noted Major areas inspected licensee action on previous Insp Findings
ANDERSON, D C Region 1, Philadelphia, Office of the Director
HANSBRO, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/29 2pp

7906000103 Responds to IE Bulletin 79-03 re weld defects in ASST SW-362 Type 304 stainless steel pipe spools Plant does not use weld spools
ANDERSON, D C Boston Edison Co 79/04/17 1p

7906110026 Forwards IE Bulletin 79-08, "Reactor Incident at TMI-2" No written response required
OHLER, B H Region 1, Philadelphia, Office of the Director 79/04/23 1p

7906070103 Responds to IE Bulletin 79-07 Discusses methods of analysis, program listings, program verification & place of action & legacy Computer code (including work)
ANDERSON, D C Boston Edison Co 79/04/24 2pp

7906020380 Forwards response to IE Bulletin 79-08, Items 1-10 Response to item 11 will be made within 30 days Training program in need established Lists all manual level instrumentation
ANDERSON, D C Boston Edison Co 79/04/29 13pp

7906050428 Respond to IE Bulletin 79-04, "Incorrect Weights for Valve Check Valves May by Valen Engineering Corp." Lists installed valves by system number of valves & valve size
ANDERSON, D C Boston Edison Co 79/05/01 2pp

7906120611 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Water Generator Not Resulted in Reactor Power Increase." No written response required
OHLER, B H Region 1, Philadelphia, Office of the Director 79/06/02 1p

7906120447 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem." No action required
OHLER, B H Region 1, Philadelphia, Office of the Director 79/06/07 2pp

7906110035 Forwards IE Bulletin 79-10, "Recirculation Training Program Statistics." Written response required
OHLER, B H Region 1, Philadelphia, Office of the Director 79/06/11 1p

7906260091 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
OHLER, B H Region 1, Philadelphia, Office of the Director 79/07/11 1p

7906260202 Notification of 790616 meeting w/utls in Bethesda, MD to discuss status of seismic reanalysis per IE Bulletin 79-07
HANSBRO, J M Operating Reactors Branch 3 (Re 790623) 79/05/18 1p

7906270166 Submits addl response to IE Bulletin 79-04 Seismic & weight load safety assumed per recalculation
ANDERSON, D C Boston Edison Co 79/05/17 2pp

7906280029 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
OHLER, B H Region 1, Philadelphia, Office of the Director 79/06/18 1p

7906290775 Responds to IE Bulletin 79-10, "Recirculation Training Program Statistics." Forwards shd recirculation training program statistics
ANDERSON, D C Boston Edison Co 79/03/26 2pp

7906000250 Responds to 790624 letter request Forwards supplementary info re response to IE Bulletin 79-07 & number design
ANDERSON, D C Boston Edison Co 79/03/25 2pp

7906200026 Responds to IE Bulletin 79-01 & 79-08 re safety-related ASST selected valves Five such valves in use Analysis shows valves not unqualified Valves shd not be used in 24-hr reporting
ANDERSON, D C Boston Edison Co 79/03/15 2pp

H Periodic operating reports & related correspondence

7906100348 Forwards monthly operating report for May 1979
MCQUIRE, P J Philadelphia Electric Co 79/06/11 1p

7906100250 Monthly operating report for May 1979
MCQUIRE, P J Boston Edison Co 79/06/07 2pp

I Reportable occurrences, LERs & related correspondence

7906100317 Forwards LER 79-004/03-5
MCQUIRE, P J Boston Edison Co 79/02/14 1p

7906100317 LER 79-004/03-5 on 790107 main steam line low pressure switches used to activate at approx 35 psig Below Tech Spec requirements Caused by limited setpoint drift Existing surveillance program successfully adequate
MCQUIRE, P J Boston Edison Co 79/02/16 1p

7906100300 Forwards LER 79-008/017-1
MCQUIRE, P J Boston Edison Co 79/06/06 1p

7906120308 LER 79-018/017-1 on 790618 recirculation pump started w/utls temp between loops greater than 30 F & reactor coolant temp greater than 212 F Caused by failure to follow station operating procedure & loop monitors
MCQUIRE, P J Boston Edison Co 79/06/06 1p

DOCKET NO-394 NUCLEAR STATE UNIV RESEARCH REACTION

J Insurance & indemnity information

7906210036 Executed Amend 9 to Indemnity Agreement 6-38
SMITHSON, J Antitrust & Indemnity Group 79/05/28 1p

K Inspection reports, IE Bulletins & correspondence

7906010078 Forwards IE Insp Rpt 50-294/79-03 on 790207-28 Notice of violation withheld (ref 10CFR 7903)
HANSBRO, J A Region 3, Chicago, Office of the Director 79/04/30 2pp

7906020079 IE Insp Rpt 50-294/79-03 on 790207-28 Noncompliance noted re inspections & hardware details withheld (ref 10CFR 7903)
CHRISTENSEN, D Region 3, Chicago, Office of the Director
HANSBRO, J A Region 3, Chicago, Refueling Branch 79/04/30 1p

7906110060 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
HANSBRO, J A Region 3, Chicago, Office of the Director 79/06/11 1p

7906280172 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
HANSBRO, J A Region 3, Chicago, Office of the Director 79/06/18 1p

L Reportable occurrences, LERs & related correspondence

7906290844 Advises of incident on 790615 fuel pump indication dropped & reset during full power operation Caused by failure of thermocouples in RS serial number 7032 fuel element Meter connected to other fuel element
SMITHSON, J Michigan State Univ 79/06/22 1p

DOCKET NO-899 ILLINOIS NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

RECD: C Commonwealth Edison Co 79/04/06 Bpp

790403040 Forwards status report of unfinished and required to improve level of fire protection All work completed except for gas suppression sys. fire doors & reactor coolant pump
RECD: C Commonwealth Edison Co 79/04/06 Bpp

Q Regulatory correspondence

790403035 Inference of document containing info potentially relevant to

level of safety of spent nuclear fuel & of NRC assessment of info to be made available
RECD: C Commonwealth Edison Co 79/04/06 Bpp

790403020 Forwards II Bulletin 79-0409 1st re testimony in proceedings
SOLSKER, H Illinois, State of 79/04/02 Bpp

790403045 Notices that hearing will be held at Zion, IL on 790403-15,
& 790403-22 of needed Limited appearance will be received
LUTHER, C Atomic Safety and Licensing Board Panel 79/04/03 Bpp

790403040 Amends NRC 790405 Interrogatories Add info will be filed
when available Certificate of Rev mtg
SOLSKER, H Illinois, State of 79/04/02 Bpp

790403009 Complaint for injunctive relief in City of Lancaster v NRC
Filed in EC US District Court West management of
radiation discharge
CINAT Concerned Citizens of Lake County, IL 79/05/03 Bpp

790403014 Forwards ABL 790410 order in which questions of proposed
addenda were added in light of TSI incident If similar
questions are to be considered in current proceeding, State
of IL prepared to submit testimony
SOLSKER, H Illinois, State of 79/05/03 Bpp

790403045 Disputations between NRC & Intervenor State of IL NRC
withdraws motion for summary disposition of Contention 2(a)
Motion, in turn, withdraws contention but reserves right to
submit testimony on all alternatives Certificate of Rev
mtg
SOLSKER, H Illinois, State of 79/05/03 Bpp

790403014 Orders time change for 790403 evidentiary hearing
will start at 2 PM instead of 9 AM
LUTHER, C Atomic Safety and Licensing Board Panel 79/04/04 Bpp

790403003 Notice of reconstitution of ABL JF Wolf replaces E Luten
as Chairman
LUTHER, C Atomic Safety and Licensing Board Panel 79/04/03 Bpp

J Insurance & indemnity information

790404017 Forwards executed Amends 21.1.9 & 1 to Indemnity Agreement
B-10, B-47, B-50 & B-54, respectively
POLSKER, R Commonwealth Edison Co 79/05/29 Bpp

790403020 Forwards Endorsements 41 & 42 to NABU Policy RF-54
OSBKA, J Commonwealth Edison Co 79/04/12 Bpp

F Operating license stage documents & correspondence

790403037 "in-Plant Source Term Measurements at Zion Station"
ENR, H C SURFING, R L - DRONET, G T. CO & G, Inc 9/8/92/08-0715
79/05/03 400pp Available at NRC

790403039 Forwards Amends 47 & 48 to Licenses DPR-36 & DPR-48,
respectively, safety evaluation & notice of issuance &
availability
SOLSKER, C Operating Reactors Branch 1 (Prr 7904029) 79/04/09, Bpp

790403035 Safety evaluation supporting Amends 47 & 48 to Licenses
DPR-36 & DPR-48, respectively
Operating Reactors Branch 1 (Prr 7904029) 79/04/09 Bpp

790403032 Forwards PR notice of proposed issuance of Amends to
facility
SOLSKER, C Operating Reactors Branch 1 (Prr 7904029) 79/04/07 Bpp

790403039 PR notice of proposed issuance of Amends to facility
SOLSKER, C Operating Reactors Branch 1 (Prr 7904029)
79/04/07 Bpp

790403039 Requests for controlled copies of site emergency plans &
implementing procedures, site maps showing location & grid
station number of onsite & offsite warning monitoring
stations & site maps used for dose determinations
NEPFLER, J C Region 3, Chicago, Office of the Director 79/05/17 Bpp

790403012 Requests Revision 7 to Addendum 1 of CE-1-A Revision
displays organizational changes in QA program
INASD, V Quality Assurance Branch 79/06/06 Bpp

790403039 Responds to IE Bulletin 79-01 Forwards info re environ
modification of Class II equipment required to function
under accident conditions & info re use & maint of ABCD
relieve valves
RECD: C Commonwealth Edison Co 79/06/14 Bpp

790403039 Forwards info re PWR Feedwater Lines in response to V Bulletin
790328 request for revised drawings in Central Files
RECD: C Commonwealth Edison Co 79/06/19 Bpp

790403017 Replies of necessity of examination of feedwater lines to
determine needs & tubes will be installed in steam steam
generators Evaluation of support of water activation will
determine feasibility
RECD: C Commonwealth Edison Co 79/06/20 Bpp

B Inspection reports, IE Bulletin & correspondence

790403055 Forwards IE Insp Repts 90-295/79-03 & 90-024/79-03 on
790328-10 re non-compliance noted
SOLSKER, H Region 3, Chicago, Fuel Facility & Materials Safety
Branch 79/04/05 Bpp

790403055 IE Insp Repts 90-295/79-03 & 90-024/79-03 on 790328-10 re
non-compliance noted Major areas inspected emergency planning
activities including generating station emergency plan &
contingency measurements Insp
SOLSKER, H Region 3, Chicago, Office of the Director 79/04/05 Bpp

790404048 Forwards IE Insp Repts 90-295/79-03 & 90-024/79-03 on
790328-07 & 27-03 re non-compliance noted
FIDELL, L D Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/04/11 Bpp

790404052 IE Insp Repts 90-295/79-03 & 90-024/79-03 on 790328-07 &
27-03 re non-compliance noted Major areas inspected steam
generator welds, pipe welds, installation, review of
licensee records, mechanical welder tests & unreviewed items
CINAT, T. SOLSKER, H Region 3, Chicago, Office of the Director 79/04/05 Bpp

790403003 Forwards IE Info Bulletin 79-11, "Lower Reactor Vessel Head
Insulation Supports" Intra Notice re action required
NEPFLER, J C Region 3, Chicago, Office of the Director 79/05/07 Bpp

790404025 Responds to IE Bulletin 79-01 Lists Vessel Engineering
Key values identified as having incorrect units & values in
static piping analysis
RECD: C Commonwealth Edison Co 79/05/07 Bpp

790403003 Forwards IE Bulletin 79-10, "Recalcification Training
Program Statistics" Written response required
NEPFLER, J C Region 3, Chicago, Office of the Director 79/05/11 Bpp

790403008 Forwards IE Info Notice 79-12, "Accepted Damage to New Fuel
Assemblies"
NEPFLER, J C Region 3, Chicago, Office of the Director 79/05/11 Bpp

790403018 Provides addl info to 790407 1st Responds to IE Bulletin
79-04 Updated items 4 & 12 re identification of valves
having control switches are returnable to pre-TSI incident
position Plan to use hydrogen recombiner units
RECD: C Toledo Edison Co 79/05/17 Bpp

790403014 Forwards RE Circular 79-08, "Attempted Disturbance - Law
Enforced"
NEPFLER, J C Region 3, Chicago, Office of the Director 79/05/10 Bpp

790403002 Forwards IE Bulletin 79-11, "Facility Overcurrent Trip Device
in Circuit Breakers for Engineering Safety Sys" License
Action required
NEPFLER, J C Region 3, Chicago, Office of the Director 79/05/22 Bpp

DOCKETED ITEMS

790420000 Forwarded LE info Notice 79-03: "Indication of Low Water Level in Outer Contactor" *
HARRIS, J. S. Region 3: Chicago, Office of the Director 79/05/29 1p

R Periodic operating reports & related correspondence

790420022 Forwarded "Environ Monitoring on Lake MI." for Jan 1970-Sept 1978
HARRIS, J. S. Commonwealth Edison Co 79/06/01 1p

790420027 "Environ Monitoring on Lake MI." for Jan 1970-Sept 1978 by
Harriet Environ Sciences Corp
* Commonwealth Edison Co 79/06/01 913pp

790420043 Forwarded monthly operating report for May 1979
HARRIS, J. S. Commonwealth Edison Co 79/06/08 1p

790420049 Monthly operating report for May 1979
JEFFRIES, J. Commonwealth Edison Co 79/06/08 11pp

R Reportable occurrences, LEAs & related correspondence

790420092 Forwarded LER 79-002/003-0
HARRIS, J. S. Commonwealth Edison Co 79/05/08 1p

790420095 LER 79-002/003-0 on 790420 blower tripped on containment
vent particulate monitor resulting in low flow caused by
chemical overload due to dust blocking pump vent. Vent
cleaned & monitor tested & returned to service.
JEFFRIES, J. Commonwealth Edison Co 79/05/18 1p

790420028 LER 79-001 has been voided
* Commonwealth Edison Co 79/06/01 1p

790420027 LER 79-010 has been voided
* Commonwealth Edison Co 79/06/01 1p

790420030 LER 79-014 has been voided
* Commonwealth Edison Co 79/06/01 1p

790420029 LER 79-012 has been voided
* Commonwealth Edison Co 79/06/01 1p

790420014 Forwarded LER 79-012/013-0
HARRIS, J. S. Commonwealth Edison Co 79/06/01 1p

790420018 LER 79-012/013-0 on 790322 safety injection initiated due to
MI steam flow signal coincident w/low steam pressure
disturbance tripped for surveillance testing. Caused by
steamstop coupling to ADS during inadvertent reactor trip
JODRIS, J. Commonwealth Edison Co 79/06/01 4pp

790420020 Forwarded LER 79-019/019-0
HARRIS, J. S. Commonwealth Edison Co 79/06/08 1p

790420020 LER 79-019/019-0 on 790218 inadvertent safety injection
occurred from false steam pressure differential signal in
loop B initiated by waterhammer in IC feedwater line caused
by false signal. ADS solenoid valve replaced.
JODRIS, J. S. Commonwealth Edison Co 79/06/15 2pp

790218 Forwarded LER 79-040/028-0
HARRIS, J. S. Commonwealth Edison Co 79/06/19 1p

790218 LER 79-040/028-0 on 790203 during periodic testing, steamline
isolation signal developed on train A MSIV 10 failed to
close. Caused by de-scaled isolation control valve
sticking in de-energized position. Valve replaced.
JLHCOFF, N. A. Commonwealth Edison Co 79/06/19 1p

790218 Forwarded LER 79-041/030-0
HARRIS, J. S. Commonwealth Edison Co 79/06/21 1p

790218 LER 79-041/030-0 on 790202 during normal operation
excitator spray valves opened to 50% demand & NCR pressure
increased below Tech Spec Limit. Caused by operator bumping
bumpless on pressurizer master controller.
HARRIS, J. S. Commonwealth Edison Co 79/06/21 1p

Find transcriptions on non-attributed matters

0534 Transcript of 790612 hearing in Zion, IL. Re 280-481
* JEFFRIES, J. S. LITTLE, L. W. Atomic Safety and Licensing Board
L. 79/06/11 10pp

790420008 Transcript of 790612 hearing in Zion, IL. Re 482-384
HARRIS, J. S. LITTLE, L. W. Atomic Safety and Licensing Board
Panel 79/06/12 21pp

790420060 Transcript of 790612 hearing in Zion, IL. re spent fuel pool
expansion. Pg 702-958
HARRIS, J. S. LITTLE, L. W. Atomic Safety and Licensing Board
Panel 79/06/13 22pp

790420043 Transcript of 790612 hearing in Zion, IL. Pg 706-1194
HARRIS, J. S. LITTLE, L. W. Atomic Safety and Licensing Board
Panel 79/06/14 26pp

790420060 Transcript of 790612 hearing in Zion, IL. Pg 1193-1365
Testimony & qualifications of J. M. Bray, et al.
HARRIS, J. S. LITTLE, L. W. Atomic Safety and Licensing Board
Panel 79/06/15 20pp

60627 50-2% BROWNS FERRY NUCLEAR POWER STATION, UNIT 3
J. Insurance & indemnity information

790420029 Forwarded Endorsements 40 & 41 to NAEU Policy 16-04
FIELDER, J. Marsh & McLaughlin, N. S. Nuclear Consultants, Inc. 79/06/04 2pp

P Operating license stage documents & correspondence

790420014 Forwarded Amends 50.44, 52 to License DPF-33, DPF-52 &
DPF-58, respectively; safety evaluation & notice of issuance &
availability re move to standby gas treatment system.
JEFFRIES, J. S. Operating Reactors Branch 3 (Pw 790625)
79/05/04 2pp

790420019 Amends 50.44 & 52 to License DPF-33, DPF-52 & DPF-58,
respectively; modifying electrical controls & instrumentation
for standby gas treatment system.
JEFFRIES, J. S. Operating Reactors Branch 3 (Pw 790625)
79/05/04 2pp

790420015 Safety evaluation supporting Amends 50.44 & 52 to License
DPF-33 & DPF-52 & DPF-58, respectively.
* Operating Reactors Branch 3 (Pw 790625) 79/05/04 2pp

790420016 Notice of issuance & availability of Amends 50.44 & 52 to License
DPF-33 & DPF-52, respectively.
JEFFRIES, J. S. Operating Reactors Branch 3 (Pw 790625)
79/05/04 2pp

790420008 Forwarded Amends 50.40 & 52 to License DPF-33, DPF-52 &
DPF-58, respectively; safety evaluation & notice of issuance &
availability.
JEFFRIES, J. S. Operating Reactors Branch 3 (Pw 790625)
79/05/11 2pp

790420009 Amends 51.49 & 52 to License DPF-33, DPF-52 & DPF-58,
respectively; accelerating change of power supply for certain
low pressure coolant injection valves.
JEFFRIES, J. S. Operating Reactors Branch 3 (Pw 790625)
79/05/11 1pp

790420009 Safety evaluation supporting Amends 51.45 & 52 to License
DPF-33, DPF-52 & DPF-58, respectively.
* Operating Reactors Branch 3 (Pw 790625) 79/05/11 10pp

790420010 Notice of issuance & availability of Amends 51.45 & 52 to
License DPF-33, DPF-52 & DPF-58, respectively.
JEFFRIES, J. S. Operating Reactors Branch 3 (Pw 790625)
79/05/11 1pp

790420019 Forwarded addl revisions & relief requests to licensee pump
& valve testing program. Revisions are based on review of
facility design for compatibility w/ABR Section 31
requirements.
GILLMAN, J. E. Tennessee Valley Authority 79/06/04 2pp

790420001 Forwarded general info re surge operations & analysis of
pump valve operability.
GILLMAN, J. E. Tennessee Valley Authority 79/06/12 21pp

790420019 Forwarded "Secondary Containment Leak Rate Test, 90-Day Rept."
GILLMAN, J. E. Tennessee Valley Authority 79/06/19 1p

790420019 "Secondary Containment Leak Rate Test, 90-Day Rept."
* Tennessee Valley Authority 79/06/11 8pp

DOCKETED ITEMS

71

0 Inspection reports, IF Bulletin & correspondence

7906100710 Forwarded IE Insp Rpts 50-259/79-08, 50-260/79-08 & 50-261/79-08 re 790521-16 Noncompliance noted Reactor Branch 79/03/27 App

7906100714 IE Insp Rpts 50-259/79-08, 50-260/79-08 & 50-261/79-08 re 790521-16 Noncompliance noted Reactor Branch 79/03/27 App

7906100720 Response re IE Bulletin 79-07 Forwarded results of safety analysis of safety-related piping 79/04/24 App

7906100703 Response re IF Bulletin 79-08 Forwarded results of investigation of operational errors & misalignments identified during TMI incident 79/04/24 App

7906100718 Forwarded IE Circular 79-07, "Unexpected Speed Increases of Reactor Motor Generator Set Resulted in Reactor Power Increase." No written response required 79/05/02 App

7906100795 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpts 50-260/79-08, 50-261/79-08 & 50-262/79-08 79/05/09 App

7906100664 Forwarded IE Bulletin 79-10, "Equalization Training Program Abolished." Written response required 79/05/11 App

7906100650 Forwarded add response re IF Bulletin 79-04 re incorrect valve weights Reactor zero isolation cooling piping remedied using correct weight of valve using check valves 79/05/11 App

7906100715 Response re IF Bulletin 79-09 re OGE TMI-A-2 breakers breakers used in safety-related sys at plant; none found equipped with surge-voltage trip device 79/05/11 App

0 Periodic operating reports & related correspondence

7906100279 Forwarded Monthly operating rpt for May 1979 79/06/11 App

7906100030 Monthly operating rpt for May 1979 79/06/25 App

7906100265 Forwarded revision to "Reactor Radioactivity Levels-Annual Rept 1978" re superseded rpt issued 790627 Revision corrects some radioactive levels. Conclusions in original rpt are still valid 79/06/10 App

7906100274 "Reactor Radioactivity Levels-Annual Rept 1978" revised version 79/06/21 App

2 Reportable occurrences, LSRs & related correspondence

7906100277 Forwarded LER 79-056/03-0 79/06/09 App

7906100281 LER 79-005/03-0 re 790527 observed erratic indication of Torus Hydrogen sensor H2M-75-20 caused by defective sensor 79/06/05 App

0 Inspection reports, IF Bulletin & correspondence

7906100081 Ack receipt of 790417 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpts 50-111/79-08 & 50-257/79-08 79/06/27 App

7906100082 Response to NRC 790403 ltr re violations noted in IE Insp Rpts 50-111/79-08 & 50-257/79-08 corrective actions procedures for reporting component failures to higher officers will be implemented by 790511 79/05/17 App

7906100607 Forwarded IE Insp Rpts 50-111/79-08 & 50-257/79-08 re 790513-16 & notice of violation 79/06/03 App

7906100609 Notice of violation from Insp re 790513-16 79/06/02 App

7906100609 IE Insp Rpts 50-111/79-08 & 50-257/79-08 re 790513-16 Noncompliance noted failure to develop procedures required to establish IOPRAT program & failure to document & approve temporary procedure change 79/06/02 App

7906100351 Ack receipt of 790419 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpts 50-111/79-08 & 50-257/79-08 79/06/03 App

7906100254 Response to NRC 790507 ltr re violations noted in IE Insp Rpts 50-111/79-08, 50-257/79-08 & 79-0841/79-01 corrective actions from 792 prepared properly & copy for period Oct 1978 - Mar 1979 forwarded re Region II 79/06/19 App

7906100609 Forwarded IE Insp Rpts 50-111/79-08, 50-257/79-08 & 79-0841/79-01 re 790529-21 Notice of violation withheld (ref IOPRAT 7901) 79/06/02 App

7906100702 IE Insp Rpts 50-111/79-08, 50-257/79-08 & 79-0841/79-01 re 790529-21 Noncompliance noted failure to ensure & report accountability values re production & consumption of SM 79/06/02 App

7906100614 Forwarded IE Insp Rpts 79-12, "Attempted Damage to New Fuel Assemblies" 79/06/10 App

7906100278 COOPER NUCLEAR REACTORS
Insurance & indemnity information

7906100237 Forwarded Correspondence 36 & 37 to NRELU Policy 79-70 79/06/25 App

0 Operating license stage documents & correspondence

7906100238 Notification of 790510 meeting w/ NRC & Nuclear Power Consultants, Inc to discuss responses to 790513 QA questions. 79/06/03 App

7906100228 Forwarded Amend 56 to License DFR-46 safety evaluation & notice of issuance & availability 79/06/23 App

7906100213 Amend 56 to License DFR-46, adding conditions for completion of code & implementation of administrative controls for fire protection 79/06/23 App

7906100241 Fire protection safety evaluation supporting Amend 56 to License DFR-46 79/06/23 App

7906100248 Notice of issuance & availability of Amend 56 to License DFR-46 79/06/23 App

7906100270 Forwarded add info & revision to 790509 QA program for operating per Section II of PWRM Amend 25 79/06/23 App

DOCKETED ITEMS

--7906030271 Add para 6 revision to 790109 QA program for operation
+ Nebraska Public Power District 79/05/05 14PP

7906030108 Forwards "Proposed Radiological Effluent Tech Spec,"
"Effluent Data Assessment Manual," & "Radiological Emission
Monitoring Manual."
PLANT:J.M. Nebraska Public Power District 79/05/05 3pp

--7906030101 "Proposed Radiological Effluent Tech Spec."
+ Nebraska Public Power District 79/05/05 32pp

--7906030105 "Effluent Data Assessment Manual."
+ Nebraska Public Power District 79/05/05 80pp

--7906030107 "Radiological Emission Monitoring Manual."
+ Nebraska Public Power District 79/05/05 40pp

7906030272 Forwards results of analysis performed by GE to suppression
pool sump transients. Will revise station operating procedure
by 790620 to incorporate reaction vessel.
PLANT:J.M. Nebraska Public Power District 79/05/28 40pp

7906020257 Requests that NRC-24612, "Vessel Header Defector Load
Definition," be included in Reactor
PLANT:J.M. Nebraska Public Power District 79/05/01 1p

7906030192 Requests that NRC-25070-F, NRC-21471-2 & NRC-14507-F be
included in Reactor Repts. were transmitted to NRC by GE in
support of facility containment evaluation program.
PLANT:J.M. Nebraska Public Power District 79/05/15 2pp

7906030281 Requests radiological Tech Spec. be revised to allow
personnel access to enclosures required for ins & possible
repair of defective transient reactor grade guide tube. Repair
work will take place during June plant shutdown.
PLANT:J.M. Nebraska Public Power District 79/05/21 4pp

0 Inspection report: IE Bulletin & correspondence

7906040025 Responds to IE Bulletin 79-03. USN has no intention of
using NRC DA-12 Type 204 & 214 stainless steel pipes
spec'd only by Youngstown Welding & Engineering Co.
PLANT:J.M. Nebraska Public Power District 79/04/12 1p

7906040180 Forwards IE Insp Rept 30-270/79-06 as 790304-08. No
noncompliance noted.
RAGSDEN, G.L. Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/19 2pp

--7906030184 IE Insp Rept 30-270/79-06 as 790304-08. No noncompliance
noted. Major areas inspected: document control, corporate level
QA audit, off-site review committee function & affixate
support staff.
RAGSDEN, G.L., JOHNSON, E.L., RAGSDEN, G.L. Region 4, Dallas,
Reactor Operations Nuclear Support Branch 79/04/19 7pp

7906100020 Responds to IE Bulletin 79-07, "Dynamic Stress Analysis of
Safety-Related Piping." Re-evaluation of safety related valve
discharge piping will be completed by approx 790520. Forward
summary of verification programs.
PLANT:J.M. Nebraska Public Power District 79/04/24 4pp

7906020341 Responds to IE Bulletin 79-08. Forwards results of review of
DAB eye design & operational procedures.
PLANT:J.M. Nebraska Public Power District 79/04/22 4pp

7906070373 Responds to IE Bulletin 79-04, "Inadvertent weights for Guling
Cable Failure Prg. by Velen Engineering Corp." One piping sig
in Category 1 is affected.
PLANT:J.M. Nebraska Public Power District 79/05/05 4pp

7906030139 Forwards IE Circular 79-07, "Unexpected Speed Increase of
Reactor Motor Generator Set Resulted in Reactor Power
Increase." No written response provided.
SEYFRIED, K.V. Region 4, Dallas, Office of the Director 79/05/02 1p

7906100049 Responds to IE Bulletin 79-09, "Failure of GE Type A-2
Circuit Breakers in Safety-Related G-1." GE Type A-2
circuit breakers are not in use or planned for use at
facility.
PLANT:J.M. Nebraska Public Power District 79/05/04 1p

7906100271 Forwards IE Info Notice 79-1, "Lower Reactor Vessel Head
Insulation Support." Written response provided.
SEYFRIED, K.V. Region 4, Dallas, Office of the Director 79/05/07 1p.

7906100084 Forwards IE Bulletin 79-10, "Requalification Training
Program Statistics." Written response provided.
SEYFRIED, K.V. Region 4, Dallas, Office of the Director 79/05/11 1p

7906030023 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies."
SEYFRIED, K.V. Region 4, Dallas, Office of the Director 79/05/10 1p

7906030155 Discusses IE effort to develop insa method to evaluate
procedural deficiencies. One can lead to increased human
error. Site will be visited by contractor to obtain info for
review.
RAGSDEN, G.L. Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/05/23 1p

7906030201 Forwards IE Info Notice 79-13, "Indication of Low Water
Level in Dryer Crawl Sump."
SEYFRIED, K.V. Region 4, Dallas, Office of the Director 79/05/29 1p

0 Periodic operating reports & related correspondence

7906100294 Forwards monthly operating report for May 1979.
RAGSDEN, G.L. Nebraska Public Power District 79/06/04 1p

--7906100297 Monthly operating report for May 1979.
RAGSDEN, G.L. Nebraska Public Power District 79/06/04 4pp

5 Requirable occurrences, LERs & related correspondence

7906100108 Forwards PNO-79-ATW.
RAGSDEN, G.L. Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/05/09 1p

7906100110 Forwards PNO-79-ATW.
RAGSDEN, G.L. Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/05/12 1p

7906030231 Forwards LER 79-008/02L-0.
LEONARD, C. Nebraska Public Power District 79/05/10 2pp

--7906030232 LER 79-008/02L-0 as 790420. Breaker IFA failed to trip when
control switch operated. In trip caused by failure of
auxiliary switch contact mounted inside breaker. IFA is main
power electrical contact breaker inspected & cleaned.
RAGSDEN, L.F. Nebraska Public Power District 79/05/10 1p

7906030233 Forwards LER 79-009/02L-0.
LEONARD, C. Nebraska Public Power District 79/05/02 3pp

--7906030235 LER 79-009/02L-0 as 790430. Four penetrations found leaking
exteriorly during leak test. Leak test caused by defects in
flangeless operator torque switch, seal rings & shaft valves.
All defects repaired.
RAGSDEN, G.L. Nebraska Public Power District 79/05/02 1p

7906030236 Forwards LER 79-011/02L-0.
LEONARD, C. Nebraska Public Power District 79/05/02 2pp

--7906030234 LER 79-011/02L-0 as 790424. Reactor water cleanup. IR-18
connector failed to close manually during cold shutdown.
Caused by failure of auxiliary contact mechanism. Repairs
completed per IE Bulletin 79-28.
SCHNEIDER, J.L. Nebraska Public Power District 79/05/02 1p

7906100020 Forwards LER 79-010/02L-0.
LEONARD, C. Nebraska Public Power District 79/05/02 2pp

--7906030231 LER 79-010/02L-0 as 790424. Surface linear indication found
in weld RAD-02-13, main steam to A & B RHR heat exchangers.
& IR-18. Isolation caused by welding error. Defect removed.
RAGSDEN, L.F. Nebraska Public Power District 79/05/02 1p

7906030238 Forwards LER 79-010/02L-0.
LEONARD, C. Nebraska Public Power District 79/05/02 2pp

--7906030238 LER 79-010/02L-0 as 790111. During performance of withdrawal
control rod operability, control rod 33-30 was found
unlatched. Rod control rod drive caused by improper assembly
of unlatching of control rod drive unit was replaced.
RAGSDEN, L.F. Nebraska Public Power District 79/05/02 1p

7906100273 Forwards PNO-79-ATW & AP.
RAGSDEN, G.L. Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/05/26 1p

DOCKETED ITEMS

J. Insurance and indemnity information

7904190457 Forwards Enderbrenners 25-26 6-27 to NRC/US Policy HP-W1
DUCR, J. M. Marsh & Mullen, H. & H. Nuclear Consultants, Inc Div
79/04/12 3pp

P. Operations license, outage documents & correspondence

7904200571 Notification of 790325 meeting until in Bethesda-MD to
discuss details of safety concerns at facility resulting
from TH-2 accident
OHLBY, J. C. Operating Reactors Branch 4 (Pfr 790420) 79/04/20
2p

7904200156 Responds to 790329 ltr re proposed work to reactor coolant
flow sensing sys. Forwards safety evaluation work. Work
must be implemented prior to restart from current refueling
outage
REID, R. M. Operating Reactors Branch 4 (Pfr 790420) 79/05/11
2pp

--7904200162 Safety evaluation supporting work of design of redundant
instrument sensing lines for reactor coolant flow
+ Operating Reactors Branch 4 (Pfr 790420) 79/05/11 2pp

7904200220 Summary of 790517 Affirmation Summary 79-12 in Washington.
DC Orders to shut down reactor for reason of increased
safety & reliability were approved
OHLBY, J. C. Office of the Secretary of the Commission 79/05/17
1p

7904200274 Notifies that review of 790228 submittal re Cycle 2 raised
required add'l info
REID, R. M. Operating Reactors Branch 4 (Pfr 790420) 79/05/20
App

7904200283 Forwards add'l info re Cycle 2 & physics startup questions. In
response to 790223 request
STEART, W. P. Florida Power & Light Co 79/05/21 2pp

7904200302 Enderbrenners plans to implement permanent solution to ECCS small
break analysis problem. Requests exemption be granted
to provisions of 10CFR50.46 to operate at licensed core
thermal power until 790420
STEART, W. P. Florida Power Corp 79/04/03 App

7904200318 Forwards Tech Specs Figures 2-1 & 2-2 & Boxes Figures 2-1, 2-2, 2-3
on graph paper. Figures 2-1 & 2-2 & 2-3 re design to more
accurately depict break points on respective curves
REID, R. M. Florida Power Corp 79/04/04 App

7904200364 Responds to NRC 790302 ltr. Discusses new design for reactor
control annulus seal ring support sys. Describes
operating procedure until new sys installed
STEART, W. P. Florida Power & Light Co 79/04/06 App

7904200376 Forwards revised response to 790335 submittal of add'l info
re physics startup test program
STEART, W. P. Florida Power Corp 79/04/08 App

7904200404 Forwards comparison between sys parameters used in BSM small
break analysis & actual parameters of facility. In response
to NRC review team request BSM analysis applicable to
facility
STEART, W. P. Florida Power Corp 79/04/15 App

7904200420 Ack receipt of NRC 790325 request for add'l info re feedback
lines for plant steam generators W-15 reviewed drawings
STEART, W. P. Florida Power Corp 79/04/19 App

7904200435 Forwards revised design needs to reactor trip on loss of
feedwater flow or turbine trip. Complexes safety responses to
NRC review team concerns re design changes proposed in
790351 ltr
STEART, W. P. Florida Power Corp 79/04/22 30pp

Q. Inspection reports, IE Bulletins & correspondence

7904200502 BSM site inspector daily rept on 790407 Plant status reactor
operating at 75% power w/13 emergency safety features in
svc. Refueling outage scheduled for 790423
MCHEWY, T. J. GUION Region 2, Atlanta, Office of the Director
79/04/07 App

7904200149 BSM site inspector daily rept on 790408 Plant status reactor
operating at 73% capacity w/one coolant pump shut down due
to seal leakage
MCHEWY, T. J. GUION Region 2, Atlanta, Office of the Director,
79/04/08 App

7904200509 BSM site inspector daily rept on 790409 Plant status reactor
operating at 75% w/one coolant pump shut down due to leaky seal
ack Refueling outage scheduled for 790426
MCHEWY, T. J. GUION Region 2, Atlanta, Office of the Director
79/04/09 App

7904200509 BSM site inspector daily rept on 790411 Plant status reactor
at 75% power w/one coolant pump shut down due to leaky seal
ack Refueling outage scheduled for 790426
MCHEWY, T. J. GUION Region 2, Atlanta, Office of the Director
79/04/11 App

--7904200120 BSM site inspector daily rept on 790411 Plant status reactor
at full power w/one emergency relief valve blocking
valve closed due to leak through pressure relief valve
JENNISON, A., MILLER, J., MORAN Region 2, San Francisco, Office
of the Director 79/04/11 App

7904200307 BSM site inspector daily rept on 790412 Plant status reactor
at 75% power w/one reactor coolant pump secured due to
suspect seal
MCHEWY, T. J. Region 2, Atlanta, Office of the Director 79/04/12
2pp

7904200320 BSM site inspector daily rept on 790413 Plant status 74X
power w/one reactor coolant pump secured to prevent seal
degradation Outage scheduled for 790426
MCHEWY, T. J. Region 2, Atlanta, Office of the Director 79/04/13
2pp

7904200434 BSM site inspector daily rept on 790414 Plant status reactor
operating at 73% w/one coolant pump shut down to
prevent seal degradation. No major equipment out of svc
MCHEWY, T. J. Region 2, Atlanta, Office of the Director 79/04/14
App

7904200473 BSM site inspector daily rept on 790415 Plant status
reactor at 75% w/one coolant pump secured to prevent seal
degradation. No major equipment out of svc
MCHEWY, T. J. Region 2, Atlanta, Office of the Director 79/04/15
App

7904200519 BSM site inspector daily rept on 790417 Plant status power
at 74% w/one coolant pump secured to prevent seal
degradation. No major equipment out of commission
MCHEWY, T. J. Region 2, Atlanta, Office of the Director 79/04/17
1p

7904200604 Responds to IE Bulletin 79-008. Callir of reactor protection
sys has been revised & power operated relief valve has been
installed. No 13 device of findings when review of pressurizer
operation is completed
STEART, W. P. Florida Power Corp 79/04/22 App

7904200490 BSM site inspector daily rept on 790420 Plant status power
at 74% w/one reactor coolant pump secured to prevent seal
degradation. No major equipment out of svc
MCHEWY, T. J. PRICE, D. E. Region 2, Atlanta, Office of the
Director 79/04/20 1p

7904200608 Ack receipt of 790304 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 80-002/79-12
LEWIS, R. G. Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 79/05/09 1p

--7904200144 Responds to NRC 790411 ltr re violations noted in IE Insp
Rept 80-002/79-12. Corrective actions fuel handling procedures
790420 will be revised in these separate procedures
STEART, W. P. Florida Power Corp 79/05/04 App

--7904200107 Forwards IE Insp Rept 80-002/79-12 as 790307-09 & notice
of violation
LEWIS, R. G. Region 2, Atlanta, Reactor Operations Nuclear
Support Branch 79/04/11 App

--7904200114 Notice of violation from Insp on 790307-09
+ Region 2, Atlanta, Office of the Director 79/04/10 1p

7904200121 IE Insp Rept 80-002/79-12 on 790307-09 Noncompliance
noted: inadequate fuel handling procedures
BURNETT, P. T., GUION, R. J. Region 2, Atlanta, Office of the
Director 79/04/10 2p
Nuclear Support Branch 79/04/10 App

7904200430 Forwards IE info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
OHLBY, J. C. Region 2, Atlanta, Office of the Director
79/05/10 1p.

DOCKETED ITEMS

75

790310061 Forwards IE Bulletin 79-10. Requalification Training Program Statistics - Written responses required
LEWIS, R C Region 2, Atlanta, Office of the Director
79/03/11 1p

790310035W Acc receipt of 790409 ltr informing NRC of steps taken to correct violation noted in IE Insp Rpt 50-302/79-08
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/11 1p

---790419036W Responds to NRC 790320 ltr re violation noted in IE Insp Rpt 50-302/79-08 corrective actions due w/4-h rating ordered tentative installation date is 790340
STEWART, W F Florida Power Corp 79/04/09 1p

---790419037W Forwards IE Insp Rpt 50-302/79-08 on 790318-16 & notice of violation
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 2pp

---790419039W Notice of violation from Insp on 790312-16
* Region 2, Atlanta, Office of the Director 79/03/23 1p

---790419040W IE Insp Rpt 50-322/79-08 on 790312-16 Noncompliance noted failure to control & provide fire door on record storage area
OFFICE, D R - BULLARD, D A Region 2, Atlanta, Office of the Director
BULLARD, D A Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 7pp

790420044 Responds to IE Bulletin 79-05A Forwards info relevant to design of SMRs & events surrounding TMI incident
STEWART, W F Florida Power Corp 79/04/12 10pp

790420040W Requests info re manual trip on low pressurizer level as stated in item 4P of IE Bulletin 79-05E
MILLHAM, F J Division of Project Management 79/03/18 3pp

790420037W Submits add'l info to 790416 response to IE Bulletin 79-02 Section of 10-inch Schedule 10 stainless steel pipe contacted for use from Youngstown Welding & Engineering Co
STEWART, W F Florida Power Corp 79/03/18 2pp

790420032W Acc receipt of 790423 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpt 50-302/79-10
BUTLER, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/21 1p

---790420033W Responds to NRC 790410 ltr re violations noted in IE Insp Rpt 50-302/79-10 corrective actions efforts made in order to reduce possibility of equipment failure
STEWART, W F Florida Power & Light Co 79/04/22 6pp

---790420034W Forwards IE Insp Rpt 50-302/79-10 on 790313-16 & notice of violation
BUTLER, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/10 2pp

---790420037W Notice of violation from Insp on 790313-16
* Region 2, Atlanta, Office of the Director 79/04/10 1p

---790420032W IE Insp Rpt 50-302/79-10 on 790313-16 Noncompliance noted failure to implement control monitoring & surveillance program & failure to approve contractor procedures to implement noncompliance monitoring program
CROWDER, A L - HARRIS, J H Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/10 2pp

790420030W Forwards response to IE Bulletin 79-05E re generic design for implementation of safety-grade reactor trips into reactor protection system. Changes to Tech Specs will be submitted following issuance of RER
STEWART, W F Florida Power & Light Co 79/04/21 30pp

790420032W Responds to IE Bulletin 79-09 re IE Type AW-2 circuit breakers circuit breakers of this type are used in control and drive control sys
STEWART, W F Florida Power Corp 79/03/21 2pp

790420030W Responds to IE Bulletin 79-10 re requalification training program statistics Forwards format of annual examination
STEWART, W F Florida Power Corp 79/03/21 3pp

790420020W Forwards add'l info to items 1,2 & 5 of IE Bulletin 79-05E, in response to C Nelson request
STEWART, W F Florida Power Corp 79/04/13 2pp

R Periodic operating reports & related correspondence

790420026W Forwards monthly operating report for May 1979
STEWART, W F Florida Power Corp 79/06/12 1p

---790420027W Monthly operating report for May 1979
STEWART, W F Florida Power Corp 79/06/08 3pp

S Reportable occurrences, EBRs & related correspondence

790420039W Forwards LER 79-050/03L-0
STEWART, W F Florida Power Corp 79/06/06 1p

---790420040W LER 79-050/03L-0 on 790510 count-rate amplifier & rate of change amplifier for nuclear source range instrument N1-2 were inoperable caused by amplifiers being out of tolerance due to instrument drift Amplifiers recalibrated & returned to svc
COPPER, J Florida Power Corp 79/06/04 2pp

790420014 Forwards LER 79-040/03L-0
STEWART, W F Florida Power Corp 79/06/06 1p

---790420017W LER 79-040/03L-0 on 790509 count-rate amplifier & rate of change amplifier for nuclear source range instrument N1-2 were inoperable caused by amplifiers being out of tolerance due to instrument drift Amplifiers recalibrated
COPPER, J Florida Power Corp 79/06/04 2pp

790420025W Forwards LER 79-050/03L-0
STEWART, W F Florida Power Corp 79/06/08 1p

---790420028W LER 79-050/03L-0 on 790514 in Hold & diesel driven fire w/s pumps discharged to be out of svc Caused by diesel oil Reflector representative being authorized to upgrade plant procedures Personnel instructed
COPPER, J Florida Power Corp 79/06/07 2pp

790420029W Forwards LER 79-051/03L-0
STEWART, W F Florida Power Corp 79/06/11 1p

---790420030W LER 79-051/03L-0 on 790516 while performing safety shutdown surveillance BP-232 fire w/s tank level discovered to be 3.800 gallons below min allowed caused by improper design Alarm system failed to reach spec limit
COPPER, J Florida Power Corp 79/06/05 2pp

790420029W Forwards LER 79-053/03L-0
STEWART, W F Florida Power Corp 79/06/20 1p

---790420031W LER 79-053/03L-0 on 790523 while performing operability of boron injection sources & pumps, heat trace recorder failed rendering boron injection inoperable Caused by loose drive card Card reinstalled & recorder returned to svc
COPPER, J Florida Power Corp 79/06/13 2pp

790420014W Forwards LER 79-056/01T-0
STEWART, W F Florida Power & Light Co 79/04/23 1p

---790420016W LER 79-056/01T-0 on 790413 cracks in 4,140 volt emergency gas unmoderated heat insulation leaving observed Caused by incompatibility between Loran sleeve mat & Verba-Fab vermiculite tape Cracks repaired w/recommended tape
COPPER, J Florida Power Corp 79/06/15 2pp

U Congressional/Executive Correspondence

790420006W Provides add'l info re D Browning info request re FL nuclear power situation Documents wanted produced by FL plants, documents released & consequences of possible accident
COPPER, J W Office of the Executive Director for Operations 79/05/17 3pp

---790420009W Forwards D Browning 790404 questions re FL nuclear power situation Requests necessary info for reply
HICA, D & House of Rep 79/04/20 2pp

---790420003W Acc receipt of 790405 ltr re D Browning info request re FL nuclear power situation Forwards documents to operators re ways to prevent occurrence like TMI & JCS Memo 790410 testimony to Subcommittee on Nuclear Regulation w/ re: accident
HARRIS, J C Office of Congressional Affairs 79/04/18 1p

DOCKETED ITEMS

DOCKET 50-304 ZION NUCLEAR POWER STATION UNIT 2

F Rectifying, medical, emergency & fire protection plans

7904010340 Forwards status report of unfinished and required to improve level of fire protection. All items completed except for gas suppression sys. fire doors & reactor coolant pump
 REED, C Commonwealth Edison Co 79/04/06 App

G Adjudicatory correspondence

7903210375 Inform of document containing info potentially relevant to issue of sabotage of spent nuclear fuel & of NRC assessment of info to be made available
 GOSWARD, R J Branch 2 79/02/26 Dep

7904010320 Forwards H Kneiff 790409 letter re testimony in proceedings
 SCHULER, R H Illinois State of 79/04/12 Dep

7904010410 Reaffirms that hearing will be held at Zion, IL on 790411-15, & 790420-23. If needed limited appearances will be received on 790411
 LUTHE, R Atomic Safety and Licensing Board Panel 79/04/03 Dep

7904010266 Answers MR 790409 interrogatory. Adm info will be filed upon available Certificate of Rev and
 SCHULER, R H Illinois State of 79/04/27 App

7904010091 Complaint for injunctive relief in City of Lancaster v NRC filed in DC US District Court. Reeks equipment of radioactive discharge
 CHAT, T Concerned Citizens of Lake County, IL 79/05/03 Dep

7904010199 Forwards AMLR 790410 order in which questions of proposed made were asked in light of TMI incident if similar questions are to be considered in current proceeding. State of IL prepared to submit testimony
 SCHULER, R H Illinois State of 79/05/03 Dep

7904010613 Stipulation between NRC & Intervenor. State of IL NRC withdraws appeal for summary disposition of Substantive 2(d) State, in turn withdraws contention but reserves right to submit testimony on all alternatives NRC/Certificate of Rev
 GOLDBERG, S C Branch 2 SCHULER, R H Illinois State of 79/05/13 Dep

7904010814 Orders time change for 790401 evidentiary hearing. Hearing will start at 2 PM instead of 9 AM
 LUTHE, R Atomic Safety and Licensing Board Panel 79/04/04 Dep

7904020081 Motion for reconstitution of AMLR. JF Wolf replaces E Luten as Chairman
 LAM, R M Atomic Safety and Licensing Appeal Panel 79/04/05 Dep

I Insurance & indemnity information

7904010187 Forwards executed Amends 21-11-9 & 1 to Indemnity Agreements
 8-10, 9-47, 0-59 & 0-64, respectively
 POOLE, R B Commonwealth Edison Co 79/05/29 App

F Operating license stage documents & correspondence

7904010579 "in-Plant Source Term Measurements at Zion Station" -
 GOSWARD, R J, GOSWARD, R J, GOSWARD, R J, GOSWARD, R J, GOSWARD, R J
 79/02/03 800pp Available at NTH

7904020399 Forwards Amends 47 & 48 to Licensee SPR-39 & SPR-46, respectively, safety evaluation & notice of issuance & availability
 SCHULER, R A Operating Reactors Branch 1 (PFA 790405) 79/04/09 Dep

7904020345 Safety evaluation supporting Amends 47 & 48 to Licensee SPR-39 & SPR-46, respectively
 Operating Reactors Branch 1 (PFA 790405) 79/04/09 Dep

79040100780 Forwards PR notice of proposed issuance of Amends to Facility 2
 SCHULER, R A Operating Reactors Branch 1 (PFA 790405) 79/04/27 Dep

7904010770 PR notice of proposed issuance of Amends to Facility 2
 SCHULER, R A Operating Reactors Branch 1 (PFA 790405) 79/04/27 Dep

7904010270 Determines that 790406 RD re instrument bus 2111 as "dirty power" is not reportable
 HANSEN, M E Commonwealth Edison Co 79/05/07 Dep

7904020309 Requests two reclassified copies of site emergency plans & implementing procedures, site maps showing location & grid station number of several off-site neutron monitoring stations & site maps used for dose determinations
 KEFFLER, J C Region 2, Chicago Office of the Director 79/05/17 Dep

7904070190 Accepts Revision 7 to Addendum 1 of CE-1-A Revision Certificate - organizational changes to QA program
 HANSEN, M F Quality Assurance Branch 79/04/06 Dep

7904020305 Responds to IE Bulletin 79-31 Forwards info re various qualification of Class IE equipment required to function under accident conditions & info re use & maintenance of AEC selected valves
 REED, C Commonwealth Edison Co 79/04/14 Dep

7904020293 Forwards info re PWR Reactor Lines. In response to V State
 790402 request two overhauls drawings in Central Files
 REED, C Commonwealth Edison Co 79/04/19 App

7904020179 Notification of necessity of abandonment of Feedwater lines to determine need & tubes will be installed on seven steam generators. Evaluation of suspected of water activation will determine revision
 REED, C Commonwealth Edison Co 79/04/20 App

D Inspection reports, IE Bulletin 3, correspondence

7904020255 Forwards IE Insp Repts 50-295/79-02 & 50-304/79-03 as 790312-16. No noncompliance noted
 DAVIS, A E Region 2, Chicago, Fuel Facility & Materials Safety Branch 79/04/03 Dep

7904020365 IE Insp Repts 50-295/79-02 & 50-304/79-03 as 790312-16. No noncompliance noted. Major areas inspected emergency planning activities including generating stations, emergency plan & emergency response, maintenance, etc.
 SCHULER, R H Region 2, Chicago, Office of the Director 79/04/03 Dep

7904040045 Forwards IE Insp Repts 50-295/79-02 & 50-304/79-03 as 790312-16 & 27-28. No noncompliance noted
 SCHULER, R H Region 2, Chicago, Reactor Construction & Engineering Support Branch 79/04/03 Dep

7904040052 IE Insp Repts 50-295/79-02 & 50-304/79-03 as 790312-16 & 27-28. No noncompliance noted. Major areas inspected steam generator, pressure pipe, pressure installation, review of licensee records, mechanical, pressure tests & unregulated items
 YAM, T, SCHULER, R H Region 2, Chicago, Office of the Director 79/04/03 Dep

7904020282 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Isolation Support Problem" - No action required
 KEFFLER, J C Region 2, Chicago, Office of the Director 79/05/07 Dep

7904040282 Responds to IE Bulletin 79-04 Late Volcan Engineering Corp valves identified as having incorrect weight values in seismic piping analysis
 REED, C Commonwealth Edison Co 79/05/07 Dep

7904010581 Forwards IE Bulletin 79-10, "Regualification Training Program Statistics" written response required
 KEFFLER, J C Region 2, Chicago, Office of the Director 79/05/11 Dep

7904010079 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assembly"
 KEFFLER, J C Region 2, Chicago, Office of the Director 79/05/11 Dep

7904020316 Provides adm info in 790427 letter responses to IE Bulletin 79-04. Updated items 4 & 12 re identification of valves having control switches are returnable to pre-TMI incident position. Plan to use hydro-pneumatic valves
 REED, C Commonwealth Edison Co 79/05/17 Dep

7904020316 Forwards IE Circular 79-05, "Attempted Extension - Low Stripped W."
 KEFFLER, J C Region 2, Chicago, Office of the Director 79/05/16 Dep

DOCKETED ITEMS

77

36320082 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breaker for Engineered Safety Sys - License Action required"
HOFLEIN, J J Region 3, Chicago, Office of the Director 7/7/55/22
ip

36320088 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Byster Creek Reactor"
HOFLEIN, J J Region 3, Chicago, Office of the Director 7/7/55/29
ip

Periodic operating reports & related correspondence

06270052 Forwards "Environ Monitoring in Lake MI." for Jan 1970 - Sept 1970
WANDER, H E Commonwealth Edison Co 7/6/55/01 ip

7946795127 "Environ Monitoring in Lake MI." for Jan 1970 - Sept 1968 by Hamilton Edison-Madison Corp
Commonwealth Edison Co 7/6/55/01 513pp
j

06120043 Forwards monthly operating rep for May 1970
WANDER, H E Commonwealth Edison Co 7/6/55/02 ip

7766120349 Monthly operating rep for May 1970
JEFFERS, J Commonwealth Edison Co 7/6/55/08 11pp

Reportable occurrences, LERs & related correspondence

06360352 Forwards LER 79-031/03L-0
WANDER, H E Commonwealth Edison Co 7/7/55/17 ip

790505006 LER 79-031/03L-0 on 790417 three inseparable switches were found caused by hydraulic fluid loss in two & physical disconnection at piston rod and in third Periodic trip changed from yearly to six months
HOFLEIN, J J Commonwealth Edison Co 7/6/55/17 3pp

06360323 Forwards LER 79-029/03L-0
WANDER, H E Commonwealth Edison Co 7/6/55/22 ip

790606096 LER 79-029/03L-0 on 790423 during change of starting batteries on 20 CB pump spray gun was inadvertently rendered inoperative and performing required surveillance caused by personnel error in operating multipositional switch
HOFLEIN, J J Commonwealth Edison Co 7/6/55/22 ip

36140554 Forwards LER 79-077/03L-0
WANDER, H E Commonwealth Edison Co 7/6/55/29 ip

790604061 LER 79-077/03L-0 on 790605 isolation valve 2FV-PR26A failed to remain open causing containment particulate & gas monitors 2B0301 & 2B0302 to become inoperable caused by misaligned limit switch caused by defective low voltage
USOLINE, D J Commonwealth Edison Co 7/6/55/29 ip

36140557 Forwards LER 79-029/03L-0
WANDER, H E Commonwealth Edison Co 7/6/55/21 ip

7906140372 LER 79-032/03L-0 on 790608 condenser air ejector rod monitor 2B03013 sporadically alarmed high while reading below alarm setpoint & then failed low caused by defective low voltage power supply fuses replaced
HOFLEIN, J J Commonwealth Edison Co 7/6/55/31 ip

36140511 Forwards LER 79-079/03L-0
WANDER, H E Commonwealth Edison Co 7/6/55/31 ip

7906140521 LER 79-029/03L-0 on 790521 status lights for high steam flow would not remain energized when redemptible test push button was depressed caused by defective transmitters 05 & 07 in module 0611004-0045
HOFLEIN, J J Commonwealth Edison Co 7/6/55/31 ip

36040333 LER 79-003 has been voided
Commonwealth Edison Co 7/6/55/01 ip

06040334 LER 79-003 has been voided
Commonwealth Edison Co 7/6/55/01 ip

06040337 LER 79-011 has been voided
Commonwealth Edison Co 7/6/55/01 ip

36110126 LER 79-061 has been voided
Commonwealth Edison Co 7/6/55/01 ip

36110133 LER 79-066 has been voided
Commonwealth Edison Co 7/6/55/01 ip

7906100143 LER 79-007 has been voided
Commonwealth Edison Co 7/6/55/01 ip

7906140387 Forwards LER 79-024/03L-0
WANDER, H E Commonwealth Edison Co 7/6/55/01 ip

--7906140393 LER 79-024/03L-0 on 790511 following testing of O diesel generator, starting air system test high down starting air receivers caused by loose nut across holding valve leak to test retainer valve seat replaced & packaged correctly
HOFLEIN, J J Commonwealth Edison Co 7/6/55/01 ip

7906020355 Forwards LER 79-079/03L-0 Update notes rep number change from 79-077 to 79-079
WANDER, H E Commonwealth Edison Co 7/6/55/01 ip

--7906020363 LER 79-079/03L-0 on 790605 valve 2FV-PR26A did not remain open after containment isolation test causing particulate 1 gas monitors to be inoperable caused by misaligned limit switch switch adjusted
USOLINE, D J Commonwealth Edison Co 7/6/55/02 ip

7906120343 Forwards LER 79-032/03L-0
HOFLEIN, J J Commonwealth Edison Co 7/6/55/07 ip

--7906120359 LER 79-032/03L-0 on 790508 after reactor trip, Test A reactor trip breaker failed to open caused by plunger out of adjustment in undervoltage coil
HOFLEIN, J J Commonwealth Edison Co 7/6/55/07 ip

7906120377 Forwards LER 79-010/03L-0
WANDER, H E Commonwealth Edison Co 7/6/55/07 ip

--7906120401 LER 79-010/03L-0 on 790507 reactor tripped & breaker trip A failed to open breaker taken to shop & tested M cause found breaker misaligned & verified operable
HOFLEIN, J J Commonwealth Edison Co 7/6/55/07 ip

T Hearing transcripts on non-incident matters

7906200084 Transcript of 790611 hearing in Zion IL Pg 388-480
HOFLEIN, J J, HOFLEIN, F J, LITTLE, L M Atomic Safety and Licensing Board Panel 7/6/55/11 31pp

7906200558 Transcript of 790612 hearing in Zion IL Pg 482-701
HOFLEIN, J J, HOFLEIN, F J, LITTLE, L M Atomic Safety and Licensing Board Panel 7/6/55/12 21pp

7906200560 Transcript of 790613 hearing in Zion IL re spent fuel pool expansion Pg 702-923
HOFLEIN, J J, HOFLEIN, F J, LITTLE, L M Atomic Safety and Licensing Board Panel 7/6/55/13 21pp

7906200567 Transcript of 790614 hearing in Zion IL Pg 930-1194
HOFLEIN, J J, HOFLEIN, F J, LITTLE, L M Atomic Safety and Licensing Board Panel 7/6/55/14 24pp

7906200572 Transcript of 790615 hearing in Zion IL Pg 1195-1266
Testimony & qualifications of GE Spills encl.
HOFLEIN, J J, HOFLEIN, F J, LITTLE, L M Atomic Safety and Licensing Board Panel 7/6/55/15 30pp

DOCKET 79-005 WISCONSIN NUCLEAR POWER PLANT

0 Adjudicatory correspondence

7906060004 Requests NRC authorization to issue notice of hearing on NRC order imposing civil monetary penalties for incident re potential high radiation exposure M/craft notice of hearing & 790613 request for hearing
HOFLEIN, J J, Office of the General Counsel, SECY-A-79-31 7/6/55/04, 7pp

7906200185 Forwards notices of appearance & documents ref in 790601 notice of hearing
LIBERMAN, J Rulemaking & Enforcement Division 7/6/55/03 3pp

7906200185 Notice of appearance on behalf of unit Certificate of Suit encl
HOFLEIN, J J, Foley & Lander 7/6/55/24 3pp

7906200177 Answer to 790620 notice of hearing Unit will appear before administrative law judge & present evidence. No civil penalties are in dispute no violations occurred & no civil penalties can be imposed Certificate of Suit encl
HOFLEIN, J J, HOFLEIN, J A, Foley & Lander 7/6/55/24 4pp

DOCKETED ITEMS

7904070077 Orders prehearing conference for 790321 to discuss hearing issues pending pleadings-obtaining stipulations & admissions, identifying witnesses & setting hearing schedule
SMITH, J. H. Atomic Safety and Licensing Board Panel 79/06/09 1p

J Insurance & indemnity information

7904200036 Forwards Enforcements 45 & 46 to NELA Policy NP-004
MATHIAS, E. R. Wisconsin Public Service Corp 79/06/11 3pp

7904190401 Forwards Enforcement 36 & 37 to NELA Policy NP-71
MATHIAS, E. R. Wisconsin Public Service Corp 79/06/10 3pp

P Operating license steps documents & correspondence

7904210370 Forwards Amend 30 to License DPR-43, safety evaluation & notice of issuance & availability
SCHAEFER, A. Operating Reactors Branch 1 (Pre 790625) 79/05/07 3pp

7904210380 Amend 30 to License DPR-43, revising Tech Specs to permit working turbine stop & governor valve testing at end of cycle
SCHAEFER, A. Operating Reactors Branch 1 (Pre 790625) NRC 79/05/07 3pp

7904210380 Safety evaluation supporting Amend 30 to License DPR-43
Office of Nuclear Reactor Regulation 79/05/03 3pp

7904210393 Notice of issuance & availability of Amend 30 to License DPR-43
SCHAEFER, A. Operating Reactors Branch 1 (Pre 790625) 79/05/07 3pp

7904200317 Approves trial evaluation of postulated fuel handling accident submitted 790328 Forwards safety evaluation supporting trial conclusions
SCHAEFER, A. Operating Reactors Branch 1 (Pre 790625) 79/05/09 3pp

7904200321 Safety evaluation supporting trial conclusions of postulated fuel handling accident inside containment
SCHAEFER, A. Operating Reactors Branch 1 (Pre 790625) 79/05/09 3pp

7904200392 Summary of 790350 meeting w/trial re auxiliary feedwater sys & related station areas
GLADWIN, H. Operating Reactors Branch 1 (Pre 790625) 79/05/04 3pp

7904200401 Discusses review of rad tank exchange method to verify shutdown margin for low temp Westinghouse HRS Approves method as alternative to boron exchange method; provides certain conditions are met
SCHAEFER, A. Operating Reactors Branch 1 (Pre 790625) 79/05/15 3pp

7904200440 Requests how controlled copies of site emergency plant implementing procedures, site maps showing location & grid station numbers of auxiliary monitoring stations outside of offsite & site maps used for offsite determination
MATHIAS, E. R. Region 3, Chicago, Office of the Director 79/05/17 1p

7904190303 Forwards revised proposed Amend 35 to License DPR-43, license Tech Specs re ROS overpressure protection at low temps
MATHIAS, E. R. Wisconsin Public Service Corp 79/05/15 3pp

Q Inspection reports, IE Bulletins & correspondence

7904190379 Forwards response to IE Bulletin 79-04, Revision 1 re review of operating procedures in light of TMI incident/Emergency procedures reviewed by special team Proposal to trip level indicators does not provide greater safety
MATHIAS, E. R. Wisconsin Public Service Corp 79/06/20 3pp

7904200134 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" - NW action required
NEPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/09 1p

7904200110 Forwards IE Bulletin 79-10, "Regulification Training Program Statistics" - Written response required
NEPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/11 1p

7904200108 Forwards IE Info Notice 79-13, "Attempted Damage to New Fuel Assembly"
NEPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/11 1p

7904200116 Responds to IE Bulletin 79-09 DE AK-2 circuit breakers are not in use at facility
MATHIAS, E. R. Wisconsin Public Service Corp 79/05/16 1p

7906060209 Forwards IE Circular 79-00, "Attempted Station - Low Enriched U"
NEPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/10 1p

7904200115 Forwards IE Insp Regt 50-303/79-01 on 790420-27 Notice of violation withheld (ref 10CFR2 790)
MATHIAS, E. R. Region 3, Chicago, Office of the Director 79/05/10 3pp

7904200119 IE Insp Regt 50-305/79-04 on 790420-27 Noncompliance noted etc items identified relative to physical barriers, access control, identification authorization & badging Details withheld (ref 10CFR2 790)
CROSBY, J. R. MATHIAS, E. R. MATHIAS, J. A. Region 3, Chicago, Office of the Director 79/05/17 1p

7904200121 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" - Licensee action required
NEPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/22 1p

7904200447 Responds to request for info re IE Bulletin 79-12, ISA & 120 Westinghouse is unable to provide requested info re atypical solid multi unit end of Regt Requests extension of initial date to 791031
MATHIAS, E. R. Wisconsin Public Service Corp 79/05/23 1p

7904200143 Forwards IE Info Notice 79-12, "Indication of Low Water Level in Outer Creek Reactor"
NEPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/29 1p

7904080214 Submits info on operator requalification training program, in response to IE Bulletin 79-10
MATHIAS, E. R. Wisconsin Public Service Corp 79/05/21 3pp

R Reportable occurrences, LERs & related correspondence

7904200228 Forwards LERs 79-007/03L-0 & 79-009/03L-0
MATHIAS, E. R. Wisconsin Public Service Corp 79/05/21 1p

7904200228 LER 79-007/03L-0 on 790501 during full power operation surveillance testing; use of air containment pressure transmitters was out of control caused by instrument drift
MATHIAS, E. R. Wisconsin Public Service Corp 79/05/01 1p

7904200230 LER 79-008/03L-0 on 790503 one train of heat tracing piping between air transfer pumps common discharge header & DA filter found to be inoperative during installation Covered by open circulated warmer Failed heat tracer repaired
MATHIAS, E. R. Wisconsin Public Service Corp 79/05/31 1p

7904200275 Forwards LERs 79-009/03L-0 & 79-010/03L-0
MATHIAS, E. R. Wisconsin Public Service Corp 79/06/25 1p

7904200280 LER 79-009/03L-0 on 790526 condensate storage tank level drain below Tech Spec limit during normal shutdown occurs routinely during certain hot shutdown conditions, No further corrective action necessary
MATHIAS, E. R. Wisconsin Public Service Corp 79/05/25 1p

7904200284 LER 79-010/03L-0 on 790527 auxiliary bldg special ventilation zone boundary door found blocked open Caused by failure to post proper notice on door Notice subsequently posted
MATHIAS, E. R. Wisconsin Public Service Corp. 79/05/25 1p

DOCKET 50-304 PRASLEE ISLAND NUCLEAR STATION, UNIT 2

J Insurance & indemnity information

7904120112 Forwards Enforcements 42 & 43 to NELA Policy NP-197
JOHNSON, R. G. Northern States Power Co 79/06/07 3pp

7904120112 Forwards Enforcements 38 & 39 to NELA Policy NP-68
JOHNSON, R. G. Northern States Power Co 79/06/13 3pp

P Operating license stage comments & correspondence

790603087 Forwards Amends 3a & 3b to Licenses DPR-42 & DPR-40, respectively, safety evaluation & notice of issuance & availability

80406020-A Operating Reactors Branch 1 (Pre 790625) 79/09/08 App

--790603087 Forwards Amends 3a & 3b to Licenses DPR-42 & DPR-40, respectively, pending Tech Specs to require activation of safety injection

based on 2 out of 3 channels of low pressure breakers
80406020-A Operating Reactors Branch 1 (Pre 790625) 79/09/01 App

--790603087 Safety evaluation supporting Amends 3a & 3b to Licenses DPR-42 & DPR-40, respectively

* Office of Nuclear Reactor Regulation 79/09/01 App

--790603087 Notice of issuance & availability of Amends 3a & 3b to Licenses DPR-42 & DPR-40, respectively

80406020-A Operating Reactors Branch 1 (Pre 790625) 79/09/01 App

790603094 Forwards safety evaluation for need to safety injection activation app

LAD3MS-G Plant Systems Branch 79/09/03 App

--790603094 Safety evaluation supporting need to safety injection activation app

* Plant Systems Branch 79/09/03 App

790603095 Discussion review of info re need back exchange method to verify shutdown margin for two loop Westinghouse N2S5

Approved method an alternative to boron exchange provided conditions are met

SC406020-A Operating Reactors Branch 1 (Pre 790625) 79/09/18 App

790603095 Requests wire emergency plan & implementing procedures, site maps showing isolation & grid numbers of units & safety

exercises monitoring stations & site maps used for offsite dose determinations or evacuation

80406020-A Operating Reactors Branch 1 (Pre 790625) 79/09/17 App

790603095 Forwards amend application for Licenses DPR-42 & DPR-40 in response to NRC 78113 ltr

MAVER, L. D. Northern States Power Co 79/06/01 ltr

--790603095 Application for amend to Licenses DPR-42 & DPR-40

MAVER, L. D. Northern States Power Co 79/06/01 60pp

790603095 Forwards "Process Control Program for Waste Solidification"

MAVER, L. D. Northern States Power Co 79/06/07 ltr

--790603095 "Process Control Program for Waste Solidification"

* Northern States Power Co 79/06/01 ltr

--790603095 Offsite Dose Calculation Manual

* Northern States Power Co 79/06/01 ltr

790603095 Forwards Revision 2 to "NRC Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Request

for Relief from NRC Code Section XI Requirements"

MAVER, L. D. Northern States Power Co 79/06/08 App

--790603095 Revision 2 to "NRC Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Request

for Relief from NRC Code Section XI Requirements"

* Northern States Power Co 79/06/08 App

790603095 Responds to IE Bulletin 79-07 ALEPSPE computer code used by Fluor Research for seismic analysis of on-site inspection

line analysis repeated using PIPESTRESS design found satisfactory

MAVER, L. D. Northern States Power Co 79/04/24 App

790603095 Forwards IE Insp Repts 30-288/79-08 & 30-304/79-07 on 790321-16 & 0314-16 & notice of violation

80406020-A Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/04/28 App

--790603095 Notice of violation from Insp on 790321-16 & 0314-16

* Region 3, Chicago, Office of the Director 79/04/19 ltr

--790603095 IE Insp Repts 30-288/79-08 & 30-304/79-07 on 790321-16 & 0314-16

0314-16 Noncompliance noted delayed conduct of fire up surveillance

MAVER, L. D. SMITH, J. S. STECHER, J. F. Region 3, Chicago, Office of the Director 79/04/19 App

790603095 Forwards IE Insp Repts 30-288/79-08 & 30-304/79-07 on 790321-16

0314-16 No noncompliance noted

80406020-A Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/04/28 App

--790603095 IE Insp Repts 30-288/79-08 & 30-304/79-07 on 790321-16

0314-16 No noncompliance noted

80406020-A Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/04/28 App

790603095 Responds to IE Bulletin 79-06 Valves valve weights were

increased but have been rechecked in compliance w/ violation

MAVER, L. D. Northern States Power Co 79/05/01 App

790603095 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head

Insulation Support Problem" No action required

MAVER, L. D. Region 3, Chicago, Office of the Director 79/05/07 ltr

790603095 Forwards IE Bulletin 79-10, "Regulator Training

Program Modifies" Written response required

MAVER, L. D. Region 3, Chicago, Office of the Director 79/05/11 ltr

790603095 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel

Assemblies"

MAVER, L. D. Region 3, Chicago, Office of the Director 79/05/11 ltr

790603095 Supplements 790418 response to IE Bulletin 79-07 Definite

add info re computer codes for seismic analysis

MAVER, L. D. Northern States Power Co 79/05/13 App

790603095 Forwards License responses to IE Bulletin 79-06A

MAVER, L. D. Light Water Reactors Branch 4 79/05/17 ltr

--790603095 Responds to IE Bulletin 79-06A, Revision 1 re revision of

emergency procedures for piping transients & accidents

MAVER, L. D. Northern States Power Co 79/04/30 ltr

790603095 Forwards IE Circular 79-08, "Attempted Extension - Low

Enriched U"

MAVER, L. D. Region 3, Chicago, Office of the Director 79/05/18 ltr

790603095 Responds to IE Bulletin 79-06A, Revision 1 change to Tech

Specs issued 790501 to modify safety injection logic in the

case of three low pressure breakers

MAVER, L. D. Northern States Power Co 79/05/18 ltr

790603095 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device

in Circuit Breaker for Engineered-Safety Bus"

MAVER, L. D. Region 3, Chicago, Office of the Director 79/05/23 ltr

790603095 Forwards IE Info Notice 79-13, "Indication of Low Water

Level in Dwyer Engine Reactor"

MAVER, L. D. Region 3, Chicago, Office of the Director 79/05/29 ltr

790603095 Ack receipt of 790518 ltr informing NRC of steps taken to

correct violations noted in IE Insp Repts 30-288/79-08 &

30-304/79-07

MAVER, L. D. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/24 ltr

DOCKETED ITEMS

--7906290479 Response to NRC 790429 ltr re violations noted in BE Insp Report 79-002/79-08 & 79-006/79-07 corrective actions detector testing begun 79/01/08 & completed 79/02/28
WAGNER, L. J. Northern States Power Co. 79/05/16 App

B Periodic operating reports & related correspondence

7906050024 Submit Report 1979 Environ Event Rept 79-04 re cooling tower operations
WAGNER, L. J. Northern States Power Co. 79/06/01 App

7906140029 Forward monthly operating reports for May 1979
WAGNER, L. J. Northern States Power Co. 79/06/01 App

--7906140024 Monthly operating report for May 1979
WAGNER, L. J. Northern States Power Co. 79/06/01 App

--7906140029 Monthly operating report for May 1979
WAGNER, L. J. Northern States Power Co. 79/06/01 App

C Reportable occurrences, LERs & related correspondence

7906040028 LER 79-052 has been voided
WAGNER, L. J. Northern States Power Co. 79/06/01 App

7906050024 Forward LER 79-019/03L-0
WAGNER, L. J. Northern States Power Co. 79/06/01 App

--7906050017 LER 79-019/03L-0 on 790508 during power operation nuclear power range channel DMS3 failed low due to loss of high voltage. Caused by failure of high voltage regulated source ModuL UPD-XTM Power supply related
WAGNER, L. J. Northern States Power Co. 79/06/01 App

7906140029 Environ Event Rept 79-04 in May 1979 plant circulating water treatment facility made had excessive average daily blowdown flow for 17 days caused by accumulation of cooling tower water & proper cooling water temp
WAGNER, L. J. Northern States Power Co. 79/06/01 App

7906140024 Forward LER 79-019/03L-0
WAGNER, L. J. Northern States Power Co. 79/06/01 App

--7906140028 LER 79-019/03L-0 on 790509 during mode of surveillance program found that reactor vessel injection isolation valve test BP 2039 had not been done. Caused by failure to enter test on computer surveillance schedule
WAGNER, L. J. Northern States Power Co. 79/06/01 App

7906140029 NRC 79-18 dynamic loading during post-LOCA flow before valve closure was not included in original stress analysis of Henry Pratt containment purge valves. All purge valves administratively controlled to assure closure
TIERNEY, P. P. Northern States Power Co. 79/06/01 App

DOCKET 95-329 MAINE Yankee ATOMIC POWER PLANT

A Adjudicatory correspondence

7906050028 Requests NRC reconsideration of show cause order mandating shutdown of plant
MAINE Yankee Atomic Power Co. 79/05/16 App

MAINE Yankee 790513 order requesting plant shutdown until re indicated necessary mode. Reconsidered
will & BSM indicate mode completed
Office of Nuclear Reactor Regulation 79/05/24 App

H General Correspondence

7906050023 Response to ltr re Maine Yankee shutdown, info partially withheld, name & address of recipient (ref FDIA Exemption 6)
BRADSHAW, P. A. Commission 79/05/29 App

7906050028 Response to 790528 ltr re Maine Yankee shutdown info partially withheld, name & address of recipient (ref FDIA Exemption 6)
BRADSHAW, P. A. Commission 79/06/02 App

7906050027 Response to 790531 ltr re deceptive statements made by utility info partially withheld, name & address of recipient (ref FDIA Exemption 6)
BRADSHAW, P. A. Commission 79/06/04 App

--7906050023 Response NRC investigate utility deceptive statements info partially withheld, name & address of recipient (ref FDIA Exemption 6)
BRADSHAW, P. A. Commission 79/05/31 App

7906050025 Response to ltr re Maine Yankee shutdown info partially withheld, name & address of recipient (ref FDIA Exemption 6)
BRADSHAW, P. A. Commission 79/05/10 App

7906050028 Response to 790409 ltr re 790417 earthquake in NE Earthquake not reportable, based on current info
EISENBERG, D. Division of Operating Reactors 79/05/30 App

7906050027 Response to 790513 ltr re shutdown of five nuclear power plants because of seismic concerns. Seismic design was not in accordance with accepted engineering practice. Failed piping could cause LOCA. Plant review is being expedited.
DEWITT, M. H. Office of Nuclear Reactor Regulation 79/05/09 App

--7906050028 Expresses concern re shutdown of five reactors for seismic reasons. Action involves seismic crisis. Plant shutdown is more appropriate during refurbishing shutdown. Benefits of nuclear power outweigh seismic risks.
EISENBERG, D. Affiliation Unknown 79/05/15 App

7906050028 Response to 790510 ltr re NRC 790513 orders to shut down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent.
DEWITT, M. H. Office of Nuclear Reactor Regulation 79/05/16 App

--7906050024 Comments on NRC captioned & captioned acts. Requests immediate reversal of union decision to shut down five plants. Requests more national approach to improbable safety concerns in future.
MAYNARD, G. H. Affiliation Unknown 79/05/19 App

7906050028 Response to 790514 ltr re 790513 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent.
DEWITT, M. H. Office of Nuclear Reactor Regulation 79/05/17 App

--7906050023 Comments on 790513 orders shutting down five northeastern US nuclear power plants. Requests investigation into actual probability of major seismic activity in this region.
SMITH, B. H. Affiliation Unknown 79/05/14 App

7906050028 Response to 790520 ltr re 790513 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent.
DEWITT, M. H. Office of Nuclear Reactor Regulation 79/05/17 App

--7906050028 Comments on 790513 orders shutting down five northeastern US nuclear power plants. Requests investigation into actual probability of major seismic activity in this region.
HARRIS, C. P. Affiliation Unknown 79/05/21 App

7906050023 Response to 790403 ltr re 790513 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent.
DEWITT, M. H. Office of Nuclear Reactor Regulation 79/05/17 App

--7906050023 Comments on 790513 order shutting down five northeastern US nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent.
HARRIS, C. P. Affiliation Unknown 79/05/21 App

7906050023 Response to 790521 ltr re 790513 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent.
DEWITT, M. H. Office of Nuclear Reactor Regulation 79/05/17 App

--7906050024 Comments on 790513 order shutting down five northeastern US nuclear power plants. Economic consequences for Maine, as well as power shortages, provide slim prospect of earthquake. Plants should be reassessed.
BULL, D. W. J. Affiliation Unknown 79/05/21 App

7906050028 Response to 790527 ltr re 790513 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent.
DEWITT, M. H. Office of Nuclear Reactor Regulation 79/05/17 App

--7906050024 Comments on 790513 order shutting down five northeastern US nuclear power plants. NRC should re-evaluate its antineuclear attitude.
BULL, D. W. J. Affiliation Unknown 79/05/21 App

7902298659 Responds to 790323 ltr re 790313 orders shelving down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of earthquake US earthquake zones and
 0000000000 Office of Nuclear Reactor Regulation 79/08/17 Doc

--26020007D Comments on 790301D orders shutting down five northeastern US
nuclear power plants Plants should be reopened immediately.
due to economic prospects of plant closings
SAINSBIE, J A Affiliation Unknown 79/03/23 1a

7906280076 Response to 790002 ltr to President re 790310 orders
shutting down five nuclear power plants pending review of
analysis techniques used in seismic design of safety-related
piping. Maps of northeastern US earthquake zones encl.
DOWNSIDE, N. Office of Nuclear Reactor Regulation. 14/09/77 2p

2704290000 Responds to 790028 ltr re 790013 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
DENISE H. S. Office of Nuclear Reactor Regulation 79/05/87 3p

--790627000Z Comments on 790313 orders shutting down five northeastern US
nuclear power plants Chance of earthquake is too low to risk
economic upheaval caused by closing of plants
UNCLAS F Affiliation Unknown 79/03/28 1p

7906270087 Responds to 790615 ltr re 790613 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl

--296d202091: Comments on 740213 orders shutting down five northeastern US
nuclear power plants Decision was extremely ill-conceived
HOOBAGLE, M P Affiliation Unknown 79/03/13 1p

190420085	Response to T90337 for a T90313 endops shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones and	
DEXTON-H R	Office of Nuclear Reactor Regulation	7/9/2017
		See

--7906270099 Comments on 790013 orders shutting down five northeastern US
nuclear power plants Decision was extremely ill-conceived
HAMPLE.W W Affiliation Unknown 79/03/17 1p

3700270009 Response to 3700264 ltr re 740013 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones and

--790270514 Comments on 790213 orders shutting down five northeastern U
 nuclear power plants Decision was economically
 ill-conceived
 MODPRO, G P Affiliation Unknown 79/02/14 19

7906270119 Response to 7906022 ltr re 7903013 orders shutting down five
Nuclear power plants pending review of analysis techniques
used in seismic design of safety-related piping Maps of
northeastern US earthquake zones encl
SENTOUHL# Office of Nuclear Reactor Regulation 79/06/17 3p

--7066270622 Comments on 790323 orders shutting down five northeastern US
nuclear power plants Decision was economically ill-considered
& represents flagrant federal govt overprotection through
regulatory process
BCHG,W.K. Affiliation Unknown 79/03/22. 1p

7906270124 Responds to 790324 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl. 2000000000
DISTRIBUTION: Office of Nuclear Reactor Regulation 79/05/17. Ops.

--7904270125 Comments on YOC913 orders shutting down five northeastern US nuclear power plants Decision was dramatically ill-received.
RICHARD W J Affiliation Unknown 79/03/20. ip

7906270102 Responds to 790313 ltr re 790313 orders shutting down five
nuclear power plants pending review of analytic techniques
used in seismic design of safety-related piping. Maps of
northeastern US earthquake zones and
DENTON, R. Office of Nuclear Reactor Regulation 79/03/17 Sp

--7903270123 Comments on 790313 orders shutting down five northeastern US
nuclear power plants Decision was poorly timed &
economically ill-conceived
NOVA/DNR/SLG E Affiliation Unknown 79/03/17 1p

795270423 Response to 790312 ltr re 790362 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Reaps of northwestern US earthquake zones occi
CENTROM H R Office of Nuclear Reactor Regulation 79/05/17 Doc

---7906270146 Comments on 790313 orders shutting down five northeastern US
nuclear power plants: Decision was economically
ill-considered Requests date of last recorded earthquakes
COFFIN, W S Affiliation Unknown /7/03/13 1p

7904070101 Response to 790002 ICR re 790013 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northwestern US earthquake zones encl. DENTON H. Office of Nuclear Reactor Regulation 79/05/17 Dps

--3906270155 Comments on 790313 orders shutting down five northeastern nuclear power plants Decision was 111-conceived, considering current energy crisis
NSET2601940.W Affiliation Unknown 79/03/22 15

7906270363 Responds to 7900333 dir re 7900333 orders shipping down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
DISTRIBUTION: Office of Nuclear Reactor Regulation 79/06/17 3p

--7886276264 Comments on 790313 orders shutting down five northwestern US nuclear power plants Decision was economically ill-considered
DENIAL: E M Affiliation Unknown 79/03/23 4pp

7906270263 Responds to 790313 ltr re 790313 orders shutting down five nuclear power plants pending review of analogical techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones and

DENTALHEB OFFICE of Nuclear Reactor Regulation 79/05/87 Doc

==7906270266 Comments on 790319 orders shutting down five northeastern nuclear power plants Decision was overprotective act
KATIMAGISIN, R L Affiliation Unknown 79/03/19 2pg

7902270267 Response to 790325 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones encl.

DENTON, R. Office of Nuclear Reactor Regulation 79/03/17 3p

---986276260 Comments on 790012 orders shutting down five northeastern US
nuclear power plants Decision was economically
ill-conceived
CLARE, R. C. Affiliation Unknown 79/05/25 10

```

79062104253 Responds to
  five nuclear power
  expanded to disc2
  operation w/no
  MMTV - - -

```

George Mason
DENTON, M. B. Office of Nuclear Reactor Regulation 79/05/24 10

796601027* FOIA request for all records & communications re shutdown of
five nuclear plants
Samantha H. Green, Attorney, State of New York, 79/03/16, Doc

7904130026 Salinasites criterion to develop plant-specific info
packaged on site visits
RUSSELL, W T. Office of Nuclear Reactor Regulation 79/04/11. Spp

DOCKETED ITEMS

63

--790610291 IE Insp Rept 79-024/79-02 Noncompliance noted failure to adhere to administrative controls
 MAHONEY, H. B. Region I, Philadelphia, Office of the Director
 KRITZER, H. B. Region I, Philadelphia, Reactor Operations Nuclear Support Branch 7/9/02/27 App

790610127 Forwards IE Bulletin 79-10, "Regulatory Training Program Effectiveness" Written response required
 KRITZER, H. B. Region I, Philadelphia, Office of the Director 7/9/02/11 Ip

790610201 Forwards IE Info Notice 79-02, "Attempted Damage to New Fuel Assembly"
 KRITZER, H. B. Region I, Philadelphia, Office of the Director 7/9/02/11 Ip

790610103 Submits add response to IE Bulletin 79-068 Had to Tech Spec amendment
 MAHONEY, H. B. Maine Yankee Atomic Power Co 7/9/02/14 Ip

790610088 Forwards IE Circular 79-08, "Attempted Ejection - Low Enriched U"
 KRITZER, H. B. Region I, Philadelphia, Office of the Director 7/9/02/11 Ip

790610104 Submits report re error in aspen code used in steam generator low pressure trip bistableness. Impact on limiting transient initiated in safety analysis. Detailed review of effort to be forwarded within 60 days
 MAHONEY, H. B. Maine Yankee Atomic Power Co 7/9/02/25 Ip

P. Periodic operating reports & related correspondence

790610035 Forwards monthly operating report for May 1979
 MAHONEY, H. B. Maine Yankee Atomic Power Co 7/9/02/11 Ip

--790610020 Weekly operating report for May 1979
 MAHONEY, H. B. Maine Yankee Atomic Power Co 7/9/02/12 App

B. Reportable occurrences, LERs & related correspondence

790610026 Forwards LER 79-010/033-1
 MAHONEY, H. B. Maine Yankee Atomic Power Co 7/9/02/23 Ip

--790610229 LER 79-010/033-1 on 790313 corrects information contained in LER 79-010/033-1. Contrary to statement released said error was reported in LER 79-010/033-1 on 7/9/02/03-1
 MAHONEY, H. B. Maine Yankee Atomic Power Co 7/9/02/23 App

790610041 Forwards LER 79-010/033-0
 MAHONEY, H. B. Maine Yankee Atomic Power Co 7/9/02/05 Ip

--790610244 LER 79-010/033-0 on 790313 reactor protection sys channel B low flow trip bistableness activated at 25% out of reset in condenser/evaporator direction. Caused by defective bistableness spare unit installed & calibr
 MAHONEY, H. B. Maine Yankee Atomic Power Co 7/9/02/05 Ip

790610202 Forwards LER 79-010/033-0
 MAHONEY, H. B. Maine Yankee Atomic Power Co 7/9/02/06 Ip

--790610233 LER 79-010/033-0 on 790313 reactor protection sys low pressure trip bistableness in error set at 41% only. Caused by incorrectly transferring data transmitter calibr sheets to procedure. Calibr sheets & procedures being revised
 MAHONEY, H. B. Maine Yankee Atomic Power Co 7/9/02/06 App

DOCKET 58-011 MAHONEY NUCLEAR GENERATING STATION, UNIT 2

A. Application for construction stage documents & correspondence

790610056 This report of 790320-28 visit to plant to conduct onsite review of qualifications methods & procedures for Safety Category 1 mechanical components, electrical instrumentation, control equipment & supporting structures
 CHM, P. V. Mechanical Engineering Branch 7/9/02/25 10pp

790610028 Notification of 790327 meeting with IE. Informed IE of status qualification program
 KRITZER, H. B. Light water Reactors Branch 7/9/02/04 App

790610027 Notification of completion of const & pre-occupational testing Reactor issuance of O. in order to proceed w/inital fuel loading & start-up
 KRITZER, H. B. Public Service Electric & Gas Co. of New Jersey 7/9/02/30 Ip

J. Insurance & indemnity information

790610031 Forwards Endorsements 27, 28 & 29 to MAELI Public W-VO
 CORREA, C. Marsh & McLennan, H. B. Nuclear Consultants, INC. Div 7/9/02/04 App

P. Operating license stage documents & correspondence

790610020 Forwards requested info re main feedwater events & pressurizer heaters & steam generator schematic diagram
 KRITZER, H. B. Public Service Electric & Gas Co. of New Jersey 7/9/02/23 App

D. Inspection reports, IP Bulletin & correspondence

790610040 Forwards IE Insp Rept 30-011/79-15 on 790202 IE noncompliance noted
 KRITZER, H. B. Region I, Philadelphia, Office of the Director 7/9/02/20 App

--790610041 IE Insp Rept 30-011/79-15 on 790202 IE noncompliance noted Major areas inspected: Occupational Fuel receipt & storage practices, procedures & records
 KRITZER, H. B. Region I, Philadelphia, Office of the Director 7/9/02/20 App

790610032 Forwards IE Insp Rept 30-011/79-15 on 790202-08 IE noncompliance noted
 KRITZER, H. B. Region I, Philadelphia, Reactor Construction & Engineering Support Branch 7/9/02/20 App

--790610033 IE Insp Rept 30-011/79-15 on 790202-08 IE noncompliance noted Major areas inspected: Licensee action on previous event Insp findings
 KRITZER, H. B. Region I, Philadelphia, Reactor Construction & Engineering Support Branch 7/9/02/20 App

790610043 Forwards IE Info Notice 79-10, "Investigating Pipe Support Ejection"
 KRITZER, H. B. Region I, Philadelphia, Office of the Director 7/9/02/11 Ip

790610044 Forwards IE Insp Rept 30-011/79-18 on 790313-16 & 20 IE noncompliance noted
 KRITZER, H. B. Region I, Philadelphia, Reactor Operations Nuclear Support Branch 7/9/02/16 App

--790610047 IE Insp Rept 30-011/79-18 on 790313-16 & 20 IE noncompliance noted Major areas inspected: Occupational test program, test procedure review & verification, test results evaluation & start-up test program
 KRITZER, H. B. Region I, Philadelphia, Reactor Operations Nuclear Support Branch 7/9/02/13 12pp

790610049 Forwards IE Insp Rept 30-011/79-21 on 790313-22-23 IE noncompliance noted
 KRITZER, H. B. Region I, Philadelphia, Reactor Operations Nuclear Support Branch 7/9/02/20 App

--790610049 IE Insp Rept 30-011/79-21 on 790313-22-23 IE noncompliance noted Major areas inspected: Containment & radiation process monitoring, SM-1000 & 2000 & start-up test program, including test procedure review & verification
 KRITZER, H. B. Region I, Philadelphia, Reactor Operations Nuclear Support Branch 7/9/02/19 App

790610057 Forwards IE Bulletin 79-08, "Nuclear Incident at TMI-2"
 KRITZER, H. B. Region I, Philadelphia, Office of the Director 7/9/02/23 Ip

790610001 Requests extension until 790501 to respond to IE Bulletin 79-07
 KRITZER, H. B. Public Service Electric & Gas Co. of New Jersey 7/9/02/24 Ip

790610025 Responds to IE Bulletin 79-06A Special test scope established to coordinate review & understanding of SM-2 event. Appropriate procedural revisions being prepared
 KRITZER, H. B. Public Service Electric & Gas Co. of New Jersey 7/9/02/25 23pp

790610026 Responds to IE Bulletin 79-04 re seismic Category 1 piping w/ 3/4" & 6-inch diameter valves. Heights for 6-inch valves have been corrected/adjusted confirmation of 3/4" & 6-inch heights from Velco
 KRITZER, H. B. Public Service Electric & Gas Co. of New Jersey 7/9/02/30 App

DOCKETED ITEMS

770601014 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation" Support Provided - No action required
 GRIER, B. H. Region I, Philadelphia, Office of the Director
 7/9/81/07 2pp

770601015 Forwards IE Info Notice 79-12, "Accepted Damage to New Fuel Assembly" Support Provided - No action required
 GRIER, B. H. Region I, Philadelphia, Office of the Director
 7/9/81/11 1p

770627006 Responds to IE Bulletin 79-128, "Abnormal Weld Heat in Reactor Pressure Vessel Head" - Requests extension of response due date to 7/9/81
 SCHWARTZ, P. J. Public Service Electric & Gas Co. of New Jersey
 7/9/81/14 1p

770628009 Forwards supplemental response to IE Bulletin 79-21 & 79-21A List of qualification documentation & other data and Safety-related enclosed valves used in containment have been replaced
 SCHWARTZ, P. J. Public Service Electric & Gas Co. of New Jersey
 7/9/81/15 2pp

Periodic operating reports & related correspondence

770606047 Forwards wastewater treatment report for May 1979
 HEDRICK, H. G. Public Service Electric & Gas Co. of New Jersey
 7/9/81/07 2pp

770606048 Forwards operating report for industrial waste treatment plant for May 1979
 HEDRICK, H. G. Public Service Electric & Gas Co. of New Jersey
 7/9/81/12 2pp

770606049 Forwards discharge monitoring report for May 1979
 HEDRICK, H. G. Public Service Electric & Gas Co. of New Jersey
 7/9/81/15 1pp

Reportable occurrences, LERs & related correspondence

770607006 Confirms 770601 verbal report to E. Brunner, advising of potential RO Linear cracking observed on pump impeller. More impellers now tested & also showed cracks. Impeller being sent to vendor for testing
 HEDRICK, H. G. Public Service Electric & Gas Co. of New Jersey
 7/9/81/01 1p

DOCKET NO-212 RANCHO DECO NUCLEAR GENERATING STATION

Administrative correspondence

7706020195 Itemizes structural changes for shutdown condition until all changes are made. Long-term needs to be implemented as soon as possible
 CHILDS, J. Office of the Secretary of the Commission 7/9/81/07 2pp

770602023 Requests formal hearings re shutdown and reopening of facility
 CHRISTOPHERSON, ARNOLD J. Friends of the Earth 7/9/81/10 14pp

General correspondence

770602073 Petitions for formal hearings re plant shutdown and reopening
 UNDERHILL, M. J. REISS, J. CHRISTOPHERSON Friends of the Earth 7/9/81/10 13pp

770602085 Responds to 770601 letter on reactor safety, clarifying concerns re Davis-Besse shutdown & geologic faults near Diablo Canyon
 EISENBERG, S. Division of Operating Reactors 7/9/81/22 2pp

Insurance & indemnity information

7706020144 Forwards Underwritings 21-38 & 37 to RANLU Policy HP-70 & 610000000 38-40 to RANLU Policy HP-212
 MATTHEWS, J. J. Sacramento Municipal Utility District 7/9/81/09 7pp

Operating license status documents & correspondence

770600099 Notification of 770604 meeting w/UCIL in Bethesda, MD to discuss plant and required by NRC order resulting from TSC-2 event.
 GRIER, B. H. Operating Reactors Branch 4 IPN 7706020 7/9/81/03 1p

770604014 Ack receipt of 770603 letter (initially exemption from Class III fee for proposed Test Spec Amend 63) Submitted is not exempt from fee since NRC review effort is required
 MILLER, M. D. License Fee Management Branch 7/9/81/14 2pp

770610030 Reviews spec-101 testing unit for facility personnel & Sacramento Municipal Utility District 7/9/81/03 2pp

7706100315 Confirms 770603 turbine re part turbine & feedwater initiating events investigations of direct reactor trip as turbine would result in decrease of 3% before expected high pressure trip
 MATTHEWS, J. J. Sacramento Municipal Utility District 7/9/81/04 2pp

770610033 Forwards summary of 770603 turbine & feedwater initiating events investigation of direct reactor trip as trip will result in decrease of five plus seconds before normally expected high pressure trip
 MATTHEWS, J. J. Sacramento Municipal Utility District 7/9/81/04 2pp

7706100373 Forwards 40000 amend fee under protest
 EISENBERG, S. Sacramento Municipal Utility District 7/9/81/05 2pp

7706100387 Details add photos of turbine info as required by Commission Order NO 2590-01 Auxiliary feedwater flow values are within acceptable limits Reactor trip as loss of main feedwater or turbine trip is functional
 MATTHEWS, J. J. Sacramento Municipal Utility District 7/9/81/09 1p

7706100379 Confirms 770607 report, "Evaluation of Transient Behavior & Small Reactor Control Gas Drains in 177-Fuel Assembly Plant," was based on actual parameters. Details table comparing parameters used in analysis
 MATTHEWS, J. J. Sacramento Municipal Utility District 7/9/81/03 2pp

7706100344 Forwards info in response to 770603 turbine Auxiliary feedwater stop flow will be initiated automatically in case of feedwater loss flow provided by one auxiliary feedwater pump is sufficient to maintain plant in safe condition
 TAYLOR, J. H. Babcock & Wilcox Co. 7/9/81/03 2pp

7706100348 Provides auxiliary feedwater test space to verify design flow rate in each vapor generator on design back pressure & to verify ability to establish flow rate without auxiliary feedwater valves electrically failed
 EISENBERG, S. Sacramento Municipal Utility District 7/9/81/03 1p

7706100356 Describes design change to provide control-grade trap at reactor on generator/turbine trip &/or loss of main feedwater
 EISENBERG, S. Sacramento Municipal Utility District 7/9/81/03 2pp

7706100375 Responds to 4 Israel 770601 letter Forwards graphs re diesel generator loads during May 1974 safety features test
 MATTHEWS, J. J. Sacramento Municipal Utility District 7/9/81/04 2pp

7706100448 Notifies that submission of revised radiological effluent fact sheet is delayed until 770715
 MATTHEWS, J. J. Sacramento Municipal Utility District 7/9/81/06 1p

7706100305 Forwards info requested as 770603 re feedwater piping Diagram of steam generator w/ feedwater line diagram & feasible drawings and sketches of feedwater piping data suggest inspection and a scheduled maintenance program
 MATTHEWS, J. J. Sacramento Municipal Utility District 7/9/81/10 10pp

Inspector reports: IE Bulletin & correspondence

7706020126 Forwards IE Insp Report NO-212/79-20 on 770610-20-30 & 1206-15 & 10 IE non-compliance noted
 GRIER, B. H. Region I, San Francisco, Reactor Operations Nuclear Support Branch 7/9/81/09 2pp

7706020127 IE Insp Report NO-212/79-20 on 770610-20-30 & 1206-15 & 10 IE non-compliance noted Major areas inspected reusing activities, main pipe support & reheat pipe, feedwater as previous time findings & plant operations
 GRIER, B. H. Region I, San Francisco, Office of the Director, PIA/DOE/NSR, Region I, San Francisco, Reactor Operations Nuclear Support Branch 7/9/81/07 2pp

DOCKETED ITEMS

7904070408 B&F site Inspector daily rept on 790407 Plant shaken reactor
operating at full power since known problems Major student
decommission expected 790408
ENTER:11, CARLESON, J Region 5, San Francisco, Office of the
Director 79-04-07 2p

7906290100 BSAF auto inspector daily rept on 7906000 Plant status reactor
operating at full power w/no known problems Amilnuclear
demonstration expected on 7906000
JRM:GJF - HQM:A Region 5, San Francisco. Office of the
Director. 790604/00 Rm.

790620071 SWM site inspection daily rept on 790409 Plant status reactor
at full power w/no inspec problems
J090026P , HQHILA , Region 2, San Francisco, Office of the
Director 79/04/09 2a

99AC00010 B6W like Inspector daily rept on T93410 Plant status reactor at 754 power w/one coolant pump shut down due to seal leakage/leakage constant at 2.1 gallons per minute

RECEIVED J. J. QUICK, Region 2, Atlanta, Office of the Director
T93410 204

--PROGMO42 B&M site inspector Jolly rept on 790410 Plant status reactor
 operating normally at full power Monthly surveillance of
 diesel generator B completed
 RULLEN L. - HORN, A. Region 3, San Francisco, Office of the
 Director 79/04/SD 2pp

790320Z Forwards 1E Insp Rept 90-012/79-06 on 790320-23 & 29 No
noncompliances noted
8006.H.E Region 5, San Francisco, Fuel Facility & Materials
Safety Branch 79/04/12 Jss

--7908010254 SE Insp Rept 80-202/79-06 on 790220-23 & 29 No noncompliance
with Major areas inspected license action on previous
findings-radioactive waste sys. SE of analytical measurements
is independent insp effort
120PM:R S. BOSE,H E Region 3, San Francisco Office of the
Director 79/04/12 Bop

790409(12) BSW site inspector daily rept on 790413 Plant status reactor at full power w/no known problems Verified accuracy of containment isolation valve lineup procedures w/P510 JONHNSA, HELGELL Region 3, San Francisco, Office of the Director 790412 1p

790606045 SEN site Inspector daily rept on 790614 Plant status reactor operating at full power w/no known problems No major maint or surveillance scheduled
JONGSEN, A. MILLER, L. Region 3, San Francisco Office of the Director 790614 2pm

790200489 BW w/ve inspector daily rept on 790415 Plant status reactor operating at full power w/no known problems No significant maint scheduled
JONGMAN, A. MILLER, L Region 3, San Francisco Office of the Director 79/04/15 2pm

290290104 Responds to IE Bulletin 79-03A Forwards info re review of
operating procedures
MATTING, J J Sacramento Municipal Utility District 79/06/16
To

790420000 BSW site inspector daily report on 790412 Plant status reactor at full power w/no known problems, no major maint planned & no engineering safety features out of svc
JOHNSON, A. MILLER, L. Region 5, San Francisco, Office of the Director 79/04/12 Bsw

FROM: 0658 BSM site inspector daily rpt on 790417. Plant status, reactor at full power, w/no significant maint or surveillance scheduled.

ADDRESSES: JCHH804/P Region 3, San Francisco, Office of the Director 79/04/17 2nd

7/10/2008 Response to SE Bulletin 79-058 re setpoint changes in
reactor protection sys
MATTINGE, J. J., Sacramento Municipal Utility District, 79/04/02 1p

--795028090 Comments on IE Bulletin 79-05 Dismisses operator control
of automatic actions of engineered safety features
BATTING, J. J. Sacramento Municipal Utility District 79/04/10
2pg

--79042809Z Submit partial response to IE Bulletin 79-05 & 79-05A re review of TMI accident chronology to preclude similar occurrences.
NATTHUSE, J. Sacramento Municipal Utility District 79/04/11
Tss

2906140190 Fernando LE Insp Regt 30-212/79-04 on 79002A-0302 No
compliance noted
CRSAB-JL Region 9: San Francisco, Reactor Operations Nuclear
Support Branch 7/9/04/25 gpg

7706140200 DE Insp Rept 30-312/79-04 on 770226-0702 Re noncompliance noted Major areas inspected surveillance test program
BARBER, W. S. JOHNSON, A. B. WITT, N. Regens S. San Francisco, Office of the Director 77/04/24 Rep

790629D475 BSW site inspection daily report on 790620 Plant status reactor operating at full power w/no known problems All engineering safety features operational Next outage scheduled 790912
JOHNSON, P., MORRILL, P Region 5, San Francisco, Office of the Director 79/04/30 2pg

7956290132 Responds to IE Bulletin 79-038 Forwards info re procedures
& methods for maintaining natural circulation
HATTINSE, J. J. Sacramento Municipal Utility District 79/05/02
4pg

7906120000 Forwards JE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Support Problem" - No action required
SMELKREH,R H Region 5, San Francisco Office of the Director
79/06/07 1c

7904260331 Forwarded IE Insp Rept 30-012/79-07 ex 790331-0504 Re noncompliance noted
CREWED L Region 5: San Francisco, Reactor Operations Nuclear
Bureau's Branch 19/05/09 204

--936626543 IE Insp Rpt 59-582/79-07 an 790331-0304 No noncompliance noted Major areas inspected plant operations & IE activities re TMI-2 incident
JOHNSON A., JOHNSON P., FAULKNER, B. Region 5: San Francisco Reactor Operations Nuclear Support Branch 79/05/08
Tpo

790180488 Forward: 18 Info Notice 79-12. "Attempted Damage to New Fuel
Assemblies - No written response necessary
ENGELDAHL R H Region 3, San Francisco, Office of the Director
79/05/10 12

2906410077 Forwards IE Bulletin 79-10, "Regualification Training Program Statistics." Written response required.
CUMULATIVE IN Region 5, San Francisco. Office of the Director
79/08/11 is

79050024 Forward: IE Circular 99-09: "Attempted Extortion - Law
Enforced U"
ENFORCEMENT Section B, San Francisco, Office of the Director
March 19, 1999

7906270120 Requests info re manual trip on low measurable level as
related to item #P of IE Bulletin 79-089
WILLIAMS, J Division of Project Management 79/05/10 Dpp

9904590000 Forward 1E Bulletin 74-11, "Faulty Overcurrent Trip Device
in Circuit Breakers for Engineered Safety Sys - Licensee
action required
ENGINEER, E H Region 3, San Francisco, Office of the Director
7/9/05/02 sp

7906203095 Forward IE Info Notice 79-18. "Indication of Low Water Level in Oyster Creek Reactor"
KRODLKRN R H Region 3, San Francisco. Office of the Director
79/06/29 1c

7906180075 Forwards IE Bulletin 79-12, "Short Period Screen at SGR
Facilities." No written response necessary.
ENGLAND, R H Region 5, San Francisco- Office of the Director,
79/06/01 14

8. Periodic operating reports & related correspondence

7966190252 Forwards monthly operating report for May 1979
SODRIGUEZ, R J Sacramento Municipal Utility District 79/06/07,
1a

--7906100034 Monthly operating report for May 1979.
COLONEL R M Sacramento Municipal Utility District. 79/05/21
Enc.

■ Reportable occurrences: U.S. & related correspondence

790618002E Forward PNO-T9-67AH
DYNELKEN, R H Region 5, San Francisco, Office of the Director,
T9/05/14 1g

DOCKETED ITEMS

- 7904180278 Forwards FWS-79-A340
ZHEBELMAN, R H Region 3, San Francisco, Office of the Director
79/03/22. 1p
- 7904180347 Forwards FWS-79-A34P
ZHEBELMAN, R H Region 3, San Francisco, Office of the Director
79/03/22. 1p
- 7904180370 Forwards FWS-79-A34D
ZHEBELMAN, R H Region 3, San Francisco, Office of the Director
79/03/30. 1p
- 7904180389 Forwards LER 79-005/03L-0
MATTINDIE, J J Sacramento Municipal Utility District 79/04/11 1p
- 7904180581 LER 79-005/03L-0 on 790509 bus inaccessible safety gas hydraulic snubbers were inoperable Cause unknown One snubber repaired & tested; other snubber refilled
COLGROB, R W Sacramento Municipal Utility District 79/04/11 1p
- 7904190310 Forwards LER 79-001/04I-0
MATTINDIE, J J Sacramento Municipal Utility District 79/04/13 2pp
- 7904190516 LER 79-001/04I-0 on 790529 plant liquid effluent pH exceeded 9.5 limit Probably caused by error based associated w/ pH alarm subsequent investigation feasibility of reducing error band
COLGROB, R W Sacramento Municipal Utility District 79/04/13 1p
- DOCKET 90-010 ARKANSAS NUCLEAR ONE, UNIT 1
F. Security, medical, emergency & fire protection plans
- 7906070147 Response to 790612 let re OK action of fire protection plan Unit has met guidelines of "Nuclear Plant Fire Prevention Function Responsibilities: Administrative Controls & GA." No changes planned
TRINLE, D C Arkansas Power & Light Co 79/04/18 2pp
- D Adjunctive correspondence
- 7906120030 Orders licensee to maintain facility in shutdown condition until specified actions are satisfactorily completed
Licensee may request hearing w/ respect to order within 30 days. Request may not stay effectiveness of order
CHILKA, J. Office of the Secretary of the Commission 79/05/17 7pp
- 7906120139 Orders exempt actions to be taken re design model & changes in operating procedures Unit shall be shut down until factory completion of actions Long-term mode accomplished promptly
J. Office of the Secretary of the Commission 79/05/17
- a shutdown of facility until satisfactory completion of re- operation procedures, evaluation of issues & personnel compliance w/ approved
- 7906060556 Summary of 790509 meeting w/ Unit in Bethesda, MD re contract order to test annual switching involved in starting emergency feedwater pump
VIGORINO, G S Operating Reactors Branch 4 (Pw 790625) 79/05/14, App
- 7906120443 Notification of 790521 meeting w/ Unit in Bethesda, MD to discuss current voltage analysis relating to loading 3F-3 for acceptability w/ General Design Criteria 17
VIGORINO, G S Operating Reactors Branch 4 (Pw 790625) 79/05/18 1p
- 7906040267 Submit info re feedwater & turbine trips resulting in reactor trips & emergency feedwater flow test following starting
TRINLE, D C Arkansas Power & Light Co 79/05/22 2pp
- 7906280252 Forwards Amend 43 to License 39F-31, safety evaluation & notice of issuance & availability
REIS, R W Operating Reactors Branch 4 (Pw 790625) 79/05/23 2pp
- 7906290303 Amend 43 to License 39F-31 revising Tech Specs to reflect plant operating limits for fuel loading to be used in Cycle 4 & adding add weeks/heat detectors & fire suppression gas
REIS, R W Operating Reactors Branch 4 (Pw 790625) 79/05/23 2pp
- 7906290304 Safety evaluation supporting Amend 43 to License 39F-31
Operating Reactors Branch 4 (Pw 790625) 79/05/23 10pp.
- 7906290308 Notice of issuance & availability of Amend 43 to License 39F-31
REIS, R W Operating Reactors Branch 4 (Pw 790625) 79/05/23 2pp
- 7906070138 Response to NRC questions in 790323 meeting re analysis of diesel generator pickup, emergency feedwater flow indication, automatic annunciation in control room & permanent operator training staff Two overruled drawings and
TRINLE, D C Arkansas Power & Light Co 79/05/24 7pp
- 7906060298 Response to NRC questions resulting from 790517 order. Two questions will be violated in control room at all times until electric emergency feedwater pump is permanently connected to vital power
TRINLE, D C Arkansas Power & Light Co 79/05/28 1p
- 7906060306 Discussed and of operating guidelines for small breaks HPI must remain in operation until LPBB is in operation & flooding in excess of 1,000 gallons/minute in each line & stable for 30 minutes
TAYLOR, J H Babcock & Wilcox Co 79/05/20 2pp
- 7906100148 Forwards proposed changes to Tech Specs limiting conditions for operation related to anticipated reactor trip on loss of main feedwater w/ or turbine trip
CAWANAUGH, M Arkansas Power & Light Co 79/06/04 4pp
- 7906120357 Supplements 790516 submitted which proposed changes to Tech Specs Supp restrictions and requirements re automatic activation of pumps & block valves Also revises surveillance requirements
CAWANAUGH, M Arkansas Power & Light Co 79/06/08 7pp
- 7906190246 Forwards APL-TOP-1A, Revision 8, "QA Manual Operations," will Facility A21 3B re grant test testing & add 160 on Position A21, 6 re physical properties of reinforcing steel
TRINLE, D C Arkansas Power & Light Co 79/06/11, App.
- 7906190248 "QA Manual Operations," Revision 8
CAWANAUGH, M Arkansas Power & Light Co APL-TOP-1A, 79/06/11, 12pp
- 7906190264 Submit response to 790602 order re review of plant procedures & methods of developing procedures
CAWANAUGH, M Arkansas Power & Light Co 79/06/12 2pp
- 7906190468 Response to NRC 790602 order to review safety procedures & methods for development Appropriate steps will be taken to ensure personnel adherence to proper procedures & avoid bypassing procedures included in 790602 NO
CAWANAUGH, M Arkansas Power & Light Co 79/06/12 3pp
- 7906290306 Submit info re design changes in emergency feedwater automatic activation logic & flow control valve band switches in control room add operator training & procedural changes
TRINLE, D C Arkansas Power & Light Co 79/06/13 4pp

- 790402014 Forwards overlaid drawings of corrected feedwater lines to steam generator, including results of stress analysis tests & details of welding procedures used in making modifications. piper-to-piper & pipe welds, in response to 790325 request
TRIMBLE, D C Arkansas Power & Light Co 79/04/10 1pp
- 790402015 Submits add'l info re pressure effluent monitoring sys. in response to 790315 request. Discusses location of effluent monitoring sys detectors, range of scintillation detectors & min detectable release rate
TRIMBLE, D C Arkansas Power & Light Co 79/04/22 1pp
- 0 Inspection reports, IE Bulletin & correspondence
- 790403022 Forwards IE Insp Rpts 50-313/79-04 & 50-346/79-04 to 790312-0312 & notice of violation
MORRIS, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/04 2pp
- 790404014 Notice of violation from Insp on 790328-09
Region 4, Dallas, Office of the Director 79/04/05 1p
- 790404012 IE Insp Rpts 50-313/79-04 & 50-346/79-04 on 790305-09 Noncompliance noted failure to calibrate effluent monitors
MORRIS, G L Region 4, Dallas, Office of the Director MORRIS, G L Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/04/08 2pp
- 7904040209 Responds to IE Bulletin 79-038 Re: ASME SA-312 Type 304 Insufficiently welded pipe w/bs by Yangtzeon Welding & Engineering Co installed in safety-related sys Examination program being developed
TRIMBLE, D C Arkansas Power & Light Co 79/04/04 1p
- 790407018 Responds to IE Bulletin 79-038 re ECCS Describes revised procedures for maintaining natural circulation during insulator Support Problem - Action required
SEYFRIED, M V Region 4, Dallas, Office of the Director 79/04/07 1p
- 790407010 Requests criteria for continued operation of charging pump
MILLER, F J Division of Project Management 79/04/08 1p
- 790410003 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics" Written response required
SEYFRIED, M V Region 4, Dallas, Office of the Director 79/04/11 1p
- 7904250016 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
SEYFRIED, M V Region 4, Dallas, Office of the Director 79/04/11 1p
- 790427034 Forwards IE Region IV evaluation of licensee response to IE Bulletin 79-038
WARRA, S A Light Water Reactors Branch 4 79/04/11 1p
- 790427038 Evaluates licensee 790404 response to IE Bulletin 79-038 re revision of procedures for natural circulation & engineered safety features activation
MORRIS, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/10 2pp
- 790427044 Forwards response to IE Bulletin 79-038 re revisions of procedures & training operation personnel on schematics & maintaining natural circulation
TRIMBLE, D C Arkansas Power & Light Co 79/04/10 1p
- 7904270120 Requests info re annual trip on low pressu station in Item 4F of IE Bulletin 79-038
MILLER, F J Division of Project Management 79/04/10 1p
- 7904270133 Supplements 790411 response to IE Bulletin comments to anticipatory reactor trips Forwards indicating trip on low steam generator level would be anticipatory w/ proposed safety evaluation progr
TRIMBLE, D C Arkansas Power & Light Co 79/04/10 1p
- 790428020 Ask receipt of 790403 for informing MRC of correct violations noted in IE Insp Rpts 50-313/79-04 & 50-346/79-04
MORRIS, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/22 1p
- 790428037 Responds to IE Bulletin 79-04 re use of Violating check valves. Higher weights were used in seismic analysis; analyzers are conservative
TRIMBLE, D C Arkansas Power & Light Co 79/04/27 2pp
- 790430049 Ack receipt of 790321 for informing MRC of steps taken to correct violations noted in IE Insp Rpts 50-313/79-04 & 50-346/79-04
MORRIS, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/20 1p

DOCKETED ITEMS

B Periodic operating reports & related correspondence

7905108014 Notice that unit is shut down during Apr 1979;
no impending monitoring report necessary
THRELLS, D C Arkansas Power & Light Co 79/05/01 1p

7905109002 Forwards monthly operating report for May 1979
THRELLS, D C Arkansas Power & Light Co 79/05/14 1p

7905109002 Monthly operating report for May 1979
THRELLS, D C Arkansas Power & Light Co 79/05/14 4pp

B Reportable occurrences, LERs & related correspondence

7905000208 RD 79-010/79-02 on 790425 leak in 3-inch drain socket
void discovered in B decay heat loop discharge in reactor
55g during void shutdown Cause unknown Drain line to be
repaired Work to follow
BRAWLEY, J P Arkansas Power & Light Co 79/04/26 1p

7905100142 Forwards PMS-79-67AH
RAGSDEN, G L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/05/09 1p

7905100192 Forwards PMS-79-67AH
RAGSDEN, G L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/05/16 1p

7905100201 Forwards PMS-79-67AD & AF
RAGSDEN, G L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/05/24 1p

7905100208 Forwards LER 79-028/031-C
THRELLS, D C Arkansas Power & Light Co 79/06/12 1p

7905100607 LER 79-028/031-C on 790626 during leak rate testing,
penetration U-1 leaked in excess of 50,000 cubic centimeters
Caused by buildup of sulfuric acid crystals on valve seating
surfaces Repairs made & penetrations retested
BRAWLEY, C N Arkansas Power & Light Co 79/06/12 1p

7905100605 Forwards LER 79-006/017-B
THRELLS, D C Arkansas Power & Light Co 79/06/02 1p

7905100606 LER 79-006/017-B on 790607 vendor notified until of
possibility that turbocharger thrust bearing could be
damaged under certain repeat start operating modes
Procedures modified & improved idle-out test being designed
BRAWLEY, C N Arkansas Power & Light Co 79/06/09 4pp

DOCKET 79-010 DONALD E CORK NUCLEAR POWER PLANT, UNIT 1

B Adjudicatory correspondence

7906201000 Notice of issuance & availability of Amends 2B & 1D as
Licenses DPF-5B & DPF-74, respectively
GILBERT, A Operating Reactors Branch I (Fire 790520)
79/05/02 2pp

7906200400 Requests site emergency plan & implementing procedures, site
maps showing location & grid numbers of units & offsite
engine monitoring stations & site maps used for offsite
dose determinations or evacuation
KAPPLER, J S Region 3, Chicago, Office of the Director 79/05/17
1p

7906200100 Comments on meeting to be held to provide MI citizens
whether understanding of proposed spent fuel storage
expansion
GASBY, J E Michigan, State of 79/05/10 1p

7906200207 Supply to 790104 ltr re containment purging during normal
plant operation Requests continuation of review of Tech
Spec change request for Unit 2 to permit unrestricted
purging
GILBERT, J E Indiana & Michigan Power Co 79/06/08 4pp

7906200201 Requests to NRC 790501 request for info re feedwater line
checks Forwards 100R50 39 evaluation & special procedure
guide for feedwater line data collection Commits to
perform math-testing & surveillance programs
HUNT, R G American Electric Power Co - Inc 79/06/10 20pp

7906200201 Bulletin addl info requested after review of AEP NRC 010104,
etc 790504 & NRC 790519 belcon re analysis of pressurizer
single line
HERRING, R P Indiana & Michigan Power Co 79/06/20 3pp

7906200201 Provides info on PMS feedwater lines in response to V Shello
790580 request
GILBERT, J E Indiana & Michigan Power Co 79/06/21 10pp

B Inspection reports, IE Bulletins & correspondence

7906200409 Response to IE Bulletin 79-03 Re Type 300 Stainless Steel
piping req by Youngstown Welding & Engineering Co is in use
or planned for use in facility safety sys
GILBERT, J E American Electric Power Co - Inc 79/06/17 3pp

7906200403 Forwards IE Insp Repts 80-013/79-07 & 50-014/79-06 on
790419-20 Notice of violation without req 100P72 7903
KILBURN, R F Region 3, Chicago, Reactor Operations Nuclear
Support Branch 79/05/02 2pp

7906200400 IE Insp Repts 80-013/79-07 & 50-014/79-06 on 790419-20
Noncompliance noted failure to maintain isolation zone
Offsite without req 100P72 7903
GILBERT, J E American Electric Power Co - Inc Region 3, Chicago, Reactor Operations
Nuclear Support Branch 79/05/02 1p

7906200114 Forwards IE Info Notice 79-11, "Lowest Reactor Vessel Head
Isolation Support Position" No action required
KAPPLER, J S Region 3, Chicago, Office of the Director 79/05/07
1p

7906200500 Response to IE Bulletin 79-04 re incorrect weights of using
check valves made by Valon Engineering Corp Addl
weight will not adversely affect capability to withstand
seismic event
MILONEY, J P Indiana & Michigan Power Co 79/05/08 3pp

7906200604 Forwards IE Bulletin 79-10, "Requalification Training
Program Statistics" written request required
KAPPLER, J S Region 3, Chicago, Office of the Director 79/05/01
1p

7906200706 Forwards IE Info Notice 79-12, "Attemped Damage to New Fuel
Assemblies"
KAPPLER, J S Region 3, Chicago, Office of the Director 79/05/01
1p

7906201000 Response to IE Bulletin 79-09 06 AN-2 circuit breaker
not in use in safety-related sys.
GILBERT, J E Indiana & Michigan Power Co 79/05/13 1p

7906200207 Forwards IE Circular 79-06, "Attempted Extortion - Low
Enriched U"
KAPPLER, J S Region 3, Chicago, Office of the Director 79/05/08
1p

7906200207 Response to NRC 790605 ltr re due date for responses to IE
Bulletin 79-03 10A & 10B Requests extension to 790702 due
to delays encountered in obtaining ltr re actual work
mfr from suppliers
GILBERT, J E Indiana & Michigan Power Co 79/05/21 3pp

DOCKETED ITEMS

89

7904030097 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Regenerated Safety Sys." Licenses action required
MEPPLER, J. E. Region 3, Chicago, Office of the Director 79/05/22 1p

7904030094 Act receipt of 790403 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-013/79-03 & 80-014/79-03
BOLAN, J. E. Region 3, Chicago, Office of the Director 79/05/23 1p

7904030093 Responds to NRC 790328 ltr re violations noted in IE Insp Repts 80-013/79-03 & 80-014/79-03. Corrective actions eventually will successfully performed on 790403
BOLAN, J. E. Indiana & Michigan Power Co 79/05/26 1p

7904030092 Act receipt of 790403 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-013/79-04 & 80-014/79-04
BOLAN, J. E. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/24 1p

7904030091 Responds to NRC 790322 ltr re violations noted in IE Insp Repts 80-013/79-04 & 80-014/79-04 corrective actions
BOLAN, J. E. Indiana & Michigan Power Co 79/05/23 1p

7904030090 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Operator Control Reactor"
MEPPLER, J. E. Region 3, Chicago, Office of the Director 79/05/29 1p

7904030089 Responds to IE Bulletin 79-06A, "Review of Operational Errors & Non-Compliance Identified During TME Outages"
Forwards proposed Tech Specs implementing design changes
Class III Amend Fee incl
BOLAN, J. E. Indiana & Michigan Power Co 79/04/04 4pp

7904030087 Tech Specs implementing design changes to delete low presurizer water level consequence logic for safety function action & to convert to burst-of-three channel logic on low presurizer pressure only
Indiana & Michigan Power Co 79/04/04 12pp

8 Periodic operating reports & related correspondence

7904030079 Forwards monthly fish impingement repts for Jan/Feb & Mar 1979
BOLAN, J. E. Indiana & Michigan Power Co 79/04/05 14pp

7904030078 Forwards monthly operating rept for May 1979
BOLAN, J. E. Indiana & Michigan Power Co 79/06/13 1p

7904030076 Monthly operating rept for May 1979
BOLAN, J. E. Indiana & Michigan Power Co 79/06/13 1p

9 Reportable occurrences, LERs & related correspondence

7904030075 Forwards LER 79-033/03L-0
BOLAN, J. E. Indiana & Michigan Power Co 79/04/04 1p

7904030074 LER 79-033/03L-0 as 790268 monthly functional tests for containment area monitor contained atmosphere particulate & combustible atmosphere-gaseous monitors were not performed. Caused by daily assignment error.
BOLAN, J. E. Indiana & Michigan Power Co 79/04/04 1pp

7904030073 Forwards LER 79-019/01T-0
BOLAN, J. E. Indiana & Michigan Power Co 79/04/07 3pp

7904030072 LER 79-019/01T-0 as 790159 cracks found in 14-inch feedwater tubes adjacent to nozzle welds caused bulging of nonradioactive water in containment some caused being determined. Cause in generators being replaced.
BOLAN, J. E. Indiana & Michigan Power Co 79/04/08 14pp

10 Congressional/Executive Correspondence

7904030071 Responds public hearing re application to increase waste capacity at facility. Every effort should be made to consider all views. Request for additional waste storage confirmed. Doubt re ability to handle waste problem
BOLAN, J. E. Senate 79/05/09 1p

7904030068 Forwards 790309 ltr to JH Hendrie re hearings & increased radioactive storage
LEVINE, C. Senate 79/05/10 1p

7904030067 Responds NRC hold public hearings re until application to increase radioactive waste storage capacity
LEVINE, C. Senate 79/05/09 1p

DOCKET 80-016 DENIALS C. CODE NUCLEAR POWER PLANT, UNIT 2

General correspondence

7904030065 Responds public hearing prior to NRC authorization for increases in storage capacity of spent nuclear fuel assemblies
VOSTRA, J. Affiliation Unknown 79/04/10 1p

F Operating license stage documents & correspondence

7904030060 Forwards Amends 28 & 10 to Licenses DPR-50 & DPR-74, respectively, safety evaluation & notice of issuance & availability
SCHMIDT, A. Operating Reactors Branch 1 (Pra 790423) 79/05/02 1p

7904030058 Amends 28 & 10 to Licenses DPR-50 & DPR-74, respectively, authorizing deletion of installed part-length rods & eliminating all ref & rod rods from Tech Specs
SCHMIDT, A. Operating Reactors Branch 1 (Pra 790423) 79/05/02 1p

7904030057 Safety evaluation supporting Amends 28 & 10 to Licenses DPR-50 & DPR-74, respectively
Operating Reactors Branch 1 (Pra 790423) 79/05/02 1p

7904030056 Notice of issuance & availability of Amends 28 & 10 to Licenses DPR-50 & DPR-74, respectively
SCHMIDT, A. Operating Reactors Branch 1 (Pra 790423) 79/05/02 1p

7904030054 Request site emergency plan & implementing procedures, site maps showing location & grid number of exits & effluent emission monitoring stations & site maps used for effluent dose determinations or evaluations
MEPPLER, J. E. Region 3, Chicago, Office of the Director 79/05/17 1p

7904030053 Comments on meeting to be held to provide MR citizens whether understanding of proposed spent fuel storage expansion
CANN, J. T. Michigan, State of 79/05/16 1p

7904030052 Suppl to 790304 ltr re containment purging during normal plant operation. Requests continuation of review of Tech Spec change request for Unit 2, to permit unrestricted purging
BOLAN, J. E. Indiana & Michigan Power Co 79/04/08 4pp

7904030051 Responds to NRC 790411 request for info re feedwater line cracks. Forwards ICRP100 39 evaluation & special procedure guide for feedwater line data collection. Committee to periodic retests & surveillance programs
HARTER, R. E. American Electric Power Co, Inc 79/04/13 5pp

7904030050 Submits add info requested after review of AEP, NRC, OSHA, state 790304 & NRC 790411 telecon re reanalysis of pressurizer surge line
BOLAN, J. E. Indiana & Michigan Power Co 79/05/20 1pp

7904030049 Provides info on PAR feedwater lines in response to V Stella 790325 request
BOLAN, J. E. Indiana & Michigan Power Co 79/04/21 14pp

11 Inspection reports, IE Bulletins & correspondence

7904030048 Responds to IE Bulletin 79-02, No Type 304 Stainless Steel piping used by Vantageous Holding & Engineering Co. Is in use as planned for use in facility safety sys
BOLAN, J. E. American Electric Power Co, Inc 79/04/17 1pp

7904030047 Forwards IE Insp Repts 80-013/79-03 & 80-014/79-04 on 790419-20 Notice of violation withheld (ref ICRP62 790)
MEPPLER, J. E. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/02 1pp

DOCKETED ITEMS

7904140609 IE Insp Repts 30-315/79-07 & 30-315/79-08 on 790419-20
Noncompliance noted failure to maintain isolation zone
Details withheld (ref ICRP2 790)
BOLLER, D.V. Indiana & Michigan Power Co 79/04/13 1p
Nuclear Support Branch 79/04/05 1p

7905100314 Forwards IE Info Notice 79-12, "Lower Reactor Vessel Head
Insulation Support Problem" - No action required
BOLLER, D.V. Region 3, Chicago, Office of the Director 79/05/07
1p

7905100300 Responds to IE Bulletin 79-06 re incorrect weights of safety
circuit valves made by Velox Engineering Corp A611
valves will not adversely affect capability to withstand
seismic event
BOLLER, D.V. Indiana & Michigan Power Co 79/05/08 3pp

7905100304 Forwards IE Bulletin 79-10, "Requalification Printing
Program Statistics" - Written response required
BOLLER, D.V. Region 3, Chicago, Office of the Director 79/05/11
1p

7905100304 Forwards IE Info Notice 79-12, "Attempted Damage to Knu Fuel
Assemblies" -
BOLLER, D.V. Region 3, Chicago, Office of the Director 79/05/11
1p

7905270100 Responds to IE Bulletin 79-09 06 AA-2 circuit breaker
not in use in safety-related way
BOLLER, D.V. Indiana & Michigan Power Co 79/05/10 1p

7905060302 Forwards IE Circular 79-08, "Attempted Extortion - Low
Enriched U"
BOLLER, D.V. Region 3, Chicago, Office of the Director 79/05/10
1p

7905020257 Responds to NRC 790504 ltr re due date for responses to IE
Bulletin 79-12, ISA & ISA Requests submitted by 790502 due
to delays encountered in obtaining info re physical void
data from suppliers
BOLLER, D.V. Indiana & Michigan Power Co 79/05/21 3pp

7905100307 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device
in Circuit Breakers for Engineered Safety Sys" - License
actions required
BOLLER, D.V. Region 3, Chicago, Office of the Director 79/05/22
1p

7905060374 Act receipt of 790426 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 30-315/79-02 &
30-315/79-03
BOLLER, D.V. Region 3, Chicago, Office of the Director 79/05/23
1p

7906060300 Responds to NRC 790528 ltr re violations noted in IE Insp
Repts 30-315/79-02 & 30-315/79-03. Corrective actions,
evaluation of civil successfully performed on 790528
BOLLER, D.V. Indiana & Michigan Power Co 79/06/24 1p

7906060307 Act receipt of 790422 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 30-315/79-04 &
30-315/79-04
BOLLER, D.V. Region 3, Chicago, Office of the Director 79/06/24 1p

7906060304 Responds to NRC 790528 ltr re violations noted in IE Insp
Repts 30-315/79-04 & 30-315/79-04. Corrective actions,
evaluation of civil successfully performed on 790528
BOLLER, D.V. Indiana & Michigan Power Co 79/06/23 1p

7906060306 Forwards IE Info Notice 79-13, "Indication of Low Water
Level in Reactor Creek Reservoir"
BOLLER, D.V. Region 3, Chicago, Office of the Director 79/06/29
1p

7906060306 Responds to IE Bulletin 79-05a, "Review of Operational
Errors & Safety Misstatements Identified During SRP Incident"
Forwards proposed Tech Specs implementing design changes
Class III amend fee enc
BOLLER, D.V. Indiana & Michigan Power Co 79/06/06 4pp

7906060307 Tech Specs implementing design changes to delete low
pressure water level calculation logic for safety
injection actuation & to convert to Out-of-Of-Three
channel logic on low pressurizer pressure only
BOLLER, D.V. Indiana & Michigan Power Co 79/06/06 10pp

R. Periodic operating reports & related correspondence

7905100319 Forwards monthly fish impingement reports for Jan-Feb & Mar
1979
BOLLER, D.V. Indiana & Michigan Power Co 79/06/05 10pp

7905100341 Forwards monthly operating report for May 1979
BOLLER, D.V. Indiana & Michigan Power Co 79/06/13 1p

7906060343 Monthly operating report for May 1979
BOLLER, D.V. Indiana & Michigan Power Co 79/06/04 10pp

S. Reportable occurrences, LERs & related correspondence

7906101914 Forwards LER 79-018/01-0
BOLLER, D.V. Indiana & Michigan Power Co 79/05/20 1p

7906101977 LER 79-018/01-0 on 790420 during investigation of periodic
alarm for steam generator high steam line flow controller
2 PV 3048 turbine impulse pressure) was in manual control
Caused by controller not being returned to automatic
BOLLER, D.V. Indiana & Michigan Power Co 79/05/20 3pp

7906100329 Forwards LER 79-019/01-0
BOLLER, D.V. Indiana & Michigan Power Co 79/06/07 3pp

7906100324 LER 79-019/01-0 on 790519 cracks found in 14-inch feedwater
piping adjacent to nozzle welds caused buildup of
corrosion-resistant water in containment sump. Caused by
defective elbows in generator piping replaced
BOLLER, D.V. Indiana & Michigan Power Co 79/06/06 10pp

7906100325 Forwards LER 79-019/01-0
BOLLER, D.V. Indiana & Michigan Power Co 79/06/11 1p

7906100327 LER 79-019/01-0 on 790519 small leak found in feedwater
piping to steam generator by further deterioration
BOLLER, D.V. Indiana & Michigan Power Co 79/06/10 1p

7906100321 Discusses five deficient transmitters installed in steam
generator water level narrow range channels. Parts have been
returned to Westinghouse for recall.
BOLLER, D.V. Indiana & Michigan Power Co 79/06/13 3pp

U. Congressional/Executive Correspondence

7906290672 Requests public hearing re application to increase waste
storage capacity at Facility. Over effort should be made to
consider all views. Request for additional waste storage confirms
data re ability to handle waste problem
LEVIN, C. Senate 79/05/07 1p

7906290388 Forwards 790509 ltr to JH Hendrix re hearings & increased
radioactive storage.
LEVIN, C. Senate 79/05/10 1p

7906290320 Requests NRC hold public hearings re will application to
increase nuclear waste storage capacity
LEVIN, C. Senate 79/05/08 1p

800601 30-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1
F. Security, medical, emergency & fire protection plans

7906290320 Comments on fire protection safety evaluation
Recommendations of Committee are adequately reflected
Proposed fire protection will give reasonable assurance
that health & safety of public will not be endangered
HALL, R.E. Brookhaven National Laboratory 79/06/05 4pp

P. Operating license stage documents & correspondence

7906040303 Forwards safety evaluation of proposed design mod to plant
125 volt dc sys.
LAING, G. Plant Systems Branch 79/04/30 3pp

7906040403 Safety evaluation of proposed design mod to plant 125 volt
dc sys. Accepts proposed change
LAING, G. Plant Systems Branch 79/04/26 4pp

7906050101 Memoirs of 790517 meeting w/with in Bethesda, MD re auxiliary
feedwater system
CONNER, R.L. Operating Reactors Branch 4 (Pre 790620) 79/05/24
4pp

7906100317 Forwards revision to Section 10 of fourth cycle reload amendment
application. Revision covers startup & test functional
testing, initial criticality, low power physics testing &
miscellaneous criteria
LIMPINJAN, A.E. Bethesda Gas & Electric Co 79/05/29 8pp

DOCKETED ITEMS

97

- 7904040240 Forwards proprietary & nonproprietary versions of CEN-114101. "Revised Fuel Assembly Insp Results at Calvert Cliffs, Unit 1." Nonproprietary version withheld (ref 10CFR 7903).
LUNDVALL, A E Baltimore Gas & Electric Co 7/9/03/21 3pp
- 7904040250 "Revised Fuel Assembly Insp Results at Calvert Cliffs, Unit 1." Nonproprietary version withheld (ref 10CFR 7903).
LUNDVALL, A E Baltimore Gas & Electric Co 7/9/03/21 3pp
- 7904040260 Ack receipt of NRC 790304 comments re still actions in response to IE Bulletin 79-048. Clarifies actions re containment training, void formation, containment isolation, reactor control pump operation & age operability.
LUNDVALL, A E Baltimore Gas & Electric Co 7/9/06/05 3pp
- 7904040270 Submits responses to NRC 790607 questions re passive off-gas monitoring system.
LUNDVALL, A E Baltimore Gas & Electric Co 7/9/06/12 3pp
- 7904040280 Discusses agreement w/ utility to provide caps for patients from facility. Comments show not include radiation accident test. Request for more rigorous training requirements, radiation drills & accident guidelines.
JACOBSON, J P Calvert Memorial Hosp, Md, Maryland 7/9/06/18 1p
- 7904040290 Forwards Amdt 37 to application for CLIR site emergency plan.
LUNDVALL, A E Baltimore Gas & Electric Co 7/9/06/15 3pp
- 7904040300 Submits add info re manual bypasses of actioning system, in response to NRC belcon request. Clarifies items withheld during investigation of safety actuation circuits incorporating manual override features.
LUNDVALL, A E Baltimore Gas & Electric Co 7/9/06/21 3pp
- Inspection reports, IE Bulletins & correspondence
- 7904040310 Responds to IE Bulletin 79-03 re AHC 94-012 stainless steel welding & engineering Co pipe weld supplied in facility.
LUNDVALL, A E Baltimore Gas & Electric Co 7/9/04/16 3pp
- 7904040320 Forwards IE Bulletin 79-038, "Nuclear Incident at Mt. St. Helens." No written response required.
GRIER, D H Region 1, Philadelphia, Office of the Director 7/9/04/23 1p
- 7904040330 Forwards responses to IE Bulletin 79-037, "Basic Stress Analysis of Safety-Related Piping." Some of methods specified were used in design of facility. Lists computer codes & verification methods.
LUNDVALL, A E Baltimore Gas & Electric Co 7/9/04/24 3pp
- 7904040340 Ack receipt of 790419 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-317/79-02 & 80-318/79-03.
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 7/9/04/30 1p
- 7904040350 Responds to NRC 790330 ltr re violations noted in IE Insp Repts 80-317/79-03 & 80-318/79-03. Corrective actions withheld (ref 10CFR 7903).
EVANS, V R Baltimore Gas & Electric Co 7/9/04/19 1p
- 7904040360 Forwards IE Insp Repts 80-317/79-03 & 80-318/79-03 on 790206-00 Notice of violation withheld (ref 10CFR 7901).
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 7/9/03/30 3pp
- 7904040370 IE Insp Repts 80-317/79-03 & 80-318/79-03 on 790206-00 Noncompliance noted detection aids inadequate details withheld (ref 10CFR 7903).
GRIER, D H Region 1, Philadelphia, Safeguards Branch 7/9/03/29 1p
- 7904040380 Responds to IE Bulletin 79-04 re failure of CE Type AA-2 circuit breakers in safety-related area. Breaker used in reactor switch gear.
LUNDVALL, A E Baltimore Gas & Electric Co 7/9/05/08 3pp
- 7904040390 Forwards IE Info Notice 79-11, "Laser Reactor Vessel Head Penetration Support Problem." No action required.
GRIER, D H Region 1, Philadelphia, Office of the Director 7/9/05/07 3pp
- 7904040400 Forwards IE Bulletin 79-04, "Regulification Training Program." Submits "Written response required."
GRIER, D H Region 1, Philadelphia, Office of the Director 7/9/05/11 3p
- 7904040410 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assembly." Region 1, Philadelphia, Office of the Director 7/9/05/11 1p
- 7904040420 Forwards IE Circular 79-08, "Attempted Violation - Low Enriched U." Region 1, Philadelphia, Office of the Director 7/9/05/18 1p
- 7904040430 Notifies that AHC proposed valve used to operate containment pump valves does not meet post-accident emission qualification per IE Bulletin 79-01 & 79-01A.
LUNDVALL, A E Baltimore Gas & Electric Co 7/9/04/13 1p
- 7904040440 Responds to IE Bulletin 79-01 & 79-01A. Forwards retest summarizing emission qualification data. AHC valves are used for containment pump valves. Will provide information until valves are replaced size and type.
LUNDVALL, A E Baltimore Gas & Electric Co 7/9/04/13 3pp
- Periodic operating reports & related correspondence
- 7904040450 Forwards monthly operating repts for May 1979.
MORRIS, S O Baltimore Gas & Electric Co 7/9/05/15 1p
- 7904040460 Forwards monthly operating repts for May 1979.
MORRIS, S O Baltimore Gas & Electric Co 7/9/05/15 13pp
- Reportable occurrences, LERs & related correspondence
- 7904040470 Forwards LER 79-001/001-0.
DOUGLASS, R H Baltimore Gas & Electric Co 7/9/01/09 1p
- 7904040480 LER 79-001/001-0 on 791210. Although power bill exceeded Tech Specs limits caused by positive bias. Being corrected slightly below value of 0.000. Proposed Tech Specs change submitted to permit use of add. In-core detector segments.
HUBBELL, L Baltimore Gas & Electric Co 7/9/01/09 3pp
- 7904040490 Forwards LER 79-008/007-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/01/31 1p
- 7904040500 LER 79-008/007-0 on 790517. Cylinders showed Ag-110m at 30 g/g or more. 30 g/g/kg decreasing may be caused by degradation. No corrective action required.
GRIER, D H Baltimore Gas & Electric Co 7/9/05/31 3pp
- 7904040510 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040520 LER 79-018/001-0 on 790505. Low pressure safety injection pump stopped for 10 minutes due to spurious misactivation. Activation signal caused by voltage transients. Test procedures revised.
GRIER, D H Region 1, Philadelphia, Safeguards Branch 7/9/04/04 3pp
- 7904040530 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040540 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040550 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040560 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040570 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040580 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040590 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040600 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040610 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040620 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040630 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040640 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040650 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040660 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040670 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040680 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040690 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040700 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040710 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040720 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040730 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040740 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040750 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040760 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040770 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040780 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040790 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040800 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040810 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040820 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040830 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040840 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040850 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040860 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040870 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040880 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040890 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040900 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040910 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040920 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040930 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040940 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040950 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040960 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040970 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040980 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904040990 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041000 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041010 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041020 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041030 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041040 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041050 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041060 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041070 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041080 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041090 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041100 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041110 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041120 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041130 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041140 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041150 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041160 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041170 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041180 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041190 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041200 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041210 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041220 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041230 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041240 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041250 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041260 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041270 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041280 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041290 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041300 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041310 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041320 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041330 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041340 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041350 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041360 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041370 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041380 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041390 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041400 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041410 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041420 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041430 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041440 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041450 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041460 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041470 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041480 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041490 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041500 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041510 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041520 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041530 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041540 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041550 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041560 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041570 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041580 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041590 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041600 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041610 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041620 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041630 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041640 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041650 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041660 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041670 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041680 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041690 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041700 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041710 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041720 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041730 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041740 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041750 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041760 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041770 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041780 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041790 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041800 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041810 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041820 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041830 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041840 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041850 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041860 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041870 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041880 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041890 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041900 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041910 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041920 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041930 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041940 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041950 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041960 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041970 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041980 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904041990 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904042000 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904042010 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904042020 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904042030 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904042040 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904042050 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904042060 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904042070 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904042080 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904042090 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7904042100 Forwards LER 79-018/001-0.
HUBBELL, L Baltimore Gas & Electric Co 7/9/04/04 1p
- 7

DOCKETED ITEMS

F Operating license stage documents & correspondence

7906040400 Forwards safety evaluation of proposed design mod to plant
IES vult dc sig
LUNDWALL A E Plant Systems Branch 79/04/30 App

7906040405 Safety evaluation of proposed design mod to plant IES vult
dc sig Accepts proposed change
Plant Systems Branch 79/04/30 App

7906050151 Summary of 790517 meeting w/utill in Bethesda, MD re auxiliary
feedwater sys & related areas
CORNER, E L Operating Reactors Branch 4 (Pw 790605) 79/05/26
App

7906120285 Act receipt of NRC 790324 comments re util actions in
response to IE Bulletin 79-048 Clarifies actions re
personnel training, void formation, containment isolation.
Feasible coolant pump operation & sig operability
LUNDWALL A E Baltimore Gas & Electric Co 79/06/08 App

7906150141 Submits responses to NRC 790607 questions re gaseous
effluent monitoring sig
WALL, E H Baltimore Gas & Electric Co 79/06/12 App

7906210280 Dismisses agreement w/utill to provide care for patients
from facility Containment does not include radiation accident
victim Requests info re physician training requirements,
radiation drills & accident guidelines
JACOBS, J P Calvert Research Hosp PH, Maryland 79/06/19 App

7906250231 Forwards Amend 57 to application for CL re site emergency
plan
LUNDWALL A E Baltimore Gas & Electric Co 79/06/15 App

7906280130 Submits add info re manual bypasses of actuation sig
signals in response to NRC telcom request Clarifies items
identified during investigation of safety actuation circuits
incorporating manual override features
LUNDWALL A E Baltimore Gas & Electric Co 79/06/21 App

G Inspection reports, IE Bulletin & correspondence

7906020199 Responds to IE Bulletin 79-03 re AWE 5A-012 stainless steel
pipe spools Forwards info on application of Youngstown
Welding & Engineering Co pipe weld supplied to facility
LUNDWALL A E Baltimore Gas & Electric Co 79/06/16 App

7906110007 Forwards IE Bulletin 79-05B, "Nuclear Incident at
THI-Bugli" re written response required
GIBBS, R H Region 1, Philadelphia, Office of the Director

7906100116 Forwards IE Bulletin 79-10, "Regulification Training
Program Discontinue" written response required
GIBBS, R H Region 1, Philadelphia, Office of the Director
79/05/11 App

7906280502 Forwards IE info Notice 79-19, "Attempted Damage to New Fuel
Assembly"
GIBBS, R H Region 1, Philadelphia, Office of the Director
79/05/11 App

7906280506 Forwards IE Circular 79-06, "Attempted Extension - Low
Enriched U"
GIBBS, R H Region 1, Philadelphia, Office of the Director
79/05/18 App

7906150306 Notifies that AECO solenoid valve used to operate
containment purge valves does not meet post-accident service
qualification per IE Bulletin 79-01 & 79-05A
LUNDWALL A E Baltimore Gas & Electric Co 79/05/13 App

7906150308 Responds to IE Bulletin 79-01 & 79-05A Forwards report
summarizing environ qualification data AECO solenoids are
used for containment purge valves Will prohibit operation
until solenoid valves replaced W/ new
LUNDWALL A E Baltimore Gas & Electric Co 79/06/13 App

H Periodic operating reports & related correspondence

7906250282 Forwards monthly operating report for May 1979
BERNOLD, B D Baltimore Gas & Electric Co 79/06/19 App

7906250283 Monthly operating report for May 1979
BERNOLD, B D Baltimore Gas & Electric Co 79/06/19 13pp

I Reportable occurrences, LERs & related correspondence

7906040354 Forwards LER 79-030/03L-0
SODOLAKS, R B Baltimore Gas & Electric Co 79/06/26 App

7906040357 LER 79-030/03L-0 re 790506 discovered control element
assembly station inhibit not operable for position deviation
Caused by bad RD relay on relay card Relay replaced & station
inhibit returned to sig
CARROLL, J E, MIERHECK, R J Baltimore Gas & Electric Co
79/04/26 App

7906050500 Forwards LER 79-016/03L-0
SODOLAKS, R B Baltimore Gas & Electric Co 79/05/28 App

7906050507 LER 79-016/03L-0 re 790500 while inserting Group 3 control
element assemblies, CE 3A dropped to bottom of core Cased
by spike in 13 volt power supply Design mod to be installed
during next refueling outage
DAVID, R H, MIERHECK, R J Baltimore Gas & Electric Co 79/05/25 App

7906050505 Forwards LER 79-016/03L-0
SODOLAKS, R B Baltimore Gas & Electric Co 79/05/28 App

7906050506 LER 79-016/03L-0 re 790519 containment air lock water door
air leakage discovered to be in excess of Tech Spec limits
Caused by failed door contact hose gaskets installed & door
latch release adjusted
LADENBERG, J D, BERNHART, H J Baltimore Gas & Electric Co
79/05/25 App

666899 Forwards LER 79-017/03L-0
SODOLAKS, R B Baltimore Gas & Electric Co 79/05/31 App

7906050507 LER 79-017/03L-0 re 790500 during surveillance testing,
diesel generator 21 failed to start upon actuation of remote
start switch Caused by normally de-energized low speed relay
being energized during initial test
BERNHART, H J, BERNHART, H J Baltimore Gas & Electric Co 79/05/31 App

670294 Forwards LER 79-018/04T-0
SODOLAKS, R B Baltimore Gas & Electric Co 79/05/31 App

66070301 LER 79-018/04T-0 re 790517 cylinder samples showed Ag-110m at
EO plus or minus 5% activity & determining may be caused by
deposition. No corrective action required
BERNHART, H J Baltimore Gas & Electric Co 79/05/31 App

660015 Responds to U State 790525 ltr re possible design problem
feedwater piping Forwards Isometric drawings of feedwater
piping in containment & all pipe supports & results of stress
analysis for feedwater lines
LUNDWALL A E Baltimore Gas & Electric Co 79/06/19 App

DOCKETED ITEMS

93

7904050471 Forwards LER 79-020/03L-0
RUSSELL, L. B. Baltimore Gas & Electric Co 79/04/19 1p

--7904050472 LER 79-020/03L-0 on 790402 during safety injection tests
main safety injection tank 220 decreased to 100 inches at
1730. Control by test leakage on D2E safety injection tank
exceeding floating expectations. Valve will be repaired
CARROLL, J. F. Baltimore Gas & Electric Co 79/04/19 1p

7904050330 Forwards LER 79-018/03L-0
RUSSELL, L. B. Baltimore Gas & Electric Co 79/04/21 1p

--7904050348 LER 79-018/03L-0 on 790507 a 4V feeder breaker 100-2401
tripped open causing loss of power to 4 VV bus 24. Cause
by previous signal of monitoring loss of power to IOWA 28
logic cabinet 206R. No further action required
CARROLL, J. F. RUSSELL, L. B. Baltimore Gas & Electric Co 79/04/21 2ps

7904040399 Forwards LER 79-019/03L-0
RUSSELL, L. B. Baltimore Gas & Electric Co 79/04/21 1p

--7904040448 LER 79-019/03L-0 on 790326 during performance of
surveillance testing. Engineered safety features activation
via module BIAS B-B failed to activate at 1,730. Cause
undetected. Module replaced
CARROLL, J. F. RUSSELL, L. B. Baltimore Gas & Electric Co 79/04/21 1p

DOCKET 80-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2
A Application/Construction stage documents & correspondence

7904050107 Discusses encl BSM responses to NRC request for info re
generic issues identified in answers to DOW-241. First
round questions
RUSSELL, L. B. Assistant Director for Plant Systems 79/04/08 1p

--7904050207 Requests that BSM submit detailed responses re generic items
applicable to BSM plants currently in CP & post-CP stage
of review
EPFCL, LTD. T. A. Electric, Instrumentation & Control Systems
Branch 79/02/24 4pp

--7904050203 Requests addl generic info re BSM's integrated control sys
& steam line break isolation containment
RUSSELL, L. B. Division of Reactor Licensing (HRR-1973 encl).
79/04/04 3pp

--7904050204 Responds to NRC 790404 1tr re generic BSM design info
Discusses each requested item & parameters employed in
completing response to NRC request
BURRKE, K. E. Babcock & Wilcox Co 79/03/23 2ps

--7904050209 Discusses item 3 in NRC 790404 1tr re main steam line break
isolation containment & engineered safety features activation
BURRKE, K. E. Babcock & Wilcox Co 79/07/27 3pp

--7904050213 Discusses item 4 in NRC 790404 1tr re SCRAM activation prior
to reactor trip
BURRKE, K. E. Babcock & Wilcox Co 79/08/13 4pp

--7904050217 Discusses item 1, 3 & 5 in NRC 790403 1tr re integrated
control sys, safety-related sys & protection against loss of
reactor coolant flow due to electrical grid frequency
transients
BURRKE, K. E. Babcock & Wilcox Co 79/12/30 11pp

--7904050220 Confirms 740409 talcon that BSM will incorporate automatic
auxiliary feedwater initiation sys into design to meet
requirements of IEEE-379.
HALL, A. J. F. Babcock & Wilcox Co 79/04/24 1p

--7904050307 Discusses 790103 talcon w/R Edwards re secondary sys
equipment which BSM assumes to be available during LOCA.
HALL, A. J. F. Atomic Energy Commission (Pre 1979) 79/02/08 1p

--7904050318 Minutes of 790225 meeting w/BSM re systematic failures of
BSM reactor protection sys
EPFCL, LTD. T. A. Atomic Energy Commission (Pre 1979) 79/04/16
10pp

C Utility Environmental Report (ER); amends & correspondence

7904230314 Drafts "BSM 205-Delay Heat Removal After Small Break."
Babcock & Wilcox Co 79/04/20 104pp

F Security, medical, emergency & fire protection plans

7904100002 Notifies that fire test of full scale vertical cable tray
array was conducted on 790715 at UL. Test to verify NRC fire
protection criteria may be necessary
RUSSELL, L. B. Office of Nuclear Reactor Regulation 79/03/29 2pp

7904200192 Forwards info re emergency planning maps
STOW, J. P. Region 1, Philadelphia, Office of the Director
79/03/04 2pp

7904200149 Discusses removal of mail from within HT-protected area
Mail can only be removed under watchful physical personnel
escort
RUSSELL, L. B. Metropolitan Edison Co 79/05/17 4pp

7904200204 Responds to 790510 1tr re extra precautionary measures for
area examination sys. Adequate sources of power are
available for operation of unit
VOLLMER, R. H. Assistant Director for Site Analysis 79/05/19 1p

--7904200208 Requests end of extra precautionary measures taken to assure
adequate power to plants
RUSSELL, L. B. General Public Utilities 79/05/18 1p

--7904200201 Notifies that precautionary measures taken to maintain power
supply are no longer necessary. Personnel on standby at
switching station are needed elsewhere. Forwards outline of
electrical sys
RUSSELL, L. B. General Public Utilities 79/05/03 2pp

7904200432 Forwards memo re fire protection & security deficiencies at
TRI. Discusses scheduling of remedial imp effort
RUSSELL, L. B. Region 1, Philadelphia, Office of the Director
79/06/21 1p

--7904200440 Forwards memo raising questions re fire protection &
security deficiencies at TRI-2. Requests action
RUSSELL, L. B. Division of Reactor Operations Inspections
79/05/16 1p

7904200779 Specialized procedures & emergency procedures for
790403-004
Office of Nuclear Reactor Regulation 79/04/04 900pp

A Administrative correspondence

7904100047 Motion for extension until 790411 to prepare response to
ALAB-209
BOHNTJ, J. F. Hearings Division 79/04/02 3pp

--7904100040 Responds to 790328 request for info re status of rulemaking
proceeding to develop value for radon in Table 5-2 Regt &
proposed rule will be sent to NRC by 790404
CHS/STENBORN, C. Hearings Division 79/03/26 3pp

7905140018 Board notification semiautomatic experiment S-W-4. Unanticipated
results re cladding temp require further study to determine
safety significance. Certificate of Dev encl
A. Hearings Division 79/04/05 5pp

DOCKETED ITEMS

- 790429004B Plaintiff's first set of interrogatories in Civil Action 79-1155, US District Court for Eastern District, PA. JONHUBS, J. H. Affiliation Unknown 79/03/18 17pp
- 7904290091 Complaint for injunctive relief in City of Lancaster v ARC filed in DC US District Court State adjustment of radioactive discharges. LEFVER, S. E., MATTOCK, D. H. Barley, Snyder, Copar & Barban. MILKATHA, E. Arent, Fox, Kintner, Pottin & Mann 79/03/20 80pp
- 7904300442 Order requiring preservation of all records re TMI by all parties directly involved until Residue are to be preserved intact until released by NRC either by order or order. CHALK, B. J. Office of the Secretary of the Commission 79/05/22. 3pp
- 7904300497 Summary of meeting w/NRC solicitor to discuss notice of City of Lancaster, PA. KINTNER, G. K. Engineering Branch 79/05/22 2pp
- 7904300504 Answers to interrogatories submitted by City of Lancaster, PA including activity level & isotopic content of water. KINTNER, G. K. Engineering Branch 79/05/24 33pp
- 7904300508 Interrogatories for NRC Affidavits are requested to answer questions on activity level & isotopic content of water, how quantities are established, monitoring logs & history of discharges. Lancaster, PA 79/05/22 2pp
- 7904300508 Affidavit re TMI-2 health & safety impact until not prepared to respond promptly to accident exposure info in inconsistent & exposure increases w/distance from plant. NEPTON, C. Citizens For Safe Environment 79/05/24 4pp
- 7904300508 NRC motion for summary disposition re radio issue was in error: ALAB-540 consolidated only 3 of 4 cases. Onus NRC motion re parties in other proceedings, w/Certificate of Rev. SUP, D. H. Atomic Safety and Licensing Appeal Panel 79/05/25. 3pp
- 7904300507 Request by which that ARLAB grant summary disposition of all issues in consolidated radio proceeding, until such decision as matter of law re genuine issue as to radi issue. BILDER, J. A. Shaw, Pittman, Potts & Taubridge. VOIGHT, H. H. LeBeau, Lamb, Leiby & MacFar. CONNER, T. B. Conner, Moore & Corber 79/05/25. 4pp
- 7904300510 Statement of work facts re radio proceedings, for which there is no genuine issue to be heard. Discussed alleged deficiencies 1-7, 9-10, 20-24 & an Affidavit of 10 Outdawn & supporting documentation encl. BILBERG, J. A. Shaw, Pittman, Potts & Taubridge. VOIGHT, H. H. LeBeau, Lamb, Leiby & MacFar. CONNER, T. B. Conner, Moore & Corber 79/05/25. 30pp
- 7904300452 Confine verbal request for PA Energy Dept to continue to collect & compile all TMI accident handling data from all Federal agencies & PA Dept of Environment Resources. GERSH, T. H. Pennsylvania State of 79/04/06 1p
- 7904300460 Discusses problems encountered w/overheating of low & high pressure injection pumps when auxiliary feedwater is started. HARTMAN, E. Division of Systems Safety 79/04/08 1p
- 7904300501 Requests arrangements to be made for medical exam requested by TMI-2 info partially withheld. Social security number of individual (ref FOIA Exemption 6). BEARD, J. T. Plant Systems Branch. BENTON, H. K. Office of Nuclear Reactor Regulation 79/04/09 1p
- 7904300507 Responds to ltr re TMI info partially withheld name & address of recipient (ref FOIA Exemption 6). BRADFORD, P. A. Commission 79/04/13 1p
- 7904300507 FOIA request for transcripts of investigatory interviews w/actual team personnel involved in TMI incident. ARNHEIM, P. Pennsylvania Illustrated, Inc. 79/04/12 1p
- 7904300443 Responds to ltr re TMI info partially withheld name & address of recipient (ref FOIA Exemption 6). BRADFORD, P. A. Commission 79/04/12 1p
- 7904300467 Responds to 790328 ltr re TMI info partially withheld name & address of recipient & portion of document unrelated to TMI (ref FOIA Exemption 6). BRADFORD, P. A. Commission 79/04/12 3pp
- 7904300469 Responds to 790316 ltr to R Ryan which expressed concern for difficulty in trying to obtain info re facility shutdown. OBER, E. H. Region I, Philadelphia, Office of the Director 79/04/12 2pp
- 7904300508 Comments on text for radiation exposure performed at request of individual who took part TMI on 790328 info partially withheld name & address of person (ref FOIA Exemption 6). SHOFF, M. A. Mehreza- Univ. of Radiation Health Center 79/04/13 2pp
- 7904300439 Provides info re activities while at TMI-2. Per 790330-0407 Critical of lack of coordination between procedure writers: SM & until support personnel. WOODRUFF, C. H. Region II, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/13 2pp
- 7904300525 Forwards name to be added to 790413 list for radiation work permit training list of individuals qualified for uncorrected badges info partially withheld. Social Security numbers (ref FOIA Exemption 6). SMITH, D. H. Office of Inspection & Enforcement 79/04/14. 3pp
- 7904300209 Requests that encl notice be published in 790428 FR. FRALBY, R. F. ACRB - Advisory Committee on Reactor Safeguards 79/04/19 2pp
- 7904300507 Ack receipt of 790413 ltr commenting on financial responsibility of nuclear facility owners re TMI-2 incident. BRIDGES, D. L. Region I, Philadelphia, Office of the Director 79/04/20 1p
- 7904300508 Requests financial responsibility for TMI-2 incident be placed on Metropolitan Edison & stockholders. KETTLER, H. Affiliation Unknown. 79/04/13 3pp
- 7904300509 Ack receipt of 790416 ltr commenting on inadequate supply of water. BRIDGES, D. L. Region I, Philadelphia, Office of the Director. 79/04/20. 1p
- 7904300505 Comments on plant licensing & inadequate water supply. BRADFORD, P. A. Affiliation Unknown. 79/04/14. 2pp
- 7904300505 Ltr from citizens expressing opinions re nuclear power. OBER, E. H. Affiliation Unknown. 79/04/24 25pp.
- 7904300507 Accepts proposal of periodic briefing sessions between involved agencies Group must first designate responsibility for routine & emergency environ activities. HENRIE, J. H. Commission. 79/05/02 1p.

DOCKETED ITEMS

95

- 790200060 Confirms request for PA National Guard helicopter & pilot for aerial firefighting
SMITH, G. H. Region I, Philadelphia. Office of the Director 7/05/03 1p
- 790200031 Discusses NRC health physics staffing w/info re meter sampling & soil waste shipments
SMITH, G. H. Region I, Philadelphia. Office of the Director 7/05/03 3pp
- 790200395 Offers help in conducting studies re emergency protection plant Discusses prior experience in crisis relocation flight Forwarded prof qualifications of staff
SWAN, A. A. Contingency Planning Associates 7/05/04 7pp
- 790200007 Denies FOIA request for transcripts of interview w/THI control room personnel (ref FOIA Exemption 7)
FELTON, J. H. Division of Rules and Records 7/05/03 1p
- 790200072 Forwards name of contractor from whom trailer was rented Ask whether NRC intends to pay rental for location of trailer
FARMER, B. F. Metropolitan Edison Co 7/05/03 1p
- 790200092 Responds to citizen ltr expressing views on nuclear power & closing of BWR reactors Describes NRC actions re plant mode/procedure revisions & add personnel training
GENTON, H. R. Office of Nuclear Reactor Regulation 7/05/03 20pp
- 790200092 Responds to citizen ltr expressing views on nuclear power & closing of BWR reactors Describes NRC actions re plant mode/procedure revisions & add personnel training
GENTON, H. R. Office of Nuclear Reactor Regulation 7/05/03 80pp
- 790200092 Responds to citizen ltr to JH Hendrie expressing views on nuclear power & closing of BWR reactors Describes NRC actions re plant mode/procedure revisions & add personnel training
GENTON, H. R. Office of Nuclear Reactor Regulation 7/05/03 87pp
- 790200092 Responds to citizen ltr to JH Hendrie expressing views on nuclear power & closing of BWR reactors Describes NRC actions re revising operating procedures, plant mode & add personnel training
GENTON, H. R. Office of Nuclear Reactor Regulation 7/05/03 29pp
- 790200092 Responds to citizen ltr to JH Hendrie expressing views on nuclear power & closing of BWR reactors Describes NRC actions re revising operating procedures, plant mode & add personnel training
GENTON, H. R. Office of Nuclear Reactor Regulation 7/05/03 12pp
- 790200092 Responds to citizen ltr to JH Hendrie expressing views on nuclear power & closing of BWR reactors Describes NRC actions re revising operating procedures, plant mode & add personnel training
GENTON, H. R. Office of Nuclear Reactor Regulation 7/05/03 14pp
- 790200014 Responds to citizen ltr expressing views on nuclear power & closing of BWR reactors Describes NRC actions re revising operating procedures, plant mode & add personnel training
GENTON, H. R. Office of Nuclear Reactor Regulation 7/05/03 70pp
- 790200100 Responds to citizen ltr to President Carter re nuclear power & closing of BWR reactors Describes NRC actions re revising operating procedures, plant mode & add personnel training
GENTON, H. R. Office of Nuclear Reactor Regulation 7/05/03 21pp
- 790200090 Reports continued operation of nuclear plants in spite of TH1-2 incident Past record of safe operation does not warrant negative actions
LAIETRE, A. Affiliation Unknown 7/05/03 3pp
- 790200070 Ack receipt of 790412 ltr to JH Hendrie expressing nuclear power & closing of BWR reactors re TH1-2 incident Planning will take on greater emphasis
RYAN, R. G. Office of State Programs 7/05/03 3p
- 790200070 Comments on JH Hendrie testimony before & Mark committee re TH1 Smaller towns than Harrisburg could not be evacuated in one hour.
RYAN, R. G. Affiliation Unknown 7/04/03 3p
- 790200024 Expresses appreciation for suggestions to help improve conditions at TH1
GENTON, H. R. Office of Nuclear Reactor Regulation 7/05/03. 1p
- 790200024 Offers suggestions to release gas bubble pressure, ltr partially withheld, home telephone number (ref FOIA Exemption 6).
ALLEN, R. Affiliation Unknown 7/03/03 1p
- 790200049 Expresses concern re sabotage of nuclear power plants
JOHNS, J. Affiliation Unknown 7/05/03 1p
- I Financial Information

790200072 Forwards "Annual Financial Report 1979"
HARRISON, J. C. Metropolitan Edison Co 7/04/03 1p
- 790200030 "Annual Financial Report 1979"
Metropolitan Edison Co * CPU Service Corp 7/02/03 11pp
- J Insurance & indemnity information

790200048 Discusses effect of classifying TH1-2 incident as extraordinary linear occurrence, which would trigger waiver of defense under Price-Anderson Act
SHAPIRO, H. A. Office of the Executive Legal Director 7/03/03 1p
- 790200017 Discusses record of TH1-related action re insurance for 790200-040
BALTIMORE, J. Astritrust & indemnity group 7/04/03 11pp
- 790200010 Discusses facility Pelican AF-020 & AF-03, Secondary Financial Bonds CE-02 & CE-03 insurability limits as result of TH1 incident
CARRER, M. C. American Nuclear Insurers 7/05/03 3pp
- 790200028 Provides updated info re wage loss claim & evacuation claims from 790305 - OMS Forwards form "Final Settlement Request" for use on connection w/ wage loss evaluation
CARRER, M. C. American Nuclear Insurers 7/05/03 2p
- 790200004 Forwards Endowment 34 to HANSEL Policy IP-73
GIBBY, H. F. CPU Service Corp 7/05/03 2p
- 790200012 Addresses reinstatement of Public Liability policy for Metropolitan Edison Co. Matter still under consideration w/ carrier to supply current claim expense figures
FISCH, B. C. American Nuclear Insurers 7/05/03 1p
- K Advisory Committee on Reactor Safeguards reports & correspondence

790200043 Requests publication by 790403 of end FR notice re ACRS 790400-04 meeting
FRALBY, R. F. Office of the Executive Director for Operations 7/03/03 1p
- 790200043 Requests publication by 790403 of end FR notice re ACRS 790400-04 meeting
FRALBY, R. F. Office of the Executive Director for Operations 7/03/03 1p
- 790200043 Requests publication by 790403 of end FR notice re ACRS 790400-04 meeting w/OTD in Washington, DC to discuss TH1 incident
CHILDS, J. J. Office of the Secretary of the Commission 7/03/03 1p
- 790200037 Forwards list of highlights of 790328 FR notice re ACRS Subcommittee 790404 meeting on TH1
A Division of Operating Reactors 7/03/03 3p
- 790200024 Forwards PSN Chapter 3 Reactor Safety Chapter 4, Contingency Safety Features, W/1 encl
HARRISON, J. C. Office of State Programs 7/04/04 1p
- 790200028 Ltr to preliminary thoughts on lessons learned from TH1-2
PALLADIUM, J. ACRS - Advisory Committee on Reactor Safeguards 7/04/04 1p
- 790200042 Forwards questions & answers for hearing backup ltr to be provided for chairman, w/ACRS concerns re TH1
HARRISON, J. C. Office of Nuclear Reactor Regulation 7/04/03 2pp.
- 790200058 Requests publication by 790412 of end FR notice re ACRS And New Subcommittee 790423-24 meeting
FRALBY, R. F. ACRS - Advisory Committee on Reactor Safeguards 7/04/03 1p
- 790200056 Notification of 790423-24 meeting w/ACRS And New Subcommittee in Los Angeles, CA to discuss TH1 accident.
CHILDS, J. J. Office of the Secretary of the Commission 7/05/03. 2p
- 790200041 Forwards highlights of 790403-07 22nd ACRS meeting re TH1 & other facilities
CRITCHER, L. P. Division of Project Management 7/04/03 4pp

DOCKETED ITEMS

- 7904200078 Requests publication by 790412 of next PR notice re ACRS
790416-17 meeting
CHILDS, R. F. Office of the Executive Director for Operations
79/04/10 1p
- 7904200089 Notification of 790416-17 ACRS meeting in Washington, DC
to discuss TMI incident
CHILDS, R. F. Office of the Secretary of the Commission 79/04/10
3pp
- 7904200127 Forwards PR notice of ACRS meetings on 790416-17 &
790420-21 Paragraphs to discuss TMI incident
ACRS - Advisory Committee on Reactor Safeguards 79/04/11 3pp
- 7904180044 Rehears draft trip report of RF Fraley 790412 visit to TMI-2
Preliminary primary coolant analysis for 790411 sample &
Preliminary description of events at TMI and
FRALEY, R. F. ACRS - Advisory Committee on Reactor Safeguards
79/04/10 30pp
- 7904200001 Discusses ACRS recommendations contained in 790407, 1B & 2D
line re the investigation
HELTHER, G. J. Standardization Branch 79/04/10 8pp
- 7904130042 Confirms 790402 helcon re resource impact assessment in
line of TMI incident Details FY77 immediate & followup
efforts & FY80 followup effort
KILPATRICK, R. E. ACRS - Advisory Committee on Reactor Safeguards
79/04/06 1p
- 7904130070 Requests copy of normal shutdown procedures including going
to natural circulation & chronology of events re TMI
incident
MCNEEL, S. O. ACRS - Advisory Committee on Reactor Safeguards
79/04/06 1p
- 7904120074 Describes differences in BWM piping arrangements connecting
pressureizer to hot leg Level piping may cause problem
similar to that at TMI
FLIBERTY, H. B. ACRS - Advisory Committee on Reactor Safeguards
79/04/06 1p
- 7904130080 Notifies that reply by Industrial Advisory Group on Recovery
Operations at TMI are available for ref
MCNEEL, S. O. ACRS - Advisory Committee on Reactor Safeguards
79/04/06 1p
- 7904180030 Forwards preliminary sequence of events at TMI for first
20-h of incident Describes distribution of Metropolitan
Edison Co shutdown procedures
MCNEEL, S. O. ACRS - Advisory Committee on Reactor Safeguards
79/04/06 1p
- 7904180048 Forwards preliminary sequence of events at TMI for first
30-h of incident Sequence reconstructed from available
data sources
LOWE, R. L. GPU Service Corp 79/04/14 15pp
- 7904130015 Forwards WPPSS presentation package, "The Incident & Its
Impact on WPPSS Projects."
KILPATRICK, R. E. ACRS - Advisory Committee on Reactor Safeguards
79/03/01 1p
- 7904130020 Forwards presentation package, "TMI Incident & Its Impact on
WPPSS Projects."
KILPATRICK, R. E. Washington Public Power Supply System 79/04/10
1p
- 7904130054 Congress Chinese bomb bomb test 1-101 failed in PA to that from
TMI-2 highest 1-101 in milk from TMI-2 was 48 picocuries
MULLER, R. ACRS - Advisory Committee on Reactor Safeguards
79/03/01 1p
- 7904130199 Forwards PJ Persland 790801 memo re TMI, presenting model for
estimating fuel assembly damage
LIPINSKI, H. C. Argonne National Laboratory 79/05/02 1p
- 7904130080 Summarizes impact on sequence of events re fuel element
behavior & consequent core conditions to be expected.
Presents model of probable core damage timelines, etc.
PERSLAND, J. Argonne National Laboratory 79/05/01 4pp
- 7904130011 Testimony before Senate Subcommittee on Nuclear Regulation
on 790420 re PA Public Util Commission actions following TMI
incident.
GOSCO, H. W. Pennsylvania State of 79/04/30 23pp
- 7904180012 Highlight of Senate Subcommittee on Nuclear Regulation
790420 third hearing on TMI-2 witness list encl
ALBRECHT, H. ACRS - Advisory Committee on Reactor Safeguards
79/05/02 20pp
- 7904180017 Summary of 790501 meeting w/C-E in Bethesda, MD re effect of
TMI incidents on C-E plants Paragraph encl
WITTENBERGER, ACRS - Advisory Committee on Reactor Safeguards
79/05/02 15pp
- 7904180022 Forwards addl info items received during Ad Hoc Subcommittee
on TMI Incident 790420-0501 meeting
MULLER, R. K. ACRS - Advisory Committee on Reactor Safeguards
79/05/02 1p
- 7904180027 Summary of 790411-12 meeting w/C-E in Bethesda, MD re
corrective actions for C-E 3000 plants as result of TMI
incident
ROSS, G. F. Division of Project Management 79/04/12 3pp
- 7904180031 Summary of 790410 meeting w/WH in Bethesda, MD re natural
circulation in BWR reactors
ROSS, G. F. Division of Project Management 79/04/12 13pp
- 7904180037 Summary of 790411 meeting w/Washington in Bethesda, MD re
short-term corrective actions for Washington 3000 plants
as result of TMI incident
ROSS, G. F. Division of Project Management 79/04/12 4pp
- 7904200003 Forwards tentative schedule for continuation of 790420-0501
TMI-2 Accident Operations Subcommittee meeting on 790509
MULLER, R. K. ACRS - Advisory Committee on Reactor Safeguards
79/05/03 3pp
- 7904200004 Forwards final agenda for ACRS 229th meeting on 790509-12
22900001, P. Division of Project Management 79/05/04 1p
- 7904200013 Final agenda for ACRS 229th meeting on 790509-12
P. Division of Project Management 79/05/02 4pp
- 7904130039 Forwards two NRC reply re ACRS activities related to TMI
NRC encl
WITTENBERGER, H. E. ACRS - Advisory Committee on Reactor Safeguards
79/05/07 1p
- 7904180034 Forwards presentation slides shown at NRC 790503 briefing
on personnel exposures Reading of 1,200 millirem/hr reported
and test over site adjacent island had 900 millirem
WALLER, R. ACRS - Advisory Committee on Reactor Safeguards
79/05/07 10pp
- 7904180049 Forwards H. E. Sheringham's preliminary appraisal of TMI
incident
SHERINGHAM, H. E. ACRS - Advisory Committee on Reactor Safeguards
79/05/07 7pp
- 7904130026 Summary of 229th ACRS meeting on 790509 re TMI-2
MULLER, R. K. ACRS - Advisory Committee on Reactor Safeguards
79/05/09 2pp
- 7904200004 Forwards notice of meeting for publication in PR by 790510
CHILDS, R. F. Office of the Secretary of the Commission 79/05/10
1p
- 7904200102 Notification of 790501-0401 meeting w/ACRS in Washington, DC
to discuss implications of TMI
ROSS, G. F. ACRS - Advisory Committee on Reactor Safeguards
79/05/10 2pp
- 7904200002 Lists proposed assignments & priorities re implications of
TMI incident
ACRS - Advisory Committee on Reactor Safeguards 79/05/10 23pp
- 7904200029 Summarizes recommendations & comments of ACRS subcommittee
re long-term effects of TMI incident as presented by Grant
on 790510
ACRS - Advisory Committee on Reactor Safeguards 79/05/10 2pp
- 7904200044 Discusses 790514 meeting w/D. Major of ACRS re review of BWM
operating plants
HELTHER, G. J. Standardization Branch 79/05/14 1p
- 7904200048 Summary of 790510 meeting w/C-E of Executive Director for
Operations & Director of NRC Program Office re TMI-2
activities
MULLER, R. ACRS - Advisory Committee on Reactor Safeguards 79/05/15
20pp

--7904200174 Indicates that H. Pollard will not attend 227th ACRS meeting. will be replaced by 790420130.
 FRANKLIN, R. F. ACRS - Advisory Committee on Reactor Safeguards
 79/03/18 1p

7904090070 Interim Report 3 on TMI-2 exhibits recommendations re reactor pressure vessel level indication operator training, LER evaluation, operating procedures & electric power supply
 CARBON, H. M. ACRS - Advisory Committee on Reactor Safeguards
 79/03/16 4pp

7904070126 Interim Report 2 on TMI supplementary response to U. S. NRC 790418 request re nuclear circulation procedures, pressurizer heaters, natural circulation conditions & more with thermocouples
 CARBON, H. M. ACRS - Advisory Committee on Reactor Safeguards
 79/03/16 4pp

7904270078 Forward summary of ACRS 209th meeting on 790310-12 re TMI
 HARRIS, G. D. Light Water Reactors Branch 1 79/03/14 2pp

--7904270104 Summary of ACRS 209th meeting on 790310-12 re implications of TMI accident
 " Light Water Reactors Branch 1 79/03/12 4pp

7904070020 Requests comments re ACRS 790407-18 & 20 items containing recommendations on TMI incident Response requested by
 790320
 ROSEN, D. F. Division of Project Management 79/03/17 3pp

7904070025 Requests comments ACRS 790407-18 & 20 items containing recommendations on TMI incident Response requested by
 790320
 ROSEN, D. F. Division of Project Management 79/03/17 3pp

7904070026 Requests comments re ACRS 790407-18 & 20 items containing recommendations on TMI-2 incident Response requested by
 790322
 ROSEN, D. F. Division of Project Management 79/03/17 3pp

7904070061 Requests comments re ACRS 790407-18 & 20 items containing recommendations on TMI-2 incident Response requested by
 790323
 ROSEN, D. F. Division of Project Management 79/03/17 3pp

7904100177 Summary of NRC 790317 meeting re preliminary chronology of the event chronology and
 TAM, P. ACRS - Advisory Committee on Reactor Safeguards 79/03/17 4pp

7904180028 Notice of ACRS 790404-02 meeting in Huddell, MA to discuss technical details of the incident
 DEVEL, J. G. ACRS - Advisory Committee on Reactor Safeguards
 79/03/17 2pp

7904270022 Successor Michaelson 790310 & 11 comments at ACRS meeting re break analysis & transient sequences
 MELTZER, S. J. Standardization Branch 79/03/17 3pp

7904200024 Summary of ACRS 790310-12 meeting re circumstances relating to accident at TMI
 CARBON, H. M. ACRS - Advisory Committee on Reactor Safeguards
 79/03/16 4pp

--7904200038 Summary of ACRS 790310-12 meeting re review of accident at TMI
 CARBON, H. M. Office of Public Affairs 79/03/16 4pp

--7904200050 ACRS recommendation that NRC consider establishing quantitative safety goals for overall safety of nuclear reactors, Congress & public should comment on plan
 CARBON, H. M. Office of Public Affairs 79/03/16 1p

7904070062 Requests comment re ACRS 790407-18 & 20 items containing recommendations on TMI-2 incident Response requested by
 790320
 ROSEN, D. F. Division of Project Management 79/03/22 3pp

7904100018 Requests comment by 790320 re encl add ACRS 790314 recommendations re TMI-2 incident
 ROSEN, D. F. Division of Project Management 79/03/23 13pp

7904100025 Requests comment by 790320 re encl add ACRS 790314 recommendations re TMI-2 incident
 ROSEN, D. F. Division of Project Management 79/03/23 13pp

7904100028 Requests comment by 790320 re encl add ACRS 790314 recommendations re TMI-2 incident
 ROSEN, D. F. Division of Project Management 79/03/23 13pp

7904100030 Requests comment by 790320 re encl add ACRS 790314 recommendations re TMI-2 incident
 ROSEN, D. F. Division of Project Management 79/03/23 13pp

7904100032 Requests comment by 790320 re encl add ACRS 790314 recommendations re TMI-2 incident
 ROSEN, D. F. Division of Project Management 79/03/23 13pp

F Operating license stage documents & correspondence

7904200176 Revised unsolicited draft of notice of incident on 790328
 CHALK, S. J. Office of the Secretary of the Commission 79/03/20 13pp

7904100461 Incident 4th air morning report for 790329 info includes dose rates
 HARTEN, J. Division of Site Safety & Environmental Analysis
 79/03/29 14pp

7904200175 Submits IE 4th air morning report at 6:30 AM. Discusses radioactivity distribution info partially withheld from telephone numbers (real FOLIA exemption at
 HARTEN, J. Division of Site Safety & Environmental Analysis
 79/03/29 13pp

7904040020 Requests status report forwards questions re design similarities to TMI
 ANGELO, R. J. Commission 79/03/29 2pp

7904200462 Forwards compilation of TMI-2 sequence of events, background info & history
 CHALK, S. J. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/03/31 10pp

7904200100 Notices of NRC request that mobile Reinsende be deployed to Harrisburg airport on soon as possible
 HARTEN, J. Commerce Dept of National Oceanographic & Atmospheric Administration 79/03/31 1p

7904200104 Requests use mobile Reinsende station as expendable for 30 days at six full per day be alerted for movement to
 HARTEN, J. Commerce Dept of National Oceanographic & Atmospheric Administration 79/03/31 1p

7904030040 Summary of 790401 meeting w/General Public: Utilis & others re status of TMI-2 incident info partially withheld from telephone numbers (real FOLIA exemption at
 " Office of Nuclear Reactor Regulation 79/04/01 7pp

7904100464 Forwards summary info re calculations of TMI gas bubble vol
 ROSEN, D. W. Babcock & Wilcox Co 79/04/02 3pp

7904200047 Notifies that test group has been established to evaluate generic implications of feedwater transients in BSW-designed reactors
 GAVIN, S. R. Systematic Evaluation Program Branch (re 790620)
 79/04/02 1p

7904200040 Lists info re carbon levels of soil samples
 GAVIN, S. R. Health, Education & Welfare: Dept of 79/04/02 14pp

7904200047 Forwards description of IE enforcement actions re BSW members other than TMI inspectors must assure that
 ROSEN, D. F. Office of Inspection & Enforcement 79/04/02 3pp

7904200047 Forwards draft reply to J. California 790401 memo re Registry of workers at TMI
 GAVIN, S. R. Office of the Executive Director for Operations
 79/04/02 2pp

7904100028 Provides info re sample results from waste storage tanks
 HARTEN, J. Region 5, San Francisco, Office of the Director
 79/04/02 1p

7904100418 Forwards recommendations sent by Washington re status of Washington PMR in light of TMI incident
 HARTEN, J. R. Office of Inspection & Enforcement 79/04/03 3pp

7904100419 Notifies that Susquehanna River sample collected 790402 has been analyzed & previously reported value could not be confirmed 1-125 not present in river at that time
 HARTEN, J. R. Health, Education & Welfare: Dept of 79/04/03 1p

DOCKETED ITEMS

7906130486 Analysis of Susquehanna River water samples for C-131 as 790402 No 1-121 found
HARTIS, A. Health, Education & Welfare, Dept. of 79/04/03 1p

7906130491 Forwards status of operating plants
MILNER, E. J. Region I, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/03 2pp

7906130495 Data re background levels of Sr & Cs in milk for Philadelphia & Pittsburgh
HECHER, J. Environmental Protection Agency 79/04/03 1p

7906130507 Provides info re neutron exposure from TMI-2 incident. Lists data req'd to complete analysis. Draft request for data encl.
GOSBELL, V. Office of the Executive Director for Operations 79/04/03 2pp

7906130508 Provides guidance re procurement support for TMI-2
GOSBELL, V. Office of the Executive Director for Operations & Analysis 79/04/04 2pp

7906130513 Forwards recent FBI communication to be disseminated to direct NRC employees only w/o encl.
BRADY, R. J. Office of Administration 79/04/04 1p

7906130523 Notifies that bulletins are being sent to all licensees of nuclear power plants incorporating steam supply design information to that of TMI facility.
HECHER, J. M. Communication 79/04/03 2pp

7906130547 Provides rough estimate of source term from all data collected to date.
LEE, J. Division of Site Safety & Environmental Analysis 79/04/05 1p

7906130524 Discusses logistical support for personnel assigned to TMI-2 site.
GOSBELL, V. Office of the Executive Director for Operations 79/04/03 1p

7906130526 Discusses questions re Nucleonics Week 790405 article. "Nucleonics Week Inspector Had Already Raised TMI-Related Safety Issues - Sources needed for TMI-2 submission."
Office of Inspection & Enforcement 79/04/03 2pp

7906130530 Forwards 790328-0424 notes re handling of TMI incident info partially withheld from telephone number ref FOIA Exemption 6.
Office of Nuclear Reactor Regulation 79/04/04 2pp

7906130531 Forwards data re operation of reactor coolant pump meters at incident used which is applicable to TMI.
TAYLOR, J. H. Babcock & Wilcox Co. 79/04/04 2pp

7906130542 Requests radiation monitor recorder charts to establish time sequence for escape of radiation.
KIRKPATRICK, S. Office of Inspection & Enforcement 79/04/04 2pp

7906130527 Requests arrangements to airlift four safety filters from State of MA to Harrisburg, PA airport & then truck filters to TMI.
HECHER, J. Office of Inspection & Enforcement 79/04/04 1p

7906130532 Lists weekend schedule for morning operations ctr.
THOMPSON, D. Office of I & E Executive Director for Operations Support 79/04/04 1p

7906130420 Second round of utility interviews re TMI incident.
Metropolitan Edison Co. 79/04/04 20pp

7906130505 Discusses use & specs of hydrogen high pressure storage tanks & hydrogen Comblin compressors requested by NRC for TMI-2. Mail available for immediate followup.
HECHER, J. L. Consumer Public Int. 79/04/04 1p

7906130506 Discusses NRC request to airlift filters from state of MA to TMI-2 site.
GOSBELL, V. Office of the Executive Director for Operations 79/04/03 1p

7906130507 Forwards info re notification app for TMI incident.
MURRAY, J. M. Region 2, Atlanta, Office of the Director 79/04/03 2pp

7906130507 Provides procedures to assure coordination of mail lab support for NRC activities at TMI-2. 790407 discussion.
Forwards W. B. log of active & completed lab inputs.
MILNER, E. J. Division of Systems Safety 79/04/04 1p

7906130489 Summary of 790407 site visits to obtain better understanding of radiation overall response to crash-site capabilities & activities.
BRODERICK, J. H. Division of Fuel Facility & Materials Safety 79/04/04 2pp

7906130494 Confirms request to transfer radioactive samples from TMI-2 to Oak Ridge, TN & Aiken, SC.
GOSBELL, V. Office of the Executive Director for Operations 79/04/03 1p

7906130495 Responds to B. Conner's request for info re Region ITR initial notification of licensees & govts. officials re TMI incident.
MURPHY, J. G. Region I, Chicago, Office of the Director 79/04/03 1p

7906130481 Requests comments on review of action items from 790405 technical mtg meeting.
STELLER, V. Division of Operating Reactors 79/04/04 20pp

7906130514 Discusses meeting of NRC operations ctr during controlled preparations for nuclear conversion testing.
DAVIS, J. D. Office of Inspection & Enforcement 79/04/04 1p

7906130529 Provides info re activities while at TMI-2 for 790328-0499. Critical of NRC intra agency conflicts & will inactionism re corporate personnel. Laid.
GUYTON, K. V. Region 4, Dallas, Office of the Director 79/04/01 3pp

7906130519 Confirms request to locate & arrange for railway cars to store low level waste from TMI-2.
GOSBELL, V. Office of the Executive Director for Operations 79/04/01 1p

7906130521 Recommends that all records be provided re info contained in OS. Vessels 790403 & 0409 under re TMI incident.
STELLER, V. Division of Operating Reactors 79/04/02 1p

7906130526 Forwards Bethesda, MD daily report for TMI to support site operations coverage for Center weekend.
CABLE, E. B. Office of Nuclear Reactor Regulation 79/04/02 2pp

7906130524 Forwards handwritten notes re boron concentration at TMI-2. For 790328-0412 info partially withheld from telephone numbers. Ref FOIA Exemption 6.
Office of Nuclear Reactor Regulation 79/04/02 14pp

7906130543 Tabulates NRC personnel exposures at TMI to 790412 info partially withheld names of individuals. Ref FOIA Exemption 6.
GOSBELL, V. Region I, Philadelphia, Office of the Director 79/04/02 1p

7906130525 Forwards chart of tests performed by Div of Technical Info & Document Control in response to TMI incident.
GOSBELL, V. Technical Information & Document Control 79/04/02 4pp

7906130517 Responds to 790305 request for info re emergency preparations NRC engaged in study of products containing radioactive matter.
BENNETT, S. A. Assistant Director for Program Development 79/04/02 2pp

7906130544 Forwards info on TMI incident followup actions by NRC in response to 790412 memo.
MILLER, M. D. License Fee Management Branch 79/04/02 3pp

7906130524 Confirms NRC request to transport radioactive sample by air to Idaho Falls. Info partially withheld from contractor contact. Ref FOIA Exemption 6.
GOSBELL, V. Office of the Executive Director for Operations 79/04/02 1p

7906130502 Provides alternatives to duplicating meter recording tapes of TMI incident.
MURPHY, J. H. Office of Inspection & Enforcement 79/04/02 2pp

7906130507 Expresses gratitude to Univ. for meteorological data provided during TMI incident.
FAIRBROTHER, J. E. Hydrology Meteorology Branch 79/04/02 2pp

7906130500 Forwards report on penetration availability using instrument outside containment.
MURRAY, J. P. Assistant Director for Engineering & Projects (PRA) 79/04/02 2pp

DOCKETED ITEMS

89

7906250107 Forwards analytical results for primary coolant, including
 Write analysis: for 790329-5-0410
 RUSSELLE, J. J. Assistant Director for Engineering & Projects (P)
 790425 79/04/13 2pp

7906250109 Discusses mechanical condition of the core and ballooning
 leading to rupture expected in highest power areas of core
 RUSSELLE, J. J. Industry Advisory Group 79/04/13 2pp

7906250110 Comments on existing situation re TMI-2, including
 recommends NRC response to requests for partial withdrawal
 tentative recommendations (ref FOIA exemption 2)
 RUSSELLE, J. J. Office of the General Counsel 79/04/14 2pp

7906250226 Forwards JO Weinberg 790411 (re N. H. Mattson 790411) memo
 re criteria for use of steam generator for short-term
 long-term operation
 RUSSELLE, J. J. Assistant Director for Engineering & Projects (P)
 790425 79/04/14 2p

7906250306 Submits NRC personnel exposures at TMI-2, 790413 info
 partially withheld identification of individuals (ref FOIA
 exemption 4)
 RUSSELLE, J. J. Office of Inspection & Enforcement 79/04/16 2p

7906250405 Sampling summary for "Operation Ivory Cup" for 790413, 13
 & 16
 Environmental Protection Agency 79/04/16 7pp

7906250408 Tabulates NRC personnel exposures at TMI-2, 790413
 info partially withheld names of individuals (ref FOIA
 exemption 4)
 RUSSELLE, J. J. Region 5, Philadelphia, Office of the Director
 79/04/16 1p

7906250410 Describes personnel understanding of role of Ofc of Reg &
 Program Analysis in ongoing TMI-2 discussions
 CONNOR, S. Office of Management and Program Analysis 79/04/16 1p

7906250513 Forwards article re TMI incident, received from F. Van Noy
 790412 (ref 790412)
 RUSSELLE, J. J. Assistant Director for Systems Engineering 79/04/17 1p

7906250531 Forwards summary of 790417 planning meeting
 RUSSELLE, J. J. Office of Nuclear Reactor Regulation 79/04/17 1pp

7906250539 Forwards list of remaining Special Instrumentation Group
 tasks info partially withheld some telephone numbers (ref
 FOIA exemption 4)
 RUSSELLE, J. J. Special Instrument Group 79/04/17 2pp

7906250576 Forwards FR notice re change of meeting of ACRS ad hoc
 subcommittee on TMI
 ACRS - Advisory Committee on Reactor Safeguards 79/04/17 2pp

7906250579 Notice of meeting of 790423-24 meeting of ACRS ad hoc
 subcommittee on TMI re Los Angeles, CA
 CHILDS, J. J. Office of the Secretary of the Commission 79/04/18 1p

7906250405 Forwards revised 790410 work schedule for Incident Response
 Gr
 RUSSELLE, J. J. Division of Reactor Operations Inspections 79/04/18 2pp

7906250539 Provides info re activities while at TMI-2, for 790329-0406
 Position survey team included by lack of proper assignment
 RUSSELLE, J. J. Region 2, Atlanta, Fuel Facility & Materials Safety
 Branch 79/04/18 2pp

7906250408 Provides info re activities while at TMI-2, for 790329-0409.
 Licensee control of radioactive waste effective for 13/04/09
 RUSSELLE, J. J. Region 2, Atlanta, Fuel Facility & Materials Safety
 Branch 79/04/18 2pp

7906250448 Forwards analysis monitoring notes re TMI-2 event
 RUSSELLE, J. J. Office of State Programs 79/04/18 2pp

7906250483 Submits outline notes for TMI-2 interim report
 RUSSELLE, J. J. Office of State Programs 79/04/18 2pp

7906250526 Provides info re activities while at TMI-2, for 790329-0413
 Not involved with/on-site re plant operations
 RUSSELLE, J. J. Region 2, Atlanta, Fuel Facility & Materials Safety
 Branch 79/04/18 2pp

7906250577 Responds to request for summary of experiences at Incident
 Response Gr after TMI-2 incident, forwards selected
 communications for 790329 telephone tapes
 RUSSELLE, J. J. Office of Management and Program Analysis 79/04/18 2pp

7906250109 Forwards informal notes re TMI incident, including mail
 monitoring data
 RUSSELLE, J. J. Office of State Programs 79/04/18 2pp

7906250508 Discusses discharge water sample analysis procedures for
 TMI-2
 RUSSELLE, J. J. Power-Site Consultants, Inc 79/04/18 1p

7906250270 Forwards FR notice re corrected schedule of ACRS meetings
 & Office of Nuclear Reactor Regulation 79/04/18 2pp

7906250272 Notice of proposed meeting of ACRS
 CHILDS, J. J. Office of the Secretary of the Commission 79/04/17 2pp

7906250426 Forwards info requested by G. Chapman re dose rate at top of
 containment
 RUSSELLE, J. J. Technical & Administrative Support Branch 79/04/18 2pp

7906250431 Forwards four lab's results of boron measurement of 790411
 primary loop sample (non-pressurized) info partially
 withheld some telephone numbers (ref FOIA exemption 4)
 TELFER, J. T. Division of Operating Reactors 79/04/18 2pp

7906250504 Forwards status of mail info work requests made since 790410
 info partially withheld some telephone numbers of contractor
 contacts (ref FOIA exemption 4)
 RUSSELLE, J. J. Division of Reactor Safety Research 79/04/18 15pp

7906250402 Provides info re activities while at TMI-2, for 790329-0406
 Region II response to crisis was excellent, but not of
 for District Control & NRC personnel according to NRC mandate
 CHILDS, J. J. Region 2, Atlanta, Office of the Director 79/04/18 2pp

7906250516 Provides info re activities while at TMI-2, for 790329-0411
 Unit radioactive operations with good understanding
 CONNOR, S. Office of Management and Program Analysis 79/04/18 2pp

7906250514 Forwards list of background mail for President's Commission
 on TMI
 CONNOR, S. Office of the Executive Director for Operations 79/04/18 2pp

7906250531 Discusses White House memo & draft rules assigned to NRC &
 EPA re monitoring long-term radiation at TMI-2
 SHAPIRO, J. J. Office of the Executive Legal Director 79/04/18 2pp

7906250508 Provides info re activities while at TMI-2, for 790329-0412
 Observed licensee representative towards NRC, NRC staff
 to make map decisions during fast moving events
 CHILDS, J. J. Region 2, Atlanta, Reactor Construction &
 Engineering Support Branch 79/04/18 1p

7906250426 Provides info re activities while at TMI-2, for 790329-0417
 Status included monitoring of plant status & operator
 actions
 RUSSELLE, J. J. Region 2, Philadelphia, Office of the Director 79/04/18 1p

7906250426 Provides info re activities while at TMI-2, for 790329-0418
 All NRC personnel were present & staff
 RUSSELLE, J. J. Region 2, Atlanta, Office of the Director 79/04/18 2pp

7906250408 Summary of 790410 meeting w/PA, Health Dept & HHS/DOH
 PA to discuss strategy for evaluation of TMI-2 health
 impact
 CHILDS, J. J. Radiological Health Branch 79/04/18 2pp

7906250526 Submits record of articles re TMI-2 event, summary of
 operations site status for 790410 & preliminary
 chronology
 CONNOR, S. Office of Management and Program Analysis 79/04/18 2pp

7906250513 Act receipt of NRC bulletin re TMI incident, priority info
 needed to alert public of possible consequences &
 impact on nuclear power in Italy
 CHILDS, J. J. 79/04/18 1p

DOCKETED ITEMS

- 7904010238 Provides summary of activities while at TH-2 for 790404-16 Operations at site were well organized & coordinated
FELDMAN, L. Region 3, Philadelphia, Office of the Director 79/04/20 1p
- 7904020079 Provides summary of activities while assigned to TH-2 site MIBELT, P. H. Region 1, Philadelphia, Office of the Director 79/04/20 1p
- 7904020088 Forwards handbook of govt. agencies which may be useful in efforts w/Presidential Investigating Committee M/W mail
SAYLINDER, M. Technical Information & Document Control 79/04/23 1p
- 7904040036 Provides cost for reproduction of TH-2 PWR Risk Lists
KAPLAN, J. J. Technical Information & Document Control 79/04/24 1p
- 7904040038 Forwards calculated dose rate from condensate collector
decontamination
HARRIS, L. J. Technical & Administrative Support Branch 79/04/24 3pp
- 7904070009 Forwards requested updated primary coolant sample analyses
HARRIS, L. J. Technical & Administrative Support Branch 79/04/24 4pp
- 7904070087 Forwards C Reactor Draft testimony for President's Commission on TH-2 Requests comments info partially withheld draft testimony (ref FOIA Exemption B)
BICKNELL, L. Office of the General Counsel 79/04/24 1p
- 7904080067 Responds to 790408 11 ltr to JR Hendrix Investigation of TH-2 in initial stages Response to materials must await outcome of review
HARRIS, L. J. Office of Public Affairs 79/04/26 1p
- 7904090049 Forwards CBE editorial re nuclear power to CA invites NRC to prepare reply statement for broadcast
HARRIS, L. J. CBE News, CBE, Inc 79/04/21 4pp
- 7904090078 Forwards CBE news editorial re nuclear power plants in CA Invite NRC to prepare reply statement for broadcast
HARRIS, L. J. CBE News, CBE, Inc 79/04/28 4pp
- 7904090080 Forwards CBE news editorial re economics of nuclear power Invite NRC to prepare reply statement for broadcast
HARRIS, L. J. CBE News, CBE, Inc 79/04/28 4pp
- 7904090090 Requests personnel engaged in TH-2 to Log 790328-0401 actions, if already logged in incident response dir
SEITZ, H. H. Office of Nuclear Reactor Regulation 79/04/26 1p
- 7904090092 Describes major drawbacks to locating sampling sites for both units in same room Unit 2 tank must be moved & all existing lines flushed before Unit 1 can be connected
- 7905070008 Comments on discussions w/BS Benjamin of AP & Atty General of NY re clarification of 790403 core damage assessment & basic material info on fission products
NEWMAN, G. Core Performance Branch 79/04/26 1p
- 7905080018 Summarizes 790420 visit to BNL to discuss progress re ORR-PTT reactor physics technical assistance program
Forwards results of study of boron calculations
DUNN, L. H. Division of Systems Safety 79/04/26 5pp
- 7905080048 Provides info re activities while at TH-2, for 790320-0411 Critical of duplication of effort between IC & ORR of Nuclear Reactor Regulation
BYER, J. A. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/26 2pp
- 7905080056 Provides info re activities while at TH-2, for 790320-0418 Answer questions re reliability of licensee health physics operations
TODD, P. G. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/26 3pp
- 7905080087 Provides info re activities while at TH-2, for 790320-0413 Critical of poor communications between unit employee & NRC re-plant health physics inspectors
FRIEDST, S. J. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/26 2pp
- 7905080091 Provides info re activities while at TH-2, for 790320-0413 Contact with licensee was minimal
DUNN, L. H. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/26 2pp
- 7905090130 Notifies of reduction of routine changeout frequency of Startup WPP-217 from once every 4th to once every 24th effective midnight on 790509
PORTER, R. Reactor Consultants, Inc 79/04/26 1p
- 7905090085 Forwards exp't to 790423 memo establishing task force for actual simulation initiation New members are added to task force
HARRIS, L. J. Metropolitan Edison Co 79/04/26 1p
- 7905090096 Discusses decontamination work inside plant New question by Waste Management Group call to use isotopic surveys because of possible impact to activated charcoal filters
COHEN, M. H. Metropolitan Edison Co 79/04/26 1p
- 7905090092 Discusses later-in procedure for notifying status of planned shipments of radwaste from TH-2
HARRIS, L. J. Assistant Director for Waste Management Program 79/04/26 1p
- 7906030070 Forwards personnel records re TH-2 info includes 790329 morning repl. calculations of man/mo & beta dose rate at vicinity of equipment in contact w/primary cooling water
HARRIS, L. J. Accident Analysis Branch 79/04/27 30pp
- 7906030074 Provides personal log of communications re TH-2 as requested in JR Status 790426 memo
COFFMAN, P. S. Division of Operating Reactors 79/04/27 1p
- 7906030081 Responds to 790416 memo Notifies that only NRC actions performed for TH-2 event were LER file searches
KIRBY, J. A. Office of Management and Program Analysis 79/04/27 1p
- 7906030092 Provides summary of activities while at TH-2, for 790427-0504 Contact w/ licensee was minimal
HOLCOMB, S. J. Office of Inspection & Enforcement 79/04/27 1p
- 7906030103 Discusses President's Commission on TH-2 & Rep't by Assistant by Interagency Review Group on Nuclear Waste Mgt. Mar 1979 Requests info from Hanford Bar
LAFLEUR, J. D. Office of International Programs 79/04/27 3pp
- 7906070016 Request by Hanford Bar Association for items of ref for President's Commission & Rep't to President by Interagency Review Group on Nuclear Waste Mgt. Mar 1979
DERRICK, G. Canada 79/04/12 1p
- 04240476 Submits items of possible concern for Exclusion in orders to BNL plant licensee Forwards 790330 PWR re reactor trip & subsequent shutdown at TH-2
HARRIS, L. J. Commission 79/04/27 1p
- 7906040718 PWR 790329 reactor trip & subsequent shutdown w/emergency sys dislocation caused by loss of vital bus power eventually restored to bus
GIERHART, G. H. Region 2, Atlanta, Office of the Director 79/04/28 1p

- 7904020125 Submits parallel waste processing strategy as part of recovery plan
SMPF, B Gilbert Associates, Inc 79/04/27 10pp
- 7904020201 Comments on proposed specs provided on 790403 Although specs are directed to current plant status, comments are directed for use in long-term cooling mode
SCLHED, J F Hearings Division 79/04/27 10pp
- 7904020307 Discusses analysis of charcoal from TH1-2 auxiliary big filters indication of transuranics detected Adel meeting with passive questions re isotopes present
COLLEEN, H Assistant Director for Systems Engineering 79/04/27 1p
- 7904020425 Recommends that Metropolitan Edison Co continue to ship radwaste to State of PA Bill before state legislature prohibiting shipments until probably not pass
COLLEEN, H T Effluent Treatment Systems Branch 79/04/28 1p
- 7904040504 Forwards updated list of MEC personnel who require access to TH1 site info partially withheld Social Security numbers (ref FOIA Exemption b)
GITHEN, H H HOSCHKE, J J Office of Inspection & Enforcement 79/04/29 8pp
- 7904050049 Forwards notes on TH1-related topics. For 790328-0429
Safe partially withheld home telephone numbers (ref FOIA Exemption b)
WINDO, F Office of State Program 79/04/29 8pp
- 7904050625 Forwards analysis of charcoal from auxiliary big filters as follows to R Vulliamy 790427 memo
COLLEEN, H T Effluent Treatment Systems Branch 79/04/29 1p
- 7904050626 Discusses manuscript of charcoal absorbers from TH1 (charcoal contained WPC-238 possibly as result of Onstream bond tests Presence of Cr-51 confirmed
COLLEEN, H T Effluent Treatment Systems Branch 79/04/29 1p
- 7904050703 Forwards notes prepared in connection with TH1 actions TH1 includes action on emergency procedures info partially withheld home telephone numbers (ref FOIA Exemption b)
HOSCHKE, J J Assistant Director for Reactor Safety 79/04/30 8pp
- 7904050454 Provides info re activities while at TH1-2 for 790405-19
Critical of problems in communication 3 long delay in identification analysis of samples
EWALD, S E Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/30 2pp
- 7904050494 Discusses restrictions on use of mask/wind surveillance assembly 88185 cartridges during decontamination of auxiliary TH1 big filters
SCLHED, J F Office of Inspection & Enforcement 79/04/30 1p
- 7904050701 Discusses staff response to 790410 LV Gesselt memo re TH1-2 Incident record of actions Homes have been prepared & will be forwarded
MULLER, R Office of Management and Program Analysis 79/04/30 1p
- 7904050734 Forwards analysis of licensee dosimetry data for TH1-2 Total man hour period use 120 F
SCLHED, J F Region 1, Philadelphia, Office of the Director 79/04/30 1p
- 7904050807 Forwards callar procedures & endpoints re TH1-2 alternate work radiologic monitors I-5
FORSTER, S W Partner-Gertz Consultants, Inc 79/04/30 8pp
- 7904050808 Submits EPA environ data from 790403-29
FORSTER, S W Region 1, Philadelphia, Office of the Director 79/04/30 1p
- 7904050843 "Cooling Test Regt"
KIMMEL, R L Nuclear Consulting Services, Inc MAREN 01046/01 79/04/30 3pp
- 7904050842 Agrees & notes taken during various meetings re 790430
to discuss plant status
Office of Nuclear Reactor Regulation 79/04/30 3pp
- 7904130302 Forwards personnel records of TH1 activities as requested in HR 01046 790402
KIMMEL, R L Division of Site Safety & Environmental Analysis 79/05/01 31pp
- 7904020458 Provides info re activities while at TH1-2 for 790412-24
Critical of shift health physics operators
HAWK, J B Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/01 3pp
- 7904020529 Forwards news releases re TH1 & shutdown of Five plants re TH1 was made available to press at press ctr in Middlebrook PA Site and
MILLES, C Office of Public Affairs 79/05/01 1p
- 7904020603 Requests list of news releases re TH1 incident & shutdown of Five power plants Forwards copy of article submitted for Association Union Leader re TH1 & nuclear activities
GILMAN, L Affiliation Unknown 79/05/01 8pp
- 7904050327 Recommends changes in TH1-2 operating point
MILBURN, S W GPU Service Corp 79/05/01 2pp
- 7904050448 Forwards info re 790328 exposures of personnel investigating leakage of radwaste info partially withheld names, social security numbers, birthdates (ref FOIA Exemption b)
HOSCHKE, J J Metropolitan Edison Co 79/05/01 8pp
- 7904050725 Forwards "Plant Note for Achieving Cold Shutdown May 1979" prepared by Technical Review Group, as app to safety evaluation
NEWBY, T M Office of Nuclear Reactor Regulation 79/05/01 1p
- 7904050726 "Plant Note for Achieving Cold Shutdown May 1979" prepared by Technical Review Group
Office of Nuclear Reactor Regulation 79/05/01 8pp
- 7904050730 Discusses TH1-2 "Criteria for Loss of Offsite Loss of Plant Electrical Power, Revision 1"
SCHNEIDER, B K GPU Service Corp 79/05/01 8pp
- 7904050807 Discusses adequacy of station electric distribution sys voltage in light of MEC 770400 generic TH1-2 790501 event at AN Nuclear Co Requests plant electric sys review
WAGMAN, D D Assistant Director for Light Water Reactors 79/05/02 8pp
- 7904050807 Summarizes info obtained from BWR re TH1 incident in response to HR Section 790426 memo info partially withheld home telephone number (ref FOIA Exemption b)
GIBSON, F C Mechanical Engineering Branch 79/05/02 12pp
- 7904050900 Provides info re activities while at TH1-2 for 790410-24
Witnesses events in area of sample coordination
ALLAN, S E Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/02 2pp
- 7904050973 Provides info re TH1-2 activities on 790410 & 25 per Region 1 Announcement 79/02 Licensee making effort to apply SA & QC to ongoing work
THOMPSON, C Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/02 2pp
- 7904051000 Provides summary of activities while at TH1-2 for 790410-24
Contact witnesses use phone
EWALD, S E Office of Inspection & Enforcement 79/05/02 3pp
- 7904100219 Provides summary of activities while at TH1-2
0410 Critical of shutdown in administrative process health physics during initial phase of incident
HIRTLE, R L Region 1, Philadelphia, Office of the Director 79/05/02 3pp
- 7904050824 Reviews HP Wilson 790501 recommendations re operating point
HARTMAN, S W GPU Service Corp 79/05/02 1p
- 7904050828 Describes organization of dept to implement response to TH1
Office of Inspection & Enforcement 79/05/02
- 7904050843 Forwards info re callar procedures & endpoints re TH1-2 alternate work radiologic monitors I-5 to be re hourly Point source callar complete
FORSTER, S W Metropolitan Edison Co 79/05/02 1p
- 7904050923 Reviews TH1-2 Effluent Monitors I-5
FORSTER, S W Partner-Gertz Consultants, Inc 79/05/02
- 7904050926 Discusses endpoints for Vickers & son ducti Forwards endpoints
HAWK, J B Metropolitan Edison Co 79/05/01

DOCKETED ITEMS

103

- 790302004 Provides summary of activities while at TH1-2 site
Comments on license & NRC activities
JACKSON, T J Office of Inspection & Enforcement 7/9/05/07 App
- 790302005 Notifies of delays in requests for airborne effluent
monitoring. Delays will cause when new level readings are
installed & operative
+ Office of Inspection & Enforcement 7/9/05/07 App
- 790302010 Forwards update of health physics status of facility info
we sent to LV District for use in memo to NRC
KINNEY, L W Region I, Philadelphia, Office of the Director
7/9/05/07 App
- 790302014 Forwards supplemental recommendation to Step 2 of C Water
790507 memo re changes in operating point
WILSON, R F GPU Service Corp 7/9/05/07 App
- 790302017 Notifies that level in B steam generator should be 95%
expansion & generator should remain isolated. Procedure GP-04
determining "work area"
HARRIS, E L Metropolitan Edison Co 7/9/05/07 App
- 790302017 Forwards revision & additions to HF Wilson 790501 memo
re recommended changes in operating point. Items replace or
add steps 1-3 in memo
WILSON, R F GPU Service Corp 7/9/05/07 App
- 790302020 Discusses Change 1 to interim procedure for notifying state
agency of shipments of TH1 radioactive
WILSON, R F Assistant Director for State Agreements Program
7/9/05/07 App
- 790302020 Forwards 790503 "Technical Help on Reactor Coolant Leakdown
Eyes" - Based on 790502 "Leakdown Eyes" Design
Statement
OWENS, E E H GPU Service Corp 7/9/05/07 App
- 790302047 Provides info re activities while at TH1-2 for 790417-0901
Critical AP analysis placed on individual's affidavit. NRC
team effort needed
WILSON, R F Region 2, Atlantic, Reactor Construction &
Engineering Support Branch 7/9/05/08 App
- 790302051 Forwards executive summary re TH1-2 liquid & gas releases
for 790200 incident
PORTER, S W Porter-Goff Consultants, Inc 7/9/05/08 App
- 790302058 Status report for 790507
WILSON, R F Division of Project Management 7/9/05/08 App
- 790302061 Forwards complete compilation of emergency & special
operating procedures 790225-0908. Procedures are categorized
by process status
WILSON, R F GPU Service Corp 7/9/05/08 App
- 790302063 Forwards results of electrical methods to measure water
level in reactor big
HEMERL, T C GPU Service Corp 7/9/05/08 App
- 790302064 Describes method & procedure of determining water level
between 0.4 & 10 inches to 10 ft & inches by measuring
electrical resistances
HEMERL, T C GPU Service Corp 7/9/05/08 App
- 790302064 Forwards chart of water level to reactor operated
levels to be used to determine water level in reactor big
HEMERL, T C GPU Service Corp 7/9/05/08 App
- 790302065 Provides summary of activities while assigned to TH1-2 site
Comments on license & NRC activities
WILSON, R F Region 1, Philadelphia, Safeguards
Branch 7/9/05/08 App
- 790302065 "Tech Spec Finalizing & Placing Nonprint Permitted Content
Drafts" by Gilbert Associates, Inc
+ Metropolitan Edison Co 7/9/05/09 17pp
- 790302069 Confirms results of NRC measurements of EPA with cross-check
samples based on 37 liters of milk received & corrected to
2,000-0 an 790508
WILSON, R F Region I, Philadelphia, Fuel Facility & Materials
Safety Branch 7/9/05/09 App
- 790302069 Forwards 790508 letter to TH1 Fugate re NRC documents lists
TH1 documents that have not been forwarded to President's
Commission W/790508 graphs
WILSON, R F Office of the Executive Director for Operations
7/9/05/09 App
- 790302070 Notifies of delivery of milk requested on TH1. Lists
category breakdown of documents. Complete listing of all
documents will be available by 790509. Draft of letter
COMBELL, E H Office of the Executive Director for Operations
7/9/05/09 App
- 790302074 Forwards draft topics of PHOs re TH1 incident
COLLINS, P F Assistant Director for Emergency Preparedness
7/9/05/09 App
- 790302078 Submits daily report for 790507
COLLINS, P F Division of Project Management 7/9/05/09 App
- 790302080 Forwards BSM memo summarizing calculations re starting
natural circulation in B steam generator. Adequate head is
available to drive B loop in 7905 range
WILSON, R F GPU Service Corp 7/9/05/09 App
- 790302082 Responds to TH1 special operating procedure 2-79-073 which
recommended regulator program. Offers guidelines for
determining "work area"
HARRIS, E L Metropolitan Edison Co 7/9/05/09 App
- 790302083 Provides summary of activities while assigned to TH1-2 site
Comments on license & NRC activities
WILSON, R F Region 2, Atlantic, Reactor Operations Branch
Support Branch 7/9/05/09 App
- 790302088 Provides possible method & time required to reduce hydrogen
concentration inside containment from 3.00 to 1.00 or less,
per 4.00 Section request
SCHMIDT, L H Accident Analysis Branch 7/9/05/10 App
- 790302090 Forwards B Research 790331-0428 logs & notebooks for TH1
Fire. Partially withheld have telephone numbers. List PDA
Exemption at
HARRIS, E L Assistant Director for Plant Systems 7/9/05/10 823pp
- 790302091 Summarizes Radiation Mgt Corp contract to perform whole body
counts on each NRC employee leaving TH1 site. Additionally,
after tour of duty
WILSON, R F Region I, Philadelphia, Office of the Director
7/9/05/10 App
- 790302091 Submits recommendations to small break incidents &
accidents, natural circulation, on-site power distribution,
determination of core status, research & engineered safety
feature equipment status
+ NRC - Advisory Committee on Reactor Safeguards 7/9/05/10 App
- 790302093 Notifies of operations within TH1. Also clarifies
vacationing. Forwards procedure for independent measurements
on radioactive liquid discharges
WILSON, R F Region I, Philadelphia, Office of the Director
7/9/05/10 App
- 790302097 Submits topics for discussion at 790510 meeting. Will
also present questions to health physics organization.
New plant start treatment unit & computer unit
WILSON, R F Region I, Philadelphia, Office of the Director
7/9/05/10 App
- 790302098 Discusses deferring administration of water at night
operating power reactors
COLLINS, P F Operator Licensing Branch 7/9/05/10 App
- 790302098 Recommends near-term sampling frequencies. Samples are only
taken to ensure criticality control. Discusses the
characteristics measurement & timing status
WILSON, R F GPU Service Corp 7/9/05/10 App
- 790302099 Discusses near-term BSM generator control. Current plan is to
take primary gas down to 300-10 pressure for long-term
natural circulation. Discusses other options
WILSON, R F GPU Service Corp 7/9/05/10 App
- 790302100 Provides summary of activities while assigned to TH1-2 site
Comments on license & NRC activities
WILSON, R F Region I, Philadelphia, Office of the Director
7/9/05/10 App
- 790302103 Discusses efficiency testing of thermal filtration system at
TH1-2. Also used for reduction of radioactive effluents should
be tested every 720-6 of operation
COLLINS, P F Effluent Treatment Systems Branch 7/9/05/11 App
- 790302103 Forwards corrected 24-120 & 1-101 release graphs for
Injection W/790508 graphs
PORTER, S W Metropolitan Edison Co 7/9/05/11 App

DOCKETED ITEMS

- 7906202005 Discusses sewage & ensure air sample min detectable limits for 2-20 & particulates
PORTER, S W Metropolitan Edison Co 79/05/11 3p
- 7906202021 Provides summary of activities while at TH1-2, for 790620-20 Critical of licensee's inability to provide accurate time estimates
ROTH, J Office of Inspection & Enforcement 79/05/11 2p
- 7906202026 Forwards list of health physics staff, as of 790502 WITH D H
Region 1, Philadelphia: Office of the Director 79/05/11 1p
- 7906202028 Forwards Amends DB & 43 to licensee 899-24 & 899-27, respectively, safety evaluation & notice of issuance & availability
SCHWENKER, A Operating Reactors Branch 1 Ofc 79062021 79/05/11 14p
- 7906202030 Amends DB & 43 to Licensee 899-24 & 899-27, respectively, requiring activation of safety injection, resulting opening logic for pressure/temperature operated relief valves & modifying power supplies
SCHWENKER, A Operating Reactors Branch 1 Ofc 79062021 79/05/11 14p
- 7906202037 Safety evaluation supporting Amends DB & 43 to Licensee 899-24 & 899-27, respectively
SCHWENKER, A Operating Reactors Branch 1 Ofc 79062021 79/05/11 3p
- 7906202038 Notice of issuance & availability of Amends DB & 43 to Licensee 899-24 & 899-27, respectively
SCHWENKER, A Operating Reactors Branch 1 Ofc 79062021 79/05/11 3p
- 7906202039 Notification of format for receipt of analytical data for AMI-5 capsule Forwards summary of radiocapabilities released in Susquehanna River 790620-0311
PORTER, S Porter-Davis Consultants, Inc 79/05/11 2p
- 7906202040 Discusses concern re vessel fracture in older operating plant following small break LOCA
KELLER, G Reactor Systems Branch 79/05/11 1p
- 7906202042 Discusses qualitative evaluation of failure potential of TH1-2 reactor vessel, made for work ending 790502 No indication of cracking or embrittlement
BERMAN, C Metallurgy & Materials Branch 79/05/11 1p
- 7906202047 Forwards "Preliminary Annotated Sequence of Events, Accident of 790508, Prepared by Data Rpt Reduction Group"
JESSE, J P GPU Service Corp 79/05/11 2p
- 7906202048 Forwards TH1-2 charcoal filtration eqpt data for use in evaluating charcoal efficiency data
MCCORMACK, T Effluent Treatment Systems Branch 79/05/11 7p
- 7906201048 Discusses actions required to TH1 liquid discharges & review (urgent instructions) re: loading & unloading of tanks & vessels being discharged
STONE, J P Region 1, Philadelphia: Office of the Director 79/05/14 3p
- 7906201053 Discusses discovery of radioactive mail at TH1 landfill Area is not likely & will be surveyed Lists actions required to resolve situation
STONE, J P Region 1, Philadelphia: Office of the Director 79/05/14 2p
- 7906201056 Assigns staff for TH1 Resident Ofc at TH1-2 Discusses schedule for assignments by other 12 regions
STONE, J P Region 1, Philadelphia: Office of the Director 79/05/14 2p
- 7906201057 Responds to 790510 among Part 20 licensees apply to possession & use rather than implementation or manipulation of waste eqpt
MILLER, M L GPU Service Corp 79/05/14 1p
- 7906201058 Submits design report for 790500
ROSS, D F Division of Project Management 79/05/14 3p
- 7906201060 Requests end to dumping of water from plant into Susquehanna River Physical & medical testing of populace is in jeopardy
WILSON, A B Lancaster, PA 79/05/14 1p
- 7906201067 Provides requested summary of activities while assigned to TH1-2 site
MCARDONNELL, D H Region 2, Atlanta: Fuel Facility & Materials Safety Branch 79/05/14 1p
- 7906201080 Confirms 790515 telcon w/ Helman & H. Reers TH1 training dept intends to resume licensed operator requalification program on 790520
MILLER, G P Metropolitan Edison Co 79/05/15 1p
- 7906201085 Discusses procedures for handling radioactive shipments from facility info partially withheld from telephone number
For FIA Extension at
STONE, J P Region 1, Philadelphia: Office of the Director 79/05/15 2p
- 7906201087 Provides info re activities while at TH1-2 site, per Bill Orier 790408 memo Critical of health physics function during early stages of incident
STONE, J P Region 1, Philadelphia: Fuel Facility & Materials Safety Branch 79/05/15 3p
- 7906201096 Discusses loss of TH1 radioactive waste shipments Requests specific info for each shipment contents, package type, transport company, destination & shipment coordinator
STONE, J P Region 1, Philadelphia: Office of the Director 79/05/15 2p
- 7906202036 Lists info needed for Wednesday meeting summary table of water releases, estimate of total volume released & increase in river water gress activity on result of TH1-2 event
VOLLMER, H H Assistant Director for Systems Engineering 79/05/15 2p
- 79070170 Discusses work BSA 790528 per indicating that BSA advised owners several months ago of need to observe both (pressure) level & RCB pressure to ensure SCS is filled
WATSON, M J Division of Project Management 79/05/15 2p
- 79070176 Forwards revisions to schedule for Westinghouse & C-E repts w/ scope of work, current licensing considerations, findings & recommendations
MAGNI, A C Reactor Systems Branch 79/05/15 2p
- 79070326 Discusses request for TH1-related actions by Ofc of Nuclear Regulatory Research Forwards form to be completed & returned
790517
JONES, J H H Administrative and Resource Control Staff, 7/5/15 1p
- 79070336 Provides summary of activities while assigned to TH1-2 site (memo on license & NRC operations)
GODDY, M H Region 2, Atlanta: Fuel Facility & Materials Safety Branch 79/05/15 2p
- 79070401 Provides summary of activities while assigned to TH1-2 site (memo on license & NRC operations)
MILLER, M L Region 2, Atlanta: Fuel Facility & Materials Safety Branch 79/05/15 2p

DOCKETED ITEMS

105

- 7904200029 Discusses 790401 telcons re potential for hydrogen explosions in vicinity of high humidity tank partially withheld some telephone number (over FOIA Exemption of 501(b)(7)(D)-H) Accident Analysis Branch 79/05/14 1p
- 7904200030 Notification of 790318 meeting w/WR & OR, in Bethesda, MD to discuss further work related to shield tank reaction damage
HARRIS, R. J. Systematic Evaluation Program Branch (Pfr 790402) 79/05/14 2pp
- 7904200037 Discusses hydrologic criteria for proposed interim solid waste storage area
COLLINS, J. Effluent Treatment System Branch 79/05/14 1p
- 7904200039 Provides summary of activities while assigned to TH-2 site. Conducts re licensee's 15/05/04 application
ZAVARONIS, M. H. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/14 2pp
- 7904200040 Provides summary of activities while assigned to TH-2 site. Comments on HRC applications
JAMES, F. Region 2, Atlanta, Office of the Director 79/05/14 2pp
- 7904200050 Forwards THH activities inventory forms re security items
BRADY, S. J. Division of Security 79/04/17 7pp
- 7904200060 Discusses failure of health physics personnel to monitor use of special operating procedure 7903 reactor side temp level measurement Area activity levels elevated
Region 1, Philadelphia, Office of the Director 79/05/17 1p
- 7904200068 Discusses conducting operation in accordance w/ licensee memo & directives rather than special procedures
MCGRATH, E. M. Office of Inspection & Enforcement 79/05/17 3pp
- 7904200082 Summary of 790311 & 15 meeting w/HRC & General Public. Utility to discuss design criteria layout & plot plan
COSTELLO, H. S. Gilbert Associates, Inc. 79/05/17 8pgs, r
- 7904200084 Discusses shift operation of HRC mobile lab. Forwards lab schedule & list of personnel qualified to operate lab
MOTTE, J. J. Region 1, Philadelphia, Office of the Director 79/05/17 2pp
- 7904200085 Discusses resolved issues re alternate decay heat removal system 790314-17 site visit. Task log analyzed by Westinghouse Penetration study being prepared
LITINSKI, R. Division of System Safety 79/05/17 2pp
- 7904200086 Forwards 790314 Inspector findings re changes to plant procedures resulting from HRC 790307 order. Procedures of order & operator understanding deemed adequate
MCQUEEN, H. G. Office of Inspection & Enforcement 79/05/17 3p
- 7904200088 Confirms procedural changes resulting from HRC 790307 order & operator understanding of changes
JAMES, F. Region 2, Atlanta, Office of the Director 79/05/14 1p
- 7904200089 Notification of 790301 meeting w/WR to discuss existing & small break analysis in C-6 & Westinghouse plants containing Exxon Fuel Distribution link email
HARRIS, R. J. Standardization Branch 79/05/17 2pp
- 7904200090 Requests receipt of all THH-related documents generated by Dept. of Nuclear Regulatory Research. All THH documents will be forwarded to FOIA of
SCHEIDT, M. H. Administrative and Resource Control Staff 79/05/17 1p
- 7904200094 Recommends heating coils not be installed in filter tracks serving Auxiliary & Feed Sides
MCQUEEN, H. G. CPU Service Corp. 79/05/17 2pp
- 7904200098 Suggests experiments to measure radioactive levels of contaminated water. Results of experiments will facilitate selection of procedure to clean up water
BRIDGES, M. H. CPU Service Corp. 79/05/17 1p
- 7904200101 Forwards "BAM 177 Fuel Assembly Owners' Group Asymmetric LOCA Leads Evaluation Program, Phase 2" & "BAM 177 Owners' Group Asymmetric LOCA Leads Evaluation, Phase 2"
MCNEIL, J. G. Westinghouse Edition Co. 79/05/17 1p
- 7904200102 "BAM 177 Fuel Assembly Owners' Group Asymmetric LOCA Leads Evaluations Program, Phase 2" & "BAM 177 Owners' Group Asymmetric LOCA Leads Evaluation, Phase 2"
Westinghouse Edition Co. 79/04/10 2pp
- 7904200029 "BAM 177 Fuel Assembly Owners' Group Assumptions, Methodology & Acceptance Criteria Report for Asymmetric LOCA Leads Evaluation, Phase 2"
Westinghouse Edition Co. BAM-1000 79/04/02 37pp
- 7904200049 Discusses shift operation of HRC mobile lab. Forwards BW 800403 790318 draft memo to reactor operators inspectors assigned to THH control room watch
MOTTE, J. J. Region 1, Philadelphia, Office of the Director 79/05/18 2pp
- 7904200050 Discusses insp of more safety equipment prior to return. B. W. requests insp for contamination
MCQUEEN, H. G. Region 1, Philadelphia, Office of the Director 79/05/18 1p
- 7904200052 Forwards still position re spent resin activation for shipping & burial to anticipation of new HRC requirement. Three vessel vessels of EPICOR 2 will be designed
MCQUEEN, H. General Public Utilities 79/05/18 1p
- 7904200079 Authorizes use of INEL personnel & equipment for THH source term measurement project. Forwards amended project brief, specifying no increase in funding
ARMSTRONG, F. J. Division of Safeguards, Fuel Cycle & Environmental Research 79/05/10 7pp
- 7904200083 Requests add info re THH safety-related equipment performance & exposure data to support of ongoing qualification testing evaluation research program
LITINSKI, R. Office of Nuclear Regulatory Research 79/05/18 2pp
- 7904200088 Summits daily digest for 790507
RBS, E. P. Division of Project Management 79/05/18 4pp
- 7904200092 Discusses results of preliminary review of data on BWR pressure reactor valve failure rate
TEDESCO, R. Assistant Director for Reactor Safety 79/05/18 2pp
- 7904200093 Recommends changes in plant operating conditions in order to reach further primary pressure limit for 200-2000 operation
CLARK, S. CPU Service Corp. 79/05/18 2pp
- 7904200094 Requests returning combustion turbine generators to normal economic dispatch. Precautionary measures not needed due to localization of low emergency diesel generators
ARMSTRONG, F. J. CPU Service Corp. 79/05/18 1p
- 7904200096 Accurates of new criteria for design of pressure vessels for EPICOR 2 qualification vessels will be HRC in anticipation of potential HRC requirement
MCQUEEN, H. G. CPU Service Corp. 79/05/18 1p
- 7904200098 Provides summary of activities while assigned to TH-2 site
BRADY, S. J. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/18 1p
- 7904200099 Discusses DOT safety insp of vehicles transporting THH radioactive waste
LITINSKI, R. Region 1, Philadelphia, Office of the Director 79/05/19 1p
- 7904200100 Concern w/790518 site suggesting relaxation of extra precautionary measures for area transmission system
COLLINS, J. Division of Operating Reactors 79/05/19 1p
- 7904200104 Requests to 790518 list re extra precautionary measures for area transmission system re THH Contamination of reactor
MULLER, R. H. Assistant Director for System Engineering 79/05/19 1p
- 7904200105 Suggests performance w/relaxation of extra precautionary measures taken to ensure reliable power supply to THH W/ email 790503 BW memo
ARMSTRONG, F. J. CPU Service Corp. 79/05/18 2pp
- 7904200106 Recommends add changes to current ECR pressure reduction
CLARK, S. CPU Service Corp. 79/05/19 1p
- 7904200108 Notifies of agreement to loan govt automobiles to DOT inspectors
SCHEIDT, M. H. Region 1, Philadelphia, Office of the Director 79/05/19 1p

DOCKETED ITEMS

- 7904010007 Forwards requested info re AMOR participation in TMI incident
KOSCHMIDT, R E Division of Fuel Cycle & Material Safety 79/05/21 12pp
- 7904010008 Forwards personal record of TMI-related activities for 790320-0401, in response to H Section 790424 memo
HACKSTADT, S H Reactor Systems Branch 79/05/21 8pp
- 7904010002 Forwards instructions for transcribing TMI interview & miscellaneous info for investigation procedures
GIBBONS, A J Region 1, Philadelphia, Office of the Director 79/05/21 13pp
- 790401013a Submits daily digest for 790301
KOSCH, S F Division of Project Management 79/05/21 3pp
- 7904010026 Provides requested summary of activities while assigned to TMI-2 site Comments on licenses & NRC operations
DANIELSON, R H Region 3, San Francisco, Office of the Director 79/05/21 3pp
- 7904010104 Forwards min environ survey team routine schedule Routine surveys will be made only on day shifts, beginning 790520
STONER, J F Region 1, Philadelphia, Office of the Director 79/05/22 3pp
- 7904010169 Discusses off-hour environ surveys w/reduced manpower
KOSCHMIDT, R E Division of Fuel Cycle & Material Safety 79/05/22 1p
- 7904010176 Requests six bumper/pagers needed to implement reduced manpower phase & ensure full coverage
STONER, J F Region 1, Philadelphia, Office of the Director 79/05/22 1p
- 7904010023 Forwards latest readings on equipment hatch & containment data Requests evaluation of data
COLLINS, J T Effluent Treatment System Branch 79/05/22 4pp
- 7904010070 Forwards update of preliminary annotated sequence of events of 790320 incident
KOSCHMIDT, R E Region 1, Philadelphia, Office of the Director 79/05/22 40pp
- 7904010071 Discusses and IC memo re surveillance test procedures for auxiliary or emergency feedwater test & actions resulting from TMI incident
KOSCH, S F Division of Project Management 79/05/22 3pp
- 7904010072 Discusses isolation of auxiliary or emergency feedwater during test Requests confirmation by 790520 re test procedures of Public understanding auxiliary or emergency feedwater test
KOSCHMIDT, R E Division of Reactor Operations Inspections 79/05/22 1p
- 7904010095 Discusses tentative ACBE schedules & interests Who June 1979 full committee meeting
KOSCHMIDT, R E Division of Project Management 79/05/22 3pp
- 7904010079 Summarizes visit by City of Lancaster, PA seeking injunction against construction of nuclear decommissioning facility & dumping info partially withheld
KOSCHMIDT, R E Region 1, Philadelphia, Office of the Director 79/05/22 3pp
- 7904010081 Describes continuing manpower needs for TMI Envrion Group
KOSCHMIDT, R E Region 1, Philadelphia, Office of the Director 79/05/22 3pp
- 7904020042 Notifies of form for reqs of analytical data for HPI & HPI-2 samples, Activities of radionuclides identified as different filters will be reported
PORTER, S H Reactor-Service Consultants, Inc 79/05/22 3pp
- 7904020083 Recommends purchase of automatic TLD sys for services & continuity at TMI
KOSCH, S F Region 1, Philadelphia, Office of the Director, 79/05/22 4pp
- 7904020195 Forwards data for discussion during ACBE redaction source
COLLINS, J T Effluent Treatment System Branch 79/05/22 3pp
- 7904020024 Discusses containment inc/leakage rate Average pressure decay is 0.04 per day
KOSCHMIDT, R E Office of Nuclear Reactor Regulation 79/05/22 3pp
- 7904020029 Forwards completed TMI activities inventory for both completed & ongoing Div of Nuclear Regulatory Research-related TMI activities
KOSCHMIDT, R E Administrative and Resource Control Staff 79/05/22 60pp
- 7904020133 Forwards Revision 2 of procedure 2-63-solid plant operations Revision reflects current plant operation
KOSCHMIDT, R E CPU Service Corp 79/05/22 14pp
- 7904020157 Forwards summary of 790516 meeting w/HQ & govt officials re Weymouth, PA re discharge of contaminated water into Susquehanna River
KOSCHMIDT, R E CPU Service Corp 79/05/22 1p
- 7904020188 Forwards liquid release info 790323-20
KOSCHMIDT, R E CPU Service Corp 79/05/22 2pp
- 7904030021 Notifies of discharge of 7,400 gallons of water on 790514 & 7,100 gallons of water on 790515 Water released as incident of mechanical draft cooling tower discharge bypassing waste treatment sys
KOSCHMIDT, R E Metropolitan Edison Co 79/05/24 2pp
- 7904030017 List of officials to contact re TMI info partially withheld same telephone numbers (ref FOIA Exemption d)
KOSCHMIDT, R E Metropolitan Edison Co 79/05/24 1p
- 7904030192 Summary of 790521 meeting w/HQ Bureau of Water Quality Agency & TMI radiological environ monitoring program organizational chart envl
PORTER, S H Metropolitan Edison Co 79/05/24 3pp
- 7904030176 Summary of 790521 meeting w/HQ re discuss TMI environ monitoring data, as requested by President's Commission
PORTER, S H Metropolitan Edison Co 79/05/24 1p
- 7904030042 Forwards ME Wallace ltr re chemical explosive hazard at TMI info partially withheld address and telephone numbers (ref FOIA Exemption d)
JONES, G L Pennsylvania, State of 79/05/24 3pp
- 7904030023 Forwards names to be added to 790402 list for radiation work permit training info partially withheld Social Security numbers (ref FOIA Exemption d)
SMITH, S H Office of Inspection & Enforcement 79/05/23 1p
- 7904030022 Forwards recommendations for possible changes to nuclear power plants in light of TMI incident
KOSCHMIDT, R E Division of Operating Reactors 79/05/23 7pp
- 7904030410 Discusses while body count of exposed individual Shin dose provided for beta & gamma radiation info partially withheld name & social security number (ref FOIA Exemption d)
KOSCHMIDT, R E Region 1, Philadelphia, Office of the Director 79/05/23 1p
- 7904030025 Provides info re activities while at TMI-2, for 790409-20
KOSCHMIDT, R E Region 1, Philadelphia, Office of the Director 79/05/23 1p
- 7904030178 Forwards projected TMI liquid release info for 790523-30
COLLINS, J T Effluent Treatment System Branch 79/05/23 3pp
- 7904030241 Discusses meeting of ME Resident Div at TMI-2 during nonoutine hours
KOSCHMIDT, R E Region 1, Philadelphia, Office of the Director 79/05/23 3pp
- 7904030287 Informs 790524 releases re Norton Landfill Best source of info is 0.5 g of RBE Envrion studies by Brown Univ students were greatly from RBE data
KOSCHMIDT, R E Region 1, Philadelphia, Office of the Director 79/05/23 3pp
- 7904030615 Submits daily digest for 790525 Forwards order re TMI records
KOSCH, S F Division of Project Management 79/05/25 3pp
- 7904030057 Orders preservation of all potential sources of data related to TMI incident
KOSCH, S F Inspecting & Services Branch 79/05/22 3pp

- 7904200203 Provides summary of activities while assigned to TH1-Q site comments on licenses & NRC operations
FRIDMAN, L Region I, Philadelphia, Office of the Director
79/05/25 2pp
- 7904200416 Provides summary of activities while assigned to TH1-Q site performed environ surveys
STERNBERG, C F Region I, Philadelphia, Office of the Director
79/05/25 1p
- 79042005161 Forwards NRC 790320 statement re use of EPILOGUE-IT sys at TH1 directs until not operate sys w/contaminated water
VALLBERG, R H Assistant Director for Systems Engineering 79/05/26 1p
- 790420071615 NRC to prepare environ assessment re proposals to decontaminate & dispose of contaminated waste water
Pending review/licenses should not operate EPILOGUE-IT Sys
CHILKOT, J Office of the Secretary of the Commission 79/05/17 2pp
- 790420071616 Provides guidance re priority in notifying individuals in case of significant gaseous or liquid release info partially withheld from telephone numbers (re: FOIA Exemption b1)
STERNBERG, C F Office of Inspection & Enforcement 79/05/26 4pp
- 790420071617 Recommends monitoring of TH1-Q equipment to measure effects of abnormal environ info would be available in equipment qualification effort
CHILKOT, J Plant Systems Branch 79/05/29 1p
- 79042008161 Forwards reply on oxygen & hydrogen production & recombination re flammability & detonation limits in containment
FRIDMAN, L Assistant Director for Advanced Reactor Safety Research 79/05/29 1p
- 79042010128 Responds to NRC info request re flammability & detonation limits for hydrogen & oxygen steam mixtures at elevated temps & pressures
FRIDMAN, L Assistant Director for Advanced Reactor Safety Research 79/05/29 2pp
- 79042010128 Responds to NRC info request re potential for oxygen accumulation in reactor vessel during TH1-Q accident
FRIDMAN, L Assistant Director for Advanced Reactor Safety Research 79/05/29 2pp
- 79042010129 "Evaluation of Radiolysis Associated With TH1-Q Incident" CONTINUED C. Mobile Atomic Power Laboratory. HOPKINS, D J. LORAN, E. Oak Ridge National Laboratory 79/05/31 10pp
- 79042010149 Discusses ACBS TH1 Subcommittee 790320-0601 meeting agenda re "Preliminary Discussion on Implications of TH1-Q for SAR" Forwards vignette to be used in presentation
WELTHER, C J Standardization Branch 79/05/29 10pp
- 79042020070 Discusses radiation & contamination survey of Breger respirators & associated equipment Re excessive direct radiation or transferable contamination found
STERNBERG, C F Region I, Philadelphia, Office of the Director 79/05/30 1p
- 79042020070 Forwards procedure for adjusting reactor high steam water pressure gauges to suppl procedure-3-002 Column of water must not exist in instrumentation line during zero adjustment.
MOORE, J P CPU Service Corp 79/05/30 2pp
- 79042010150 Forwards 790320 memo & Apr 1979 monthly rept on TH1 studies re nonradiological aquatic & water quality data for Susquehanna River
HECHER, C M Environmental Specialists Branch 79/05/30 1pp
- 79042010151 Forwards Apr 1979 monthly progress rept of TH1 aquatic study.
WANDER, G A Ichthyological Associates, Inc. 79/04/30 1p
- 79042010152 Monthly rept of TH1 aquatic study Apr 1979
WANDER, G A Ichthyological Associates, Inc. 79/04/30 20pp
- 7904190704 "Population, Use & Health Impact of Accident at TH1 Nuclear Station/Preliminary Estimates Prepared by Ad Hoc Interagency Task Assessment Group." re 790320-0407.
WELSH, C Environmental Protection Agency, NELSON, M Health, Education & Welfare, Dept of ROSENSTEIN, M. H&M Dept of Plant & Drug Administration. NUREG/CH-0558 79/05/31. 103pp Available at NRC
- 79042005161 Submits outline of radiological investigation rept
SILVER, A Region I, Philadelphia, Office of the Director
79/05/31 1p
- 79042005162 Submits list of topics than Accident Analysis Branch recommends for inclusion in "Lessons Learned" activity
HOLSTON, R H Accident Analysis Branch 79/05/31 2pp
- 79042005163 Discusses replacement of Helirapillon Edwin deindekist at TH1
SILVER, A Region I, Philadelphia, Office of the Director
79/05/31 1p
- 79042005167 Summary of 790330 briefing in Washington, DC re TH1-Q Incident response program & status of improvements at facility
CHILKOT, J Office of the Secretary of the Commission 79/05/31 1p
- 79042005168 Summary of 790405 meeting w/ACBS in Washington, DC re scope & timing of ACBS annual rept on NRC safety research program
CHILKOT, J Office of the Secretary of the Commission 79/04/05 1p
- 79042005167 "1-104 Renewal Efficiency Determination of Adsorbent Samples" DEUTER, C D, KAVACH, J L. Nuclear Consulting Services, Inc 79/05/31 2pp
- 79042005168 Requests meeting to identify engineering evaluations of TH1 incident
HATFIELD, J Division of Systems Safety 79/05/01 2pp
- 79042005167 Authorizes review of hands-on search for members of Congressional Subcommittee on Natural Resources & Environ during 790405 plant tour
VALLBERG, R H Assistant Director for Systems Engineering 79/04/01 1p
- 79042005167 Agrees for technical working group & planning meetings re TH1-Q for 790405-0601
Office of Nuclear Reactor Regulation 79/04/01 40pp
- 79042005167 Makes recommendations for reestablishing natural circulation at facility in event of loss of loss of natural circulation gives results of calculation performed
NELSON, M H Analysis Branch 79/04/01 2pp
- 79042005168 Forwards invoice from Radiation Mgt Corp for environ dosimetry & waste body counting for 790320-0430 Request
VALLBERG, R H Division of Accounting 79/04/01 2pp
- 79042005168 Requests complete review of TH1 data collected to date by all Data Reduction & Mgt Group
CORRELL, R K Office of the Executive Director for Operations 79/04/01 1p
- 79042005168 Comments on proposed TH1 radiation protection plan. Licensee should provide organization chart to reflect change of command & commitment to ALARA program
HOPKINS, D J Division of Site Safety & Environmental Analysis 79/7

DOCKETED ITEMS

- 7704130415 Evacuation security arrangements for East-West Towers due to round-the-clock warning of NBC operations cfr in support of activities at TH1
7704090500 E Office of J & E Executive Officer for Operations
Report 7/5/04/06 2pp
- 7704130416 President interim guidance for TH1 investigators
7704090500 E Office of Inspection & Enforcement 7/5/04/06 3pp
- 7704130416 Successes learned from TH1-2 incident re release of iodine & hydrogen sulfide from containment elements more easily released than previously thought
7704090500 E Accident Analysis Branch 7/5/04/07 6pp
- 7704090455 Forwarded "Supplementary Startup Rept."
7704090500 E Metropolitan Edison Co 7/5/04/11 1p
- 7704090455 Forwarded "Supplementary Startup Rept."
7704090500 E Metropolitan Edison Co 7/5/04/11 10pp
- 7704090455 Forwarded update of comments resulting from TH1 incident made by DOE on behalf of operating plant customers
7704090500 E Babcock & Wilcox Co 7/5/04/13 6pp
- 7704090423 Contract "Conduct of Special Inquiry into the Incident."
7704090500 E Division of Contracts FEN B-1360 7/5/04/13 40pp
- 7704090507 Forwarded Sandia Lab TH1008 1st & 2nd re contingency waste-filter for TH1-2 reactor
7704090500 E Probabilistic Analysis Branch 7/5/04/13 1p
- 7704090502 Submit add info to TH1013 presentation re contingency waste-filter for TH1-2 reactor
7704090500 E Sandia Laboratories 7/5/04/13 21pp
- 7704090503 Lists goals of TH1-2 investigation discussed 7704130415 evaluation factors regarding incident & evaluate performance of licensee as basis for corrective action
7704090500 E Office of Inspection & Enforcement 7/5/04/20 8pp
- 7704090504 Mod I-revising accounting & appropriation data to MRC-10-70-421 Contract number is hereafter changed to MRC-10-70-421
7704090500 E Division of Contracts 3-1350 7/5/04/20 1p
- 7704090505 Forwarded input to TH1008 request for info re TH1-2 activities
7704090500 E Program Coordination Branch 7/5/04/15 1p
- 7704090504 Advances of TH1001 inciting coils at Incident Response Center
7704090500 E Division of Safeguards 7/5/04/15 1p
- 7704090505 Forwarded input to TH1008 request re TH1-2 activities
7704090500 E Probabilistic Analysis Branch 7/5/04/15 1p
- 7704090507 Submit TH1001 record of action in determining requirements for emergency response action assuming core melt accident would occur
7704090500 E Probabilistic Analysis Branch 7/5/04/21 13pp
- 7704090509 Responds to TH1013 request for add info re TH1 activities
7704090500 E Division of Safeguards 7/5/04/21 3pp
- 7704090510 Responds to TH1013 request re record of actions in TH1 Incident Advances re Involvement
7704090500 E Probabilistic Analysis Branch 7/5/04/21 1p
- 7704090512 Responds to TH1013 memo from LV Division re recording actions taken on TH1 incident Subdivisions questions related to sgs operations & backstop/contingency provisions
7704090500 E Probabilistic Analysis Branch 7/5/04/21 1p
- 7704090514 Advances investigations w/TH1 incident included weldment analysis, natural circulation/boiler and cooling analysis & containment waste-filtering assessment
7704090500 E Probabilistic Analysis Branch 7/5/04/21 2pp
- 7704090516 Responds to TH1013 memo re TH1-2 activities involved in research project manager & coordinator of info between
7704090500 E Environmental Effects Research Branch 7/5/04/21 2pp
- 7704090519 Responds to TH1013 memo re TH1-2 activities Naval Research Lab analyzing characteristics of activated charcoal IHL staff mobile lab
7704090500 E Division of Safeguards 7/5/04/21 1p
- 7704090521 Advances E Safeguards performed clinical duties 770403-0507
7704090500 E Division of Safeguards Fuel Cycle & Environmental Research 7/5/04/14 1p
- 7704090522 Responds to TH1013 memo re TH1-2 activities Subdivisions description of clinical duties performed 770404-0521
7704090500 E Assistant Director for Operations & Evaluations 7/5/04/14 1p
- 7704090523 Comments on Lessons Learned Task Force item 13 protection of containment should not be inhibited by any "legal constraints" of BSA theology
7704090500 E Reactor Systems Branch 7/5/04/15 1p
- 7704090524 Forwarded "Second Interim Rept on TH1-2 Incident"
7704090500 E Metropolitan Edison Co 7/5/04/15 1p
- 7704090525 "Second Interim Rept on TH1-2 Incident"
7704090500 E Metropolitan Edison Co 7/5/04/15 10pp
- 7704090526 Summary of TH1013 meeting w/DOE, EIC & OIC of Nuclear Reactor Regulation re actions now being taken by industry in response to TH1-2 incident
7704090500 E Assistant Director for Reactor Safety 7/5/04/15 1p
- 7704090527 Discusses need to determine adequacy of portable radiation survey instruments as indicator of gamma exposure rates due to ambient cloud of I-133 resulting from TH1
7704090500 E Region 1, Philadelphia Office of the Director 7/5/04/19 1p
- 7704090528 Discusses new personnel handling requirements for TH1
7704090500 E Region 1, Philadelphia Office of the Director 7/5/04/19 1p
- 7704090529 Notification info requested by TH1008 1st re adequacy of station electric distribution bus voltage will be provided by TH1001
7704090500 E Metropolitan Edison Co 7/5/04/25 1p
- 0 Inspection reports, IE Bulletin & correspondence
- 7704090539 Forwarded Insp plan IP-1, "Insp Requirements to Review License Actions Taken in Response to Nuclear Incident at TH1" Plan to be implemented immediately in State of PA
7704090500 E Region 1, Philadelphia Reactor Operations Nuclear Support Branch 7/5/04/11 7pp
- 7704090544 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090545 Forwarded IE Insp Repts TH1-059/77-00 & TH1-059/77-07 on TH1013-02 & 06 No noncompliances noted
7704090500 E Region 1, Philadelphia Reactor Operations Nuclear Support Branch 7/5/04/20 2pp
- 7704090546 IE Insp Repts TH1-059/77-00 & TH1-059/77-07 on TH1013-20 & 26 No noncompliances noted
7704090500 E Region 1, Philadelphia Reactor Operations Nuclear Support Branch 7/5/04/20 2pp
- 7704090547 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090548 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090549 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090550 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090551 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090552 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090553 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090554 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090555 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090556 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090557 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090558 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090559 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090560 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090561 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090562 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090563 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090564 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090565 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090566 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090567 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090568 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090569 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090570 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090571 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090572 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090573 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090574 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090575 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090576 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090577 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090578 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090579 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090580 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090581 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090582 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090583 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090584 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090585 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090586 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090587 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090588 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090589 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090590 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090591 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090592 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090593 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090594 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090595 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090596 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090597 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090598 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp
- 7704090599 Responds to IE Bulletin TH1-054 Forwarded info re review of operating procedures
7704090500 E Departmental Municipal Utility District 7/5/04/16 7pp

7905295241 Responds to IE Bulletin 79-08 Forwards results of review of P&ID eqp designs & operational procedures
POLAK, J.M. Nebraska Public Power District 79/05/23 App

7905295242 Requests clarification of requirement for "Verification of Corrosibility" from IE Bulletin 79-08
MILLIAMS, F.J. Division of Project Management 79/04/27 Ip

7905295243 Responds to IE Bulletin 79-08 Forwards info re review of THI Incident Existing line isolation not important to EOS Injection
ROSEN, G. Commonwealth Edison Co 79/04/27 22pp

7905295244 Responds to IE Bulletin 79-08 re events relevant to RMB identified during THI Incident
CRNEP, S.A. Pacific Gas & Electric Co 79/05/01 5pp

7905295245 Responds to IE Bulletin 79-08 Forwards info re procedures & methods for maintaining natural circulation
MATTIOLLO, J.J. Sacramento Municipal Utility District 79/05/02 4pp

7905295246 GC procedure 307-H-012 for final acceptance insp & CPU Services Corp 79/05/04 22pp

7905295247 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Isolation Support Problem." No action required
GRUBB, B.H. Region 1, Philadelphia, Office of the Director 79/05/07 2pp

7905295248 Urges more conservative 3-loop requirement by keeping only one reactor coolant pump in operation; IE Bulletin 79-08
MILLIAMS, F.J. Division of Project Management 79/05/07 Ip

7905295249 Requests review of encl C-4 790420 response to IE Bulletin 79-08 re THI-related matters
ROSEN, G.F. Division of Project Management 79/05/08 27pp

7905295250 Requests criteria for continued operation of charging pump
MILLIAMS, F.J. Division of Project Management 79/05/08 Ip

7905295251 Recommends that ORC study potential use of nuclear instrumentation source & interconnect to determine existence of void re IE Bulletin 79-08; Revision 1
MILLIAMS, F.J. Division of Project Management 79/05/08 Ip

7905295252 Requests establishing requirement for zero thermocouples per IE Bulletin 79-08
MILLIAMS, F.J. Division of Project Management 79/05/07 Ip

7905295253 Requests info re consideration given to possible pressure spikes in ice condenser containment plants per IE Bulletin 79-08; Revision 1
MILLIAMS, F.J. Division of Project Management 79/05/09 Ip

7905295254 Forwards "Operation Plan for IE Resident Ofr at THI-2"
GRUBB, B.H. Region 1, Philadelphia, Office of the Director 79/05/11 5pp

7905295255 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
GRUBB, B.H. Region 1, Philadelphia, Office of the Director 79/05/11 Ip

7905295256 Forwards IE Region IV evaluation of licensee response to IE Bulletin 79-08
WYBICK, S.A. Light Water Reactors Branch 4 79/05/11 Ip

7905295257 Evaluates licensee 790504 response to IE Bulletin 79-08 re revision of procedures for natural circulation & registered safety features action
ROSEN, G.F. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/10 2pp

7905295258 Forwards response to IE Bulletin 79-08 re revisions of procedures & training apparatus personnel on establishing & maintaining natural circulation
TRINICK, G.C. Arkansas Power & Light Co. 79/05/04 Ip

7905295259 Responds to IE Bulletin 79-08 Forwards info relevant to design of RMB & events surrounding THI Incident
BUDWART, W.P. Florida Power Corp. 79/05/12 10pp

7905295260 Notices of licensee procedures for radioactive shipments
GRUBB, B.H. Region 1, Philadelphia, Office of the Director 79/05/10 Ip

7905295261 Discusses licensee response to IE Bulletin 79-08; Revision 1 & recommends not consider assessing current licensee operator understanding of THI Incident
MILLIAMS, F.J. Division of Project Management 79/05/10 Ip

7905295262 Discusses procedure for coordinating DOT safety insp of vehicles transporting THI radioactive info partially withheld from telephone numbers (ref RMA Evaluation A)
SLOAN, J.P. Region 3, Philadelphia, Office of the Director 79/05/16 2pp

7905295263 Discusses licensee response to IE Bulletin 79-08, "Review of Operational Errors & Key Misalignments Identified During THI Incident"
WYBICK, S.A. Light Water Reactors Branch 4 79/05/16 Ip

7905295264 Submits update to 790404 response to IE Bulletin 79-08; Revision 1 re Drilling of Pressurizer Water Level Bistables & resulting of containment isolation
GOSWAMI, S. Portland General Electric Co 79/05/04 2pp

7905295265 Notices of IE procedures for handling Metropolitan Edison Co correspondence
Office of Inspection & Enforcement 79/05/17 2pp

7905295266 Forwards licensee response to IE Bulletin 79-08
WYBICK, S.A. Light Water Reactors Branch 4 79/05/17 Ip

7905295267 Responds to IE Bulletin 79-08; Revision 1 re revision of emergency procedures for coping w/aircrafts & accidents
WACHNER, L.J. Northern States Power Co 79/05/10 7pp

7905295268 Forwards IE Circular 79-08, "Attempted Extortion - Law Enforced"
GRUBB, B.H. Region 1, Philadelphia, Office of the Director 79/05/10 Ip

7905295269 Discusses duties of reactor operations inspectors assigned to THI control room watch facilities requirements of operation plan
GOSWAMI, S.W. Region 1, Philadelphia, Office of the Director 79/05/18 2pp

7905295270 Forwards draft IE circular clarification of requirements for procurement processing & distribution of pharmaceuticals for human use
Office of Inspection & Enforcement 79/05/18 2pp

7905295271 Forwards info re manual trip on low pressurizer level; as stated in case of IE Bulletin 79-08
MILLIAMS, F.J. Division of Project Management 79/05/18 2pp

7905295272 Forwards modified "Schedule for Personnel Assignments, Region II-IV" re IE Resident Ofr at THI-2
GRUBB, B.H. Region 1, Philadelphia, Office of the Director 79/05/20 3pp

7905295273 Reviews main activities & equipment likely to have affected THOCS event
FABIAN, B.R. Region 1, Philadelphia, Office of the Director 79/05/21 2pp

7905295274 Lists IE Bulletin issued after THI Incident which have been withheld due to lack of available utility resources
GRUBB, B.H. Region 1, Philadelphia, Office of the Director 79/05/20 2pp

7905295275 Periodic operating reports & related correspondence

7905295276 Discusses long-term environ radiation monitoring as THI & designates EPA as lead agency for radioactive exposure estimates from DOE & Savannah Hall Labs.
MATTSON, J.C. President of DOE & Executive Offices 79/04/10 10pp

7905295277 Forwards "THI Aquatic Study," monthly rept for Jan/Feb & March 1979; received in response to requests for nonradiochemical associated data 790504 encl.
HICKNEY, C.R. Environmental Specialists Branch 79/05/03 Ip

7905295278 Forwards "THI Aquatic Study," monthly rept for Jan/Feb & Mar per MRC 790414 request forwarding 1tr from Ichthyological Associates, Inc.
WYBICK, S.A. Metropolitan Edison Co 79/04/16 2pp

7905295279 "THI Aquatic Study," monthly rept for Jan 1979 by Ichthyological Associates, Inc.
Metropolitan Edison Co 79/01/31 54pp

DOCKETED ITEMS

--7906290DIO "TMI Aquatic Study," monthly rep9 for Feb 1979 by
Ecophysiological Associates, Inc
+ Metropolitan Edison Co 79/02/28 17pp

==79062908i: "TMI Aquatic Study," monthly rept for Mar 1979 by
[pathological Associates, Inc
HARDWARE, © A Metropolitan Edison Co 79/03/31 8pp

7904300472 Update of TMI-2 calculations re 790423-26 damage to Zircaloy
fuel rod cladding in core
PICKLESIMER, H Division of Reactor Safety Research 79/03/04
1400

7906200254 "THE Desimetry Project Rept For Data Collected 790331-0418 "
 * HEN:Dept of: Food & Drug Administration 79/09/97 20pp

7966260316 Forwards daily key word in context index from Data Reduction
& Hgt Group
WEBSTER, J L GPU Service Corp 79/05/16 277

7906260343 Forward graph depicting containment in-leakage rate
790462-0520
80081084.5 Commission 79/05/20 Doc

790622D1Z6 Forward's preliminary soils data & soil boring logs
WILKINSON TONCO Goldwert Associates, Inc. 79085/95 25m

7906200429 "Status of THI Offsite Emergency Radiological Review
Monitoring Program." 790503-30
SBN72.9 H Parker-Garis Consultants, Inc 79/05/30 75pp

5 Reportable occurrences, LORs & related correspondence

7906220222 Subjects summary of events 790328-790410 within Middletown
Police Dept dealing w/incident at THJ
HILLER, D M Middletown, PA 79/04/10 app

796229026 Forwards noncompliance rept re pneumatic attestors &
colonyid accessories which may not conform to spec
Investigation under way to determine similar values
KRAUSE, R W GH Bettele Corp 795/04/11 4pm

790504038V Forwards PHO-79-07AL:AD & AS per IRC 790400 Ue trans
IE Bulletin 79-03
ENGLAND, R H Region 5, San Francisco, Office of the Director
79/04/30 3p

7906220199 Unexecuted draft of notice of 790322 nuclear incident at
the
CHOLE, R J Office of the Secretary of the Commission 79/05/02

79DAG60178 FWD-79-ATM(Corrected) summary of info re nuclear incident
44 of 790914 Describes plant status & environ status
PAULUS, R C, THEPSON, B Office of Inspection & Enforcement
79/05/14 2aa

790619053E Forwards "Interim Rept on TKI-2 Accident"
HONOLULU-J O Hattogalusa Edises Co 79/03/15 10

7704150925 "Miracle Report on TWS-2 Accident"
 * Metropolitan Edison Co 7/23/13 20ppp

7706060101 PWD-79-5742 summary of info re nuclear incident at 7705231. Describes plant status & emergency status. Highest income temp reading was 303 F. Leaks identified & are being corrected in Loop A.

PAUL R C E 7706060101 Office of Inspection & Enforcement
 7/25/52 2pp

790606Z197 PHO-79-67AP summary of info re nuclear incident as of 790820. Describes plant & environ status investigation under way to determine if death of cows was caused by radiation. FLACK, E. S., CIVILIAN. HAMIL J. MIDLAND. Office of Inspect Enforcement 79/05/20, 2pp.

790600061 PWD-79-6740 summary of info re nuclear incident as of 790628. Describes plant & enviro status, employee radiation levels consistent w/natural levels. PWSLUS, C. C. THOMPSON, D. Office of Inspection & Enforcement 790600062. Doc

770622013Z PWD-79-676N summary of info re nuclear incident at
770604 Describes plant status & environ status. Average
coolant temp 157 F
PAULUS,R.C. , THOMPSON,G Office of Inspection & Enforcement
79/06/04, Zee

7906270001: FHO-79-6745 summary of info re nuclear incident as of
790611; Describes plant & environ status Highest incore
thermocouple reading is 380 F
PAULUS, E C Office of Inspection & Enforcement 79/06/11 20

7906270007 PHO-79-67AF summary of info re nuclear incident as of
790616 Describes phase 3 emission status Highest incere
thermocouple reading 273 F
PUBLISH 0 0 Office of Inspection & Enforcement 79/06/10 Da

790280040 Requests info re hydrogen explosion at THS-2
MILITARY, H C Division of Systems Safety 09/06/10

7906200045 Comments on constructive changes to regulatory requirement
for nuclear power plants insalage of reactor vessel water
level & gas bubble dispersion need addressing
WUJINGCHEN, K C Reactor System Standards Branch 79/06/18 14

T Hearing transcripts re non-adversely affected.

7906070012 Forensic transcript of 790405-04 & 09 closed meetings info partially withheld staff and scope of Commission sponsored investigation (ref FOIA Exemption b) BIRMINGHAM, Office of the General Counsel 79/04/17 Bun

7906230168 Summary of 790417 meeting w/ACRS in Washington, DC re TMI Pa
335-466
ACRS - Advisory Committee on Reactor Safeguards 79/06/17

7704370027 Parwade draft cover sheet explaining legal & factual background of TH1 mapping transmittals info pertaining to/related draft cover sheet (ref FOIA Exemption B1)
BIDMUT.L, Office of the General Counsel 7/20/10 10

7905201014 Transcript of 790587 public meeting in Washington, DC re
focusing on facts of TMI operational sequence Pg 1-100
Informal operational sequence of events at 790508 and
IN0508E, J H, GILBERT, V, REDNEED, R ? Commission 79/03/17
663pp

7906210014 Forwards site procedures for handling transcript files as
SRI
#INCOM T Office of Inspector & Auditor 79/05/24 Sg

PW061007A Transcript of ACRS Ad Hoc Subcommittee on TH1-2 Accident
 Implications PW06031 meeting in Washington, DC Pg. 1-280
 ORRNT, D., CARROLL, R. W., ETHERINGTON, H. ACRS - Advisory Committee on
 Reactor Safeguards 79/05/21 051pg

7906180324 Transcript of Ad Hoc Subcommittee on TSI-2 Accident
Implications 790601 meeting in Washington, DC Pg. 381-700
Supporting documentation encl
ORIENT. D. CAPRIGLIA W. STEPHENSON, H. ADRE - Advisory Committee o
Reactor Safeguards 79/06/01 400pp

7904102214 Transcripts of ACRB Subcommittee on TH-2 790426 meeting
in Middletown, PA Pg 8-192
CARSON, M. W., LAMBERS, D., BENDER, M. ACRB - Advisory Committee on

7906150234 Transcript of ACRS Subcommittee on TH-2 790607 meeting
in Middletown, Pa. Pg. 193-400
CARROLL, H. W., LAWRENCE, J. B., BENSON, R. ACRS - Advisory Committee on
Reactor Safeguards 79/06/07 200pp

7706180875 Statement by UK Davis, vice-president of Natl Acad of Engineering, re the incident
DAVID M K National Academy of Engineering 74/06/13 6p

U Congressional/Executive Correspondence

7906060196 Forwards Resolution of Inquiry by Representative J Weaver directing ABC to provide Congress w/complete info on THI incident. Weaver's photo release re resolution encl
JUNTERD.C Office of Congressional Affairs 29/06/02 3pg

7906250002 Forward draft interim response to Congress re THE Incident
MEMPHIS, A. Office of Policy Evaluations. 79/04/04 Doc

7906060044 Forwards TH1-related LGRs & weekly operating expn per
790405 telcon re Senator Mark 790403 ltr
H888016, F U Office of Nuclear Reactor Regulation 79/06/03 i

79D606094 Forward draft of JM Hendrix 79D410 statement for
Subcommittee on Nuclear Regulation of Senate Committee on
Environment & Public Works Requests comment. W/o encl
HARRIS, C Office of Congressional Affairs 79/04/04 10

DOCKETED ITEMS

111

7004150231 Transcript of 7/10/10 hearing before Senate Subcommittee on Nuclear Regulation re: TMI incidents Pg. 1-102
HARRIS, J. H. Committee: HARRY, D. HARRIS, D. Senate: Environment & Public Health 7/10/10 10pg

7004150232 Links comprehensive to be notified in case of unexpected TMI events if not partially withheld home telephone numbers (v)
FDR: Exemption of
HARRIS, D. Office of Congressional Affairs 7/10/10 2pg

7004150233 Forwarded (v) 7/10/10 "Nuclear Power TMI Accident & its Investigation"
HARRIS, D. H. Library of Congress 7/10/10 1p

7004150234 Issue Brief 7/10/10: "Nuclear Power TMI Accident & its Investigation"
HARRIS, D. H. Library of Congress 7/10/10 3pg

7004150235 Forwarded 1980 population distribution for 0-10 miles from TMI in response to 7/10/10 TMI nuclear safety & waste storage press release and
CLINTON, M. J. Division of Fuel Facilities & Materials Safety 7/10/10 2pg

7004150236 Discusses congressional task force created to investigate TMI-2 incident hearings will address TMI-2 nuclear safety & waste storage press release and
HARRIS, D. Office of Congressional Affairs 7/10/10 3pg

7004150237 Transcript of Task Force on TMI accident hearing before Committee on Interior & Insular Affairs re: TMI-2 in Washington, DC Pg. 1-10
HARRIS, D. H. House of Rep., Interior & Insular Affairs 7/10/10 1pg

7004150238 Transcript of task force on TMI accident hearing before Committee on Interior & Insular Affairs re: TMI-2 in Washington, DC Pg. 1-10
HARRIS, D. H. House of Rep., Interior & Insular Affairs 7/10/10 1pg

7004150239 Transcript of Task Force on TMI accident hearing before Committee on Interior & Insular Affairs re: TMI-2 in Washington, DC Pg. 1-10
HARRIS, D. H. House of Rep., Interior & Insular Affairs 7/10/10 1pg

7004150240 Transcript of task force on TMI accident hearing before Committee on Interior & Insular Affairs re: TMI-2 in Washington, DC Pg. 1-10
HARRIS, D. H. House of Rep., Interior & Insular Affairs 7/10/10 1pg

7004150241 Transcript of ASER Ad Hoc Subcommittee on TMI-2 Accident implications 7/10/10 meeting in Washington, DC Pg. 1-10
HARRIS, D. H. House of Rep., Interior & Insular Affairs 7/10/10 1pg

7004150242 Forwarded list of upcoming Congressional hearings & calendar of nuclear accident & TMI hearings
HARRIS, D. Office of Congressional Affairs 7/10/10 1pg

7004150243 Discusses agenda of USGI committee investigation/hearings into TMI accident & nuclear safety issues
HARRIS, D. Office of Congressional Affairs 7/10/10 1pg

7004150244 Summary of 7/10/10 meeting w/USC & govt officials in Harrisburg, PA to discuss discharge of contaminated water from plant into Susquehanna River
HARRIS, D. L. Pennsylvania, State of 7/10/10 1pg

7004150245 Response to 7/10/10 TMI-2 HRC action following TMI-2 incident, initial actions included review of possible genetic problems.
HARRIS, D. H. Commission 7/10/10 1pg

7004150246 Forwarded proposed response to 7/10/10 TMI-2 HRC action & local capabilities to cope w/ nuclear nuclear accident
HARRIS, D. H. Office of State Program 7/10/10 1pg

7004150247 Summary of 7/10/10 TMI-2 HRC action & local capabilities to cope w/ nuclear nuclear accident
HARRIS, D. H. Office of State Program 7/10/10 1pg

7004150248 Forwarded C. Nicholson Jan 1978 summary of "Reactor Heat Removal During Very Small Break LOCA for BWR 203-PWR Assembly"
HARRIS, D. H. Division of Operating Reactors 7/10/10 1pg

7004150249 Draft "Reactor Heat Removal Problem Associated w/Reactor Heat Removal Break LOCA for Combustion Engineering S/S BWR"
HARRIS, D. H. Division of Operating Reactors 7/10/10 1pg

7004150250 Notifies that transcript of HRC discussion are not ready & will be sent when available
HARRIS, D. Office of Congressional Affairs 7/10/10 1pg

7004150251 Statement of M. Waller before House Subcommittee on Natural Resources & Environment
WALLER, M. H. Assistant Director for Site Analysis 7/10/10 2pg

7004150252 Statement of R. C. Clusen before House Subcommittee on Natural Resources & Environment
CLUSEN, R. C. Energy/Dept of 7/10/10 1pg

7004150253 Statement of G. H. Bretthorn before House Subcommittee on Science & Technology
BRETTHORN, G. H. Environmental Protection Agency 7/10/10 1pg

7004150254 Forwarded notes of witnesses & participants for Subcommittee on Natural Resources & Environment 7/10/10 meeting
HARRIS, D. H. Science & Technology 7/10/10 2pg

7004150255 Testimony before Subcommittee on Natural Resources & Environment of House Science & Technology Committee re: 7/10/10
HARRIS, D. H. House of Rep., Science & Technology 7/10/10 2pg

7004150256 Response to 7/10/10 TMI-2 HRC action & local capabilities to cope w/ nuclear nuclear accident
HARRIS, D. H. Division of Operating Reactors 7/10/10 1pg

7004150257 Response to 7/10/10 TMI-2 HRC action & local capabilities to cope w/ nuclear nuclear accident
HARRIS, D. H. Division of Operating Reactors 7/10/10 1pg

7004150258 Response to 7/10/10 TMI-2 HRC action & local capabilities to cope w/ nuclear nuclear accident
HARRIS, D. H. Division of Operating Reactors 7/10/10 1pg

7004150259 Response to 7/10/10 TMI-2 HRC action & local capabilities to cope w/ nuclear nuclear accident
HARRIS, D. H. Division of Operating Reactors 7/10/10 1pg

7004150260 Response to 7/10/10 TMI-2 HRC action & local capabilities to cope w/ nuclear nuclear accident
HARRIS, D. H. Division of Operating Reactors 7/10/10 1pg

7004150261 Response to 7/10/10 TMI-2 HRC action & local capabilities to cope w/ nuclear nuclear accident
HARRIS, D. H. Division of Operating Reactors 7/10/10 1pg

7004150262 Response to 7/10/10 TMI-2 HRC action & local capabilities to cope w/ nuclear nuclear accident
HARRIS, D. H. Division of Operating Reactors 7/10/10 1pg

7004150263 Response to 7/10/10 TMI-2 HRC action & local capabilities to cope w/ nuclear nuclear accident
HARRIS, D. H. Division of Operating Reactors 7/10/10 1pg

7004150264 Response to 7/10/10 TMI-2 HRC action & local capabilities to cope w/ nuclear nuclear accident
HARRIS, D. H. Division of Operating Reactors 7/10/10 1pg

7004150265 Response to 7/10/10 TMI-2 HRC action & local capabilities to cope w/ nuclear nuclear accident
HARRIS, D. H. Division of Operating Reactors 7/10/10 1pg

7004150266 Response to 7/10/10 TMI-2 HRC action & local capabilities to cope w/ nuclear nuclear accident
HARRIS, D. H. Division of Operating Reactors 7/10/10 1pg

7004150267 Response to 7/10/10 TMI-2 HRC action & local capabilities to cope w/ nuclear nuclear accident
HARRIS, D. H. Division of Operating Reactors 7/10/10 1pg

7004150268 Response to 7/10/10 TMI-2 HRC action & local capabilities to cope w/ nuclear nuclear accident
HARRIS, D. H. Division of Operating Reactors 7/10/10 1pg

7004150269 Response to 7/10/10 TMI-2 HRC action & local capabilities to cope w/ nuclear nuclear accident
HARRIS, D. H. Division of Operating Reactors 7/10/10 1pg

DOCKETED ITEMS

7906140001 Ack receipt of IE Insp Rpts 30-321/79-10 & 30-366/79-12 on 7/20/81-0316 No preliminary info
STAFFA.R.H. Georgia Power Co 7/20/81 1p

6 Inspection reports, IE Bulletin & correspondence

7906140028 Forwarded IE Insp Rpts 30-321/79-10 & 30-366/79-12 on 7/20/81-0316 No noncompliance noted
LEWIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 7/20/81 2pp

7906140073 IE Insp Rpts 30-321/79-10 & 30-366/79-12 on 7/20/81-0316 No noncompliance noted Major areas inspected IE Circumstances & Auditing, L&S & following of personnel, Fuel Findings
HIVK.W.D. Region 2, Atlanta, Office of the Director
DANCE.T. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 7/20/81 2pp

7906140426 Responded to IE Bulletin 79-07 Discusses demagnet program used in class analysis of safety-related piping
STAFFA.R.H. Georgia Power Co 7/20/81 2pp

7906140443 Forwarded IE Circular 79-07, "Unapproved Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase" to IE without response required
O'BRIEN.J.P. Region 2, Atlanta, Office of the Director 7/20/81 2pp

7906140493 Forwarded IE Info Notice 79-12, "Attempted Damage to New Feed Assembly"
O'BRIEN.J.P. Region 2, Atlanta, Office of the Director 7/20/81 1p

7906140565 Forwarded IE Bulletin 79-10, "Requalification Training Program Statistics" without response required
O'BRIEN.J.P. Region 2, Atlanta, Office of the Director 7/20/81 1p

7906140582 Ack receipt of 790610 & 0508 ltr informing ABC of steps taken to correct violations noted in IE Insp Rpts 30-321/79-08 & 30-366/79-10
LEWIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 7/20/81 1p

7906140599 Responded to ABC 790608 ltr re violations noted in IE Insp Rpts 30-321/79-08 & 30-366/79-10 Corrective actions and policy re definition of operability has been established & test results will be reported
STAFFA.R.H. Georgia Power Co 7/20/81 2pp

7906140602 Responded to ABC 790604 ltr re violations noted in IE Insp Rpts 30-321/79-08 & 30-366/79-10 Corrective actions taken. Reqs re insurability reporting will be followed & test results will be reported
STAFFA.R.H. Georgia Power Co 7/20/81 2pp

7906140690 Forwarded IE Insp Rpts 30-321/79-08 & 30-366/79-10 on 7/20/81-0316 0129-0209 & notice of violation
O'BRIEN.J.P. Region 2, Atlanta, Office of the Director 7/20/81 2pp

46 Notice of violation from Insp on 790614-15, 790610-03 & 209
Region 2, Atlanta, Office of the Director 7/20/81 2pp

insp Rpts 30-321/79-08 & 30-366/79-10 on 7/20/81-0316 127-0209 Noncompliance noted failure to report re zone isolation cooling inoperable & failure isolation flow condition test results
Region 2, Atlanta, Office of the Director
Support Branch 7/20/81 2pp

7906140698 Forwarded Amend 1 to 790603 inservice insp program re 790602 request
WHITEN.R.C. Georgia Power Co 7/20/81 1p

7906140829 Amend 1 to 790603 inservice insp program
Georgia Power Co 7/20/81 2pp

8 Periodic operating reports & related correspondence

7906140937 Forwarded "Marine/Navigation Radiological Environ Operating Rpt."
MARINE.N. Georgia Power Co 7/20/81 1p

7906140951 Forwarded monthly operating report for May 1979
MARINE.N. Georgia Power Co 7/20/81 1p

7906140953 Monthly operating report for May 1979
MARINE.N. Georgia Power Co 7/20/81 1p

9 Reportable occurrences, LERs & related correspondence

7906140959 Forwarded LER 79-036/037-0
MARINE.N. Georgia Power Co 7/20/81 1p

7906140964 LER 79-036/037-0 on 790608 possibility exists for overloading trip of plant water pumps during L&S Logic schemes will be modified to distinguish between loss of sys pressure & vessel leak condition
GREGG.T.V. Georgia Power Co 7/20/81 1p

7906140968 MO 30-321/79-08 on 790623 during review of Class IE equipment in drywell, Dechert noted solenoid on 440/36 isolation valve did not have qualification document for accident conditions No safety hazards
MARINE.N. Georgia Power Co 7/20/81 1p

7906140969 Forwarded LER 79-013/015-1
MARINE.N. Georgia Power Co 7/20/81 1p

7906140972 LER 79-013/015-1 on 790613 upon received an Intermediate Range monitor 10-11 trip at mesh 28 of rod 42-15 Caused by actuator being withdrawn past point required to achieve critically Positively Tripped
GREGG.T.V. Georgia Power Co 7/20/81 2pp

7906140981 Forwarded LER 79-033/017-0
MARINE.N. Georgia Power Co 7/20/81 1p

7906140982 LER 79-033/017-0 on 790610 5901 return valves C11-P0158 & C11-P0178 & 5901 pump section valves leaked during local leak test. Cause unknown. Corrective action will be performed to allow satisfactory leakage rate
GREGG.T.V. Georgia Power Co 7/20/81 2pp

7906140983 Forwarded LER 79-033/017-0
MARINE.N. Georgia Power Co 7/20/81 1p

7906140984 LER 79-033/017-0 on 790610 sprinker hanger made indicated seismic design deficiency for cable spreading room sprinker. Cause by lack of detailed seismic analysis. Analysis & Mech have begun
GREGG.T.V. Georgia Power Co 7/20/81 2pp

7906140985 Forwarded LER 79-036/017-0
MARINE.N. Georgia Power Co 7/20/81 1p

7906140986 LER 79-036/017-0 on 790623 review of Class IE electrical equipment in drywell indicated that solenoid on reactor sample isolation valve 591-F019 was not documented as able to perform under accident condition. Cause noted: ordered
GREGG.T.V. Georgia Power Co 7/20/81 2pp

7906140987 Forwarded LER 79-033/031-0
MARINE.N. Georgia Power Co 7/20/81 1p

7906140988 LER 79-033/031-0 on 790621 diesel generator 1A found able to carry less than 50% of rated load. Cause by improper alignment of synchronizer gear. Gear realigned
GREGG.T.V. Georgia Power Co 7/20/81 1p

7906140989 Forwarded LER 79-032/037-1
MARINE.N. Georgia Power Co 7/20/81 1p

7906140990 Forwarded LER 79-032/037-1
MARINE.N. Georgia Power Co 7/20/81 1p

7906140991 LER 79-032/037-1 on 790614 made indicated seismic design deficiency for cable spreading room sprinker. Cause caused by failure to perform detailed seismic analysis on design
GREGG.T.V. Georgia Power Co 7/20/81 2pp

7906140992 LER 79-032/037-1 on 790614 made indicated seismic design deficiency for cable spreading room sprinker. Cause caused by failure to perform detailed seismic analysis on design
GREGG.T.V. Georgia Power Co 7/20/81 2pp

7906140993 LER 79-032/037-1 on 790614 made indicated seismic design deficiency for cable spreading room sprinker. Cause caused by failure to perform detailed seismic analysis on design
GREGG.T.V. Georgia Power Co 7/20/81 2pp

7906140994 LER 79-032/037-1 on 790614 made indicated seismic design deficiency for cable spreading room sprinker. Cause caused by failure to perform detailed seismic analysis on design
GREGG.T.V. Georgia Power Co 7/20/81 2pp

7906140995 LER 79-032/037-1 on 790614 made indicated seismic design deficiency for cable spreading room sprinker. Cause caused by failure to perform detailed seismic analysis on design
GREGG.T.V. Georgia Power Co 7/20/81 2pp

DOCKETED ITEMS

113

79040290306 LER 79-007/017-2 on 79040206 review of Class II dwell equipment per IE Bulletin 79-02. Found inadequate documentation of limit switches on HWY 321-0002 A,B,C & D. Caused by changed requirements. New switch orders GREENGL, R. Georgia Power Co 79/05/18 3pp

H General correspondence

DOCKET 50-022 BUREAU OF NUCLEAR POWER STATION

1 Application/Construction stage documents & correspondence

7904020075 Notification of 790516-17 meeting with in Walling River, IN. Reassessment of plant with view to discuss security program. WILSON, J. R. Light Water Reactors Branch 4 79/05/03 2pp

B Inspection reports: IE Bulletin & correspondence

7904020084 Forwarded IE Info Notice 79-02: "Nonconforming Pipe Support Struts" for written response necessary. GREEN, R. H. Region 1, Philadelphia: Office of the Director 79/05/14 3p

7904020015 Forwarded IE Bulletin 79-008: "Nuclear Incident at 100-0000" No written response required. GREEN, R. H. Region 1, Philadelphia: Office of the Director 79/04/23 1p

7904020045 Responds to 790320 ltr requesting formal guidance on type of tests for monitoring type that would be acceptable to NRC. Forwarded draft Reg Guide 1.003. WILSON, J. R. Light Water Reactors Branch 4 79/05/03 14pp

7904020041 Responds to NRC request for analysis re dry storage under optimum moderator conditions. Dry storage under such conditions is feasible & a new fuel will be less than 0.05 per all values of moderator density. NEWARK, J. P. Long Island Lighting Co 79/05/09 4pp

7904020044 All receipt of 790320 ltr referring NRC of steps taken to correct violation noted in IE Insp Report 50-022/79-02. CAMERON, R. T. Region 1, Philadelphia: Reactor Construction & Engineering Support Branch 79/05/27 1p

7904020075 Notify that spray nozzles & spray nozzle attachment welds are not have been hydrostatically tested. All existing Code Case 1046-B to ASME Section III Change will be incorporated into appropriate design specs. NEWARK, J. P. Long Island Lighting Co 79/05/23 1p

7904020075 Responds to NRC 790320 ltr re violation noted in IE Insp Report 50-022/79-02. Corrective actions records of all welds previously heat treated have been reviewed & engineering evaluation indicated same welds have been reviewed. NEWARK, J. P. Long Island Lighting Co 79/05/23 3pp

7904020075 Notification of use of add note for component supports & alternate design requirements. Included points by Inspect Code Case 1046-B to ASME Section III Change will be incorporated into appropriate design specs. NEWARK, J. P. Long Island Lighting Co 79/05/23 1p

7904020075 Forwarded IE Insp Report 50-022/79-02 on 790320-26 & notice of violation. CAMERON, R. T. Region 1, Philadelphia: Reactor Construction & Engineering Support Branch 79/05/25 3pp

7904020075 Notify that will have invoked Code Case 10702 to ASME Section III permitting use of flexible metal hose in control of Class II & piping Change to be held in designating design appropriate design spec & installation documentation. NEWARK, J. P. Long Island Lighting Co 79/05/29 1p

7904020075 Notice of violation from Insp on 790320-26. Region 1, Philadelphia: Reactor Construction & Engineering Support Branch 79/05/23 1p

7904020081 Forwarded 790319 report: "Add Info on Justification of Mark II Lead Plant Safety Relief Valve Load Definition" by SLM to response to NRC 790427 request. NEWARK, J. P. Long Island Lighting Co 79/05/23 1p

7904020081 IE Insp Report 50-022/79-02 on 790320-26. Noncompliance noted. Failure to control peak weld heat treatment per applicable ASME II code requirements. GREEN, R. H. Region 1, Philadelphia: Office of the Director 79/05/15 13pp

7904020083 "Add Info on Justification of Mark II Lead Plant Safety Relief Valve Load Definition" by SLM to response to NRC 790427 request. Green & Webster, Inc 79/05/15 14pp

7904020083 Forwarded IE Circular 79-07: "Unsuspected Speed Increase of Reactor Motor Generator Set Resulting in Reactor Power Increase" No written response required. GREEN, R. H. Region 1, Philadelphia: Office of the Director 79/05/22 1p

B Adjudicatory correspondence

7904020084 Forwarded IE Info Notice 79-11: "Lead Reactor Vessel Head Insulation Support Problem" No action required. GREEN, R. H. Region 1, Philadelphia: Office of the Director 79/05/07 3pp

7904020082 Answer applicant 790303 request for summary disposition of certain conditions. Note that response time as to two determinable conditions, be held in designating design insurance Certificate of the work. NEWARK, J. P. Branch 4 79/05/02 3pp

7904020085 Forwarded IE Info Notice 79-13: "Alleged Damage to New Fuel Assembly" GREEN, R. H. Region 1, Philadelphia: Office of the Director 79/05/11 1p

7904020097 Forwarded memo to NRC regulations for physical protection of nuclear power plants (10CFR73), effective 790320. NEWARK, J. P. Branch 4 79/05/07 3pp

E
F

7904020091 Responds to 790320 request Forwarded documents on behalf of Suffolk County, NY, NY, and NEWARK, J. P. Branch 4 79/04/20 3pp

7904020092 Forwarded IE Bulletin 79-02: "Pipe Support Base Plate Design Using Concrete Expansion Anchor Bolts" BORDENHUGH, R. H. Branch 4 79/04/26 1p

7904020093 Responds to 790320 ltr re design deficiencies in support base plates. NRC still waiting for SLM evaluation of both piping & electrical type supports. Info will be evaluated as part of constituting safety review. BORDENHUGH, R. H. Branch 4 79/05/15 1p

7904020140 Forwarded info re provisions ensuring safe plant design, spent fuel storage & disposal of radioactive waste in response to 790403 ltr. NEWARK, J. P. Branch 4 79/05/09 12pp

7904020152 Request licensing of facility because of possibility of accident & lack of assurance re storage & disposal of nuclear waste. MONTANA-DURN, R. Affiliation Unknown 79/04/03 3pp

DOCKETED ITEMS

- 79040190420 Qualification Type Test Report Linatongue Valve Actuators for Class IIE DVC Outside Primary Containment *
REBEL, T. A. BORAN, J. D. FORD, J. C. Linatongue Corp 79/03/02 App
- 79040190428 Rept of Seismic Test on SRC-04 Valve Control (ISOL) *
Pacific Gas & Electric Co 79/03/03 70pp
- 79040190428 Qualification Rept for Controller Modules for AR Nuclear One Unit 2 *
FORD, T. G. H. C. Linatongue Corp IPS-409 79/03/04 23pp
- 79040190525 Provides addl info re environ qualification of Borden pressure & differential pressure transmitters
CRANE, P. A. Pacific Gas & Electric Co 79/03/14 1p
- 79040200444 Forward response to 790314 request for addl info re main steam line break inside containment w/proprietary & nonproprietary versions of "Equipment Qualification" & applications for withholding proprietary info
CRANE, P. A. Pacific Gas & Electric Co 79/03/14 1p
- 7904030472 Application for withholding proprietary info from public disclosure pursuant to "Equipment Qualification" & applications for withholding proprietary info
CRANE, P. A. Pacific Gas & Electric Co 79/03/14 2pp
- 7904030488 Nonproprietary version of "Equipment Qualification" *
Westinghouse Electric Corp 79/03/02 2pp
- 79040180231 Forward changes to input parameters to correct logic error reported in Westinghouse App A 0025 model Change accounts for heating effect of circulating water reaction
CRANE, P. A. Pacific Gas & Electric Co 79/03/13 2pp
- G. Adjudicatory correspondence
- 79040200423 Requests status of OL
BROWN, J. P. Northern California Electrical Council 79/03/01 1p
- 79040200423 Requests alternate power sources & conservation measures in CA in lieu of insulating CP
BROWN, J. P. Northern California Electrical Council 79/03/16 1p
- 79040180253 Requests halt to nuclear plant cont
Affiliation Unknown 79/04/02 1p
- 79040180259 Demands postponement of OL issuance until earthquake safety factor is guaranteed
BATES, T. H. NAPILOFF, L. CASIN, California, State of 79/04/03 3pp
- 79040180267 Forward request that re facility cont near geologic fault Request any info dealing w/ matter
ANDREWS, H. House of Rep 79/03/02 1p
- 79040180274 Expresses concern re reactor cont near active geologic fault
LEHMAN, B. B. Affiliation Unknown 79/03/18 1p
- 79040180284 Opposes nuclear facility cont
PETERS, H. Affiliation Unknown 79/04/02 1p
- 79040180293 Opposes cont of facility near active geologic fault
SILCOX, R. Affiliation Unknown 79/04/02 1p
- 79040180309 Requests facility cont cease due to possible health hazards
REYNOLDS, J. A. REYNOLDS, P. Affiliation Unknown 79/03/30 1p
- 79040180317 Requests facility cont cease
HERSTEL, R. Affiliation Unknown 79/04/02 1p
- 79040180320 Requests facility cont cease due to radiation hazards.
KATSKER, D. J. Affiliation Unknown 79/04/03 1p
- 79040180332 Expresses concern over cont of facility
RECTOR, R. J. CASIN, H. J. Affiliation Unknown 79/04/02 2pp
- 79040180338 Award notification schedule experiment D-W-4 Unidentified results re cladding base require further study to determine safety significance Certificate of Div. encl
Hearings Division 79/04/02 2pp
- 79040700327 Hellen by joint intervenors Republic Wholesale Preservation Conference-Dan Luis Shasta Mothers for Peace-D. Silver, Ecology Action Club & J. Farner for withholding of CP Certificate of Div. encl
FLEISCHER, D. B. Fleischer, D. B. MILLER, J. M. KRISTOVICH, G. Center for Law in the Public Interest 79/04/12 1pp
- 79040100399 Response to 790321 1p concerning unresolved questions about low level radiation & nuclear waste disposal until waste plans for increasing spent fuel pool storage capacity in main domes
WAGNER, J. S. Assistant Director for Light Water Reactors 79/03/02 2pp
- 79040200318 Response to lit expressing opposition to plant operation because of proximity to active earthquake fault & problem of disposal of wastes Board is in process of preparing decision re plant licensing
BROWN, J. Division of Project Management 79/03/04 2pp
- 79040100341 Request by joint intervenors that ASLE reopen evidentiary hearings to address Class V accidents & emergency planning in alternative mode directed certification as related questions Certificate of Div. encl
FLEISCHER, D. B. Fleischer, D. B. MILLER, J. M. KRISTOVICH, G. Center for Law in the Public Interest 79/03/09 11pp
- 79040200013 Forward attachments & agenda sheet to joint intervenors
790329 request to reopen or in alternative request for directed certification Certificate of Div. encl
FLEISCHER, D. B. Fleischer, D. B. 79/03/10 10pp
- 79040200313 Create sheet to joint intervenors 790329 request to reopen or in alternative request for directed certification
FLEISCHER, D. B. Fleischer, D. B. 79/03/10 1p
- 79040200329 Comments on Governor ED Brown 790304 lit re JM Hearing Request for extraordinary action of staying out plant for suspension of licensing proceedings is unsubstantiated
BROWN, J. P. Pacific Gas & Electric Co 79/03/11 2pp
- 79040200498 Response to 790425 & OL lit re opposition to facility cont near Hager's fault its evidence generated in ASLE hearings for earthquakes at Hager's greater than 7.0
BENTON, H. B. Office of Nuclear Reactor Regulation 79/03/14 2pp
- 79040400347 Before relied on reopening evidentiary hearings until ASLE completes rept on effects of III on proceeding Other parties will be provided opportunity to respond to rept
BROWN, E. B. Atomic Safety and Licensing Board Panel 79/04/03 2pp
- H. General correspondence
- 79040400329 Requests that earthquake potential be considered before granting CP
SILCOX, R. Affiliation Unknown 79/03/17 2pp
- 79040100379 Discusses reasons for delays in facility cont completion in response to 790328 lit of concrete Verification of ability of plant to withstand possible earthquake in main cause of delay
BENTON, H. B. Office of Nuclear Reactor Regulation 79/04/02 2pp
- 79040200399 Requests info re delays in completion of cont of facility Continued delays only preclude use of alternate energy sources to conserve all
BROWN, J. P. Affiliation Unknown 79/03/28 1p
- 79040100301 Objects to plan 790328 lit supporting postponement of OL issuance Requests development of nuclear power
CASTALDO, V. F. Affiliation Unknown 79/04/26 1p
- 79040400311 Requests OL be denied due to proximity to earthquake zone
WILSON, J. WATERHOUSE, H. WATERHOUSE, E. Affiliation Unknown 79/04/26 2pp
- 79040700441 Response to 790328 lit re potential for delays in issuance of OL decision re order to satisfy antinuclear minority groups concerned re plant ability to withstand effect of earthquakes
BROWN, J. Division of Project Management 79/04/27 2pp
- 79040700460 Comments on granting of OL operation of plant should not be further postponed to satisfy anti-nuclear minority
RECTOR, R. J. Affiliation Unknown 79/03/28 1p
- 79040100320 Requests that CA Public Utility Commission withhold issuance of "Certificate of necessity" for plant until Santa Barbara County can devise emergency evacuation plan
RECTOR, R. J. Affiliation Unknown 79/03/01 1p

DOCKETED ITEMS

115

7/03/03020 Act receipt of 7/03/02 for re R. Lowery correspondence
Forwards info giving brief history & status of licensing
Process info email
KAGG@NRC.gov Office of Congressional Affairs 7/03/02 1p

7/03/12020 Revisions potential for delay in issuance of decision on
On-line order to satisfy antitrust minority groups
BEGD@NRC.gov Division of Project Management 7/03/02 2pp

7/03/190172 Response to 7/06/13 for re safety considerations involved in
Co. issuance
KAGG@NRC.gov Assistant Director for Light Water Reactors
7/03/10 2pp

7/03/190120 Response to 7/03/17 for re issuance of CP Forwards info re
Vibrational design, inflation allowances for decommissioning
equipment, storage, low level radiation efficiencies &
transport of spent fuel
BEGD@NRC.gov Division of Project Management 7/03/15 4pp

3. Inspections & independent information

7/03/27041 Forwards Enforcement 97 & 60 to NRCIA Policy HP-073
BEGD@NRC.gov Northeast Nuclear Energy Co. (Northeast Utilities)
7/03/25 1pp

3. Inspection reports, IC Bulletin 6 correspondence

7/03/120147 Forwards OE Info Notice 79-13, "Lower Reactor Vessel Head
Insulation Support Problem - No action required
BEGD@NRC.gov Region 3, San Francisco, Office of the Director
7/03/12 1p

7/03/120149 Forwards IE Info Notice 79-13, "Attempted Damage to RW Fuel
Assembly" - No written response necessary
BEGD@NRC.gov Region 3, San Francisco, Office of the Director
7/03/10 1p

7/03/120241 Forwards IF Circular 79-08, "Attempted Extortion - Low
Enriched U"
BEGD@NRC.gov Region 3, San Francisco, Office of the Director
7/03/18 1p

7/03/120241 Forwards IC Bulletin 79-13, "Early Decommission Trip Device
in Circuit Breakers for Engineered Safety Sys - License
Action required
BEGD@NRC.gov Region 3, San Francisco, Office of the Director
7/03/22 1p

7/03/180374 Forwards IE Bulletin 79-13, "Short Period Scan at SW
Facilities" - No written response necessary
BEGD@NRC.gov Region 3, San Francisco, Office of the Director
7/03/21 1p

9. Reportable occurrences, LERs & related correspondence

7/03/040339 Forwards PNO-79-67A, AJ & AK per NRC 770401 for transmitting
IC Bulletin 79-03
BEGD@NRC.gov Region 3, San Francisco, Office of the Director
7/04/20 1p

7/03/040360 PNO-79-67A summary of info re nuclear incident at of
7/04/08. Distribution plant & reactor status
Office of Inspection & Enforcement 7/04/20 2pp

7/03/130211 Forwards PNO-79-67A
BEGD@NRC.gov Region 3, San Francisco, Office of the Director
7/03/14 1p

7/03/130260 Forwards PNO-79-67A
BEGD@NRC.gov Region 3, San Francisco, Office of the Director
7/03/21 1p

7/03/130336 Forwards PNO-79-67A
BEGD@NRC.gov Region 3, San Francisco, Office of the Director
7/03/22 1p

7/03/130314 Forwards PNO-79-67A
BEGD@NRC.gov Region 3, San Francisco, Office of the Director
7/03/20 1p

7/03/130380 Response to 7/03/01 for Details corrective actions for bus
bars of transmission re building installation of double
brackets & new Class 1 conductors over Class 1
equipment
BEGD@NRC.gov Pacific Gas & Electric Co 7/03/04 3pp

U Congressional/Executive Correspondence

7/03/090197 Forwards IE from department containing Senate Barbara CA
Board of Supervisors resolution that NRC defer final action
re license application until adequate safety checks have
been completed
KAGG@NRC.gov U House of Rep 7/04/24 2pp

7/03/090228 Response to 7/04/01 for forwarding J. Schlesinger 7/04/01 for
re Senate Barbara CA Board of Supervisors resolution urging
NRC to defer final licensing action on facility until safety
checks can be deferred
KAGG@NRC.gov U Office of the Executive Director for Operations
7/03/25 2pp

DOCKET 20-224 BRIDGEVIEW STEAM ELECTRIC PLANT, UNIT 2

7/03/090117 Summary of 7/04/24 meeting w/UT&I & OE in Bethesda, MD re
resolution of questions on end-of-cycle recirculation
pump trip feature Request for add'l info: mtc
KAGG@NRC.gov J Operating Reactors Branch 3 (Per 7/04/20) 7/04/30 3pp

7/03/070304 Forwards Amend 24 & 48 to Licenses DPR-71 & DPR-02,
respectively, safety evaluation & notice of issuance &
availability
IFPD@NRC.gov J Operating Reactors Branch 3 (Per 7/04/25) 7/03/02 2pp

7/03/070304 Forwards Amend 24 & 48 to Licenses DPR-71 & DPR-02, respectively,
providing Tech Specs for protective instrumentation
associated w/HR recirculation pump trip
IFPD@NRC.gov J Operating Reactors Branch 3 (Per 7/04/25) 7/03/02 4pp

7/03/070400 Safety evaluation supporting Amends 24 & 48 to Licenses
DPR-71 & DPR-02, respectively
J Operating Reactors Branch 3 (Per 7/04/25) 7/03/02 10pp

7/03/070404 Notice of issuance & availability of Amends 24 & 48 to
Licenses DPR-71 & DPR-02, respectively
IFPD@NRC.gov J Operating Reactors Branch 3 (Per 7/04/25) 7/03/02 2pp

7/03/070404 Notice of issuance & availability of Amends 24 & 48 to
Licenses DPR-71 & DPR-02, respectively
IFPD@NRC.gov J Operating Reactors Branch 3 (Per 7/04/25) 7/03/02 2pp

7/03/120102 Notification of 7/03/21 meeting w/UT&I in Bethesda, MD to
discuss status of seismic analyses
KAGG@NRC.gov J Operating Reactors Branch 3 (Per 7/04/25) 7/03/17 1p

7/03/120102 Forwards to NRC 7/03/10 for re implementation schedule for
data required as result of Mark II program West Bend
defect in only major and required Schedule event
UTLEY@NRC.gov Carolina Power & Light Co 7/03/21 4pp

7/03/120102 Requests written confirmation re review of recirculation
pump trip and
UTLEY@NRC.gov Carolina Power & Light Co 7/03/22 1p

7/03/120102 Requests written confirmation re implementation of efficient Tech Specs
Requests implementation of Tech Specs as of 7/03/21
UTLEY@NRC.gov Carolina Power & Light Co 7/03/21 4pp

7/03/120102 Forwards MD Provider affidavit requesting that computer
listings for MS/PS-2, large & small, be withheld from public disclosure
from public disclosure (ref 30CFR 790)
UTLEY@NRC.gov Carolina Power & Light Co 7/03/21 1p

7/03/120102 Affidavit requesting computer listings for MS/PS-2, large
small, be withheld from public disclosure (ref
10CFR 790)
KAGG@NRC.gov U United Engineers & Constructors, Inc (subs of
Raytheon Co) 7/03/23 3pp

7/03/120102 Notifies that general & instrument terminations action
insulating sleeve did not pass nondestructive testing by Engineers
& Constructors. Justification info for continued operation
unnecessary
UTLEY@NRC.gov Carolina Power & Light Co 7/03/25 1p

7/03/120102 Notifies seismic analysis of safety-related piping stress
verification completed for all Category 1 & 2 lines inside
containment dome. Analysis of Category 3 & 4 lines to be
completed by 7/04/25
KAGG@NRC.gov Carolina Power & Light Co 7/03/24 10pp

- 7904202970 Summary of discovery that upon installing portions of compression termination last sent by AMP, Inc. had failed investigation initiated & permanent solution will be implemented during next refueling outage
UTLEY, E E Carolina Power & Light Co 79/04/04 3pp
- 7904203048 Struckup results of feedwater & control rod drive system
Linn article 1980
UTLEY, E E Carolina Power & Light Co 79/04/14 7pp
- G. Inspection reports: IE Bulletin & correspondence
- 7904203052 Forwards IE Insp Repts 50-324/79-09 & 50-325/79-09 as 790204-0201 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/04 2pp
- 7904203058 IE Insp Repts 50-324/79-09 & 50-325/79-09 on 790204-0201 No noncompliance noted Major areas inspected including periodic refueling tests & preparation for refueling
JULIAN, C. & GRAYSON, J Region 2, Atlanta, Office of the Director MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 4pp
- 7904203058 Forwards IE Insp Repts 50-324/79-11 & 50-325/79-11 as 790310-02 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/09 2pp
- 7904203054 IE Insp Repts 50-324/79-11 & 50-325/79-11 as 790310-16 No noncompliance noted Major areas inspected including mainline fire protection mode, condenser water Spac. operating limits, shutdown source removal & IE Bulletin & Circulars
RILEY, A W Region 2, Atlanta, Office of the Director DANIEL, S Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/04 4pp
- 7904203058 Forwards IE Insp Repts 50-324/79-12 & 50-326/79-12 as 790310-22 No noncompliance noted
BUTTERLAND, T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/10 2pp
- 7904203058 IE Insp Repts 50-324/79-12 & 50-326/79-12 as 790310-22 No noncompliance noted Major areas inspected including mainline shield physics program & radioactive waste not program
GIBSON, F Region 2, Atlanta, Office of the Director DANIEL, S Region 2, Atlanta, Office of the Director THOMPSON, C L Region 2, Atlanta, Office of the Director 79/04/09 6pp
- 7904203061 Forwards IE Insp Repts 50-324/79-13 & 50-325/79-13 as 790327-02 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/20 2pp
- 7904203060 IE Insp Repts 50-324/79-13 & 50-325/79-13 as 790327-02 No noncompliance noted Major areas inspected fire protection & safe shutdown sys mode
DANIEL, S, GUTHRIE, J E, & RILEY, A W Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/20 3pp
- 7904203067 Forwards IE Insp Repts 50-324/79-13 & 50-326/79-13 as 790402-05 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/20 2pp
- 7904203070 IE Insp Repts 50-324/79-15 & 50-325/79-15 as 790402-05 No noncompliance noted Major areas inspected complex Tech Spec surveillance tests & pipe supports & restraint sys
MARTIN, R D, & BROWN, E H Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/20 3pp
- 7904203081 Response to IE Bulletin 79-08 re events relevant to S&Hs identified during TMI investigation team has been established to review utility's nuclear plant design & operating procedures to ensure continuing safety
PUGH, B J Carolina Power & Light Co 79/04/23 17pp
- 7904130154 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase & No Action Response Required"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/02 1p
- 7904201094 Forwards affidavit for withholding info required in response to IE Bulletin 79-07, Requests that computer listings designated as Attachment 1 of 790420 1st be withheld (ref 40CFR 7001)
UTLEY, E E Carolina Power & Light Co 79/05/04 8pp
- 7904205045 Forwards IE Info Notice 79-02, "Anticipated Damage to New Fuel Assembly"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 1p
- 7904110079 Forwards IE Bulletin 79-05, "Recalibration Training Program Evaluation"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/11 1p
- 7904203044 Ack receipt of 790320 1st re (informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/79-09 & 50-325/79-09)
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/14 1p
- 7904203051 Response to NRC 790221 1st re violations noted in IE Insp Repts 50-324/79-09 & 50-326/79-02 Corrective actions review of safety-related sys will be made & QA manual revised
PUGH, B J Carolina Power & Light Co 79/05/20 3pp
- 7904204041 Response to IE Bulletin 79-08 re implications of TMI incident on S&Hs No Tech Spec changes required
PUGH, B J Carolina Power & Light Co 79/05/15 1p
- 7904203220 Notification of 790402 meeting results in Bethesda, MD on discuss status of seismic remediation per IE Bulletin 79-07
MARTIN, R D Operating Reactors Branch 2 (Per 790420) 79/05/15 1p
- 7904203067 Response to IE Bulletin 79-09 No OE type AS-2 circuit breakers used in safety-related sys
UTLEY, E E Carolina Power & Light Co 79/05/18 1p
- 7904203067 Response to IE Bulletin 79-10 re operating recalibration training program available containing info requested in item 1-B
UTLEY, E E Carolina Power & Light Co 79/05/24 3pp
- 7904203021 Forwards addl info in response to IE Bulletin 79-07 re seismic pipe stress analysis as requested by NRC at 790321 meeting w/Supporting documentation
UTLEY, E E Carolina Power & Light Co 79/05/29 20pp
- H. Periodic operating reports & related correspondence
- 7904140444 Forwards monthly operating rept for May 1979
BANKS, H R Carolina Power & Light Co 79/06/11 1p
- 7904140444 Monthly operating rept for May 1979
MILLER, E Carolina Power & Light Co 79/06/04 10pp
- I. Reportable occurrences: LERs & related correspondence
- 7904150340 Forwards LER 79-034/BSL-0
PUGH, B J Carolina Power & Light Co 79/02/27 1p
- 7904150341 LER 79-034/BSL-0 as 790131-while performing high pressure functional check of core spray NPSI & LPCA A loop RHR logic failure alarm received caused by blown fuse in PA17
TULLERSON, A C Carolina Power & Light Co 79/02/27 1p
- 7904040952 Forwards 14-day radiological environ mon rept on 790206-08 event released from valve left open after tank transfer, resulting reduced from reactor kld through leak occurred cover Tank transfer procedure revised
BANKS, H R Carolina Power & Light Co 79/03/22 4pp
- 7904140297 Confirms 790320 helcon w/ET Verdyer re deficient nylon insulating sleeves reported per IE Bulletin 79-01, "Critical Qualification of Class 3E Equipment," LSR to be exhibited within 14 days
TULLERSON, A C Carolina Power & Light Co 79/03/29 1p
- 7904150341 Confirms 790320 helcon w/ET Cottle re hanger supports in main steam safety relief & NPSI sys not meeting requirements of IE Bulletin 79-07 re seismic stress analysis LER to be submitted within 14 days
TULLERSON, A C Carolina Power & Light Co 79/05/29 1p
- 7904150341 Confirms 790320 helcon w/ET re equipment inadequate sign insulating sleeves may have been used LSR will be submitted within 14 days
TULLERSON, A C Carolina Power & Light Co 79/05/29 1p

DOCKETED ITEMS

- 7906120164 Affidavit requesting computer listings for AQLPFB-D, large & small variations, be withheld from public disclosure (ref 102182 PWS)
WHESTER, H B United Engineers & Constructors, Inc (subs of Raytheon Co) 79/03/23 3pp
- 7906120013 Notices that control & instrument terminations nylon insulating sleeve did not pass swollen testing (see Engineers & Constructors justification info for continued operation)
WHESTER, H B United Engineers & Constructors, Inc (subs of Raytheon Co) 79/03/23 3pp
- 7906120027B Discussion seismic analysis of safety-related piping stress verification completed for all Category 1 & 2 lines inside containment stress analysis of Category 3 & 4 lines to be completed by 790615
FURR, S J Carolina Power & Light Co 79/06/06 10pp
- 7906120030 Notices of discovery that nylon insulating portions of compression-type termination logs mfg by APF, Inc had failed investigation initiated & permanent solution will be implemented during next refueling outage
URLEY, E E Carolina Power & Light Co 79/05/06 2pp
- 7906120038 Sixteen results of feedwater & control rod drive return tests
URLEY, E E Carolina Power & Light Co 79/05/14 7pp
- G Inspection reports, IE Bulletins & correspondence
- 7906120018 Forwarded IE Insp Repts 50-324/79-09 & 50-325/79-09 on 790229-0303 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 2pp
- 7906120019 IE Insp Repts 50-324/79-09 & 50-325/79-09 on 790229-0303 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 2pp
- 7906120020 IE Insp Repts 50-324/79-11 & 50-325/79-11 on 790219-16 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/09 2pp
- 7906120021 IE Insp Repts 50-324/79-11 & 50-325/79-11 on 790219-16 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/09 2pp
- 7906120022 IE Insp Repts 50-324/79-12 & 50-325/79-12 on 790219-22 No noncompliance noted
BUTTMAN, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/10 2pp
- 7906120023 Response to IE Bulletin 79-08 re events relevant to BMS identified during TNE investigation team has been established to review all nuclear plant designs & operating procedures to ensure continued safety
FURR, S J Carolina Power & Light Co 79/04/23 37pp
- 7906120024 Forwarded IE Circular 79-07: "Unexpected Speed Increase of Reactor Motor Operator Sub Resulted in Reactor Power Increase" No written response required
URLEY, E E Region 2, Atlanta, Office of the Director 79/05/02 1p
- 7906120025 Forwarded affidavits for withholding info required in response to IE Bulletin 79-07 Requests that Computer Listings designated as Attachment 1 of 790624 1ir be withheld (ref 100782 PWS)
URLEY, E E Carolina Power & Light Co 79/05/04 0pp
- 7906120040 Forwarded IE Info Notice 79-12: "Attempted Damage to New Fuel Assembly"
URLEY, E E Region 2, Atlanta, Office of the Director 79/05/02 1p
- 7906120059 Forwarded IE Bulletin 79-10: "Resqualification Training Program Statistics" Written response required
URLEY, E E Region 2, Atlanta, Office of the Director 79/05/15 1p
- 7906120064 Ack receipt of 790420 1ir informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/79-02 & 50-325/79-02
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/14 1p
- 7906120065 Response to NRC 790321 1ir re violations noted in IE Insp Repts 50-324/79-02 & 50-325/79-02 Corrective actions review of safety-related sig will be made & DA manual revised
FURR, S J Carolina Power & Light Co 79/05/20 3pp
- 7906120066 Response to IE Bulletin 79-08 re implications of TNE incident on BMS No Tech Spec changes required
FURR, S J Carolina Power & Light Co 79/05/15 1p
- 7906120067 Notification of 790516 meeting results in Bethesda, MD to discuss status of seismic redesign per IE Bulletin 79-07
WANDL, J Operating Reactors Branch 3 (PWS 790323) 79/05/19 1p
- 7906120071 Response to IE Bulletin 79-09 No OE type AK-2 circuit breakers used in safety-related sig
URLEY, E E Carolina Power & Light Co 79/05/10 1p
- 7906120087 Response to IE Bulletin 79-10 re operating resqualification training program W/Attachment 1 containing info requested in Items 1-3
URLEY, E E Carolina Power & Light Co 79/05/24 3pp
- 7906120092 Forwarded add info in response to IE Bulletin 79-09 re seismic pipe stress analysis, as requested by NRC at 790332 meeting W/operating documentation
URLEY, E E Carolina Power & Light Co 79/05/28 22pp
- E Periodic operating reports & related correspondence
- 7906120046 Forwarded monthly operating rept for May 1979
WANDL, J R Carolina Power & Light Co 79/06/01 1p
- 7906120048 Monthly operating rept for May 1979
WANDL, J R Carolina Power & Light Co 79/06/04 10pp
- B Reportable occurrences, LERs & related correspondence
- 7906120053 Forwarded 14-day radiological emission event rept on 790508-08 event resulted from valve left open after tank transfer causing release into reactor bldg through Jones access cover Tank transfer procedure revised
WANDL, J R Carolina Power & Light Co 79/05/22 4pp
- 7906120059 Forwarded LER 79-034/02L-0
WANDL, J R Carolina Power & Light Co 79/05/29 1p
- 7906120062 LER 79-034/02L-0 on 790403 while performing chloride injection monitor calibr & functional check 1-CBS-C-300-1 would not provide alarm function Caused by break in contact wiring assembly from mechanical wear
WANDL, J R Carolina Power & Light Co 79/05/29 1p

DOCKETED ITEMS

--790670033 Forwarded LER 79-043/02L-D on 790629 during normal reactor shutoff, control rod drive SR-23 had no indication at notch SR Logic checked correctly. Dugout instrumentation will be checked during next outage
TOLLESON, A C Carolina Power & Light Co 79/06/27 1P

790670034s Forwarded LER 79-039/03L-G
MANN, H H Carolina Power & Light Co 79/06/27 1p

--790670037 LER 79-039/03L-D on 790628 during normal operation SR shutoff gas train diverter for approx 40 minutes caused by hot spot breaker for SR reactor water cleanup pump causing breaker from E-A to trip to trip breaker removed
TOLLESON, A C Carolina Power & Light Co 79/06/27 2pp

DOCKET 90-326 UNEV OF CALIFORNIA AT SEVENE RES REACTOR

J. Intermittent & indemnity information

790670037s Forwarded executed Amended B to Indemnity Agreement E-16 Amended A to Indemnity Agreement C-28 Amended B to Indemnity Agreement C-23 and Amended 13 to Indemnity Agreement C-15
GEMMEL, S J California Univ of Berkeley 79/06/26 3pp

0 Inspection reports; IE Bulletins & correspondence

790670104s Act receipt of 790616 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-327/79-12 & 80-328/79-07
MURPHY, C E Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/27 1p

790670040s Forwarded IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies - No written response necessary"
WILLIAMS, R M Region 2, San Francisco, Office of the Director 79/02/10 1p

790670024s Forwarded IE Circular 79-03, "Attempted Corruption - Low Corrupted U"
MURPHY, C E Region 2, San Francisco, Office of the Director 79/03/18 1p

DOCKET 90-327 GEORGIA NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

790670045s Forwarded & discussion proposed agenda for 790620-04 site visit to take representative protection group channels Early stage of work presented tracings during last visit
LAWRENCE, B B Electric, Instrumentation & Control Systems Branch 79/02/19 4pp

790670037s Suggest comparison of "Inspection" & "Discarding view" facets of visit produced in LER 790619 item Requester brief analysis of agenda items & time spent on various activities of work for inspection & expected results "Inspection"
MANN, H H Assistant Director for Plant Safety 79/02/26 1p

Requests approval of flexible metal hose for use as used piping by 790615s Forwarded data demonstrating working Guide 104 & AOME case applications
Case Code H-402
E Tennessee Valley Authority 79/03/01 300pp

Office 1044 responses to five geotechnical engineering submitted in 790629 ltr are included in Amended A
E Tennessee Valley Authority 79/03/30 1p

790670045s Forwarded met info re seismic qualification data package in response to 790628 telcon request
WILLIAMS, J E Tennessee Valley Authority 79/04/27 70pp

Security, medical, emergency & fire protection plan

790670045s Forwarded revisions to radiological emergency plan
WILLIAMS, J E Tennessee Valley Authority 79/04/04 300pp

Intermittent & indemnity information

790670076s Forwarded executed Amended 12 & D to Indemnity Agreements B-32 & B-32 respectively
MANN, H H Tennessee Valley Authority 79/03/29 3pp

790670076s Forwarded HMLD Rinder SR-24, including declarations & bond for payment of retroactive premiums
SUGGS, J R Mann & McLane, H & M Nuclear Consultants, Inc Div 79/04/04 4pp

H Utility Final Safety Analysis Report (FSAR) & amendments

790670029s Forwarded affidavit certifying that copies of Amended A to FSAR were mailed to interested individuals as 790615
WILLIAMS, H Tennessee Valley Authority 79/06/18 2pp

0 Inspection reports; IE Bulletins & correspondence

790670080s Forwarded IE Insp Repts 80-327/79-12 on 790626-06 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/25 2pp

--790670059s IE Insp Repts 80-327/79-12 on 790626-06 No noncompliance noted Major areas inspected fire protection & prevention procedures
BRADY, H H WILLIAMS, J E Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/25 2pp

790670070s Forwarded IE Insp Repts 80-327/79-12 & 80-328/79-07 on 790626-07 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/26 2pp

--790670072s IE Insp Repts 80-327/79-12 & 80-328/79-07 on 790626-07 No noncompliance noted Major areas inspected deficient areas noted in previous ltr, including concrete walls in pumping station access roadway
WILLIAMS, J E Region 2, Atlanta, Office of the Director 79/03/26 2pp

790670089s Forwarded IE Insp Repts 80-327/79-17 & 80-328/79-10 on 790626-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 2pp

--790670059s IE Insp Repts 80-327/79-17 & 80-328/79-10 on 790626-12 No noncompliance noted Major areas inspected test surveillance & progress of installation of self-regulated major mechanical components in reactor bldgs.
WILLIAMS, J E Region 2, Atlanta, Office of the Director 79/04/02 2pp

790670135s Forwarded IE Insp Repts 80-327/79-20 & 80-328/79-11 on 790626-13 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 2pp

790670162s IE Insp Repts 80-327/79-20 & 80-328/79-11 on 790626-13 No noncompliance noted Major areas inspected inspector Airlock time & SO audits by TSC Const Div
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 2pp

790670029s Forwarded IE Insp Repts 80-327/79-19 on 790613-14 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/17 2pp

--790670162s IE Insp Repts 80-327/79-19 on 790613-14 No noncompliance noted Major areas inspected, proportional heat unloading, containment integrated test heat leak observation & independent verification of test data
SCOTT, V J WILLIAMS, J E Region 2, Atlanta, Office of the Director 79/04/18 2pp

790670070s Act receipt of 790408 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-327/79-08 & 80-328/79-04
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/28 2pp

--790670075s Response to NRC 790614 ltr re violations noted in IE Insp Repts 80-327/79-08 & 80-328/79-04, corrective actions missing pipe caps replaced & uncovered carbon steel reps & studs covered up
WILLIAMS, J E Tennessee Valley Authority 79/04/03 2pp

--790670077s Forwarded IE Insp Repts 80-327/79-08 & 80-328/79-04 on 790614-08 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/14 2pp

- 7906040002 Notice of violation from Insp on 790130-0301
Region 2, Atlanta, Office of the Director 79/03/14 1p
- 7906040003 IE Insp Rept 80-027/79-08 & 80-320/79-04 on 790630-0301
Noncompliance noted failure to follow procedure for handling & prevention of stainless steel piping
VANDERKAM, P R Region 2, Atlanta, Office of the Director
CONCERN, J E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/06 3pp
- 7906040004 Forwarded IE Insp Rept 80-027/79-04 on 790411-13 NA
Noncompliance noted
KENDRA, M B Region 2, Atlanta, Safeguards Branch 79/04/25 2pp
- 7906040005 IE Insp Rept 80-027/79-04 on 790411-13 NA Noncompliance noted Major areas inspected security plan, security organization, barriers, access controls, lock & key control, & detection aids Details withheld Insp 100762 7901
TODIN, M J Region 2, Atlanta, Safeguards Branch 80060606, K H Region 2, Atlanta, Office of the Director 79/04/25 1p
- 7906040006 Requests info re consideration given to possible pressure spikes in ice condenser containment plants per IE Bulletin 79-06A, Revision 1
WILLIAMS, P J Division of Project Management 79/05/09 1p
- 7906040009 Responds to IE Bulletin 79-03 investigation shows no piping in use or planned for use in safety-related area Effort in progress to locate any ASME BW-121 Type 304 piping supplied by Westinghouse Welding & Engineering Co
OILLELAND, J E Tennessee Valley Authority 79/05/16 1p
- 7906040017 Requests response to IE Bulletin 79-06A & 79-06A, Revision 1
At re: request assessment & response to ASRS 13rs re recommendations resulting from TMO-2
VARDA, B A Light Water Reactors Branch 79/06/01 2pp
- 7906040019 First interim deficiency report incorrect Valve valve weights used in seismic piping analysis Final response to IE Bulletin 79-04 will be submitted before fuel load in Unit 1
OILLELAND, J E Tennessee Valley Authority 79/06/25 1p
- 2 Reportable occurrences, LERs & related correspondence
- 7906040020 Final deficiency report bistable contacts in auxiliary room loose or precusor pump relief valve failed in undesirable position Valve wiring corrected No other deficiencies found
Tennessee Valley Authority 79/05/10 1p
- 7906040021 Submits second interim deficiency report female anchor capacitors lower than assumed in design allowable Initially reported on 790512 Weld anchor fastening undergo complete analysis to be submitted before Unit 1 fuel load
OILLELAND, J E Tennessee Valley Authority 79/05/14 1p
- 7906040022 Forwarded revised corrective action scheme to 790510 final deficiency report re failure of Control Top bistable in loss of power
OILLELAND, J E Tennessee Valley Authority 79/05/31 1p
- 7906040023 Revised 790510 final deficiency report re control loop Bistable failure in loss of power Revision specifies that wiring diagram for bistable have been corrected & physical wiring will be corrected
Tennessee Valley Authority 79/05/31 1p
- 7906040024 Forwarded interim report re design basis accident movements of steel containment not properly accounted for in design
Rept will be made by 790509
OILLELAND, J E Tennessee Valley Authority 79/06/11 4pp
- 7906040025 Submits third interim deficiency report re vibration in SAR piping Initially reported 790508 Possible to avoid operational modes that result in unacceptable vibration
Cross Valve Bypassing mode recommendations being developed
OILLELAND, J E Tennessee Valley Authority 79/06/11 1p
- 7906040026 Forwarded final deficiency report re overstressed penetrations in containment shell
Design drawings are being revised to move penetrations & secure them between piping & steel containment flange will be performed prior to respective fuel load dates
Tennessee Valley Authority 79/06/15 1p
- 7906040027 Forwarded final deficiency report re pipe restraint structural strand torn
Pipe strand insulation being redesigned to provide horizontal U-bend configuration in areas where strands are in close proximity to pipe
Tennessee Valley Authority 79/06/18 2pp
- 7906040028 Final deficiency report pipe restraint structural strand torn Pipe strand insulation being redesigned to provide horizontal U-bend configuration in areas where strands are in close proximity to pipe
Tennessee Valley Authority 79/06/18 2pp
- 7906040029 Forwarded revised final deficiency report re motor operated valve control circuit failures
OILLELAND, J E Tennessee Valley Authority 79/06/20 1p
- 7906040030 Revised final deficiency report motor operated valve control circuit failure Relay failure could have triggered events deactivating part of one train of safety system Relays will be substituted by backup period
Tennessee Valley Authority 79/06/20 2pp
- 7906040031 Forwarded first interim deficiency report re flexible bellows penetrations of steel containment vessel installed during installation
OILLELAND, J E Tennessee Valley Authority 79/06/25 1p
- 7906040032 First interim deficiency report during hot functional preoperational testing, removal of bellows restraints revealed misalignment caused by facility installation sequence Bellows reinstalled
Tennessee Valley Authority 79/06/25 2pp
- DOCKET 80-328 SOUTHERN NUCLEAR PLANT, UNIT 2
A Application/construction stage documents & correspondence
- 7906040033 Forwarded & discussed proposed agenda for 790602-04 site visit to trace representative protection system channels Early stage of cost prevented tracings during last visit
LAWRENCE, S B Electric, Instrumentation & Control Systems Branch 79/05/19 4pp
- 7906040034 Suggests completion of "Imp" & "Impensing review" facets of visit proposed in Letter 790519 memo Requests brief analysis of agenda items re how spent on review suitability of work for Inspector & expected workload "Imp" task
HARRIS, S H Assistant Director for Plant Systems 79/05/21 1p
- 7906040035 Requests approval of flexible metal hose for use on safety-related piping by 790619 Forwarded data demonstrating compliance with ASME B & ASME code applications addressed in Case Code 9-192
OILLELAND, J E Tennessee Valley Authority 79/05/21 30pp
- 7906040036 Notifies that responses to five pretechnical engineering questions transmitted in 790522 are included in Amend A at P348
OILLELAND, J E Tennessee Valley Authority 79/05/30 1p
- 7906040037 Forwarded add info re seismic qualification data package in response to 790528 Section Request
OILLELAND, J E Tennessee Valley Authority 79/06/01 1p

DOCKETED ITEMS

7706230918 IE Resp Repts 50-329/79-05 & 50-333/79-05 re 790502-01 No
 accommodations noted Major areas inspected site conditions
 & inadequate review of seismic & environ components
 certification 1985 data
 HSE/MS-C, COOH-B-J Region 3, Chicago, Office of the Director
 79/04/25 App

7706130910 Forwards IE Info Notice 77-11, "Lower Reactor Vessel Head
 Insulation Problem - No action required
 HSE/MS-C Region 3, Chicago, Office of the Director 79/05/02
 1p

7706140907 Forwards IE Info Notice 77-12, "Attempted Damage to New Fuel
 Assembly"
 HSE/MS-C Region 3, Chicago, Office of the Director 79/05/13
 1p

7706150912 Response to IE Bulletin 79-03, "Longitudinal Weld Defects in
 ASME SA-512 Type 304 Stainless Steel Pipe Spools H/W by
 Youngtown Welding & Engineering Co." Spools may be in use
 Final report to be submitted by 7/9/79
 HSE/MS-C Region 3, Chicago, Office of the Director 79/05/14 1p

7706160912 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device
 in Circuit Breakers for Engineered Safety Sys." Licensee
 action required
 HSE/MS-C Region 3, Chicago, Office of the Director 79/05/22
 1p

7706180914 Requests page 2 of Insp Repts 50-329/79-05 & 50-333/79-05 be
 repleated w/mtl
 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering
 Support Branch 79/05/22 1p

7706200109 Forwards IE Info Notice 79-13, "Indication of Low Water
 Level in Syntex Reactor"
 HSE/MS-C Region 3, Chicago, Office of the Director 79/05/29
 1p

B. Reportable occurrences, LWRs & related correspondence

7706170922 Notification of receipt of 790420 Interim rept re settlement
 of direct generator foundations & sigs still under matter
 upon receipt of final rept
 FIORELLI, G Region 3, Chicago, Office of the Director 79/05/17
 1p

7706220916 Ack receipt of 790504 Interim rept re component heating M111
 complete review upon receipt of final rept
 FIORELLI, G Region 3, Chicago, Office of the Director 79/05/18
 1p

7706230927 Ack receipt of 770501 rept concerning reactor bldg
 spray piping supports Telcon rept of installed hangers at
 ventline welds/ins. Drawings will necessitate further review
 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering
 Support Branch 79/05/23 1p

7706250922 Forwards 790607 Interim deficiency rept re discrepancies
 of direct generator components of COG ratio control panel SA
 program mkt corrective action rept encl
 HSE/MS-C Region 3, Chicago, Office of the Director 79/06/20 2pp

7706260923 Interim deficiency rept re 790527 Five loose wire
 terminations found on status display panel module of
 main control panel Caused by insufficient mfg & insp
 procedures Insp procedures being developed
 Bechtel Power Corp (subs of Bechtel Corp)
 1p

790613 Interim deficiency rept re unacceptable
 in feedline pipe spools
 era Power Co 79/06/20 App

7706280937 Interim Deficiency Rept 1 from 790325-0301 w/mtl since pipe
 supports failed to meet ASME physical impact requirements
 caused by failure to follow ASME Charge Impact procedures
 Next interim rept scheduled for 7/9/79
 HSE/MS-C Region 3, Chicago, Reactor Construction & Engineering
 Support Branch 79/06/13 App.

E. Hearing transcripts on non-arbitrated matters

7706290922 Description of AH Amend on 790530 in Jackson-MI pp 1-65
 AYINBA, A H Consumers Power Co 79/05/20 8app

7706300927 Description of J. Bacon on 790530 in Jackson-MI pp 1-84
 BACON, J L Consumers Power Co 79/05/23 8app

7706310933 Description of RC Yungdahl on 790601 in Washington DC
 2p 1-147
 YOUNGDAHL, R C Consumers Power Co 79/06/11 147pp

DOCKET 50-330 NUREG-RD PLANT, UNIT 2

A. Application/consentation stage documents & correspondence

7706320934 Forwards second round questions re PSAR review Major areas
 covered are review qualification of safety-related
 equipment, response time testing & post-accident monitoring
 equipment requirements
 BATTENFIELD, M H Electric, Instrumentation & Control Systems
 Branch 79/05/20 13pp

7706140923 Canals 770509 meeting w/mtl in Bethesda, MD re status of
 safety & environ review schedule
 HSE/MS-C Light Water Reactors Branch 4 79/05/23 1p

7706160925 Notification of RL application Requests advice re add'l
 certifying action
 REYNOLDS, H Environmental Projects Branch 2 79/05/01 App

7706190925 Forwards wtl position re implementation of Reg Guide 1.1,
 1.4 & 7.1 (2), 2.1, 4.2, 5.2, 6.4 & 7.0, scheduled to be
 discussed in MRC 791218 meeting Reg Guide 1.4 wmtl
 BARNHART, E Consumers Power Co 79/01/07 2pp

7706290926 Summary of 790449-20 meeting w/mtl Bechtel & BW in
 Bethesda, MD re open items in review of PSAR
 HSE/MS-C Light Water Reactors Branch 4 79/05/15 30pp

7706301940 Requests for controlled region of site emergency plan &
 instrumentation procedures site location & grid
 station numbers of assets & effluents various monitoring
 stations & maps used for effluent dose determination
 HSE/MS-C Region 3, Chicago, Office of the Director 79/05/17
 1p

7706370907 Requests review of possibility of requiring Banks of
 precursor tanks to be classified as safety sys
 LATINAK, S Plant Systems Branch 79/05/29 App

7706370923 Forwards Revision 1 to 790424 response to 100920 SA request
 re plant fill
 HSE/MS-C Consumers Power Co 79/05/30 20pp

7706130929 Describes status of efforts by BW & Bechtel to upgrade
 Reactor bents 3 & 4 of each precursor to Class II
 HSE/MS-C Consumers Power Co 79/06/01 App

7706190925 Requests that sections/chapters of PSAR be evenly
 redistributed to comply w/Section 21
 CASTLEBURY, M L Bechtel Power Corp (subs of Bechtel Corp)
 79/06/12 1p

7706200916 Submits quarterly rept per ALAD-106 & Amend 1 to CF
 Successes cases were performed on siting qualifications of
 site supervisors & changes in personnel
 HSE/MS-C Consumers Power Co 79/06/23 10pp

F. MRC Safety Evaluation Report (ESR), Support & correspondence

7706140928 Forwards Plant Sys SW input protection against dynamic
 effects of piping rupture, spray fuel storage, fuel handling
 sys, chemical & vol control sys, auxiliary & area ventilation
 sys, fire protection sys still unresolved
 HANAUER, R H Assistant Director For Plant Systems 79/05/20
 91pp

G. Adjudicatory correspondence

7706100923 Response to 790429 order scheduling 790501 as date for
 prehearing conference & argument re applicant's motion
 for summary disposition Supports applicant's motion
 Certificate of the SW encl
 STEIN, F J & STEIN, M L Dow Chemical Co 79/04/25 App

7706300930 Request by intervenors other than Dow Chemical Co to
 reschedule prehearing conference & briefing due to
 conflicting obligations
 FLYNN, P Affiliation Unknown 79/04/27 1p

7706300930 Forwards motion by all intervenors other than Dow Chemical
 Co for rescheduling of prehearing conference if motion is
 denied/will appeal to ARJAC for emergency relief
 FLYNN, P Cherry, M H /Skany, Figen & Kayser 79/04/27 App

DOCKETED ITEMS

79060333 Forwards 790607 Interim deficiency report re discrepancies noted in isolated components of JOL main control panel OA program not corrective action report sent
BELL, L. H. Consumers Power Co 79/06/30 3pp

7906030707 Interim deficiency report on 790509 Five switch wire terminations found on status display panel modules of main control panel. Caused by inefficient wiring & loop procedures loop procedures being upgraded
ANDERSON, J. H. Bechtel Power Corp 1546 of Bechtel Corp 1 79/06/07 3pp

790603071 Forwards 790603 Interim deficiency report re unacceptable impact status of main feedline pipe welds
HUBBARD, H. Consumers Power Co 79/06/20 4pp

7906030729 Interim Deficiency Report 1 on 790626-0001 switch nine pipe repair failed to meet ASME physical inspection requirements
Caused by failure to follow ASME Clamping impact procedures
Next interim report scheduled for 790710
ANDERSON, J. H. Bechtel Power Corp 1546 of Bechtel Corp 1 79/06/12 3pp

Hearing transcripts on non-accident matters

790603022 Deposition of AH Agard on 790529 in Jackson, MI Pp 1-36
WHELAN, A. H. Consumers Power Co 79/05/30 36pp

790603051 Deposition of J. Bacon on 790601 in Jackson, MI Pp 1-244
BACON, J. L. Consumers Power Co 79/05/31 244pp

790603052 Deposition of RC Youngdahl on 790601 in Washington, DC Pp 1-147
YOUNGDAHL, R. C. Consumers Power Co 79/06/16 147pp

DOCKET 90-001 DAVIS ARNOLD ENERGY CENTER

B Security, medical, emergency & fire protection plans

7906030199 Forwards "Fire Hazard Analysis"
LILL, Iowa Electric Light & Power Co 79/06/07 1p

--7906030204 "Fire Hazard Analysis" prepared by Bechtel
LILL, Iowa Electric Light & Power Co 79/06/20 10pp

7906030505 Forwards modified physical security plan Plan withheld (see 7906030701)
RODZ, L. B. Iowa Electric Light & Power Co 79/06/22 1p

J Insurance & indemnity information

04150016 Forwards executed Amad & to Indemnity Agreement 6-80
BECHEM, P. E. Iowa Electric Light & Power Co 79/06/11 3pp

Indemnity 41 & 42 to HELIA Policy HP-214 &
5 to RABU Policy HP-79
in: Neuman, Wals, Arnold & Tull 79/06/11 3pp

documents & correspondence

7906030332 "Rep of Metallurgical Examination & Stress Evaluation of Reactor Pressure Vessel Nozzle Safe-End Cracking." Rept IE-146
MILLER, B., DEAN, R. S., FOLEY, W. J. Parameter, Inc 860-08-77-186 79/06/16 25pp

--7906030336 "Final Rept on Examination of Inconel Safe-End From Source Amad"
PARTAPATY, V. J., MURPHY, G. P., PARRELO, D. H. Battelle Material Institute, Columbus Laboratories 80L-000-9 79/06/16 48pp

7906030371 Request schedule for availability of add'l info re App 6 operating curves
1990615-1 A Operating Reactors Branch 3 (Piv 790625) 79/06/23 3pp

7906040329 Request add'l info re w/ 790127 proposal to use actual rod drive screw insertion plans rather than those used in plant safety analyses.
1990615-1 A Operating Reactors Branch 3 (Piv 790625) 79/06/23 3pp

7906030330 Request for controlled copies of site emergency plans & implementing procedures, site maps showing location & grid station numbers of outside & offsite emission monitoring stations & site maps used for offsite dose determination
KEFFLER, J. O. Region 3, Chicago, Office of the Director 79/05/17 1p

7906030334 Forwards description of statistical analysis & compilation of data used in 8803-04087-3 submitted interim time data.
B&W/3 & 4 curve time data; full core & partial core data & amount of Reactor 3 of 4 curve time
LILL, Iowa Electric Light & Power Co 79/05/23 217pp

7906030372 Forwards Revision 2 to Part 1 project schedule which corrects 790517 submittal
LILL, Iowa Electric Light & Power Co 79/06/04 4pp

0 Inspection reports, IE Bulletin & correspondence

7906030323 Forwards IE Insp Rept 30-331/79-12 on 790527-28, 0301-06-06 & 12-14 No noncompliance noted
KEFFLER, J. O. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/14 4pp

--7906030540 IE Insp Rept 30-331/79-12 on 790527-28, 0301-06-06 & 12-14 No noncompliance noted Major areas inspected plant operations, workshop, technical license action on previous Insp findings & LER followup
JACHNICK, W. J., ANDERSON, R. S., REY, H. J. Region 3, Chicago, Office of the Director 79/06/23 14pp

7906030530 Forwards IE Insp Rept 30-331/79-12 on 790512, 16, 0202 & 8026 No noncompliance noted
FISHER, L. J. Region 3, Chicago, Office of the Director 79/06/19 3pp

--7906030533 IE Insp Rept 30-331/79-12 on 790512, 16, 0202 & 8026 No noncompliance noted Major areas inspected allegations relative to weld radiographs & supporting documentation
FISHER, L. J., ANDERSON, R. S., REY, H. J. Region 3, Chicago, Office of the Director 79/06/17 10pp

7906030532 Responds to IE Bulletin 79-04 Forwards info re incorrect schedule for using check valves
LILL, Iowa Electric Light & Power Co 79/05/01 3pp

7906030504 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Inspection Support Problem." No action required
KEFFLER, J. O. Region 3, Chicago, Office of the Director 79/05/07 1p

7906030504 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics." Written response required
KEFFLER, J. O. Region 3, Chicago, Office of the Director 79/05/11 1p

7906030504 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assembly"
KEFFLER, J. O. Region 3, Chicago, Office of the Director 79/05/11 1p

7906030506 Responds to IE Bulletin 79-07 re IE AM-2 circuit breakers are in use or are planned to be used in safety-related ops
LILL, Iowa Electric Light & Power Co 79/05/11 1p

7906030505 Forwards IE Circular 79-28, "Attempted Extension - Low Enriched U"
KEFFLER, J. O. Region 3, Chicago, Office of the Director 79/05/08 1p

7906030506 Forwards revision to page 2 of response to IE Bulletin 79-28
WILLAGE, J. A. Iowa Electric Light & Power Co 79/05/23 2pp

7906030503 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required
KEFFLER, J. O. Region 3, Chicago, Office of the Director 79/05/22 1p

7906030502 Responds to Item 11 of IE Bulletin 79-08 re TMS effect on BWR Tech Spec changes are required based on presently available info
WILLAGE, J. A. Iowa Electric Light & Power Co 79/05/22 1p

7906030535 Act receipt of 790610 re informing NRC of steps taken to correct violations noted in IE Insp Rept 30-331/79-12
KEFFLER, J. O. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/23 1p

DOCKETED ITEMS

127

790620042 Responds to NRC 790704 ltr re violations noted in IE Insp Rpt 79-031 79-12 Corrective actions taken and investigation into cause completed. Re: Nuclear Electric Light & Power Co 79/03/15 1p

790620049 Act receipt of 790427 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpt 79-031 79-12 79/05/20 2p Region 3, Chicago, Office of the Director

790620054 Responds to NRC ltr re violation noted in IE Insp Rpt 79-031 79-12 Corrective actions taken and investigation into cause completed. Re: Nuclear Electric Light & Power Co 79/04/27 3p

790620072 Forwarded IE Info Notice 79-13, "Indication of Low Water Level in Dryer Creek Reactor" 79/05/20 1p Region 3, Chicago, Office of the Director

790620082 Act receipt of 790426 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpt 79-031 79-12 79/05/20 1p Region 3, Chicago, Office of the Director

790620087 Responds to NRC 790503 ltr re violation noted in IE Insp Rpt 79-031 79-12 Corrective actions taken and investigation into cause completed. Re: Nuclear Electric Light & Power Co 79/04/26 3p

Re Periodic operating reports & related correspondence

790620088 Forwarded monthly operating report for May 1979 79/06/14 1p Nuclear Electric Light & Power Co

790620089 Monthly operating report for May 1979 79/06/14 1p Nuclear Electric Light & Power Co

Re Reportable occurrences, LERs & related correspondence

790620090 Forwarded LER 79-012/03-0 79/06/21 1p Nuclear Electric Light & Power Co

790620091 Ltr 79-012/03-0 on 790522 during surveillance testing email issue noted at increased level of power. Ltr also noted in monitoring alarm. Cause by switch which had vibrated loose in monitoring system allowing lubricant to escape. Switch tightened. 79/06/21 1p Nuclear Electric Light & Power Co

800427 79-032 BARNHILL REPROCESSING PLANT

Re Inspection reports, IE Bulletin & correspondence

790620093 Forwarded IE Info Notice 79-13, "Attempted Damage to New Fuel Assemblies" 79/05/20 1p Region 2, Atlanta, Office of the Director

800427 79-033 JMWBL A FLETCHER NUCLEAR POWER PLANT

Re General correspondence

790620094 Responds to 790506 ltr re Ryan which expressed concern for difficulty in trying to obtain info re facility shutdown 79/06/12 2p Region 1, Philadelphia, Office of the Director

790620095 Responds to 790515 ltr re Ryan facility use shut down by NRC 790515 order due to questions re ability of piping system to withstand earthquakes. Division will be reviewing a plant redesigning operation as well as possible removal of piping. 79/05/04 1p

790620096 Expresses concerns re shutdown of facility. Personnel kept of plant employees could have adverse effect on team of management. 79/05/15 1p Region 3, Chicago, NY

790620097 Responds to 790515 ltr re shutdown of five nuclear power plants because of seismic concerns. Seismic design was not in compliance with regulatory practice. Facility piping could cause LERs. Plant redesign is being completed. 79/05/04 1p

790620098 Responds to 790515 ltr re shutdown of five nuclear power plants because of seismic concerns. Seismic design was not in compliance with regulatory practice. Facility piping could cause LERs. Plant redesign is being completed. 79/05/04 1p

790620099 Responds to 790515 ltr re shutdown of five nuclear power plants because of seismic concerns. Seismic design was not in compliance with regulatory practice. Facility piping could cause LERs. Plant redesign is being completed. 79/05/04 1p

790620100 Responds to 790515 ltr re shutdown of five nuclear power plants because of seismic concerns. Seismic design was not in compliance with regulatory practice. Facility piping could cause LERs. Plant redesign is being completed. 79/05/04 1p

790620101 Responds to 790515 ltr re shutdown of five nuclear power plants because of seismic concerns. Seismic design was not in compliance with regulatory practice. Facility piping could cause LERs. Plant redesign is being completed. 79/05/04 1p

790620102 Responds to 790515 ltr re shutdown of five nuclear power plants because of seismic concerns. Seismic design was not in compliance with regulatory practice. Facility piping could cause LERs. Plant redesign is being completed. 79/05/04 1p

790620103 Responds to 790515 ltr re shutdown of five nuclear power plants because of seismic concerns. Seismic design was not in compliance with regulatory practice. Facility piping could cause LERs. Plant redesign is being completed. 79/05/04 1p

790620050 Expresses concerns re shutdown of five reactors for seismic reasons. Requests action on seismic energy, cracks & that plant overhaul more appropriate during refueling activities. Director of Nuclear Power Section. 79/05/15 2p

790620048 Responds to 790515 ltr re NRC 790515 orders to shut down five nuclear power plants. NRC orders to review situation in expedited & accelerated manner. Refueling activities in operation were threat to public health & safety. 79/05/16 3p

790620049 Comments on NRC 790515 & 790516 orders. Requests immediate reversal of orders. Decision to shut down five plants. Requests more rational approach to independent safety concerns in future. 79/05/19 2p

790620050 Responds to 790514 ltr re 790513 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent. 79/05/17 3p

790620051 Responds to 790513 ltr re 790513 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent. 79/05/17 3p

790620052 Comments on 790513 orders shutting down five northeastern US nuclear power plants. Requests investigation into actual probability of major seismic activity in this region. 79/05/17 3p

790620053 Responds to 790513 ltr re 790513 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent. 79/05/17 3p

790620054 Comments on 790513 orders shutting down five northeastern US nuclear power plants. Requests investigation into actual probability of major seismic activity in this region. 79/05/17 3p

790620055 Responds to 790513 ltr re 790513 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent. 79/05/17 3p

790620056 Responds to 790513 ltr re 790513 orders shutting down five northeastern US nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent. 79/05/17 3p

790620057 Responds to 790513 ltr re 790513 orders shutting down five northeastern US nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent. 79/05/17 3p

790620058 Responds to 790513 ltr re 790513 orders shutting down five northeastern US nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent. 79/05/17 3p

790620059 Responds to 790513 ltr re 790513 orders shutting down five northeastern US nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent. 79/05/17 3p

790620060 Responds to 790513 ltr re 790513 orders shutting down five northeastern US nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent. 79/05/17 3p

790620061 Responds to 790513 ltr re 790513 orders shutting down five northeastern US nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent. 79/05/17 3p

790620062 Responds to 790513 ltr re 790513 orders shutting down five northeastern US nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent. 79/05/17 3p

790620063 Responds to 790513 ltr re 790513 orders shutting down five northeastern US nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent. 79/05/17 3p

790620064 Responds to 790513 ltr re 790513 orders shutting down five northeastern US nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent. 79/05/17 3p

- 7904270007 Responds to 790319 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7904270091 Comments on 790319 orders shutting down five northeastern US nuclear power plants Decision was extremely ill-considered
MCGRATH, E W F Affiliation Unknown 79/03/13 1p
- 7904270095 Responds to 790317 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7904270094 Comments on 790312 orders shutting down five northeastern US nuclear power plants Decision was extremely ill-considered
HARPER, W H Affiliation Unknown 79/03/17 1p
- 7904270109 Responds to 790314 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7904270119 Responds to 790322 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7904270124 Responds to 790324 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7904270132 Responds to 790317 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7904270133 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was poorly timed & economically ill-considered
MCGRATH, E W F Affiliation Unknown 79/03/17 1p
- 7904270143 Responds to 790319 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7904270151 Responds to 790322 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7904270153 Comments on 790312 orders shutting down five northeastern US nuclear power plants Decision was ill-considered, considering current energy crisis
HARTZSCHMAR, M Affiliation Unknown 79/03/02 1p
- 7904270163 Responds to 790322 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7904270204 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-considered
MCGRATH, E W F Affiliation Unknown 79/03/03 1p
- 7904270205 Responds to 790315 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7904270245 Comments on 790312 orders shutting down five northeastern US nuclear power plants Decision was overprotective Act
KATZEMSTEIN, R L Affiliation Unknown 79/03/13 3pp
- 7904270247 Responds to 790320 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7904270433 Responds to 790314 ltr re 790313 orders re shut down five nuclear power plants NRC prefers to review situation in expedited & disciplined manner, to return plants to operation with threat to public health & safety
DENTON, H R Office of Nuclear Reactor Regulation 79/05/01 3pp
- 7904270441 States that NRC overreacted in closing five nuclear plants Comments on report of NRC action 790313 regarding ltr to NRC media re shutdown of plants
HEART, P P Affiliation Unknown 79/03/14 3pp
- 7904270528 Requests that distribution list be updated by deleting LR Bennett as counsel & substituting WJ Corman
EARLY, P J Power Authority State of New York 79/05/12 1p
- J. Insurance & indemnity information
- 7904270544 Forwards Endorsements 41-43 to NELA Policy NF-208 & Endorsements 39 & 35 to NELA Policy NF-77
DEBB, B R Power Authority State of New York 79/05/31 3pp
- F. Operating license stage documents & correspondence
- 7904270570 FOIA request for all records & communications re shutdown of five nuclear plants
CARROLL, V J Power Authority State of New York 79/03/16 3pp
- 7904270606 Believes criterion to develop plant-specific info packages on site visits
RUSSELL, E T Office of Nuclear Reactor Regulation 79/04/12 3pp
- 7904270632 Forwards attendance list of 790429-30 meeting at plant site re inservice testing program
POLK, P J Operating Reactors Branch 3 (P) 7904251 79/04/30 3pp
- 7904270637 Forwards listing of deleted info describing QA program
EARLY, P J Power Authority State of New York 79/04/30 3pp
- 7904270610 Notification of 790606 meeting w/ULI, DE & B&W in Bethesda, MD to discuss schedule & plan of action for interim approval
POLK, P J Operating Reactors Branch 3 (P) 7904251 79/05/01 1p
- 7904270601 Forwards memo discussing J McDermentt concerns re shutdown of B&W plants
ROBB, D P Division of Project Management 79/05/17 1p
- 7904270610 Requests assessment of safety of continued operation of B&W reactor based on performance of relief & safety valves, performance of RPI pumps, reliability of auxiliary feedwater & core cooling in natural circulation
ROBB, D P Division of Project Management 79/05/08 3pp
- 7904270610 Discusses safety assessment of B&W plants, in response to 790509 memo B&W plants should be shut down until reassessments have been completed re core cooling in natural circulation
MCGRATH, E W F Quality Assurance Branch 79/05/14 7pp
- 7904270612 Discusses J McDermentt 790514 memo re safety of B&W plants
MCGRATH, E W F Quality Assurance Branch 79/05/13 3pp
- 7904270614 Discusses J McDermentt 790514 memo re safety of B&W plants, disagrees w/B McDermentt position favoring shutdown
MCGRATH, E W F Assistant Director for Quality Assurance & Operations 79/05/13 3pp
- 7904270607 Forwards Amend 46 to License DPR-26, EIA & notice of issuance & availability
IPPOLITO, T A Operating Reactors Branch 3 (P) 7906251 79/05/17 3pp
- 7904270620 Amend 46 to License DPR-29 approving deletion of limiting conditions of operation from EIA & mode to enhance nonradioactive aquatic biological monitoring program
IPPOLITO, T A Operating Reactors Branch 3 (P) 7906251 79/05/17 3pp
- 7904270634 EIA supporting Amend 46 to License DPR-29 & Operating Reactors Branch 3 (P) 7906251 79/05/17 17pp
- 7904270636 Notice of issuance & availability of Amend 46 to License DPR-29
ROBB, D P V L Operating Reactors Branch 3 (P) 7906251 79/05/17 3pp

- 7906010273 Series FOIA request for Olsson 790215 & Thompson 790318 memos to Commissioner Bradford which contain NRC opinions & recommendations re five shutdown plans into off-standby (see FOIA exemption 3)
FELDMAN, J. H. Division of Rules and Records 79/05/01 App
- 7906010407 Requests authorization to conduct plant outloading upon piping stress reevaluation & necessary make up of amendments in inaccessible areas Forwarded re: reevaluation status of safety-related piping vgt
KARLYN, P. J. Power Authority State of New York 79/04/08 App
- 7906020463 Informs that interpretive repts. "Hill's Point Aquatic Ecology Studies 1978" which address data for Pisgahkill Unit 1, has been submitted under 790529 cover ltr from
R. Schneider
BLANK, J. H. Power Authority State of New York 79/06/11 App
- 7906030378 Corrects several editorial errors in Tech Spec Amend A4
CHILDS, V. Power Authority State of New York 79/06/18 App
- 7906040423 Forwarded add'l info re spent fuel storage expansion in response to NRC 790315 & 21 requests
EARLY, P. J. Power Authority State of New York 79/06/22 App
- 7906050123 Forwarded application for amend to License DFR-79
EARLY, P. J. Power Authority State of New York 79/06/26 App
- 7906060204 Application for amend to License DFR-79 to modify Tech Specs w/ emergency w/ water pump test acceptance criteria
Proposed changes & safety evaluation wgt
Power Authority State of New York 79/06/26 App
- 9 Inspection reports, IE Bulletin & correspondence
- 7906080059 Responds to IE Bulletin 79-04 re incorrect weights for using stress valves wgt to stress Engineering Corp. Results of investigation will be available w/ completion of pipe stress analysis
LEONARD, J. D. Power Authority State of New York 79/06/14 App
- 7906110027 Forwarded IE Bulletin 79-05B: "Nuclear Incident at TMI-2" - No written response required
GELBER, S. H. Region 1, Philadelphia: Office of the Director 79/04/23 App
- 7906120027 Forwarded IE Insp Rept 79-032/79-05 on 790315 Re noncompliance noted
GELBER, S. H. Region 1, Philadelphia: Fuel Facility & Materials Safety Branch 79/04/24 App
- 7906130032 IE Insp Rept 79-032/79-05 on 790315 Re noncompliance noted
Major areas inspected: results of effluent sample split between licensee & NRC during previous Insp on 790327-28
GELBER, S. H. Region 1, Philadelphia: Office of the Director 79/04/24 App
- 7906130106 Forwarded IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase" - No written response required
GELBER, S. H. Region 1, Philadelphia: Office of the Director 79/05/03 App
- 7906150185 Forwarded IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Export Problem" - No action required
GELBER, S. H. Region 1, Philadelphia: Office of the Director 79/05/07 App
- 7906150143 Forwarded IE Bulletin 79-10: "Recalibration Training Program Statistics" - Written response required
GELBER, S. H. Region 1, Philadelphia: Office of the Director 79/05/11 App
- 7906160134 Forwarded IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies."
GELBER, S. H. Region 1, Philadelphia: Office of the Director 79/05/11 App
- 7906080648 Forwarded IE Circular 79-08, "Attempted Extension - Low Restricted U."
GELBER, S. H. Region 1, Philadelphia: Office of the Director 79/05/12 App
- 7906090743 Responds to IE Bulletin 79-09 re GE Type MW-2 circuit breakers. Four AW-24-005 & fifteen AW-24-025 breakers installed in 400 volt emergency power sys. Provides specific functions of breakers.
LEONARD, J. D. Power Authority State of New York 79/05/15 App
- 7906090930 Responds to IE Bulletin 79-11 re faulty overcurrent trip device in circuit breaker for emergency safety sys
Breakers not in use at facility
LEONARD, J. D. Power Authority State of New York 79/05/24 App
- 7906100448 Forwarded responses to questions re insurance loss program contained in NRC 790323 ltr
EARLY, P. J. Power Authority State of New York 79/06/20 App
- 7906120609 Responds to IE Bulletin 79-01A Plant staff has reviewed application of AR20 steamoid valves utilized within primary containment. Replacement parts ordered to replace sealed plastic & Buna R neck containing parts
LEONARD, J. D. Power Authority State of New York 79/06/02 App
- 9 Periodic operating reports & related correspondence
- 7906120645 Forwarded monthly operating repts for May 1979
LEONARD, J. D. Power Authority State of New York 79/06/07 App
- 7906120721 Monthly operating repts for May 1979
EARLY, P. J. Power Authority State of New York 79/06/20 App
- 7906130274 Submits weekly repts of status of RSW piping reanalysis efforts of 790323
EARLY, P. J. Power Authority State of New York 79/06/23 App
- 9 Repeatable occurrences, LERs & related correspondence
- 7906040223 EO 79-01 on 790309 Subject piping to safety relief valves was 6-inch double extra strong-casting inside diameter to be slightly smaller than 100% diameter of valve Vendor evaluation repts due in Feb
FARROWMAN, J. Power Authority State of New York 79/01/05 App
- 7906040222 Forwarded LER 79-028/031-0
LEONARD, J. D. Power Authority State of New York 79/02/03 App
- 7906040207 LER 79-028/031-0 on 790310 during normal plant operation, smoke emanated from supply breaker for 12KV/430 reactor core overload. Caused by electrical overload damaged parts replaced
POBUTYCHWICZ, S. Power Authority State of New York 79/03/09 App Available at NRC
- 7906040205 Provides OE analysis & safety review results concerning potential 80 79-01 re nuclear safety valve valve piping. Analysis concludes that piping does not compromise safe operation of facility
LEONARD, J. D. Power Authority State of New York 79/03/29 App
- 7906040276 Forwarded LER 79-037/031
LEONARD, J. D. Power Authority State of New York 79/04/23 App
- 7906040208 LER 79-037/031-0 on 790305 primary containment pressure suppression pool level exceeded Tech Spec limit by two inches. Caused by operator failure to isolate RSW as free keep-full valve
GELBER, S. H. Power Authority State of New York 79/04/30 App
- 7906040303 LER 79-040, number not used
Power Authority State of New York 79/05/29 App
- 7906090231 Forwarded LER 79-034/031-0
LEONARD, J. D. Power Authority State of New York 79/06/05 App
- 7906090235 LER 79-034/031-0 on 790507 radiologic bldg exhaust fan 49-79-084 did not trip re 79-M radiation signal caused by closed/jarred position switch associated w/ discharge damper
Switch damage repaired
GELBER, S. H. Power Authority State of New York 79/06/05 App
- 7906100273 Forwarded LER 79-027/031-0
LEONARD, J. D. Power Authority State of New York 79/06/12 App
- 7906150275 LER 79-027/031-0 on 790514 instrument 52-34-19-723 tripped while AT 2 inches. Instrument recalibrated, then replaced. Weekly testing will continue to ensure good performance
GELBER, S. H. Power Authority State of New York 79/06/12 App
- 7906100340 Forwarded LER 79-028/031-0
LEONARD, J. D. Power Authority State of New York 79/06/15 App

DOCKETED ITEMS

- 790102047 Forwards LER 79-026/03-0 on 790317 during cold shutdown level instrument of carbon dioxide storage run was out of calibration. Cause by procedural error. Instrument repaired & satisfactorily tested.
CHILDS, W. V. Power Authority State of New York 79/03/17 2pp
- 790102044 Forwards LER 79-026/03-0
LEONARD, J. D. Power Authority State of New York 79/03/15 1p
- 790102049 LER 79-026/03-0 on 790319 sequencing timer associated with fluidizing carbon dioxide gas not functioning. Preliminary Cause not stated. Sequencing timer cause adjusted.
CHILDS, W. V. Power Authority State of New York 79/03/19 2pp
- 790102074 Forwards LER 79-030/03-0
LEONARD, J. D. Power Authority State of New York 79/03/15 1p
- 790102080 LER 79-030/03-0 on 790318 during cold shutdown, test point was discovered in area. Cause by deviations in connection of surveillance test procedures. F-10P-09 Procedure was immediately corrected & surveillance complete.
CHILDS, W. V. Power Authority State of New York 79/03/15 2pp
- 790102071 Forwards LER 79-029/03-0
LEONARD, J. D. Power Authority State of New York 79/03/15 1p
- 790102079 LER 79-029/03-0 on 790308 during shutdown, 14 shabbers required some work & 4 shabbers were determined to be potentially inoperable. Shabbers removed & tested. Two shabbers failed tests & were declared inoperable.
CHILDS, W. V. Power Authority State of New York 79/03/15 2pp
- 790102010 Forwards LER 79-031/03-0
LEONARD, J. D. Power Authority State of New York 79/03/15 1p
- 790102014 LER 79-031/03-0 on 790318 fire door between north & south emergency switch gear room failed to close on automatic signal. Door & closing mechanism lubricated & adjusted.
CHILDS, W. V. Power Authority State of New York 79/03/15 2pp
- 790102074 Forwards LER 79-023/03-0
LEONARD, J. L. Power Authority State of New York 79/03/20 1p
- 790102077 LER 79-023/03-0 on 790324 during review of plant age, determined that reactor side cooling air supply & return lines to drywell; equipment drain pump did not have seismic stress analysis performed. Uncertain if it is required.
CHILDS, W. V. Power Authority State of New York 79/03/20 2pp
- 790102058 Forwards LER 79-024/03-0
LEONARD, J. D. Power Authority State of New York 79/03/21 1p
- 790102070 LER 79-024/03-0 on 790301 date sheets associated with instrument surveillance procedures F-10P-05 had not been revised as part of procedure revision which changed instruments safety range. Personnel reeducated.
CHILDS, W. V. Power Authority State of New York 79/03/21 2pp
- 790102075 Forwards LER 79-025/03-0
LEONARD, J. D. Power Authority State of New York 79/03/21 1p
- 790102076 LER 79-025/03-0 on 790307 sealant pressure switch F-10P-05 failed to trip at 15.7 inches of mercury. Pressure switch retested & operation restored by completing surveillance procedure F-10P-14-1.
CHILDS, W. V. Power Authority State of New York 79/03/21 2pp
- CHSR 30-234 BEAVER VALLEY POWER STATION, UNIT 1
Additional correspondence
- 790102035 Amend to PA Public Utility Commission. 790402 petition to intervene & request for hearing Certificate of Dismissal.
LEVIN, J. A. Pennsylvania, State of 79/04/30 5pp
- General correspondence
- 790102043 Responds to 790310 1st re shutdown of five nuclear power plants. Concern of seismic concerns. Seismic design was not in accord with accepted engineering practices. Failed piping could cause LCRB Plant review is being expedited.
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/09 1p
- 790102030 Expresses concern re shutdown of five reactors for seismic reasons. Suggests action assumes energy crisis & that plant operators are appropriate during refueling shutdown. Benefits of nuclear power outweigh seismic risks.
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/11 2pp
- 790102041 Responds to 790311 1st re NRC 790313 orders to shut down five nuclear power plants. NRC prefers to review situation in expedited & disciplined manner, to return plants to operation after threat to public health & safety.
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/15 2pp
- 790102044 Comments on NRC Certificate & Cavalier action. Requests immediate reversal of certificate decision to shut down five plants. Suggests more national approach to inoperable safety systems in future.
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/19 2pp
- 790102058 Responds to 790314 1st re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent.
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 2pp
- 790102060 Responds to 790321 1st re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent.
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 2pp
- 790102062 Responds to 790313 order shutting down five northeastern US nuclear power plants. Requests investigation into actual probability of major seismic activity in this region.
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/21 2pp
- 790102063 Responds to 790403 1st re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent.
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 2pp
- 790102064 Comments on 790313 orders shutting down five northeastern US nuclear power plants. Actions poorly reasoned.
FULLEN, D. S. Affiliation Unknown 79/03/22 1p
- 790102065 Responds to 790321 1st re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent.
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 2pp
- 790102066 Comments on 790313 orders shutting down five northeastern US nuclear power plants. Economic consequences for Holston as well as power shutoffs. Consideration of project of earthquake. Plants should be repaired.
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/21 1p
- 790102068 Responds to 790327 1st re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent.
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 2pp
- 790102069 Comments on 790313 orders shutting down five northeastern US nuclear power plants. NRC should re-evaluate its anti-nuclear attitudes.
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/22 1p
- 790102069 Responds to 790323 1st re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent.
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 2pp
- 790102073 Comments on 790313 orders shutting down five northeastern US nuclear power plants. Plants should be repaired immediately, due to economic prospects of plant closings.
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/22 1p
- 790102074 Responds to 790322 1st re President re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent.
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 2pp
- 790102076 Responds to 790328 1st re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent.
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 2pp
- 790102087 Responds to 790315 1st re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping. Maps of northeastern US earthquake zones sent.
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 2pp

DOCKETED ITEMS

131

- 7904270091 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was extremely ill-conceived
REIDHALL, H. F. Affiliation Unknown 79/03/15 3p
- 7904270095 Responds to 790317 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 3pp
- 7904270099 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was extremely ill-conceived
REIDHALL, H. F. Affiliation Unknown 79/03/17 3p
- 7904270109 Responds to 790314 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 3pp
- 7904270119 Responds to 790322 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 3pp
- 7904270124 Responds to 790324 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 3pp
- 7904270132 Responds to 790317 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 3pp
- 7904270133 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was poorly timed & economically ill-conceived
REIDHALL, H. F. Affiliation Unknown 79/03/17 3p
- 7904270143 Responds to 790319 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 3pp
- 7904270151 Responds to 790322 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 3pp
- 7904270155 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was ill-conceived, considering current energy crisis
REIDHALL, H. F. Affiliation Unknown 79/03/22 3p
- 7904270262 Responds to 790323 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 3pp
- 7904270264 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-conceived
REIDHALL, H. F. Affiliation Unknown 79/03/22 3pp
- 7904270268 Responds to 790319 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 3pp
- 7904270269 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was overprotective act
KATZIN, H. L. Affiliation Unknown 79/03/17 3pp
- 7904270267 Responds to 790325 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/17 3pp
- 7904270433 Responds to 790314 ltr re NRC 790313 orders to shut down five nuclear power plants NRC prefers to review situation in expedited & disciplined manner, to return plants to operation with threat to public health & safety
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/21 3pp
- 7904270444 States that NRC overreacted in closing five nuclear plants Comments on impact of NRC action w/790313 forwarding ltr to US House re shutdown of plants
BENTON, H. R. Affiliation Unknown 79/03/14 3pp
- J Insurance & Indemnity Information
- 7904270423 Forwards executed Amend 3 to Indemnity Agreement 8-73
CHILDS, R. D. Success Light Co 79/03/25 3pp
- F Operating license stage documents & correspondence
- 7904270512 Discusses 790301 telecon w/with & BSM NRC requested copy of PIPESPEC computer code to compare w/with PIPESPEC BSM stated policy of not releasing codes or calculations Meeting re 790322 for BSM to bring PIPESPEC to NRC for review
BENTON, H. R. Operating Reactors Branch 1 (PRA 790425) 79/03/26 3p
- 7904270526 Solicits criteria to develop plant-specific info packages re site visits
BENTON, H. R. Office of Nuclear Reactor Regulation 79/04/01 3pp
- 7904270528 Summary of 790411-12 meeting w/with & BSM in Boston, MA re status of remaining efforts & review of packages submitted to date
BENTON, H. R. Operating Reactors Branch 1 (PRA 790425) 79/04/02 3pp
- 7904270540 Requests withdrawal of solid radioactive waste packaging QA program submitted 790316 Approves operational QA program
BENTON, H. R. Success Light Co 79/03/27 3p
- 7904270546 Summary of 790512 meeting w/with re auxiliary feedwater sp & related items
BENTON, H. R. Operating Reactors Branch 1 (PRA 790425) 79/05/15 3pp
- 7904270591 Forwards memo discussing B. McDermott concerns re shutdown of BSM plants
BENTON, H. R. Division of Project Management 79/03/17 3p
- 7904270601 Requests assessment of safety of continued operation of BSM reactor based on performance of relief & safety valves, performance of HP pump, reliability of auxiliary feedwater & surge tank in natural circulation
BENTON, H. R. Division of Project Management 79/05/02 3pp
- 7904270616 Discusses safety assessment of BSM plants, in response to 790509 memo BSM plants should be shut down until investigations have been completed re core cooling in natural circulation, leaks break LOCA & COOL
BENTON, H. R. Quality Assurance Branch 79/05/14 3pp
- 7904270622 Discusses B. McDermott 790514 memo re safety of BSM plants Discusses w/with McDermott position favoring shutdown
BENTON, H. R. Quality Assurance Branch 79/05/15 3pp
- 7904270614 Discusses B. McDermott 790514 memo re safety of BSM plants Discusses w/with McDermott position favoring shutdown
BENTON, H. R. Assistant Director for Quality Assurance & Operations 79/05/15 3pp
- 7904270604 Response to FOIA request for documents re discrepancy between revision of original piping analysis for seismic stresses (plans partially denied documents w/with opinion & recommendations) re FOIA Exemption B1
BENTON, H. R. Division of Rules and Records 79/05/21 3pp
- 7904270612 Requests info re history of plant water hammer & pipe vibration problems
BENTON, H. R. Commission 79/03/13 3p
- 7904270618 Discusses plant water hammer & pipe vibration history in response to Commission 790313 790313 memo
BENTON, H. R. Office of Nuclear Reactor Regulation 79/03/15 3p
- 7904270627 Discusses discovery of error in plant seismic design & subsequent NRC decision to shutdown five nuclear power plants
BENTON, H. R. Commission 79/03/14 3pp

DOCKETED ITEMS

904290282 Responds to HRC 790518 ltr Forecasts amplified response spectra based on soil structure interpretation Details result of analysis of small strain values of plus or minus 300.
DUNN, C W Duquesne Light Co 79/05/23 45pp

--3906070228 Notice of violation from Insp on 790212-14
* Region 1, Philadelphia- Office of the Director 79/02/14
2-

932290550 Notification of 798524 meeting w/Phil & Edw to discuss response system to be used in facility pipestress

--7956670244 DE Insp Rept 90-368/77-05 on 790212-16 Noncompliance noted
Failure to maintain records of surveillance testing
RECKMAN, D. A. Region 1, Philadelphia, Office of the Director
SEBRO, R. B. Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 79/03/12 2100

F04000000 Discusses use of soil structure interaction for seismic
 pipe stress analysis being performed Methodology may
 be used provided seismic stresses calculated are increased
 by factor of 1.0
 EHS000000, D & Assistant Director for Systems Engineering 79/05/21
 Doc.

790620000 Forwards IE info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem." No action required
DNCR:JW Region I, Philadelphia, Office of the Director
79/05/07 JWS

704102212 Discussion present status of piping age reanalysis Reanalysis complete & two hydraulic shuttles installed No pipe is overstressed in event of safe shutdown earthquake Rept supporting 770070 request to be submitted by 7/26/81
MOLESWERB, J. Oskayee Licht Co. 79/04/11 30x

990606020 Forwards IE Bulletin 79-10, "Requalification Training
Program Statistics." Written response required
CNSR,S H Region 1: Philadelphia. Office of the Director
790606 1a

790626000 Forwards IE info Notice 79-12, "Attempted Damage to New Fuel Assemblies"

[illegible]

-7704300158 "Soil-Structure Interaction in Development of Amplified Response Spectra"

7004200790 Requests response date to IE Bulletin 70-12, 70-124 &
70-128 be changed to 700700
0000, C M Defense Light Co 79/03/11 10

7706210131 Perseus "Sept an Reanalysis of Safety-Related Foping Sys"
Requests mod of 77061013 order for shutdown to permit
operation until refueling Certificate of Suit able
Date: 04/04/2000 10:00:00 AM 77061013-1-1

7906270196 Forwards response to item 13 per Revision 1 of IE Bulletin
79-044 Only Tech Spec b design change necessary is mod to
pressureizer safety injection logic
DARRIN H. BARNETT/LEADS Co 79/06/17 Doc

-7906210132 "Expt on Reanalysis of Safety-Related Piping Sys "
 * Stone & Webster, Inc 79/06/15 225pp

PT04080077 Forwarded DE Circular 74-08, "Attempted Sabotage - Enriched U"
ORIELLO H Region 1, Philadelphia, Office of the Director
20/03/18 1c

7906220351 Submitte info requested by ARE on 790625 re design,
fabrication history, pre-service/post-service images & operating
history of facility feedwater lines
DUNN, G N Duquesne Light Co 79/06/20 4pg

FW0427074A Responds to SE Bulletin JW-10. "Requalification Training Program Statistics" Forwards all Requalification Training program statistics
 (AWG) C H - Southwest Light Co. 28/05/03 Sec

D Inspection reports, IE Bulletins & correspondence

7904100401: Response to IE Bulletin 79-01 Light switches have been replaced. Safety-related electrical equipment is qualified by IIR of compliance. Test repts & analysis of equipment
Tech Spec available in Central Files only
DASH, C N Duquesne Light Co 79/06/14 Bus

7902300:55 Pucanas IE Insp Rpt 50-024/79-00 an 790200-0327 No
noncompliance noted
CARLSON, T Region 1, Philadelphia, Bracker Construction &
Engineering, Suscott Branch 79/04/00 Doc

B. Periodic operating reports & related correspondence

7902260665 IE Insp Rept 80-00479-03 on 790208-0327 No noncompliance noted Major areas impacted soil-boring & testing program in area of station two-Gene Kidg
EMERSON S D. VARELA A A Region 1, Philadelphia, Office of the Director 79/04/20 Spa

7906010182 Forwards Jan. 1979 Natl Pollution Discharge Elimination Sys
monthly reports submitted to PA Dept of Environ Resources
000001-2 M. Thompson, 1010 N. Washington, Wash.
000001-2 M. Thompson, 1010 N. Washington, Wash.

790411001) Forwarded IE Bulletin 79-008, "Nuclear Incident at
TNT-Suppl." No written response required
09002.9 M Region 1, Philadelphia, Office of the Director
79/04/23 1a

7906950275 Forwards pages 240 & 244 & revised table of contents to be added to "Annual Review, Sept 1978, Neurobiological, Vol 5," previously forwarded on 790326. Pages summarize use of herbicides

GUNN, C. H. Bethesda Light Co. 79/05/20 Tex

7905100104 Forwards response to J.E Bulletin 79-688. Procedural changes & training planned for completion prior to facility startup
WOLVERINE J Duquesne Light Co 79/04/30 80pp

7906120325 Forwards monthly operating rept for
MOORE, G W Buquesen Light Co 79/06/08 1p

790418277 Responds to IE Bulletin 79-04, "Incorrect Weights for Owing
Check Valves Mfg by Welan Engineering Corp " Analysis of
24 valves for potential overstress is in progress
MOOREHEAD, E J Duesenre Light Co 28/04/80 in.

--7986120328 Monthly operating rept for May 1979
TOMAS, B R Bakers Light Co 79/06/06 4pg

PP0AD70023 Ask Receipt of 790828 ltr informing NRC of steps taken to correct violation noted in IE Insp Rpt 58-33479-04
 061000Z E J Region 1 Philadelphia, Reactor Operations Nuclear
 Support Branch 790830 1a

7906340245 Forwards LEE 78-001/040
WORLDING, J A Sequeste Light Co 78/01/16, 19

-7906670825 Request to MRC 790314 str re violation noted in IE insp
Sept 20-2038/79-04 Corrective actions reviewed test data for
missing documents & submitted info to OSHA Safety
Committee
DMM:C N, Buquesse Light Co 79/04/05 2pg

--7906044249 LDR-78-001/040 on 771025 reporting level in ETO for gross beta particles was reached or exceeded 771000-10 Caused by Chinese bomb fallout No corrective action appropriate
GEM/LNO, J A Sweeney Light Co 70/01/86 Rsp

7706070206 Forwarded IE Insp Rpt 56-304/79-04 on 790202-ss & notice violation
SUSANNE, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch. 79/03/14, Gpp

7906260397 NO on 740618 radiographs taken on 770615-16 & 18 of three steam generator outlet-to-feedwater inlet piping welds showed cracking present in three inlet pipes. Additional info & corrective action will be provided in following rept.

WELTING, J. A. Duquesne Light Co. 77/06/17 Doc

7906290328 Forwards LERs 79-009/OOL-D & 79-012/OOL-D.
WELING, J A, Squease Light Co 79/06/21. Rep

DOCKETED ITEMS

133

--7904040325 Act receipt of 790301 for informing NRC of steps taken to correct violations noted in IE Insp Rept 50-323/79-04
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/07 sp

--7904042209 LER 79-013/03-0 on 790302 during surveillance of control room reliability, non-prepared regulators for control room parameterization were found cycling. Caused by improper callout controls time & procedure tracked
MERLING, J A Sequence Light Co 79/06/21 sp

DOCKNEY 50-333 ST. LUCIE PLANT, UNIT 1

J Insurance & indemnity information

7904040617 Forwards Enforcement 25 & 26 to NREU Policy HF-08
DICK, J R Marsh & McLennan, H & M Nuclear Consultants, Inc Div 79/04/12 2pp

M Antitrust correspondence

7904040410 Response of still in opposition to Ft. Clinton' motion for antitrust hearing & motion for consolidated hearings
Certificate of Eve Smith
BOGARD, J A Louisiana, Neuman, Reis, Arndt & Tull 79/04/12 3pp

P Operating license stage documents & correspondence

7904050019 Responds to 790317 for requesting ref to specific SA program used to meet requirements of 10CFR 55.46 Revised 2 to topical SA page in its effect for Turkey Point & FARM SA program in its effect for St Lucie
WRIGHT, R E Florida Power & Light Co 79/04/23 sp

7904050010 Summary of 790428 meeting w/O-E re natural circulation capability for C-E plants
TOWNSEND, A C Reactor Systems Branch 79/05/02 43pp

7904050025 Notifies that response to IE Bulletin 79-04 re Valian using check valves will be submitted by 790320
WRIGHT, R E Florida Power & Light Co 79/05/02 sp

7904050027 Forwards summary of 790301 meeting w/O-E re natural circulation conditions in C-E operating reactors
TOWNSEND, A C Reactor Systems Branch 79/05/09 sp

7904050037 Forwards C-E proprietary rept "Control Element Assembly Guide Tube Entry Current Testing" Forwards AE Shorer affidavit attesting to proprietary nature of rept
WRIGHT, R E Florida Power & Light Co 79/05/23 6pp

7904050015 Notifies of reduction in allowable peak linear heat rate in accordance w/790226 & 27 telcon w/P Electric Reduction necessitates change in Tech Spec Revised figures and
WRIGHT, R E Florida Power & Light Co 79/05/20 4pp

7904050010 Submits proposed change to qualification program parameters 0000720 re test scope an annual exam Requisite response to
FISCHER, P L, METZ, C M Florida Power & Light Co 79/05/30 sp

7904050034 Forwards requested info re Feedwater line design & fabrication history
WRIGHT, R E Florida Power & Light Co 79/05/20 4pp

Q Inspection reports, IE Bulletins & correspondence

7904050044 Responds to IE Bulletin 79-03 Status rept re Youngstown Welding & Engineering Co pipe will be sent no later than 790521
WRIGHT, R E Florida Power & Light Co 79/04/17 sp

7904050045 Act receipt of IE Bulletin 79-04 & 79-04B Forwards responses to 79-04B & procedures identified for review
WRIGHT, R E Florida Power & Light Co 79/04/24 9pp

7904050038 Forwards IE Insp Rept 50-325/79-09 on 790321-23 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/24 2pp

--7904050075 IE Insp Rept 50-325/79-09 on 790321-23 No noncompliance noted. Major gross inspected steam generator cleaning program necessitates amend rept program plan procedures, IE bulletins & notices & open items.
CANTRELL, F R, WERTER, C H Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/23 2pp

7904050023 Act receipt of 790301 for informing NRC of steps taken to correct violations noted in IE Insp Rept 50-323/79-04
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/07 sp

--7904050034 Responds to NRC 790404 for re violations noted in IE Insp Rept 50-325/79-06 Corrective actions safety evaluation completed & procedures reviewed & determined satisfactory
WRIGHT, R E Florida Power & Light Co 79/05/03 2pp

--7904050009 Forwards IE Insp Rept 50-323/79-04 on 790312-14 & notice of violation
LEWIS, R C Region 2, Atlanta, Office of the Director 79/04/04 2pp

--7904050010 Notice of violation from insp on 790321-14 & Region 2, Atlanta, Office of the Director 79/04/03 sp

--7904050013 IE Insp Rept 50-325/79-04 on 790321-14 Noncompliance noted. Failure to complete written safety evaluation of new to use described in PSAR & failure to review & approve maint test procedures
WRIGHT, R E, CANTRELL, F R Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/03 7pp

7904050023 Act receipt of 790410 for informing NRC of steps taken to correct violations noted in IE Insp Rept 50-323/79-07
MERLING, J A Region 2, Atlanta, Safeguards Branch 79/05/09 sp

--7904050019 Responds to NRC 790323 for re violations noted in IE Insp Rept 50-323/79-07 Corrective actions withheld inf
10CFR 55.46
WRIGHT, R E Florida Power & Light Co 79/04/18 sp

--7904050025 Forwards IE Insp Rept 50-323/79-07 on 790321-26 Notice of violation withheld inf 10CFR 55.46
CANTRELL, F R Region 2, Atlanta, Office of the Director 79/05/23 2pp

--7904050023 IE Insp Rept 50-325/79-07 on 790321-26 Noncompliance noted. No security details withheld inf 10CFR 7901
WRIGHT, R E Region 2, Atlanta, Office of the Director
MERLING, J A, LONG, F J Region 2, Atlanta, Safeguards Branch 79/05/13 2pp

7904050042 Forwards IE Info Notice 79-10, "Attempted Damage to New Fuel Assemblies"
O'HEILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 sp

7904050042 Forwards IE Bulletin 79-10, "Recertification Training Program Statistics" Written response required
O'HEILLY, J P Region 2, Atlanta, Office of the Director 79/05/11 sp

7904050042 Responds to IE Bulletin 79-04 re OE Model MK-2 circuit breaker bank under load to perform checks described in OE Ref Advice Rept 125 & checks will be incorporated into switchgear maint procedures
WRIGHT, R E Florida Power & Light Co 79/05/22 sp

DOCKETED ITEMS

790610024 Forwarded LER 79-017/03-3
SCHMIDT, A J Florida Power & Light Co 79/04/07 1p

--790610030 LER 79-017/03-3 as 790509 28 charging pump casing block contained several internal cracks centered around pressure chambers caused by suction cavitation resulting in vibration Pump Block replaced
GCHERRMAN, H A Florida Power & Light Co 79/04/07 2pp

790610037 Forwarded LER 79-018/03-3
SCHMIDT, A J Florida Power & Light Co 79/04/07 1p

--790610050 LER 79-018/03-3 as 790508 during routine diesel generator main-valves installed an engine crankshaft oil drain line prior to performance of written safety evaluation caused by failure to follow procedure
SCHERRMAN, H A Florida Power & Light Co 79/04/07 1p

U Congressional/Executive Correspondence

790606066 Provide add info re B Browning info request concerning PL reactor power situation. Reactor was produced by PL plants, offsite released, & consequences of possible accident
GCHERRMAN, H A Office of the Executive Director for Operations 79/05/13 3pp

DOCKET 50-306 MILLSTONE NUCLEAR POWER STATION, UNIT 2

I Financial Information

790606074 Forwarded annual financial repts for minor-licenses
GCHERRMAN, H A Northeast Nuclear Energy Co 79/05/13 3pp

--790606075 Annual Financial Rept 1978
Western Massachusetts Electric Co 79/12/31 17pp

--790606097 Annual Financial Rept 1978
Hartford Electric Light Co 79/12/31 21pp

--790606097 Annual Financial Rept 1978
Connecticut Light & Power Co 79/12/31 21pp

J Insurance & Security Information

790610020 Forwarded Undercarriage 34 & 35 to MGLU Policy 79-50
CONNELL, T Northeast Nuclear Energy Co (Northeast Utilities) 79/04/12 3pp

790606094 Forwarded Undercarriage 79 & 40 to ANI Policy 79-133
SEDER, R R Northeast Utilities 79/04/31 1p

F Operating license stage documents & correspondence

790606030 Forwarded Mar 1979 "Thermal Flame Study"
COUNTELL, M G Northeast Utilities 79/04/16 1p

--790606036 "Thermal Flame Study," Mar 1979
Northeast Utilities 79/03/31 32pp

790606036 Summary of 790420 meeting w/C-E re natural circulation capability for C-E plants
THERMAN, A C Reactor Systems Branch 79/05/02 62pp

790606087 Forwarded summary of 790501 meeting w/C-E re natural circulation conditions on C-E operating reactors
THERMAN, A C Reactor Systems Branch 79/05/09 1p

790606088 Forwarded questions & comments re interview testing program & confirm 790523-34 meeting. Requests formal response by 790425
KILB, R H Operating Reactors Branch 4 (Pre 790625) 79/05/11 7pp

790607037 Forwarded Amend 32 to License 09F-05 safety evaluation & notice of issuance & availability
KILB, R H Operating Reactors Branch 4 (Pre 790625) 79/05/12 5pp

--790607020 Amend 32 to License 09F-05 authorizing Cycle 3 operation at 21340 MW untested fuel tubes for control element assembly
KILB, R H Operating Reactors Branch 4 (Pre 790625) 79/05/12 10pp

--790607029 Safety evaluation supporting Amend 32 to License 09F-05
Operating Reactors Branch 4 (Pre 790625) 79/05/12 4pp

--790607030 Notification that mgt performance is adequate & responsive to NRC concerns. No outstanding imp items are related to safe operation of plant at current power level
KILB, R H Operating Reactors Branch 4 (Pre 790625) 79/05/12 1p

--790607031 Notice of issuance & availability of Amend 32 to License 09F-05
KILB, R H Operating Reactors Branch 4 (Pre 790625) 79/05/12 3pp

790606033 Summary of 790511 meeting w/C-E & Beechle re auxiliary reactor systems & related areas
CONNELL, T Operating Reactors Branch 4 (Pre 790625) 79/05/13 4pp

790606034 Progress that min. of two licensed reactor operators be stationed in main control rooms at all times-one of whom has direct responsibility for feedwater sys
COUNTELL, M G Northeast Utilities 79/05/13 2pp

790610037 Forwarded add info re C-E elevated control element assembly pipe tubes data indicates that fuel assemblies remain acceptable for Cycle 3 operation
COUNTELL, M G Northeast Utilities 79/04/16 3pp

790610038 Forwarded info in response to V Beale 790325 request re design fabrication history & insp of feedwater lines. Re assets code requirements & can continue to operate safely
COUNTELL, M G Northeast Nuclear Energy Co (Northeast Utilities) 79/04/18 27pp

B Inspection reports, SE Bulletin & correspondence

790606043 Forwarded IE Insp Repts 50-245/79-41 & 50-336/79-38 on 79104-1207. No noncompliance noted
SEDER, R R Region 1, Philadelphia, Office of the Director 79/05/21 3pp

--790606047 IE Insp Repts 50-245/79-41 & 50-336/79-38 on 79104-1207. No noncompliance noted. Major areas inspected accessible periphery of Unit 1 reactor, turbine & radioactive bldgs. Unit 2 auxiliary & turbine bldgs & radioactive emissions
SEDER, R R Region 1, Philadelphia, Office of the Director 79/05/21 3pp

790606073 Forwarded IE Insp Rept 50-336/79-38 on 79036-04. No noncompliance noted
SEDER, R R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/10 3pp

--790606083 IE Insp Rept 50-336/79-38 on 79036-09. No noncompliance noted. Major areas inspected reflecting preparations, containment indicator line valve test procedure & outage unit
KILB, R H, GCHERRMAN, H A Region 1, Philadelphia, Office of the Director 79/04/16 1p

790606085 Response to 790511 by re IE Bulletin 79-03. ASME DA-312 stainless steel pipe manufactured by Yongmuong Heilig & Engineering Co. Forwarded info on piping in use & program for volumetric examination
COUNTELL, M G Northeast Utilities 79/04/16 4pp

790606086 Forwarded IE Insp Repts 50-245/79-41 & 50-336/79-38 on 79020-0316. No noncompliance noted
SEDER, R R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/16 3pp

--790606088 IE Insp Repts 50-245/79-41 & 50-336/79-38 on 79020-0316. No noncompliance noted. Major areas inspected accessible periphery of Unit 1 reactor, turbine & radioactive bldgs. Unit 2 auxiliary & turbine bldgs
SEDER, R R, KILB, R H, GCHERRMAN, H A Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/16 22pp

790610020 Response to IE Bulletin 79-01 re review qualification of Class IE equipment. Bolts used on safety-related valve in Unit 2 containment not qualified. Bolts will be replaced before Cycle 3 operation
COUNTELL, M G Northeast Utilities 79/04/18 2pp

790610019 Forwarded IE Bulletin 79-03, "Nuclear Incident at Unit 2" - No utility response required
SEDER, R R Region 1, Philadelphia, Office of the Director 79/04/23 1p

7904020210 Responds to IE Bulletin 79-07 re seismic stress analyses of safety-related piping
COUNCIL-W O Northeast Utilities 79/04/24 3pp

7904020307 Responds to IE Bulletin 79-03, "Operational Errors & Misalignments Identified During Last Incident: Emergency Procedures have been revised to provide specific guidance, if voiding is indicated by check of reactor coolant gas flow
COUNCIL-W O Northeast Utilities 79/04/24 3pp

7904020408 Requests clarification of requirement for "Verification of Operability" from IE Bulletin 79-04
MILLIAMS-F J Division of Project Management 79/04/27 1p

7904020412 Responds to IE Bulletin 79-04, "Incorrect Weights for Ring Check Valves Held by Velen Engineering Corp." Lists sub. valves used in Seismic Category I piping sys investigation indicates no drawing discrepancies re valves
COUNCIL-W O Northeast Utilities 79/04/30 2pp

7904020428 Responds to IE Bulletin 79-03 re longitudinal weld defects in ASME SA-312 stainless steel pipe Melas found to be acceptable (Request submitted per 790412 comment)
COUNCIL-W O Northeast Utilities 79/05/03 2pp

7904020500 Ack receipt of 790402 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/79-03 & 50-256/79-03
BETH-G M Region 1, Philadelphia: Fuel Facility & Materials Safety Branch 79/05/03 1p

--7904020508 Responds to NRC 790520 ltr re violations noted in IE Insp Repts 50-245/79-03 & 50-256/79-03 Corrective actions 30-ft, 4-inch elevation immediately posted w/ign barriers (radiation caution signs)
COUNCIL-W O Northeast Nuclear Energy Co (Northeast Utilities) 79/04/12 2pp

--7904020509 Forwards IE Insp Repts 50-245/79-03 & 50-256/79-03 re 790510-15 & status of violation
BETH-G M Region 1, Philadelphia: Fuel Facility & Materials Safety Branch 79/05/20 3pp

--7904020510 Notice of violation from Insp re 790512-15 & Region 1, Philadelphia: Fuel Facility & Materials Safety Branch 79/05/16 1p

--7904020512 IE Insp Repts 50-245/79-03 & 50-256/79-03 re 790512-15 Noncompliance noted failure to post radioactive materials storage area as required
YOUNG-O P, CROCKRELL-W M Region 1, Philadelphia: Fuel Facility & Materials Safety Branch 79/05/16 2pp

7904020715 Forwards IE Info Notice 79-11, "Leak Reactor Vessel Head Installation Support Problem" No action required
BETH-G M Region 1, Philadelphia: Office of the Director 79/05/07 2pp

7904020808 Supplements 790507 responses to IE Bulletin 79-07 Safety-related piping re: seismic seismic sys criteria
COUNCIL-W O Northeast Utilities 79/05/07 1p

7904020917 Requests establishing requirement for core thermocouples per IE Bulletin 79-08
MILLIAMS-F J Division of Project Management 79/05/07 1p

7904020984 Responds to IE Bulletin 79-08 Re Tech Spec changes required at present
COUNCIL-W O Northeast Nuclear Energy Co (Northeast Utilities) 79/05/10 1p

7904030100 Forwards IE Bulletin 79-09, "Regulification Training Program Statistics" Written response required.
BETH-G M Region 1, Philadelphia: Office of the Director 79/05/11 1p

7904030124 Forwards IE Info Notice 79-12, "Accepted Damage to New Fuel Assembly"
COUNCIL-W M Region 1, Philadelphia: Office of the Director 79/05/11 1p

7904030401 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
BETH-G M Region 1, Philadelphia: Office of the Director 79/05/18 1p

7904030707 Supplements response to IE Bulletin 79-07 Assessment revealed nitrogen addition sys & charging sys are in conformance w/ high energy pipe break criteria specified in PSBR
COUNCIL-W O Northeast Nuclear Energy Co (Northeast Utilities) 79/05/08 2pp

7904030804 Responds to IE Bulletin 79-01, "Environ Qualification of Class 1E Equipment" Second suppl to be submitted by 790501
COUNCIL-W O Northeast Utilities 79/04/12 13pp

B Periodic operating reports & related correspondence

7904030845 Forwards monthly operating rept for May 1979
GREGA-J F Northeast Utilities 79/04/05 1p

--7904030847 Monthly operating rept for May 1979
GREGA-J F Northeast Utilities 79/04/07 2pp

B Reportable occurrences, LBNs & related correspondence

7904030851 Forwards LBN 79-014/03L-0
PHELPS-E J Northeast Nuclear Energy Co (Northeast Utilities) 79/07/14 1p

--7904030903 LBN 79-014/03L-0 re 790417 while performing monthly control element assembly surveillance testing assembly & dropped to zero steps from 120 steps No component failures causing control element assembly to drop
CROCKRELL-W M Northeast Nuclear Energy Co (Northeast Utilities) 79/07/14 1p

7904030909 Forwards LBN 79-020/03L-0
GREGA-J F Northeast Utilities 79/10/12 1p

--7904030907 LBN 79-020/03L-0 re 790912 during routine steady-state operation spent fuel storage ventilation gaseous radiation monitor failed low level by shunted level alarm horn which also caused supply from horn disconnected & fuse replaced
CROCKRELL-W M Northeast Utilities 79/10/12 1p

7904030993 Forwards LBN 79-012/01T-0
GREGA-J F Northeast Utilities 79/06/05 1p

--7904030401 LBN 79-012/01T-0 re 790502 during rise in 300 power, loss of four linear power range channels found to be impermissible open connections fused between detector cable & field wiring caused by connector pins pushed into connector
GREGA-J F Northeast Utilities 79/06/05 2pp

7904030408 Forwards LBN 79-019/030-0
GREGA-J F Northeast Utilities 79/06/14 1p

--7904030409 LBN 79-019/030-0 re 790325 while operating 130 diesel for surveillance, leaking injector pump observed caused by external lead inclusion, resulting in stress riven at surface of valve cage
GREGA-J F Northeast Utilities 79/06/14 2pp

7904030500 Forwards LBN 79-013/03L-0
GREGA-J F Northeast Utilities 79/06/08 1p

--7904030509 LBN 79-013/03L-0 re 790325 during check of control room alarm detection sys, both detectors declared inoperable due to low drip rates in sensor caused by clogged bypasses bypasses cleaned, resulting operability
BETH-G M Northeast Utilities 79/06/22 1p

7904030607 Forwards LBN 79-006/030-3
GREGA-J F Northeast Utilities 79/06/26 1p

--7904030609 LBN 79-006/030-3 re 791108 during routine operation, activated waste evaporator condensate tank was pressurized under a rupture caused by application of 100 psi air to tank & rupture in tank in unvalued vent line. No repair planned
BETH-G M Northeast Utilities 79/06/26 2pp

SOCKET 50-320 NORTH ANNA POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

7904030104 Requests investigation of bus 808 items believed to be unjustified Reinsurer coverage on 808 3 elevation in unnecessary since area above base of pump is solid concrete
BETH-G M Virginia Electric & Power Co 79/06/11 2pp

DOCKETED ITEMS

D Administrative Correspondence

- 7903101437 Committee 790308 meeting in Bethesda, MD objectives to proceeding to discuss availability of Citizens' Energy Program Contingents
SOLBERG, D. C. Branch 2 79/03/08 1p
- 7903101437 Motion for extension until 790401 to prepare response to ALB-301
SEINFELD, J. F. Hearings Division 79/04/02 2pp
- 7903101438 Response to 790328 request for info re status of Valmeting proceeding to develop value for radon in Table B-3 Book 3 proposed rule will be sent to NRC by 790405 Rule does not address health effects of radon releases
CHRISTENSEN, R. E. Hearings Division 79/03/28 24pp
- 7903101441 Forwards two stipulations of contingents executed & served at 790329 prehearing conference
SOLBERG, D. C. Branch 2 79/04/04 1p
- 7903101442 Forwards will testimony & exhibits to be presented as evidence at public hearing during use of 790418 W/o end
CHRISTENSEN, J. H. Hutton & Williams 79/04/27 4pp
- 7903101443 Objects to ALE 790401 under Request re-instatement of contention labeled "alternatives" & seeks revocation from Citizens Energy Forum on emissions issue Certificate of Evt end
SOLBERG, D. C. Potomac Alliance 79/03/03 5pp
- 7903101444 Requests that ALE reverse denial of contingents acceptable to will. NRC & intervenors seek admission of new lead & leakage issues & contingents re EIS & need for present and Certificate of Evt end
HRODT, I. B. Citizens Energy Forum 79/05/03 4pp
- 7903101445 Forwards add portions of "NRC Staff Testimony re Pumphouse Settlement"
SOLBERG, D. C. Branch 1 79/05/04 5pp
- 7903101446 Forwards response to 790307 & 10 interrogatories & document requests from Intervenor & Arnold Objects to some questions & requests that are irrelevant to pumphouse settlement Certificate of Evt end
CHRISTENSEN, J. H. Hutton & Williams 79/03/04 3pp
- 7903101447 Response to 790407 & 10 interrogatories & document requests from Intervenor & Arnold re pumphouse settlement Supporting Documentation end
Virginia Electric & Power Co. 79/05/04 57pp
- 7903101448 Requests that ALE postpone 790408 prehearing conference to 790328 Add time necessary for discovery & filing of motions Certificate of Evt end
HRODT, I. B. Citizens Energy Forum 79/05/18 3pp
- 7903101449 Evidentiary hearing re pumphouse settlement & turbine misfire issues will commence on 790410 in Bethesda, MD Names of witnesses & content must be submitted by 790408
SOLBERG, D. C. Atomic Safety and Licensing Appeal Panel 79/03/21 1p
- 7903101450 NRC motion for summary disposition re radon issue was in error ALB-345 consolidated until 5 of 10 cases before NRC motion as to parties in other proceedings Certificate of Evt end
SOLBERG, D. C. Atomic Safety and Licensing Appeal Panel 79/03/23 3pp
- 7903101451 ALE will not take oral limited appearance statements at 790408 evidentiary hearing re pumphouse settlement & turbine misfire issues ALE will accept written statements to be included in record.
SOLBERG, D. C. Atomic Safety and Licensing Appeal Panel 79/03/30 3pp

J Insurance & Indemnity Information

- 7904120334 Underwriting 41 to NEHA Policy HW-37
SOLBERG, D. C. Mutual Atomic Energy Liability Underwriters 79/05/10 1p
- 7904120335 Underwriting 42 to NEHA Policy HW-37
SOLBERG, D. C. Mutual Atomic Energy Liability Underwriters 79/05/10 1p

P Operating License Stage Documents & Correspondence

- 7904120336 Forwards Amend 10 to License APP-06 safety evaluation & notice of issuance & availability
PARR, D. D. Light Meter Reactors Branch 3 79/04/27 4pp
- 7904120337 Amend 10 to License APP-06 incorporating changes to Tech Specs re structural integrity of reactor coolant pump section elbow splitter
VASSALLO, D. B. Assistant Director for Light Meter Reactors 79/04/27 18pp
- 7904120338 Safety evaluation supporting Amend 10 to License APP-06 & Light Meter Reactors Branch 3 79/04/27 12pp
- 7904120339 Notice of issuance & availability of Amend 10 to License APP-06
PARR, D. D. Light Meter Reactors Branch 3 79/04/27 2pp
- 7904120340 Results of Acceptance Tests of Outside Rotating Pump
PARR, D. D. Final Test
MAUCH, B. Franklin Institute FIN 8-A567 79040623 79/04/20 33pp
- 7904120341 Request review of electrical power sys re conditions which could result in simultaneous or consequential loss of both required circuits to affectors hardware
VASSALLO, D. B. Assistant Director for Light Meter Reactors 79/05/02 9pp
- 7904120342 Forwards 790409 ltr from J Allen of North Anna Environ Coalition requesting termination of QLA LTR is being treated as request for action per 10CFR2.236 Also forwards FR review ltr not end
SOLBERG, D. C. Office of Nuclear Reactor Regulation 79/05/04 1p
- 7904120343 Notice of 790409 North Anna Environ Coalition request for NRC to revoke QLA due to alleged nonperformance of estimated peak fuel cladding temp under of 10CFR2.236
SOLBERG, D. C. Office of Nuclear Reactor Regulation 79/05/04 2pp
- 7904120344 Summary of 790408 meeting w/ all to discuss auxiliary feedwater sys & related station areas
SOLBERG, D. C. Operating Reactors Branch 1 79/04/25 79/05/09 4pp
- 7904120345 Requests until 790312 ltr requesting exemptions to Tech Specs requirements re demonstration of operability of each diesel generator once every 18 months
PARR, D. D. Light Meter Reactors Branch 2 79/05/14 2pp
- 7904120346 Grants 790328 request for withholding rept "Ovcr Water Reservoir & Spray No Performance Testing Evaluations" (ref 10CFR 2.236)
PARR, D. D. Light Meter Reactors Branch 3 79/05/17 5pp
- 7904120347 Discusses radiological effluent tech specs for facility Requires submittal of valid waste process control program & Offsite Dose Calculation Manual by 790701
PARR, D. D. Light Meter Reactors Branch 3 79/05/23 4pp
- 7904120348 Submit info re treatment & release of liquid wastes in response to NRC 790323 ltr
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/29 4pp
- 7904120349 Connects designations re svr water pumphouse included in report of expansion joints and Overhaul drawing end
SOLBERG, D. C. Virginia Electric & Power Co. 79/05/29 4pp
- 7904120350 Advises that Units 3 & 4 should also be included on 790518 ltr
SOLBERG, D. C. Virginia Electric & Power Co. 79/05/30 1p
- 7904120351 Discusses 790518 rept "SA Program Operations Phase," Requests exception from ANSI NRS 2.4 & NRC 2.0 paragraphs re calibrator control & equipment test discussions proposed alternative
SOLBERG, D. C. Virginia Electric & Power Co. 79/05/31 2pp
- 7904120352 Forwards corrections for 790402 EIA re expansion of spent fuel pool
SOLBERG, D. C. Environmental Projects Branch 2 79/06/01 4pp
- 7904120353 Schedule requested in NRC 790601 ltr re Instrument qualification will be submitted by 790715
STALLINGS, C. M. Virginia Electric & Power Co. 79/06/19 1p

DOCKETED ITEMS

137

7904030041 Forwards info re PWR feedwater piping in response to 790323 STALLING, C. H. Virginia Electric & Power Co 79/04/20 App

3 Inspection reports, DE Bulletins & correspondence

7904030074 Forwards IE Insp Repts 30-338/79-02 & 30-339/79-04 on 790309-12 No noncompliance noted
LEMIN, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/27 App

7904030086 IE Insp Repts 30-338/79-02 & 30-339/79-04 on 790309-12 No noncompliance noted Major areas inspected: steam generator, integrated leak testing & testing pipe support & fastenings, steam heating
JOHNSON, A. H., BROWN, E. H., MARTIN, R. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/26 App

7904030141 Forwards IE Insp Repts 30-338/79-14 & 30-339/79-00 on 790309-29 No noncompliance noted
BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/16 App

7904030142 IE Insp Repts 30-338/79-14 & 30-339/79-00 on 790309-29 No noncompliance noted Major areas inspected: sealed steam leak tests, fallout on inspector, identified items & investigation & calibr of radiation monitoring sys
JOHNSON, A. H., BROWN, E. H., MARTIN, R. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/16 App

7904030211 Forwards IE Insp Rept 30-338/79-10 & 30-339/79-19 on 790309-04 No noncompliance noted
LEMIN, R. C. Region 2, Atlanta, Office of the Director 79/04/19 App

7904030238 IE Insp Rept 30-338/79-10 & 30-339/79-15 on 790309-04 No noncompliance noted Major areas inspected: operations review, IE Bulletin & circular review & review of containment purge
GANTRELL, F. S., DAVIS, J. A., WEDDERT, E. H. Region 2, Atlanta, Office of the Director 79/04/16 App

7904030341 Forwards IE Insp Rept 30-338/79-17 on 790401-13 No noncompliance noted
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/23 App

7904030345 IE Insp Rept 30-338/79-17 on 790401-13 No noncompliance noted Major areas inspected: ultrasonic insp of reactor coolant pump elbow splitter plates
COULSON, T. E., CHASE, E. H. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/23 App

7904030370 Responds to IE Bulletin 79-07 re seismic analysis of safety-related piping. Forwards 790419 ltr from Nuclear React Care & Research for from Telephony Engineering Soc
SPENCER, M. C. Virginia Electric & Power Co 79/04/24 lpp

7904030384 Forwards IE Insp Rept 30-338/79-12 on 790309-17 No noncompliance noted
O'NEILL, V. P. Region 2, Atlanta, Office of the Director 79/04/25 App

7904030414 IE Insp Rept 30-338/79-13 on 790309-18 No noncompliance noted Major areas inspected: settlement data collected on evn water pumphouse. Summary of inquiry re foundation conditions encl
LOPES, J. J. Region 2, Atlanta, Office of the Director
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/25 App

7904030503 Asst receipt of 790423 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-338/79-07 & 30-339/79-14
LEMIN, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/02 App

7904030512 Responds to NRC 790329 ltr re violations noted in IE Insp Repts 30-338/79-04 & 30-339/79-14 Corrective actions filed changes completed & APR 104 & cover sheet modified
STALLING, C. H. Virginia Electric & Power Co 79/04/22 App

7904030515 Forwards IE Insp Repts 30-338/79-04 & 30-339/79-14 on 790309-0302 & notice of violation
LEMIN, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/29 App

7904030520 Notice of violation from Insp on 790309-0302
Region 2, Atlanta, Office of the Director 79/03/22 App

7904030535 IE Insp Repts 30-338/79-09 & 30-339/79-14 on 790309-0302 Noncompliance noted failure to follow procedures for ensuring completion of corrective action
KIDEL, H. M. Region 2, Atlanta, Office of the Director
GANTRELL, F. S. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/22 lpp

7904030548 Forwards IE Bulletin 79-10, "Regualification Training Program Statistics." Written response required
KIDEL, H. M. Region 2, Atlanta, Office of the Director 79/03/21 App

7904030556 Responds to IE Bulletin 79-01 Forwards "Failure of Bolanoid Operated Valves to Meet IE Bulletin 79-01 Environ Modification Requirements"
STALLING, C. H. Virginia Electric & Power Co 79/04/14 App

7904030558 "Failure of Bolanoid Operated Valves to Meet IE Bulletin 79-01 Environ Modification Requirements." Environmentally unsatisfactory valves have been or will be replaced
Virginia Electric & Power Co 79/04/14 App

R Periodic operating reports & related correspondence

7904030561 Forwards monthly operating rept for May 1979
STALLING, C. H. Virginia Electric & Power Co 79/04/12 App

7904030593 Monthly operating rept for May 1979
VALE, S. W. Virginia Electric & Power Co 79/04/04 App

R Reportable occurrences, LERs & related correspondence

7904030675 RE 79-057/017-0 on 790404 potential overload exists, 4, 140 watt feeder bus & feeder breakers are not capable of continuously carrying full load current. Caused by improper sizing of transfer bus equipment
Virginia Electric & Power Co 79/04/23 App

7904030685 Forwards LER 79-073/017-0
STALLING, C. H. Virginia Electric & Power Co 79/05/21 App

7904030686 LER 79-073/017-0 on 790517 incorrect valve weights used for stress calculations involving accumulator isolation. Manual operated valves cause unknown liner adjustment to spring hanger will restore compliance
GANTRELL, F. S. Virginia Electric & Power Co 79/05/26 App

7904030693 Forwards LERs 79-039/031-0, 79-045/031-0, & 79-046/031-0
STALLING, C. H. Virginia Electric & Power Co 79/05/23 App

7904030698 LER 79-039/031-0 on 790501 fire protection hose stations in auxiliary bldg were inoperative for 10-hr w/o backup use of firewater established. Caused by isolation of auxiliary bldg for main, taking longer than initially estimated
GANTRELL, F. S. Virginia Electric & Power Co 79/05/26 App

7904030699 LER 79-042/031-0 on 790502 during routine startup operation, actual flux difference deviated greater than 3% from target. Caused by power increasing too rapidly during startup operation
GANTRELL, F. S. Virginia Electric & Power Co 79/05/21 App

--

DOCKETED ITEMS

- 790410100 LER 79-04A/03L-0 on 790506 narrow range level transmitter LT-49A in L steam generator read erratically Channel 1000000 Problem cause was drain lines at 3000 high & low pressure sides of transmitter lines clogged
CARTWRIGHT, M R Virginia Electric & Power Co 79/04/04 App
- 790410101 LER 79-03A/03L-0 on 790506 pressurizer level indicator LT-1400 failed during performance of 10P7-03 2 Cause unknown Wires reconnected & surveillance undertaken
CARTWRIGHT, M R Virginia Electric & Power Co 79/04/04 App
- 790410102 Forward LERs 79-05B/03L-0, 79-06A/03L-0 & 79-071/03L-0
STALLINGS, C M Virginia Electric & Power Co 79/04/06 1p
- 790410200 LER 79-04B/03L-0 on 790505 radiation monitoring channels PM-100 & PM-1000 IAD wires detached (separable) due to failure of sample pump 1-PM-1000 19A 3 19B Caused by collapsed valve coil vibrating not coil replaced
CARTWRIGHT, M R Virginia Electric & Power Co 79/04/06 App
- 790410202 LER 79-04A/03L-0 on 790505 during test transmission axial flux difference deviated greater than 5% from target for four minutes Caused by rapid load reduction of 125 MW due to loss of drain pump & control rods withdrawn
CARTWRIGHT, M R Virginia Electric & Power Co 79/04/06 App
- 790410204 LER 79-071/03L-0 on 790501 during permit test at steady state operation low head safety injection pump 1A discharge valve failed to open within 40+ seconds Cause unknown Valve manually opened, rechecked & returned to operation
CARTWRIGHT, M R Virginia Electric & Power Co 79/04/06 App
- 790410307 Forward LER 79-07A/03L-0
STALLINGS, C M Virginia Electric & Power Co 79/04/06 1p
- 790410311 LER 79-07A/03L-0 on 790501 test station AB-10-24 was isolated to perform dump on angle valve 10P7-100 Caused by angle valve leak angle valve replaced & test station returned to operation status
CARTWRIGHT, M R Virginia Electric & Power Co 79/04/07 1p
- 790410303 Forward LER 79-08A/03L-0
STALLINGS, C M Virginia Electric & Power Co 79/04/13 1p
- 790410304 LER 79-08A/03L-0 on 790503 charging pump removed from svc to repair crack inlet piping Caused by heat weld at base of vane 1300 crack ground out & re welded
CARTWRIGHT, M R Virginia Electric & Power Co 79/04/13 App
- 790410306 Forward LER 79-077/03L-0
STALLINGS, C M Virginia Electric & Power Co 79/04/18 1p
- 790410309 LER 79-077/03L-0 on 790501 during power reduction axial flux difference deviated greater than 5% from target for two minutes Caused by high bearing temp of reductor pump C bearing corrected problem
CARTWRIGHT, M R Virginia Electric & Power Co 79/04/18 App
- 790410316 Forward LERs 79-07B/03L-0, 79-08B/03L-0 & 79-09B/03L-0
STALLINGS, C M Virginia Electric & Power Co 79/04/27 1p
- 790410320 LER 79-07B/03L-0 on 790504 during steady state operation, axial flux difference deviated over 5% from target for two minutes contrary to Tech Specs Caused by insect infestation initiated by rod operability test Power reduced by 25
CARTWRIGHT, M R Virginia Electric & Power Co 79/04/27 App
- 790410323 LER 79-08B/03L-0 on 790508 individual rod position indicators H-10 & D-10 placed in test station contrary to Tech Specs Caused by repair work to remove previously installed jumper cable performed
CARTWRIGHT, M R Virginia Electric & Power Co 79/04/27 App
- 790410325 LER 79-08B/03L-0 on 790608 during power escalation axial flux difference deviated more than +5% from target for 16 minutes contrary to Tech Specs Caused by withdrawal of control rods
CARTWRIGHT, M R Virginia Electric & Power Co 79/04/27 App
- T Hearing transcripts on noncontroversial matters
- 790410331 Transcript of 790518 meeting in Bethesda, MD Pg 1-200
ROSENTHAL, A B ; BUCK, J H ; FARBER, M C Atomic Safety and Licensing Appeal Panel 79/04/18 22pp
- 790410332 Transcript of 790518 meeting in Bethesda, MD Pg 459-623
ROSENTHAL, A B ; BUCK, J H ; FARBER, M C Atomic Safety and Licensing Appeal Panel 79/04/20 165pp
- U Congressional/Executive Correspondence
- 790410307 Forward constituent's letter re opening of plant
BUTLER, M C House of Rep 79/04/19 App
- DOCKET 50-029 NORTH ANNA POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 790410313 Forward Amend 10 to License NPF-04, safety evaluation & notice of issuance & availability
PARRO, D C Light Water Reactors Branch 3 79/04/27 App
- 790410319 Amend 10 to License NPF-04, incorporating changes to Tech Specs re structural integrity of reactor coolant pump section above splitter
VALLALLO, C B Assistant Director for Light Water Reactors 79/04/27 10pp
- 790410321 Safety evaluation supporting Amend 10 to License NPF-04
Light Water Reactors Branch 3 79/04/27 12pp
- 790410323 Notice of issuance & availability of Amend 10 to License NPF-04
PARRO, D C Light Water Reactors Branch 3 79/04/27 App
- 790410326 Discusses draft safety evaluation re exemptions to requirements of App. B.1 & J of 10P703
ROSE, F F Division of Project Management 79/05/02 12pp
- 790410320 Forward evaluation & request for add info re "Svc Water Reservoir & Spray Sps Performance Testing & Evaluation"
Request response by 790505
PARRO, D C Light Water Reactors Branch 3 79/05/03 App
- 790410317 Grants 790308 request for withholding rept "Svc Water Reservoir & Spray Sps Performance Testing Evaluation" (79/10070 3 7901)
PARRO, D C Light Water Reactors Branch 3 79/05/17 App
- 790410308 Discusses redesign of effluent tank space for facility
Requires submission of solid waste process control program & Offsite Dose Calculation Manual by 790501
PARRO, D C Light Water Reactors Branch 3 79/05/23 App
- 790410327 Grants info re treatment & release of liquid wastes in response to NRC 790323 (1)
STALLINGS, C M Virginia Electric & Power Co 79/05/29 App
- 790410328 Corrects designations re svc water purchase included in survey of expansion joints and Overhaul drawing and
ROSEN, G C Virginia Electric & Power Co 79/05/29 App
- 790410325 Requests issuance of OL for facility in spite of 3-month moratorium imposed by NRC
790327FF, M L Virginia Electric & Power Co 79/05/30 App
- 790410326 Advises that Units 3 & 4 should also be included on 790518 letter
ROSEN, G C Virginia Electric & Power Co 79/05/30 1p
- 790410320 Discusses 790318 rept "QA Program, Operations Plans"
Requests exemption from ANSI N45.2 d & ANSI Z 39.50 re calibr control & equipment test Discusses proposed alternative
BAUM, C A Virginia Electric & Power Co 79/05/31 App
- 790410319 Forward corrections for 790402 EIA re expansion of spent fuel pool
ROSEN, M H Environmental Projects Branch 2 79/06/01 App
- 790410328 Requests 790318 completion date for facility review conducted in response to TMI incident Util will submit rept discussing recommended actions by 790501
790327FF, M L Virginia Electric & Power Co 79/06/01 App

7906200501 Forward info re PHR Redwater piping in response to 790505 request add info to re was he 790527
STALLINGS, E C Virginia Electric & Power Co 79/06/20 4pp

7906200500 Submits add info re instrument qualification in response to 790501 request use of Barton transmitters is fully justified based on presently & previously submitted data use of sample lines from primary area components under review
BROOKS, B C Virginia Electric & Power Co 79/06/22 2pp

F Security, medical, emergency & fire protection plans

79062005104 Requests investigation of two BER items believed to be unjustified sprinkler coverage on 2DF 3 situation is extraordinary since area above base of pumps is solid concrete
BROOKS, B C Virginia Electric & Power Co 79/06/21 2pp

G Adjudicatory correspondence

7906200527 Confirms 790508 meeting in Bethesda, MD w/ parties to proceeding to discuss admissibility of Citizens' Energy Forum contentions
GILBERTSON, E C Branch 2 79/06/02 1p

7906200547 Motion for extension until 790611 to prepare response to ALAB-395
DICKINSON, J F Hearings Division 79/06/02 2pp

7906200560 Responds to 790522 request for info re status of rulemaking proceeding to develop value for radon in Table B-10 Rule & proposed rule will be sent to NRC by 790606 Rule does not address health effects of radon release
GILBERTSON, E C Hearings Division 79/06/26 2pp

7906200561 Forwards two stipulations of contentions accepted & served at 790620 prehearing conference
GILBERTSON, E C Branch 2 79/06/04 1p

7906200503 Forwards will testimony & exhibits to be presented as evidence at public hearing during use of 790618 N/A sent
GILBERTSON, J H Hutton & Williams 79/06/27 4pp

7906200509 Objects to ASLE 790601 order Requests reinstatement of contentions labeled "admissibility" & seeks avoidance from Citizens Energy Forum on admissibility issue Certificate of Dec
BOLHEART, B D Petition Alliance 79/06/02 3pp

7906200502 Requests that ASLE reverse denial of contentions acceptable to utility, NRC & intervenors seeks admission of heavy lead & leakage issues & contentions re SIB & need for present mod Certificate of Dec sent
HODOT, J D Citizens Energy Forum 79/06/02 4pp

79062005128 Forwards add portions of "NRC Staff Testimony re Pumphouse Settlement"
BMAHSON, D ? Branch 1 79/06/04 3pp

7906200519 Forwards response to 790607 & 10 interrogatories & document requests from intervenor G Arnold Objects to same questions & requests that are irrelevant to pumphouse settlement Certificate of Dec sent
GILBERTSON, J H Hutton & Williams 79/06/04 3pp

7906200520 Response to 790607 & 10 interrogatories & document requests from intervenor G Arnold re pumphouse settlement Repertory documentation sent
Virginia Electric & Power Co 79/06/04 3pp

7906200528 Requests that ASLE postpone 790605 prehearing conference to 790624 Add time necessary for discovery & filing of motions Certificate of Dec sent
HODOT, J D Citizens Energy Forum 79/06/18 3pp

7906200532 Evidentiary hearing re pumphouse settlement & turbine nozzle issues will commence on 790611 in Bethesda, MD Names of witnesses & counsel must be submitted by 790609
BROWNSTON, R M Atomic Safety and Licensing Appeal Panel 79/06/21 1p

7906200535 NRC motion for summary disposition re radon issue was in error, ALAB-340 consolidated only 5 of 14 cases Denies NRC motion as to parties in other proceedings Certificate of Dec sent
DUFFLE, R E Atomic Safety and Licensing Appeal Panel 79/06/25 3pp

7906200537 ASLE will not take oral limited appearance statements at 790618 evidentiary hearing re pumphouse settlement & turbine nozzle issues ASLE will accept written statements to be included in record
DUFFLE, R E Atomic Safety and Licensing Appeal Panel 79/06/20 3pp

H Insurance & indemnity information

7906200534 Endorsement 41 to NDL&A Policy 79-07
GEMF, T Mutual Atomic Energy Liability Underwriters 79/06/10 1p

7906200531 Endorsement 42 to NDL&A Policy 79-07
GEMF, T Mutual Atomic Energy Liability Underwriters 79/06/10 1p

I Inspection reports, IE Bulletin & correspondence

7906200576 Forwards IE Insp Repts 50-338/79-02 & 50-339/79-04 on 790509-12 No noncompliance noted
LUNDBERG, C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/27 2pp

7906200582 IE Insp Repts 50-338/79-02 & 50-339/79-04 on 790509-12 No noncompliance noted Major areas inspected preexercise inspection integrated leak testing & testing pipe support & restrained gas testing
JACKSON, A H - BRIDGES, E H - HANFORD, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/21 3pp

7906200508 Forwards IE Insp Rept 50-339/79-17 on 790506-08 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Safeguards Branch 79/06/28 2pp

7906200511 IE Insp Rept 50-339/79-17 on 790506-08 No noncompliance noted Major areas inspected preexercise Insp of reactor vessel welds & steam generator C tube outer observation, data review & evaluation
GOLDSMAN, I E Region 2, Atlanta, Safeguards Branch 79/06/28 2pp

7906200519 Forwards IE Insp Repts 50-338/79-14 & 50-339/79-09 on 790520-29 No noncompliance noted
BUTTERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/18 2pp

7906200522 IE Insp Repts 50-338/79-14 & 50-339/79-09 on 790520-29 No noncompliance noted Major areas inspected mailed source leak tests, followup on inspector identified items & installation & calibr of radiation monitoring age
JACKSON, A H Region 2, Atlanta, Office of the Director 79/06/18 4pp

7906200531 Forwards IE Insp Rept 50-338/79-10 & 50-339/79-18 on 790509-09 No noncompliance noted
LUNDBERG, C Region 2, Atlanta, Office of the Director 79/06/19 2pp

7906200518 IE Insp Rept 50-338/79-10 & 50-339/79-18 on 790509-09 No noncompliance noted Major areas inspected operations review IE bulletin & circular review & review of containment purge
GANTRELL, F B - BRIDGES, E H - HANFORD, R C Region 2, Atlanta, Office of the Director 79/06/18 1pp

7906200504 Forwards IE Insp Repts 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200527 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

7906200532 IE Insp 50-339/79-23, 50-406/79-01 & 50-407/79-01 on 790610-12 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 79/06/25 2pp

--7906180018 Forwards IE Insp Repts 50-338/79-09 & 50-339/79-16 on 790209-0202 & notice of violation
LEBUE, C Region 3, Atlanta, Reactor Operations Nuclear
Support Branch 79/03/29 2pg

--7906180021 Notice of violation from Insp on 790209-0202
* Region 3, Atlanta, Office of the Director 79/03/22 1p

--7906180035 IE Insp Repts 50-338/79-09 & 50-339/79-16 on 790209-0202
Noncompliance noted failure to follow procedures for
assessing completion of corrective action
KIDDER, R Region 3, Atlanta, Office of the Director
KIDDER, L G Region 3, Atlanta, Reactor Operations Nuclear
Support Branch 79/03/22 1pg

7906180047 Advice of response to IE Bulletin 79-03 re Yongestown weld
defects by 790601
BROOK, H C Virginia Electric & Power Co 79/05/10 1p

7906180036 Response to IE Bulletin 79-03 Forwards "Failure of Bolemaid
Operated Valves to Meet IE Bulletin 79-03 Nuclear
Qualification Requirements"
STALLINGS, D H Virginia Electric & Power Co 79/06/14 1p

--7906180038 "Failure of Bolemaid Operated Valves to Meet IE Bulletin
79-03 Nuclear Qualification Requirements" Environmentally
unqualified valves have been or will be replaced
* Virginia Electric & Power Co 79/06/14 3pg

G Reportable occurrences, LERs & related correspondence

7906200240 Notification that six unlicensed operated valves on containment
isolation valves in sampling system located around
qualification data all valves replaced prior to fuel
loading
BROOK, H C Virginia Electric & Power Co 79/03/16 2pg

7906180442 Technical report re potential overloads of electrical system
supplying offsite power for startup calculations
Review about automatic shedding of certain non-essential
normal loads will provide adequate voltage profile
BROOK, H C Virginia Electric & Power Co 79/03/23 3pg

7906180452 Bulletin final report on deficiencies reported 790601 angle iron
bracket located on exhaust ducting of diesel generator
cooling fans Failure of angle iron brace tack welds could
have caused fan brackets removed
BROOK, H C Virginia Electric & Power Co 79/03/23 2pg

7906180178 Final deficiency report re pipe stress analysis passing
through main steam valve because manufacturer of girth
spray nozzle pump will complete work to new space &
return pump to use position to fuel loading
BROOK, H C Virginia Electric & Power Co 79/06/06 2pg

7906200038 Transcript of 790619 meeting in Bethesda, MD by 201-458
ROSENTHAL, A S ; BUCK, J W ; FARRAR, H C Atomic Safety and Licensing
Appeal Panel 79/06/19 20pg

7906200070 Transcript of 790620 hearing in Bethesda, MD by 459-423
ROSENTHAL, A S ; BUCK, J W ; FARRAR, H C Atomic Safety and Licensing
Appeal Panel 79/06/20 18pg

U Congressional/Executive Correspondence

7906200057 Forwards constituent's letter re opening of plant
BUTLER, M C House of Rep 79/04/19 3pg

DOCKET 50-361 ENRICHED URANIUM ATOMIC POWER PLANT, UNIT 2

A Application/Construction stage documents & correspondence

7906180316 Notification of 790311 site visit w/visit at Monroe County, HI
to tour facility
KIDDER, L L Light Water Reactors Branch 1 79/04/22 3pg

7906200088 Lists generic items & where group documents transmitted to
BEC by DOE which are applicable to Facility
JENSEN, M H Detroit Edison Co 79/05/23 2pg

7906180378 Forwards Certificate of Rev for Amend 33 to amended &
substituted application for license
KIDDER, S H Detroit Edison Co 79/06/07 2pg

C Utility Environmental Report (ER), amendments & correspondence

7906010052 Ack receipt of 790409 interim report re boric acid block
deficiency
FIDELL, L O Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/05/01 1p

D Additional correspondence

7906200319 Forwards stipulation of contentions signed by all parties if
acceptable, stipulations should be submitted as issues by ASB
order which would also begin formal discovery
BLACK, H L Branch 1 79/03/05 1p

--7906200320 Stipulation of contentions & agreement among parties
Contentions refer to cost problems & design of radiation
monitoring system
HILLER, D Citizens for Energy & Environment BLACK, H L Branch 1
1 VOIOT, H H Detroit Edison Co 79/02/28 3pg

E Utility Final Safety Analysis Report (FSAR) & amendments

7906010222 Forwards Amend 33 to FSAR Page withheld (ref 10CFR2 7901
VOIOT, H H LeBeauf, Lamb, Leiby & Harlow 79/05/31 3pg

--7906010220 Amend 33 to FSAR Proprietary page withheld (ref 10CFR2 7901
applicable) encl
* Detroit Edison Co 79/05/29 17pg

G Inspection Reports, IE Bulletin & correspondence

06140447 Forwards IE Insp Rept 50-341/79-07 on 790314-16 & notice of
violation
FIDELL, L O Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/04/04 3pg

--7906140601 Notice of violation from Insp on 790314-16
* Region 3, Chicago, Reactor Construction & Engineering Support
Branch 79/04/04 1p

--7906140608 IE Insp Rept 50-341/79-07 on 790314-16 Noncompliance noted
Investigation began Insp corrective action
DANIELSON, D H ; VAN, J F Region 3, Chicago, Reactor
Construction & Engineering Support Branch 79/04/08 3pg

7906180156 Forwards IE Insp Rept 50-341/79-08 on 790327-08 & notice of
violation
FIDELL, L O Region 3, Chicago, Office of the Director 79/04/10 2pg

--7906180139 Notice of violation from Insp on 790327-08
* Region 3, Chicago, Office of the Director 79/04/09 1p

DOCKETED ITEMS

141

- 790420143 IE Insp Rept 90-341/79-08 re 790327-30 Noncompliance noted failure to follow procedure for welding activities & records
LEE, E M Region 3, Chicago, Office of the Director 79/04/02 2pp
- 7904140501 Forwards IE Insp Rept 90-341/79-10 re 790329-30 Noncompliance noted
HINES, E Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/12 2pp
- 790414047 IE Insp Rept 90-341/79-10 re 790329-30 Noncompliance noted Major areas inspected followed by previous items of noncompliance & related unresolved matters
DANIELSON, D H, WILLIAMS, C C Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/09 5pp
- 790420097 Forwards IE Insp Rept 90-341/79-09 re 790328-04 & notice of violation
FIDORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/19 2pp
- 790420094 Notice of violation from Insp re 790328-04
Region 3, Chicago, Office of the Director 79/05/19 2pp
- 790420092 IE Insp Rept 90-341/79-09 re 790328-04 Noncompliance noted inadequate qualifications of personnel & mark of test records
WATTS, R S, HARRIS, E J, DANIELSON, D H Region 3, Chicago, Office of the Director 79/04/16 13pp
- 7904120104 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Inspection Support Problem" No action required
KOPFLER, J O Region 3, Chicago, Office of the Director 79/05/07 1p
- 7904040449 Act receipt of 790426 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 90-341/79-05
FIDORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/10 1p
- 790404033 Response to NRC 790327 ltr re violations noted in IE Insp Rept 90-341/79-05 Corrective actions review of backfill repair was done to evaluate quantities & determine areas not adequately tested
HINES, E Detroit Edison Co 79/04/26 5pp
- 7904104346 Response to IE Bulletin 79-09 re failure in SE Type AN-2 low voltage power circuit breaker breaker not in use or planned for use
HINES, E Detroit Edison Co 79/05/10 2pp
- 7904100092 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
KOPFLER, J O Region 3, Chicago, Office of the Director 79/05/11 1p
- 7904030228 Forwards response to IE Bulletin 79-03 dtd 790312 ABNE
84-312, Type 394 or other welded pipe w/sg by Youngstown Welding & Engineering Co was in use at facility
HINES, E Detroit Edison Co 79/05/14 4pp
- 7904100079 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Licensee action required
KOPFLER, J O Region 3, Chicago, Office of the Director 79/05/02 1p
- 790400097 Act receipt of 790504 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 90-341/79-03
FIDORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/23 1p
- 7904040508 Response to NRC ltr re violations noted in IE Insp Rept 90-341/79-07 Corrective actions Wigner & Becker procedures were modified
HINES, E Detroit Edison Co 79/05/04, 5pp
- 7904200118 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Dwyer Creek Reactor"
KOPFLER, J O Region 3, Chicago, Office of the Director 79/05/29 1p
- 7904200407 Act receipt of 790501 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 90-341/79-05
FIDORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/30 1p
- 7904200404 Response to NRC 790410 ltr re violation noted in IE Insp Rept 90-341/79-08 Corrective actions written requested until he issued his general foreman for unauthorized methods of implementing repairs and training will be given
HINES, E Detroit Edison Co 79/05/11 4pp
- 5 Reportable occurrences, LERs & related correspondence
- 7904200376 Act receipt of 790501 final rept re torus ring beam weld indications Review will be completed during future Insp
FIDORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/23 1p
- 7904000363 Confirms 790419 action in which NRC notified that the variation in insulation thickness on LE cable jacketing was determined "nonreportable"
FAHRNER, W J Detroit Edison Co 79/05/25 2pp
- 7904000344 Confirms 790421 action in which NRC notified that the cracking of insulator vane of core spray pump B & C was determined "nonreportable"
FAHRNER, W J Detroit Edison Co 79/05/25 1p
- DOCKET 90-344 TRIUMF NUCLEAR PLANT, UNIT 1
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 7904200466 Forwards add info re installation of isolation outcrops at local control stations for safe shutdown equipment & add design details for installation in 790326 SER in response to 790426 & 2418 requests
GOSWAMI, G Portland General Electric Co 79/06/10 46pp
- F Security, medical, emergency & fire protection plans
- 7904200302 Forwards request for add info re fire protection to complete safety evaluation
SCHWENKER, A Operating Reactors Branch 1 (Fns 790425) 79/04/16 4pp
- G Administrative correspondence
- 7904070360 First set of interrogatories submitted to H Bell & Consolidated Intervenor Affidavit & Certificate of Due Diligence
JOHNSON, R W Portland General Electric Co 79/03/05 10pp
- 7904070362 First set of interrogatories submitted to E Roselle & Consolidated Intervenor Affidavit & Certificate of Due Diligence
JOHNSON, R W Portland General Electric Co 79/03/03 10pp
- 7904100712 Motion for order compelling H Bell & Consolidated Intervenor to respond to ENCI 790329 interrogatories
Certificate of Due Diligence
JOHNSON, R W Portland General Electric Co ARLAND, H. CARB, A V Loomis-Henrichs, Inc. Austin & Tall 79/03/23 4pp
- 7904100719 Licensee's first set of interrogatories to H Bell & Consolidated Intervenor Affidavit & Certificate of Due Diligence
JOHNSON, R W Portland General Electric Co 79/03/03 14pp
- 7904040396 Confirms action taken during prehearing conference, Phase II, re contents of Affidavit for Safe Power & Consolidated Intervenor's Affidavit & Certificate of Due Diligence
HILLER, R E Atomic Safety and Licensing Board Panel 79/04/12 4pp
- 7904040149 Answers by Consolidated Intervenor to second phase of first set of NRC Interrogatories Certificate of Due Diligence
BELL, R Affiliation Unknown 79/04/14 5pp
- 7904040149 Answers by Consolidated Intervenor to licensee's first set of interrogatories
BELL, R Affiliation Unknown 79/04/14 4pp
- 7904050074 Opposes 790410 petition of EN Garret pro se add Condition for Safe Power, seeking NRC review of ARLAND 790321 decision Certificate of Due Diligence
HARTSHORN, W Portland General Electric Co 79/04/20 5pp
- 7904200410 Provides answers to intervenor's questions raised in 790326 prehearing conference, Certificate of Due Diligence
ERIKSSON, L W Pacific Gas & Electric Co 79/04/20 18pp

DOCKETED ITEMS

7904060109 Responses to intervenor's questions raised at 790331 prehearing conference. Certificate of Doc. seal
ELISABETH L. H. Portland General Electric Co 79/04/20 10pp

J Insurance & indemnity information

7904060297 Forwards executed Amend 4 to Indemnity Agreement B-70
GREGORY, E. Portland General Electric Co 79/04/24 3pp

K. Utility Final Safety Analysis Report (FSAR) & amendments

7904060301 Forwards logic diagrams (modified FSAR Figures 7.2-11 in response to NRC request for add'l info in support of license Amend 24 Diagrams show change in precursor safety injection logic. Tack Space Change and
BOSCH, J. J. Portland General Electric Co 79/04/29 4pp

P. Operating license stage documents & correspondence

7904060416 Ack receipt of w/rt 790306 for containing responses to questions re possible transfer of grade out unit location across site since proposed transportation has been abandoned. Future actions have been discussed
SCHMIDT, A. Operating Reactors Branch 1 (P) 790425 79/04/20 2pp

7904060419 Summary of 790312 meeting w/rt re auxiliary feedwater sys & tests required in non-BMW plants in light of TMI-2
TRAVIS, L. C. Operating Reactors Branch 1 (P) 790425 79/05/10 2pp

7904060549 Responds to NRC 780128 ltr re containment purging during normal plant operation. Provides add'l info on isolation valve closure & seismic Category I hydrogen vent sys
GOODMAN, C. Portland General Electric Co 79/05/21 3pp

7904101030 Forwards License Change Application 3A requesting amend of License NP-1 Application evaluated as Class III
Certificate of Doc. seal
BROOKS, J. J. Portland General Electric Co 79/04/24 2pp

7904101036 License Change Application 3A requesting change to License NP-1 engineered safeguard features activation logic in precursor
BROOKS, J. J. Portland General Electric Co 79/04/24 3pp

7904104025 Ack receipt of NRC 790318 ltr re FGE-1020 Response schedule will be confirmed by 790419
JOHNSON, S. W. Portland General Electric Co 79/04/21 1p

7904200344 Responds to 790325 request for info on PWR feedwater lines. Results of radiographic loop not yet complete. Forwards isometric drawings re feedwater lines to steam generator, details of feedwater control system & supports
GOODMAN, C. Portland General Electric Co 79/04/18 23pp

7904201180 Responses late receipt of NRC 790318 ltr forwarding questions requesting add'l technical plant info. Provides more formal arrangements re NRC distribution of plant-related correspondence
FRANK, L. Oregon, State of 79/04/19 1p

add'l info re proposed control bldg design in unit. Further responses to be submitted until along defense M will be modified. Nuclear Certificate of Doc. seal
General Electric Co 79/06/02 40pp

to & correspondence

"Lower Reactor Vessel Head
closed"
"by the Director"

7904200602 Forwards licensee response to IE Bulletin 79-06A, "Review of Operational Errors & Dry Missalignments Identified During TMI Accident"
WAGS, S. A. Light Water Reactors Branch 4 79/03/16 1p

7904200605 Submits update to 790484 response to IE Bulletin 79-06A, Revision 1 re tripping of precursor water level stabilizes & resetting of containment isolation
GOODMAN, C. Portland General Electric Co 79/05/04 5pp

7904060342 Forwards IE Circular 79-08, "Adopted Extension - Low Enriched U"
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/03/18 1p

7904060345 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/03/22 1p

7904060354 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Quyer Creek Reactor"
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/03/21 1p

7904060361 Forwards 790510 telex w/rt Transmittal in response to IE Bulletin 79-01, Item 4. Location of valve MS 10010 is below past-LOC containment water level. Design activities initiated to relocate valve
GOODMAN, C. Portland General Electric Co 79/04/21 2pp

N Periodic operating reports & related correspondence

7904060322 Forwards monthly operating rept for May 1979
WITHERS, S. D. Portland General Electric Co 79/04/05 1p

7904060327 Monthly operating rept for May 1979
BOLD, S. D. Portland General Electric Co 79/04/05 4pp

O Reportable occurrences, LERs & related correspondence

7904060101 Notifies of potential deficiency in impeller locknut design for containment sump pumps. Defect could cause locknut to loosen & lead to pump failure if impeller contained pump running
GOODMAN, C. Portland General Electric Co 79/04/16 1p

7904100321 Forwards PWR-79-474N
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/03/14 1p

7904100340 Forwards PWR-79-474D
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/03/21 1p

7904100343 Forwards PWR-79-474P
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/03/22 1p

7904100347 Forwards LER 79-007/03L-0
WITHERS, S. D. Portland General Electric Co 79/03/23 1p

7904100350 LER 79-007/03L-0 re 790427, following reactor trip, feedwater isolation valve failed to close automatically. Caused by sticking piston valve in hydraulic operator sys. Valve closed manually. Valve will be inspected
PERRY, J. C. Portland General Electric Co 79/03/28 2pp

7904100345 Forwards PWR-79-474D
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/03/20 1p

7904200323 Forwards LER 79-008/03T-0
WITHERS, S. D. Portland General Electric Co 79/03/21 1p

7904200344 LER 79-008/03T-0 re 790521, during review of containment purge sys design, containment purge supply ducting was overscreened. Caused by faulty design which does not allow for effects of dynamic forces following LOCA
OSWALD, M. H. Portland General Electric Co 79/05/01 2pp

7904104025 Forwards LER 79-039/03L-0
WITHERS, S. D. Portland General Electric Co 79/04/04 1p

DOCKETED ITEMS

790610436 LER 79-09/02L-0 on 790504 three transmitters found less conservative than Tech Spec limits caused by normal instrument drift Transmitters monitor within Tech Spec limits
BOHNETT, R P. Peralta General Electric Co. 79/04/04 0pp

DOCKET NO-334 DAVIS-BORNE NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

790600523 Discusses 790507-11 Insp re implementation of parts of approved security plan Plans should be implemented in accordance w/what is LER withheld (ref ISCRP 7901)
REGAN, J S. Region 3, Chicago, Office of the Director 79/03/16 1p

790600503 Emergency Procedures 1203 26 when supply gas rupture
MISOL, L. ; MURRAY, I S. Toledo Edison Co. 79/06/02 17pp

D. Adjudicatory correspondence

7906070145 Orders shutdown of plant until AEC determines that still has completed identified changes in safety sys operating procedures & employee training
CHALK, S J. Office of the Secretary of the Commission 79/05/16 10pp

790610024 Requests denial of 790424 demands by Toledo Coalition For Safe Energy to human & mechanical operational problems emerging plans & request for hearing demands vague & inconsistent w/regulations
CHURCHILL, S W. Shaw, Pittman, Pelts, & Townbridge 79/06/08 2pp

J. Insurance & indemnity information

790600036 Parsons Endorsements 20 & 23 in NRC's Policy NF-92
LLOYD, S D. Marsh & McLennan, H & M Nuclear Consultants, Inc. Div 79/04/12 0pp

H. Activist correspondence

790620066 Notifies that certain documents were removed from AGLAB secretary's desk by unauthorized person Documents found in another off investigation initiated
BUTLER, H C. Atomic Safety and Licensing Appeal Panel 79/10/02 0pp

790602070 Forwards AGLAB memo issued in Davis-Besse & Perry proceeding re missing papers in file
ROSENTHAL, A S. Atomic Safety and Licensing Appeal Panel 79/10/02 1p

790602077 Forwards 791107 re: "Investigation of Unauthorized Removal of AGLAB Documents - Rept withheld (ref FDA Exemptions 7A & 7C)
CUMMINGS, J J. Office of Inspector & Auditor 79/11/10 1p

790602083 Provides info re limited inquiry into loss or theft of AGLAB sensitive documents Info partly withheld due to enforcement proceedings (ref FDA Exemptions 7A & 7C)
ATWELL, E L. Division of Security 79/10/05 2pp

790602092 Provides summary of investigation into alleged removal of documents from AGLAB after info partly withheld due to enforcement proceedings (ref FDA Exemptions 7A & 7C)
ABSTON, G D. Office of Inspector & Auditor 79/11/07 4pp

790602099 Comments as Ofc of Inspector & Auditor re: investigation of document removal Info partly withheld due to enforcement proceedings (ref FDA Exemption 7A)
ROSENTHAL, A S. Atomic Safety and Licensing Appeal Panel 79/11/08 2pp

790602036 Responds to 791107 memo re investigation of document removal Info partly withheld due to enforcement proceedings - (ref FDA Exemption 7A)
BURNETT, C. Division of Security 79/12/04 2pp

790602047 Comments as Ofc of Inspector & Auditor re: investigation of document removal Info partly withheld due to enforcement proceedings (ref FDA Exemption 7A & 7C) Forwards Washington Post 790528, G213 & 20 articles
HURNEY, F. F. Office of Inspector & Auditor 79/02/20 7pp

790602034 Comments as Ofc of Inspector & Auditor re: investigation of document removal Info partly withheld due to enforcement proceedings (ref FDA Exemption 7A)
CUMMINGS, J J. Office of Inspector & Auditor 79/04/22 2pp

G. Advisory Committee on Reactor Safeguards reports & correspondence

790602017 Submits requested change to Page 2/4 3-13 & associated safety evaluation, increasing certain safety margins
ROE, L E. Toledo Edison Co. 77/10/27 0pp

F. Operating license stage documents & correspondence

790602008 Requests status 1987 Forwarded questions re design similarities to TH-1
AHMAD, J P. Commission 79/03/27 0pp

790602019 Responds to 790507 request re plant status Unaware of any current problems of immediate health & safety significance Delays in power testing monitored by Region III Plans to evaluate control sys to improve regulatory performance
GORTON, H R. Office of Nuclear Reactor Regulation, BWG, J C. Office of Inspection & Enforcement 79/04/13 3pp

790602032 Requests plant status report Forwarded questions
AHMAD, J P. Commission 79/03/29 0pp

790602074 Submits items of possible concern for inclusion in order to TH-1 plant license Forwarded 790328 PLO re reactor trip & subsequent shutdown at TH-2
AHMAD, J P. Commission 79/04/27 1p

790602006 Responds to 790501 request for info re QA program Util nuclear QA manual, revised 790108, to use for shipments of Type B casks
ROE, L E. Toledo Edison Co. 79/04/30 1p

790610034 Notification of 790603 meeting w/Util in Bethesda, MD to discuss facility upgrading to enhance ability to respond to Reactor Transients Time change in 9:30 AM
VIGOR, S G. Operating Reactors Branch 4 (P# 790625) 79/05/02 1p

790610012 Notification of 790608 meeting w/Util in Bethesda, MD to present plan for control grade hardwired reactor trips based on loss of Reactor & turbine trip conditions
SMITH, D. N. Operating Reactors Branch 4 (P# 790625) 79/05/08 1p

790602084 Requests solid radioactive product control program not included in 790316 radiological effluent Tech Specs
REID, R W. Operating Reactors Branch 4 (P# 790625) 79/05/13 2pp

790603040 Requests site emergency plan & implementing procedures, site maps showing location & grid numbers of onsite & offsite source monitoring stations & site maps used for offsite dose determinations or evacuations
REFFEL, G D. Region 3, Chicago, Office of the Director 79/05/17 1p

790607082 Summary of 790517 Affirmation Session 79-12 in Washington, DC Orders to shut down reactor for reasons of increased safety & reliability were approved
CHALK, S J. Office of the Secretary of the Commission 79/05/17 1p

790607030 Forwards revised operating procedures complying w/NRC 790509 order w/modified unit in Central Plains only
ROE, L E. Toledo Edison Co. 79/05/20 0pp

790602080 Appendix to 790508 request Submits post-mod test plans for auxiliary feedwater pump dynamic brake, Interim anticipatory reactor trip sys & auxiliary feedwater flow indicators
ROE, L E. Toledo Edison Co. 79/05/26 4pp

790602093 Forwards revised procedure matrix reflecting updated procedures modified by NRC 790507 order
ROE, L E. Toledo Edison Co. 79/05/27 4pp

790602072 Submits response to 790506 request re diesel generator lockout
ROE, L E. Toledo Edison Co. 79/05/30 3pp

790602028 Forwards info re unit actions complying w/NRC 790516 order
ROE, L E. Toledo Edison Co. 79/05/13 12pp

790602028 Forwards "Analysis of Complete Loss of Feedwater Transient for Facility," in response to request for study of reliability of auxiliary feedwater sys w/ and
ROE, L E. Toledo Edison Co. 79/05/13 1p

DOCKETED ITEMS

7902050431 Forwards responses to questions raised by NRC during 790408
site visit re procedural performance effect of flow on
power operated relief valve valve error detection & reset
functionality
RDELL, E Toledo Edison Co 79/04/18 App

7902050432 Forwards electrical drawings of PMH feedwater lines in
response to 790325 request for design info on cracking
problem
RDELL, E Toledo Edison Co 79/04/19 App

7902050434 Operated drawings of PMH feedwater lines
Toledo Edison Co 79/04/19 2pp

7902050435 Submits requested info re analysis on capability of dry &
isolated steam generator to vent auxiliary feedwater pump
30 minutes after loss of all main auxiliary feedwater &
test results for anticipatory reactor trip age
RDELL, E Toledo Edison Co 79/04/23 1pp

0 Inspection reports: DE Bulletin & correspondence

7902050436 Forwards IE Insp Rept 50-344/79-04 on 790305-09 a notice of
violation
HEIDENHAIN, R Region 3, Chicago, Reactor Operations Nuclear
Support Branch 79/03/23 2pp

7902050438 Notice of violation from Insp on 790305-09
Region 3, Chicago, Office of the Director 79/03/27 1p

7902050439 IE Insp Rept 50-344/79-04 on 790305-09 Noncompliance noted
failure to follow procedures
GREGG, J. B. CHEN, E. T. STEINER, J. F. Region 3, Chicago,
Office of the Director 79/03/27 1pp

7902050440 BSW site inspector daily rept on 790402 Plant status reactor
in Mode 5 cold shutdown for main general valve maint &
condenser leak tests currently in progress
FARBER, T. Region 3, Chicago, Office of the Director 79/04/07 2pp

7902050441 BSW site inspector daily rept on 790402 Plant status reactor
in Mode 5 cold shutdown for main general valve maint &
condenser leak tests currently in progress
FARBER, T., SMITH, J. Region 3, Chicago, Office of the Director
79/04/08 2pp

7902050442 BSW site inspector daily rept on 790402 Plant status reactor
in Mode 5 cold shutdown for main general valve maint &
condenser leak tests currently in progress
FARBER, T., SMITH, J. Region 3, Chicago, Office of the Director
79/04/09 1p

7902050443 BSW site inspector daily rept on 790402 Plant status reactor
in Mode 5 cold shutdown for main general valve maint &
condenser leak tests currently in progress
FARBER, T., SMITH, J., RIZEN, D. Region 3, Chicago, Office of the
Director 79/04/10 2pp

7902050444 BSW site inspector daily rept on 790402 Plant status reactor
in Mode 5 cold shutdown for main general valve maint &
condenser leak tests currently in progress
FARBER, T. N. SMITH, R. N., SMITH, J. D. Region 3, Chicago, Office of
the Director 79/04/13 2pp

re daily rept on 790412 Plant status reactor
outage Administrative controls

JOHN, M. S. Region 3, Chicago, Office of
the Director 79/04/12 2pp

daily rept on 790414 Plant status reactor
No major equipment out
Region 3, Chicago, Office of the Director

7902050445 BSW site inspector daily rept on 790415 Plant status reactor
in cold shutdown for main general valve maint &
condenser leak tests currently in progress
FARBER, T., SMITH, J. S. Region 3, Chicago, Office of the Director
79/04/16 2pp

7902050446 BSW site inspector daily rept on 790412 Plant status reactor
in cold shutdown for main general valve maint &
condenser leak tests currently in progress
FARBER, T., SMITH, J. S., RIZEN, D. S. Region 3, Chicago, Office of
the Director 79/04/12 4pp

7902050447 BSW site inspector daily rept on 790417 Plant status reactor
in Mode 5 cold shutdown for main general valve maint &
condenser leak tests currently in progress
FARBER, T., SMITH, J. S. Region 3, Chicago, Office of the Director
79/04/17 2pp

7902050448 Responds to IE Bulletin 79-07 Forwards computer codes &
analytical methods used to predict stresses in safety-
related piping
GREGG, J. F. Toledo Edison Co 79/04/24 2pp

7902050449 Forwards IE Insp Rept 50-344/79-04 on 79/04/14 & 29
KAPLAN, J. D. Region 3, Chicago, Office of the Director 79/04/23 2pp

7902050450 IE Insp Rept 50-344/79-04 on 79/04/14 & 29 Noncompliance noted
STREETER, J. F., ANDERSON, E. E., VOLK, J. E. Region 3, Chicago,
Office of the Director 79/04/20 2pp

7902050451 Forwards LER 79-04/01-0
GREGG, J. D. Toledo Edison Co 79/04/23 1p

7902050452 LER 79-04/01-01-5 on 790412 voltage & time delay setpoints
of essential bus underfrequency trip relays found incorrect
caused by defective relay settings changed & time
delay & voltage setpoints adjusted
GREGG, J. D., FARBER, T. Toledo Edison Co 79/04/25 2pp

7902050453 Describes events re Jul 1978 plant operation & equipment
failures during degraded grid voltage condition
STOLZ, J. F. Light Water Reactors Branch 1 79/04/15 2pp

7902050454 Notifies that based on NRC Insp efforts, will have modified
license re protective circuitry to provide broader
coordination & isolation of critical electrical bus
KAPLAN, J. D. Region 3, Chicago, Office of the Director
77/10/30 1p

7902050455 BSW site inspector daily rept on 790420 Plant status reactor
in Mode 5 cold shutdown main outage
FARBER, T., SMITH, J., SMITH, J. S. Region 3, Chicago, Office of the
Director 79/04/20 2pp

7902050456 Forwards IE Insp Rept 50-344/79-07 on 790409-12 & notice
of violation
HEIDENHAIN, R. F. Region 3, Chicago, Office of the Director
79/04/27 2pp

7902050457 Notice of violation from Insp on 790409-12
Region 3, Chicago, Office of the Director 79/04/27 1p

7902050458 IE Insp Rept 50-344/79-07 on 790409-12 Noncompliance noted
failure to review & approve applicable procedures
recommended in Reg Guide 1.10 App A re safety relief valve
 Insp & repair
RIZEN, D. S., FARBER, T. L. Region 3, Chicago, Office of the
Director 79/04/23 4pp

7902050459 Ack receipt of 790304 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-344/79-03
GREGG, J. D. Region 3, Chicago, Fuel Facility & Materials Safety
Branch 79/04/20 1p

7902050460 Responds to NRC 790304 ltr re violations noted in IE Insp
Rept 50-344/79-03 Corrective actions: bus antennas to insure
bus lock
GREGG, J. S. Toledo Edison Co 79/03/26 2pp

7902050461 Forwards IE Insp Rept 50-344/79-08 on 790410
No noncompliance noted
KAPLAN, J. D. Region 3, Chicago, Office of the Director 79/04/20 2pp

7902050462 IE Insp Rept 50-344/79-08 on 790410 Noncompliance noted
Major areas: incorrect administrative & operating regulations
performance of facility
FARBER, T., SMITH, J. S., SMITH, J. S. Region 3, Chicago, Office of the
Director 79/04/20 2pp

7902050463 Responds to IE Bulletin 79-04 Describes investigation re
possible need in pipe stress analysis of swing check valves
Supporting documentation sent.
GREGG, J. D. Toledo Edison Co 79/05/03 10pp

DOCKETED ITEMS

790420097 Forwards IE Info Rept 30-346/79-09 on 790410-11 No noncompliance noted
 FISHELL, B Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/01 App

--790420050 IE Info Rept 30-346/79-09 on 790410-11 No noncompliance noted Major area inspected licensee action re IE Circular 79-08
 JAMES, R F J J HAYES, D M Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/30 App

790420044 Forwards responses to IE Bulletin 79-039 re TH-2 incident
 GRANT, J B Toledo Edison Co 79/05/04 App

790420020 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem." No action required
 NEFFLER, J O Region 3, Chicago, Office of the Director 79/05/07 App

790420018 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics." Written response required
 NEFFLER, J O Region 3, Chicago, Office of the Director 79/05/11 App

790420002 Forwards IE Info Notice 79-10, "Attempted Gaseous to New Fuel Assembly."
 NEFFLER, J O Region 3, Chicago, Office of the Director 79/05/11 App

790420003 Responds to IE Bulletin 79-09 re use of OR Type AG-2 without breakers in safety-related area Program established to ensure proper cycling, cleaning & lubrication of control rod drive control rod breakers
 GRANT, J B Toledo Edison Co 79/05/15 App

790420004 Reviews 790324 transmittal re change in response to IE Bulletin 79-008, Item 4 Procedures will not be modified to provide manual reactor trip on low pressurizer level
 GRANT, J B Toledo Edison Co 79/05/15 App

790419050 Ack receipt of 790418 ltr informing NRC of steps taken to correct violation noted in IE Info Rept 30-346/79-08
 NEFFLER, J O Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/13 App

--790419050 Responds to NRC 790322 ltr re violation noted in IE Info Rept 30-346/79-08 Corrective actions demanded which address to procedures, close review of procedures & mechanism for red
 GRANT, J B Toledo Edison Co 79/04/18 App

790420040 Submits follow-up to 790416 ltr in response to IE Bulletin 79-03 Ultrasonic examination evaluation indicates acceptance state of Section III of ASME Code, 1971 edition, are acceptable
 GRANT, J B Toledo Edison Co 79/05/16 App

790420020 Forwards IE Circular 79-08, "Attempted Exortion - Low Siphoned U"
 NEFFLER, J O Region 3, Chicago, Office of the Director 79/05/18 App

790420020 Requests info re manual trip on low pressurizer level as noted in Item 4 of IE Bulletin 79-03
 WILLIAMS, F J Division of Project Management 79/05/18 App

790420007 Forwards responses to Items 3 & 7 of IE Bulletin 79-039 re TH-2 incident (Babcock). In conjunction w/790324.15 & 16 ltr, completes responses to bulletin
 GRANT, J B Toledo Edison Co 79/05/23 App

790420016 Forwards IE Bulletin 79-11, "Facility Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required
 NEFFLER, J O Region 3, Chicago, Office of the Director 79/05/22 App

790420017 Forwards IE Info Notice 79-12, "Indication of Low Water Level in Quaker Creek Reactor."
 NEFFLER, J O Region 3, Chicago, Office of the Director 79/05/29 App

790420019 Ack receipt of 790317 ltr informing NRC of steps taken to correct violations noted in IE Info Rept 30-346/79-07
 NEFFLER, J O Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/29 App

--790420019 Responds to NRC 790427 ltr re violations noted in IE Info Rept 30-346/79-07 Corrective actions use of safety related valves ltr W-6 has been discontinued No plant procedures will be written
 GRANT, J B Toledo Edison Co 79/05/17 App

R Periodic operating reports & related correspondence

790420094 Forwards monthly operating report for May 1979
 MURRAY, T B Toledo Edison Co 79/06/06 App

--790420008 Monthly operating report for May 1979
 GRANT, J B Toledo Edison Co 79/06/06 App

G Reportable occurrences, LDRs & related correspondence

790420009 Summary of 790500 meeting w/Util & Reactor in Bethesda, MD re license design of hard wire controlled reactor trip caused by loss of feedwater A/W turbine trip & other matters related to NRC shutdown order
 24ET10-0 D Operating Reactors Branch 4 (Pre 790625) 79/05/13 App

790420003 RD as 790518 RD hydraulic snubbers failed 10-month functional test verifying piston movement design being conducted
 MURRAY, T B Toledo Edison Co 79/05/18 App

790420027 Forwards LER 79-056/03L-0
 MURRAY, T B Toledo Edison Co 79/05/29 App

--790420029 LER 79-056/03L-0 on 790501 excessive leakage found through containment isolation valve M232C Caused by either dirt on valve sealing surface or slipped actuator linkage Valve closed & recaller
 MURRAY, T B Toledo Edison Co 79/05/29 App

790420042 Forwards LER 79-056/03L-0
 MURRAY, T B Toledo Edison Co 79/05/30 App

--790420042 LER 79-056/03L-0 on 790503 IEM Spt 7 contact data logger failed, rendering fire & radiation remote monitoring inoperable Cause of failure unknown Computer replaced & placed in operation
 MURRAY, T B Toledo Edison Co 79/05/30 App

790420020 Forwards LER 79-057/01L-0
 MURRAY, T B Toledo Edison Co 79/06/06 App

--790420020 LER 79-057/01L-0 on 790518 hydraulic snubbers may not have fulfilled their functional requirements Cause under investigation but possibly from improper installation of snubbers during coast
 MURRAY, T B Toledo Edison Co 79/05/30 App

790420028 Forwards LER 79-034/01L-2
 MURRAY, T B Toledo Edison Co 79/06/01 App

--790420028 LER 79-034/01L-2 on 790518 HP pump 1-1 stopped, due to low recirculation flow indication Caused by inability of heat trace to maintain HP pump recirculation line temp above freezing Thermostat setting increased
 MURRAY, T B Toledo Edison Co 79/05/23 App

790420046 Forwards LER 79-060/03L-0
 MURRAY, T B Toledo Edison Co 79/06/13 App

--790420046 LER 79-060/03L-0 on 790519 fire barrier removed to allow removal of hydraulic snubbers but continuous fire watch was not established Caused by facility procedure not made re hydraulic snubber testing procedure
 MURRAY, T B Toledo Edison Co 79/06/13 App

790420049 Forwards LER 79-059/03L-0
 MURRAY, T B Toledo Edison Co 79/06/13 App

--790420051 LER 79-059/03L-0 on 790517 unsealed hole discovered in fire barrier floor Caused by uncompleted survey of work items, gap sealed & training meeting held w/working & crew supervisors
 MURRAY, T B Toledo Edison Co 79/06/13 App

790420052 Forwards LER 79-061/03L-0
 MURRAY, T B Toledo Edison Co 79/06/14 App

DOCKETED ITEMS

--7906202039 LER 79-061/03L-0 on 790618 central room emergency danger
790618A, status in open position during surveillance testing
caused by humidity causing brass bushings of shaft damper
required 5. Humidifiers refueled.
BUDAPHE, J. J. Toledo Edison Co 79/06/14 2pp

7906202037 Forwards LER 79-062/03L-0
MURRAY, T. D. Toledo Edison Co 79/06/15 1p

--790620403 LER 79-062/03L-0 on 790621 automatic feedwater suction
pressure switches found inoperative specified maintenance caused
by instrument drift & component failure. Switches returned to
normal operation on 790623
HARRIS, J. J. KITCHENS, D. Toledo Edison Co 79/06/15 4pp

7906202035 Forwards LER 79-062/03L-0
MURRAY, T. D. Toledo Edison Co 79/06/15 1p

--7906202035 LER 79-062/03L-0 on 790623 containment pressurizer smoke
detector BB 8828 did not alarm when tested caused by broken
wire in detector fixed hose wire repaired & detector
successfully tested
CHERRY, R. C. Toledo Edison Co 79/06/28 2pp

7906202035 Forwards LER 79-062/03L-0
MURRAY, T. D. Toledo Edison Co 79/06/22 1p

--7906202035 LER 79-062/03L-0 on 790626 heated water storage tank
isolation valves 307A & B were mistakenly closed. Closed by
personnel error. Valves reopened & auxiliary operator
disciplined
BEGAL, D. H. Toledo Edison Co 79/06/26 3pp

DOCKET 79-048 JOSEPH H. FANLEY NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

7906202040 Responds to 790612 ltr re delays in implementing
requirements of 10CFR72.55. Region II should be notified when
full compliance is achieved & compensatory measures are
discussed
SCHMIDTKE, A. Operating Reactors Branch 1 (Pfr 790625) 79/06/30
2pp

F. Operating license stage documents & correspondence

7906202040 Discusses review of unit 790606 revised ECCS analysis, which
satisfies criteria of NRC 740427 order for end of license
Forwards safety evaluation of 2nd water correction to ECCS
analysis
SCHMIDTKE, A. Operating Reactors Branch 1 (Pfr 790625) 79/06/29
2pp

--7906202047 Safety evaluation supporting end of 2nd water correction to
ECCS analysis
Operating Reactors Branch 1 (Pfr 790625) 79/06/29 4pp

7906202039 Summary of 790608 meeting w/ unit in Bethesda, MD re auxiliary
feedwater age & related info
BREWSTER, A. Operating Reactors Branch 1 (Pfr 790625) 79/06/15
4pp

ion of 790606 meeting w/ unit to discuss Age 1
and Tech Spec proposed by 790616 for
aging Reactors Branch 1 (Pfr 790625) 79/06/22

Isolation of bus prerequisites for startup after
stop term means of reactor
unit have been installed
= C 79/06/28 1p

Reactor limits in response to ABC
vings and H/O once
79/06/15 140pp

7906202047 Forwards proposed Tech Spec changes re containment purge
gas & single dropped rad protection safety evaluation req
CLAYTON, F. L. Alabama Power Co 79/06/20 10pp

G. Inspection reports, IE Bulletin & correspondence

7906202040 Forwards IE Insp Rept 80-348/79-11 on 790612-16 Noncompliance noted
recompilance noted
BUTLER, J. E. Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 79/06/29 2pp

--790620403A IE Insp Rept 80-348/79-11 on 790612-16 Noncompliance
noted Major areas inspected temporary shielding re
safety-related piping & separation of containment waste
gas from noncontainment plant gas
HIGLEY, C. H. 01899, A. P. Region 2, Atlanta, Fuel Facility &
Materials Safety Branch 79/06/29 7pp

7906202040 Forwards IE Insp Rept 80-348/79-11 on 790627-30 No
noncompliance noted
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 79/06/12 2pp

--7906202039 IE Insp Rept 80-348/79-11 on 790627-30 No noncompliance
noted Major areas inspected refueling activities
VIGOR, L. B. Region 2, Atlanta, Office of the
Director 79/06/12 4pp

7906202039 Forwards IE Insp Rept 80-348/79-11 & 50-364/79-09 on
790627-30 No noncompliance noted
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 79/06/17 2pp

--790620403 IE Insp Repts 80-348/79-11 & 50-364/79-09 on 790627-30 No
noncompliance noted Major areas inspected procedural
test procedures & test procedures for mod & refueling
WISNER, A. D. Region 2, Atlanta, Office of the
Director 79/06/16 4pp

7906202040 Responds to IE Bulletin 79-06 & 79-06A, Revision 1
Forwards info re TME incident Proposed design & Tech Spec
changes will be submitted by 790618
CLAYTON, F. L. Alabama Power Co 79/06/26 21pp

7906202040 Act receipt of 790627 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 80-348/79-11 &
50-364/79-09
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 79/06/07 1p

--7906202047 Responds to NRC 790611 ltr re violations noted in IE Insp
Rept 80-348/79-11 & 50-364/79-09 Corrective actions new
in-house procedure implemented to control electrical prints &
construction of all final supervisory
CLAYTON, F. L. Alabama Power Co 79/06/27 2pp

--7906202048 Forwards IE Insp Repts 80-348/79-11 & 50-364/79-09 on
790627-30 & notice of violation
MURPHY, C. E. Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 79/06/11 2pp

--7906202049 Notice of violation from Insp on 790627-30
= Region 2, Atlanta, Office of the Director 79/06/12 1p

--7906202050 IE Insp Repts 80-348/79-11 & 50-364/79-09 on 790627-30
Noncompliance noted failure to control superheated drawings
MONT, B. A. Region 2, Atlanta, Office of the Director, HDSB, A. H.
Region 2, Atlanta, Reactor Construction & Engineering Support
Branch 79/06/12 4pp

7906190218 Act receipt of 790625 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 80-348/79-11
KORSAK, B. Region 2, Atlanta, Safeguards Branch 79/06/29 1p

--7906190218 Forwards IE Insp Rept 80-348/79-09 on 790612-16 Notice of
violation withheld (ref 10CFR 7901
KORSAK, B. Region 2, Atlanta, Safeguards Branch 79/06/29
2pp

--7906190223 IE Insp Rept 80-348/79-09 on 790612-16 Noncompliance noted
infraction re protected area control/protected area
isolation zone & vital area control Details withheld
(ref 10CFR 7901
RODRIGUEZ, J. H. Region 2, Atlanta, Office of the Director
TODD, J. Region 2, Atlanta, Safeguards Branch 79/06/29
1p

7906202047 Forwards IE Info Notice 79-12, "Assessment Damage to New Fuel
Assembly
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/06/10 1p

7906100000 Forwards IE Bulletin 79-10, "Qualification Training
Program Activities." Initial response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/06/11 1p

7906070761 Responds to IE Bulletin 79-09 & IE Type AK-2 circuit breakers
are used in safety-related features at Unit 1 & 2
CLAYTON, F. L. Alabama Power Co 79/06/18 2pp

790420223 Forwarded info in response to IE Bulletin 79-10 re qualification training program
CLAYTON, F. L. Alabama Power Co 79/05/22 3pp

B Periodic operating reports & related correspondence

7904190228 Forwarded monthly operating rept for May 1979
CLAYTON, F. L. Alabama Power Co 79/05/12 1p

--7904190260 Monthly operating rept for May 1979
HAINBROTH, M. G. Alabama Power Co 79/05/01 4pp

C Reportable occurrences, LERs & related correspondence

790420290 FDIA request for documents re abnormal occurrences at plants; info re Westinghouse proposed nuclear fuel assembly plant in Prattville, AL & info re transportation of nuclear waste & fuel through AL
SHRER, D. L. Affiliation Unknown 79/04/25 2pp

7904203285 Forwarded nonroutine environ operating rept providing 30-day written notification of 790315 occurrence
CLAYTON, F. L. Alabama Power Co 79/05/28 1p

--7904203087 Nonroutine environ operating rept discussing 790320-0514 drainage of 1,960 gallons contaminated water onto Unit 2
floor drain pipe. Caused by inadequate design change control
Unit was plugged
Alabama Power Co 79/05/25 3pp

7904202277 Forwarded LER 79-021/017-2
CLAYTON, F. L. Alabama Power Co 79/05/29 1p

--7904203283 LER 79-021/017-2 on 790412 initial results of test program revealed statistical sampling would not provide probability of greater than 95% anchor bolt reliability. Bolt testing program expanded to include 100% testing
HAINBROTH, M. G. Alabama Power Co 79/05/29 4pp

7904203077 Response to 790425 FDIA request for documents computer printout of abnormal occurrences at plants until May 1979; power on "Transportation of Nuclear Fuel & Waste." & list of package designs for which title is registered
MELTON, J. H. Division of Water and Records 79/05/30 57pp

7904203238 Forwarded LER 79-019/021-1
CLAYTON, F. L. Alabama Power Co 79/05/08 1p

--7904203042 LER 79-019/021-1 on 790425 fluoride & chloride concentrations in PCB in violation of Tech Spec limits. Cause not determined. RCR integrity not impaired & acceptable for continued operation
HAINBROTH, M. G. Alabama Power Co 79/05/08 1p

7904203289 Forwarded LER 79-017/017-2
CLAYTON, F. L. Alabama Power Co 79/05/18 1p

--7904203092 LER 79-017/017-2 on 790320 unit notified by Westinghouse of single dropped rod w/potential for calculated SDR ratios lower than required by NRC for floating nuclear plants. Cause by incorrect measurement during rod drop events
HAINBROTH, M. G. Alabama Power Co 79/05/18 3pp

7904203290 Forwarded LER 79-021/017-3
CLAYTON, F. L. Alabama Power Co 79/05/19 1p

--7904203032 LER 79-021/017-3 on 790412 statistical sampling of Helium Category I anchor bolts would not provide probability greater than 95% reliability. Cause under investigation. Testing extended to 100% verification of aluminum pipe
HAINBROTH, M. G. Alabama Power Co 79/05/19 4pp

7904203033 Forwarded 790418 ltr to EPA re item of noncompliance. Analysis of turbine bleed pump effluent showed 9.12 ppm. Cause by error in sampling & analysis steps have been taken to ensure violation does not recur
CLAYTON, F. L. Alabama Power Co 79/05/19 2pp

DOCKET 90-382 LINCOLN GENERATING STATION, UNIT 1

A Application/construction stage documents & correspondence

7904203023 Discusses effect of TMI-2 incident on proposed cant of nuclear facilities
BENTON, A. S. Office of Nuclear Reactor Regulation 79/05/11 3pp

C Adjudicatory correspondence

7904142479 Requests NRC position on nuclear plant cant in Limerick Township, PA
RENNER, R. H. Region 1, Philadelphia, Office of the Director 79/04/12 2pp

7904200085 Opposes cant of facilities in close proximity to populated areas. Plants should be built at least 30 miles from densely populated areas
GODDARD, S. J. Affiliation Unknown 79/04/27 1p

H General correspondence

7904202277 Ack receipt of 790413 ltr commenting on financial responsibility of nuclear facility owners re TMI-2 incident
BENTON, A. S. Region 1, Philadelphia, Office of the Director 79/04/25 1p

--7904202280 Requests financial responsibility for TMI-2 incident be placed on Metropolitan Edison & stockholders
BENTON, A. S. Affiliation Unknown 79/04/13 2pp

7904130609 Ack receipt of 790414 ltr commenting on inadequate supply of water
BENTON, A. S. Region 1, Philadelphia, Office of the Director 79/04/20 1p

--7904202079 Comments on plant licensing & inadequate water supply
BENTON, A. S. Affiliation Unknown 79/04/14 2pp

7904102095 Ack receipt of 790412 ltr. Board of Supervisors will be placed on Metropolitan Edison for results re results of TMI investigation. No current plans to close cant of nuclear power plants. Facility will be formally reviewed
BENTON, A. S. Office of Nuclear Reactor Regulation 79/05/14 2pp

--7904202088 Expresses concern of Board of Supervisors of Limerick Township, PA re continued cant of facility in light of TMI accident. Requests NRC to investigate safety of facility
RENNER, R. H. Pottstown, PA 79/04/13 2pp

G Inspection reports, IE Bulletins & correspondence

7904203043 Forwarded 18 Info Notice 79-15, "Unconforming Pipe Support Struts." No written response necessary
SHRER, D. L. Region 1, Philadelphia, Office of the Director 79/04/14 1p

7904203043 Ack receipt of 790302 ltr informing NRC of steps taken to correct violations noted in 18 Insp Repts 50-256/79-12 & 50-355/79-03
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/23 1p

--7904203047 Response to NRC 790313 ltr re violations noted in 18 Insp Repts 50-352/79-12 & 50-353/79-08. Corrective actions required insp performed & documented. Open insp plans reviewed & field staff restructured
SHRER, D. L. Philadelphia Electric Co 79/05/02 2pp

--7904203021 Forwarded IE Insp Repts 50-352/79-12 & 50-353/79-08 on 791226-29 & 790326 notice of violation
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/31 2pp

--7904203025 Notice of violation from Insp on 791226-29 & 790326
CARLSON, R. T. Region 1, Philadelphia, Office of the Director 79/05/30 1p

--7904203021 IE Insp Repts 50-352/79-12 & 50-353/79-08 on 791226-29 & 790326. Noncompliance noted. Failure to perform insp for piping installation activities
BENTON, A. S. Region 1, Philadelphia, Office of the Director 79/05/31 2pp

7904100319 Forwarded IE Bulletin 79-028, "Nuclear Incident at TMI-Supp 1." No written response required
BENTON, A. S. Region 1, Philadelphia, Office of the Director 79/04/23 1p

7904130179 Forwarded IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator & Resulted in Reactor Power Increase." No written response required
BENTON, A. S. Region 1, Philadelphia, Office of the Director 79/05/02 1p

DOCKETED ITEMS

7906020256 Responds to IE Bulletin 79-03: "Longitudinal Weld Defects in ARN 88-212 Type 304 Stainless Steel Pipe Spools Rfg by Youngman Welding & Engineering Co." Some pipe present-but not installed
BOYER, V S Philadelphia Electric Co 79/05/07 3p

7906120189 Forwards IE Info Notice 79-11: "Lower Reactor Vessel Head Insulation Support Problem - No action required"
OSHER, B H Region 1, Philadelphia, Office of the Director 79/05/07 2p

Re reportable occurrences, LERs & related correspondence

7906020258 Ack receipt of 790420 ltr forwarding limintorque lockout installation deficiency
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/02 1p

7906020261 Forwards Significant Deficiency Rept B re limintorque lockout installation deficiency
BOYER, V S Philadelphia Electric Co 79/04/20 3p

7906020263 Significant Deficiency Rept B limintorque lockout installation deficiency
Philadelphia Electric Co 79/04/20 4pp

SECRET 50-253 LINERICK GENERATING STATION, UNIT 2

A Application/construction stage documents & correspondence

7906280333 Discusses effect of TH1-2 incident on proposed const of nuclear facilities
OSHER, B H Office of Nuclear Reactor Regulation 79/05/01 3pp

0 Adjudicatory correspondence

7906140437 Requests RRC position on nuclear plant const in Linerick Township, PA
HEINER, E H Region 1, Philadelphia, Office of the Director 79/04/13 3pp

7906060808 Opposes const of facilities in close proximity to populated areas. Plans should be built at least 50 miles from densely populated areas.
OSHER, B H Affiliation Unknown 79/04/27 3p

H General correspondence

7906070277 Ack receipt of 790413 ltr commenting on financial responsibility of nuclear facility owners re TH1-2 incident
BOYER, V S Region 1, Philadelphia, Office of the Director 79/04/28 1p

7906070280 Requests financial responsibility for TH1-2 incident be placed on Metropolitan Edison & stockholders
LEITZ, L H Affiliation Unknown 79/04/13 2pp

7906130807 Ack receipt of 790414 ltr commenting on inadequate supply of water
BOYER, V S Region 1, Philadelphia, Office of the Director 79/04/28 1p

7906130809 Comments on plant licensing & inadequate water supply
BALDWIN, J A Affiliation Unknown 79/04/16 2pp

7906050197 Responds to RRC 790421 ltr re violations noted in IE Insp Rept 79-03/79-12 & 79-03/79-03. Corrective actions required. Insp performed & documented. Insp plans reviewed & field staff restructured.
BOYER, V S Philadelphia Electric Co 79/05/03 2pp

7906050201 Forwards IE Insp Repts 79-03/79-12 & 79-03/79-03 on 791226-29 & 790102 & notice of violation
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/21 2pp

7906050204 Notice of violation from Insp on 791226-29 & 790102
Region 1, Philadelphia, Office of the Director 79/05/20 1p

7906050212 IE Insp Repts 79-03/79-12 & 79-03/79-03 on 791226-129 & 790102. Reinspection noted. Failure to perform Insp for piping installation activities.
OSHER, B H Region 1, Philadelphia, Office of the Director 79/05/01 13pp

7906110331 Forwards IE Bulletin 79-08: "Nuclear Incident at TH1-2 Rept" - No written response required
OSHER, B H Region 1, Philadelphia, Office of the Director 79/04/23 1p

7906131172 Forwards IE Circular 79-07: "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase" - No written response required
OSHER, B H Region 1, Philadelphia, Office of the Director 79/05/02 1p

7906300206 Responds to IE Bulletin 79-03: "Longitudinal Weld Defects in ARN 88-212 Type 304 Stainless Steel Pipe Spools Rfg by Youngman Welding & Engineering Co." Some pipe present-but not installed.
BOYER, V S Philadelphia Electric Co 79/05/07 3p

7906120189 Forwards IE Info Notice 79-11: "Lower Reactor Vessel Head Insulation Support Problem - No action required"
OSHER, B H Region 1, Philadelphia, Office of the Director 79/05/07 2pp

Re reportable occurrences, LERs & related correspondence

7906020258 Ack receipt of 790420 ltr forwarding limintorque lockout installation deficiency
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/02 1p

7906020261 Forwards Significant Deficiency Rept B re limintorque lockout installation deficiency
BOYER, V S Philadelphia Electric Co 79/04/20 3p

7906020263 Significant Deficiency Rept B limintorque lockout installation deficiency
Philadelphia Electric Co 79/04/20 4pp

SECRET 50-254 HOPE CREEK NUCLEAR STATION, UNIT 1

0 Adjudicatory correspondence

7906280547 Motion for extension until 790431 to prepare response to ALAB-505
BALDWIN, J F Hearings Division 79/04/09 2pp

7906210060 Responds to 790322 request for info re status of remarking proceeding to develop value for rebar in Table B-7 Rept B prepared rule will be sent to NRC by 790406. Rule does not address health effects of radon release.
CHRISTENBURG, E Hearings Division 79/03/26 3pp

7906180634 Motion for reconsideration of ALAB-340 & sanctions from consolidation established by ALAB-340. Admin issues not raised by any party & reports from "lead case" procedure previously adopted. Certificate of Doc #611.
OSHER, B H Center, Harris & Corbin 79/03/02 1pp

7906250593 RRC action for summary disposition re radon issue was in error. ALAB-340 consolidated only 8 of 14 cases. Denies RRC action as to parties in other proceedings. Certificate of Doc #611.
BALDWIN, J F Atomic Safety and Licensing Appeal Panel 79/03/23 2pp

DOCKETED ITEMS

7904030107 Request by utility that ALAB grant summary disposition of all issues in consolidated radon proceeding Decisions sought as matter of law since no genuine issue as to radi facts
SILBERG, J E Shau, Pitman, Patts, & Troubridge 7/9/03/25 App

7904030107 Request by utility that ALAB grant summary disposition of all issues in consolidated radon proceeding Decisions sought as matter of law since no genuine issue as to radi facts
SILBERG, J E Shau, Pitman, Patts, & Troubridge 7/9/03/25 App

--7904030110 Statement of radi facts re radon proceedings as to which there is no genuine issue to be heard Discussed Alleged Deficiencies 1-7-7-10-20-24 & 25 Affidavit of MI Goldmen & supporting documentation encl
GILBERT, J E Shau, Pitman, Patts, & Troubridge 7/9/03/25 26pp

--7904030110 Statement of radi facts re radon proceedings as to which there is no genuine issue to be heard Discussed Alleged Deficiencies 1-7-7-10-20-24 & 25 Affidavit of MI Goldmen & supporting documentation encl
GILBERT, J E Shau, Pitman, Patts, & Troubridge 7/9/03/25 26pp

--7904030112 Supplement 790325 affidavit of MI Goldmen & utility 790409 none re radon emissions & de minimus approach Discussed Alleged Deficiencies 2-9-10 & 21 Seek action for summary disposition Certificate of Div encl
SILBERG, J E Shau, Pitman, Patts, & Troubridge 7/9/03/25 19pp

--7904030112 Supplement 790325 affidavit of MI Goldmen & utility 790409 none re radon emissions & de minimus approach Discussed Alleged Deficiencies 2-9-10 & 21 Seek action for summary disposition Certificate of Div encl
SILBERG, J E Shau, Pitman, Patts, & Troubridge 7/9/03/25 19pp

G Inspection reports, IE Bulletins & correspondence

G Inspection reports, IE Bulletins & correspondence

7904010304 Forwards IE Insp Repts 30-354/79-02 & 30-355/79-02 on 790227-0301 No noncompliance noted
CARLSON, R T Region 1, Philadelphia, Office of the Director 7/9/03/21 App

7904010304 Forwards IE Insp Repts 30-354/79-02 & 30-355/79-02 on 790227-0301 No noncompliance noted
CARLSON, R T Region 1, Philadelphia, Office of the Director 7/9/03/21 App

--7904010309 IE Insp Repts 30-354/79-02 & 30-355/79-02 on 790227-0301 No noncompliance noted Major areas inspected OC program for pipe hangers & supports & subcontractors program for fabrication & installation of containment liner
HARRIS, L L, FANABIA, A M Region 1, Philadelphia, Office of the Director 7903/19 80pp

--7904010309 IE Insp Repts 30-354/79-02 & 30-355/79-02 on 790227-0301 No noncompliance noted Major areas inspected OC program for pipe hangers & supports & subcontractors program for fabrication & installation of containment liner
HARRIS, L L, FANABIA, A M Region 1, Philadelphia, Office of the Director 7903/19 80pp

7904100413 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Details" No written response necessary
GRIER, B H Region 1, Philadelphia, Office of the Director 7/9/04/1A 1p

7904100413 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Details" No written response necessary
GRIER, B H Region 1, Philadelphia, Office of the Director 7/9/04/1A 1p

7904100327 Forwards IE Bulletin 79-028, "Nuclear Incident at TMI-2" No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 7/9/04/22 1p

7904100327 Forwards IE Bulletin 79-028, "Nuclear Incident at TMI-2" No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 7/9/04/22 1p

7904030174 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Bus Resulted in Reactor Power Increase" No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 7/9/05/02 1p

7904030174 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Bus Resulted in Reactor Power Increase" No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 7/9/05/02 1p

7904100194 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required
GRIER, B H Region 1, Philadelphia, Office of the Director 7/9/05/07 2pp

7904100194 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required
GRIER, B H Region 1, Philadelphia, Office of the Director 7/9/05/07 2pp

7904030131 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 7/9/05/11 1p

7904030131 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 7/9/05/11 1p

7904030351 Requests 30-day extension until 790704, to complete evaluation of items mentioned in NRC Bulletin 79-12, 79-12A, & 79-12B re alleged void melt in reactor pressure vessel
MARTIN, T J Public Service Electric & Gas Co. of New Jersey 7/9/05/20 1p

7904030351 Requests 30-day extension until 790704, to complete evaluation of items mentioned in NRC Bulletin 79-12, 79-12A, & 79-12B re alleged void melt in reactor pressure vessel
MARTIN, T J Public Service Electric & Gas Co. of New Jersey 7/9/05/20 1p

DOCKET 30-355 HOPE CREEK NUCLEAR STATION, UNIT 2

DOCKET 30-356 UNIV OF ILLINOIS LORRA RESEARCH REACTOR

G Adjudicatory correspondence

G Inspection reports, IE Bulletins & correspondence

7904030067 Motion for extension until 790401 to prepare response to ALAB-109
SCINTO, J F Hearings Division 7/9/04/02 2pp

7904030067 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
SCINTO, J F Region 3, Chicago, Office of the Director 7/9/05/11 1p

--7904030080 Response to 790329 request for info re status of rulemaking proceeding to develop value for radon in Table 3-3 Rept & proposed rule will be sent to NRC by 790405 Rule does not address health effects of radon releases
GRIESTON, J E Hearings Division 7/9/03/26 2pp

--7904030081 Forwards IE Circular 79-06, "Attempted Extension - Low Enriched U"
SCINTO, J F Region 3, Chicago, Office of the Director, 7/9/05/11 1p

7904100405 Motion for reconsideration of ALAB-340 & severance from consideration established by ALAB-085 Admins issues not raised by any party & depart from "lead case" procedure previously adopted Certificate of Div encl
CONNER, T S Conner, Moore & Curker 7/9/05/02 19pp

DOCKET 30-356 WILLIAM H ZIPPER NUCLEAR STATION, UNIT 1

7904030095 NRC notice for summary disposition re radon issue was in error ALAB-340 considered only 8 of 10 cases Denies NRC motion as per parties in other proceedings Certificate of Div encl
GRIER, B H Atlantic Safety and Licensing Appeal Panel 7/9/05/28 2pp

7904030383 Forwards assembly drawings for vertical fitting of 12-incl radon & unapproved fitting of forced sections
BARTHA, P L Harkins Harkins 7/9/05/21 9pp

7904030383 Forwards request for add info re radiological assessment complete review of CR application
BTL, L J F Light Water Reactors Branch 1, 7/9/05/10 App

DOCKETED ITEMS

7904295280 Motion to amend petition to intervene & seek adj. conclusion re insufficiency of radiological air monitoring program proposed by applicant Affidavit & Certificate of Dnc encl
LUSKINSKY, T. A. HEILIG, W. P. Cincinnati, OH 79/03/20 5pp

7904295293 Five requests to make limited appearance statements at licensing prehearing conference
FLANNERY, J. DIERIG, V. SCHADLER, E. Affiliation Unknown 79/05/22 5pp

7904295294 Ltr from eight citizens requesting to be present or be represented at 790522 & 23 pre-hearing conferences
HILLER, W. R. CURRY, J. A. HOSBORN, C. Affiliation Unknown 79/05/20 13pp

7904295295 Applicant opposes Miami Valley Power Project motion to allow participation of non-affiliates in hearing should be denied as matter of policy & per NRC Rules of Practice Notice of appearance, documentation & Certificate of Dnc encl
OSHER, T. D. RADER, R. H. Conner, Moore & Corbin 79/05/20 21pp

7904295296 Forwarder testimony re Contention & testimony & proof qualifications of Dr. Bergmann & Henry 790450 affidavit will be introduced into evidence re Contention 5
SETTER, M. R. J. Conner, Moore & Corbin 79/04/01 5pp

7904295297 Applicant response to City of Cincinnati motion to amend petition to intervene Reu consultation board issues & should not be admitted Certificate of Dnc encl
COPPER, H. J. Conner, Moore & Corbin 79/06/04 5pp

7904295298 Exclusionary hearing on 790417 will be held at US District Court Bldg, Cincinnati, OH Limited appearance statements will be taken on morning of 790429 & evening of 790430
SCHNEIDER, C. Atomic Safety and Licensing Board Panel 79/04/05 1p

J Insurance & Indemnity Information

7904295304 Forwarder executed Amend 2 to Indemnity Agreement B-50
BENTON, W. E. Cincinnati Gas & Electric Co 79/06/14 2pp

K Utility Final Safety Analysis Report (FSAR) & amendments

7904295317 Forwarder response to second round questions submitted in NRC 790522 & 16 ltr Response consists of Amend 93 to license application, in form of FSAR Revision 38
BENTON, W. E. Cincinnati Gas & Electric Co 79/04/06 2pp

--7904295318 Revision 38 to FSAR contained in Amend 93 to license application
Cincinnati Gas & Electric Co 79/04/06 170pp

7904295325 Forwarder Certificate of Dnc for Amend 93 to license application, in form of Revision 38 to FSAR
BENTON, W. E. Cincinnati Gas & Electric Co 79/04/14 2pp

S Inspection reports, IE Bulletin & correspondence

7904295326 Forwarder IE Insp Rpt 50-238/79-11 on 790410-19 No noncompliance noted
FIDELL, L. J. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/04 2pp

--7904295327 IE Insp Rpt 50-238/79-11 on 790410-19 No noncompliance noted Major areas inspected safety-related hangers, vented tanks & structures
VINE, L. F. DANIELSON, S. H. Region 3, Chicago, Office of the Director 79/04/20 2pp

7904295328 Forwarder IE Info Notice 79-11, "Lower Reactor Vessel Head Inspection Support Problem - No action required"
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/07 1p

7904295329 Responds to IE Bulletin 79-09 re failure of GE Type AA-2 circuit breakers in safety-related sys. Breakers not utilized
BENTON, W. E. Cincinnati Gas & Electric Co 79/05/27 1p

7904295330 Forwarder IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
KEPPLER, J. G. Region 3, Chicago, Office of the Director, 79/05/11 1p

7904295331 Responds to IE Bulletin 79-03 No ASME SA-312 Type 304 or other welded pipe mfg by Youngstown Welding & Engineering Co. sps in use
BENTON, W. E. Cincinnati Gas & Electric Co 79/05/18 1p

7904295332 Forwarder IE Bulletin 79-11, "Facility Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee on required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/11 1p

7904295333 Forwarder IE Info Notice 79-13, "Indication of Low Water Level in Quiescent Creek Reactor"
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/11 1p

S Reportable occurrences, LERs & related correspondence

7904295334 Forwarder corrective actions to be implemented at plant. Consent on suppression pact not adding safety release valve quench discharge devices will come until all conditions are fulfilled
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/11 1p

T Hearing transcripts on non-ambush matters

7904295335 Transcript of 790522 meeting in Cincinnati, OH pp 121-214
SCHNEIDER, C. HOSBORN, F. F. BRIGHT, G. D. Atomic Safety and Licensing Board Panel 79/05/21 93pp

7904295336 Transcript of 790522 prehearing conference in Moscow, OH pp 215-222
SCHNEIDER, C. HOSBORN, F. F. BRIGHT, G. D. Atomic Safety and Licensing Board Panel 79/05/22 14pp

7904295337 Transcript of 790523 prehearing conference in Cincinnati, OH pp 223-232
SCHNEIDER, C. HOSBORN, F. F. BRIGHT, G. D. Atomic Safety and Licensing Board Panel 79/05/23 105pp

U Congressional/Executive Correspondence

7904295338 Responds to 790521 ltr which forwarded Hattham Family 790412 ltr re inadequate welding & insp of components
HATTHAM, J. B. Atomic Safety and Licensing Board Panel 79/05/20 1p

--7904295339 Forwarder Hattham Family 790412 ltr re allegations of inadequate welding & insp of components
HATTHAM, J. B. House of Rep 79/05/21 2pp

7904295340 Forwarder tables of environ. radiological monitoring data around plant Data has been accumulated for three years
Applicant program monitors routine releases. IE is considering placing monitoring network at nuclear stations
KAMMERER, C. Office of Congressional Affairs 79/05/20 5pp

DOCKET 50-245 BATTLE MOUND SERIAL UNIT CRITICAL FACILITY

Q Inspection reports, IE Bulletin & correspondence

7904295341 Forwarder IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies - No written response necessary"
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director 79/05/10 1p

7904295342 Forwarder IE Circular 79-06, "Attempted Damage to Reactor"
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director 79/05/10 1p

DOCKETED ITEMS

7904080388 Forwards 7902-79-0746
CROSSLAND, R. H. Region 2, San Francisco, Office of the Director
79/03/20 1p

7904030236 Refuses that final rept to 790202 interim rept re Taylor
Farge pipe defects will be delayed until 790402
SOLAR, S. Southern California Edison Co 79/03/04 1p

7904070227 Forwards final deficiency rept re surface defects in Taylor
Farge carbon steel pipe
HORSER, J. H. Southern California Edison Co 79/03/20 1p

--7904070204 Final deficiency rept Taylor Farge pipe defects
Describe investigation of surface flaws in pipe all
liner indications identified were removed by surface
conditioning &/or weld repair
Southern California Edison Co 79/03/22 2pp

7904070404 Forwards Final deficiency rept re design deficiencies in
containment solar crane support girder bracket connections
HORSER, J. H. Southern California Edison Co 79/03/22 1p

--7904070411 Final deficiency rept design deficiencies in containment
solar crane support girder bracket connections structural
members to be added to reduce tension load requirement on
bolts to acceptable level
Southern California Edison Co 79/03/22 7pp

DOCKET 79-040 FORKED RIVER NUCLEAR STATION, UNIT 1

1 Inspection reports, IE Bulletin & correspondence

7904030007 Forwards IE info Notice 79-10, "Nonconforming Pipe Support
Structs." to written response regarding
CROSSLAND, R. H. Region 2, Philadelphia, Office of the Director
79/04/16 1p

7904040401 Ack receipt of 790319 1st informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-340/79-15
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering
Support Branch 79/04/17 1p

--7904040407 Responds to NRC 790319 1st re violations noted in IE Insp
Rept 50-340/79-15 Corrective actions identified were performed &
two technicians sent for retraining
FIRMROCK, L. B. Jersey Central Power & Light Co 79/03/15 1p

7904050053 Forwards IE Bulletin 79-085, "Nuclear Incident at
TMI-Bugs." No written response required
CROSSLAND, R. H. Region 1, Philadelphia, Office of the Director
79/04/20 1p

7904070294 Responds to IE Bulletin 79-09 Re SE Type AN-2 circuit
breakers purchased to date
FIRMROCK, L. B. Jersey Central Power & Light Co 79/05/01 1p

7904070295 Responds to IE Bulletin 79-04 Being check valves not
installed in facility
FIRMROCK, L. B. Jersey Central Power & Light Co 79/05/01 1p

7904080179 Ack receipt of 790420 1st informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-343/79-02
CROSSLAND, R. T. Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 79/05/23 1p

--7904080189 Responds to NRC 790312 1st re violations noted in IE Insp
Rept 50-343/79-02 Corrective actions initiated of program
for daily monitoring of equipment pressurized against gas
FIRMROCK, L. B. Jersey Central Power & Light Co 79/04/20 2pp

--7904050190 Forwards IE Insp Rept 50-343/79-02 on 790212-15 & notice of
violation
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 79/03/12 2pp

--7904080192 Notice of violation from Insp on 790212-15
Region 1, Philadelphia, Reactor Construction & Engineering
Support Branch 79/03/07 1p

--7904050195 IE Insp Rept 50-343/79-02 on 790212-15 Noncompliance noted
violate re emission procedure of LOFT gas blanket as
required
HORSER, J. H., CROSSLAND, R. H., MCARDY, R. H. Region 1, Philadelphia,
Reactor Construction & Engineering Support Branch 79/03/09
10pp

7904020163 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Support Problem." No action required
CROSSLAND, R. H. Region 1, Philadelphia, Office of the Director
79/03/07 2pp

7904060112 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assembly"
CROSSLAND, R. H. Region 1, Philadelphia, Office of the Director
79/03/11 1p

DOCKET 79-040 JOSEPH H. PAVLEY NUCLEAR PLANT, UNIT 3

1 Application/Construction change documents & correspondence

7904040444 Forwards info re PWR Feedwater Lines, in response to NRC
790325 request four revised drawings and URS and
CLARKSON, F. L. Alabama Power Co 79/04/13 14pp

1 Inspection reports, IE Bulletin & correspondence

--7904020208 Forwards IE Insp Repts 50-340/79-14 & 50-344/79-04 on
790327-29 & notice of violation
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 79/04/11 2pp

7904040410 Forwards IE Insp Repts 50-340/79-15 & 50-344/79-05 on
790327-27 No noncompliance noted
LUTHE, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 79/04/17 2pp

--7904040417 IE Insp Repts 50-340/79-15 & 50-344/79-05 on 790327-27 No
noncompliance noted Major areas inspected preoperational
test procedures & test procedures for mod & refueling
WAGNER, A. D., MURPHY, C. E. Region 2, Atlanta, Office of the
Director 79/04/16 2pp

7904040401 Responds to IE Bulletin 79-04 & 79-06A, Revision 1
Forwards info re TMI incident proposed design & Tech Spec
changes will be submitted by 790514
CLARKSON, F. L. Alabama Power Co 79/04/08 21pp

7904020204 Ack receipt of 790327 1st informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-340/79-14 &
50-344/79-05
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 79/03/07 1p

--7904020203 Responds to NRC 790311 1st re violations noted in IE Insp
Repts 50-340/79-14 & 50-344/79-05 Corrective actions new
in-house procedure implemented to control electrical prints
& instruction of all field supervision
CLARKSON, F. L. Alabama Power Co 79/04/27 2pp

--7904020204 Notice of violation from Insp on 790327-29
Region 2, Atlanta, Office of the Director 79/04/12 1p

--7904020205 IE Insp Repts 50-340/79-14 & 50-344/79-05 on 790327-29
Noncompliance noted failure to control suspended drawings
MURPHY, C. E. Region 2, Atlanta, Office of the Director MURPHY, C. E.
Region 2, Atlanta, Reactor Construction & Engineering Support
Branch 79/03/12 4pp

7904060347 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assembly"
D'NEILL, J. P. Region 2, Atlanta, Office of the Director
79/03/10 1p

7904070711 Responds to IE Bulletin 79-09 SE Type AN-2 circuit
breakers are used in safety-related features at Units 1 & 2
CLARKSON, F. L. Alabama Power Co 79/03/18 2pp

1 Reportable occurrences, URS & related correspondence

7904020203 FOIA request for documents re abnormal occurrences at plants,
info re Washington proposed nuclear fuel assembly plant in
Prattville, AL, re re incorporation of nuclear waste &
fuel through AL
GROSS, S. L. Affiliation Unknown, 79/04/22 2pp

7904030277 Responds to 790323 FOIA request Forwards computer printout
of abnormal occurrences at plants until May 1979, paper on
"Transportation of Nuclear Fuel & Waste." & list of package
designs for which until is registered
FIRMROCK, L. B. Division of Rules and Records 79/05/30 87pp

DOCKETED ITEMS

7904040033 Forwards 790415 ltr to EPA re issue of noncompliance Analysis of turbine blade stop efficient about 9.12 per caused by error in sampling & analysis steps have been taken to ensure violation does not recur
CLATTON, F. L. Alabama Power Co 79/04/19 2pp

--7904140092 IE Insp Repts 50-321/79-10 & 50-364/79-12 on 790314-16 No noncompliance noted Major areas inspected IE Circuits & Isolations, LEWIS & following of previous issue findings
HINCHLEY, D. O Region 2, Atlanta, Office of the Director
DANCE, H. C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/03 2pp

DOCKET 30-364 EDWIN I WYCKE NUCLEAR PLANT, UNIT 2
F Security, medical, emergency & fire protection plans

7904140036 Responds to IE Bulletin 79-07 Discussion computer program used in stress analysis of safety-related piping
STAFFA, R. H Georgia Power Co 79/03/23 2pp

7904030274 Forwards prepared amendment to fire protection Tech Specs covering add fire detection instrumentation & water suppression sys
MATHIAS, C. F Georgia Power Co 79/03/29 12pp

7904130141 Forwards IE Circular 79-07, "Unspecified Speed Increase of Reactor Motor Generator Set Resulted in Member Power Increase" No written response required
D'NEILLY, J. P Region 2, Atlanta, Office of the Director 79/03/02 1p

J Insurance & Indemnity Information

7904030453 Forwards IE Info Repts 79-12, "Attempted Damage to New Fuel Assemblies"
D'NEILLY, J. P Region 2, Atlanta, Office of the Director 79/03/10 1p

7904190237 Forwards Endorsements 40 & 41 to AEC Policy HP-78
DICK, J. R Mark & McNamara, R. H Nuclear Consultants, Inc Div 79/04/12 2pp

P Operating license stage documents & correspondence

7904100403 Forwards IE Bulletin 79-10, "Regulator/Training Program Statistics" Written response required
D'NEILLY, J. P Region 2, Atlanta, Office of the Director 79/03/11 1p

7904101025 Progress amend to Tech Specs Amend would substitute use of core mass fraction of limiting power density for max total peaking factor in determination of average power range
LEWIS, R. C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/10 1pp

7904030802 Ack receipt of 790410 & 0528 ltrs informing AEC of steps taken to correct violations noted in IE Insp Repts
50-321/79-08 & 50-364/79-10
LEWIS, R. C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/15 1p

S Inspection reports, IE Bulletin & correspondence

--7904030527 Responds to AEC 790304 ltr re violations noted in IE Insp Repts 50-321/79-08 & 50-364/79-10 corrective actions new policy re definition of operability has been established & test results will be reported
STAFFA, R. H Georgia Power Co 79/04/10 2pp

7904070021 Forwards IE Bulletin 79-04, "Events Relevant to SWR Identified During 3MI Incident" - Licensee action required
D'NEILLY, J. P Region 2, Atlanta, Office of the Director 79/04/14 2pp

--7904030832 Respond to AEC 790428 telcom re violations noted in IE Insp Repts 50-321/79-08 & 50-364/79-10 corrective actions Tech Specs re inoperability reporting will be followed & test acceptance criteria will be followed
STAFFA, R. H Georgia Power Co 79/05/08 1p

7904030074 Ack receipt of 790416 ltr informing AEC of steps taken to correct violations noted in IE Insp Repts 50-364/79-09
LEWIS, R. C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/25 1p

--7904030840 Forwards IE Insp Repts 50-321/79-08 & 50-364/79-10 on 791214-15, 790310-03 & 5129-5209
D'NEILLY, J. P Region 2, Atlanta, Office of the Director 79/03/16 2pp

--7904050025 Responds to AEC 790323 ltr re violations noted in IE Insp Repts 50-364/79-09 Corrective actions startup test procedures being changed to use correct core mass peaking factor value
STAFFA, R. H Georgia Power Co 79/04/16 1p

7904030544 Notice of violation from Insp on 790326-15, 790310-03 & 5129-5209
Region 2, Atlanta, Office of the Director 79/03/08 1p

--7904050134 Forwards IE Insp Rept 50-364/79-09 on 790320-23 & notice of violation
LEWIS, R. C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 2pp

--7904030392 IE Insp Repts 50-321/79-08 & 50-364/79-10 on 791214-15, 790310-03 & 5129-5209 Noncompliance noted Failures to report RP1 & reactor core isolation cooling inoperable & failure to report recirculation flow conditions test results
DANCE, H. C Region 2, Atlanta, Office of the Director
DANCE, H. C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/08 2pp

--7904050091 Notice of violation from Insp on 790320-03
Region 2, Atlanta, Office of the Director 79/03/23 1p

R Periodic operating reports & related correspondence

--7904050100 IE Insp Rept 50-364/79-09 Noncompliance noted failure to effect proper corrective action in disseminating corrected value for core mass peaking factor
VOOT, L. G. L. R. Region 2, Atlanta, Office of the Director 79/03/23 2pp

7904120424 Forwards monthly operating rept for May 1979
MATHIAS, C. F Georgia Power Co 79/04/06 1p

7904050108 Ack receipt of IE Insp Rept 50-364/79-13 on 790314-2016 No preparatory info
STAFFA, R. H Georgia Power Co 79/04/25 1p

--7904120428 Monthly operating rept for May 1979
STANLEY, R. Georgia Power Co 79/04/03 2pp

--7904050112 Forwards IE Insp Rept 50-364/79-13 on 790314-2016 No noncompliance noted
ROBINSON, E. E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/08 2pp

S Reportable occurrences, LEWIS & related correspondence

--7904090117 IE Insp Rept 50-364/79-13 on 790314-16 No noncompliance noted Major areas inspected concrete suspension member installation
ROBINSON, E. E Region 2, Atlanta, Office of the Director
STANLEY, J. C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/30 2pp

7904190294 Forwards LEW 79-005/03-0
MATHIAS, C. F Georgia Power Co 79/05/24 1p

--7904150034 LEW 79-009/03-0 on 790311 low switch & high switch of RCS-1018 operated contrary to Tech Specs caused by switch setpoint drift Corrected by performance of HPF-2-3202 procedure
NEE, R. E Georgia Power Co 79/03/24 1p

7904140001 Ack receipt of IE Insp Repts 50-321/79-10 & 50-364/79-12 on 790314-2016 No preparatory info
STAFFA, R. H Georgia Power Co 79/04/25 1p

7904040024 Forwards LEW 79-004/01T-0
MATHIAS, C. F Georgia Power Co 79/03/21 1p

--7904150088 Forwards IE Insp Repts 50-321/79-10 & 50-364/79-12 on 790314-2016 No noncompliance noted
LEWIS, R. C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/03 2pp

--7904040027 LEW 79-004/01T-0 on 790314 instruments in remote shutdown panel H21-7172 & H21-7173 testing work done & air conditioning panels H21-7408 & H21-7407 did not meet seismic requirements Covered by installation error Proper Instruments installed
MATHIAS, C. F Georgia Power Co 79/03/21 2pp

DOCKETED ITEMS

7904000303 Forwards LER 79-030/03L-0
HARRY, M Georgia Power Co 79/05/24 1p

--790400039 LER 79-030/03L-0 on 790015 procedure HP-1-2-195, weekly
breaker alignment checks, was performed one day late
Caused by late issuance of alignment sheets Surveillance
engineer made aware of importance of prompt sheet issuance
GREENE, T V Georgia Power Co 79/05/24 1p

7904100414 RD 30-36A/79-34 on 790024 listed valves did not meet
individual valve leak rate criteria per ASME Section II
HARRY, M Georgia Power Co 79/05/24 1p

790410038 RD 30-36A/79-34 on 790028 line of piping for feedwater flow
transmitters revealed piping in piped up incorrectly
Piping arrangement until be changed prior to startup
HARRY, M Georgia Power Co 79/05/25 1p

7904100467 RD 30-36A/79-34 on 790523 during review of Class IE
equipment, reactor temple isolation valve 2801-050-7010 did
not have complete radiation qualification test report
document Radiant valve available to compensate
HARRY, M Georgia Power Co 79/05/25 1p

7904100443 Forwards LER 79-036/01T-0
HARRY, M Georgia Power Co 79/05/30 1p

--7904000449 LER 79-036/01T-0 on 790014 sprinker header made indicated
nozzle design deficiency for valve bypassing near
designs Frager analysis & mods have begun
GREENE, T V Georgia Power Co 79/05/30 3pp

7904100441 Forwards LER 79-036/01T-0
HARRY, M Georgia Power Co 79/05/30 1p

--7904100446 LER 79-036/01T-0 on 790523 proper seismic documentation for
RIB used absent Caused by failure to document change Review
of other changes revealed no problem
GREENE, T V Georgia Power Co 79/05/30 1p

7904100501 Forwards LER 79-041/01T-0
HARRY, M Georgia Power Co 79/05/30 1p

--7904100509 LER 79-041/01T-0 on 790023 during maint outage, review
indicated solenoid on reactor sample isolation valve did not
have complete qualification testing Caused by design error
Solenoid will be replaced
GREENE, T V Georgia Power Co 79/05/30 3pp

7904100517 Forwards LER 79-039/01T-0
HARRY, M Georgia Power Co 79/05/30 1p

--7904100508 LER-029/01T-0 on 790523 during shutdown, one feedwater check
valve & three RHM pump section valves deemed to have
excessive leak rates Caused by change to ASME criteria
ASME criteria reviewed & found too stringent
GREENE, T V Georgia Power Co 79/05/30 3pp

7904100526 Forwards LER 79-040/01T-0
HARRY, M Georgia Power Co 79/05/31 1p

--7904100301 LER 79-040/01T-0 on 790023 during repair outage, two
feedwater flow elements found piped to wrong low pressure
Ras Caused by personnel error during vent flow elements
were replaced to correct bias
GREENE, T V Georgia Power Co 79/05/31 3pp

7904100419 Forwards LER 79-037/03L-0
HARRY, M Georgia Power Co 79/06/01 1p

--7904100404 LER 79-037/03L-0 on 790017 during cold shutdown, technicians
inadvertently set isolation trip setpoint of alarm units
2901-0603AS for leakage flow of 136 gallons/minute
Caused by incorrect procedure Procedure revised
NIX, R T Georgia Power Co 79/06/01 1p

7904100255 LER 30-36A/84-0 has been voided
HARRY, M Georgia Power Co 79/06/04 1p

7904100447 Forwards LER 79-023/02L-1
HARRY, M Georgia Power Co 79/06/04 1p

7904100270 LER 79-023/02L-1 on 790214 while performing startup test
procedure HP-2-10925 (SRV) closure, discovered 2801-050A
submerged SRV closed in 2-3 degree position due to failure of seal
cartridge bushing & seal assembly Parts repaired
GREENE, T V Georgia Power Co 79/06/04 1p

7904000465 RD 30-36A/1979-45, Revision 0, on 790603 following reactor
scram, 2L41-C001 HPCI pump failed to start Caused by HPCI
stop valve remaining closed
HARRY, M Georgia Power Co 79/06/04 1p

7904100241 Forwards LER 79-032/03T-0
HARRY, M Georgia Power Co 79/06/07 1p

--7904100366 LER 79-032/03T-0 on 790038 during review of emergency load
shed logic schemes, possibility for unnecessary trip of plant
hot water pump during LOGA arose Logic schemes to be
modified
GREENE, T V Georgia Power Co 79/06/07 1p

7904100426 RD 30-36A/79-05, Revision 1, on 790607 during reactor power
ascension, power level fell below 1,000 cents, causing HPCI
to initiate Caused by leaking HPCI pump mechanical seal
Valve level maintained by restoring condensate vlv
HARRY, M Georgia Power Co 79/06/07 3pp

7904100483 Forwards LER 79-029/02L-1
HARRY, M Georgia Power Co 79/06/08 1p

--7904100418 LER 79-029/02L-1 on 790015 while about break for repairs, main
steam safety relief valve discharge line vacuum breaker
valves found to be partially opened, hinge pins bent &
springs distorted Caused by valves being slammed open
NIX, R T Georgia Power Co 79/06/07 3pp

7904100202 Forwards LER 79-046/01T-0
HARRY, M Georgia Power Co 79/06/11 1p

--7904100200 LER 79-046/01T-0 on 790603 following scram, reactor core
isolation steam vlv tripped Caused by ruptured turbine
exhaust diaphragm
NIX, R T Georgia Power Co 79/06/11 3pp

7904100406 Forwards LER 79-043/03L-0
HARRY, M Georgia Power Co 79/06/11 1p

--7904100392 LER 79-043/03L-0 on 790027 while performing normal
surveillance procedure HP-2-2011 on pressure switches
2801-0202A & 0-2020B tripped at 1.046 & 1.047 gpsi
Caused by vacuum drift
NIX, R T Georgia Power Co 79/06/11 1p

7904100509 Forwards LER 79-048/01T-0
HARRY, M Georgia Power Co 79/06/11 1p

--7904100514 LER 79-045/01T-0 on 790603 following reactor scram,
HPCI age received isolation signal but failed to start
when turbine stop valve did not open Caused by real water
line leaking water to bracket drain saving line repaired
NIX, R T Georgia Power Co 79/06/11 3pp

7904100167 LER 79-042 is voided
HARRY, M Georgia Power Co 79/06/11 1p

7904100284 LER 79-027 has been voided
Georgia Power Co 79/06/14 1p

7904100301 LER 79-012 has been voided
Georgia Power Co 79/06/14 1p

7904100303 LER 79-018 has been voided
Georgia Power Co 79/06/14 1p

7904100303 LER 79-018 has been voided
Georgia Power Co 79/06/14 1p

DOCKET 80-067 RAILLY DEBRATING STATION
S. Inspection reports, IE Bulletin & correspondence

7904100118 Forwards IE Info Notice 79-12, "Lower Reactor Vessel Head
Insulation Support Problem" No action required
REFFLER, J D Region 2, Chicago, Office of the Director 79/05/07
1p

7904000403 Responds to IE Bulletin 79-00 No ASME SA-312 Type 304
voided also used
GREENE, T V Northern Indiana Public Service Co 79/06/09 1p

7904100004 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assembly"
REFFLER, J D Region 2, Chicago, Office of the Director 79/05/15
1p

DOCKETED ITEMS

7904250040 Responds to IE Bulletin 79-04 Being check valves have not been purchased or solicited from Valon Engineering Corp.
GIBBS, E. M. Northern Indiana Public Service Co. 79/05/21 1p

7904250104 Forward IE Bulletin 79-11 "Passing Overcurrent Trip Device on Circuit Breakers for Empowered Safety Sys." Licenses action required
NEFFLER, J. D. Region 2, Chicago, Office of the Director 79/05/22 1p

7904250128 Forward IE Info Notice 79-15 "Indication of Low Water Level in Dryer Creek Reactor"
NEFFLER, J. D. Region 2, Chicago, Office of the Director 79/05/29 1p

R Periodic operating reports & related correspondence

7904250326 Forward plant well charts, well level readings, water meter readings, pond level readings, pneumatic pressure transducer measurements & Pilot Lake pump station rainfall readings
BONNE, R. J. Northern Indiana Public Service Co. 79/05/22 3pp

7904250179 Forward 790518-23 well charts, 790522 Wellie wells w/o recorders, 790523 pond levels, 790523 pneumatic pressure transducers & 790523 water meter readings
BONNE, R. J. Northern Indiana Public Service Co. 79/06/04 3pp

7904250420 Forward well charts for 790523-25 wells w/o recorders, pneumatic pressure transducers, water meter readings for 790520 & pond levels for 790520
BONNE, R. J. Northern Indiana Public Service Co. 79/06/08 3pp

7904250423 Forward info well charts for 790520-0426, Wellie wells w/o recorders for 790606, pond levels, pneumatic pressure transducers, water meter readings & USSS wells for 790606
BONNE, R. J. Northern Indiana Public Service Co. 79/06/15 3pp

7904250518 Forward well charts for 790606-15, Wellie wells w/o recorders for 790612, pond levels for 790613, pneumatic pressure transducers for 790613 & water meter readings for 790613
BONNE, R. J. Northern Indiana Public Service Co. 79/06/22 3pp

U Congressional/Executive Correspondence

7904250548 Responds to 790413 ltr re installation of safety-related short pilings & evacuation plans for facility E2828
review leading to issuance of CP Forwarded PSE W/o act
SOMMER, L. V. Office of the Executive Director for Operations 79/05/21 3pp

--7904250563 Request complete review of facility CP, including proposed use of short pilings Requests examination of evacuation plans & public hearing re CP
FITZGERALD, J. House of Reps. 79/04/13 2pp

DOCKET 30-368 ARKANSAS NUCLEAR ENG. UNIT 2
F Security, medical, emergency & fire protection plans

7904270147 Responds to 790413 ltr re GA section of fire protection plan Unit has met guidelines of "Nuclear Plant Fire Protection Function Responsibility-Administrative Controls & BA" No changes planned
TRIMBLE, D. C. Arkansas Power & Light Co. 79/04/18 2pp

D Adjudicating correspondence

7904270088 Forward proposed order confirming utility commitment to shut down facility & modify operating procedures
BENTON, M. B. Office of Nuclear Reactor Regulation 79/05/14 3pp

7904270097 Summary of 790509 meeting w/utl to evaluate emergency feedwater sys. re issue of TMI incident
ENGLE, L. B. Light Water Reactors Branch 1 79/05/18 13pp

7904270093 Orders shutdown of plant pending upgrade, testing & analyses of emergency feedwater sys.
CHILKOT, J. J. Office of the Secretary of the Commission 79/05/17 7pp

* Operating license stage documents & correspondence

7904250040 Discusses need of operating guidelines for small breaks NPS unit remain in operation until LPIS is in operation & flowing in excess of 3,000 gallons/minute in each line & stable for 30 minutes
TAYLOR, J. H. Babcock & Wilcox Co. 79/05/20 2pp

7904250420 Forward ARF-TOP-1A Revision 3 "BA Manual Operations" until Position 421 88 re gross melt testing & add info on Position 421 88 re physical properties of reinforcing steel
TRIMBLE, D. C. Arkansas Power & Light Co. 79/06/11 1pp

--7904250425 "BA Manual Operations" Revision 3
CANNON, W. M. Arkansas Power & Light Co. ARF-TOP-1A 79/06/11 13pp

7904250421 Forward event and drawings of selected feedwater steam generator, including results of stress analysis tests & details of welding processes used in making nozzle-to-tee pipe, pipe-to-tee pipe & pipe welds in response to 790525 request
TRIMBLE, D. C. Arkansas Power & Light Co. 79/06/18 17pp

7904270115 Submit addl info re gross melt monitoring sys. in response to 790413 request Gross melt location of effluent monitoring sys. detectors, range of oscillation detectors & max detectable release rate
TRIMBLE, D. C. Arkansas Power & Light Co. 79/06/22 11pp

Q Inspection reports, IE Bulletins & correspondence

7904250023 Forward IE Insp Repts 50-313/79-04 & 50-368/79-04 on 790418-2018 & notice of violation
BENTON, M. B. Region 4, Dallas, Reactor Operations Nuclear Supp. Branch 79/04/04 2pp

--7904250045 Notice of violation from Insp on 790418-0318
Bent, A. Dallas, Office of the Director 79/04/04 1p

--7904250055 IE Insp Repts 50-313/79-04 & 50-368/79-04 on 790418-0318 Noncompliance noted (adequacy of control of non-Class IE test equipment)
WICKSTROM, T. F. J. 7904250423, B. C. Region 4, Dallas, Office of the Director 79/04/03 18pp

7904250013 Requests addl 30 days to respond to IE Bulletin 79-25 re welding piping manufactured by Youngstown Welding & Engineering Works are currently being searched-response to be submitted by 790514
TRIMBLE, D. C. Arkansas Power & Light Co. 79/04/12 1p

7904250074 Responds to IE Bulletin 79-04 re use of Valon culing check valves Higher weights were used in seismic analysis
TRIMBLE, D. C. Arkansas Power & Light Co. 79/04/27 2pp

7904260149 Ack receipt of 790321 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/79-04 & 50-368/79-04
BENTON, M. B. Region 4, Dallas, Reactor Operations Nuclear Supp. Branch 79/04/30 1p

7904260152 Responds to NRC 790328 ltr re violations noted in IE Insp Repts 50-313/79-04 & 50-368/79-04 re effluent monitors to be added by 790401
TRIMBLE, D. C. Arkansas Power & Light Co. 79/05/21 2pp

--7904260156 Forward IE Insp Repts 50-313/79-04 & 50-368/79-04 on 790328-09 & notice of violation
BENTON, M. B. Region 4, Dallas, Reactor Operations Nuclear Supp. Branch 79/05/28 2pp

--7904260162 IE Insp Repts 50-313/79-04 & 50-368/79-04 on 790328-09 Noncompliance noted Failure to calibrate effluent monitors
BENTON, M. B. Region 4, Dallas, Office of the Director BENTON, M. B. Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/05/25 4pp

7904260209 Responds to IE Bulletin 79-03 Bore ARMS GA-312 Type 304 longitudinal welded pipe mfg by Youngstown Welding & Engineering Co. included in safety-related app Examination program being developed
TRIMBLE, D. C. Arkansas Power & Light Co. 79/05/04 1p

7904260263 Forward IE Info Notice 79-11 "Lower Reactor Vessel Head Excavation Repair Problem" - No action required
BENTON, M. B. Region 4, Dallas, Office of the Director 79/05/11 1p

DOCKETED ITEMS

- 790610002 Forwards IE Bulletin 79-10. "Regulofication Training Program Reevaluation" - Written response required
REVERT, R V Region 4, Dallas, Office of the Director 79/03/11
1p
- 7906030010 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assembly"
REVERT, R V Region 4, Dallas, Office of the Director 79/03/11
1p
- 7906050075 Ack receipt of 790604 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-368/79-05
HAGBERG, D L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/02 1p
- 7906040108 Response to NRC 790604 1tr re violations noted in IE Insp Rept 80-368/79-05
Corrective actions completed for connecting test equipment to safety-related equipment will be established
TRINLAGE, R C Arkansas Power & Light Co 79/04/26 App
- 7906040220 Ack receipt of 790420 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-019/79-05 & 50-305/79-03 Requests add info re steps taken to prevent recurrence of but items of noncompliance
HAGBERG, D L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/02 1p
- 7906060235 Forwards IE Insp Rept 80-368/79-11 on 790504-11 No noncompliance noted
HINDS, J B Region 2, Chicago, Safeguards Branch 79/05/24 App
- 7906040237 IE Insp Rept 80-368/79-11 on 790504-11 No noncompliance noted Rept areas inspected shipping & receiving equipment & nuclear fuel control Reliance withdrawn (NCR 790)
FINLEY, A S PATTERSON, J P HINDS, J A Region 2, Chicago, Safeguards Branch 79/05/01 1p
- 7906060239 Forwards IE Info Notice 79-13. "Indication of Low Water Level in Outer Creek Reactor"
REVERT, R V Region 6, Dallas, Office of the Director 79/05/07 1p
- 7906010020 Response to IE Bulletin 79-10 No Washington 08-79 or 60-50 circuit breakers are used in safety-related Class IE circuits
TRINLAGE, R C Arkansas Power & Light Co 79/04/14 1p
- B Periodic operating reports & related correspondence
- 7906100208 Forwards monthly operating report for May 1979
TRINLAGE, R C Arkansas Power & Light Co 79/06/19 1p
- 7906100273 Monthly operating report for May 1979
TRINLAGE, R C Arkansas Power & Light Co 79/06/19 App
- B Reportable occurrences, ERE & related correspondence
- 7906160142 Forwards AMD-79-a7AW
HAGBERG, D L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/09 1p
- 7906160192 Forwards AMD-79-a7AW
HAGBERG, D L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/16 1p
- 79-036/03L-0 & 79-037/03L-0
Co 79/04/10 1p
- 7906100057 LER 79-037/03L-0 on 790614 During Made & supply valves to steam generator would not respond to control room demand signal Control & Steam Pumps & steam relief Similar to LER 80-368/79-038 Repairs made & valves proven operable
BUTLER, C H Arkansas Power & Light Co 79/04/10 1p
- DOCKET 80-369 HILLMAN & HIGGINS NUCLEAR STATION, UNIT 1
A Application/construction stage documents & correspondence
- 7906160399 Forwards w/applicant evaluation of Reg Guide 1.14 Revision 1 re compliance to RSC criteria Facility condition of Reg Guide
HILLMAN, J J Operator Licensing Branch 79/05/14 1p
- 7906050022 Notification of 790608 meeting w/utl in Bethesda-MD to review radiological effluent Tech Spec
FINKEL, R A Light Water Reactors Branch 2 79/05/23 App
- J Inspection & Licensing Information
- 7906160380 Forwards awarded Amendment 2 to Indemnity Agreement B-82
PARKER, W D Safe Power Co 79/04/07 App
- 7906160381 Forwards Enforcement 84 & 85 to ANSI Policy HP-180 5
Enforcement 84 & 45 to ANSI Policy HP-180
BANDER, F D Safe Power Co 79/04/08 App
- B Inspection reports, IE Bulletin & correspondence
- 7906040208 Ack receipt of IE Insp Repts 50-367/79-10 & 50-370/79-09 on 790523-15 No noncompliance noted
PARKER, W D Safe Power Co 79/04/23 1p
- 7906040348 Forwards IE Insp Repts 50-367/79-10 & 50-370/79-09 on 790523-15 No noncompliance noted
HARRIS, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/28 App
- 7906040356 IE Insp Repts 50-367/79-10 & 50-370/79-09 on 790523-15 No noncompliance noted Major areas inspected nondestructive testing, control deficiencies, piping, warehouse storage, electrical storage areas & IE Bulletin responses
HARRIS, C E Region 2, Atlanta, Office of the Director HARRIS, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/27 App
- 7906160384 Ack receipt of 790418 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-367/79-10 & 50-370/79-07
HARRIS, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/23 1p
- 7906160393 Response to NRC 790323 1tr re violations noted in IE Insp Repts 50-367/79-10 & 50-370/79-07 corrective actions all correct & correct SA personnel instructed in manufacturer's manual use
PARKER, W D Safe Power Co 79/04/18 App
- 7906160377 Forwards IE Insp Repts 50-367/79-10 & 50-370/79-07 on 790523-0302 & notice of violation
HARRIS, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/23 App
- 7906160404 Notice of violation from Insp on 790328-0302
Region 2, Atlanta, Office of the Director 79/05/23 1p
- 7906160404 IE Insp Repts 50-367/79-10 & 50-370/79-07 on 790528-0302
Noncompliance noted assembly of safety valves w/o documented instructions
HARRIS, C E Region 2, Atlanta, Office of the Director HARRIS, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/23 App
- 7906160403 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assembly"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/09 1p
- 7906160404 Ack receipt of IE Insp Repts 50-367/79-03 & 50-370/79-10 on 790528-0302 No noncompliance noted
PARKER, W D Safe Power Co 79/05/16 1p
- 7906160408 Forwards IE Insp Repts 50-367/79-03 & 50-370/79-10 on 790528-0302 No noncompliance noted
HARRIS, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/16 App

DOCKETED ITEMS

- 7906101056 IE Insp Repts 80-369/79-21 & 50-370/79-10 re 790328-30 RA noncompliance noted Major areas inspected steam generator pressure range level instrumentation installation records & storage of safety related cable
WALTERS, D R Region 2, Atlanta, Office of the Director
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/17 App
- 7906000120 Act receipt of 790418 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-369/79-14
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/15 App
- 7906000121 Response to NRC 790418 ltr re violation noted in IE Insp Rept 50-369/79-14 Corrective actions all safety-related terminal blocks in containment are being replaced w/sealed splices
PARKER, W D Duke Power Co 79/04/12 App
- 7906000124 Forwards IE Insp Rept 50-369/79-14 re 790321-22 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/21 App
- 7906000126 Notice of violation from Insp on 790321-22
Region 2, Atlanta, Office of the Director 79/03/20 App
- 7906000128 IE Insp Rept 50-369/79-14 re 790321-22 Noncompliance noted improper cable termination
WALTERS, D R Region 2, Atlanta, Office of the Director
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/02/29 App
- 7906101012 Response to IE Bulletin 79-33 ASME SA-512 welded pipe method of liquid penetration checks requirements
PARKER, W D Duke Power Co 79/02/15 App
- 7906201013 Act receipt of 790502 & 0528 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-369/79-15
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/23 App
- 7906201015 Response to NRC 790411 ltr re violation noted in IE Insp Rept 50-369/79-15 Corrective actions shutdown request issued & damaged cable replaced
PARKER, W D Duke Power Co 79/05/08 App
- 7906200034 Inform NRC that revised response to IE Bulletin 79-33 will be submitted by 790601
PARKER, W D Duke Power Co 79/05/23 App
- W Congressional/Executive Correspondence
- 7906200035 Response to 790422 ltr re W Austin inquiry about radiological impact of nuclear power plant cooling on drinking water Forwards applicable FOS w/44 unit
ROBINSON, L V Office of the Executive Director for Operations 79/05/15 App
- 7906200544 Request info re radiological impact of nuclear power plant cooling on drinking water re W Austin inquiry
LEWIS, M F House of Rep 79/04/23 App
- DOCKET 50-370 WILLIAM D MCQUIRE NUCLEAR STATION UNIT 2
- A. Application/Construction Stage documents & correspondence
- 7906102539 Commence w/applicant evaluation of Reg Guide 1.14, Revision 1, re performance to NRC matters Facility complies w/reg guide
HOLMAN, J J Operator Licensing Branch 79/05/14 App
- 7906200522 Notification of 790608 meeting w/Unit 1 in Bethesda, MD to review radiological effluent Tech Sp
BIRNBAUM, A Light Water Reactors Branch 2 79/05/23 App
- J Insurance & Indemnity Information
- 7906102080 Forwards executed Amendment 2 to Indemnity Agreement B-83
PARKER, W D Duke Power Co 79/04/07 App
- 7906102031 Forwards Endorsements 54 & 55 to AIE Policy WF-102 & Endorsements 40 & 41 to AIE Policy WF-61
PARKER, W D Duke Power Co 79/04/08 App
- B Inspection reports, IE Bulletins & correspondence
- 7906000330 Act receipt of IE Insp Repts 50-369/79-10 & 50-370/79-09 on 790313-13 re noncompliance info
PARKER, W D Duke Power Co 79/04/23 App
- 7906000342 Forwards IE Insp Repts 50-369/79-10 & 50-370/79-09 on 790313-13 re noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/28 App
- 7906040044 IE Insp Repts 50-369/79-10 & 50-370/79-09 on 790313-13 re noncompliance noted Major areas inspected defective testing, control deficiencies repts, warehouse storage, outside storage areas, QA audits & IE bulletin responses
BRYANT, J C Region 2, Atlanta, Office of the Director
PARKER, W D Duke Power Co 79/04/27 App
- 7906100024 Act receipt of 790418 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/79-15 & 50-370/79-07
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/23 App
- 7906100032 Response to NRC 790322 ltr re violations noted in IE Insp Repts 50-369/79-15 & 50-370/79-07 Corrective actions all work & cost QA personnel instructed in manufacturer's manual use
PARKER, W D Duke Power Co 79/04/18 App
- 7906100039 Forwards IE Insp Repts 50-369/79-15 & 50-370/79-07 on 790322-0323 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/23 App
- 7906100041 Notice of violation from Insp on 790322-0323
Region 2, Atlanta, Office of the Director 79/03/23 App
- 7906100044 IE Insp Repts 50-369/79-15 & 50-370/79-07 on 790322-0323 Noncompliance noted assembly of safety valves w/o documented instructions
ANDERSON, P Region 2, Atlanta, Office of the Director
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/23 App
- 7906100114 Act receipt of 790503 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-370/79-08
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 App
- 7906100122 Response to NRC 790429 ltr re violations noted in IE Insp Rept 50-370/79-08 Corrective actions welding inspector & welder instructed to follow proper sequence for filling out documentation
PARKER, W D Duke Power Co 79/05/03 App
- 7906100149 Forwards IE Insp Rept 50-370/79-08 on 790503 violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/09 App

DOCKETED ITEMS

--7706000380 IE Insp Repts 30-36/79-21 & 30-37/79-10 on 770320-30 No noncompliance noted. Major areas inspected: steam generator, narrow range level instrumentation, installation, records & storage of safety related cable.
HARRIS, J. W. Region 3, Atlanta, Office of the Director
SHEPARD, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 77/04/17 Spp

7706140181 Response to IE Bulletin 77-03 ASSE 3A-312 welded pipe method of liquid penetration tests requirements
PARKER, W. D. Duke Power Co 77/05/15 Spp

7706030284 Informing AEC that revised response to IE Bulletin 77-03 will be submitted by 770601
PARKER, W. D. Duke Power Co 77/05/23 Spp

B. Reportable occurrences, LERs & related correspondence

7706030284 Forwards Significant Deficiency Rept 3070/79-03
PARKER, W. D. Duke Power Co 77/05/23 Spp

--7706010251 Significant Deficiency Rept 3070/79-03 on 770503 and photo finger found in bottom of motor's oil pan caused by inadequate control during load process of specific motor
* Duke Power Co 77/05/23 Spp

U. Congressional/Executive Correspondence

7706050294 Response to 770423 Ltr re W Austin inquiry about radiological impact of nuclear power plant cooling on drinking water. Forwards applicable FEI file and 6050504, L.V. Office of the Executive Director for Operations 77/05/15 Spp

--7706050294 Requests info re radiological impact of nuclear power plant cooling on drinking water to GE, DuPont inquiry
LEWIS, M. F. House of Rep 77/04/23 Spp

DOCKET 38-370 LABALLE COUNTY STATION, UNIT 1

A. Application/transposition issue documents & correspondence

7706070409 Notification of 770328-03 meeting w/utl to discuss open items in draft RER
BOURNIA, A. Light Water Reactors Branch 3 77/05/07 Spp

7706020308 Confirms 770321 meeting w/utl to discuss open items in draft RER
SHEPARD, J. C. Region 3, Chicago, Office of the Director 77/05/08 Spp

F. Security, medical, emergency & fire protection plans

7706040038 Forwards fire protection status report covering portion of review for which Power Sys Branch has review responsibility
HARRIS, J. W. Power Systems Branch 77/05/08 Spp

I. Insurance & indemnity information

7706040037 Forwards executed Amends 21.11.9 & 8 to Indemnity Agreements 8-03, 8-47, 8-97 & 8-04, respectively
HARRIS, J. W. Commonwealth Edison Co 77/05/09 Spp

P. Operating license stage documents & correspondence

Items 770321 meeting w/utl to discuss open items in draft RER
Region 3, Chicago, Office of the Director 77/05/08

item 4

1/17

--7706050294 IE Insp Repts 30-37/79-12 & 30-37/79-09 on 770318-026 No noncompliance noted. Major areas inspected: 1075 & 1076 procedures re used to reactor refueling activities, 1075 safe-ends & thermal sleeves & suppression pool and well activities.
HARRIS, J. W. PHILLIPS, J. S. Region 3, Chicago, Office of the Director 77/05/04 Spp

7706140518 Forwards IE Insp Rept 30-37/79-09 on 770321-23 No noncompliance noted.
HARRIS, J. W. Region 3, Chicago, Reactor Operations Nuclear Support Branch 77/04/13 Spp

--7706050294 IE Insp Rept 30-37/79-09 on 770321-23 No noncompliance noted. Major areas inspected: operating staff training & station operating procedures.
HARRIS, J. W. WRIGHT, J. C. Region 3, Chicago, Reactor Operations Nuclear Support Branch 77/04/13 Spp

7706040281 Forwards IE Insp Rept 30-37/79-16 on 770417-18 No noncompliance noted.
PARKER, W. D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 77/04/09 Spp

--7706040281 IE Insp Rept 30-37/79-16 on 770417-18 No noncompliance noted. Major areas inspected: no of miscellaneous area.
LEWIS, M. F. DUBOIS, J. W. Region 3, Chicago, Office of the Director 77/04/27 Spp

7706070284 Act receipt of 770418 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-37/79-11 & 30-37/79-08
PARKER, W. D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 77/05/01 Spp

--7706070284 Response to NRC 770315 ltr re violations noted in IE Insp Repts 30-37/79-11 & 30-37/79-08. Corrective actions: miscellaneous defects cleaned out of cable pan & electric nuclear grade splice boxes applied over cable jackets.
REED, C. Commonwealth Edison Co 77/04/10 Spp

7706100283 Forwards IE Info Notice 77-11, "Leak Reactor Vessel Head Insulation Support Problem - No action required."
SHEPARD, J. C. Region 3, Chicago, Office of the Director 77/05/07 Spp

7706050294 Response to IE Bulletin 77-03 on radiological weld defects in ASME 3A-312 type 304 stainless steel pipe splice. Splice not in use or planned for use.
REED, C. Commonwealth Edison Co 77/05/10 Spp

7706100278 Forwards IE Info Notice 77-12, "Accepted Damage to New Fuel Assembly."
SHEPARD, J. C. Region 3, Chicago, Office of the Director 77/05/01 Spp

7706100284 Forwards IE Bulletin 77-13, "Facility Overcurrent Trip Device in Circuit Breakers for Engineering Safety Sys." Licensee action required.
SHEPARD, J. C. Region 3, Chicago, Office of the Director 77/05/02 Spp

7706040038 Response to IE Bulletin 77-04 Review indicates survey sheet values are by Union Engineering Corp are not installed per will be installed in any Electric Category 1 piping area.
REED, C. Commonwealth Edison Co 77/05/04 Spp

7706040039 Forwards IE Info Notice 77-13, "Indication of Low Water Level in Quaker Creek Reactor."
SHEPARD, J. C. Region 3, Chicago, Office of the Director 77/05/07 Spp

B. Reportable occurrences, LERs & related correspondence

7706030274 Act receipt of 770418 final report on post-benching survey Repts 770320, 770321 repts. "Investigation of Stationhead Defects."
PARKER, W. D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 77/05/23 Spp

7706140038 Forwards deficiency repts re nonperformance of ventilation steel stack.
DELBRESE, L. D. Commonwealth Edison Co 77/04/06 Spp

--7706140038 Deficiency repts nonperformance of ventilation steel stack. Nondestructive examination revealed crack in stack. Permanent repair under study. Final repts will be submitted by 770601.
* Commonwealth Edison Co 77/04/06 Spp.

DOCKETED ITEMS

7904250284 Forwards Inrgc 790309 rept. "Investigation of Battenhead
Defects" in response to 790323 request W/O and
REED.C Commonwealth Edison Co 79/04/18 1p

DOCKET 50-374 LABALLE COUNTY STATION, UNIT 2

A Application/construction stage documents & correspondence

7904270409 Notification of 790326-22 meeting w/ will to discuss open
items in draft SR
BOURNE.A Light Water Reactors Branch 3 79/05/07 App

7904020130 Confirms 790521 meeting w/ will to discuss
open findings re const activities
NEPFLER.J.D Region 3, Chicago, Office of the Director 79/05/28
1p

F Security, medical, emergency & fire protection plans

7904050025 Forwards fire protection status rept covering portions of
review for which Power Ops Branch has review responsibility
SAGE.S Power Systems Branch 79/05/02 App

J Insurance & indemnity information

7904020187 Forwards executed Amends 21.51.9 & 1 to Indemnity Agreements
8-10, 8-47, 8-59 & 8-84, respectively
FOBLE.R.D Commonwealth Edison Co 79/05/29 App

P Operating license stage documents & correspondence

7904050029 Requests two controlled copies of site emergency plans &
implementation procedures, with maps showing location & grid
station number of onsite & offsite emission monitoring
stations & site maps used for dose determinations
NEPFLER.J.D Region 3, Chicago, Office of the Director 79/05/17

R Inspection reports, IE Bulletins & correspondence

7904050024 Forwards IE Insp Repts 50-373/79-12 & 50-374/79-09 on
790324-0318 No noncompliance noted
FIORILLI.G Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/04/04 App

7904050029 IE Insp Repts 50-373/79-12 & 50-374/79-09 on 790324-0318 No
noncompliance noted major areas inspected work & procedures
re used re reactor recirculating sys nozzle safe-ends &
thermal stresses & expansion seal and work activities
NEPFLER.J.D, PHILLIPS.B.R., REED.C Region 3, Chicago, Office
of the Director 79/05/06 App

7904070244 Act receipt of 790418 ltr informing ABC of steps taken to
correct violations noted in IE Insp Repts 50-373/79-11 &
50-374/79-08
FIORILLI.G Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/05/01 1p

7904070202 Responds to ABC 790318 ltr re violations noted in IE Insp
Repts 50-373/79-11 & 50-374/79-08 Corrective actions
miscellaneous debris cleaned out of cable pen & obsolete
cable grade splices began applied over cable jackets
REED.C Commonwealth Edison Co 79/04/18 App

7904120083 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Repair Problem" No action required
NEPFLER.J.D Region 3, Chicago, Office of the Director 79/05/07
1p

7904180784 Responds to IE Bulletin 79-03 re longitudinal weld defects in
ASME Sec-III Type 304 stainless steel pipe spools Reactor
not in use or planned for use
REED.C Commonwealth Edison Co 79/05/10 App

7904190078 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies."
NEPFLER.J.D Region 3, Chicago, Office of the Director 79/05/11
1p

7904150082 Forwards IE Bulletin 79-11, "Facility Overcurrent Trip Device
in Circuit Breakers for Engineered Safety Sys." License
action required
NEPFLER.J.D Region 3, Chicago, Office of the Director 79/05/22
1p

7904040328 Responds to IE Bulletin 79-04 Review indicates some check
values w/o by Union Engineering Corp are not installed nor
will be installed in any Safety Category 1 piping sys
REED.C Commonwealth Edison Co 79/03/24 1p

7904030080 Forwards IE Info Notice 79-13, "Indication of Low Water
Level in Outer Great Reactor" re "Investigation of
NEPFLER.J.D Region 3, Chicago, Office of the Director 79/05/29
1p

G Reportable occurrences, LRIs & related correspondence

7904030074 Act receipt of 790419 final rept re post-bonding
test Requests 790309 Inrgc rept. "Investigation of
Battenhead Defects"
FIORILLI.G Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/05/23 1p

7904140083 Forwards deficiency rept re nonconformance of ventilation
steel stack
DELSENGER.L.D Commonwealth Edison Co 79/04/06 1p

7904140092 Deficiency rept nonconformance of ventilation steel
stack Nondestructive examination revealed crack in stack
Permanent repair under study Final rept will be submitted by
790501
= Commonwealth Edison Co 79/04/06 App

7904050084 Forwards Inrgc 790309 rept. "Investigation of Battenhead
Defects," in response to 790323 request W/O and
REED.C Commonwealth Edison Co 79/04/18 1p

DOCKET 50-375 NUCLEAR EXAMINATION REACTION

G Inspection reports, IE Bulletins & correspondence

7904100426 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies." No written response necessary
NEPFLER.J.D Region 3, San Francisco, Office of the Director
79/05/10 1p

7904050024 Forwards IE Circular 79-06, "Attempted Extension - Low
Enriched U -
GROBLAND.R.H Region 3, San Francisco, Office of the Director
79/03/18 1p

DOCKET 50-382 WATERFORD DEMONSTRATING STATION, UNIT 3

A Application/construction stage documents & correspondence

7904100277 Censors w/recommended schedule change of GL safety review
Oral approval already received from Licensing Project
Manager
HAWNER.R.H Assistant Director for Plant 3

7904050148 Forwards attendance list ---
application
OSTA.P.C

DOCKETED ITEMS

7906149066 Notice of appearance on behalf of utility Certificate of Site
encl
STEVENSON, W. H. Monroe & Lemay 7/9/04/17 3pp

7906170170 Response to LA Consumer's League contentions submitted
790486 Contentions 2, 3, 4 & 6 should be accepted & Contentions
1 rejected Ruling re Contentions 5 & 7 should be deferred
Certificate of Site encl
HOUWELLMAN, J. Branch 3 7/9/04/25 16pp

7906184034 Joint statement to ASLE by participants Bayler Shell
Alliance, Bayou City Refinery & VCC indicating agreement on
contentions in pending Permit unable to reach agreement
on Contentions 8-10 & 22
HOUWELLMAN, J. Branch 3 7/9/04/25 30pp
Gillmore & Jones

1. Utility Final Safety Analysis Report (FSAR) & Amendments

7906140282 Forwarded Amend 4 to PSAR
ASLELL, S. & Louisiana Power & Light Co 7/9/04/07 1p

7906140345 Amend 4 to PSAR
Louisiana Power & Light Co 7/9/04/07 10pp

Inspection reports, IE Bulletins & correspondence

7906200223 Forwarded IE Insp Rept 30-082/79-04 on 790320-23 & notice of
violation
ASLELL, S. & C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 7/9/04/11 2pp

7906220228 Notice of violation from Insp on 790320-23
Region 4, Dallas, Office of the Director 7/9/04/11 2pp

7906220241 IE Insp Rept 30-082/79-04 on 790320-23 Noncompliance noted
failure to follow contract procedures re care & maintenance of
safety-related components & failure to perform required
background surveillance per procedures
HOUWELLMAN, J. C. Region 4, Dallas, Reactor Construction &
Engineering Support Branch 7/9/04/11 4pp

7906220241 IE Bulletin 79-05B, "Nuclear Incident at
TMI-2" "No written response required"
ASLELL, S. & C. Region 4, Dallas, Office of the Director 7/9/04/21
1p

7906230270 Forwarded IE Info Notice 79-01, "Lower Reactor Vessel Head
Insulation Support Problem" "No action required"
ASLELL, S. & C. Region 4, Dallas, Office of the Director 7/9/04/07
1p

7906230282 Forwarded IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
ASLELL, S. & C. Region 4, Dallas, Office of the Director 7/9/05/11
1p

7906240143 Ack receipt of 790427 ltr informing AEC of steps taken to
correct violations noted in IE Insp Rept 30-082/79-03
ASLELL, S. & C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 7/9/03/18 1p

7906240245 Response to NRC 790320 ltr re violations noted in IE Insp
Rept 30-082/79-03 Corrective action noncompliance reph
disagrees & procedure revision will be completed by
790330
ASLELL, S. & C. Louisiana Power & Light Co 7/9/04/27 3pp

7906240273 Forwarded IE Bulletin 79-11, "Faulty Overcurrent Trip Device
in Circuit Breaker for Engineered Safety Sys." License
action required
ASLELL, S. & C. Region 4, Dallas, Office of the Director 7/9/05/02
1p

E. Reportable occurrences, LERs & related correspondence

7906100165 Forwarded PSAR 79-07AM
ASLELL, S. & C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 7/9/05/06 1p

7906100168 Forwarded PSAR 79-07AM
ASLELL, S. & C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 7/9/05/16 1p

7906100247 Forwarded PSAR 79-07AM
ASLELL, S. & C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 7/9/05/22 1p

7906240288 Forwarded Part 21 reph from Zorn Industries, Inc. Review of
reph finds only one facility affected & two vendors
involved
ALBESON, C. E. Region 2, Atlanta, Office of the Director
7/9/05/22 1p

7906240288 Confirms 790518 helpline re cooling towers supplied to utility
by Zorn Industries, Inc. No further action by Zorn Industries
is required. Obligations now fulfilled
ALBESON, C. E. Region 2, Atlanta, Office of the Director
7/9/05/22 1p

7906240245 Notice of concern re capability of essential cooling
water sys. in function in manner adequately providing for
all safety-related cooling requirements. Supporting
documentation encl
ASLELL, S. & C. Zorn Industries, Inc. 7/9/05/03 33pp

7906100288 Forwarded PSAR 79-07AM
ASLELL, S. & C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 7/9/05/23 1p

DOCKET 30-087 EUROSHAWNEE STEAM ELECTRIC STATION, UNIT 1

A. Application/construction stage documents & correspondence

7906200223 Summary of 790419 meeting w/ utility on Oakdale, MO re security
plans. Forwarded request for add'l info for permit issued
pending re draft security plan evaluation reph Request
withheld (ref 100P93 7901)
CLARK, R. A. Reactor Safeguards Licensing Branch 7/9/05/00 3pp

7906120004 Approves request for withholding Kraftwerk Union
Atkinsgesellschaft tests & reph from public disclosure
(ref 100P93 7901)
PARR, D. D. Light Water Reactors Branch 3 7/9/05/11 3pp

7906120015 Pennsylvania second round questions re containment design &
testing. Revision 1 to design assessment reph is currently
under review
PARR, D. D. Light Water Reactors Branch 3 7/9/05/13 11pp

7906220162 Forwarded request for add'l info re initial tests & operation
Light Water Reactors Branch 3 7/9/05/18 10pp

7906230218 Summary of 790323 meeting w/ utility, Kraftwerk Union & GRI. In-ltr
to discuss condensation oscillation test to be conducted in
Germany
HINER, B. Light Water Reactors Branch 3 7/9/05/21 14pp

7906230294 Submits schedule for responding to NRC 790518 request for add'l
info for Section 523
CURTIS, H. W. Pennsylvania Power & Light Co 7/9/06/07 1p

7906120004 Submits schedule for responding to 790518 request for add'l
info for Section 523
CURTIS, H. W. Pennsylvania Power & Light Co 7/9/06/08 1p

7906100420 Forwarded Affidavit of Site for Amend 11 to facility GL
application
CURTIS, H. W. Pennsylvania Power & Light Co 7/9/06/12 3pp.

7906240280 Submits licensing schedule for facility Pressurized
water
CURTIS, H. W. Pennsylvania Power & Light Co 7/9/06/20 8pp

C. Utility Environmental Report (ER), amendments & correspondence

7906240288 Forwarded Amend 12 to GL application, containing Revision 2 to
environment reph
CURTIS, H. W. Pennsylvania Power & Light Co 7/9/06/01 4pp

7906240280 Amend 12 to GL application, 4/4 790780, containing Revision 2
to environment reph
CURTIS, H. W. Pennsylvania Power & Light Co 7/9/06/01 30pp

F. Security, medical, emergency & fire protection plans

7906240288 Request for add'l info re physical security plan for review of
GL application. Security info withheld (ref 100P93 7901)
PARR, D. D. Light Water Reactors Branch 3 7/9/05/23 2pp

G. Adjudicatory correspondence

7906140682 Request to make limited appearance statement at licensing
proceeding unfavorable
MELLINGER, J. M. Affiliation Unknown 7/9/06/18 1p

DOCKETED ITEMS

790408007 Requests limited appearance at licensing hearings
FORD, D Affiliation Unknown 79/05/06 1p

--790408008 Requests limited appearance statement
BULFORD, E Affiliation Unknown 79/05/11 1p

--790408010 Requests limited appearance at preliminary hearing
HUNT, D Affiliation Unknown 79/05/11 1p

790410013 Forwarded motion to restrain until from obtaining govt permits
involving safety or environ matters prior to evidentiary
hearings on DC Petitions Governor of PA to declare
LERNMAN, C Citizens Against Nuclear Dangers 79/05/12 1p

--790410130 Requests motion to restrain until from obtaining govt permits
involving safety or environ matters prior to evidentiary
hearings on DC Petitions Governor of PA to declare
LERNMAN, C Citizens Against Nuclear Dangers 79/05/12 1p

790410040 First round discovery requests & interrogatories submitted
to Citizens Against Nuclear Dangers per ASLB 790306 special
prehearing conference order re Contention 2, 4, 6, 9-11, 16 &
17
CUTCHIN, J M Branch 3 79/05/21 11pp

--790410045 First round discovery requests & interrogatories submitted
to Citizens Against Nuclear Dangers per ASLB 790306 special
prehearing conference order re Contention 2, 4, 6, 9-11, 16 &
17
CUTCHIN, J M Branch 3 79/05/21 11pp

--790410072 First round discovery requests & interrogatories submitted
to European Environ Associates per ASLB 790306 special
prehearing conference order re Contention 2, 4, 6, 9-11, 16 &
17
CUTCHIN, J M Branch 3 79/05/21 11pp

--790410075 First round discovery requests & interrogatories re
Contentions 1-9 & 18, submitted to Environ Coalition on
Nuclear Power per ASLB 790306 order re Certificate of Dec
CUTCHIN, J M Branch 3 79/05/21 11pp

790427018 Series Citizens Against Nuclear Dangers 790512 motion to
prevent from obtaining govt permits including
permit from State of PA which sought to against NRC policy
NRC act as authority over Governor of PA
BECHEM, C Atomic Safety and Licensing Board Panel 79/06/07
5pp

K. Utility Final Safety Analysis Report (FSAR) & amendments

790400100 Forwarded Amend II to GL consisting of Revision 9 to FSAR
CURTIS, H W Pennsylvania Power & Light Co 79/06/01 1p

--790400105 Amend III to GL consisting of Revision 9 to FSAR
CURTIS, H W Pennsylvania Power & Light Co 79/06/01 130pp

G. Inspection reports, IE Bulletins & correspondence

790414001 Forwarded IE Insp Rept 90-387/79-00 on 790227-0302 No
noncompliance noted
BROOKS, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 79/03/29 2pp

--790414007 IE Insp Rept 90-387/79-08 on 790227-0302 No noncompliance
noted Major areas inspected implementation of
operational testing administrative controls & followup on
defective actions re IE bulletins & circulars
BROOKS, E J Region 1, Philadelphia, Office of the Director,
Nuclear Safety & Licensing Branch 79/03/29 10pp

790414001 Forwarded IE Insp Repts 90-387/79-05 & 90-388/79-04 on
790209-0302 No noncompliance noted
CARLSON, R T Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 79/04/09 2pp

--790414008 IE Insp Repts 90-387/79-05 & 90-388/79-04 on 790209-0302 No
noncompliance noted Major areas inspected installation &
use of reactor coolant pressure boundary in Unit 1 &
installation of safety-related pipe support sys in Unit 2
CARLSON, R T Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 79/04/09 7pp

790418047 Forwarded IE Info Notice 79-16, "Nonconforming Pipe Support
Brackets." No written response necessary
CARLSON, R T Region 1, Philadelphia, Office of the Director
79/04/16 1p

790426019 Forwarded IE Insp Rept 90-387/79-09 on 790227-08 & 0301-02 No
noncompliance noted
CARLSON, R T Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 79/04/20 2pp

--790426020 IE Insp Rept 90-387/79-09 on 790227-08 & 0301-02 No
noncompliance noted Major areas inspected activities
associated with re-entrant nozzles & storage of
safety-related components
TRIPLE, L E - NAL, 1004 J A, JEROME, E P Region 1, Philadelphia,
Reactor Construction & Engineering Support Branch 79/04/19 4pp

790410030 Forwarded IE Bulletin 79-05B, "Nuclear Incident at
TRI-UMPH." No written response required
CARLSON, R T Region 1, Philadelphia, Office of the Director
79/04/20 1p

790413170 Forwarded IE Circular 79-07, "Unspecified Speed Increase of
Reactor Motor Generator Set Resulted in Reactor Power
Increase." No written response required
CARLSON, R T Region 1, Philadelphia, Office of the Director
79/05/02 1p

790407017 Del receipt of 790420 ltr informing NRC of steps taken to
correct violation noted in IE Insp Repts 90-387/79-04 &
90-388/79-03
CARLSON, R T Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 79/05/04 1p

--790407018 Response to NRC 790302 ltr re violation noted in IE Insp
Repts 90-387/79-04 & 90-388/79-03 Corrective actions
nonconforming weld joint removed
BAND, A M Pennsylvania Power & Light Co 79/04/30 3pp

--790407019 Forwarded IE Insp Repts 90-387/79-04 & 90-388/79-03 on
790212-15 & notice of violation
CARLSON, R T Region 1, Philadelphia, Office of the Director
79/03/02 2pp

--790407025 Notice of violation from insp on 790212-15
&
CARLSON, R T Region 1, Philadelphia, Office of the Director 79/03/02 1p

--790407021 IE Insp Repts 90-387/79-04 & 90-388/79-03 on 790212-15
Nonconformities noted. No action required
BAND, A M Region 1, Philadelphia, Office of the Director
TRIPLE, L Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 79/03/01 4pp

790410010 Forwarded IE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Support Problem." No action required
CARLSON, R T Region 1, Philadelphia, Office of the Director
79/03/07 2pp

790400140 Forwarded IE Info Notice 79-12, "Attempted Damage to New Fuel
Assembly." CARLSON, R T Region 1, Philadelphia, Office of the Director
79/05/11 1p

G. Reportable occurrences, LERs & related correspondence

790413040 Acc receipt of 790410 ltr evaluating cast cable deficiency
CARLSON, R T Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 79/05/03 1p

790413004 Acc receipt of 790406 ltr forwarding final rept re
undersized weld on safety-related pipe hanger
CARLSON, R T Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 79/05/14 1p

--790413003 Final deficiency rept undersized weld on safety-related
pipe hanger, discussed in 790202 & 790404 ltrs Shop
fabrication of hangers spec lacked specific criteria for
acceptance/rejection of weld
CURTIS, H W Pennsylvania Power & Light Co 79/04/06 45pp

790400240 Final rept of abnormal wear of roller pins in crosshead
assembly of emergency standby diesel generators Roller
pins supplied by Cooper Energy Inc
CURTIS, H W Pennsylvania Power & Light Co 79/03/29 2pp

DOCKET 90-388 BURESHAWA STEAM ELECTRIC STATION, UNIT 2

A. Application/construction stage documents & correspondence

790426020 Summary of 790419 meeting w/Unit 1 Burehawa, MD re security
plans. Forwarded request for add info for second round
question re draft security plan evaluation rept Request
withheld (ref 105782 790426020)
CARLSON, R T Reactor Safeguards Licensing Branch 79/05/06 2pp

DOCKETED ITEMS

- 7904130548 Approves request for withholding Kraftwerk Union antineutronium tests & report from public disclosure
 (rad 100FR2 7901)
 PARKS, D. S. Light Water Reactors Branch 3 79/05/11 2pp
- 7904130108 Forwards second round questions re containment design & testing Revision 1 to design assessment report is currently under review
 PARKS, D. S. Light Water Reactors Branch 3 79/05/11 10pp
- 7904200102 Forwards request for addl info re initial tests & operation
 PARKS, D. S. Light Water Reactors Branch 3 79/05/18 14pp
- 7904200105 Summary of 790323 meeting w/ Kraftwerk Union & SRI Int'l to discuss construction certification test to be conducted in Germany
 PARKS, D. S. Light Water Reactors Branch 3 79/05/21 14pp
- 7904220394 Submits schedule for responding to NRC 790318 request for addl info for Question Q21
 CURTIS, H. M. Pennsylvania Power & Light Co 79/05/27 1p
- 7904220403 Submits schedule for responding to 790508 request for addl info for Question Q23
 CURTIS, H. M. Pennsylvania Power & Light Co 79/05/28 1p
- 7904130423 Forwards Affidavit of Sec for Ass'd II to Facility Q1 application
 CURTIS, H. M. Pennsylvania Power & Light Co 79/05/12 2pp
- 7904200300 Submits licensing schedule for Facility Press releases
 CURTIS, H. M. Pennsylvania Power & Light Co 79/05/30 8pp
- C Utilizing Environmental Report (ER); attend & correspondence
- 7904040200 Forwards Amend II to Q1 application, containing Revision 2 to revision page
 CURTIS, H. M. Pennsylvania Power & Light Co 79/05/01 4pp
- F Security: medical, emergency & fire protection plans
- 7904070739 Requests addl info re physical access plan for review of Q1 application Security info withheld (rad 100FR2 7901)
 PARKS, D. S. Light Water Reactors Branch 3 79/05/29 2pp
- G Adjudicatory correspondence
- 7904140525 Requests to date limited appearance videotape at licensing prehearing conference
 MILLER, R. D. Affiliation Unknown 79/04/18 1p
- 7904050937 Requests limited appearance at licensing hearings
 FORD, S. Affiliation Unknown 79/05/06 1p
- 7904030041 Requests limited appearance statement
 BUXFORD, C. Affiliation Unknown 79/05/11 1p
- 7904050210 Requests limited appearance at preliminary hearing conference
 HARTING, M. Affiliation Unknown 79/05/12 1p
- 7904190012 Forwards motion to restrain whl from obtaining govt permits involving safety or environ matters prior to adjudicatory hearing re Q1 action pending Governor of PA to declare moratorium on issuance of permits
 LEMMON, J. Citizens Against Nuclear Dangers 79/05/12 1p
- 7904190150 Requests motion to restrain whl from obtaining govt permits involving safety or environ matters prior to adjudicatory hearing re Q1 action pending Governor of PA to declare moratorium on issuance of permits
 LEMMON, J. Citizens Against Nuclear Dangers 79/05/12 1p
- Initiated
- 7904190565 First round discovery requests & interrogatories submitted to C HPA&L per ABL 790306 special prehearing conference schedule, re Conventions 4-6 & 9-11
 CUTCHIN, J. H. Branch 3 79/05/21 13pp
- 7904190772 First round discovery requests & interrogatories submitted to Susquehanna Environ Associates per ABL 790306 special prehearing conference, re Conventions 1,3,4,6,9-11 & 18
 CUTCHIN, J. H. Branch 3 79/05/21 13pp
- 7904190776 First round discovery requests & interrogatories re Conventions 1-9 & 18, submitted to Susquehanna Coalition on Nuclear Power per ABL 790306 order w/ Certificate of Sec CUTCHIN, J. H. Branch 3 79/05/21 10pp
- 7904270185 Series Citizens Against Nuclear Dangers 790312 motion to restrain applicant from obtaining govt permits, including permit from State of PA, whl sought is against NRC policy; NRC has no authority over Governor of PA
 BECHTOLD, C. Atomic Safety and Licensing Board Panel 79/04/07 5pp
- H Utilizing Panel Safety Analysis Report (PSAR) & amendments
- 7904040193 Forwards Amend II to Q1, consisting of Revision 7 to PSAR
 CURTIS, H. M. Pennsylvania Power & Light Co 79/04/01 1p
- 7904040196 Amend II to Q1, consisting of Revision 9 to PSAR
 CURTIS, H. M. Pennsylvania Power & Light Co 79/04/01 10pp
- I Inspection reports, IE Bulletin & correspondence
- 7904100421 Forwards IE Insp Rpts 50-387/79-03 & 50-388/79-04 on 790205-0302 No noncompliance noted
 CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/09 2pp
- 7904100420 IE Insp Rpts 50-387/79-03 & 50-388/79-04 on 790205-0302 No noncompliance noted Major areas inspected Installation & welding of reactor vessel pressure boundary in Unit 2 & installation of safety-related pipe support in Unit 2
 CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/08 7pp
- 7904130457 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts - No written response required"
 CARLSON, R. T. Region 1, Philadelphia, Office of the Director 79/04/16 1p
- 7904130423 Forwards IE Bulletin 79-058, "Nuclear Incident at 50-388-12" No written response required
 CURTIS, H. M. Region 1, Philadelphia, Office of the Director 79/04/23 1p
- 7904130173 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Due Resulted in Reactor Power Increase" No written response required
 CURTIS, H. M. Region 1, Philadelphia, Office of the Director 79/05/02 1p
- 7904070179 Ask receipt of 790420 1st inferring NRC of steps taken to correct violation noted in IE Insp Rpts 50-387/79-04 & 50-388/79-03
 CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/04 1p
- 7904070484 Responds to MRC 790302 1st re violation noted in IE Insp Rpts 50-387/79-04 & 50-388/79-03 Corrective actions nonconforming used tank repaired
 CARLSON, R. T. Pennsylvania Power & Light Co 79/04/30 2pp
- 7904070187 Forwards IE Insp Rpts 50-387/79-04 & 50-388/79-03 on 790212-12 & 790213-12 & 790214-12 No noncompliance noted
 CARLSON, R. T. Region 1, Philadelphia, Office of the Director 79/05/02 2pp
- 7904070206 Notice of violation from Insp on 790212-12 & 790213-12 & 790214-12 No action required
 CURTIS, H. M. Region 1, Philadelphia, Office of the Director 79/05/02 1p
- 7904070213 IE Insp Rpts 50-387/79-04 & 50-388/79-03 on 790212-12 Noncompliance noted Failure to meet AGN 211 safe requirements for pipe weld joint alignment
 CURTIS, H. M. Region 1, Philadelphia, Office of the Director 79/05/02 2pp
- 7904130192 Forwards IE Info Notice 79-15, "Lower Reactor Vessel Head Insulation Support Problem" No action required
 CURTIS, H. M. Region 1, Philadelphia, Office of the Director 79/05/07 2pp
- 7904200145 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assembly"
 CURTIS, H. M. Region 1, Philadelphia, Office of the Director 79/05/11 1p

DOCKETED ITEMS

5 Reportable occurrences, LRNs & related correspondence

7704130300 Act receipt of 770419 ltr evaluating core cable deficiency
CARLSON R T Region 1: Philadelphia, Reactor Construction & Engineering Support Branch 77/03/03 lg

7704130304 Act receipt of 770404 ltr forwarding final wpt re underwelds on safety-related pipe hangers
CARLSON R T Region 1: Philadelphia, Reactor Construction & Engineering Support Branch 77/03/04 lg

--7704130304 Final deficiency report underwelds on safety-related pipe hangers; discussed in 770202 & 770404 ltr; Shop fabrication of hangers spc lacked specific criteria for acceptance/rejection of welds
CURTIS H W Pennsylvania Power & Light Co 77/04/04 45pp

7704130305 Final wpt of abnormal wear of roller pins in overhead assemblies of emergency standby (diesel) generators
Butler plus supplied by Cooper Energy Svc
CURTIS H W Pennsylvania Power & Light Co 77/05/02 2pp

DOCKET 30-58V ST. LUCIE PLANT, UNIT 2

A Application/construction stage documents & correspondence

7704130302 Notification of 770316 meeting w/atl in Bethesda, MD to discuss failure of offsite power w/initial/known onsite partial failure & other ALAB-537 matters; hearing originally scheduled for 770303
DIFKUL R A Light Water Reactors Branch 2 77/03/02 2pp

7704130313 Notification of 770306 meeting w/atl in Bethesda, MD to discuss failure of offsite power w/initial/known onsite partial failure & other ALAB-537 matters
DIFKUL R A Light Water Reactors Branch 2 77/03/02 2pp

B Adjudicatory correspondence

7704130407 Motion for extension until 770411 to prepare response to ALAB-539
MCINTOSH J F Hearings Division 77/04/02 3pp

--7704130600 Responds to 770302 request for info re status of rulemaking regarding to design value for radon in Table B-3 Rpts & proposed rule will be sent by NRC by 770406. Rule does not address health effects of radon releases
CHRISTENSEN E Hearings Division 77/03/06 34pp

7704130600 Rule & order terminating jurisdiction over ALAB-435 steam generator tube integrity interveners' action for new contention is dismissed as moot; stay motion is denied & parties are directed to file prepared testimony
DIFKUL R A Atomic Safety and Licensing Appeal Panel 77/04/05 2pp

7704130608 Denies wtl's motion to cancel hearings & interveners' motion for discovery re adequacy of emergency power sys
DIFKUL R A Atomic Safety and Licensing Appeal Panel 77/05/03 4pp

7704130609 Motion for extension of time in which to answer questions re applicant's electrical grid & emergency power sys; Applicant does not object to request Motion granted by ASLAP on 770313 Certificate of Svc and
PATTON W D Branch 4 77/03/11 6pp

7704140514 Orders extension of time until 770404 to review portion of ALAB-537 re electrical grid stability & emergency power sys
NRC has decided not to review other items decided in ALAB-537.
CHILDS J J Office of the Secretary of the Commission 77/05/17 lg

7704130607 NRC notice for summary disposition re radon issue was in error; ALAB-540 consolidated only 3 of 16 cases. Denies NRC motion as to parties in other proceedings; Certificate of Svc and
DIFKUL R A Atomic Safety and Licensing Appeal Panel 77/05/25 2pp

J. Insurance & indemnity information

7704130419 Forwards Endorsements 25 & 26 to NREL Policy 99-08
BURN J E Marsh & McLennan; H & R Nuclear Consultants; Inc Div 77/04/12 3pp

6 Inspection reports, EE Delineating & correspondence

7704130604 Forwards IE Insp Rpt 50-389/77-06 on 770327-29 No noncompliance noted
HARRIS C E Region 2: Atlanta, Reactor Construction & Engineering Support Branch 77/04/11 2pp

--7704130604 IE Insp Rpt 50-389/77-06 on 770327-29 No noncompliance noted. Major areas inspected safety-related piping, radiography review & reactor bldg refueling canal liner; welding steel containment liner; weld repairs
HARRIS C E Region 2: Atlanta, Office of the Director
COMLINT E Region 2: Atlanta, Reactor Construction & Engineering Support Branch 77/04/10 4pp

7704130606 Forwards IE Insp Rpt 50-389/77-06 on 770327-29 No noncompliance noted
HARRIS C E Region 2: Atlanta, Reactor Construction & Engineering Support Branch 77/04/12 2pp

--7704130606 IE Insp Rpt 50-389/77-06 on 770327-29 No noncompliance noted. Major areas inspected containment steel structures; safety-related components & safety-related structures outside containment
HARRIS C E Region 2: Atlanta, Office of the Director
COMLINT E Region 2: Atlanta, Reactor Construction & Engineering Support Branch 77/04/11 4pp

7704130607 Forwards IE Info Notice 77-12: "Accepted Damage to New Fuel Assemblies"
HARRIS C E Region 2: Atlanta, Office of the Director 77/03/12 lg

7704130608 Responds to IE Bulletin 77-04 re Valves swing check valves
No such valves being supplied for unit
HARRIS C E Florida Power & Light Co 77/03/22 lg

U Congressional/Executive Correspondence

7704130609 Provides addl info re D. Browning info request concerning PL nuclear power situation; discusses wastes produced by PL plants; effluents released; & consequences of possible accident
O'BRIEN L V Office of the Executive Director for Operations 77/03/17 3pp

DOCKET 30-290 MATES BAY NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7704130620 Forwards second round questions for biennially to applicant; Outstanding items qualification of safety-related equipment; identification of safety sys & equipment & identification of NRC requirements re safety sys
DINTERFIELD B Electric, Instrumentation & Control Systems Branch 77/03/21 12pp

7704130607 Notification of 770317-18 meeting w/EVA in Knoxville, TN to discuss building design criteria; using addl info requests as basis for discussion
STALE C R Light Water Reactors Branch 4 77/05/06 3pp

7704130608 Submits requests for addl info on mat integrity & structural engineering; Requests responses by 770407
WILSON E A Light Water Reactors Branch 4 77/03/16 15pp

7704130609 Request
safef
comd
ASST
DIA

Q Inspection reports, 66 Bulletins & correspondence

7906158457 Forwards IE insp Repts 50-290/79-11 & 50-291/79-08 as
790305-08 Re noncompliance noted
SUNBELT, INC. J T Region 2: Atlanta, Fuel Facility & Material
Safety Branch 79/03/30 See

--PROBATION IE Insp Repts 50-34674-11 & 50-29179-07 on 790309-
noncompliance noted Major areas inspected radiological
environ monitoring program
MACARTHUR, J C, KENNEDY, W W, HUGHAN, J M Region 2, Atlanta,
Office of the Director 79/03/29 dan

3900000003 Forwarded IE Insp Repts SO-090/79-14 & SO-091/79-10 as
390000-8320 No noncompliance noted
RJR/RJC IE Region 2, Atlanta- Swach Construction & Engineering
Support Branch 79/04/03 Doc

--7903050075 IE Insp Rpts 80-270/79-14 & 80-270/79-11 on 790320-0321 to noncompliance noted Major areas inspected reactor vessel internals quality records & safety-related pipe support restraint sys & Unit 2 Containment penetrations records
VALLIN, E W Region 2, Atlanta, Office of the Director
BRWANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/03 Spa

790220084 Forwarded IE Insp Repts 50-09579-15 & 50-09179-02 as
790220-23 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 79/04/11 2ea

9-7460220093 IE Insp Repts 80-390/79-18 & 80-071/79-12 on 782280-22 Mo
noncompliance noted Major areas inspected production of
installed instrumentation components & panels, fire
suppression equipment & installation & records re cables
RUFF, A E Region 2, Atlanta, Office of the Director
SRVMT, J C Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 78/04/06 4pp

790620286 Forwards IE Insp Repts SO-290/79-15 & SO-291/79-12 re
790627-38 Re noncompliance noted
MURRAY, C E Region 2, Atlanta: Traffic Construction & Engineering
Support Branch 79/06/12 Doc

99-7932100F1 IE Insp Repts 50-DWD/79-16 & 50-DWI/79-13 on 790327-33 No
noncompliance noted Major areas inspected license action on
previous insp findings, preservice insp-review of procedures
& preservice insp-observation of work & work activities
OIS&D E Region 2, Atlanta, Office of the Director
COL&D E Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 79/04/12, Jaa

790620004: Ask receipt of 790611 ltr informing WRC of steps taken to
correct violations noted in IE Insp Repts 90-090/77-09 &
90-391/77-07
MURPHY, C E Region 2-Atlanta, Reactor Construction & Engineering
Support Branch 79105/09 Sum

7906210045 Responds to NRE 790288 ltr re violations noted in IE insp
Sept 58-249/79-04 & 58-249/79-09 Corrective actions insp of
units show only 1 75 inches exceed specs. No further action
will be taken
GIL/ELN:J E Tennessee Valley Authority 09/06/79 2-1

798210031 Forwards IE invg Regis SO-SFO/79-09 & SO-SFO/79-07 on
79220-03 & notice of violation
RMB/Pr.C E Region 2: Atlanta: Office of the Director
79/03/20 Jys

* Region 2, Atlanta, Office of the Director 7/6/03 10

7Y06210007 DE Engr Repts 50-340779-07 & 50-340779-07 on 740020-2
Noncompliance noted weld reinforcement on chemical & weld
rod eye bolts exceeded specs
R.E.H. - CORRUPT DE Region 2, Atlanta, Office of the

--7904210100 Notice of violation from insp on 790206-09
* Region 2, Atlanta, Reister Construction & Engineering Support
Branch 79020710 1a

--790621010 DE Insp Regd 00-390/77-07 on 790304-09 Noncompliance noted
failure to follow procedure applicable to cable routing in
Tachau
REF: A.D. - DRYANT, J.C. Season 2, Atlanta, Reactor Construction

7906280074 Act receipt of 790427 for informing SSC of steps taken to correct violations noted in IE Insp Repts 90-390/79-12 b
58-381/79-07
MARPHR C E Region 2, Atlanta: Reactor Construction & Engineering

--P90200106 Response to NRC P90404 10/ re violation cited in IF Insp
Repts 50-296/79-12 & 50-291/79-08 Connective actions record
requiring approval signature signed Painted over corrections
determined to be typographical in nature
GILLBLAND, J E Tennessee Valley Authority 79/04/27 Dep

--7486200193 Forwarded to Insp Regs 30-390/79-12 & 30-296//9-09 on 7/23/12-12 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 7/23/08 2pm

--7906200196 Notice of violation from intp on 790312-18
* Region 2, Atlanta: Office of the Director 79/04/04 to

--796200284 SE Insp Reg'd 30-390/79-12 & 30-391/79-09 on 790312-13
Noncompliance noted insufficient records used to furnish
evidence of activities affecting quality Record corrections
dated over, instead of line drawn through & corrected
WAK 0300Z P K Region 2, Atlanta; Office of the Director
CONJUL T K Region 2, Atlanta; Research Construction &
Engineering Support Branch 79/04/04 Sep

FD-302 (Rev. 10-6-95) Responds to IE Bulletin 77-03 Investigation shows no piping in use or planned for use in safety-related systems. Efforts in progress to locate any ADE (S-112) Type 304 piping supplied by Youngstown Welding & Engineering Co. DITTELAND, J. E. Tennessee Valley Authority 7/26/2015 1a

7906080289 Submits revised response to SA records deficiency noted
790404 Insp Repts 80-240/79-12 & 50-390/79-09
SULLIVAN, J E Tennessee Valley Authority TN 37604

PROAD00094 First interim deficiency rept incorrect Velan valve used in seismic piping analysis final response to IC Bulletin 79-04 will be submitted before fuel load in Univ.]

396u29772 Submits response to deviation & infractions cited in IC
 Insp Repts 50-393/79-20 & 50-391/79-1a
 GILLBLAND, J E Tennessee Valley Authority 79/04/20 Tex

* Reportable occurrences, LERs & related correspondence.

PW36140088 Forwards final deficiency report to installation of
pipe hanger anchors.
DILLARD, J E Tennessee Valley Authority memphis TN

--790648387 Final deficiency report improper installation of seismic pipe hanger anchor caused by lack of concern by some installers Anchor bolts inspected & add instructions provided

PH06080277 Dussell: Fifth Eserum deficiency rept re possible
unconservative pressure-rep relief & safety line Westdown
analysis Rept to be submitted by 770710, after Westdown
review of noise loads
BILLEARD, J E TROUSSE Valley Authority, TROUSSE, J

00440404 Forwards final deficiency rpt re potential excessive water
hammer forces in main feedwater line
GILLESPIE, J E Yreka Valley Authority 77/05/21 1p

2906140410 Final deficiency report Westinghouse informed utility of potential excessive water hammer forces in main feedwater stop Analysis revealed check valves adequate to perform under accident conditions

61404M Submits second interim rept potential interior structural
test containment vessel movement envelope. Util analysis of
6-bolt condition is not yet complete. Next rept will be
submitted by 7/20/87
ILLINOIS J E Tennessee Valley Authority

DOCKETED ITEMS

7906140579 Submitt fifth interim deficiency rept possible
unconservative pressurizer relief & safety line blowdown
analysis. Initially reported on 790505. Next rept to be sent
790718. After vendor completes review of nozzle loads
OILDELAND, J E Tennessee Valley Authority 79/03/29 is

7706080207 Revised 79010 final deficiency repleve control loop
bistable failure on loss of power Revision specifies that
wiring diagram for bistables have been corrected to physical
wiring will be corrected
* Tennessee Valley Authority 77/05/31 JP

7906100300 Forwards interim deficiency report for files supporting essential raw cooling water pipe slab not being driven to drawing requirements investigation under magic corrective action to be determined
GILLELAND, J E Tennessee Valley Authority 79/06/04 10

```
--7996100307 First interim deficiency rep't piles supporting essential raw
cooling water pipe slab not driven to design requirement
CER 79-3
* Tennessee Valley Authority 79/04/04 IP
```

3904286403 Buhrmests second interim deficiency report re power operated relief valves initially reported 790609 Valve extended structure to be modified to increase natural frequency of valve

GALELAND, J E Tennessee Valley Authority 79/06/13 1p

190432007: Forwards first interim rep't re Deficiency 4 (ord/Flanges)
GILLELAND, J E Tennessee Valley Authority 79/06/18 1p

--7904220075 First interim deficiency report ariside flanges do not meet
spec Full investigation to be conducted to determine
cause of ariside flanges hydro failure & possible
consequences
* Tennessee Valley Authority 79/04/17 Doc

7903200086 Forwards final deficiency rept re pipes embedded in structural concrete, as reported on 790128 & discussed in 790220 interim rept
DILLER, J E Tennessee Valley Authority 79/05/12 is

--7905220067 Final deficiency report pipes embedded in structural concrete
US1 failed to comply w/AGE DIB-63 requirements General
civil design criteria for affected structures evaluated &
revised to ensure compliance
* Tennessee Valley Authority 7/9/05/13 Ben

7906270210 Forward fuel deficiency rept re auxiliary feedwater pump essential ram cooling water valves
 8-11M 8-11M 7906270210 7906270210 7906270210

--7906020020 Final deficiency reft auxiliary feedwater pump essential
rem cooling water valves which might not open fast enough to
prevent pump damage due to pumps running dry Supply valve
operators to be replaced by faster acting operators
* Tennessee Valley Authority 79/06020 is

FD06270324 Forwards revised final deficiency rept re motor operated
valve control circuit faileres
GOLLELAND, J E Tennessee Valley Authority 29/06/20 1c

--7904370226 Revised final deficiency report notes operated valve control circuit failure Relay failure could have triggered events deactivating part of one train of safety sys Relays will be subjected to burn-in period
* Tennessee Valley Authority 7/9/04/20 Doc

790600204 Requests approval of flexible metal hose for use as safety-related piping by 790615 Forwards data demonstrating compliance w/Reg Guide 1.94 & ASME Code applications addressed in Case 14-192

DILLIARD, J E Tennessee Valley Authority 79/05/21 0000

79060102022 Confirms schedule Perdue agenda for 790624-15 meeting in Knoxville, TN to discuss containment buckling criteria
GILLILAND, J E Tennessee Valley Authority 790629 20a

7956010196 Forwards Amend 09 to FEAR
GILLILAND, J E Tennessee Valley Authority 79/03/29 1a

--79060109 Amend 34 to FEAR includes responses to NRC second round questions, revised FEAR figures & miscellaneous FEAR test revisions
* Tennessee Valley Authority 7906/29 256pp

79060703491 Forward Certificate of Evt. averring that Amnd 39 to FEAR
was served on 790605
MILLER, M Tennessee Valley Authority TN/04/05 Eas

9. Inspection reports, IC Bulletin & correspondence

7906190487 Forwards SE Insp Regs 80-390/79-11 & 80-391/79-08 on
790305-08 No noncompliance noted
SOUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials
Safety Branch 29/03/80 2pg

--7906150463 IE Insp Repts SO-290/79-11 & SO-391/79-07 on 790303-08 Re noncompliance noted Major areas inspected radiological environ monitoring program
MACARTHUR, T C, POBRY, W M, HUFFMAN, J W Region 2, Atlanta
Office of the Director 79/03/29 day

7903030AC Forwards IR Insp Repts 20-39D/79-14 & 20-39I/79-11 on
790320-0322 Re noncompliance noted
HARRIS, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 79/04/03 See

--9906050075 IE Insp Repts 05-090/79-14 & 05-091/79-11 on 790329-0021 N
noncompliance noted Major areas inspected Reactor vessel
Internal quality records & safety-related pipe supports
Reinforced concrete & Unit 2 containment penetrations records
VALLEJO, E J Region 2, Atlanta, Office of the Director
BYRNAT, J C Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 79/04/03 3pm

7904220084 Forwards IE Insp Rpts 88-090/79-10 & 88-091/79-12 on
790380-20 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 79/04/13 Doc

--7906280049 IE Insp Rpts SC-DPO/79-13 & SC-DPI/79-12 on 790328-23 Re
noncompliance noted Major Areas Inspected protection of
installed instrumentation components & gasels, fire
suppression equipment & installation & records & cables
NUPP.A 2 Region 2, Atlanta, Office of the Director
OSWANT, J C Region 2, Atlanta, Spector Construction &
Engineering Support Branch 79/04/06 4pp

7906210286 Forwards IC insp Repts 50-298/79-16 & 50-291/79-12 as
790327-38 No noncompliance noted
NABPHV, C.E. Region 3, Atlanta, Tracker Construction & Eng'g
Buckner Branch, 78/04/10 Don

BUCKET 50-091 WATTD BAR NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

79D4ia0279 Forwards second round questions for transmittal to
applicant. Outstanding items: qualification of safety-related
equipment; identification of safety sys & equipment &
identification of NRC requirements re safety sys
WATTONFIELD, R Electric, Instrumentation & Control Systems
Branch 79/03/21 1230

7906050087 Notification of 790517-DM meeting w/TW in Knoxville, TN to discuss buckling design criteria, using encl info requests as basis for discussion
STANLEY, C B Light Water Reactors Branch 4 79/05/08 See

7904280006 Submits requests for addi info on matl integrity &
mechanical engineering. Requests responses by 790429.
VWR0A:R, A Light Meter Reactors Branch 4 79/03/16 1900

DOCKETED ITEMS

- 7904210084 Notice of violation from Insp on 790420-03
* Region 2, Atlanta, Office of the Director 79/03/19 1p
- 7904200207 IE Insp Repts 50-390/79-04 & 50-391/79-07 on 790420-03
Atmosphere noted w/d reinforcement on chemical & val
control has been accepted
GILLILAND, J E Region 2, Atlanta, Office of the
Director 79/03/19 1p
- 7904190227 Act receipt of 790402 & 30 ltr informing MRC of steps
taken to correct violation noted in IE Insp Rept
50-391/79-04
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 79/03/19 2p
- 7904190505 Response to MRC 790309 ltr re violation noted in IE Insp
Rept 50-391/79-04 Corrective actions core barrel assembly
installed
GILLILAND, J E Tennessee Valley Authority 79/04/20 2p
- 7904200174 Act receipt of 790427 ltr informing MRC of steps taken to
correct violations noted in IE Insp Repts 50-390/79-02 &
50-391/79-04
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 79/03/19 2p
- 7904200186 Response to MRC 790404 ltr re violations noted in IE Insp
Repts 50-390/79-02 & 50-391/79-04 Corrective actions noted
requiring approved tagboard signed Painted over connections
determined to be symmetrical in nature
GILLILAND, J E Tennessee Valley Authority 79/04/27 2p
- 7904200193 Forwarded IE Insp Repts 50-390/79-02 & 50-391/79-04 on
790312-15 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 79/04/04 2p
- 7904200194 Notice of violation from Insp on 790312-15
* Region 2, Atlanta, Office of the Director 79/04/04 1p
- 7904200204 IE Insp Repts 50-390/79-02 & 50-391/79-04 on 790312-15
Atmosphere noted insufficient records used to furnish
evidence of activities affecting quality. Several corrections
initiated over instead of ltr 50-390/79-04
GILLILAND, J E Region 2, Atlanta, Office of the Director
Engineering Support Branch 79/04/04 2p
- 7904200205 Response to IE Bulletin 79-02 Investigation shows no piping
in use or planned for use in safety-related area. Effort to
inspect to locate any ASME 300-312 Type 304 piping supplied
by Yonagatah Welding & Engineering Co
GILLILAND, J E Tennessee Valley Authority 79/04/14 1p
- 7904200204 Submits revised response to OA records deficiency noted in
790404 ltr Repts 50-390/79-02 & 50-391/79-04
GILLILAND, J E Tennessee Valley Authority 79/04/01 2p
- 7904200204 First interim deficiency reft incorrect valve weights
used in testing piping analysis. Final response to IE
Bulletin 79-04 will be submitted before April 1st
GILLILAND, J E Tennessee Valley Authority 79/04/22 1p
- 7904200207 Submits response to deviation & deflections cited in IE
Insp Repts 50-390/79-02 & 50-391/79-04
GILLILAND, J E Tennessee Valley Authority 79/04/03 2p
- 5 Reportable unsatisfactory LRNs & related correspondence
- 7904190201 Forwarded final deficiency reft re installation of seismic
pipe hanger anchor
GILLILAND, J E Tennessee Valley Authority 79/03/15 2p
- 7904190207 Final deficiency reft improper installation of seismic
pipe hanger anchor caused by lack of concern by some
installers. Anchor bolts inspected & dist. instructions
provided
* Tennessee Valley Authority 79/03/15 2p
- 7904060277 Submits fifth interim deficiency reft re possible
nonconservative pressure relief & safety line blowdown
analysis. Reft to be submitted by 790718 after Westinghouse
review of nozzle loads
GILLILAND, J E Tennessee Valley Authority 79/05/30 1p
- 7904190404 Forwarded final deficiency reft re potential excessive water
hammer forces in main feedwater pps
GILLILAND, J E Tennessee Valley Authority 79/05/21 1p
- 7904190410 Final deficiency reft Westinghouse informed of
potential excessive water hammer forces in main feedwater
pps. Analysis revealed check valves adequate to perform
under accident conditions
* Tennessee Valley Authority 79/05/21 2p
- 7904190452 Submits second interim reft potential interior structural
steel containment vessel movement envelope. Util. analysis of
ar-bolt condition is not yet complete. Next reft will be
submitted by 790717
GILLILAND, J E Tennessee Valley Authority 79/05/24 1p
- 7904190570 Submits fifth interim deficiency reft re possible
nonconservative pressure relief & safety line blowdown
analysis. Initially reported on 790305. Next reft to be sent
790718 after vendor completes review of nozzle loads
GILLILAND, J E Tennessee Valley Authority 79/05/29 1p
- 7904060207 Revised 790310 final deficiency reft re control loop
bleed failure on loss of power. Revision specifies that
wiring diagram for Siliablas have been corrected & physical
wiring will be corrected
* Tennessee Valley Authority 79/05/31 1p
- 7904190330 Forwarded interim deficiency reft re pipes supporting
essential raw cooling water pipe slab not being driven to
drawing requirements. Investigation under way. Corrective
action to be determined
GILLILAND, J E Tennessee Valley Authority 79/06/04 1p
- 7904190337 First interim deficiency reft pipes supporting essential raw
cooling water pipe slab not driven to design requirement
COR 79-13
* Tennessee Valley Authority 79/06/04 1p
- 7904200423 Submits second interim deficiency reft re power operated
relief valves initially reported 790409. Valve extended
structure to be modified to increase natural frequency of
valve
GILLILAND, J E Tennessee Valley Authority 79/06/13 1p
- 7904200201 Forwarded first interim reft re Deficiency & (seismic
flanges)
GILLILAND, J E Tennessee Valley Authority 79/06/13 1p
- 7904200279 First interim deficiency reft seismic flanges do not meet
spec. Full investigation is being conducted to determine
cause of seismic flange hydro failure & possible
consequences
* Tennessee Valley Authority 79/06/17 2p
- 7904200281 Forwarded final deficiency reft re pipes embedded in
structural concrete as reported on 790312 & discussed in
790208 interim reft
GILLILAND, J E Tennessee Valley Authority 79/06/15 1p
- 7904200207 Final deficiency reft pipes embedded in structural concrete
util failed to comply WACI 318-63 requirements. Material
(civil) design criteria for affected structures evaluated &
revised to assure compliance
* Tennessee Valley Authority 79/06/15 2p
- 7904200218 Forwarded final deficiency reft re auxiliary feedwater pump
essential raw cooling water valves
GILLILAND, J E Tennessee Valley Authority 79/06/20 1p
- 7904200220 Final deficiency reft auxiliary feedwater pump essential
raw cooling water valves which might not open fast enough to
prevent pump damage due to pump running dry. Supply valve
operators to be replaced by faster acting operators
* Tennessee Valley Authority 79/06/20 1p
- 7904200224 Forwarded revised final deficiency reft re motor operated
valve control circuit failures
GILLILAND, J E Tennessee Valley Authority 79/06/20 1p
- 7904200228 Revised final deficiency reft re motor operated valve
control circuit failure. Relay failure could have triggered
events deactivating much of raw train of safety sys. Control
circuit forms to meet Code & solid state relays accepted
* Tennessee Valley Authority 79/06/20 2p
- DOCKET 30-396 CALIFORNIA STATE POLYTECHNIC COLLEGE AMS REACTOR
- 5 Inspection reports, IE Bulletin & correspondence
- 7904200415 Forwarded IE Insp Rept 50-394/79-02 on 790415-13 No
noncompliance noted
GIBSON, J L Region 5, San Francisco, Reactor Operations Nuclear
Support Branch 79/05/04 2p

DOCKETED ITEMS

7904200489 IE Insp Rept 30-394/79-02 an 790412-13 No noncompliance noted Major areas inspected organization & administration, surveillance procedures, reactor operations & , disassembly
JANSEN, S W, FAULKENBERG, R Region 3, San Francisco, Reactor Operations Nuclear Support Branch 79/05/04 1p

7904200467 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" No written response necessary
KUSLEMAN, R H Region 3, San Francisco, Office of the Director 79/05/10 1p

7904200527 Forwards IE Circular 79-02, "Attempted Extension - Low Enriched U"
KUSLEMAN, R H Region 3, San Francisco, Office of the Director 79/05/18 1p

DOCKET 30-395 VIRGIL C SANFORD NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

7904200299 Requests certification that discharges will comply w/applicable sections of Federal Water Pollution Control Act amendments of 1972
BALLARD, R L Environmental Projects Branch 1 79/05/03 1p

7904201214 Notification of 790405 meeting w/Util in Bethesda, MD to discuss induced seismicity at plant site
BAER, R L Light Water Reactors Branch 2 79/05/11 4pp

7904200228 Requests review & consideration of suggested changes in Radiolysis Discharge Elimination Sys monitoring program. NRC comments & recommendations on aquatic biological & water quality monitoring programs sent
BALLARD, R L Environmental Projects Branch 1 79/05/15 4pp

J Insurance & indemnity information

7904200270 Forwards executed Amend 1 to Indemnity Agreement 8-84
NICHOLS, T C South Carolina Electric & Gas Co 79/05/30 2pp

R Utility Plant Safety Analysis Report (PSAR) & append

7904200294 Forwards Amend 14 to PSAR Affidavit of Div encl
CHEN, H H South Carolina Electric & Gas Co 79/05/04 2pp

7904200299 Amend 14 to PSAR
South Carolina Electric & Gas Co 79/05/04 200pp

N Ambient correspondence

7904201028 Util seeks 2-week extension until 790419, for filing of response to scheduling order submitted by NRC as 790328
Certificate of Div encl
CONNER, H B Conner, Moore & Corber 79/04/02 4pp

7904200258 IE Public Div Authority reply to Central Electric Power Cooperative 790310 reply brief re motions to dismiss
letter's amended petition & no latter's 790328 ltr
Certificate of Div encl
NICHOLS, R W, LAMAR, C C Cahill, Darden & Reindel 79/04/19 10pp

7904201124 Forwards page 2 of encl to 790360 ltr from SH Fletcher of SC Electric & Gas to PT Allen of Central Electric Power Cooperative Ltr was appended to Jan 67's response to letter's reply 3/1/79
BAER, R H Conner, Moore & Corber 79/05/08 4pp

G Inspection reports, IE Bulletins & correspondence

7904200388 MetLife Hastinghouse will submit necessary mail for response to IE Bulletin 79-12 & 79-12A, re stipulated voids, before 790508 deadline
CHEN, H H South Carolina Electric & Gas Co 79/04/20 1p

7904200458 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 1p

7904200468 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 1p

7904200478 Response to IE Bulletin 79-03 re ASME EA-312 Type 304 welded pipe. Pipe met in use on planned fan use
CHEN, H H South Carolina Electric & Gas Co 79/05/11 1p

7904200152 Ack receipt of IE Insp Repts 30-395/79-11, 30-395/79-12 & 30-395/79-13 No proprietary info Insp Rept 30-395/79-13 encl
JANSEN, R C South Carolina Electric & Gas Co 79/05/15 1p

7904200162 Forwards IE Insp Rept 30-395/79-10 on 790405-12 No noncompliance noted
HARRIS, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/27 2pp

7904200169 IE Insp Rept 30-395/79-13 on 790405-12 No noncompliance noted Major areas inspected electrical cable installation & rework, electrical components installation & repairs, licensee identified items & inspection followup
BUFF, A B Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/24 4pp

7904200271 Ack receipt of IE Insp Repts 30-395/79-11, 30-395/79-12 & 30-395/79-13 No proprietary info Insp Rept 30-395/79-13 encl
JANSEN, R C South Carolina Electric & Gas Co 79/05/15 1p

7904200274 Forwards IE Insp Rept 30-395/79-11 on 790405-04 No noncompliance noted
HARRIS, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/23 2pp

7904200281 IE Insp Rept 30-395/79-11 on 790405-04 No noncompliance noted Major areas inspected prestressing tendons, electrical penetrations through containment wall & emergency diesel generators
SMITH, J C, BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/23 4pp

7904200284 Ack receipt of IE Insp Repts 30-395/79-11, 30-395/79-12 & 30-395/79-13 No proprietary info Insp Rept 30-395/79-13 encl
JANSEN, R C South Carolina Electric & Gas Co 79/05/15 1p

7904200289 Forwards IE Insp Rept 30-395/79-12 on 790414-19 No noncompliance noted
HARRIS, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/27 2pp

7904200290 IE Insp Rept 30-395/79-12 on 790414-19, No noncompliance noted Major areas inspected (license action on previous insp findings, IE bulletins & inspections, 105F80 SSC) items & correct activities
BURNETT, R E, HENDRICK, A H Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/27 2pp

7904200284 Ack receipt of 790320 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-395/79-10
HARRIS, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/31 1p

7904200280 Response to NRC 790301 ltr re violations noted in IE Insp Rept 30-395/79-10 Corrective actions clarification of work guidelines for piping welding
JANSEN, R C South Carolina Electric & Gas Co 79/05/28 2pp

G Reportable occurrences, LERs & related correspondence

7904200300 Provides info re noted loadings for upset conditions on pipe supports & incorrect terminations on 7 ft. meters.
JANSEN, R C South Carolina Electric & Gas Co 79/04/18 2pp

DOCKET 30-394 UNIV OF VIRGINIA CAVALIER REACTOR

G Inspection reports, IE Bulletins & correspondence

7904200424 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 1p

DOCKET 30-397 HPPBS NUCLEAR PROJECT, UNIT 2

A Application/construction stage documents & correspondence

7904200271 Forwards Analysis Branch first round questions re DL application Requests response by 790725.
VARMA, D A Light Water Reactors Branch 4 79/05/17 3pp

DOCKETED ITEMS

P Security, nuclear, emergency & fire protection plans

7904120336 Forwards responses to NRC 790203 questionnaire re physical security plan responses with/without staff 100982 7905
HENDERSON, D L Washington Public Power Supply System 79/06/11 2pp

P Operating license stage documents & correspondence

7904100491 Requests 790710 meeting w/NRC to discuss geology-related matters
HENDERSON, D L Washington Public Power Supply System 79/06/13 1p

7904100492 Notice of violation from Insp on 790201-02 & 14-15
Region 3, San Francisco, Reactor Construction & Engineering Support Branch 79/06/21 2pp

--7904100279 IE Insp Repts 30-397/79-03, 30-460/79-04 & 30-513/79-04 on 790201-02 & 14-15 Noncompliance noted failure to respond effectively to audit finding & failure to implement effective inspec program
BISHOP, T W Region 3, San Francisco, Reactor Construction & Engineering Support Branch 79/06/21 7pp

7904100085 Responses to NRC 790321 ltr re violations noted in IE Insp Repts 30-397/79-03, 30-460/79-04 & 30-513/79-04 Corrective actions audit conducted Feb 1977 Deficient Inspect 80-405 will be removed & replaced properly
HENDERSON, D L Washington Public Power Supply System 79/04/20 2pp

--7904100090 Ask release of 790420 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-397/79-03, 30-460/79-04 & 30-513/79-04
HENDERSON, D L Region 3, San Francisco, Reactor Construction & Engineering Support Branch 79/05/03 1p

--7904100038 Forwards IE Insp Repts 30-397/79-03, 30-460/79-04 & 30-513/79-04 on 790201-02 & 14-15 notice of violation
SPENCER, D D Region 3, San Francisco, Reactor Construction & Engineering Support Branch 79/05/21 2pp

--7904100043 Notice of violation from Insp on 790201-02 & 14-15
Region 3, San Francisco, Reactor Construction & Engineering Support Branch 79/05/21 2pp

--7904100279 IE Insp Repts 30-397/79-03, 30-460/79-04 & 30-513/79-04 on 790201-02 & 14-15 Noncompliance noted failure to respond effectively to audit finding & failure to implement effective inspec program
BISHOP, T W - BINGHAMTON, D C - HANDEL, R C Region 3, San Francisco, Reactor Construction & Engineering Support Branch 79/06/21 7pp

7904100135 Forwards IE Circular 79-03, "Unscheduled Speed Increase of Reactor Heat Generator Set Resulted in Reactor Power Excesses" & No written response required
HENDERSON, D L Region 3, San Francisco, Office of the Director 79/05/02 1p

7904100337 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Inspection Request Problem" & No action required
HENDERSON, D L Region 3, San Francisco, Office of the Director 79/05/07 1p

7904100488 Forwards IE Info Notice 79-13, "Assessed Damage to New Fuel Assemblies" & No written response necessary
HENDERSON, D L Region 3, San Francisco, Office of the Director, IN 1p

B Reportable occurrences, URRs & related correspondence

7904100232 Forwards 7902-79-6746
HENDERSON, D L Region 3, San Francisco, Office of the Director 79/05/14 1p

7904100230 Forwards 7902-79-6740
HENDERSON, D L Region 3, San Francisco, Office of the Director 79/05/21 1p

7904100231 Forwards 7902-79-6747
HENDERSON, D L Region 3, San Francisco, Office of the Director 79/05/22 1p

7904100371 Forwards 7902-79-6740
HENDERSON, D L Region 3, San Francisco, Office of the Director 79/05/23 1p

7904000231 Forwards deficiency report re possible failure of portion of pipe whip restraint structure in main steam tunnel
HENDERSON, D L Washington Public Power Supply System 79/05/31 1p

--7904000303 Deficiency report defective steel plate used in supporting structure for pipe whip restraint in main steam tunnel
Cracking attributed to overhauling BM-327 Class 31 steel
Defective A-307 steel rejected
Washington Public Power Supply System 79/05/31 1p

7904000232 Forwards deficiency report on 780413 re defective welder connections on electrical penetrations 3100-A, B, C & D
HENDERSON, D L Washington Public Power Supply System 79/05/31 1p

--7904000231 Deficiency report on 780413 defective welder connections on electrical penetrations 3100-A, B, C & D Reported on 790504
Repair & QC procedures provided by Washington
Washington Public Power Supply System 79/05/31 1p

900807 30-440 SHEWAN HARRIS NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

7904100263 Commence w/corrective action re backfill against Category I structures & cone casing Per dams & dike Agreements to remove water/voids if it occurs field moisture control procedures
JACKSON, R R Des Moines Branch 79/05/08 2pp

7904000207 Inform that seismic Category I fill placement criteria & test criteria was found acceptable Request IE determine whether acceptable plans to replace with w/fill which meets specs if not add info is needed
WHEELER, D S Division of Project Management 79/05/09 2pp

7904000413 Confirm occurrence w/schedule for resumption of fill placement in dams & dikes in cone void areas which presently contain no fill
O'NEILL, J P Region 3, Atlanta, Office of the Director 79/05/10 1p

7904100381 Approve revised placement & test criteria in IN Design 790324 ltr re BM Backfill Forwards request for info re design criteria for fill & backfill supporting dams & conduits
HARRIS, D S Light Water Reactors Branch 3 79/05/17 4pp

7904100420 Forwards geologic report on fault P3 shift layer at Station 14152 at main dam feature is not fault or capable fault as defined per 10CFR100. App A Overlaid diagram and REDRAFTED-A Carolina Power & Light Co. 79/06/08 31pp

DOCKETED ITEMS

7904010592 Summary of NRC guidelines for preparation of environ rept- as discussed at 790308 meeting
MCDFPFE.N A Carolina Power & Light Co 79/05/29 2pp

D Adjudicatory correspondence

7904010547 Motion for extension until 790411 to prepare response to ALAB-509
GC1MTC.A J F Hearings Division 79/04/02 2pp

7904010506 Response to 790302 request for info re status of rulemaking proceeding to develop value for radon in Table B-3 Rept 3 proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases
CH010708MY.E Hearings Division 79/03/26 24pp

7904010577 Submits corrections to transcript of 790307-0308 proceedings Certificate of Biv. encl
BARTM.C.A Branch 3 79/04/16 7pp

7904010508 Denies motion by intervenors Conservation Council of NC & Make Environ. Inc to remand & reopen hearings re necessity of Facility Future actions re OPA must be consistent w/10CFR20.20A
CH01A.R.J Office of the Secretary of the Commission 79/05/02 2pp

7904010542 Grants 10-day extension of time for NRC to file proposed findings of fact & conclusions of law
BRTM.T.M Atomic Safety and Licensing Board Panel 79/05/08 1p

7904010593 NRC motion for summary disposition re radon issue was in error/ALAB-540 cancelled only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Biv. encl
GCFLD.N.E Atomic Safety and Licensing Appeal Panel 79/05/28 2pp

7904010543 Request evidentiary hearing due to changes in wgt which are materially relevant to remanded issue Directs still to submit affidavit detailing changes
BRTM.T.M Branch 1 79/03/29 2pp

E Inspection reports, IF Bulletin & correspondence

7904010540 Forwards IR Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
D'NEILL.J.P Region 2: Atlanta, Office of the Director 79/05/10 1p

7904010507 Response to IF Bulletin 79-09 re ASME SA-312 Type 304 pipe wsg by Youngstown Welding & Engineering Co Pipe not in use or planned for use
MCDFPFE.N A Carolina Power & Light Co 79/05/17 1p

F Reportable occurrences, LERs & related correspondence

7904010570 RO as 790404 welds in 12 containment liner sleeves were not stress relieved caused by undershielding of solvent of code equipment Quite returned to vendor for stress relieving
CH0206C.N.H Chemstar Corp., Tube Turns Div 79/05/07 2pp

T Hearing transcripts on non-emergency matters

7904010547 Transcript of 790302 hearing in Raleigh, NC Pp 2,297-2,979
Panel 3 Evidentiary encl
BRTM.T.M - LMSD.J.V - BR10HT.O.O Atomic Safety and Licensing Board Panel 79/03/02 200pp

7904010509 Transcript of 790304 hearing in Raleigh, NC Pp 2,980-2,989
Panel 3 Evidentiary encl
BRTM.T.M - LMSD.J.V - BR10HT.O.O Atomic Safety and Licensing Board Panel 79/03/06 240pp

7904010516 Transcript of 790307 hearing in Raleigh, NC Pp 3,224-3,306.
In use Note Bulletin & Bulletin encl
BRTM.T.M - LMSD.J.V - BR10HT.O.O Atomic Safety and Licensing Board Panel 79/03/07 400pp

A Application/construction stage documents & correspondence

7904010585 Considers w/informative action re backfill against Category 1 structures & core cased for dams & fills agree to remove earthwork IF IR accepts field moisture control procedures
JCH0206.R.E. Geotechnical Branch 79/05/08 2pp

7904010585 Informs that Category 1 fill placement criteria & test criteria was found acceptable Requests IR determine whether applicant plans to replace mat w/fill which meets specs IF not, add info is needed
VAB0406.D.B Division of Project Management 79/05/09 2pp

7904010515 Confirms concurrence w/schedule for resumption of fill placement in dam & fills in cat 1 sites areas which presently contain no fill
D'NEILL.J.P Region 2: Atlanta, Office of the Director 79/05/10 1p

7904010576 Approves revised placement & test criteria in HR Dams
790504 1st to RA MCDFPFE.N Forwards request for info re design criteria for fill & backfill supporting pipes & conduits
BARTM.C.A Light Water Reactors Branch 3 79/05/17 2pp

7904010540 Forwards geologic rept on fault F3 shift layer at Station 11+50 at main dam Features is not fault or capable fault- as defined per 10CFR60. App A Overlaid diagrams encl
MCDFPFE.N A Carolina Power & Light Co 79/04/04 11pp

7904010539 Notifies that portions of main & auxiliary dewater trenches are ready for inst per App A to 10CFR60
MCDFPFE.N A Carolina Power & Light Co 79/05/11 2pp

7904010585 Response to 790517 request for info re 20-inch svc water lines & adjacent electrical conduit between emergency svc water, rolling tower makeup intake structure & Tank Bldg 1
Info re seismic Category 1 piping to be submitted
MCDFPFE.N A Carolina Power & Light Co 79/06/12 135pp

7904010549 Confirms exposure of site fault in west auxiliary dam foundation Rehearses mapping documentation during routine mapping sequence
MCDFPFE.N A Carolina Power & Light Co 79/06/18 1p

C Utility/Environmental Report (ER), amendments & correspondence

7904010592 Summary of NRC guidelines for preparation of environ rept- as discussed at 790308 meeting
MCDFPFE.N A Carolina Power & Light Co 79/05/29 2pp

D Adjudicatory correspondence

7904010547 Motion for extension until 790411 to prepare response to ALAB-509
GC1MTC.A J F Hearings Division 79/04/02 2pp

7904010506 Response to 790302 request for info re status of rulemaking proceeding to develop value for radon in Table B-3 Rept 3 proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases
CH010708MY.E Hearings Division 79/03/26 24pp

7904010577 Submits corrections to transcript of 790307-0308 proceedings Certificate of Biv. encl
BARTM.C.A Branch 3 79/04/16 7pp

7904010508 Denies motion by intervenors Conservation Council of NC & Make Environ. Inc to remand & reopen hearings re necessity of Facility Future actions re OPA must be consistent w/10CFR20.20A
CH01A.R.J Office of the Secretary of the Commission 79/05/02 2pp

7904010542 Grants 10-day extension of time for NRC to file proposed findings of fact & conclusions of law
BRTM.T.M Atomic Safety and Licensing Board Panel 79/05/08 1p

7904010593 NRC motion for summary disposition re radon issue was in error/ALAB-540 cancelled only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Biv. encl
GCFLD.N.E Atomic Safety and Licensing Appeal Panel 79/05/28 2pp

7904010543 Request evidentiary hearing due to changes in wgt which are materially relevant to remanded issue Directs still to submit affidavit detailing changes
BRTM.T.M Branch 1 79/03/29 2pp

E Inspection reports, IF Bulletin & correspondence

7904010540 Forwards IR Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
D'NEILL.J.P Region 2: Atlanta, Office of the Director 79/05/10 1p

790529707 Response to IE Bulletin 79-03 re ASME SA-512 Type 304 pipe w/ By Yonpiston Welding & Engineering Co Pipe not in use or planned for use
MCDFP/IE, H A Carolina Power & Light Co 79/03/17 1p

B. Reportable occurrences, LERs & related correspondence

790529690 RD on 790604 welds in 15 containment liner sleeves were not stress relieved. Caused by misunderstanding of intent of code requirement Units returned to vendor for stress relieving
GDS&E, H H Chemtreat Corp - Tube Turns Div 79/06/07 2pp

T. Hearing transcripts on non-testimony matters

790534006 Transcripts of 790502 hearing in Raleigh, NC Pg 2, 3897-2, 439
Panel 3 testimony encl
SMITH, T W, LEEDS, J V, BRIDGM, S O Atomic Safety and Licensing Board Panel 79/03/05 200pp

790534009 Transcripts of 790504 hearing in Raleigh, NC Pg 2, 3907-2, 3203
SMITH, T W, LEEDS, J V, BRIDGM, S O Atomic Safety and Licensing Board Panel 79/03/05 242pp

790534016 Transcripts of 790507 hearing in Raleigh, NC Pg 2, 3904-2, 3064
In two vols Exhibits & testimony encl
SMITH, T W, LEEDS, J V, BRIDGM, S O Atomic Safety and Licensing Board Panel 79/03/07 400pp

DOCKET 30-400 SHARON HARRIS NUCLEAR POWER PLANT, UNIT 3

A. Application/construction stage documents & correspondence

790540988 Concern w/corrective action re backfill against Category 1 structures & core containment dams & date agrees to resume backfilling if IE accepts field moisture control procedures
JWC&S, H E Desenciones Branch 79/03/08 2pp

790540990 Informal talk re Category 1 fill placement criteria & test criteria with found acceptable Requests IE determine whether applicant plans to replace matl w/fill which meets specs if not used info re needed
VMS&L, S B Division of Project Management 79/05/09 2pp

7905200615 Confirms concurrence w/schedule for resumption of fill placement in dam & dikes in containment areas which presently contain no fill
O'HEILL, J P Region 2, Atlanta, Office of the Director 79/05/10 1p

790540990 Accepts revised placement & test criteria on HF Densit
790504 lit to RA McDFP/IE Forwarding request for info re design criteria for fill & backfill supporting pipes & cables
PARR, S B Light Water Reactors Branch 3 79/03/17 4pp

790534028 Forwarding geologic map on fault F3 shift layer at Station 11452 at main dam. Problem is not fault or possible fault.
As defined per SCDFP/IE, App A Overlaid diagram encl
MCDFP/IE, H A Carolina Power & Light Co 79/04/06 11pp

790534031 Notifies that portions of main & auxiliary damne trenches are ready for inspection per App A to SCDFP/IE
MCDFP/IE, H A Carolina Power & Light Co 79/03/11 2pp

790540938 Responds to 790517 request for info re 30-inch cut water lines & adjacent electrical conduit between emergency vuc water-holding lower main-dam intake structure & Tube 304
Info re seismic Category 1 piping to be submitted
MCDFP/IE, H A Carolina Power & Light Co 79/06/12 12pp

790534039 Confirms exposure of site fault in west auxiliary dam foundation. Schedules mapping documentation during routine mapping sequence
MCDFP/IE, H A Carolina Power & Light Co 79/04/10 1p

E. Utility Environmental Report (ER), amendments & correspondence

790540942 Completes NRC guidelines for preparation of environ report as discussed w/ 790508 meeting
MCDFP/IE, H A Carolina Power & Light Co 79/05/09 2pp

G. Administrative correspondence

790534047 Motion for extension until 790415 to prepare response to 444-309
SC/REG, J P Hearings Division 79/04/02 2pp

790529060 Responds to 790502 request for info re status of rulemaking proceeding to develop value for reason in Table G-2 Regt & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon release
GDS&E, H H Hearings Division 79/03/06 34pp

790529077 Exhibits corrections to transcript of 790507-0308 proceedings Certificate of Rec encl
SMITH, T W Branch 3 79/04/16 7pp

790530035 Motion motion by intervenors Conservation Council of NC, & N. A. Conservation to remove & reopen hearings re necessity of facility future motion re OPE must be consistent w/SCDFP 204
GILL, E J Office of the Secretary of the Commission 79/03/02 3pp

790530142 Grants 10-day extension of time for NRC to file proposed findings of fact & conclusions of law
SMITH, T W Atomic Safety and Licensing Board Panel 79/03/08 1p

790530039 NRC motion for summary disposition re radon issue was to be removed from consolidated only 3 of 15 cases Denies NRC motion as to parties in other proceedings Certificate of Rec encl
GILL, E J Atomic Safety and Licensing Appeal Panel 79/05/25 3pp

7905200473 Responds evidentiary hearing due to changes in ngt which are substantially relevant to requested issue Directs until its subject affidavit detailing changes
SMITH, T W Branch 1 79/03/25 2pp

G. Inspection reports, IE Bulletins & correspondence

790520040 Forwards IE Info Notice 79-12, "Assumed Damage to New Fuel Assemblies"
O'HEILL, J P Region 2, Atlanta, Office of the Director 79/05/10 1p

790529077 Response to IE Bulletin 79-03 re ASME SA-512 Type 304 pipe w/ By Yonpiston Welding & Engineering Co Pipe not in use or planned for use
MCDFP/IE, H A Carolina Power & Light Co 79/03/17 1p

G. Reportable occurrences, LERs & related correspondence

790530090 RD on 790604 welds in 15 containment liner sleeves were not stress relieved. Caused by misunderstanding of intent of code requirement Units returned to vendor for stress relieving
GDS&E, H H Chemtreat Corp - Tube Turns Div 79/06/07 2pp

T. Hearing transcripts on non-testimony matters

790534006 Transcripts of 790502 hearing in Raleigh, NC Pg 2, 3897-2, 439
Panel 3 testimony encl
SMITH, T W, LEEDS, J V, BRIDGM, S O Atomic Safety and Licensing Board Panel 79/03/05 200pp

790534009 Transcripts of 790504 hearing in Raleigh, NC Pg 2, 3907-2, 3203
SMITH, T W, LEEDS, J V, BRIDGM, S O Atomic Safety and Licensing Board Panel 79/03/05 242pp

790534016 Transcripts of 790507 hearing in Raleigh, NC Pg 2, 3904-2, 3064
In two vols Exhibits & testimony encl
SMITH, T W, LEEDS, J V, BRIDGM, S O Atomic Safety and Licensing Board Panel 79/03/07 400pp

DOCKET 30-400 SHARON HARRIS NUCLEAR POWER PLANT, UNIT 4

A. Application/construction stage documents & correspondence

790540988 Concern w/corrective action re backfill against Category 1 structures & core containment dams & date agrees to resume backfilling if IE accepts field moisture control procedures
JWC&S, H E Desenciones Branch 79/03/08 2pp

790540990 Informal talk re seismic Category 1 fill placement criteria & test criteria with found acceptable Requests IE determine whether applicant plans to replace matl w/fill which meets specs if not used info re needed
VMS&L, S B Division of Project Management 79/05/09 2pp

7905200615 Confirms concurrence w/schedule for resumption of fill placement in dam & dikes in containment areas which presently contain no fill
O'HEILL, J P Region 2, Atlanta, Office of the Director 79/05/10 1p

DOCKETED ITEMS

7906100701 Accepts revised placement & test criteria in MC Denham
790604 1st to MA McCaffrey Forwards request for info re
design criteria for Full & backfill supporting pipes &
consults
PARM, G D Light Water Reactors Branch 3 79/05/17 App

7906100428 Forwards geologic map on fault F2 shift layer at Station
11-50 at Main San Feature re not fault or capable fault
as defined per 10CFR100.4pp & Operated diagrams encl
KEDUFFIE, M A Carolina Power & Light Co 79/06/06 11pp

7906100519 Notifies that portions of main & auxiliary damper
brackets are ready for shop per App A to 10CFR100
KEDUFFIE, M A Carolina Power & Light Co 79/06/11 2pp

7906100585 Responds to 790617 request for info re 30-inch wet water
lines & adjacent electrical cabinet between emergency AWC
water-cooling tower makeup intake structures & Tank 8140 1
Info re electric Category I piping to be substituted
KEDUFFIE, M A Carolina Power & Light Co 79/06/12 13pp

7906100549 Confirms approval of site fault in west auxiliary dam-
per Foundation Schedules mapping documentation during routine
mapping sequence
KEDUFFIE, M A Carolina Power & Light Co 79/06/15 1p

C Utility Environmental Report (ER), amendments & correspondence

7906101192 Summaries NRC guidelines for preparation of environ report
as discussed at 790506 meeting
KEDUFFIE, M A Carolina Power & Light Co 79/05/29 App

Q Adjudicatory correspondence

7906101047 Motion for extension until 790411 to prepare response to
ALAB-309
SEINTO, J F Hearings Division 79/06/02 App

--7906101060 Responds to 790528 request for info re status of rulemaking
proceeding to develop value for radon in Table 5-3 Rept &
proposed rule will be sent to NRC by 790405 Rule does not
address health effects of radon radon
CHINISSEMY, E Hearings Division 79/03/26 3pp

7906070177 Submits corrections to transcript of 790327-0308
proceedings Certificate of Doc encl
BARTH, C A Branch 3 79/04/16 7pp

7906070295 Denies motion by intervenor Conservation Council of NC &
Maine Environ Inc to demand 2 program hearings re necessity of
facility future radon release re consent permits must be consistent
w/10CFR2 206
CHILDS, J J Office of the Secretary of the Commission 79/05/02
3pp

7906050142 Grants 10-day extension of time for NRC to file proposed
findings of fact & conclusions of law
KREITH, L A Atomic Safety and Licensing Board Panel 79/05/08 1p

7906050095 NRC motion for summary disposition re radon issue was in
error/MA3-540 consolidated only 5 of 16 cause Denies NRC
motion as to parties in other proceedings Certificate of Doc encl
DUPLO, H E Atomic Safety and Licensing Board Panel 79/05/03
3pp

7906020470 Requests evidentiary hearing due to changes in subj which are
materially relevant to remedial issue. Objects still to submit
affidavit detailing changes
BRITH, L W Branch 1 79/05/05 App

B Inspection reports, IE Bulletins & correspondence

7906050440 Forwards IE info Notice 79-12 "Attempted Damage to New Fuel
Assemblies"
D'NEILLY, J P Region 2, Atlanta, Office of the Director
79/05/10 1p

7906060707 Responds to IE Bulletin 79-03 re ANM 64-312 Type 204 pipe
only by Youngtown Welding & Engineering Co Pipe met in use
or planned for use
KEDUFFIE, M A Carolina Power & Light Co 79/05/17 1p

B Reportable occurrences, LERs & related correspondence

7906100280 SO on 790604 advises in 15 containment liner sleeves were not
properly relieved. Cited by misunderstanding of intent code
reporting Units returned by vendor for sleeves relieving
GEORGIAN, H H Chemetron Corp, Tube Turns Div 79/06/07 App

DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

7906060520 Forwards evaluation & request for addl info re "New Water
Reservoir & Spray Box Performance Testing & Evaluation"
Requests response by 790518
PARM, G D Light Water Reactors Branch 3 79/05/03 App

7906050080 Details positions re Reg Guide 1.11 Revision G & Reg Guide
1.120 Revision I Will comply w/Reg Guide 1.11 w/exception of
containment pressure instrument lines Reg Guide 1.120 not
applicable
BRUNN, E C Virginia Electric & Power Co 79/05/30 App

7906050336 Advises that Units 3 & 4 should also be included on 790518
1p
BRUNN, E C Virginia Electric & Power Co 79/05/30 1p

7906050323 Discusses 790110 rept "QA Program Operations Phase"
Requests exception from ANM NRS 2 & 4 NRS 2.8 paragraphs re
valve control & equipment test Discusses proposed
alternative
BAUM, E A Virginia Electric & Power Co 79/05/31 App

G Adjudicatory correspondence

7906100785 PR notice of negative declaration supporting 790514 order
extending completion of final sales No environ impact
attributable to order other than statement considered in
NABLP 790518 initial decision
KEDUFFIE, M Environmental Projects Branch 2 79/06/18 App

J Insurance & indemnity information

7906100324 Endorsement 41 on NGLIA Policy HP-57
SERAF, T Mutual Atomic Energy Liability Underwriters 79/05/10 1p

7906100331 Endorsement 42 on NGLIA Policy HP-57
SERAF, T Mutual Atomic Energy Liability Underwriters 79/05/10 1p

G Inspection reports, IE Bulletins & correspondence

7906040354 Forwards IE Insp Repts 50-329/79-25-35-404/79-01 &
50-405/79-21 on 790410-12 No noncompliance noted
RUMPHR, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 79/04/28 App

--7906040327 IE Insp 50-329/79-25-50-404/79-01 & 50-405/79-01 on
790410-12 No noncompliance noted Major areas inspected
10CFR50 301c items, classifying of foundations & piling Part
21 notices
MCFAIRLAND, C E, REBOT, A B Region 2, Atlanta, Reactor
Construction & Engineering Support Branch 79/04/25 App

7906100487 Advises of response to IE Bulletin 79-03 re Youngtown weld
defects by 790511
BRUNN, E C Virginia Electric & Power Co 79/05/10 1p

DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4

A Application/construction stage documents & correspondence

7906060520 Forwards evaluation & request for addl info re "New Water
Reservoir & Spray Box Performance Testing & Evaluation"
Requests response by 790518
PARM, G D Light Water Reactors Branch 3 79/05/03 App

7906050080 Details positions re Reg Guide 1.11 Revision G & Reg Guide
1.120 Revision I Will comply w/Reg Guide 1.11 w/exception of
containment pressure instrument lines Reg Guide 1.120 not
applicable
BRUNN, E C Virginia Electric & Power Co 79/05/30 App

7906050336 Advises Units 3 & 4 should also be included on 790518 1p
BRUNN, E C Virginia Electric & Power Co 79/05/30 1p

7906050323 Discusses 790110 rept "QA Program Operations Phase"
Requests exception from ANM NRS 2 & 4 NRS 2.8 paragraphs re
valve control & equipment test Discusses proposed
alternative
BAUM, E A Virginia Electric & Power Co 79/05/31 App

D Adjudication correspondence

790400705 FR notice of negative declaration supporting 790401 order extending collection of consent data to ensure impact attributable to order rather than statement considered in 190477018 initial decision
 REISMAN, D L Operating Reactors Branch 2 79/04/18 1p

J Insurance & indemnity information

790412024 Endorsement 41 to NDLIA Policy 79-87
 GERSH, T Mutual Atomic Energy Liability Underwriters 79/05/10 1p

790412531 Endorsement 42 to NDLIA Policy 79-87
 GERSH, T Mutual Atomic Energy Liability Underwriters 79/05/10 1p

Q Inspection reports, IE Bulletin & correspondence

790402524 Forwards IE Insp Rept 30-337/79-23, 30-404/79-01 & 30-405/79-01 as noncompliance noted Major areas inspected
 KOPPEL, J E Region 2, Atlanta, Office of the Director
 Support Branch 79/04/25 3pp

790402527 IE Insp Rept 30-337/79-23, 30-404/79-01 & 30-405/79-01 as noncompliance noted Major areas inspected
 KOPPEL, J E Region 2, Atlanta, Office of the Director
 Construction & Engineering Support Branch 79/04/25 3pp

790414087 Address of response to IE Bulletin 79-03 re Washington unit defects by 790411
 BIGGS, C Virginia Electric & Power Co 79/05/10 1p

DOCKET 30-404 TUGBORE INST RESEARCH REACTOR

Q Inspection reports, IE Bulletin & correspondence

790403025 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
 TITCHELL, J P Region 2, Atlanta, Office of the Director
 79/05/10 1p

DOCKET 30-407 UNIV OF UTAH RESEARCH REACTOR

Q Inspection reports, IE Bulletin & correspondence

790405018 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
 GORVINE, V Region 4, Dallas, Office of the Director 79/05/11 1p

DOCKET 30-409 LA CROSSE BOILING WATER REACTOR

F Security, medical, emergency & fire protection plans

790406020 "Fire Protection in Operating Nuclear Stations, LaCrosse Boiling Water RWR Review"
 MALL, R E & MACDONALD, R C Oneida National Laboratories
 79/04/30 3pp

790410008 Forwards Amend 13 to License 89H-45 & notice of issuance & notice of issuance by plan evaluation rept withheld
 REISMAN, D L Operating Reactors Branch 2 (Pfr 7904025) 79/05/16 2p

P Operating license steps documents & correspondence

790406025 Forwards request for add info re LACROSSE Unit 6 in order to continue review of 790426 request for Tech Spec change
 REISMAN, D L Operating Reactors Branch 2 (Pfr 7904025) 79/04/24 1p

790405021 Forwards draft evaluation of systematic evaluation program Topic V-12 A, "Water Purification of Reactant" Request Review & response within 30 days
 REISMAN, D L Operating Reactors Branch 2 (Pfr 7904025) 79/04/30 1pp

790410012 Summary of 790426 meeting w/ add info re River Spring-10 re results of unit Cycle 3 fuel examinations performed during current refueling outage Supporting documentation incl
 REISMAN, D L Operating Reactors Branch 2 (Pfr 7904025) 79/04/30 1pp

790410017 Forwards W Harrison comments & results of NRC review of Reactor & Reactor Regs: Review of License/Operation Permit(s): La Crosse BWR (LACROSSE) Near Sens. Vessel Counting, etc. Planned program for further work is acceptable
 REISMAN, D L Operating Reactors Branch 2 (Pfr 7904025) 79/04/30 3pp

790410017 Forwards add info re availability of boron carbide poison melt prepared for high density fuel storage racks
 LINDBER, P Delmarva Power Cooperative 79/05/17 1pp

790402023 Request two controlled copies of site emergency plan & implementing procedures, site maps showing location & grid or station numbers of various monitoring stations onsite & offsite & site maps used for offsite dose determination
 KOPPEL, J E Region 2, Chicago, Office of the Director 79/05/17 1p

790407034 Forwards Amend 13 to License 89H-45, safety evaluation & notice of issuance & availability
 REISMAN, D L Operating Reactors Branch 2 (Pfr 7904025) 79/05/25 1pp

790407037 Amend 13 to License 89H-45 adding core power distribution limits for Aft-Channels Type 1 fuel assemblies & changing limits for off-gas emission rates to address for cleanup of steam activity
 REISMAN, D L Operating Reactors Branch 2 (Pfr 7904025) 79/05/25 1pp

790409043 Safety evaluation supporting Amend 13 to License 89H-45
 Operating Reactors Branch 2 (Pfr 7904025) 79/05/25 11pp

790409043 Notice of issuance & availability of Amend 13 to License 89H-45
 REISMAN, D L Operating Reactors Branch 2 (Pfr 7904025) 79/05/25 3pp

790410017 Forwards add info for systematic evaluation program in response to NRC 790408 request re WPCD discharge line. Info includes audit analysis piping q's for reactor plants, computer printouts & several oversized diagrams
 LINDBER, P Delmarva Power Cooperative 79/05/11 3pp

790402030 Forwards requested info re gaseous effluent monitoring capabilities
 REISMAN, D L Delmarva Power Cooperative 79/04/12 3pp

790404021 Forwards review incl to add 790517 for add info re availability of boron carbide poison melt prepared for reactor high density fuel storage racks
 LINDBER, P Delmarva Power Cooperative 79/05/21 3pp

Q Inspection reports, IE Bulletin & correspondence

790402019 Response to IE Bulletin 79-03 re Type 304 stainless steel piping mfg by Youngstown Welding & Engineering Co is in use or planned for use in safety-related sys at facility.
 LINDBER, P Delmarva Power Cooperative 79/04/20 2pp

790501028 Forwards IE Insp Rept 30-409/79-08 on 790408-11 re noncompliance noted
 REISMAN, D L Region 2, Chicago, Reactor Operations Nuclear Reports Branch, 79/04/25 3pp

790502038 IE Insp Rept 30-409/79-08 on 790408-11 re noncompliance noted Major areas inspected preparation for refueling outage, refueling & fuel handling activities & maint during refueling outage
 LITTLE, W E & REISMAN, D L Region 2, Chicago, Office of the Director 79/04/25 3pp

DOCKETED ITEMS

- 7704260309 Forwards IE Insp Rept 30-409/77-06 on 770328-29 No noncompliance noted
KEMPFLER, J. P. Region 3, Chicago, Reactor Operations Nuclear Support Branch 77/04/29 2pp
- 7704260310 IE Insp Rept 30-409/77-06 on 770328-29 No noncompliance noted Major areas inspected handling, packaging & shipping of spent fuel assemblies & operations during refueling
WAMHOUT, R. F. 810066V-N 1 Region 3, Chicago, Office of the Director 77/04/30 App
- 7704260387 Forwards IE Insp Rept 30-409/77-07 on 770407-11 No noncompliance noted
FISCHL, J. B. Region 3, Chicago, Reactor Construction & Engineering Support Branch 77/04/30 2pp
- 7704260388 IE Insp Rept 30-409/77-07 on 770409-11 No noncompliance noted Major areas inspected QA/QC program, peripheral thread replacement & implementing procedures
WAGS, R. D. 810090SE-N H. DANIEL, DONALD H Region 3, Chicago, Office of the Director 77/04/27 7pp
- 7704130014 Forwards IE Info Notice 77-11, "Lower Reactor Vessel Head Inspection Support Problem" No action required
KEMPFLER, J. D. Region 3, Chicago, Office of the Director 77/05/07 1p
- 7704030316 Act receipt of 770409 1tr Informing NRC of steps taken to correct violation noted in IE Insp Rept 30-409/77-03
KEMPFLER, J. P. Region 3, Chicago, Reactor Operations Nuclear Support Branch 77/03/08 1p
- 7704030318 Responds to NRC 770315 1tr re violation noted in IE Insp Rept 30-409/77-03 Corrective actions completed personnel advised to review procedures for procurement actions
LINDSEY, F. D. Baitland Power Cooperative 77/04/07 2pp
- 770410298 Forwards IE Bulletin 77-10, "Regulification Training Program Statistics" Written responses required
KEMPFLER, J. D. Region 3, Chicago, Office of the Director 77/05/11 1p
- 7704140148 Responds to IE Bulletin 77-09 re GE Type AA-S circuit breakers Circuit breakers not in use or planned for use
LINDSEY, F. D. Baitland Power Cooperative 77/05/11 1p
- 7704100490 Forwards IE Info Notice 77-12, "Attempted Damage to New Fuel Assemblies"
KEMPFLER, J. P. Region 3, Chicago, Office of the Director 77/05/11 1p
- 7704090201 Forwards IE Circular 77-06, "Attempted Substitution - Low Enriched U"
KEMPFLER, J. P. Region 3, Chicago, Office of the Director 77/05/18 1p
- 7704020066 Act receipt of 770507 1tr Informing NRC of steps taken to correct violations noted in IE Insp Rept 30-409/77-03
HEND, J. A. Region 3, Chicago, Safeguards Branch 77/05/18 1p
- 7704020073 Responds to NRC 770413 1tr re violations noted in IE Insp Rept 30-409/77-03 Corrective actions withheld
LINDSEY, F. D. Baitland Power Cooperative 77/05/07 1p
- 7704100077 Forwards IE Bulletin 77-11, "Safety Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Action required
KEMPFLER, J. D. Region 3, Chicago, Office of the Director 77/05/22 1p
- 7704020016 Forwards IE Info Notice 77-13, "Indication of Low Water Level in Dyster Creek Reactor"
KEMPFLER, J. D. Region 3, Chicago, Office of the Director 77/05/29 1p
- H Periodic operating reports & related correspondence
- 7704120447 Forwards monthly operating rept for May 1977
LINDSEY, F. D. Baitland Power Cooperative 77/06/07 1p
- 7704120487 Monthly operating rept for May 1977
PAPPERT, L. S. Baitland Power Cooperative, 77/06/06 24pp
- H Periodic occurrences, LEDs & related correspondence
- 7704140486 Forwards LER 77-008/03L-0 Drawing of containment ventilation exhaust damper leakage test and
LINDSEY, F. D. Baitland Power Cooperative 77/03/22 App
- 7704040345 Forwards LER 77-008/03L-0 on 770429 During periodic Type C leakage rate testing containment isolation did not meet Test Spec criteria Caused by danger stick shaft packing Replaced
WAMHOUT, R. F. 810066V-N 1 Region 3, Chicago, Office of the Director 77/05/28 1p
- 7704120353 Forwards LER 77-009/03L-0
LINDSEY, F. D. Baitland Power Cooperative 77/04/11 2pp
- 7704120318 LER 77-009/03L-0 on 770507 While reactor plant 125 volt dc battery was removed for maintenance power 14v switch turned on procedural change will be initiated requiring use of info tag on key switch
PAPPERT, L. S. Baitland Power Cooperative 77/06/11 1p
- 7704120318 Forwards LER 77-010/03L-0
LINDSEY, F. D. Baitland Power Cooperative 77/06/20 2pp
- 7704120304 LER 77-010/03L-0 on 770522 During reactor shutdown, gross alpha activity of primary coolant exceeded Tech Spec Caused by irradiated fuel melt in RCS Primary purification vessels replaced & concentration reduced
PAPPERT, L. S. Baitland Power Cooperative 77/06/20 App
- DOCKET 50-465 NINE HOLE POINT NUCLEAR STATION, UNIT 2
H General correspondence
- 7704120353 Responds to 770315 1tr to JF Hardin Facility was shut down by NRC 770313 order due to questions re ability of piping sys to withstand earthquake Situation will be reviewed & plant returned to operation as soon as possible
BENTON, R. H. Office of Nuclear Reactor Regulation 77/05/04 1p
- 7704120306 Expresses concerns re shutdown "r" facility Prolonged leakoff of plant employees could have adverse effect on town of Oswego, NY
FITZGERALD, J. E. Oswego, NY 77/03/19 1p
- B Inspection reports, IE Bulletins & correspondence
- 7704100490 Forwards IE Info Notice 77-10, "Nonconforming Pipe Support Bracket" No written response necessary
ORRIS, B. H. Region 1, Philadelphia, Office of the Director 77/04/16 1p
- 7705110021 Forwards IE Bulletin 77-08, "Nuclear Incident at TCU-Suppl" No written response required
ORRIS, B. H. Region 1, Philadelphia, Office of the Director 77/04/29 1p
- 7704120347 Forwards IE Circular 77-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase" No written response required
ORRIS, B. H. Region 1, Philadelphia, Office of the Director 77/05/02 1p
- 7704120382 Forwards IE Info Notice 77-11, "Lower Reactor Vessel Head Inspection Support Problem" No action required
ORRIS, B. H. Region 1, Philadelphia, Office of the Director 77/05/07 2pp
- 7704120321 Forwards IE Info Notice 77-12, "Attempted Damage to New Fuel Assemblies"
ORRIS, B. H. Region 1, Philadelphia, Office of the Director, 77/05/11 1p
- 7704120318 Responds to IE Bulletin 77-03 Downstream piping per primary containment provided by Bravo Corp Volumetric insp of downstream have shown porosity indications
SHODE, G. H. Niagara Mohawk Power Corp. 77/05/18 1p
- E Repeatable occurrences, LEDs & related correspondence
- 7704120318 Forwards interim deficiency rept.
SHODE, G. H. Niagara Mohawk Power Corp. 77/06/19 1p
- 7704120318 Interim deficiency rept review of ultrasonic testing results revealed that tests for downstream liner were inadequate & certain ultrasonic testing techniques may not have been done by personnel
* Niagara Mohawk Power Corp 77/06/27 2pp

DOCKET 50-412 PEPPER VALLEY REACTOR STATION, UNIT 2

A Application/construction stage documents & correspondence

7906100279 FOLIA request for all records & communications to shutdown of five nuclear plants
GASPAR, V J Power Authority State of New York 79/03/16 App

7906100273 Bureaus FOLIA request for Gibson 790314 & Thompson 790315 memo to Commissioner Bradford, which contain NRC opinions & recommendations re five shutdown plants info withheld
trial FOLIA Exemption 3
MELTOLA, H Division of Rules and Records 79/05/21 App

7906100822 Ack receipt of 790509 application for extension of expiration date on CPPI-103 Advice \$1,300 fee required
SILVER, E J License Fee Management Branch 79/05/23 App

7906100840 Response to 790523 ltr Forwarded fee for review of CP extension request
MCELVER, E J Duplicates Light Co 79/06/26 App

O Inspection reports, IE Bulletins & correspondence

7906100823 Forwarded IE Info Notice 79-10, "Nonconforming Pipe Support Struts." No written response necessary
CRITER, B H Region 1, Philadelphia, Office of the Director 79/04/16 App

7906100812 Forwarded IE Bulletin 79-05A, "Nuclear Incident at TMI-Unit 1." No written response required
CRITER, B H Region 1, Philadelphia, Office of the Director 79/04/23 App

7906100815 Forwarded IE Info Notice 79-11, "Lower Reactor Vessel Head Division Subject Problem." No action required
CRITER, B H Region 1, Philadelphia, Office of the Director 79/05/07 App

7906100810 Forwarded IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
CRITER, B H Region 1, Philadelphia, Office of the Director 79/05/11 App

7906100803 Response to IE Bulletin 79-07 No computer codes identified by RSG which used any of methods described in item 1. IRI/IE 02/01-03/10 computer code used in seismic stress analysis of safety-related piping
MCELVER, E J Duplicates Light Co 79/05/16 App

B Reportable accidents, LERs & related correspondence

7906100977 Ack receipt of 790423 ltr forwarding interim rept on "Stop Work Directive" for Ringham-Billietine Co
GASPAR, V J Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/04 App

7906100940 Interim rept on Significant Deficiency 79-01, "Stop Work Directive" for Ringham-Billietine Co
Maque, Light Co 79/03/29 App

7906100920 Bureaus Interim Rept #2 of potential Reportable Deficiency 79-02 improper drawings supplied by GE All intermediate cabinet events at site are being reviewed against as-shipped drawings Final rept to be submitted 790431
MELTOLA, H Mississippi Power & Light Co 79/05/09 App

Director's Fax

re welding & NOT of quench pump recirculation spray pumps & auxiliary feedwater pumps
Maque, Light Co 79/06/04 App

DOCKET 50-413 CATAMBA NUCLEAR STATION, UNIT 1

J Insurance & indemnity information

7906100833 Forwarded Endorsements 34 & 55 to ARI Policy AF-1802 & Endorsements 40 & 41 to MRELU Policy NF-61
SANDERS, F D Duke Power Co 79/06/06 App

O Inspection reports, IE Bulletins & correspondence

7906100439 Response to IE Bulletin 79-03 Site has received 350 ft of pipe mfg by Youngstown Welding & Engineering Co Pipe will receive field hydrostatic test
MELTOLA, C Duke Power Co 79/05/20 App

7906100154 Response to IE Bulletin 79-04 Design of facility has been reviewed No valve valves in use
MELTOLA, C Duke Power Co 79/04/24 App

7906100444 Forwarded IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
O'BRIEN, J P Region 2, Atlanta, Office of the Director 79/05/10 App

7906100731 Ack receipt of 790527 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/79-05 & 50-414/79-05
MURPHY, C E Region 3, Atlanta, Reactor Construction & Engineering Support Branch 79/05/13 App

7906100741 Response to NRC 790413 ltr re violations noted in IE Insp Repts 50-413/79-05 & 50-414/79-05 Corrective actions nitrogen blanket placed on heat exchanger & personnel instructed re nonconforming steam test
MELTOLA, C Duke Power Co 79/05/07 App

7906100732 Forwarded IE Insp Repts 50-413/79-05 & 50-414/79-05 as 790513-16 & notice of violations
MURPHY, C E Region 3, Atlanta, Reactor Construction & Engineering Support Branch 79/05/13 App

7906100730 Notice of violation from Insp as 790513-16
M Region 3, Atlanta, Office of the Director 79/06/12 App

7906100744 IE Insp Repts 50-413/79-05 & 50-414/79-05 on 790513-16 Noncompliance noted deficiency in vendor qualification main records & infrastructure re steamtest spray heat exchanger storage requirements
MELTOLA, C E, CRITER, B H Region 2, Atlanta, Office of the Director 79/05/13 App

7906100478 Forwarded revised cover sheet for IE Insp Repts 50-413/79-05 & 50-414/79-05
MURPHY, C E Region 3, Atlanta, Reactor Construction & Engineering Support Branch 79/06/03 App

DOCKET 50-414 CATAMBA NUCLEAR STATION, UNIT 2

J Insurance & indemnity information

7906100235 Forwarded Endorsements 34 & 55 to ARI Policy AF-1802 & Endorsements 40 & 41 to MRELU Policy NF-61
SANDERS, F D Duke Power Co 79/06/06 App

O Inspection reports, IE Bulletins & correspondence

7906100439 Response to IE Bulletin 79-03 Site has received 350 ft of pipe mfg by Youngstown Welding & Engineering Co Pipe will receive field hydrostatic test
MELTOLA, C Duke Power Co 79/05/20 App

7906100154 Response to IE Bulletin 79-04 Design of facility has been reviewed No valve valves in use
MELTOLA, C Duke Power Co 79/04/24 App

7906100444 Forwarded IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
O'BRIEN, J P Region 2, Atlanta, Office of the Director 79/05/10 App

7906100731 Ack receipt of 790527 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/79-05 & 50-414/79-05
MURPHY, C E Region 3, Atlanta, Reactor Construction & Engineering Support Branch 79/05/13 App

7906100741 Response to NRC 790413 ltr re violations noted in IE Insp Repts 50-413/79-05 & 50-414/79-05 Corrective actions nitrogen blanket placed on heat exchanger & personnel instructed re nonconforming steam test
MELTOLA, C Duke Power Co 79/05/07 App

7906100730 Forwarded IE Insp Repts 50-413/79-05 & 50-414/79-05 as 790513-16 & notice of violations
MURPHY, C E Region 3, Atlanta, Reactor Construction & Engineering Support Branch 79/06/13 App

DOCKETED ITEMS

17

- 7904100750 Notice of violation from insp on 790215-16
* Region 2, Atlanta, Office of the Director 7/9/04/12 1p
- 7904100744 IE Insp Repts 50-413/79-05 & 50-414/79-05 on 790215-16
Noncompliance noted. Deficiencies in welder qualification main
ventrals & infiltration re containment spray heat exchanger
storage requirements
MOSLEMAN, C H. Region 2, Atlanta, Office of the
Director 7/9/04/12 1p
Engineering Support Branch 7/9/04/13 7p
- 7904090475 Forwards revised cover sheet for IE Insp Repts 50-413/79-07
& 50-414/79-07
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 7/9/04/05 2pp
- DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence
- 7904100337 Responds to 790311 ltr Discusses made to reactor protection
sys power supplies per conceptual design submitted Sept 1978
by GE
DALL, F Mississippi Power & Light Co 7/9/05/29 1p
- 7904100335 Responds to 790427 ltr Forwards Affidavit of Sec for
Verification of Amend 35
DALL, F Mississippi Power & Light Co 7/9/05/04 2pp
- 7904100333 Forwards "Summary of Envelope Protection Program re Const of
Grand Gulf Nuclear Station" for six months ending 790430
MOSLEMAN, C H. Region 2, Atlanta, Office of the Director 7/9/05/06 1p
- 7904100326 "Summary of Envelope Protection Program re Const of Grand
Gulf Nuclear Station" for six months ending 790430
* Mississippi Power & Light Co 7/9/05/06 2pp
- G Adjectively correspondence
- 7904090338 Requests denial of intersector Municipal Energy Agency of MS
790328 petition to close cause until it affords Florida South
Energy has complied with license conditions of CP
CONRAD, T C. Gannon, Moore & Corbin 7/9/05/19 1p
- M Antitrust correspondence
- 7904090301 Municipal Energy Agency of MS requests commencement of
proceedings to require until to comply w/CP license
conditions re intersector agreement Related correspondence
w/250 encl
MOSLEMAN, C H. Region 2, Atlanta, Office of the Director 7/9/05/29 150pp
- G Inspection reports, IE Bulletins & correspondence
- 7904090309 Forwards IE Insp Repts 50-414/79-03 & 50-417/79-03 on
790227-0301 No noncompliance noted
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials
Safety Branch 7/9/05/28 2pp
- 7904070104 IE Insp Repts 50-414/79-03 & 50-417/79-03 on 790227-0301 No
noncompliance noted. Major areas inspected electrical control
panel control, pressurizer hydrology, the erosion & runoff &
review of monthly quarterly reports
MOSLEMAN, C H. Region 2, Atlanta, Fuel Facility & Materials Safety
Branch 7/9/05/28 2pp
Director 7/9/05/28 2pp
- 7904100489 Forwards IE Insp Repts 50-414/79-04 & 50-417/79-04 on 790221-02 No
noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 7/9/05/30 2pp
- 7904100484 IE Insp Repts 50-414/79-04 & 50-417/79-04 on 790221-02 No
noncompliance noted. Major areas inspected electrical control
panel cable terminations, storage & laydown areas & SA
equipment inspection
BAUSON, J R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 7/9/05/30 4pp
- 7904100373 Forwards IE Insp Rept 50-416/79-06 & 50-417/79-06 on
790221-02 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 7/9/05/11 2pp
- 7904090308 IE Insp Rept 50-416/79-06 & 50-417/79-06 on 790221-02 No
noncompliance noted. Major areas inspected 3A program
insulation, storage & laydown areas, turbine bldg roof,
cable tray supports, concrete testing & chamber operation
MOSLEMAN, C H. Region 2, Atlanta, Office of the Director 7/9/05/11 2pp
Engineering Support Branch 7/9/05/11 2pp
- 7904090312 Ack receipt of IE Insp Repts 50-416/79-06 & 50-417/79-06 on
790221-02 No noncompliance noted
MOSLEMAN, C H. Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 7/9/05/11 2pp
- 7904090313 Forwards IE Insp Repts 50-416/79-06 & 50-417/79-06 on
790221-02 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 7/9/05/11 2pp
- 7904090310 IE Insp Repts 50-416/79-06 & 50-417/79-06 on 790221-02 No
noncompliance noted. Major areas inspected electrical
components & sys, electrical cables & terminations,
insulation & fire protection
MOSLEMAN, C H. Region 2, Atlanta, Office of the Director 7/9/05/11 2pp
Director 7/9/05/11 2pp
Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 7/9/05/11 2pp
- 7904100444 Forwards IE Circular 79-07, "Unexpected Speed Increase of
Reactor Motor Generator Set Resulted in Reactor Power
Increase" No written response required
MOSLEMAN, C H. Region 2, Atlanta, Office of the Director 7/9/05/11 2pp
- 7904100440 Ack receipt of 790423 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-416/79-06 &
50-417/79-06
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 7/9/05/11 2pp
- 7904100441 Forwards IE Insp Repts 50-416/79-06 & 50-417/79-06 on
790221-02 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 7/9/05/11 2pp
- 7904090302 Notice of violation from insp on 790215-16
* Region 2, Atlanta, Office of the Director 7/9/05/12 1p
- 7904090305 IE Insp Repts 50-416/79-06 & 50-417/79-06 on 790221-15
Noncompliance noted. Failure to follow procedure for control
of used filler metal
VANDEUSEN, P H. Region 2, Atlanta, Office of the Director 7/9/05/15 2pp
- 7904090363 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assembly"
MOSLEMAN, C H. Region 2, Atlanta, Office of the Director 7/9/05/15 1p
- 7904090362 Responds to IE Bulletin 79-12, 12A & 12B re reactor pressure
vessel welds No discrepancies noted
CONRAD, T C. Gannon, Moore & Corbin 7/9/05/11 2pp
- 7904090373 Responds to IE Bulletin 79-03, "Longitudinal Weld Defects in
SALE-A-212 Type 304 Stainless Steel Piping" No such piping
purchased from Youngblood Welding & Engineering Co
DALL, F Mississippi Power & Light Co 7/9/05/16 1p
- 7904090303 Ack receipt of IE Insp Repts 50-416/79-06 & 50-417/79-06 on
790221-02 No noncompliance noted
MOSLEMAN, C H. Region 2, Atlanta, Office of the Director 7/9/05/16 2pp
- 7904090364 Responds to IE Bulletin 79-12, 12A & 12B re reactor
pressure vessel welds No discrepancies noted
DALL, F Mississippi Power & Light Co 7/9/05/16 1p
- E Reportable occurrences, LTRs & related correspondence
- 7904090446 Submits interim deficiency report re 4-inch x 10-inch long radius 90
degree elbow. Caused by mfg error. No having carbon content
greater than specified was identified w/line carbon test
number. Will issue final report by 790625
DALL, F Mississippi Power & Light Co 7/9/05/16 1p
- 7904100373 Forwards IE Insp Rept 50-416/79-06 & 50-417/79-06 on
790221-02 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 7/9/05/11 2pp
- 7904100444 Submits interim deficiency report re 4-inch x 10-inch long radius 90
degree elbow. Caused by mfg error. No having carbon content
greater than specified was identified w/line carbon test
number. Will issue final report by 790625
DALL, F Mississippi Power & Light Co 7/9/05/16 1p
- 7904100446 Submits interim deficiency report re 4-inch x 10-inch long radius 90
degree elbow. Caused by mfg error. No having carbon content
greater than specified was identified w/line carbon test
number. Will issue final report by 790625
DALL, F Mississippi Power & Light Co 7/9/05/16 1p

7906145008 Submits Interim Report 2 of potential Reportable Deficiency
79-08 improper drawings supplied by GE All termination
cabinet panels at site are being reviewed against
as-shipped drawings. Final report will be submitted 790503
DALL, L.F. Mississippi Power & Light Co 79/05/29 1p

7906145037 Submits Interim Report 2 of potential Reportable Deficiency
79-08 inadequate crimping found in power generation control
cables interconnecting cables Panel Final report will be submitted
on 791115
DALL, L.F. Mississippi Power & Light Co 79/05/29 1p

7906145049 Submits Interim Report 2 for deficiency re failure by GE to
establish & implement approved QA program for electrical
work performed. Updated QA manual approved. Final report by
790605
DALL, L.F. Mississippi Power & Light Co 79/06/05 1p

7906050219 Interim deficiency report failure of several small state
devices out of low voltage power circuit breakers. Will
complete final & submit final report by 791031
DALL, L.F. Mississippi Power & Light Co 79/06/19 1p

404662 79-417 CDND DALL NUCLEAR STATION, UNIT 2
A. Application/Construction stage documents & correspondence
790505

7906145055 Responds to 790627 for Forensic Affidavit of Gov for
distribution of Amend 30
DALL, L.F. Mississippi Power & Light Co 79/06/26 2pp

7906145059 Forwarded "Summary of Environ Protection Program re Coast of
Coast Gulf Nuclear Station" for six months ending 790430
McGOWAN, J.P. Mississippi Power & Light Co 79/05/05 1p

7906145056 "Summary of Environ Protection Program re Coast of Grand
Gulf Nuclear Station" for six months ending 790430
Mississippi Power & Light Co 79/06/05 2pp

0. Regulatory correspondence

7906230278 Requests denial of intervenor Municipal Energy Agency of MS
790529 petition to show cause Unit 1 & affiliate Delta South
Energy, Inc. have complied with conditions of CP
200606 N. B. Comer, Name & Color 79/06/19 App

0. Ambient correspondence

7906040201 Municipal Energy Agency of MS requests commencement of
proceedings to require unit to comply w/CP license
conditions re intervenor agreement. Sustained correspondence
w/DOE encl
McGOWAN, J.P. Siegel & McFarland 79/05/29 180pp

0. Inspection reports, IE Bulletins & correspondence

7906070099 Forwarded IE Insp Repts 79-416/79-03 & 79-417/79-03 on
790527-7901 No noncompliance noted
Region 2, Atlanta, Reactor Fuel Facility & Materials
Safety Branch 79/05/29 2pp

7906070104 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070109 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070110 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070111 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070112 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070113 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070114 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070115 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070116 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070117 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070118 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070119 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070120 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070121 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070122 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070123 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070124 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070125 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070126 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070127 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070128 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070129 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070130 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070131 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7906070132 IE Insp Repts 79-416/79-03 & 79-417/79-03 on 790527-7901 No
noncompliance noted. Major areas inspected administrative & QA
program implementation
McGOWAN, J.P., MONT, A.R. Region 2, Atlanta, Reactor Construction
& Engineering Support Branch 79/05/29 App

7904140429 Bobmits Interim Rep't 2 for deficiency re failure by SE to establish & implement approved QA program for electrical work performed. Upgraded 3N annual approved Final rept by 790428
DMLC/L F Mississippi Power & Light Co 79/06/01 1p

79040700219 Interim deficiency report failure of several solid state devices, part of low voltage power circuit breakers will complete insp & submit final rept by 790503
DMLC/L F Mississippi Power & Light Co 79/06/10 1p

DOCKET 50-423 HOLLISTONE NUCLEAR POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

79041200130 Notification of 790515 meeting w/uttl in Bethesda, MD to discuss multi-reported fault
DORRERICH, R A Light Water Reactors Branch 3 79/05/07 2pp

79042900136 Summary of 790515 meeting w/uttl & NRC in Bethesda, MD re bedrock fault in foundation areas
JACKSON, R E Geosciences Branch 79/05/23 7pp

I Financial information

79042000376 Forwards annual financial repts for owner-licensess
O'CONNOR, L A Northeast Utilities 79/05/10 3pp

--79042000379 Annual Financial Rept 1978
* Western Massachusetts Electric Co 79/12/31 17pp

--79042000376 Annual Financial Rept 1978
* Hartford Electric Light Co 79/12/31 21pp

--79042000377 Annual Financial Rept 1978
* Connecticut Light & Power Co 79/12/31 21pp

J Insurance & indemnity information

79041200292 Forwards Endorsements 34 & 35 to NOLIA Policy NF-32
CONWELL, T Northeast Nuclear Energy Co (Northeast Utilities) 79/04/12 3pp

79040700241 Forwards Endorsements 39 & 40 to NOLIA Policy NF-173
SEIGER, R H Northeast Nuclear Energy Co (Northeast Utilities) 79/04/21 3pp

79042800241 Forwards Endorsements 79 & 80 to NOLIA Policy NF-173
SEIGER, R H Northeast Utilities 79/05/21 1p

G Inspection reports, IE Bulletins & correspondence

79041200297 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Brackets" - No written response necessary
CIRIEL, R H Region 1, Philadelphia, Office of the Director 79/04/16 1p

79041200119 Forwards IE Bulletin 79-059, "Nuclear Incident at WH-3001" - No written response required
CIRIEL, R H Region 1, Philadelphia, Office of the Director 79/04/23 1p

79041200176 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" - No action required
CIRIEL, R H Region 1, Philadelphia, Office of the Director 79/05/27 2pp

79040400124 Forwards SF Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" -
CIRIEL, R H Region 1, Philadelphia, Office of the Director 79/05/11 1p

79042900224 Responds to IE Bulletin 79-03 re welded pipe supplied by Yonkers Welding & Engineering in use on planned rev. app.
CONWELL, M D Northeast Utilities 79/05/15 3pp

DOCKET 50-424 ALVIN H. VOITTE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

79041200277 Notifies that final rept re welded assemblies, originally scheduled for submittal by 790601, will be delayed until 790601
EISENHARDTER, H Georgia Power Co 79/06/01 1p

F Security, medical, emergency & fire protection plans

79040700277 Forwards fire hazards analysis includes re-evaluation of other fire protection systems requested in 790503 ltr
EISENHARDTER, H Georgia Power Co 79/05/26 1p

--79040700300 Fire hazards analysis
* Georgia Power Co 79/06/01 77pp

G Adjudicatory correspondence

79042002770 Ack receipt of Georgians Against Nuclear Energy petition requesting reconsideration of 790413 denial of earlier Georgians Against Nuclear Energy petition. Forwards FE notice
BENTON, H R Office of Nuclear Reactor Regulation 79/04/06 1p

--79042002770 Notice of receipt & availability of 790501 petition from Georgians Against Nuclear Energy requesting reconsideration of denial of earlier Georgians Against Nuclear Energy petition
BENTON, H R Office of Nuclear Reactor Regulation 79/06/06 1p

79042002777 Forwards Georgians Against Nuclear Energy 790501 petition for reconsideration of request for suspension of CF 78 notice and
BENTON, H R Office of Nuclear Reactor Regulation 79/06/06 2pp

H General correspondence

79040400204 Requests revision to distribution list for OPPE-100 & OPPE-101
EISENHARDTER, H Georgia Power Co 79/05/20 2pp

G Inspection Reports, IE Bulletins & correspondence

79041200277 Ack receipt of IE Insp Repts 50-424/79-04 & 50-425/79-04 on 790326-00 Ho proprietary info
STAFFA, R H Georgia Power Co 79/04/20 1p

--79041200270 Forwards IE Insp Repts 50-424/79-04 & 50-425/79-04 on 790326-00 Ho noncompliance noted
HARRIN, C C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 2pp

--79041200270 IE Insp Repts 50-424/79-04 & 50-425/79-04 on 790326-00 Ho noncompliance noted. Major areas inspected (ICF830 201a) items previous insp findings, water quality, SC Inspector training & vessel fabrication shop metal control
HUNT, H U Region 2, Atlanta, Office of the Director HERST, A R Region 3, Atlanta, Reactor Construction & Engineering Support Branch 79/05/30 4pp

79041400230 Responds to IE Bulletin 79-23 Rebuttal info re pipe spools used in fabrication of piping subassemblies
STAFFA, R H Georgia Power Co 79/05/29 2pp

79042004893 Forwards IE Info Notice 79-10, "Attempted Damage to New Fuel Assemblies" -
O'NEILL, J P Region 2, Atlanta, Office of the Director 79/05/10 1p

DOCKET 50-425 ALVIN H. VOITTE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

79041200287 Notifies that final rept re welded assemblies, originally scheduled for submittal by 790601, will be delayed until 790601
EISENHARDTER, H Georgia Power Co 79/06/01 1p

F Security, medical, emergency & fire protection plans

79040700277 Forwards fire hazards analysis includes re-evaluation of other fire protection systems requested in 790503 ltr
EISENHARDTER, H Georgia Power Co 79/05/26 1p

--79040700300 Fire hazards analysis
* Georgia Power Co 79/06/01 77pp

© Adjudicatory competence

7902665270 Ack receipt of Georgians Against Nuclear Energy petition
requesting reconsideration of 790410 denial of earlier
Georgians Against Nuclear Energy petition Forwards FR
notice
DENTON, W R Office of Nuclear Reactor Regulation 79/06/06 1p

7906260000 Notice of receipt & availability of 790601 petition from Georgians Against Nuclear Energy requesting reconsideration of denial of earlier Georgians Against Nuclear Energy petition
DENTON, R. Office of Nuclear Energy Regulation 79/06/26 1

7906280247 Forwards Georgians Against Nuclear Energy 790581 petition for reconsideration of request for suspension of CP FR notice encl
DISTRIBUTION R Office of Nuclear Reactor Regulation 79/06/06 2pg

4 General correspondence

7906060284 Requests revision to distribution list for CPPB-228 &
CPPB-109
KRENSPORDER,W Georgia Power Co 79/05/36 Rps

3. Inspection reports, IE Bulletins & correspondence

7906100677 Act receipt of IE Insp Regis 80-424/79-04 & 80-425/79-04 en
790306-02 No proprietary info
BTAPPA-R M Georgia Power Co 79/04/25 10

--7904sB0090 Forwards IE Insp Rpts 50-424/79-04 & 50-425/79-04 on
790305-08 No noncompliance noted
HJSPH:C E Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 79/04/RSZ Rps

---7906100000 IE Insp Repts 50-428/79-04 & 50-428/79-04 on 790306-08 He
nanc compliance noted Major areas inspected LCCF50 05(e)
Items previous noted Findings, water quality GC Inspector
training & steel fabrication shop wall control
HUNT, M D Region 2, Atlanta, Office of the Director HERD, A R
Region 2, Atlanta, Reactor Construction & Engineering Support
Branch 79/02/06 doc

7906140326-Response to IE Bulletin 79-03 Submits info re pipe spec
used in fabrication of piping subassemblies
STAFFA, R W Georgia Power Co 79/05/09 2pp

7906250455 Forwards IE Info Notice 79-12: "Attempted Damage to New Fuel Assemblies"
G'REILLY, J P Region 2: Atlanta, Office of the Director
79/05/10 1a

EXHIBIT SD-433 UC-SANTA BARBARA RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

7904200304 Forwards repts an alterations to reactor facility Physical security plan being revised to reflect repts Hapt withheld (inf 100FR 790)

4. Insurance & indemnity information

7706260070 Forwards, executed Amend 8 to Indemnity Agreement E-16, Amend
4 to Indemnity Agreement E-28/Amend 2 to Indemnity Agreement
E-23 & Amend 12 to Indemnity Agreement E-15
DENEEN, B J California, Univ of, Berkeley 79/06/21 Ssp

⑤ Inspection reports, IE Bulletins & correspondence

DOCKET NO-434 SLURRY POWER STATION, UNIT 2

11. Capitalization/Expense Correspondence

790410337 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Stage have been taken re review of pipe stress reassesses Discusses site-specific consideration for seismic events
HUGHES, J M Commission 79/05/21 Doc

--9064102278 Art receipt of VA congressional delegation 790219 ltr re
shakedown of facilities Steps have been taken to review af
fairs stress management Distances site-specific
considerations for seismic events
HONORABLE J M Cannon 79/05/21 Gos

--795430300 are receipt of VA congressional delegation 795219 site re
shutdown of facilities Steps have been taken re review of
pipe stress analyses Discusses site-specific
considerations for seismic events
RENDTIE, J M Commission 79/05/21 App

--TPOC00000000 rec receipt of WA congressional delegation TPOC019 ltr re shutdown of facilities Steps have been taken re review of pipe stress analyses Discusses site-specific considerations for seismic events
MEMORIE, J.M. Commission 79/05/21 See

--706610385 Asa receipt of VA congressional delegation 790219 ltr re
shortage of facilities Steps have been taken re review of
sign stress researches Distances also specific
considerations for oceanic events
HNSCPRIC J N Commission 79/03/21 Sep

--PROA(10287) Act receipt of 98 congressional delegation 740219 its re
submissions of facilities steps have been taken re review of
pipe stress reanalysis Discusses inter-specific
considerations for seismic events
MEMPHIS, J.N. Commission, 79/05/21 See

---P06400000 Art receipt of VA congressional delegation 790319 ltr re studies of facilities Steps have been taken re review of pipe stress analyses Discussions site-specific considerations for seismic events
W66016 J.M. Gosselman 79-05/20 Rm

---7966180094 Ack receipt of VA congressional delegation 790319 ltr re
shutdown of facilities. Steps have been taken re review of
pipe street requirements. Discusses site-specific
considerations for seismic events
UNRECORDED J.M. Deaconson 79085J20 One

-----7006110097 Ach receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress analyses Discusses site-specific considerations for seismic events
1000001E J.M. Commission 791014/20 Doc

--PROCEEDING Feb receipt of VA congressional delegation 790319 ltr re
shortage of facilities Steps have been taken re review of
pipe stress analyses Discusses site-specific
considerations for seismic events
HARRIS, J. M. Commission 79/06/20 Doc

---PROLIFERATION Forwards draft of proposed responses to 790019 18r from 10
VA congressional delegates re pipe stress analysis at
facility
OEDT:JH:K Office of Nuclear Reactor Regulation 79/08/86 8p

--7905110411 Requests expedited review of piping stress reassess.
independent from review of other three plants shut down for
seismic-related issues
BUTLER, C. H. , DANIEL, R. W. , HERRIN, H. E. House of Rep 79/05/19
200

SECRET SO-425 SUBVY PIONEER STATISTICAL UNIT 4

11. Compression of Transactions

7906110067 Feb receipt of VA congressional delegation 790019 ltr re
shortcom of facilities Steps have been taken re review of
pipe stress remaining discussed site-specific consideration
for seismic events
REDAKED J M Commission 79/06/21 Res

--790618037H Ast receipt of VA congressional delegation 790019 ltr re
sheds of facilities Bldgs have been taken re review of
pipe street Pavedness Discuss site-specific
considerations for seismic events
HEADLINE J M Commission 79/07/21 Gsa

7906180489 Forwarded RE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies." No written response necessary.
WISSELING, R. L. Region 5, San Francisco, Office of the Director
79/05/15. 1a

79C6080237 Forwarded in Circular 79-06. "Attempted Extortion - Low
Enriched U"
ENGLISH, R H Region 5, San Francisco. Office of the Director,
79/05/18 10

DOCKETED ITEMS

--790404045 IE Insp Repts 50-438/79-04 & 50-439/79-04 on 790312-15 No noncompliance noted Major areas inspected structural steel status of 1500psi structures & cables & site audit program
WRIGHT, A. H. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/23 App

7904050352 Forwards IE Insp Repts 50-438/79-04 & 50-439/79-04 on 790403-06 No noncompliance noted
WRIGHT, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/24 App

--7904050353 IE Insp Repts 50-438/79-04 & 50-439/79-04 on 790403-06 No noncompliance noted Major areas inspected structural steel status of 1500psi structures & cables & site audit program
WRIGHT, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/23 App

7904050998 Responds to IE Bulletin 79-03 Investigation shows no piping in use or planned for use in safety-related systems Effort in progress to locate any ASME SA-312 Type 304 piping supplied by Youngtown Welding & Engineering Co.
GILLESPIE, J. E. Tennessee Valley Authority 79/05/14 App

7904052019 Act receipt of 790508 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/79-04 & 50-439/79-04
WRIGHT, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/14 App

--7904052019 Responds to NRC 790412 ltr re violations noted in IE Insp Repts 50-438/79-04 & 50-439/79-04
GILLESPIE, J. E. Tennessee Valley Authority 79/05/08 App

--7904052024 Forwards IE Insp Repts 50-438/79-04 & 50-439/79-04 on 790327-30 re notice of violation
WRIGHT, C. E. Region 2, Atlanta, Office of the Director 79/04/12 App

--7904052029 Notice of violation from Insp on 790327-30
* Region 2, Atlanta, Office of the Director 79/04/12 App

--7904052042 IE Insp Repts 50-438/79-04 & 50-439/79-04 on 790327-30 Noncompliance noted during welding filler metal certificate & inspector qualification records
WRIGHT, P. H. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/12 App

5 Reportable occurrences, LERs & related correspondence

7904040420 Forwards deficiency report re blown fuses in low voltage switchgear
GILLESPIE, J. E. Tennessee Valley Authority 79/03/25 App

--7904040423 First interim deficiency report blown fuses in low voltage switchgear Cause unknown Ull informed Westinghouse & requested investigation of problem
* Tennessee Valley Authority 79/05/25 App

7904050921 Provides first interim report re seismic response for primary branch lines which may not be conservative Expects to submit next report by 790727
GILLESPIE, J. E. Tennessee Valley Authority 79/05/07 App

6 Inspection reports, IE Bulletins & correspondence

7904050352 Forwards IE Insp Repts 50-438/79-04 & 50-439/79-04 on 790403-06 No noncompliance noted
WRIGHT, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/23 App

--7904050353 IE Insp Repts 50-438/79-04 & 50-439/79-04 on 790403-06 No noncompliance noted Major areas inspected quality records & observation of work on reactor coolant pressure boundary piping
WRIGHT, J. J., KLEINSMITH, P. J., GILLESPIE, J. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/26 App

7904050446 Forwards IE Insp Repts 50-438/79-04 & 50-439/79-04 on 790327-30 No noncompliance noted
WRIGHT, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/30 App

--7904050445 IE Insp Repts 50-438/79-04 & 50-439/79-04 on 790312-15 No noncompliance noted Major areas inspected status of 1500psi structures & cables & site audit program
WRIGHT, A. H. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/23 App

7904050352 Forwards IE Insp Repts 50-438/79-04 & 50-439/79-04 on 790403-06 No noncompliance noted
WRIGHT, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/24 App

--7904050353 IE Insp Repts 50-438/79-04 & 50-439/79-04 on 790403-06 No noncompliance noted Major areas inspected structural steel status of 1500psi structures & cables & site audit program
WRIGHT, J. J., KLEINSMITH, P. J., GILLESPIE, J. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/23 App

7904050998 Responds to IE Bulletin 79-03 Investigation shows no piping in use or planned for use in safety-related systems Effort in progress to locate any ASME SA-312, Type 304 piping supplied by Youngtown Welding & Engineering Co.
GILLESPIE, J. E. Tennessee Valley Authority 79/05/14 App

7904052019 Act receipt of 790508 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/79-04 & 50-439/79-04
WRIGHT, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/14 App

--7904052019 Responds to NRC 790412 ltr re violations noted in IE Insp Repts 50-438/79-04 & 50-439/79-04
GILLESPIE, J. E. Tennessee Valley Authority 79/05/08 App

--7904052024 Forwards IE Insp Repts 50-438/79-04 & 50-439/79-04 on 790327-30 re notice of violation
WRIGHT, C. E. Region 2, Atlanta, Office of the Director 79/04/12 App

--7904052029 Notice of violation from Insp on 790327-30
* Region 2, Atlanta, Office of the Director 79/04/12 App

--7904052042 IE Insp Repts 50-438/79-04 & 50-439/79-04 on 790327-30 Noncompliance noted during welding filler metal certificate & inspector qualification records
WRIGHT, P. H., GILLESPIE, J. E. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/12 App

6 Reportable occurrences, LERs & related correspondence

7904040420 Forwards deficiency report re blown fuses in low voltage switchgear
GILLESPIE, J. E. Tennessee Valley Authority 79/03/25 App

--7904040423 First interim deficiency report blown fuses in low voltage switchgear Cause unknown Ull informed Westinghouse & requested investigation of problem
* Tennessee Valley Authority 79/05/25 App

7904050921 Provides first interim report re seismic response for primary branch lines which may not be conservative Expects to submit next report by 790727
GILLESPIE, J. E. Tennessee Valley Authority 79/05/07 App

7904050921 Forwards final interim deficiency report re pipes embedded in structural concrete
GILLESPIE, J. E. Tennessee Valley Authority 79/05/15 App

DOCKETED ITEMS

183

- 7906200201 Final interim deficiency report issued in structural concrete Review confirmed that RC conductivity size of spalling violation impeded structural integrity
* Tennessee Valley Authority 7/9/06/13 2pp
- 7906200113 Forwarded Final deficiency report re failure of cadweld sister splice rather than meet ASTM A618 strength requirements
GILLESPIE, J E Tennessee Valley Authority 7/9/06/22 2pp
- 7906200114 Final deficiency report failure of cadweld sister splice rather than meet ASTM A618 strength requirements Rebar in failed splice is not representative of rebar used in permanent structure
* Tennessee Valley Authority 7/9/06/22 1p
- DOCKET 30-440 PERRY NUCLEAR POWER PLANT, UNIT 1
- H Audit/Trust correspondence
- 7906200203a Notifies that certain documents were removed from ASL&B secretary's desk by unauthorized person Documents found in another office investigation initiated
CURRIE, R E Atomic Safety and Licensing Appeal Panel 78/10/02 2pp
- 7906200270 Forwarded ASL&B memo issued in Davis-Besse & Perry proceeding re missing papers in file
REEDER, A S Atomic Safety and Licensing Appeal Panel 78/10/03 1p
- 7906200277 Forwarded 781007 rept. "Investigation of Unauthorized Removal of ASL&B Documents" Rept withheld (ref FOIA Exemptions 7a & 7c)
CURRIE, R E Office of Inspector & Auditor 78/11/10 1p
- 7906200283 Provides info re limited inquiring in less or theft of ASL&B sensitive documents Info partly withheld due to enforcement proceedings (ref FOIA Exemptions 7a & 7c)
ATMELL, F L Division of Security 78/10/03 2pp
- 7906200283 Provides summary of investigation into alleged removal of documents from ASL&B office Info partly withheld due to enforcement proceedings (ref FOIA Exemptions 7a & 7c)
ASTON, D G Office of Inspector & Auditor 78/11/07 4pp
- 7906200283 Comments on OIC of Inspector & Auditor rept re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7a)
REEDER, A S Atomic Safety and Licensing Appeal Panel 78/11/08 2pp
- 7906200283 Responds to 781107 memo re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7a)
BURN, C L Division of Security 78/12/04 2pp
- 7906200289 Comments on OIC of Inspector & Auditor rept re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7a & 7c) Forwarded Washington Post 79/01/28 0212 & 03 articles
HARMER, F F Office of Inspector & Auditor 79/02/08 7pp
- 7906200294 Comments on OIC of Inspector & Auditor rept re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7a)
CURRIE, R E Office of Inspector & Auditor 79/06/22 2pp
- 0 Inspection reports, IE Bulletins & correspondence
- 7906200303 Forwarded IE Insp Repts 30-440/79-02 & 30-441/79-02 re 790313-16 No noncompliance noted
FELDMAN, L B Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/04 2pp
- 7906200304 IE Insp Repts 30-440/79-02 & 30-441/79-02 re 790313-16 No noncompliance noted Major areas inspected audit observations, review of Event-Condition BA implementing procedures & quality records relative to civil activities
HARMER, F F, HARVEY, D M Region 3, Chicago, Office of the Director 79/04/02 11pp
- 7906200348 Responds to IE Bulletin 79-02 No ASME BA-352 Types 304 & 316 piping used
DAVIDSON, D H Cleveland Electric Illuminating Co 79/06/02 1p
- 7906200377 Forwarded IE Info Notice 79-12, "Lower Reactor Vessel Head Inspection Report Problem No action required."
REPPER, J G Region 3, Chicago, Office of the Director, 79/02/07 1p
- 7906190006 Forwarded IE Info Notice 79-12, "Attempted Damage to New Fuel Assembly"
REPPER, J G Region 3, Chicago, Office of the Director 79/02/11 1p
- 7906130006 Forwarded IE Bulletin 79-11, "Passing Overcurrent Trip Device in Circuit Breaker for Engineered Safety Sys" License action required
REPPER, J G Region 3, Chicago, Office of the Director 79/02/22 1p
- 7906200301 Forwarded IE Info Notice 79-12, "Indication of Low Water Level in Dwyer-Creek Reactor"
REPPER, J G Region 3, Chicago, Office of the Director 79/05/29 1p
- B Reportable occurrences, LERs & related correspondence
- 7906200279 Summarizes status of evaluation of significant deficiency re B&B Constructors, Inc BA program work on intake structures continuing final report delayed until 790821
DAVIDSON, D H Cleveland Electric Illuminating Co 79/09/29 1p
- DOCKET 30-441 PERRY NUCLEAR POWER PLANT, UNIT 2
- H Audit/Trust correspondence
- 7906200203a Notifies that certain documents were removed from ASL&B secretary's desk by unauthorized person Documents found in another office investigation initiated
CURRIE, R E Atomic Safety and Licensing Appeal Panel 78/10/02 2pp
- 7906200270 Forwarded ASL&B memo issued in Davis-Besse & Perry proceeding re missing papers in file
REEDER, A S Atomic Safety and Licensing Appeal Panel 78/10/03 1p
- 7906200277 Forwarded 781007 rept. "Investigation of Unauthorized Removal of ASL&B Documents" Rept withheld (ref FOIA Exemptions 7a & 7c)
CURRIE, R E Office of Inspector & Auditor 78/11/10 1p
- 7906200283 Provides info re limited inquiring in less or theft of ASL&B sensitive documents Info partly withheld due to enforcement proceedings (ref FOIA Exemptions 7a & 7c)
ATMELL, F L Division of Security 78/10/03 2pp
- 7906200283 Provides summary of investigation into alleged removal of documents from ASL&B office Info partly withheld due to enforcement proceedings (ref FOIA Exemptions 7a & 7c)
ASTON, D G Office of Inspector & Auditor 78/11/07 4pp
- 7906200283 Comments on OIC of Inspector & Auditor rept re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7a)
REEDER, A S Atomic Safety and Licensing Appeal Panel 78/11/08 2pp
- 7906200283 Responds to 781107 memo re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7a)
BURN, C L Division of Security 78/12/04 2pp
- 7906200289 Comments on OIC of Inspector & Auditor rept re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7a & 7c) Forwarded Washington Post 79/01/28 0212 & 03 articles
HARMER, F F Office of Inspector & Auditor 79/02/08 7pp
- 7906200344 Comments on OIC of Inspector & Auditor rept re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7a)
CURRIE, R E Office of Inspector & Auditor 79/06/22 2pp
- 0 Inspection reports, IE Bulletins & correspondence
- 7906100300 Forwarded IE Insp Repts 30-440/79-02 & 30-441/79-02 re 790313-16 No noncompliance noted
FELDMAN, L B Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/04 2pp
- 7906100304 IE Insp Repts 30-440/79-02 & 30-441/79-02 re 790313-16 No noncompliance noted Major areas inspected audit observations, review of Event-Condition BA implementing procedures & quality records relative to civil activities
HARMER, F F, HARVEY, D M Region 3, Chicago, Office of the Director, 79/04/02 11pp

DOCKETED ITEMS

790602048 Response to IE Bulletin 79-02 Re AHM 24-012 Types 304 & 316 piping used
DAVIDSON, D R Cleveland Electric Illuminating Co 79/05/02 1p

790602097 Forwarded IE Info Notice 79-11, "Steam Reactor Vessel Head Insulation Support Problem." No action required
HOPFLER, J O Region 3, Chicago, Office of the Director 79/05/07 1p

790619086 Forwarded IE Info Notice 79-12, "Attenuated Damage to New Fuel Assemblies"
HOPFLER, J O Region 3, Chicago, Office of the Director 79/05/11 1p

790623090 Forwarded IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Regulated Safety Bus." Licensee action required
HOPFLER, J O Region 3, Chicago, Office of the Director 79/05/02 1p

790629091 Forwarded IE Info Notice 79-13, "Indication of Low Water Level in Reactor Core Reactor"
HOPFLER, J O Region 3, Chicago, Office of the Director 79/05/29 1p

Re reportable occurrences, LERs & related correspondence

790609257 Summarizes status of evaluation of significant deficiency re DMR Construction, Inc. QA program work on intake structures. Outstanding report delayed until 790801
DAVIDSON, D R Cleveland Electric Illuminating Co 79/05/29 1p

DOCKET 50-443 SEABOARD NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

790609082 Response to NRC 790508 request. Forwarded Anti-Smear Hydro-Electric Co filed under Amend 29 of license application, dtd 790519. Requests expedited antismear review, in order to complete processing of new Amend 40
BENNER, J A Region 3, Gray 79/05/28 4pp

0 Adjudicatory correspondence

790629047 Motion for extension until 790401 to prepare response to ALAB-509
SCARRO, J F Hearings Division 79/06/02 2pp

790629069 Response to 790502 request for info re status of evaluating proceeding to develop value for radon in Table B-3 Part 1 and proposed rule will be sent to AEC by 790406. Rule does not address health effects of radon releases
CHRISTENSEN, C Hearings Division 79/06/26 24pp

790609036 Lists reasons for nonparticipation in seismic design proceedings. Relates AEC incident to AEC studies by Public Sec Co of SM. Seismic comments re facilities presented to Commissioner. Dr. Ray, but not allowed as evidence
WERNER, S E H Affiliation Unknown 79/04/30 10pp

790609036 Forwarded Seaboard Anti-Pollution League 790502 request for order to show cause re suspension or revocation of CPE Certificate. A. O'Hall, Seaboard. Appendix 79/05/02 1p

790609078 Request by Seaboard Anti-Pollution League for order to show cause re suspension or revocation of CPE Certificate of One unit

7906010275 Suggests further consideration of alternative site issues to appeal court finding that cooling towers were not required
BURLIN, H E Atomic Safety and Licensing Appeal Panel 79/03/14 5pp

7906210093 NRC motion for summary disposition re radon issue was in pending. 790501 consolidated with 3 of 10 cases. Seaboard NRC action as to parties in other proceedings. Certificate of One unit
BURLIN, H E Atomic Safety and Licensing Appeal Panel 79/03/23 3pp

0 General correspondence

7906070045 Ack receipt of 790325 ltr to J. Deutsch of DOE re use of emergency core discharge capability of unitary type re withdrawal reheat/heat exchanger & other damaging items
DEVOLAND, R C Division of Site Safety & Environmental Analysis 79/04/14 4pp

1 Financial information

790605046 Forwarded Suppl 1 to Amend 40. Supporting documentation, including financial justifications of several units re partial transfer of ownership
BITTNER, J A Region 3, Gray 79/06/02 1p

790605053 Forwarded info re Suppl 1 to Amend 40 & request for partial transfer of OPR-125 & OPR-136. Forwarded "Annual Financial Rept 1978" for unit
HEWELL, D R Public Service Co of New Hampshire 79/06/01 2pp

790606036 "Annual Financial Rept 1978" Supplemental info incl
Central Vermont Public Service Corp 78/12/31 200pp

790606037 "Annual Financial Rept 1978" Supplemental info incl
Green Mountain Power Corp 78/12/31 100pp

790606050 "Annual Financial Rept 1978" Supplemental info incl
Bangor Hydro-Electric Co 78/12/31 110pp

790606067 "Annual Financial Rept 1978" Supplemental info incl
Central Maine Power Co 78/12/31 175pp

790606068 "Annual Financial Rept 1978" Supplemental info incl
Taconic Municipal Lighting Plant 78/12/31 81pp

790610037 Forwarded annual financial repts for each facility
BITTNER, J A Region 3, Gray 79/06/18 2pp

790619030 "Annual Financial Rept 1978"
Northeast Utilities 78/12/31 40pp

790619036 "Annual Financial Rept 1978"
Hudson River Hudson Light & Power Corp 78/12/31 23pp

790619036 "Annual Financial Rept 1978"
Western Utilities Associates 78/12/31 40pp

790619037 "Annual Financial Rept 1978"
Fitchburg Gas & Electric Light Co 78/12/31 20pp

790619036 "Annual Financial Rept 1978"
Vermont Electric Cooperative, Inc 78/12/31 24pp

790619036 "Annual Financial Rept 1978"
Hancockville Municipal Wholesale Co 78/12/31 40pp

790619037 "Annual Financial Rept 1978"
United Illuminating 78/12/31 28pp

790619037 "Annual Financial Rept 1978"
New England Gas & Electric Assoc 78/12/31 26pp

790619037 "Annual Financial Rept 1978"
Maine Public Service Co. 78/12/31 24pp

790619037 "Annual Financial Rept 1978"
Vermont Electric Power Co., Inc. 78/12/31 22pp

1984 Forwarded annual financial repts for Public Sec Co of NH. New and Power Co & United Illuminating
BURLIN, H E Region 3, Gray 79/06/02 200pp

DOCKETED ITEMS

7906200000 Requests amend to CRRS-126 & 127 to authorize withdrawal of groundwater during const for addl year Sakinaka pumpage remedy. TS govt well data & ltr re evaluation of planned treatment facility Amend fee & two overlaid maps encl GARY, R J Texas Utilities Generating Co 79/06/15 020s

G Adjudicators correspondence

790510000 Casfire 790418 meeting in Arlington, TX to discuss
contentions re facility Requests proposed contentions be
forwarded before meeting
CHANDLER L J Branch 6 79/04/06 10

7906095026 Suppl to petition to intervene Add contentions re const of
plant Affidavits & Certificate of Env anal
FOUR, S L - JACOBSON, M H Citizens for Fair Udding Regulation
79/06/07 23ss

7906070308 Reply to 790228 petition to intervene & listing of
 contributors
 ELLIS, J Citizens Association for Sound Energy 79/05/07 56pp

7905260084 Suppl to amended petition of Intervenor's Association of
Community Organizations for Reform No. 44 & C 42464 b C & N
Head Links & provides bases for safety & environ
commissions Affidavit & Certificate of Exc excd
6/11/08 West Texas Legal Services 79/05/07 3865

7906070399 Denies 790406 motion by Association of Community Organizations for Reform Now & West TX Legal Socy for continuance of prehearing conference & filing sanctions BOWEN, E E Atomic Safety and Licensing Board Panel 79/03/09 Doc

7904289488 Memo by applicants re interest & contentions of petitioners
No petitioner has shown requisite interest or valid
contention necessary to support intervention in proceeding
Certificate of Rev and
REHOLDB, N. B. Bebovolos & Lieberman 79/05/17 10aa

7906260205 Recommends intervenor status be granted to all petitioners.
Intervenor contentions should be consolidated; drafts
acceptable contention re adequacy of facility sent
Certificate of Use and
CHANDLER, L. J. Branch 1 79/05/17 Sep

7906260974 Memo by applicants re significance of ALAB-549 in
proceeding Associational standing doctrine has been
misapplied in organizations seeking standing through people
who are not members. Certificate of Gov and
REYNOLDS, H B Bebovoice & Lieberman 79/06/04 9pg

K. Utility Flood Safety Analysis Report (UFSAR) & Appendices

7906120033 Forwards Amend & to PSNR Affidavits encl
GARY, R J Texas Utilities Generating Co 79/08/31. 3pp

```

==7906120239 Amend & to F&ER
  * Texas Utilities Generating Co  79/09/31  50000

```

7906120029 Forwards Affidavit of Dvc for Amend 6 to FBR
FEIST, C K Texas Utilities Services, Inc 79/05/00 3pp

4. Antitrust correspondence

7906070001 Notice of appearance of MD Berger on behalf of DOJ
Certificate of Svc and
BERGER, M D Justice Dept of 79/06/10 4pp

7906870217 Answer of TS Util Co & subsidiaries to Central Power &
Light's first set of Interrogatories & request for
production of documents Affidavit & Certificate of Sw. each
HONGHAI J I, GANFELD H O Morham Forsythe & Gansels 79/03/28
16aa

7906600330 TX Utils Generating Co discovery reqst for Mar 1979
 response to interogatories & document requests from NRC.
 City of Brownsville & Central Power & Light & submitted
 response to NRC motion to compel M/Certificates of Dye
 HMDTTS, J B Scheviele & Lisherman 79/04/05 Rec

7906080255 Supplemental answers by TE Utility Generating Co & subsidiaries in first set of interrogatories & request for production of documents from DOJ Supporting documentation & Certificate of Sec mail
MORRIS, J. I. - SANFELIX, H. D. Wersham, Forsythe & Sampson AMOTS, J. O.
Dehewise & Lieberman. 79/04/15. 40cc

7903040417 Request by Newton Lighting & Power for extension until 790430, for filing replies to motions for summary disposition Certificate of Div and
BARNETT, E W Oaker & Bates EDUARD, J A - FRANKLIN, W J
Lorenstein, Newman, Reis, Aschard & Tall 79/04/11 See

7906050129 Response by DOJ to various motions of Houston Lighting & Power, T2 Utility Generating Co & City of Austin Supporting documentation & Certificate of Evc encl
HARRIS, J L - BERGER, M D - CLARK, N H Justice-Dept of 79/04/23
4066

7906040136 Forwards answer by Tse-La Electric Cooperative, Inc. to TX
Utility Generating Co. re: sudden de-energizing Central & South West
Corp. as per its interconnect. in alternative for summary
disposition Certificate of Elec. util.
BUTTS, R. W. Northridge, Ede. 7906040136 Doc.

--7906040150 Forwarded answer by Tex-La Electric Cooperative, Inc to Tex
Utiles Generating Co motion to dismiss Central & South West
Corp as party intervenor, et al alternative for summary
disposition
RITTS, F H Northwest Etw 79/06/20 In

==7906484154 Request by Tea-La Electric Cooperative for denial of motion
by TE Utility Generating Co to dismiss Central & South West
Corp as party intervenor, or in alternative, for summary
disposition
RITTS, F W Northwest Kix 79/04/23 Doc

7906040434 Series 790405 motion filed by Public Utility Board of City of
Brownsville, TX to compel further production of documents by
South TX Electric Cooperative & Hedden Cooperative
MILLER, H E Atomic Safety and Licensing Board Panel 790604023
22x

79C102009 Add responses by Houston Lighting & Power to EQJ first set of interrogatories & request for production of documents
Certificate of Doc and
COPCLAM, J O Baker & Batta 79/04/27 3100

7906190034 Forwarded second supplemental answer of 13 Utility Generating Co to DOJ first interrogatories & requests for production of documents, forwarded per 790618 meeting
M. KAPLAN, M. V. Meehan, Kenneth A. Hargis, 79-004-003, 40

--7706190043 Second supplemental answer by TX Utils Generating Co to DOJ
First interrogatories & requests for production of
documents Supporting documentation & Certificate of Due
diligence
MORRISMAN, I., SAWYER, N D Norham, Forsythe & Sampels HNOTTS, J D
Behavens & Liebman 79/04/22 2504

7906030819 Response by Public Utility Board of City of Brownsville, TX to
Central Power & Light Co first set of interrogatories &
request for production of documents (Certificate of New and)
JAILSON, R A, Nieves & McDiarmid 79/08/30 23ss

7904020163 Answer in opposition to Houston Lighting & Power motion to
compel NRC production of privileged documents Certificate of
Dvt encl
LENNAR, BLUMEN Anti-Trust Division 79/04/20 10ap

7906020069 Response by Houston Lighting & Power to NEC 790419 motion
for reconsideration of AMLD 790419 order Requests that AMLD
affirms order re creation of new documents not maintained in
normal course of business Certificates of Doc and
Bourneight, J. A., FRANKLIN, W. J. Lowenstein, Newman, Reis, Aronson & Tall
BARNETT, E. W. Baker & Butte 79/04/20 11pg

7906020290 Reply by TX Utils Generating Co to combined answer of
Central Power & Light & Central & Southwest in opposition to
former's 790403 motion to dismiss Central & Southwest as
intervenor W/ pertinent documentation & Certificate of Env
PHOTTS, J B Bebevoise & Lieberman NORRMAN, J L, BARRELL, K D
Horsman, Forsythe & Sampels 79/04/30 Snp

7904190054 Discovery progress report for Aer 1979 Responded to TC Utility
Generating Co & Houston Lighting & Power Interrogatories Net
w/utills on 790419 Certificate of Gvc encl
HARRIS, J L. BERGER, H O. CLARK, R H Justice: Dept of 79/04/20
Auc

7904200299 Forward Public Utility Boards of City of Brownsville, TX
response to Houston Lighting & Power Co first set of
interrogatories & first request for production of documents
Affidavit & Certificate of Due and
WHITE, R C Spiegel & McDermid 79/03/02 dpp

DOCKETED ITEMS

---7904200500 Public Utility Board of Brownsville responds to Houston Lighting & Power Co. first interrogatories & first request for production of documents
JABLON, R. A. Spiegel & McDermott 7/9/05/02 11pp

7904200505 TX Utility Generating Co answers to Central Power & Light 7904200505 Co. compel further responses to letter interrogatories previously supplied answers are complete & satisfactory demands by Central Power are redundant
KORRIG, J. B. Debevoise & Lieberman EDWARDS, J. A. Lounsbury, N. H. Reiss, A. J. T. 7/9/05/02 11pp

7904200506 Discovery status report for Apr 1979 HRC filed answer in opposition to motion of Houston Lighting & Power Co. to compel production of privileged documents
LEDSB, R. P. Anti-Trust Division 7/9/05/03 3pp

7904200507 TX Utility Generating Co discovery progress report for Apr 1979 responded to interrogatories from DOJ w/ US&A & HRC & answered to coordinate remaining discovery w/ City of Brownsville, TX Certificate of Doc and
KORRIG, J. B. Debevoise & Lieberman EDWARDS, J. A. Lounsbury, N. H. Reiss, A. J. T. 7/9/05/04 3pp

7904200508 South TX Electric Cooperative & Mexico Electric Cooperative monthly discovery report for Apr 1979 as now discovery requests initiated or received during month
JABLON, R. A. Spiegel & McDermott 7/9/05/04 4pp

7904200509 Responses by Houston Lighting & Power to Central Power & Light 7904200509 motions to compel answers to interrogatories. Provides info re preparation of previous answers Certificate of Doc and
BARNETT, E. W. Baker & Bette 7/9/05/07 10pp

7904200510 Rules an discovery in response to HRC 7904200510 motion for production of documents & compelling order re protection of settlement documents & existing Houston Lighting & Power from producing certain documents
MILLER, H. E. Atomic Safety and Licensing Board Panel 7/9/05/07 2pp

7904200511 Requested request for will supplemental production of technical documents
BLUME, R. B. Anti-Trust Division 7/9/05/08 1p

7904200512 Answer by Public Utility Board of City of Brownsville, TX to 7904200512 motions by Gulf States Util Co re compliance w/ HRC's discovery demands because they are supporting documentation & Certificate of Doc and
MCDERMOTT, R. C. & P. Spiegel & McDermott 7/9/05/10 90pp

7904200513 Answer in opposition to Gulf States Util 7904200513 motion for protective order & for order setting conditions for compliance w/ 7904200513 subpoena for production of documents Certificate of Doc and
MURKIN, J. L. Justice Dept 7/9/05/11 10pp

7904200514 Notice of appearance by SE Cuyler & RH Clark on behalf of DOJ Certificate of Doc and
CUMMINGS, E. B. & CLARK, R. H. Justice Dept 7/9/05/11 3pp

7904200515 Houston Lighting & Power Co petition for extension until 7904200515 to compel further responses from Public Utility Board of City of Brownsville, TX. Addressing request to determine scope of planned motion Certificate of Doc and
KORRIG, J. B. Debevoise & Lieberman EDWARDS, J. A. Lounsbury, N. H. Reiss, A. J. T. 7/9/05/11 3pp

7904200516 Answers filed set of interrogatories & request for production of documents submitted by TX Utility Generating Co. Includes documentation & Certificate of Doc and
LEDSB, R. P., BLUME, R. B. Anti-Trust Division 7/9/05/14 10pp

7904200517 Notice of 7904200517 conference in Richmond, MD to discuss pending motions & responses re discovery & summary judgment
MILLER, H. E. Atomic Safety and Licensing Board Panel 7/9/05/15 3pp

7904200518 Motion by Houston Lighting & Power to include Central Power & Light within scope of 7904200518 protective order setting terms for production of confidential documents to Public Utility Board of City of Brownsville, TX. Certificate of Doc and
BARNETT, E. W. Baker & Bette EDWARDS, J. A. Lounsbury, N. H. Reiss, A. J. T. 7/9/05/15 2pp

7904200519 Motion by Gulf States Util Co to file brief in reply to DOJ & City of Brownsville, TX answers to previous motion & supplemental motion for protective order. Seeks to clarify third party status.
MCDERMOTT, R. C. & P. Spiegel & McDermott 7/9/05/16 7pp

7904200520 Grants Houston Lighting & Power Co. 7904200520 motion for extension of time until 7904200520 for filing motion to compel further production from City of Brownsville, TX
MILLER, H. E. Atomic Safety and Licensing Board Panel 7/9/05/16 1p

7904200521 Requests HRC order & HRC documents be added to NYC list
MILLER, H. E. Atomic Safety and Licensing Board Panel 7/9/05/16 1p

7904200522 All Houston Lighting & Power confidential documents produced for Public Utility Board of City of Brownsville, TX & returned by Central Power & Light, shall be subject to terms & conditions of 7904200522 protective order
MILLER, H. E. Atomic Safety and Licensing Board Panel 7/9/05/18 1p

7904200523 Grants Gulf States Util 7904200523 motion requesting leave to file reply brief in response to DOJ & City of Brownsville, TX answers to DOJ request for protective order
MILLER, H. E. Atomic Safety and Licensing Board Panel 7/9/05/18 1p

7904200524 TX Utility Generating Co discovery report for May 1979 w/ provided supplementary responses to HRC interrogatories & requests for production of documents Certificate of Doc and
KORRIG, J. B. Debevoise & Lieberman EDWARDS, J. A. Lounsbury, N. H. Reiss, A. J. T. 7/9/05/18 3pp

8 Inspection reports, IF Bulletins & correspondence

7904200525 Forwards IE Insp Repts 50-445/70-08 & 50-446/70-08 to 7904200525 No noncompliance noted
SEDFIELD, R. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch 7/9/05/17 2pp

---7904200526 IE Insp Repts 50-445/70-08 & 50-446/70-08 to 7904200526 No noncompliance noted. Major areas inspected observation of work & review of OR documentation re schedule placement in containment bldg & safety injection via sheet valves
SEDFIELD, R. V. Region 4, Dallas, Office of the Director 7/9/05/17 2pp

7904200527 Forwards IE Bulletin 79-050, "Nuclear Incident at TR-Boyle" - No written response required
SEDFIELD, R. V. Region 4, Dallas, Office of the Director 7/9/05/21 1p

7904200528 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Elevation Support Problem" - No action required
SEDFIELD, R. V. Region 4, Dallas, Office of the Director 7/9/05/21 1p

7904200529 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assembly" -
SEDFIELD, R. V. Region 4, Dallas, Office of the Director 7/9/05/21 1p

7904200530 Forwards IE Bulletin 79-11, "Facility Government Trip Device in Circuit Breakers for Engineered Safety Sys." - License action required
SEDFIELD, R. V. Region 4, Dallas, Office of the Director 7/9/05/22 1p

7904200531 Receipt of 7904200531 for informing HRC of steps taken to correct violations noted in IE Insp Repts 50-445/70-08 & 50-446/70-08
SEDFIELD, R. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch 7/9/05/22 1p

---7904200532 Responses to HRC ltr re violations noted in IE Insp Repts 50-445/70-08 & 50-446/70-08. Corrective actions implemented: use of supplemental water from Steam Crank Reservoir
SEDFIELD, R. V. Texas Utilities Generating Co 7/9/05/27 2pp

8 Reportable documents, LTRs & related correspondence

7904200533 Notifies that evaluation of reactor vessel nozzle weld metal defects in continuing will be informed of satisfaction when reached
SEDFIELD, R. V. Texas Utilities Generating Co 7/9/05/16 1p

7904200534 Forwards 790-79-670H
SEDFIELD, R. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch 7/9/05/16 1p

7904200535 Forwards 790-79-670H
SEDFIELD, R. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch 7/9/05/16 1p

DOCKETED ITEMS

1

1904080250 Forwards PHO-79-4740
RECEIVED C Region 4, Dallas: Reactor Construction & Engineering
Support Branch 7/9/82 1p

790410031 Forwards PHO-79-4740
RECEIVED C Region 4, Dallas: Reactor Construction & Engineering
Support Branch 7/9/82 1p

790410030 Informs of RO of apparent weld metal defects in shop weld
between Unit 1 reactor pressure vessel hot leg nozzle C &
safe-end investigation continuing
GARY, R J Texas Utilities Generating Co 7/9/82 3p

790410009 Notifies that 1981-82 2,300 MW installation pipe supports
may not meet seismic requirements. Condition may be
reportable investigation continuing
GARY, R J Texas Utilities Co 7/9/82 1p

790410024 Receives 790502 verbal rep to RO Taylor that pipe wall
thickness requirements on project piping specs may not be
adequately conservative to meet ASME Code stress
requirements. Investigation & evaluation continue
GARY, R J Texas Utilities Generating Co 7/9/82 1p

T Hearing transcripts on non-Affidavit matters

790410011 Transcripts of 790502 prehearing conference in Glen Rose, TX
Pg 1-133
GIBBS, E J, GILLES, R F, ROSENBLUTH, L Atomic Safety and Licensing
Board Panel 7/9/82 12pp

790410013 Transcript of 790601 hearing in Bethesda, MD Pg 213-471
ROSENBLUTH, L, GILLES, R J Atomic Safety and Licensing Board Panel
7/9/82 25pp

DOCKET 90-446 COWHAYE PEAK STEAM ELECTRIC STA., UNIT 2
A Applicant/Construction stage documents & correspondence

790405044 Summary report to Unit 2 pressure vessel misplacement caused
by combined factors, including inadequate communication of
existing design criteria to designers & breakdown in vendor
drawing review between Gibbs & Hill & Westinghouse
GARY, R J Texas Utilities Generating Co 7/9/82 3pp

790405019 Summary of 790327 meeting w/Unit in Bethesda, MD to discuss
repair of reactor vessel support pedestal for Unit 2
BURNELL, B J Light Water Reactors Branch 2 7/9/82 4pp

790405020 Summary of 790428 meeting w/Unit in Bethesda, MD re
status of & applicant plans for control of exclusion area
BURNELL, B J Light Water Reactors Branch 2 7/9/82 4pp

790405010 Forwards requests for add info required to complete
evaluation of application for Unit 2
GARY, R J Light Water Reactors Branch 2 7/9/82 20pp

790410003 Forwards 790501 update of PWR info re natural gas & oil
wells surrounding facility site
FEIST, C K Texas Utility Services, Inc 7/9/82 1p

--790410012 Updates FEAR info re natural gas & oil wells in vicinity of
nuclear facility. Overlaid drawing sent
HILLER, C H J Gray & Associates, Inc 7/9/82 10pp

790405022 Requests amend to CRR-126 & 127 be authorized withdrawal of
groundwater during construction for add gen Bunkie prepaqs
to obtain TE cost well data & for re evaluation of planned
treatment facility Amend Fee & Use overlaid map sent
GARY, R J Texas Utilities Generating Co 7/9/82 30pp

O Adjudicatory correspondence

790410004 Confirms 790408 meeting in Arlington, TX to discuss
contaminants re facility. Requests proposed conditions be
forwards before meeting
CHARNICK, L J Branch 1 7/9/82 1p

790405023 Supply to petition to intervene. Add conditions re cost of
plant Affidavits & Certificate of Use sent
POLAK, N L, JACOBSON, H H Citizens for Fair Utility Regulation
7/9/82 2pp

790405024 Supply to petition to intervene & listing of
contaminants.
ELLIS, J Citizens Association for Sound Energy 7/9/82 8pp

790405004 Supply to amended petition of Intervenor Association of
Community Organizations for Reform. New & C Bishop & O & W
Add Links & provide books for safety & avirous
contaminant Affidavits & Certificate of Use sent
GARY, R J West Texas Legal Services 7/9/82 30pp

790407029 Dallas 790406 action by Association of Community
Organizations for Reform. New & West TX Legal Svcs for
continuation of prehearing conference & filing conditions
304785 C 8 Atomic Safety and Licensing Board Panel 7/9/82 2pp

790405003 Memo by applicants re interest & contentions of petitioners
by petitioners re intervenor status on valid
conditions necessary to support intervention in proceeding
Certificate of Use sent
ROSENBLUTH, L, GILLES, R J 7/9/82 17 10pp

790405020 Recommend intervenor status be granted to all petitioners
Intervenor conditions should be consolidated. Drafts
acceptable condition re adequacy of facility cost
Certificate of Use sent
CHARNICK, L J Branch 1 7/9/82 17 3pp

790410117 Tune for AGC to elect to review ALAD-535 & ALAD-539
extended until 7/9/82
CHARNICK, L J Office of the Secretary of the Commission 7/9/82 1p

790405044 Memo by applicants re significance of ALAD-549 in
proceeding. Association's standing doctrine has been
misapplied to organizations seeking standing through people
who are not members. Certificate of Use sent
ROSENBLUTH, L, GILLES, R J 7/9/82 17 10pp

K Utility Final Safety Analysis Report (FSAR) & amendments

790410020 Forwards Amend & to FSAR Affidavit sent
GARY, R J Texas Utilities Generating Co 7/9/82 3pp

--790410021 Amend & to FSAR
to Texas Utilities Generating Co 7/9/82 1 60pp

790410023 Forwards Affidavit of Use for Amend & to FSAR
FEIST, C K Texas Utility Services, Inc 7/9/82 3pp

H Antitrust correspondence

790407011 Notice of appearance of NG Berger on behalf of DOJ
Certificate of Use sent
BERGER, N J Justice Dept of 7/9/82 1p

790407011 Answer of TX Unit Co & subsidiaries to Central Power &
Light's first set of interrogatories & request for
production of documents Affidavit & Certificate of Use sent
WORTHMAN, J J, GARNER, M H Worthman, Forsythe & Searles 7/9/82 20 1pp.

790404030 TX Utility Generating Co discovers report Mar 1979
regarding re interrogatories & documents requests from HEC,
City of Brownsville & Central Power & Light & submitted
response to HEC motion to compel W/Certificates of Use
WORTHMAN, J J, GARNER, M H 7/9/82 20 1pp

790405028 Supplemental answers by TX Utility Generating Co &
subsidiaries to first set of interrogatories & request for
production of documents from DOJ Supporting documentation &
Certificate of Use sent
WORTHMAN, J J, GARNER, M H Worthman, Forsythe & Searles 7/9/82 1 60pp

790404017 Request by Houston Lighting & Power for extension until
790405 for filing replies to motions for summary
disposition Certificate of Use sent
BARNETT, C H Baker & Roberts, BARNETT, J A, FRANKLIN, W J
Louisiana, Houston, Texas, Acacia & Tull 7/9/82 1 1pp

790405028 Responses by DOJ to various motions of Houston Lighting &
Power, TX Utility Generating Co & City of Austin Supporting
documentation & Certificate of Use sent
WORTHMAN, J J, BERGER, N J, CLARK, R H Justice Dept of 7/9/82 20 60pp

790404024 Forwards answers by Tex-Lu Electric Cooperative, Inc to TX
Utility Generating Co motion to dismiss Central & South West
Corp as party Intervenor, or in alternative for summary
disposition Certificate of Use sent
WORTHMAN, J J 7/9/82 20 1pp

- 77004040130 Forwards answer by Tera Electric Cooperative, Inc. to TX Utility Generating Co motion to dismiss Central & South West Co's ex parte intervention, or, in alternative, for summary disposition
BETTS, F H Northcutt Ely 7/9/04/23 1p
- 77004040134 Request by Tera Electric Cooperative for denial of motion by TX Utility Generating Co to dismiss Central & South West Co's ex parte intervention, or, in alternative, for summary disposition
BETTS, F H Northcutt Ely 7/9/04/23 3pp
- 77004040138 Denies 7700403 motion filed by Public Utility Board of City of Brownsville, TX to compel further production of documents by South TX Electric Cooperative & Houston Lighting & Power
MILLER, H E Atomic Safety and Licensing Board Panel 7/9/04/23 2pp
- 77004050009 Adds responses by Houston Lighting & Power to DOJ first set of interrogatories & request for production of documents
Certificate of Doc encl
COPPELAND, J B Baker & Batts 7/9/04/27 3pp
- 77004050034 Forwards second supplemental answer of TX Utility Generating Co to DOJ first interrogatories & requests for production of documents forwarded per 7700403 meeting
BETTS, F H Northcutt Ely 7/9/04/27 1p
- 77004050043 Second supplemental answer by TX Utility Generating Co to DOJ first interrogatories & requests for production of documents Supplementing documents & Certificate of Doc encl
WORMAN, J L, SAMPFELS, H D Northcutt Ely & Batts 7700403/27 3pp
- 77004050043 Answer by Public Utility Board of City of Brownsville, TX to Central Power & Light Co first set of interrogatories & request for production of documents Certificate of Doc encl
WORMAN, J L Spiegel & McDaniel 7/9/04/20 20pp
- 77004050063 Answer in opposition to Houston Lighting & Power motion to compel HRC production of privileged documents Certificate of Doc encl
LEDDY, E P, BLUM, H B Anti-Trust Division 7/9/04/30 10pp
- 77004050069 Response by Houston Lighting & Power to HRC 7700403 motion for reconsideration of ASLR 7700403 order Requests that ASLR affirm order re creation of new documents not maintained in its course of business Certificate of Doc encl
BARNETT, E W, FRANKLIN, J A, LOUWENTRIN, H M, Rabinowitz, J & Telford 7700403/27 10pp
- 77004050080 Reply by TX Utility Generating Co to combined answer of Central Power & Light Co Central & SouthWest in opposition to former's 7700403 motion to dismiss Central & SouthWest as intervenor
MILLER, H E Atomic Safety and Licensing Board Panel 7/9/04/23 10pp
- 77004050084 Discovery progress report for Apr 1979 Responded to TX Utility Generating Co & Houston Lighting & Power interrogatories met
MILLER, H E Atomic Safety and Licensing Board Panel 7/9/04/20 4pp
- 77004050099 Forwards Public Utility Board of City of Brownsville, TX responses to Houston Lighting & Power Co first set of interrogatories & first request for production of documents Affidavit & Certificate of Doc encl
WILLIAMS, J Spiegel & McDaniel 7/9/05/02 4pp
- 77004050090 Public Utility Board of Brownsville response to Houston Lighting & Power Co first interrogatories & first request for production of documents
WILLIAMS, J Spiegel & McDaniel 7/9/05/02 11pp
- 77004050097 TX Utility Generating Co answer to Central Power & Light 7700403 motion to compel further responses to latter's interrogatories Forwards supplemental answers are complete & satisfy all demands by Central Power & Light
MILLER, H E Atomic Safety and Licensing Board Panel 7/9/05/02 4pp
- 77004050097 Discovery status report for Apr 1979 HRC filed answer in opposition to motion of Houston Lighting & Power Co to compel production of privileged documents
- 77004050102 TX Utility Generating Co discovery progress report for Apr 1979 responded to interrogatories from DOJ, HRC & HRC 6 answered to HRC's remaining discovery w/ City of Brownsville TX Certificate of Doc encl
MILLER, H E Atomic Safety and Licensing Board Panel 7/9/05/04 3pp
- 77004050091 South TX Electric Cooperative & Houston Electric Cooperative monthly discovery report for Apr 1979 on new discovery requests initiated or returned during month
MILLER, H E Atomic Safety and Licensing Board Panel 7/9/05/04 4pp
- 77004050140 Response by Houston Lighting & Power to Central Power & Light 7700403 motion to compel answers to interrogatories Provides info re preparation of previous answers Certificate of Doc encl
BARNETT, E W Baker & Batts 7/9/05/07 10pp
- 77004050143 Replies on discovery, in response to HRC 7700403 motion for reconsideration of ASLR 7700403 order Which order re production of settlement documents & existing Houston Lighting & Power from producing certain documents
MILLER, H E Atomic Safety and Licensing Board Panel 7/9/05/07 2pp
- 77004050050 Second request for still supplemental production of confidential documents
BLUM, H B Anti-Trust Division 7/9/05/08 1p
- 77004050037 Answer by Public Utility Board of City of Brownsville, TX to 7700403 & 7700403 motions by Gulf States Utility re compliance w/770020 subpoena duces tecum from ASLR Supplementing documents & Certificate of Doc encl
MILLER, H E Atomic Safety and Licensing Board Panel 7/9/05/10 10pp
- 77004050037 Answer in opposition to Gulf States Utility 7700403 motion for reconsideration of ASLR 7700403 order Which order re compliance w/770020 subpoena for production of documents Certificate of Doc encl
MILLER, H E Atomic Safety and Licensing Board Panel 7/9/05/11 10pp
- 770040500167 Notices of appearance by RD Copher & RH Clark on behalf of DOJ Certificate of Doc encl
COPHER, R B, CLARK, R H Justice Dept. of 7/9/05/11 5pp
- 77004050026 Houston Lighting & Power Co petition for rehearing until 7700420 to compel further responses from Public Utility Board of City of Brownsville, TX added time required to determine scope of planned motion Certificate of Doc encl
FRANKLIN, J A, LOUWENTRIN, J A, LOUWENTRIN, H M, Rabinowitz, J & Telford 7700403/27 10pp
- 77004050147 Answer first set of interrogatories & request for production of documents submitted by TX Utility Generating Co Supplementing documents & Certificate of Doc encl
LEDDY, E P, BLUM, H B Anti-Trust Division 7/9/05/14 10pp
- 77004050012 Notice of 7700401 conference in Bethesda, MD to discuss pending motions & responses re discovery & summary disposition
MILLER, H E Atomic Safety and Licensing Board Panel 7/9/05/15 8p
- 77004050109 Motion by Houston Lighting & Power to include Central Power & Light within ASLR 7700403 protective order setting terms for production of confidential documents to Public Utility Board of City of Brownsville, TX Certificate of Doc encl
BARNETT, E W Baker & Batts LOUWENTRIN, J A LOUWENTRIN, H M, Rabinowitz, J & Telford 7700403/27 10pp
- 77004050046 Motion by Gulf States Utility Co to file brief in reply to DOJ & City of Brownsville, TX answers to previous DOJ motion & supplemental motion for protective order seeks to clarify third party status
MILLER, H E Atomic Safety and Licensing Board Panel 7/9/05/16 7pp
- 77004050015 Grants Houston Lighting & Power Co 7700401 motion for extension of time until 7700420 for filing motion to compel further production from City of Brownsville, TX
MILLER, H E Atomic Safety and Licensing Board Panel 7/9/05/16 1p
- 77004050124 Requests RM Rader & ON Clements be added to doc list
BARNETT, E W, CLARK, R H, CLARK, R H 7/9/05/16 1p
- 77004050066 All Houston Lighting & Power confidential documents produced for Public Utility Board of City of Brownsville, TX & returned by Central Power & Light, shall be subject to terms & conditions of protective order
C Safety and Licensing Board Panel 7/9/05/18 8p

DOCKETED ITEMS

15

790601018 Drafts Gulf States Util 790606 action requesting leave to file reply brief in response to DOE & City of New Orleans. TX answers to still request for protective order MILLER, H E Atomic Safety and Licensing Board Panel 79/05/22 1p

790601050 TE Utila Generating Co discovery report for May 1979 still provided supplementary responses to NRC interagency requests & requests for production of documents Certificate of Review 610778 J B Dubovick & Lieberman 79/06/06 3pp

G Inspection reports, IE Bulletin & correspondence

790602079 Forwards IE Insp Rpts 90-442/79-05 & 90-444/79-05 on 790602-29 No noncompliance noted SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/17 3pp

790602084 IE Insp Rpts 90-445/79-05 & 90-446/79-05 on 790602-29 No noncompliance noted Major areas inspected observation of review & review of documentation re concrete placement in containment sump & safety injection air check valves. EPIA, J L, TAYLOR, R O, & HALL, R E Region 4, Dallas, Office of the Director 79/06/17 3pp

790602079 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem". No action required SEYFRIED, K V Region 4, Dallas, Office of the Director 79/05/07 1p

790602087 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assembly". SEYFRIED, K V Region 4, Dallas, Office of the Director 79/05/11 1p

790602073 Forwards IE Bulletin 79-13, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys". License action required SEYFRIED, K V Region 4, Dallas, Office of the Director 79/05/22 1p

790602088 Ack receipt of 790617 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpts 90-445/79-05 & 90-446/79-05 SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/12 1p

790602083 Responses to NRC ltr re violations noted in IE Insp Rpts 90-445/79-05 & 90-446/79-05 Corrective actions implementation of use of supplemental water from Square Creek Reservoir GALT, J D Texas Utilities Generating Co 79/05/17 3pp

8 Reportable occurrences, LRS & related correspondence

790602087 Notifies that evaluation of reactor vessel nozzle weld metal defects in containment NRC will be informed of conclusion after reached GALT, J D Texas Utilities Generating Co 79/06/16 1p

790602083 Forwards PHO-79-0785, SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/08 1p

790602084 Forwards PHO-79-0786, SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/16, 1p.

790602085 Forwards PHO-79-0787, SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/22 1p

790602083 Forwards PHO-79-0788, SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/22 1p

790602088 Inform of 86 of apparent weld metal defects in shop weld between Unit 3 reactor pressure vessel and leg nozzle C & safe-end investigations continuing GALT, J D Texas Utilities Generating Co 79/06/08 1p

790602089 Notifies that 1901-83 2,300 MM installation pipe supports may not meet seismic requirements Condition may be reportable investigation continuing GALT, J D Texas Utilities Generating Co 79/06/15 1p

790602088 Receives 790622 verbal report to NG Taylor that pipe weld thickness requirements in present piping specs may not be adequate conservative to meet ASME code stress requirements investigation & evaluation continue GALT, J D Texas Utilities Generating Co 79/06/18 1p

Y Hearing transcripts on non-safety matters

790602011 Transcript of 790522 prehearing conference in Glen Rose, TX Pg 1-133 BOMBO, C D, COLLE, F, & KOSHELITZ, L Atomic Safety and Licensing Board Panel 79/05/22 133pp

790602030 Transcript of 790601 hearing in Belvidere, MO Pg 213-471 MILLER, H E, & WELFE, S J Atomic Safety and Licensing Board Panel 79/06/01 363pp

DOCKET 90-432 SHEPPARD ENERGY CENTER, UNIT 2

A Application/construction stage documents & correspondence

790602077 Discusses reactivation of civilian review of CP application. Forewarns proposed outline of "Need for the Plant" section of FES report. GALLAGHER, E J, Environmental Projects Branch 1 79/05/23 4pp

B NRC Draft/Final Environmental Statements, suppl & correspondence

790602084 Ack receipt of 790523 memo Requests copy of preliminary DSS & opportunity to review statement. MILLER, H E Michigan, State of 79/06/06 1p

DOCKET 90-433 SHEPPARD ENERGY CENTER, UNIT 3

A Application/construction stage documents & correspondence

790602077 Discusses reactivation of civilian review of CP application. Forewarns proposed outline of "Need for the Plant" section of FES report. GALLAGHER, E J, Environmental Projects Branch 1 79/05/23 4pp

B NRC Draft/Final Environmental Statements, suppl & correspondence

790602084 Ack receipt of 790523 memo Requests copy of preliminary DSS & opportunity to review statement. MILLER, H E Michigan, State of 79/06/06 1p

DOCKET 90-434 SYNERGIZATION, UNIT 1

A Application/construction stage documents & correspondence

7906050125 Supports part of motion requesting ARLI schedule prehearing conference Opposes contention in motion that sufficient time has been allowed for preparation Certificate of Doc. No. JONES, D C League of Women Voters of Maryland, IL 79/04/23 2pp

7906020128 Confirms 790523 meeting w/att in Dian Elgin, IL to discuss line findings re cement activities. MILLER, H E Region 3, Chicago, Office of the Director 79/05/08 1p

7906020126 Forwards specific requests for info re review of CC application Covers areas of review performed by various NRC branches Auxiliary Sys, Power Sys, Mechanical Engineering, Structural Engineering, QA & Effluent Treatment Sys. VORSH, R A Light Water Reactors Branch 4 79/05/15 77pp

B Adjudicatory correspondence

7906020445 Requests clarification of procedures necessary to be adopted as petitioner at prehearing conference. JONES, D C League of Women Voters of Rockford, IL 79/04/06 2pp

7906020124 Responds in support of applicant 790610 motion requesting scheduling of special prehearing conference Conference should be scheduled at earliest convenient date Certificate of Doc. No. JONES, D C Branch 2 79/05/01 4pp

G Inspection reports, IE Bulletin & correspondence

790602084 Forwards IE Insp Rpts 90-454/79-05 & 90-455/79-05 on 790602-0233 No noncompliance noted FIORELLO, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/06 3pp

790602087 IE Insp Rpts 90-454/79-05 & 90-455/79-05 on 790602-23 Hs noncompliance noted Major areas inspected, hanger installation & related hanger procedures & records & concrete anchor installation. GALLAGHER, E J, GUTTMANN, J F, & HATTE, D W Region 3, Chicago, Office of the Director 79/05/23 7pp

DOCKETED ITEMS

7904250132 Forwards EE Insp Repts 50-454/79-06 & 50-455/79-06 on 790404-11 & notice of violation
FIORELLI, J G Region 3, Chicago, Office of the Director 79/04/20 2pp

7904250134 Notice of violation from Insp on 790404-11
a Region 3, Chicago, Office of the Director 79/04/18 1p

7904250141 EE Insp Repts 50-454/79-06 & 50-455/79-06 on 790404-11
Noncompliance noted inadequate storage of piping
concentrations
RMP, R C, O'ALLAGHER, E J, HAWKINS, J E Region 3, Chicago,
Office of the Director 79/04/18 13pp

7904250282 Forwards EE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Support Problem" No action required
HEFFLER, J G Region 3, Chicago, Office of the Director 79/05/07 1p

7904250241 Responds to EE Bulletin 79-02 Requests 90-day extension
to review present use of ASME SA-512 Type 304 pipe spools
NEEDS C Commonwealth Edison Co 79/05/08 2pp

7904250270 Forwards EE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies" No action required
HEFFLER, J G Region 3, Chicago, Office of the Director 79/05/11 1p

7904250282 Forwards EE Bulletin 79-11, "Faulty Overcurrent Trip Device
in Circuit Breaker for Engineered Safety Sys" License
action required
HEFFLER, J G Region 3, Chicago, Office of the Director 79/05/22 1p

7904250280 Forwards EE Info Notice 79-13, "Indication of Low Water
Level in Outer Creek Reactor" No action required
HEFFLER, J G Region 3, Chicago, Office of the Director 79/05/29 1p

3 Reportable occurrences, LERs & related correspondence

7904250234 Ack receipt of 790419 final report re post-lansing
buttonhead deficiencies
FIORELLI, J G Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/05/09 1p

7904250284 Forwards Improc report, "Investigation of Buttonhead
Defects," in response to 790423 request W/O and
SCLC/ROD/EC, L G Commonwealth Edison Co 79/05/10 1p

DOCKET 50-455 SWORN STATEMENT, UNIT 2

A Application/construction stage documents & correspondence

7904250125 Reports part of motion requesting ASLB schedule preheating
conference discussion contention in motion that sufficient time
has been allowed for preparation Certificate of SW and
JANUS, S League of Women Voters of MacFarland, IL 79/05/23 2pp

7904250120 Confirms 790321 meeting w/Util in Glen Ellyn, IL to discuss
loop findings re cond activities
HEFFLER, J G Region 3, Chicago, Office of the Director 79/05/28 1p

7904250154 Forwards specific requests for info re review of CR
application. Covers areas of review performed by various
ASLB branches Auxiliary Sys, Power Sys, Mechanical Engineering,
Structural Engineering, QA & Efficient Treatment Sys
WMSL, S A Light Water Reactors Branch 4 79/05/15 77pp

3 Adjudicatory correspondence

7904250124 Responds in support of applicant 790418 motion requesting
scheduling of special preheating conference. Conference
should be scheduled at earliest convenient date Certificate
of SW and
SCLC/ROD/EC, L G Region 3 79/05/04 4pp

3 Inspection reports, EE Bulletin & correspondence

7904250104 Forwards EE Insp Repts 50-454/79-06 & 50-455/79-06 on
790321-3203 No noncompliance noted.
FIORELLI, J G Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/04/26 2pp

7904250132 EE Insp Repts 50-454/79-06 & 50-455/79-06 on 790321-3203
Noncompliance noted Reactor vessel head inspection hanger
installation & related hanger procedures & records & records
concrete anchor installation
O'ALLAGHER, E J, HAWKINS, J E Region 3, Chicago,
Office of the Director 79/04/20 2pp

7904250132 Forwards EE Insp Repts 50-454/79-06 & 50-455/79-06 on
790321-3203 & notice of violation
FIORELLI, J G Region 3, Chicago, Office of the Director 79/04/20 2pp

7904250134 Notice of violation from Insp on 790404-11
a Region 3, Chicago, Office of the Director 79/04/18 1p

7904250141 EE Insp Repts 50-454/79-06 & 50-455/79-06 on 790404-11
Noncompliance noted inadequate storage of piping
concentrations
RMP, R C, O'ALLAGHER, E J, HAWKINS, J E Region 3, Chicago,
Office of the Director 79/04/18 13pp

7904250282 Forwards EE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Support Problem" No action required
HEFFLER, J G Region 3, Chicago, Office of the Director 79/05/07 1p

7904250241 Responds to EE Bulletin 79-02 Requests 90-day extension
to review present use of ASME SA-512 Type 304 pipe spools
NEEDS C Commonwealth Edison Co 79/05/08 2pp

7904250270 Forwards EE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies" No action required
HEFFLER, J G Region 3, Chicago, Office of the Director 79/05/11 1p

7904250282 Forwards EE Bulletin 79-11, "Faulty Overcurrent Trip Device
in Circuit Breaker for Engineered Safety Sys" License
action required
HEFFLER, J G Region 3, Chicago, Office of the Director 79/05/22 1p

7904250280 Forwards EE Info Notice 79-13, "Indication of Low Water
Level in Outer Creek Reactor" No action required
HEFFLER, J G Region 3, Chicago, Office of the Director 79/05/29 1p

3 Reportable occurrences, LERs & related correspondence

7904250234 Forwards Improc report, "Investigation of Buttonhead
Defects," in response to 790419 final report re post-lansing
buttonhead deficiencies
FIORELLI, J G Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/05/09 1p

7904250284 Forwards Improc report, "Investigation of Buttonhead Defects"
and 790423, in response to 790423 request W/O and
SCLC/ROD/EC, L G Commonwealth Edison Co 79/05/10 1p

DOCKET 50-456 SWORN STATEMENT, UNIT 1

A Application/construction stage documents & correspondence

7904250120 Confirms 790321 meeting w/Util in Glen Ellyn, IL to discuss
loop findings re cond activities
HEFFLER, J G Region 3, Chicago, Office of the Director 79/05/28 1p

7904250154 Forwards specific requests for info re review of CR
application. Covers areas of review performed by various
ASLB branches Auxiliary Sys, Power Sys, Mechanical Engineering,
Structural Engineering, QA & Efficient Treatment Sys
WMSL, S A Light Water Reactors Branch 4 79/05/15 77pp

7904250124 Responds to 790418 request for info re preheating & preheating
portion of aquatic monitoring programs Approver proposed
note
SCLC/ROD/EC, L G Environmental Projects Branch 1 79/05/18 3pp

3 Adjudicatory correspondence

7904250124 Responds to applicant 790418 motion requesting scheduling of
special preheating conference at earliest possible date
Certificate of SW and
SCLC/ROD/EC, L G Region 3 79/05/04 4pp

G Inspection reports, IE Bulletin & correspondence

7904050022 Forwards IE Insp Repts 90-456/79-02 & 90-457/79-03 as 790313-0315 No noncompliance noted
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/04 2pp

7904050028 IE Insp Repts 90-456/79-02 & 90-457/79-03 on 790313-0315 No noncompliance noted Major areas inspected status of electrical contractors & respective IAW/DC programs Review of previously identified items of noncompliance
JONES, C E - ANSP-R C Region 3, Chicago, Office of the Director 79/04/04 4pp

7904120003 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/07 1p

7904070241 Responds to IE Bulletin 79-03 Requests 90-day extension to review present use of ASME BA-312 Type 304 pipe spools
REED, C Commonwealth Edison Co 79/05/08 3pp

7904100070 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/11 1p

7904130002 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/22 1p

7904200138 Forwards ASME response supporting still contention re welding of split backing rings in cast Requests NRC re-examine apparent noncompliance & consider changing infraction to observation
REED, C Commonwealth Edison Co 79/05/23 4pp

7904200020 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Outer Creek Reactor"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/29 1p

DOCKET 90-458 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

7904290050 Forwards specific requests for info re review of EL application Covers areas of review performed by various NRC Branches Aviation System/Program Mechanical Engineering, Structural Engineering, & Effluent Treatment Sys
VALLS, D A Light Water Reactors Branch 4 79/05/10 7pp

7904290056 Responds to 790409 request for info to fish eggs & larvae portion of aquatic monitoring programs Approves proposed mods
BAGLAND, R L Environmental Projects Branch 3 79/05/18 3pp

G Adjudicatory correspondence

7904300449 Requests clarification of procedures necessary to be applied to petitioner at preliminary conference
JOHNSON, B League of Women Voters of Rockford, IL 79/04/06 2pp

7904200420 Responds to applicant 790418 motion requesting scheduling of special prehearing conference at earliest possible date
Certificate of Doc and
KARNAM, H Branch 2, 79/05/04 4pp

F Operating license stage documents & correspondence

79043000130 Confirms 790501 meeting w/with in Glen Ridge, IL to discuss last findings re test activities
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/08 1p

G Inspection reports, IE Bulletin & correspondence

7904300020 Forwards IE Insp Repts 90-456/79-02 & 90-457/79-03 as 790313-0315 No noncompliance noted
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/04 2pp

7904300028 IE Insp Repts 90-456/79-02 & 90-457/79-03 on 790313-0315 No noncompliance noted Major areas inspected status of electrical contractors & respective IAW/DC programs Review of previously identified items of noncompliance
JONES, C E - ANSP-R C Region 3, Chicago, Office of the Director 79/04/04 4pp

7904120003 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/07 1p

7904070241 Responds to IE Bulletin 79-03 Requests 90-day extension to review present use of ASME BA-312 Type 304 pipe spools
REED, C Commonwealth Edison Co 79/05/08 3pp

7904100070 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/11 1p

7904130002 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/22 1p

7904200138 Forwards ASME response supporting still contention re welding of split backing rings in cast Requests NRC re-examine apparent noncompliance & consider changing infraction to observation
REED, C Commonwealth Edison Co 79/05/23 4pp

7904200020 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Outer Creek Reactor"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/29 1p

DOCKET 90-458 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

7904300040 Requests that preparatory portion of Gould, Inc qualification test w/with, "Accelerated Aging Procedure" be withdrawn & returned to utility for placement in PDB (ref ICRF 7901)
WEDBAND, J O Gulf States Utilities Co 79/04/06 1p

G Inspection reports, IE Bulletin & correspondence

7904300001 Forwards IE Bulletin 79-03B, "Nuclear Incident at Tri-Gen" No written responses required
SEFFERT, K V Region 4, Dallas, Office of the Director 79/04/21 1p

7904300045 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required
SEFFERT, K V Region 4, Dallas, Office of the Director 79/05/07 1p

7904300016 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
SEFFERT, K V Region 4, Dallas, Office of the Director 79/05/11 1p

7904300048 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Action required
SEFFERT, K V Region 4, Dallas, Office of the Director 79/05/22 1p

G Reportable occurrences, LERs & related correspondence

7904300005 Updates report re potential deficiency of cadwell sleeves Evaluation continues; issue not resolved at present; Update to follow within 30 days
BURNHURST, L L Gulf States Utilities Co 79/04/27 1p

79043000130 Forwards 790501 meeting w/with in Glen Ridge, IL to discuss last findings re test activities
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/08 1p

7904300020 Forwards IE Insp Repts 90-456/79-02 & 90-457/79-03 as 790313-0315 No noncompliance noted
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/04 2pp

DOCKETED ITEMS

7904180041 Forwards FHO-79-67AD
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/05/22 1p

7904180018 Forwards FHO-79-67AF
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/05/23 1p

7904180092 Notifies that deficiencies re: re-secured sleeves will be
completed within 30 days
MEISWHE, J. D. Gulf States Utilities Co 79/05/01 1p

DOCKET 50-45V RIVER BEID STATION, UNIT 2

A. Application/construction stage documents & correspondence

7904180004 Requests that proprietary portion of Guellet's qualification
re: suppl. "Accelerated Aging Procedures" be withdrawn &
returned to util w/o placement in FHO (ref 100582 7901).
MEISWHE, J. D. Gulf States Utilities Co 79/04/01 1p

D. Inspection reports, IE Bulletins & correspondence

7904180034 Forwards IE Bulletin 79-05B, "Nuclear Incident at
TMI-Supp 1" No action requested
SEIDLE, W. C. Region 4, Dallas, Office of the Director 79/04/21
1p

7904180045 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Support Problem" No action required
SEIDLE, W. C. Region 4, Dallas, Office of the Director 79/05/07
1p

7904180019 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies" SEIDLE, W. C. Region 4, Dallas, Office of the Director 79/05/11
1p

7904180045 Forwards IE Bulletin 79-11, "Facility Overcurrent Trip Device
in Circuit Breakers for Engineered Safety Sys" Action
required
SEIDLE, W. C. Region 4, Dallas, Office of the Director 79/05/23
1p

B. Reportable occurrences, LERs & related correspondence

7904180158 Forwards FHO-79-67AH
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/05/03 1p

7904180174 Forwards FHO-79-67AH
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/05/14 1p

7904180241 Forwards FHO-79-67AD
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/05/22 1p

7904180218 Forwards FHO-79-67AF
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/05/23 1p

DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

A. Application/construction stage documents & correspondence

7904060013 Approved amendment #111 of Aug 1980 for submittal of FMR &

D. Inspection reports, IE Bulletins & correspondence

7904020120 Forwards IE Insp Repts 80-440/79-03 & 50-513/79-03 on
790327-29 re noncompliance noted
SEIDLER, R. H. Region 3, San Francisco, Office of the Director
79/04/10 2pp

7904020137 IE Insp Repts 50-440/79-03 & 50-513/79-03 on 790327-29 re
noncompliance noted Major areas inspected re: activities,
training programs & miscellaneous open items
ALBERT, U. D. & HANWELL, R. C. Region 3, San Francisco, Office of the Director
79/04/13 4pp

7904180002 Responds to NEC 790021 re re violations noted in IE Insp
Repts 30-397/79-03, 30-440/79-04 & 50-513/79-04 Corrective
actions audit conducted Feb 1977 Deficient changes 83-405
will be removed & replaced properly
SEIDLER, R. H. Washington Public Power Supply System 79/04/20
3pp

7904180070 Re: receipt of 790420 re informing NRC of steps taken to
correct violations noted in IE Insp Repts 30-397/79-03,
50-440/79-04 & 50-513/79-04
SEIDLER, R. H. Region 3, San Francisco, Reactor Construction &
Engineering Support Branch 79/03/21 1p

7904180039 Forwards IE Insp Repts 30-397/79-03, 30-440/79-04 &
50-513/79-04 on 790321-02 & 10-13 re notice of violation
SEIDLER, R. H. Region 3, San Francisco, Reactor Construction &
Engineering Support Branch 79/03/21 2pp

7904180046 Notice of violation from Insp on 790321-02 & 10-13
Region 3, San Francisco, Reactor Construction & Engineering
Support Branch 79/03/21 2pp

7904180079 IE Insp Repts 30-397/79-03, 30-440/79-04 & 50-513/79-04 on
790321-02 & 10-13 Noncompliance noted Re: steps to respond
effectively to audit finding & failure to implement
effective Insp program
SEIDLER, R. H. & HANWELL, R. C. Region 3, San
Francisco, Reactor Construction & Engineering Support Branch
79/03/21 7pp

7904180057 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Support Problem" No action requested
SEIDLER, R. H. Region 3, San Francisco, Office of the Director
79/04/07 1p

7904180048 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies" No written response necessary
SEIDLER, R. H. Region 3, San Francisco, Office of the Director
79/05/10 1p

7904020023 Forwards IE Circular 79-06, "Attempted Extortion - Low
Enriched U"
SEIDLER, R. H. Region 3, San Francisco, Office of the Director
79/05/10 1p

7904180034 Forwards IE Bulletin 79-11, "Facility Overcurrent Trip Device
in Circuit Breakers for Engineered Safety Sys" License
action required
SEIDLER, R. H. Region 3, San Francisco, Office of the Director
79/05/22 1p

7904020041 Forwards IE Info Notice 79-13, "Indication of Low Water
Level in Quiescent Core Reactor"
SEIDLER, R. H. Region 3, San Francisco, Office of the Director
79/05/29 1p

B. Reportable occurrences, LERs & related correspondence

7904180021 Forwards FHO-79-67AH
SEIDLER, R. H. Region 3, San Francisco, Office of the Director
79/05/14 1p

7904180020 Forwards FHO-79-67AD
SEIDLER, R. H. Region 3, San Francisco, Office of the Director
79/05/21 1p

180331 Forwards FHO-79-67AF,
SEIDLER, R. H. Region 3, San Francisco, Office of the Director
7/05/22 1p

180331 Forwards FHO-79-67AD
SEIDLER, R. H. Region 3, San Francisco, Office of the Director
7/05/22 1p

DOCKET 90-441 CLINTON POWER STATION, UNIT 2

O Inspection reports, IE Bulletin & correspondence

790620701H Forwards IE Insp Reps 90-441/79-06 & on 790620-05 No compliance noted
Region 3, Chicago, Reactor Construction & Engineering
Reps 11 Branch 79/06/25 App

790620501B IE Insp Reps 90-441/79-04 on 790620-05 No compliance noted Major areas inspected procedures for removal & replacement of recirculation inlet safe ends (RSE) as reactor pressure vessel
GALLER, G E CBE, C H Region 3, Chicago, Office of the Director 79/04/25 App

790620111 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem - No action required"
KEPFLER, J D Region 3, Chicago, Office of the Director 79/05/07

79064004A Advises that response to IE Bulletin 79-33, "Longitudinal Weld Defects in ASME SA-312 Type 304 Stainless Steel Pipe Spools," will be submitted by 7/1/21
GALLER, G E Illinois Power Co 79/05/10 Ip

790610025 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
KEPFLER, J D Region 3, Chicago, Office of the Director 79/03/11 Ip

790620103 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys - Licensee action required"
KEPFLER, J D Region 3, Chicago, Office of the Director 79/05/03 Ip

790620125 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Outer Core Reactor"
KEPFLER, J D Region 3, Chicago, Office of the Director 79/05/09 Ip

DOCKET 90-442 CLINTON POWER STATION, UNIT 2

O Inspection reports, IE Bulletin & correspondence

790610011 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem - No action required"
KEPFLER, J D Region 3, Chicago, Office of the Director 79/05/07 Ip

79064004A Advises that response to IE Bulletin 79-33, "Longitudinal Weld Defects in ASME SA-312 Type 304 Stainless Steel Pipe Spools," will be submitted by 7/1/21
GALLER, G E Illinois Power Co 79/05/10 Ip

790610075 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
KEPFLER, J D Region 3, Chicago, Office of the Director 79/05/11 Ip

790610125 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys - Licensee action required"
KEPFLER, J D Region 3, Chicago, Office of the Director 79/05/02 Ip

DOCKET 90-443 CLINTON POWER STATION, UNIT 2

O Inspection reports, IE Bulletin & correspondence

790620125 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Outer Core Reactor"
KEPFLER, J D Region 3, Chicago, Office of the Director 79/05/09 Ip

DOCKET 90-443 PULMON GENERATING STATION, UNIT 1

O Adjudicatory correspondence

790620225 Requests by Save Balance Environ Conservation Fund that NRC order shell to show cause why application should not be terminated
SAGER, L Sager & Sager Associates 79/05/14 Tpp

790620035 Urges on behalf of Peach Bottom Township, PA that site be reviewed at time plant needs to be constructed
HALDRE, D S Affiliation Unknown 79/05/03 App

790620034 Responds to 780501 IE re proposed meeting on behalf of Fulton Township, PA requesting that NRC not grant early site review
SIDESBOTH, W J Affiliation Unknown 78/05/12 Ip

790620035 Advises that Fulton Township, PA Planning Commission opposes consent of electrical generating plant on proposed site
Requests termination of utility application
HEARN, J W Affiliation Unknown 78/05/26 Ip

790620075 Requests on behalf of Drummer Township, PA supervisors, termination of early site review plan Opposes consent of any type of electrical generating plant
HERR, S A Affiliation Unknown 79/04/07 App

O Adjudicatory correspondence

790620075 Opposes consent of add nuclear facility in area
HERR, S A Pennsylvania, State of 79/04/30 App

790620035 Opposes application for early site review
HITOFF, R P Pennsylvania, State of 79/03/08 App

790620035 Opposes application for early site review Requests termination of proceeding Certificate of Rev shell
HERR, S A House of Rep 78/07/03 App

DOCKET 90-444 PULMON GENERATING STATION, UNIT 2

O Adjudicatory correspondence

790620025 Requests by Save Balance Environ Conservation Fund that NRC order shell to show cause why application should not be terminated
SAGER, L Sager & Sager Associates 79/05/14 Tpp

790620035 Urges on behalf of Peach Bottom Township, PA that site be reviewed at time plant needs to be constructed
HALDRE, D S Affiliation Unknown 79/05/03 App

790620034 Responds to 780501 IE re proposed meeting on behalf of Fulton Township, PA requesting that NRC not grant early site review
SIDESBOTH, W J Affiliation Unknown 78/05/12 Ip

790620035 Advises that Fulton Township, PA Planning Commission opposes consent of electrical generating plant on proposed site
Requests termination of utility application
HEARN, J W Affiliation Unknown 78/05/26 Ip

790620075 Requests on behalf of Drummer Township, PA supervisors, termination of early site review plan Opposes consent of any type of electrical generating plant
HERR, S A Affiliation Unknown 79/04/07 App

790620075 Opposes consent of add nuclear facility in area
HERR, S A Pennsylvania, State of 79/04/30 App

790620035 Opposes application for early site review
HITOFF, R P Pennsylvania, State of 79/03/08 App

790620035 Opposes application for early site review Requests termination of proceeding Certificate of Rev shell
HERR, S A House of Rep 78/07/03 App

DOCKET 90-444 ALLIANCE NUCLEAR STATION, UNIT 1

O NRC Draft/Final Environmental Statement; supp & correspondence

790610408 Requests add info re endangered or threatened species in area of proposed facility Forwards appropriate sections of FES & suppl WFO shell
SALLARD, R L Environmental Projects Branch 1 79/04/26 Ip

O Adjudicatory correspondence

790620225 Request by utility that two 790622 motions be found untimely
NRC action to file brief notice surmise & joint motion for extension to file brief notice surmise by NRC & Inst for Public Representation Certificate of Rev shell
HERR, S A HERR, S A CLE, S H Laurentin-Neuman, Rost, Anselm & Tull 79/02/16 App

DOCKETED ITEMS

- 7706010040 Request for convenient location for prehearing conference
Certificates of Doc encl
HENDERSTEIN, C. Affiliation Unknown 7/03/24 2pp
- 7706010050 Motion for period of discovery extension until 7/05/02
HENDERSTEIN, C. Affiliation Unknown 7/03/24 2pp
- 77060080193 Motion by Houston Lighting & Power Co for denial of TX PIRG
770019 amicus curiae brief from NRDC & Inst for Public
Representation
REIS, H. P. ; BERMAN, J. H. ; LEWENTZIN, HUMAN, REIS, ASHOLD & TOLL
COPELAND, J. O. Baker & Smith 7/03/20 2pp
- 7706009010 Request by Houston Lighting & Power Co to NRDC & Inst for
Public Representation brief amicus curiae in support of
Natl Lawyers Guild Urges denial of appeal
BERMAN, J. H. ; REIS, H. P. ; LEWENTZIN, HUMAN, REIS, ASHOLD & TOLL
COPELAND, J. O. Baker & Smith 7/03/20 10pp
- 7706040032 Motion to postpone until investigation of TNEC is
completed, all further action in hearing process, except for
discovery Certificate of Doc encl
SCOTT, J. H. Texas Public Interest Research Group 7/04/02 2pp
- 7706040099 Request for production of documents
SCOTT, J. H. Texas Public Interest Research Group 7/04/02 1p
- 7706040094 Interrogatories submitted to State of TX
SCOTT, J. H. Texas Public Interest Research Group 7/04/02 1p
- 770510440 Request by Houston Lighting & Power for denial of TX PIRG
Continuation 12 re PIRG brief seeking admission of Texas-based
Continuation 12 re PIRG brief seeking admission of Texas-based
BERMAN, J. H. ; REIS, H. P. ; CULP, R. H. ; LEWENTZIN, HUMAN, REIS, ASHOLD & TOLL
7/04/03 7pp
- 7706030016 First set of Interrogatories & first request for documents
submitted to MRC Certificate of Doc encl
BENNETT, J. F. Affiliation Unknown 7/04/04 4pp
- 7706030032 Forwarded response to first round of interrogatories
submitted by TX PIRG
LEWENTZIN, R. H. Texas State of 7/04/05 1p
- 7706040445 Denies motions, filed by TX PIRG & J. O. Berman for postponement
of action Denies applicant's motion to reconsider 770604
order Denies TX PIRG motion to Adopt J. O. Berman's
contentions
WOLFE, S. J. Atomic Safety and Licensing Board Panel 7/04/03 2pp
- 7706029107 Answers & Hinderstein's second set of interrogatories &
requests for production of documents Affidavit & Certificate
of Doc encl
COPELAND, J. O. ; BAKER & SMITH ; BERMAN, J. H. ; CULP, R. H. ;
LEWENTZIN, HUMAN, REIS, ASHOLD & TOLL 7/04/07 7pp
- 7706030026 First request for admissions from Houston Lighting & Power
Co Certificate of Doc encl
BENNETT, J. F. Affiliation Unknown 7/04/07 1pp
- 7706030191 Request for documents from MRC Certificate of Doc encl
BENNETT, J. F. Affiliation Unknown 7/04/07 1p
- 7706030116 Expresses opposition to nuclear plant construction
VANDER, P. B. Affiliation Unknown 7/04/07 1p
- 7706180768 Requests opportunity to make limited appearance at
witness hearing
WOLFE, S. J. Affiliation Unknown 7/04/03 2pp
- 7706008082 Applicant's response in opposition to TX PIRG request for
entry upon land Request, fails to set forth & describe items
& lands to be inspected irrefragable particularly
Certificates of Doc encl
COPELAND, J. O. ; BAKER & SMITH ; BERMAN, J. H. ;
LEWENTZIN, HUMAN, REIS, ASHOLD & TOLL 7/04/20 2pp
- 7706010070 Applicant response to R & S French 770403 contentions
Petitioner's contentions should be denied due to untimely
filing & lack of merit Certificates of Doc encl
COPELAND, J. O. ; BAKER & SMITH 7/04/03 2pp
- 7706180720 Applicant response to JF Berman first set of
interrogatories & second set of requests for documents
Affidavit & Certificate of Doc encl
COPELAND, J. O. ; BAKER & SMITH ; BERMAN, J. H. ; CULP, R. H. ;
LEWENTZIN, HUMAN, REIS, ASHOLD & TOLL 7/04/03 10pp
- 7706190055 Applicant response to JF Berman first request for
documents re 770602-20043, 770602-10349, 770602-20904 & 770602-
Certificates of Doc encl
COPELAND, J. O. ; BAKER & SMITH 7/04/03 2pp
- 7706030088 Responds to intervenor C. Hinderstein's first set of
interrogatories & requests for production of documents
received by MRC as 770603 Supporting Documentation &
Certificate of Doc encl
PROCTOR, R. H. Division of Site Safety & Environmental Analysis
7/03/01 10pp
- 7706030114 Responds to TX PIRG 770052 request for production of
documents Certificate of Doc encl
BENNETT, J. F. Branch 3 7/03/01 10pp
- 7706030010 Grants petitioners Behr, French, Finkbeiner, Hirsch &
Berman's submission 770025, in which the file submission
denies summary to clarify affiliation with PIRG
WOLFE, S. J. Atomic Safety and Licensing Board Panel 7/03/01 10
- 7706070226 Responds to intervenor JF Berman 770407 request for
production of documents Forwarded Research Info for Weather
documents will be placed in DSM file encl Certificate of Doc
encl
BENNETT, J. F. Branch 3 7/03/01 2pp
- 7706030444 Notification that time for MRC review of ALAB-523 is extended
until 7/03/02 to correspond with review of ALAB-523
CHILDS, R. J. Office of the Secretary of the Commission 7/03/02
1p
- 7706180124 Applicant response to JF Berman first request for
admissions Denies officers have discussed permanent
admissions of case because of ALAB 770404 decision
Affidavit & Certificate of Doc encl
COPELAND, J. O. ; BAKER & SMITH 7/03/02 2pp
- 7706040430 Denies TX PIRG motion for reconsideration & clarification
of ALAB-523 re application of relief on notice publication
issue
WOLFE, S. J. Atomic Safety and Licensing Board Panel 7/03/03 2pp
- 7706070240 Asks intervenor JF Berman's reconsideration & clarification
of strength of steel containment shells
WOLFE, S. J. Atomic Safety and Licensing Board Panel 7/03/03 2pp
- 7706180240 Presents location of plant in close proximity to populated
area Requests full party status for CP proceedings & receipt of
CP
GRIFITH, R. H. Affiliation Unknown 7/03/03 1p
- 7706020178 Forwards 770316 board notification re recent issue on
non-safety-grade equipment to mitigate threats
BENNETT, J. F. Branch 3 7/03/03 2pp
- 7706020177 Board notification recent issue on non-safety-grade
equipment to mitigate threats
BENNETT, J. F. Assistant Director for Reactor Safety 7/03/04 2pp
- 7706150225 Requests full party status for CP proceedings & receipt of
CP
SCOTT, L. W. ; FULLER, C. ; MCPHARLAND, D. Affiliation Unknown 7/03/04 1p
- 7706070119 Denies on basis of untimeliness & Berman 770501 appeal of
ALAB 770025 rejection of petition to intervenor
CU ALAB, R. H. Atomic Safety and Licensing Board Panel 7/03/00 2pp

DOCKETED ITEMS

19.

7904202458 Applicant motion for supplemental notice of intervention procedures. Notice would provide opportunity for parties disavowed by 790501 & 0711 motions to file petitions for writ notice & Certificate of Div. and
REIS, M. F. / NEWHAM, J. F. / Louvenstein, Herman, Reiss, Axelrad & Tall
CORLADO, J. G. / Baker & Sottis 7/9/05/09 12pp

7904202459 Opposes plant construction Request EIR for Facility & status as full party to CP proceedings
STACE, K. L. / Affiliation Unknown 7/9/05/09 3pp

7904202460 Defers action as applicant 790509 motion for supplementary notice of intervention procedures in view of Committee
790502 order indicating NRC review of ALAB-305 & ALAB-309
HOLFE, S. J. / Atomic Safety and Licensing Board Panel 7/9/05/11 1p

7904202462 Deposition by applicant to Intervenor FM Petheff updated motion for 10-day extension to file submission, per ASLJ
790411 order Petheff has not shown good cause for extension
CORLADO, J. G. / THORAB, C. S. / Baker & Sottis / NEWHAM, J. F. / Louvenstein, Herman, Reiss, Axelrad & Tall 7/9/05/14 4pp

7904202464 Houston Lighting & Power second set of interrogatories & request for production of documents, submitted to Intervenor
EX PERO Certificate of Div. and
CORLADO, J. G. / THORAB, C. S. / Baker & Sottis / NEWHAM, J. F. / Louvenstein, Herman, Reiss, Axelrad & Tall 7/9/05/18 18pp

7904202465 Grants Petheff extension of time, until 790402, to file submission permitted by 790411 order
HOLFE, S. J. / Atomic Safety and Licensing Board Panel 7/9/05/21 2pp

7904202466 Responds to applicant 790509 motion for supplementary notice of intervention procedures Approves of motion, but seeks two amendments to restrictions in motion limits contentions & have given to potential intervenors
POTTS, D. F. H. / Affiliation Unknown 7/9/05/22 2pp

7904202468 Submits new contentions per ALAB-305 & 790412 order Questions ability of EDCS, solely dependent upon ASLJ single source of power
OTTEN, D. F. H. / Affiliation Unknown 7/9/05/23 3pp

7904202469 Submits add contentions per 790501 order Conservation program if initiated, will eliminate need for generating capacity. Witness use environmentally preferable to facility
POTTS, D. F. H. / Affiliation Unknown 7/9/05/24 3pp

H General correspondence

7904202470 Comments on radioactive emissions during normal operations, temporary onsite storage of spent fuel elements & other contaminated materials possible technical nature & geologic feasibility at proposed site
BARKER, E. / Affiliation Unknown 7/9/05/01 3pp

B Inspection reports, IE Bulletin & correspondence

7904202471 Forwards IE Bulletin 79-006, "Nuclear Incident at Three-Mile-Isle: No written response required"
BRITTON, K. V. / Region 4, Dallas, Office of the Director 7/9/04/21 1p

DOCKET 570-50-470 CCBAR SYSTEM 00

A Application/objection status documents & correspondence

7904202472 Requests extension to file add info re CCBAR-F pre-docketing need
SCHURE, A. E. / Combustion Engineering, Inc 7/9/04/01 1p

DOCKET 570-50-471 PLURINUCLEAR POWER STATION UNIT 2

A Application/objection status documents & correspondence

7904202473 Forwards final suppl to FEE re plant construct (INR05-0249)
REDAW, M. H. / Environmental Projects Branch 2 7/9/05/16 3pp

7904202474 Notice of availability of final suppl to FEE re unit construct
REDAW, M. H. / Environmental Projects Branch 2 7/9/05/16 3pp

7904202475 Forwards SED re CP application (INR05-0251) & FR notice of availability. Also forwards document alternate site study (INR05-0260) & Pilgrim FEE-Final suppl (INR05-0249), for use in review of SED
MILLARD, R. L. / Environmental Projects Branch 1 7/9/05/21 3pp

7904202476 Final suppl to FEE re plant construct
Office of Nuclear Reactor Regulation / INR05-0249 7/9/04/21 10pp Available at NTS 7 25

B Adjudications correspondence

7904202477 Forwards EA Licita affidavit indicating that NRC recommendations of reactor safety per Louis Committee recommendations will have no impact on this proceeding
SMITH, H. Branch 2 7/9/05/01 4pp

7904202478 Forwards draft suppl to FEE re unit construct
SMITH, H. Branch 2 7/9/04/12 1p

7904202479 Notices of appearance of FD Wright & RM Leach on behalf of Commonwealth of MA & notice of withdrawal of appearance of C. Carl & J. Brand on behalf of Commonwealth of MA Certificate of Div. and
MILTON, F. S. / Massachusetts, State of 7/9/04/12 3pp

7904202480 Clarifies Commonwealth of MA request for extension of time to submit on draft suppl to FEE (INR05-0250)
SMITH, L. / Massachusetts, State of 7/9/04/13 3pp

7904202481 Notifies that deposition interview of oral personnel who prepared draft report "Siting Study, Boston Edison Co." will be on 790404. Deposition will bring documents reflecting changes in cost since 790321 Certificate of Div. and
MILTON, F. S. / Massachusetts, State of 7/9/04/20 3pp

7904202482 Response in support of Commonwealth of MA second motion to suppl record on "need for power" issue Requests ASLJ enter add testimony as filed by 790310 Supporting Certificate of Div. and
MILTON, F. S. Branch 2 7/9/04/25 13p

7904202483 Responds to defendant's deposition of applicant's consultant scheduled for 790326 Certificate of Div. and
MILTON, F. S. / Massachusetts, State of 7/9/04/28 3pp

7904202484 Motion for consideration of emergency planning issues Parties should be given opportunity to discuss sufficiency of emergency plans prior to ASLJ issuance of CP Certificate of Div. and
MILTON, F. S. / MILTON, L. / Massachusetts, State of 7/9/04/27 14pp

7904202485 Sets dismissal of Intervenor Citizens 790416 Interrogatories re motion values in Table S-3 ASLJ does not have jurisdiction over interrogatories as presented Certificate of Div. and
MILTON, F. S. Branch 2 7/9/05/07 2pp

7904202486 Responds to 790322 request re status of rulemaking to develop value for radon in Table S-3 ASLJ is presently preparing paper & proposed rule which will be sent by 790405
SMITH, S. E. / Hearings Division 7/9/03/26 1p

7904202487 Grants Commonwealth of MA 790404 motion to request record re "need for power" issue Applicant shall submit most recent long-range energy & demand forecasts of utility & New England Power Pool
LUTZ, E. / Atomic Safety and Licensing Board Panel 7/9/05/09 1p

7904202488 Testimony on behalf of State of MA re ability of utility to finance share of facility financial analysis, transcript of all Board of Directors meeting, add testimony & Certificate of Div. and
LEVIN, P. F. / Arkansas, State of 7/9/05/09 10pp

7904202489 Forwards PF Levy 790509 testimony on behalf of State of MA
MEYER, M. S. / Massachusetts, State of 7/9/05/09 1p

7904202490 Direct testimony on behalf of applicant re alternative siting, elaborates on utility siting study for 1400 range generating capacity expansion
GRIFFIN, W. R. / Boston Edison Co. / FRANKLIN, J. / United Engineers & Constructors, Inc 1400 of Hingham Co 7/9/05/11 10pp

7904202491 Direct testimony on financial qualifications of Intervenor State of MA Contention R, delineates RM Reboon role in siting application & general financial duties elaborates on TJ How financial responsibilities
MILTON, F. S. / MA, T. J. / Boston Edison Co 7/9/05/11 13pp

7906278142 Opposition by staff to State of MA motion to admit emergency planning conditions on factored basis presented or good cause shown for admission of contentious
LEAH, D. O. H. Rogers & Gray STODOLSKY, D. O. Duxton Edison Co
79/05/14 13pp

7906222016 Boston Edison Co supplemental testimony re need for facility testimony provided by RM Weiner-PA Legren-20
Weiner, Dr. Bartolucci Turner, M. Goolley & J. Hanna Supporting
Documentation only
WEINER, B. M. - LEGREN, P. A. Boston Edison Co 79/05/21 39pp

7906206000 Notification of appearance on behalf of MA Governor Ofc of State's Resources
KELLY, F. J. Massachusetts, State of 79/05/26 1p

7906204324 Orders resumption of evidentiary hearing on 790611 at
Hendred Hall, Plymouth, MA
LUTON, E. Atomic Safety and Licensing Board Panel 79/06/04 1p

7906200104 Furnish State of MA Ofc of Energy Resources to participate in proceeding re need for power lease at Intervenor state
Agency
LUTON, E. Atomic Safety and Licensing Board Panel 79/06/07 2pp

7906202020 Notice of reconstitution of ASLAC AC Conference replaces
E. Luton as chairman
LUTON, E. Atomic Safety and Licensing Board Panel 79/06/07 1p

T Hearing transcripts on non-abstract matters

7906140117 Transcript of 790524 meeting on Plymouth, MA. Pg 1007-1210
LUTON, E. - COLE, R. F. - CALLIHAN, D. Atomic Safety and Licensing Board Panel 79/05/28 121pp

7906101053 Transcript of 790520 hearing on Plymouth, MA. Pg 929-9437
LUTON, E. - COLE, R. F. - CALLIHAN, D. Atomic Safety and Licensing Board Panel 79/05/29 109pp

7906220047 Transcript of 790527 meeting on Plymouth, MA. Pg 428-5, 500
LUTON, E. - COLE, R. F. - CALLIHAN, D. Conference 79/05/29 183pp

7906180750 Transcript of 790525 hearing on Plymouth, MA. Pg 5243-5, 746
LUTON, E. - COLE, R. F. - CALLIHAN, D. Atomic Safety and Licensing Board Panel 79/05/30 200pp

7906220109 Transcript of 790531 hearing on Plymouth, MA. Pg 7799-10, 048
LUTON, E. - COLE, R. F. - CALLIHAN, D. Atomic Safety and Licensing Board Panel 79/05/31 24pp

T Hearing transcripts on non-abstract matters

7906180726 Transcript of 790601 hearing on Plymouth, MA
Pg 10, 247-16, 261
LUTON, E. - COLE, R. F. - CALLIHAN, D. Atomic Safety and Licensing Board Panel 79/06/01 133pp

7906206540 Transcript of 790611 hearing on Plymouth, MA. Pg 10, 200-
10, 244
GODDARD, A. C. - COLE, R. F. - CALLIHAN, D. Atomic Safety and Licensing Board Panel 79/06/11 133pp

ROCKET STN-90-402 WOLF CREEK GENERATING STATION

A Application/Construction stage documents & correspondence

7906270212 Clarify current status of resolution of concrete problems
DAVIS, J. G. Office of Inspection & Enforcement 79/04/25 4pp

7906200214 Opposes further bldg of nuclear plants in MA Concern re
facility location
BARNARD, J. Wolf Creek Nuclear Opposition, Inc 79/01/22 1p

7906180190 Responds to 790624 ltr re quality of cement being used at
site Furnishes current summary of facts related to concrete
problems At present time no concrete is being placed in
reactor containment bldg-pending resolution of problem
DAVIS, J. G. Office of Inspection & Enforcement 79/04/27 2pp

7906180208 Expresses concern re quality of cement being used
BRILLMAN, M. Women's International League for Peace & Freedom
78/12/24 1p

7906120043 Requests NRC concurrence to use of ASME Section III Code
Case N-240 "Metal Certification"
PEIRICK, R. A. SNUPP-Standardized Nuclear Unit Power Plant System,
79/06/01 1p

7906101017 Submits addl info re bldg work in response to 790529 telcon
request by Liaison, Section 1 & MC
KOSBURN, G. L. Kansas Gas & Electric Co 79/06/06 7pp

7906102047 Submits info re SSP computer program & miscellaneous
project-developed programs in response to NRC Request
Requests classification of info as proprietary Mail
withheld inf 100792 7901
KOSBURN, G. L. Bechtel Power Corp. cause of Bechtel Corp 79/06/06
2pp

D Adjudicatory correspondence

7906200447 Motion for extension until 790401 to prepare response to
ALAB-529
BENNETT, J. F. Hearings Division 79/04/02 2pp

7906201040 Responds to 790202 request for info re status of rulemaking
proceeding to develop rules for n.d. in Table 9-3 Regt &
proposed rule will be sent to NRC by 790404 Rule does not
address health effects of radon releases
CHARTERED, E. Hearings Division 79/03/26 34pp

7906100171 Responds to 790130 ltr to JH Hendrix Forewarns summary of
concrete problems at facility At present, several requests
for revocation of CP are under consideration & will be
addressed where investigations are done
DAVIS, J. G. Office of Inspection & Enforcement 79/04/27 3pp

7906100171 Forewarns CP be revoked due to concrete problems
DEBELL, G. M. Affiliation Unknown 79/01/20 1p

7906200204 Reports nationwide hold in nuclear plant const Cites
Wolf Creek controversy as example
MARTIN, D. K. L. Affiliation Unknown 79/04/27 1p

7906200234 Requests CP be revoked Forewarns ltr to newspaper
WOLF, F. Affiliation Unknown 79/03/03 1p

7906100293 NRC motion for summary disposition re radon issue was in
appal/ALAB-940 consolidated only 3 of 14 cases Series NRC
motion as to parties in other proceedings Certificate of SVC
sent
BURLIN, E. Atomic Safety and Licensing Appeal Panel 79/05/23
3pp

7906200403 Requests timely notification of any SL proceedings within
jurisdiction of MD Public Use Commission to facilitate state
participation
HEARNE, J. Missouri, State of 79/06/19 1p

H General correspondence

7906100207 Responds to 790224 hearing re possible sale of 17% interest
in rural electric cooperatives Request for hearing is
premature; submittal notice not yet received
ENDLUND, T. P. Deputy Executive Legal Director 79/04/16 3pp

7906100309 Requests hearing re possible sale of 17% interest in
facility to obtain rural electric cooperatives
BELL, J. E. Affiliation Unknown 79/03/26 1p

G Inspection reports, IE Bulletin & correspondence

7906200094 Ack receipt of IE Insp Rpt 50-482/79-13 Re proprietary
info
KOSBURN, G. L. Kansas Gas & Electric Co 79/03/05 1p

7906120022 Forewarns IE Insp Rpt 50-482/79-05 on 790324-29 Re
noncompliance notice
BIDDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/16 2pp

7906120022 IE Insp Rpt 50-482/79-05 on 790324-29 Re noncompliance
notice Major areas inspected cover activities including
review of records & work on safety-related concrete &
piping
BIDDLE, W. C. - HALL, R. E. Region 4, Dallas, Reactor
Construction & Engineering Support Branch 0305, C. R. Region 4,
Dallas, Office of the Director 79/04/16 3pp

7906100003 Forewarns IE Bulletin 79-098, "Nuclear Incident at
Tex-Gas" Is written response required
BUTTRICK, K. V. Region 4, Dallas, Office of the Director 79/04/21
1p

DOCKETED ITEMS

7904010000 Notifies Bechtel does concur w/initial assessment re unacceptable work in piping pressure/vibration installation of assemblies suspended until differences are resolved
HDSBTR, G.L. Kansas Gas & Electric Co 79/04/23 1p

7904010005 Ack receipt of 790405 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-482/79-13
Requests add info re failure to complete user tests within time limits
SEILJE, M.G. Region 4, Dallas, Office of the Director 79/04/26 1p

7904010006 Responds to NRC 790216 ltr re violations noted in IE Insp Rept 80-482/79-13 corrective actions A&I Method 1 will be followed for new design. Compliance w/Items 2,3,4,5 & 6 has been achieved
HDSBTR, G.L. Kansas Gas & Electric Co 79/03/22 4pp

7904010007 Ack receipt of 790323 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-482/79-03
Requests add info re testing of concrete for slump limits, bleeding & corrective measures planned
SEILJE, M.G. Region 4, Dallas, Office of the Director 79/04/26 1p

7904010008 Responds to NRC 790201 ltr re violations noted in IE Insp Rept 80-482/79-01 corrective actions documentation of failure to test batches 7885 & 7887 has been sent to A/E
HDSBTR, G.L. Kansas Gas & Electric Co 79/03/22 2pp

7904120008 Forwards IE Info Notice 79-12, "Lower Reactor Vessel Head Isolation Support Problem." No action required
SEIFERT, R.V. Region 4, Dallas, Office of the Director 79/03/07 1p

7904010009 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
SEIFERT, R.V. Region 4, Dallas, Office of the Director 79/03/11 1p

7904130027 Ack receipt of 790423 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-482/79-03
HDSBTR, G.L. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/14 1p

7904010033 Responds to NRC 790216 ltr re violations noted in IE Insp Rept 80-482/79-13 corrective actions intensive training program conducted for concrete crew & concrete control procedures revised
HDSBTR, G.L. Kansas Gas & Electric Co 79/04/23 2pp

7904140143 Ack receipt of 790423 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 80-482/79-12
SEILJE, M.G. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/14 1p

7904014017 Responds to NRC 790201 ltr re violation noted in IE Insp Rept 80-482/79-12 corrective actions used procedural changes have been completed & surveillance steps will be completed by 790520
HDSBTR, G.L. Kansas Gas & Electric Co 79/04/26 2pp

7904130008 Forwards IE Bulletin 79-11, "Faulty Decoupler Trip Device in Circuit Breakers for Emergency Safety Sys." Licensee action required
SEIFERT, R.V. Region 4, Dallas, Office of the Director 79/06/22 1p

0 Regulatory correspondence, LERs & related correspondence

7902120002 Final significant deficiency report re spot resistance welding of electrical roadway support nails. Discusses nail deficiency safety implications & testing program at job sites
Kansas Gas & Electric Co 79/02/07 14pp

7904180160 Forwards PMB-79-67WH
SEILJE, M.G. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/08 1p

7904180177 Forwards PMB-79-67WH
SEILJE, M.G. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/16 1p

7904180245 Forwards PMB-79-67WH
SEILJE, M.G. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/22 1p

7904180254 Forwards PMB-79-67WH
SEILJE, M.G. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/22 1p

U Congressional/Executive Correspondence

7904050016 Ack receipt of 790201 request. Forwards summary of concrete problems at site. Re concrete being placed in reactor containment bldg. Pending resolution of basket strength questions
GOSSEL, V. Office of the Executive Director for Operations 79/05/01 4pp

7904050017 Requests info re concrete in facility basement
HITTAUER, R. House of Rep 79/02/03 1p

7906200439 Forwards EL Bates 790142 ltr to E. Cagle re substantial bldg static disposal of radioactive wastes
EASLEY, R.F. Senate 79/03/07 2pp

DOCKET SEN-80-483 CALLEWAY PLANT, UNIT 1

A Application/construction stage documents & correspondence

7904150198 Forwards Dames & Moore interim report, "Detailed Excavation Mapping/Ultimate Heat Sink Excavations." Rept available in Central Files only
SCHWALL, D.P. Union Electric Co 79/03/09 1p

790420146 Confirms plan to discuss & resolve matters re fuel rod bowing effects in RUPPS PRAM
PETERSON, M.A. DUPPS-Standardized Nuclear Unit Power Plant System 79/04/30 1p

7904120263 Requests AEC concurrence re use of ASME Section III Code Case No.264, "Nail Certification"
PETERSON, M.A. DUPPS-Standardized Nuclear Unit Power Plant System 79/04/04 1p

0 Regulatory correspondence

7904260403 Requests timely notification of any OL proceedings within jurisdiction of SD Public Use Commission to facilitate stake participation
HARRIS, T. Missouri, State of 79/06/19 1p

0 Inspection reports, IE Bulletins & correspondence

7904140162 Forwards IE Insp Rept 80-483/79-03 on 790308-12 & notice of violation
FISCHL, L.G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/04 2pp

7904140264 Notice of violation from Insp on 790405-12
Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/04 1p

7904140376 IE Insp Rept 80-483/79-03 on 790305-12 Noncompliance noted failure to follow established procedures for training non-SAC personnel who perform safety-related work activities
RAMP, R.C. & HARRIS, M.A. & JABLONSKI, F.J. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/02 14pp

7904050184 Ack receipt of 790423 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-483/79-03
F
0

--

DOCKETED ITEMS

7906120118 Forwards IE Bulletin 79-11, "Faulty Recurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required
KFFLER, J G Region 3, Chicago, Office of the Director 7/9/05/02
1p

7906200479 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Dwyer Creek Reactor"
KFFLER, J G Region 3, Chicago, Office of the Director 7/9/05/29
1p

DOCKET 83N-50-484 IYOWNE ENERGY PARK, UNIT 1
A Application/construction stage documents & correspondence

7906120146 Confirms plan to discuss & resolve matters re fuel rod bowing effects in SHAFPS FWR
PETERSON, N A SHAFPS-Standardized Nuclear Unit Power Plant System 7/9/05/20 1p

7906120283 Requests NRC endorsement re use of ASME Section III Code Case N-242, "Nuts Certification"
PETERSON, N A SHAFPS-Standardized Nuclear Unit Power Plant System 7/9/05/01 1p

0 Adjudicatory correspondence

7906120447 Motion for extension until 7/9/01 to prepare response to ALAB-309
SCHEIDT, J F Hearings Division 7/9/04/02 2pp

--7906120646 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table B-3 Regt & proposed rule will be sent to NRC by 7/9/06 Rule does not address health effects of radon releases
CHISTENSEN, E Hearings Division 7/9/03/26 3pp

7906120595 NRC motion for summary disposition re radon issue was in error/ALAB-540 consolidated only 3 of 16 issues Denies NRC motion as to parties in other proceedings Certificate of Dvc
DUPLOIN, H E Atomic Safety and Licensing Appeal Panel 7/9/05/25 3pp

7906120807 Request by which that ALAB grant summary disposition of all issues in consolidated Radon proceeding Decision sought as matter of law since no genuine issue as to merit facts
SILBERT, J E Shaw, Pittman, Potts, & Trowbridge 7/9/05/25 4pp

--7906120810 Statement of merit facts re Rn proceedings as to which there is no genuine issue to be heard Discusses Alleged Deficiencies 1-7, 9-10, 20-24 & 26 Affidavit of RI Golden & supporting documentation encl
SILBERT, J E Shaw, Pittman, Potts, & Trowbridge 7/9/05/25 3pp

--7906120812 Supp's 790325 affidavit of RI Golden & v/s 790409 memo re Rn extension & de minimus approach Discusses Alleged Deficiencies 2, 9-10 & 21 Dv's motion for summary disposition Certificate of Dvc encl
SILBERT, J E Shaw, Pittman, Potts, & Trowbridge 7/9/05/25 1pp

7906120403 Requests timely notification of any GL proceedings within jurisdiction of MO Public Sec Commission to facilitate state participation
SEANE, T Missouri, State of 7/9/04/19 1p

3 Financial information

7906200036 "Annual Financial Rep 1978"
Cooperative Power Association 7/9/04/01 25pp

0 Inspection reports, IE Bulletin & correspondence

7906120119 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" re action required
KFFLER, J G Region 3, Chicago, Office of the Director 7/9/05/07 1p

7906190079 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
KFFLER, J G Region 3, Chicago, Office of the Director 7/9/05/11 1p

7906120005 Responds to IE Bulletin 79-03 re use of fusion welded pipe spools mfg by Yonkers Welding & Engineering Co. No such pipe spools have been shipped to facility
SILBERT, J E Northern States Power Co 7/9/05/11 3pp

7906120111 Forwards IE Bulletin 79-11, "Faulty Recurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required
KFFLER, J G Region 3, Chicago, Office of the Director 7/9/05/02 1p

7906200426 Responds to IE Bulletin 79-04 re incorrect weights for valves using check valves incorrect valve weights not used No req required
SILBERT, J E Northern States Power Co 7/9/05/22 2pp

7906200446 Responds to IE Bulletin 79-07 re seismic stress analysis of safety-related piping lists computer codes used in analyses
SILBERT, J E Northern States Power Co 7/9/05/23 2pp

7906120123 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Dwyer Creek Reactor"
KFFLER, J G Region 3, Chicago, Office of the Director 7/9/05/29 1p

DOCKET 83N-50-405 STERLING POWER PROJECT NUCLEAR, UNIT 1
A Application/construction stage documents & correspondence

7906120146 Confirms plan to discuss & resolve matters re fuel rod bowing effects in SHAFPS FWR
PETERSON, N A SHAFPS-Standardized Nuclear Unit Power Plant System 7/9/05/20 1p

7906120283 Requests NRC endorsement re use of ASME Section III Code Case N-242, "Nuts Certification"
PETERSON, N A SHAFPS-Standardized Nuclear Unit Power Plant System 7/9/05/01 1p

7906200540 Requests notification of date for meeting w/NRC to discuss register details which reflect upon planon injection of EGS
WHEELER, D Rochester Gas & Electric Corp 7/9/05/20 1p

0 Adjudicatory correspondence

7906120447 Motion for extension until 7/9/01 to prepare response to ALAB-309
SCHEIDT, J F Hearings Division 7/9/04/02 2pp

--7906120646 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table B-3 Regt & proposed rule will be sent to NRC by 7/9/06 Rule does not address health effects of radon releases
CHISTENSEN, E Hearings Division 7/9/03/26 3pp

7906120810 Requests 2-day extension until 7/9/05 in which to file memo per NRC 790325 order
SILBERT, J E March 3 7/9/04/05 2pp

7906120975 NRC motion for summary disposition re radon issue was in error/ALAB-340 consolidated only 3 of 16 issues Denies NRC motion as to parties in other proceedings Certificate of Dvc
DUPLOIN, H E Atomic Safety and Licensing Appeal Panel 7/9/05/25 3pp

7906120807 Request by which that ALAB grant summary disposition of all issues in consolidated Radon proceeding Decision sought as matter of law since no genuine issue as to merit facts
SILBERT, J E Shaw, Pittman, Potts, & Trowbridge 7/9/05/25 4pp

--7906120810 Statement of merit facts re Rn proceedings as to which there is no genuine issue to be heard Discusses Alleged Deficiencies 1-7, 9-10, 20-24 & 26 Affidavit of RI Golden & supporting documentation encl
SILBERT, J E Shaw, Pittman, Potts, & Trowbridge 7/9/05/25 3pp

--7906120812 Supp's 790325 affidavit of RI Golden & v/s 790409 memo re Rn extension & de minimus approach Discusses Alleged Deficiencies 2, 9-10 & 21 Dv's motion for summary disposition Certificate of Dvc encl
SILBERT, J E Shaw, Pittman, Potts, & Trowbridge 7/9/05/25 1pp

7906120403 Requests timely notification of any GL proceedings within jurisdiction of MO Public Sec Commission to facilitate state participation
SEANE, T Missouri, State of 7/9/04/19 1p

3 Inspection reports, IE Bulletins & correspondence

7906100417 Forwards IE Info Notice 79-10: "Nonconforming Pipe Support Struts." No written response necessary
SHELDON, R Region 1, Philadelphia: Office of the Director 79/04/14 1p

7906100042 Forwards IE Bulletin 79-08B: "Nuclear Incident at Unit 3." No written response required
SHELDON, R Region 1, Philadelphia: Office of the Director 79/04/23 1p

7906100022 Forwards IE Info Notice 79-11: "Lower Reactor Vessel Head Insulation Support Problem." No action required
SHELDON, R Region 1, Philadelphia: Office of the Director 79/03/27 2pp

7906270195 Responds to IE Bulletin 79-03 To date, there have been no pipe spalls of any type fabricated for or shipped to facilities
ARTHUR, J E Rochester Gas & Electric Corp 79/03/10 3pp

7906200187 Forwards IE Info Notice 79-12: "Attempted Damage to New Fuel Assemblies"
SHELDON, R Region 1, Philadelphia: Office of the Director 79/03/11 1p

SECRET 83N-50-88A CALLAWAY PLANT, UNIT 2

A Application/construction stage documents & correspondence

7906100146 Confirms plan to discuss & resolve matters re fuel rod loading effects in SWAPP PWR
PETERICK, H A SWAPP-Standardized Nuclear Unit Power Plant System 79/03/30 1p

7906100063 Requests NRC concurrence re use of ASME Section III Code Case N-582 "Nuts Certification"
PETERICK, H A SWAPP-Standardized Nuclear Unit Power Plant System 79/04/01 1p

3 Adjudicatory correspondence

7906100452 Requests timely notification of any GL proceedings within jurisdiction of MD Public Use Commission to facilitate state certification
HEARN, T Niagara, State of 79/04/19 1p

3 Inspection reports, IE Bulletins & correspondence

7906100127 Forwards IE Info Notice 79-11: "Lower Reactor Vessel Head Insulation Support Problem." No action required
KOPPLEN, J G Region 3, Chicago: Office of the Director 79/05/07 1p

7906100184 Forwards IE Info Notice 79-12: "Attempted Damage to New Fuel Assemblies"
KOPPLEN, J G Region 3, Chicago: Office of the Director 79/05/11 1p

7906100258 Responds to IE Bulletin 79-02 re use of fusion welded stainless steel pipe spig by Youngstown Welding & Engineering Co
SHELDON, R Union Electric Co 79/05/11 5pp

7906100418 Forwards IE Bulletin 79-11: "Faulty Overcurrent Trip Device in Circuit Breakers for Engineering Safety Sys." License action required
SHELDON, J G Region 3, Chicago: Office of the Director 79/05/22 1p

7906200129 Forwards IE Info Notice 79-13: "Indication of Low Water Level in Quaker Creek Reactor."
SHELDON, J G Region 3, Chicago: Office of the Director 79/05/29 1p

SECRET 83N-50-489 PERKINS NUCLEAR STATION, UNIT 1

3 Adjudicatory correspondence

7906100126 Opposes intervenors 790305 motion to reopen record for add hearing Requests initial decision be issued
KOPPLEN, J M Duke Power Co 79/05/21 5pp

7906200240 Forwards memo re problems experienced in connection w/pipes support base plate design Problems are applicable to Facility
BARTH, C A Branch 3 79/04/05 2pp

7906100009 Forwards addl info on accumulator delivery re PWIs, as identified during continuing studies of ECCS performance
NRC Does not believe this matter has any effect on operating issues
BARTH, C A Branch 3 79/04/05 2pp

7906100017 Concludes accumulator delivery behavior can have important effect on ECCS performance Suggests US std problem participants provide pressure & flow comparisons for all past & future std problems where applicable
NRCB, D F Assistant Director for Reactor Safety 79/04/05 3pp

7906100185 Denies intervenors 790305 motion to reopen record for add hearings Reviews wording of 790307 partial initial decision.
SHELDON, R Atomic Safety and Licensing Board Panel 79/04/12 5pp

7906100112 Opposes intervenors 790405 motion to reopen record & stay or suspension of licensing activities Intervenor have not satisfied criteria for stay of proceedings Certificate of
Brc and
BARTH, C A Branch 3 79/04/19 5pp

H General correspondence

7906100576 Ltr of concern re use of nuclear power
JACKSON, P WINDYB, S Affiliation Unknown 79/04/22 3pp

J Insurance & indemnity information

7906100031 Forwards Endorsements 34 & 35 to AIE Policy NP-102 & Endorsements 40 & 41 to HRAU Policy NP-61
SHELDON, R D Duke Power Co 79/04/08 2pp

3 Inspection reports, IE Bulletins & correspondence

7906100443 Responds to IE Bulletin 79-03 Site has received 200 ft of pipe spig by Youngstown Welding & Engineering Co Youngstown methods meet ASME Code std
BARTH, C A Duke Power Co 79/04/20 2pp

7906100428 Responds to IE Bulletin 79-04 Valve valves not in use
BARTH, C A Duke Power Co 79/04/24 1p

7906200446 Forwards IE Info Notice 79-12: "Attempted Damage to New Fuel Assemblies"
SHELDON, J G Region 3, Atlanta: Office of the Director 79/05/10 1p

SECRET 83N-50-489 PERKINS NUCLEAR STATION, UNIT 2

3 Adjudicatory correspondence

DOCKETED ITEMS

790604083 Series Intervenor 790305 motion to reopen record for addl hearings. Review wording of 7901027 partial initial decision.
Paragraph 20
DOHERTY, E. M. Atomic Safety and Licensing Board Panel 79/04/12
Bp

790602013 Opposes intervenors 790405 motion to reopen record & stay or suspension of licensing activities. Intervenor has not satisfied criteria for stay of proceedings. Certificate of due diligence.
BARTH, C. A. Branch 3 79/04/19 App

J Insurance & Identity Information

790603030 Forwards Endorsements 54 & 55 to ANSI Policy NF-102 & Endorsements 40 & 41 to ANSI Policy NF-61
SANDERS, P. D. Duke Power Co 79/04/03 App

G Inspection reports; IE Bulletin & correspondence

790613049 Responds to IE Bulletin 79-02. Duke has received 200 ft of pipe mfg by Youngstown Welding & Engineering Co. Youngstown mobile heat ASME code vites.
DALL, L. C. Duke Power Co 79/04/20 App

790614042 Responds to IE Bulletin 79-04. Valves not in use.
DALL, L. C. Duke Power Co 79/04/24 App

790625046 Forwards IE info Notice 79-10, "Attempted Damage to New Feed Assembly."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/10 App

DOCKET BTH-50-450 PERRIN NUCLEAR STATION, UNIT 3

B Adjudicatory correspondence

790610104 Opposes intervenors 790305 motion to reopen record for addl hearing. Requests initial decision be issued.
Certificate of due diligence.
MCARDY, J. M. Duke Power Co 79/02/23 App

790605074 Forwards memo which contains info potentially relevant to issue of sabotage of spent nuclear fuel.
BARTH, C. A. Branch 3 79/04/05 App

790605090 Forwards memo re problems encountered in connection w/pipe support base plate design. Problems are applicable to facility.
BARTH, C. A. Branch 3 79/04/05 App

790613009 Forwards addl info on accumulator delivery re PWRs, as identified during continuing studies on ECCS performance.
NRC does not believe this matter has any effect on proceedings. Likens.
BARTH, C. A. Branch 3 79/04/05 App

790610017 Concludes accumulator delivery behavior can have important effect on ECCS performance. Suggests US and problem participants provide pressure & flow comparisons for all past & future addl problems where applicable.
DOHERTY, E. M. Assistant Director for Reactor Safety 79/04/05 App

790604041 Series intervenors 790305 motion to reopen record for addl hearings. Review wording of 7901027 partial initial decision.
Paragraph 20
DOHERTY, E. M. Atomic Safety and Licensing Board Panel 79/04/12 App

790612013 Opposes intervenors 790405 motion to reopen record & stay or suspension of licensing activities. Intervenor has not satisfied criteria for stay of proceedings. Certificate of due diligence.

G Inspection reports; IE Bulletin & correspondence

790613043 Responds to IE Bulletin 79-02. Duke has received 200 ft of pipe mfg by Youngstown Welding & Engineering Co. Youngstown mobile heat ASME code vites.
DALL, L. C. Duke Power Co 79/04/20 App

790614042 Responds to IE Bulletin 79-04. Valves not in use.
DALL, L. C. Duke Power Co 79/04/24 App

790628044 Forwards IE info Notice 79-10, "Attempted Damage to New Feed Assembly."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/10 App

DOCKET BTH-50-450 PERRIN NUCLEAR STATION, UNIT 1

G Adjudicatory correspondence

790610047 Notice for submission until 790411 to prepare responses to ALB-501.
O'REILLY, J. P. Hearings Division 79/04/02 App

790625046 Responds to 790322 request for info re status of releasing proceeding to develop value for radon in table B-3. Heat & temperature rule will be sent to NRC by 790404. Rule days not affect health effects of radon release.
O'REILLY, J. P. Hearings Division 79/03/26 App

790613043 Responds to IE Bulletin 79-02. Duke has received 200 ft of pipe mfg by Youngstown Welding & Engineering Co. Youngstown mobile heat ASME code vites.
DALL, L. C. Duke Power Co 79/04/20 App

790610098 NRC action for summary disposition re radon issue was in error; ALB-501 consolidated only 3 of 16 cases. Timeline 102 action as to parties in other proceedings. Certificate of due diligence.
O'REILLY, J. P. Atomic Safety and Licensing Appeal Panel 79/03/25 App

J Insurance & Identity Information

790613003 Forwards Endorsements 54 & 55 to ANSI Policy NF-102 & Endorsements 40 & 41 to ANSI Policy NF-61
SANDERS, P. D. Duke Power Co 79/04/03 App

G Inspection reports; IE Bulletin & correspondence

790613004 Forwards IE Insp Repts 30-491/79-04, 30-492/79-04 & 30-493/79-04 on 790323-16. No noncompliance noted.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/05 App

790613002 IE Insp Repts 30-491/79-04, 30-492/79-04 & 30-493/79-04 on 790323-16. No noncompliance noted. Major areas inspected: BA program, control procedures, Part 21 implementation, containment plate welding & vendor surveillance.
O'REILLY, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, HSD-21, Region 2, Atlanta, Office of the Director 79/04/05 App

790613002 IE Insp Repts 30-491/79-04, 30-492/79-04 & 30-493/79-04 on 790323-16. No noncompliance noted. Major areas inspected: BA program, control procedures, Part 21 implementation, containment plate welding & vendor surveillance.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/05 App

790614042 Responds to IE Bulletin 79-04. Valves not in use.
DALL, L. C. Duke Power Co 79/04/24 App

790612014 Act receipt of IE Insp Repts 30-491/79-04, 30-492/79-04 & 30-493/79-04 on 790417-19. No noncompliance noted.
DALL, L. C. Duke Power Co 79/05/01 App

790619016 Forwards IE Insp Repts 30-491/79-04, 30-492/79-04 & 30-493/79-04 on 790417-19. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/01 App

790619020 IE Insp Repts 30-491/79-04, 30-492/79-04 & 30-493/79-04 on 790417-19. No noncompliance noted. Major areas inspected: review of BA implementing procedures for safety-related structures & containment.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/01 App

DOCKETED ITEMS

203

7904250087 Response to NRC 790413 for re violations noted in IE Insp Rept 30-493/79-06, 30-493/79-06, 30-493/79-06 Corrective actions taken used for soil & concrete aggregate tests will be in regular calibr program
DALL, L C Duke Power Co 79/03/09 1p

7904250087 Response to NRC 790413 for re violations noted in IE Insp Rept 30-493/79-06, 30-493/79-06, 30-493/79-06 Corrective actions taken used for soil & concrete aggregate tests will be in regular calibr program
DALL, L C Duke Power Co 79/03/09 1p

7904250446 Forward IE Info Notice 79-10. "Attempted Damage to New Fuel Assemblies"
C-RELL, V J Region 2, Atlanta, Office of the Director 79/03/10 1p

7904250446 Forward IE Info Notice 79-10. "Attempted Damage to New Fuel Assemblies"
C-RELL, V J Region 2, Atlanta, Office of the Director 79/03/10 1p

8 Repeatable occurrences, LEDs & related correspondence

8 Repeatable occurrences, LEDs & related correspondence

7904250504 Forward Final Rept 79/01-SFB-491/492/493 re recall of pipe fittings
DALL, L C Duke Power Co 79/03/10 1p

7904250504 Forward Final Rept 79/01-SFB-491/492/493 re recall of pipe fittings
DALL, L C Duke Power Co 79/03/10 1p

--7904250504 Final Rept 79/01-SFB-491/492/493 weld fittings w/out number N6719 contained erroneously identified high carbon steel metal that could crack when being welded All metal returned to vendor on 790412
Duke Power Co 79/03/11 1p

--7904250504 Final Rept 79/01-SFB-491/492/493 weld fittings w/out number N6719 contained erroneously identified high carbon steel metal that could crack when being welded All metal returned to vendor on 790412
Duke Power Co 79/03/11 1p

DOCKET 87N-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

DOCKET 87N-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

8 Adjudicatory correspondence

8 Adjudicatory correspondence

7904250647 Motion for extension until 790411 to prepare response to ALAB-509
SCINTO, J F Hearings Division 79/04/02 3pp

7904250647 Motion for extension until 790411 to prepare response to ALAB-509
SCINTO, J F Hearings Division 79/04/02 3pp

--7904250647 Response to 790302 request for info re status of rulemaking proceeding to develop value for radon in Table 3-3 Rept 3 & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases
CHRISTENSEN, E Hearings Division 79/03/26 3pp

--7904250647 Response to 790302 request for info re status of rulemaking proceeding to develop value for radon in Table 3-3 Rept 3 & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases
CHRISTENSEN, E Hearings Division 79/03/26 3pp

7904250648 Response to IE Bulletin 79-03 Site has received 200 ft of pipe mfg by Youngstown Welding & Engineering Co Youngstown machine most ASME code studs
DALL, L C Duke Power Co 79/04/20 2pp

7904250648 Response to IE Bulletin 79-03 Site has received 200 ft of pipe mfg by Youngstown Welding & Engineering Co Youngstown machine most ASME code studs
DALL, L C Duke Power Co 79/04/20 2pp

7904250695 NRC motion for summary disposition re radon issue was in error ALAB-502 consolidated only 8 of 16 cases Besides NRC motion as to parties in other proceedings Certificate of Service
DALL, L C Atomic Safety and Licensing Appeal Panel 79/05/02 3pp

7904250695 NRC motion for summary disposition re radon issue was in error ALAB-502 consolidated only 8 of 16 cases Besides NRC motion as to parties in other proceedings Certificate of Service
DALL, L C Atomic Safety and Licensing Appeal Panel 79/05/02 3pp

8 Insurance & indemnity information

8 Insurance & indemnity information

7904250695 Forward Endorsements 54 & 55 to ANI Policy NF-182 & Endorsements 40 & 41 to PUEL Policy NF-1
BAHRENS, F B Duke Power Co 79/04/02 3pp

7904250695 Forward Endorsements 54 & 55 to ANI Policy NF-182 & Endorsements 40 & 41 to PUEL Policy NF-1
BAHRENS, F B Duke Power Co 79/04/02 3pp

9 Inspection reports, IE Bulletin & correspondence

9 Inspection reports, IE Bulletin & correspondence

7904250695 Forward IE Insp Repts 30-491/79-04, 30-492/79-04 & 30-493/79-04 on 790313-16 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Office of the Director 79/04/06 3pp

7904250695 Forward IE Insp Repts 30-491/79-04, 30-492/79-04 & 30-493/79-04 on 790313-16 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Office of the Director 79/04/06 3pp

--7904250695 IE Insp Repts 30-491/79-04, 30-492/79-04 & 30-493/79-04 on 790313-16 No noncompliance noted Major areas inspected GA program, tank procedures, Part 31 implementation, containment plate welding & vendor surveillance
BAUSCH, J H Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/01 3pp

--7904250695 IE Insp Repts 30-491/79-04, 30-492/79-04 & 30-493/79-04 on 790313-16 No noncompliance noted Major areas inspected GA program, tank procedures, Part 31 implementation, containment plate welding & vendor surveillance
BAUSCH, J H Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/01 3pp

7904250695 Response to IE Bulletin 79-04 Valve valves not in use
DALL, L C Duke Power Co 79/04/21 1p

7904250695 Response to IE Bulletin 79-04 Valve valves not in use
DALL, L C Duke Power Co 79/04/21 1p

7904250695 Act receipt of IE Insp Repts 30-491/79-04, 30-492/79-04 & 30-493/79-04 on 790313-16 No noncompliance noted
DALL, L C Duke Power Co 79/05/08 1p

7904250695 Act receipt of IE Insp Repts 30-491/79-04, 30-492/79-04 & 30-493/79-04 on 790313-16 No noncompliance noted
DALL, L C Duke Power Co 79/05/08 1p

--7904250695 Forward IE Insp Repts 30-491/79-04, 30-492/79-04 & 30-493/79-04 on 790313-16 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/01 3pp

--7904250695 Forward IE Insp Repts 30-491/79-04, 30-492/79-04 & 30-493/79-04 on 790313-16 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/01 3pp

--7904250695 IE Insp Repts 30-491/79-04, 30-492/79-04 & 30-493/79-04 on 790313-16 No noncompliance noted Major areas inspected review of GA implementing procedures for safety-related structures & containment
BAUSCH, J H Region 2, Atlanta, Office of the Director 79/03/01 3pp

--7904250695 IE Insp Repts 30-491/79-04, 30-492/79-04 & 30-493/79-04 on 790313-16 No noncompliance noted Major areas inspected review of GA implementing procedures for safety-related structures & containment
BAUSCH, J H Region 2, Atlanta, Office of the Director 79/03/01 3pp

DOCKETED ITEMS

- 790600027 Responses to NRC 790413 re re violations noted in IE Insp
 Rept 30-491/79-03, 30-492/79-03, 30-493/79-03 Corrective
 actions taken used for soil & concrete aggregate tests will
 be put in regular calibration program
 GALLU, C Duke Power Co 79/03/29 1p
- 790600046 Forwarders IE Info Notice 79-12: "Attempted Damage to New Fuel
 Assembly" *
 O'REILLY, J P Region 2: Atlanta Office of the Director
 79/03/16 1p
- 0 Reportable occurrences, LERs & related correspondence
- 790600034 Forwarders Final Rept 79/01-39B-491/492/493 re recall of
 pipe fittings
 GALLU, C Duke Power Co 79/03/10 1p
- 790600031 Final Rept 79/01-39B-491/492/493 used fittings w/lot number
 00779 contained erroneously identified high carbon steel
 nuts that could crack when being welded All nuts returned
 to vendor on 790412
 * Duke Power Co 79/03/11 1p
- DOCKET 5111-50-415 WENDELM-F1

 A Application/construction stage documents & correspondence
- 790601018 Forwarders Amend 2 to Preliminary Design Approval-4 & FB
 notice
 BORD, B Division of Project Management 79/03/04 7pp
- 790601017 Extends expiration date of Preliminary Design Approval-4
 from 790503 to 790603
 BORD, B Division of Project Management 79/03/04 2pp
- 790600917 Notices of extension of expiration date of Preliminary
 Design Approval-4 from 790503 to 790603
 MELTHERS, C Standardization Branch 79/03/04 4pp
- DOCKET 5111-50-408 DOWDY TEXAS PROJECT, UNIT 1

 A Application/construction stage documents & correspondence
- 790610044 Forwarders "Harviken Full-Scale Critical Flow Tests Interim
 Report/Results From Test 7" Rept to assist NRC in responding
 to request for justification of use of BAFAB-V methods for
 prediction of flow through orifices w/line
 PARR, D Light Water Reactors Branch 3 79/03/02 3pp
- 790600075 Requests add info by 790714 for review of FBAB
 PARR, D Light Water Reactors Branch 3 79/03/22 4pp
- 790601019 Summary of 790510 meeting w/att in Bethesda, MD re soil/
 structure interaction analysis
 LICHTEN, E A Light Water Reactors Branch 3 79/03/22 3pp
- 0 Adjudicatory correspondence
- 790600040 Notifies that L.A. Brinton will replace C Ryan as group
 representative before Board in petition for intervention in DL
 JAMES, B H Citizens Concerned About Nuclear Power, Inc 79/03/14
 8pp
- 790600095 Opposes applicant brief appealing ASLB prehearing
 conference order ruling on intervention petitions. Unanimous
 submission of petition to intervene due to mitigating
 circumstances
 BUCHHEIM, P Affiliation Unknown 79/04/30 13pp
- 790600040 Opposes Citizens Concerned About Nuclear Power, Inc 790604
 to respond to applicants' brief on appeal
 DRAPO, H E Atomic Safety and Licensing Appeal Panel 79/05/01 1p
- 790600041 Notice to strike applicant 790417 appeal & 790410 brief
 Brief & appeal are not in compliance w/NRC rules of
 practice Notice of appearance & Certificate of Doc encl
 SHIRIN, S A Citizens Concerned About Nuclear Power, Inc 79/05/01
 7pp
- 790600032 Responds to applicant 790417 brief appealing 790403
 prehearing conference order granting intervention petitions
 ASLB did not abuse its discretion nor err in finding
 standing Certificate of Doc encl
 HEDGECOCK, B Branch 1 ALMAN, H B Operations & Administrative
 Division 79/05/02 20pp
- 790600032 Denies motion by Citizens Concerned About Nuclear Power
 to strike applicant appeal from order granting
 intervention Applicant papers satisfy criteria of
 10CFR2.104
 BUCHHEIM, P Atomic Safety and Licensing Appeal Panel 79/05/02
 2pp
- 790610030 Supports ALAB-049 allowing Citizens Concerned About Nuclear
 Power, Inc to intervene at party appealing issuance of DL
 Denies Citizens for Equitable Utility petition to Board for
 judgment in favor of admission
 BUCHHEIM, H Atomic Safety and Licensing Appeal Panel 79/05/16
 13pp
- 790600095 Submits reformulated comments re denial of DL Petition
 has not been built in compliance w/safety system reasonable
 assurance exists re public health & safety & applicant has
 violated 10CFR50.54 of DC requirements
 SHIRIN, S A Citizens Concerned About Nuclear Power, Inc 79/05/29
 4pp
- K Utility Final Safety Analysis Report (FSAR) & amendments
- 790610034 Forwarders Amend 2 to FSAR Certificate of Doc encl
 TURNER, E A Houston Lighting & Power Co 79/04/11 3pp
- 790610033 Amend 2 to FSAR
 * Houston Lighting & Power Co 79/04/11 200pp
- H Antitrust correspondence
- 790600031 Notice of appearance of RO Berger on behalf of DOJ
 Certificate of Doc encl
 BERGER, H D Justice, Sept of 79/03/19 4pp
- 790600037 Answer of TX Util Co to 6 subpoenas re Central Power &
 Light's first set of interrogatories & request for
 production of documents Affidavit & Certificate of Doc encl
 WOODMAN, J L, BOWEN, D M D Houston, Forsythe & Bengels 79/03/28
 14pp
- 790600030 TX Util Generating Co discovery rept for Mar 1979
 requested to interrogatories & document requests from NRC,
 City of Houston & Central Power & Light & submitted
 response to NRC motion to compel w/Certificate of Doc
 WOOTEN, J B DeWitt & Liebman 79/04/02 2pp
- 790600032 Supplemental answers by TX Util Generating Co &
 subsidiaries to first set of interrogatories & request for
 production of documents from DOJ Supporting documentation &
 Certificate of Doc encl
 WOODMAN, J L, BOWEN, D M D Houston, Forsythe & Bengels 79/04/02
 40pp
- 790604047 Request by Houston Lighting & Power for extension until
 790420 for filing replies to motions for summary
 disposition Certificate of Doc encl
 BARNETT, E M Baker & Watts BARNETT, J A, FRANKLIN, W J
 Lowenstein, Newman, Reiss, Axelrod & Teitl 79/04/11 5pp
- 320129 Response by DOJ to various motions of Houston Lighting &
 w/ TX Util Generating Co & City of Austin Supporting
 documentation & Certificate of Doc encl
 WOOTEN, J L, BERGER, H O, SLABER, H H Justice, Sept of 79/04/23
 8p

790604004 Denies 790405 motion filed by Public Utility Board of City of Houston, TX to compel further production of documents by SOUTH TX Electric Cooperative & Hedine Cooperative
HILLER, H. E. Atomic Safety and Licensing Board Panel 79/04/03 2pp

790600001 Motion by Gulf States Utility Co for protective order re confidential info Requests production of documents per 790405 subpoena to condition an reimbursement of expenses Supporting documentation & Certificate of Svc encl
HETTERMAN, H. J. Conner, Moore & Corbin 79/04/03 2ppp

790602009 Adm responses by Houston Lighting & Power Co DOJ first set of interrogatories & request for production of documents
Certificate of Svc encl
COMPELLA, J. G. Baker & Butts 79/04/02 2ppp

790604008 Forwards second supplemental answer of TX Utility Generating Co to DOJ first interrogatories & requests for production of documents forwarded per 790405 subpoena
BLICKER, F. H. Harkins, Faraythe & Sampsel 79/04/02 3p

7906010043 Second supplemental answer by TX Utility Generating Co to DOJ first interrogatories & requests for production of documents Supporting documentation & Certificate of Svc encl
WISSEMAN, J. L. SAWYER, S. H. D. Harkins, Faraythe & Sampsel KNOTTS, J. D. Debevoise & Lieberman 79/04/02 2ppp

7906010043 Forwards reply of Houston Lighting & Power Co in support of motion for summary disposition Certificate of Svc encl
NEIDER, R. F. Baker & Butts 79/04/02 7pp

7906020020 Reply by Houston Lighting & Power Co in support of motion for summary judgment Urges that request for application of collateral estoppel against Central Power & Light be granted Certificate of Svc encl
BARRETT, E. W. Baker & Butts SCHWARTZ, J. A. Lounstein-Neuman, Hais, Asired & Tall 79/04/03 2ppp

7906020019 Responses by Public Utility Board of City of Brownsville, TX to Central Power & Light Co first set of interrogatories & request for production of documents Certificate of Svc encl
WISSEMAN, J. L. Spiegel & McDermid 79/04/03 3ppp

7906020015 Answer in opposition to Houston Lighting & Power motion to compel NRC production of privileged documents Certificate of Svc encl
LEBBY, R. F. BLAKE, H. Anti-Trust Division 79/04/03 10pp

7906020029 Responses by Houston Lighting & Power to NRC 790419 motion for reconsideration of ASLB 790418 order Requests that ASLB affirm order on creation of new documents not retained in National Archive of business Certificate of Svc encl
SCHWARTZ, J. A. FRANKLIN, H. J. Lounstein-Neuman, Hais, Asired & Tall BARRETT, E. W. Baker & Butts 79/04/03 11pp

7906020020 Reply by TX Utility Generating Co to combined answer of Central Power & Light & Central & Northeast in opposition to demand 790405 motion to dismiss Central & Northeast as intervenor Support documentation & Certificate of Svc encl
KNOTTS, J. D. Debevoise & Lieberman, WISSEMAN, J. L. SAWYER, S. H. D. Harkins, Faraythe & Sampsel 79/04/03 10pp

7906040090 Supplemental motion by Gulf States Utility seeking protective order re confidential info Requesting further complicity
w/ subpoena Certificate of Svc encl
RAIDER, R. R. Conner, Moore & Corbin 79/04/03 App

7906040084 Discovery progress report for Apr 1979 Responded to TX Utility Generating Co & Houston Lighting & Power interrogatories Re: utility on 790405 NRC's of Svc encl
HARRIS, J. L. WISSEMAN, J. D. CLARK, R. H. Justice, Dept of 79/04/03 App

7906020029 Forwards Public Utility Board of City of Brownsville, TX response to Houston Lighting & Power Co first set of interrogatories & first request for production of documents Affidavit & Certificate of Svc encl
WISSEMAN, J. L. Spiegel & McDermid 79/05/02 App

7906020020 Public Utility Board of Brownsville response to Houston Lighting & Power Co first interrogatories & first request for production of documents
WISSEMAN, J. L. Spiegel & McDermid 79/05/02 11pp

7906020076 TX Utility Generating Co answer to Central Power & Light 790418 motion to compel further production of documents to Southern Interrogatories Previously supplied answers are complete & retrieved demands by Central Power are redundant
KNOTTS, J. D. Debevoise & Lieberman, WISSEMAN, J. L. Harkins, Faraythe & Sampsel 79/05/02 App

7906020062 Records Apr 1979 discovery progress report for City of San Antonio Certificate of Svc encl
HILLER, H. E. Matthews, Neulim, McFarlane & Barnett 79/05/02 App

7906070034 Discovery status report for Apr 1979 NRC filed answer in opposition to motion of Houston Lighting & Power Co to compel production of privileged documents
LEBBY, R. F. Anti-Trust Division 79/05/03 2pp

7906040028 TX Utility Generating Co discovery progress report for Apr 1979 responded to interrogatories from DOJ, not w/ ASLB & answered to conditions remaining discovery w/ City of Brownsville, TX Certificate of Svc encl
KNOTTS, J. D. Debevoise & Lieberman 79/05/04 5pp

7906020051 South TX Electric Cooperative & Hedine Electric Cooperative monthly discovery report for Apr 1979 no new discovery requests initiated or received during month
JOHN, O. F. Allin, Bump, Hauer & Field 79/05/04 App

7906010040 Responses by Houston Lighting & Power to Central Power & Light 790420 motions to compel answers to interrogatories Provides info re preparation of previous answers Certificate of Svc encl
BARRETT, E. W. Baker & Butts 79/05/05 10pp

7906010040 Rules on discovery, in response to NRC 790419 motion for reconsideration of ASLB 790418 order Upholds order re production of settlement documents & regarding Houston Lighting & Power from producing certain documents
HILLER, H. E. Atomic Safety and Licensing Board Panel 79/05/07 2pp

7906040020 Second request for still supplemental production of non-technical documents
BLAKE, H. Anti-Trust Division 79/05/08 1p

7906020012 Answer by Public Utility Board of City of Brownsville, TX to 790420 & 790430 motions by Gulf States utility re compliance w/ 790420 subpoena Duce from ASLB Supporting documentation & Certificate of Svc encl
HARRIS, J. L. FRANKLIN, H. J. Spiegel & McDermid 79/05/10 96pp

7906020027 Answer in opposition to Gulf States Util 790420 motion for protective order & for order setting conditions for compliance w/ 790420 subpoena for production of documents
Certificate of Svc encl
HARRIS, J. L. Justice, Dept of 79/05/11 15pp

7906020017 Notice of appearance by RD Cyphert & MI Clark on behalf of DOJ Certificate of Svc encl
CYPERT, E. S. CLARK, R. H. Justice, Dept of 79/05/11 5pp

7906020024 Houston Lighting & Power Co petition for subpoena until 790529 to compel further responses from Public Utility Board of City of Brownsville, TX Adm time required to determine scope of planned motion Certificate of Svc encl
FRANKLIN, H. J. SCHWARTZ, J. A. Lounstein-Neuman, Hais, Asired & Tall BARRETT, E. W. Baker & Butts 79/05/11 5pp

7906010017 Answers first set of interrogatories & request for production of documents submitted by TX Utility Generating Co Supporting documentation & Certificate of Svc encl
LEBBY, R. F. BLAKE, H. Anti-Trust Division 79/05/14 10pp

7906020012 Notice of 790405 conference in Bethesda, MD to discuss pending motions & responses re discovery & summary disposition
HILLER, H. E. Atomic Safety and Licensing Board Panel 79/05/15 1p

7906020025 Motion by Houston Lighting & Power to include Central Power & Light until ASLB 790409 protective order setting limits for production of confidential documents to Public Utility Board of City of Brownsville, TX Certificate of Svc encl
BARRETT, E. W. Baker & Butts, SCHWARTZ, J. A. Lounstein-Neuman, Hais, Asired & Tall 79/05/15 7pp

7906070034 Motion by Gulf States Utility Co to file brief in reply to DOJ & City of Brownsville, TX answers to previous utility motion & supplemental action for protective order seeks to clarify third party status.
HETTERMAN, H. J. RAIDER, R. R. Conner, Moore & Corbin 79/05/16 7pp

7906070013 Grants Houston Lighting & Power Co 790611 motion for extension of time until 790529 for filing motion to compel further production from City of Brownsville, TX
HILLER, H. E. Atomic Safety and Licensing Board Panel 79/05/16 1p

7906010024 Requests RM Rider & OH Clements to add to svc list
RAIDER, R. R. Conner, Moore & Corbin 79/05/16 1p

790600096 All Houston Lighting & Power confidential documents, produced for Public Utility Board of City of Brownsville, TX & reviewed by Central Power & Light, shall be subject to terms & conditions of 7904009 protective order
HILLMAN, H E Atomic Safety and Licensing Board Panel 79/05/18 1p

790610040 Grants Gulf States Unit 790504 motion requesting leave to file reply brief in response to DOJ & City of Brownsville, TX answers to will request for protective order
HILLMAN, H E Atomic Safety and Licensing Board Panel 79/05/22 1p

790620023 Gulf State Unit reply brief to DOJ & Public Utility Board of City of Brownsville, TX answers in response to will motion for protective order & order setting conditions for compliance of respondents affidavit & Certificate of Gov and
WETTERHOLM, J J, RADER, R M, Carner, Moore & Conner 79/05/31 37pg

790620096 TX Utility Generating Co documents re: Feb Mar 1979 all provide supplementary responses to NRC interrogatories & requests for production of documents Certificate of Gov and
KNOTTS, J R, Delavigne & Lieberman 79/06/04 3pg

G Inspection reports, IE Bulletins & correspondence

790635004 Forwards IE Insp Repts: 90-498/79-04 & 90-499/79-04 on 790320-23 & notice of violation
GILLMAN, H E Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/11 2pg

--790635007 Notice of violation from insp on 790320-23
Region 4, Dallas, Office of the Director 79/04/11 3pg

--790635001 IE Insp Repts 90-498/79-04 & 90-499/79-04 on 790320-23 Noncompliance notes failure to follow concrete placement procedures
HILLMAN, H E Region 4, Dallas, Office of the Director
HALL, R E Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/11 3pg

790618002 Forwards IE Bulletin 79-050: "Nuclear Incident at TMI-Supp" No written response required
HILLMAN, H E Region 4, Dallas, Office of the Director 79/04/21 1p

790618007 Second interim report of reportable deficiency dimensional error in base stat of mechanical-electrical Unit 2 auxiliary piping determines progress on reduction of piping
Final report will not be available by 790501
TURNER, E A Houston Lighting & Power Co 79/04/24 2pg

790620019 Confirms 790405 & 27 letters re improper storage of reinforcing steel NRC understands that steel has found no significant degradation exist from reinforcing steel requirements of site quality control procedures
BENNETT, H V Region 4, Dallas, Office of the Director 79/05/01 2pg

7906120037 Forwards IE Insp Notice 79-11: "Lower Reactor Vessel Head Insulation Support Problem" No action required
BENNETT, H V Region 4, Dallas, Office of the Director 79/05/02 1p

Repaired Damage to New Fuel
The Director 79/05/11

H Reportable occurrences, LERs & related correspondence

790618004 Forwards PNO-79-07A7
GILLMAN, H E Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/08 1p

790618017A Forwards PNO-79-07A7
GILLMAN, H E Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/16 1p

790618004 Forwards PNO-79-07A7
GILLMAN, H E Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/22 1p

790618030 Forwards PNO-79-07A7
GILLMAN, H E Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/23 1p

790618030 Forwards Final deficiency report re concrete voids behind liner plate in reactor slag separator wall
TURNER, E A Houston Lighting & Power Co 79/06/03 1p

--790618037 Final deficiency report on 790505 12th lift concrete voids caused by inadequate planning for large pour, long pour time, longer than normal slick lines & concrete pump breakdowns. Immediate & long-term corrective actions have been effected
Houston Lighting & Power Co 79/06/10 1pg

790618036 Second interim report of deficiency re improper anchor bolt metal rebar with not submitted until 790610 due to complexity of identifying & testing suspect bolts
TURNER, E A Houston Lighting & Power Co 79/06/03 2pg

790618007 Forwards Final deficiency report re failure to properly conduct application of certain prestressed loads in interior structural steel beam. Deficiency would not have resulted in significant safety hazard
TURNER, E A Houston Lighting & Power Co 79/06/03 2pg

--790618008 Final deficiency report on 790505 beam-to-column connection caused by human error & inadequate prestressing bearing beams have been manipulated, errors corrected & calculations design verified
Houston Lighting & Power Co 79/06/05 3pg

790620067 Interim deficiency report on 790516 essential cooling water pump cranes not designed to withstand DBT caused by breakdown in design change program Design & change procedure being corrected
TURNER, E A Houston Lighting & Power Co 79/06/10 2pg

I Hearing transcripts on non-confidential matters

790618036 Transcript of 790601 hearing in Delavigne, RD # 910-471
HILLMAN, H E, BOWTE, B J Atomic Safety and Licensing Board Panel 79/06/01 25pg

J Congressional/Executive Correspondence

790620040 Requests info on Westinghouse reactor design & possibility of facility not in light of TMI incident
FISCHLE, J J Moves of Rep 79/04/25 2pg

790620027 Responses to 790416 letter which forwarded J Lorry 790406 letter requesting info on safety of plant construction & operation
Forwards Summary of Progress of South TX Plant. Providing general info re facility
GIBBONS, J V Office of the Executive Director for Operations 79/05/20 4pg

--790620028 Forwards J Lorry 790404 letter requesting info on safety of plant construction & operation
GIBBONS, J V Senate 79/06/16 2pg

K 90-499 SOUTH TEXAS PROJECT, UNIT 3

Application/Construction stage documents & correspondence

10414 Forwards "Harboran Full-Scale Critical Flow Tests Interim Results from Test 7" Request to assist NRC in responding request for justification of use of SNTAG-J methods for dictum of flow through orifices R.O. and
Light Water Reactors Branch 3, 79/05/28 3pg

30875 Requests add info by 790716 for review of PBR
R.O. Light Water Reactors Branch 3 79/05/32 3pg

DOCKETED ITEMS

790402904000 Summary of 790310 meeting (until in Bethesda, MD re soil structure interaction analysis)
LUCITRA, E. A. Light Water Reactors Branch 2 79/03/20 3pp

G Adjudicatory correspondence

790402904000 Reaffirms that LA Smith will replace C. Ryan as group representative before Board in petition to intervene in G. request by mail Certificate of Div. encl
JAMES, R. H. Citizens Concerned About Nuclear Power, Inc 79/04/14 3pp

79040290200 Motion for continuance so as to comply w/ASLB 790400 order re intervention Certificate of Div. encl
JUGHORN, P. Affiliation Unknown 79/04/22 3pp

79040290300 Applicants' supplemental memo re 790417 appeal of 790403 prehearing conference order Since Justice Citizens for Ecological Energy have not filed info per order, 790417 appeal should be treated as most Certificate of Div. encl
HUBBARD, J. H., HUBBARD, J. P. Louisiana-Journal News-Advertiser & Tall Timber 79/04/27 3pp

79040290100 Intervenor's motion for extension of time, until 790514, to respond to applicant's Brief in appeal
KRAMER, L. A. Citizens Concerned About Nuclear Power, Inc 79/04/20 1p

79040290200 Grants NRC 790403 motion for extension until 790509 for parties to file reply on conditions
BECHTOLD, C. Atomic Safety and Licensing Board Panel 79/04/20 2pp

79040290500 Opposes applicant brief appealing ASLB Preliminary conference order noting on intervention petitions Unlimited submission of petition to intervene due to violating circumstances
BUCHHEIM, P. Affiliation Unknown 79/04/20 13pp

79040290400 Grants Citizens Concerned About Nuclear Power until 790514 to respond to applicant's Brief in appeal
DUFFLOH, E. Atomic Safety and Licensing Appeal Panel 79/05/01 1p

79040290500 Motion to strike applicant 790417 appeal & 790416 Brief Brief & appeal are not in compliance w/NRC rules of practice Notice of appearance & Certificate of Div. encl
HELMKE, E. A. Citizens Concerned About Nuclear Power, Inc 79/05/01 2pp

79040290500 Responds to applicant 790417 Brief appealing 790403 prehearing conference order granting intervention petitions ASLB did not about its discretion nor are its findings standing Certificate of Div. encl
HUGHES, R. H. Branch 3 ULMAN, H. B. Operations & Administrative Division 79/05/02 21pp

79040290100 Denies motion by Citizens Concerned About Nuclear Power to strike applicant appeal from order granting intervention Applicant asked ruling criteria of 10CFR 70.4
SHURTLE, R. H. Atomic Safety and Licensing Appeal Panel 79/05/07 3pp

79040290400 Suggests ASLB-May allowing Citizens Concerned About Nuclear Power, Inc to intervene at early opening issuance of G. Since Citizens for Ecological Energy petition to Board for judgment in favor of admission
SHURTLE, R. H. Atomic Safety and Licensing Appeal Panel 79/05/10 33pp

79040290400 Submits reformulated combinations re denial of G. Facility has been built in compliance w/safety, etc., no reasonable assurance exists re public health & safety & applicant has violated 10CFR 70.4 of OC requirements
SHURTLE, R. A. Citizens Concerned About Nuclear Power, Inc 79/05/29 3pp

K Utility Final Safety Analysis Report (FSAR) & amendments

79040290310 Forwards ASLB 0 to FSAR Certificate of Div. encl
TURNER, E. A. Houston Lighting & Power Co 79/05/11 3pp

--790403010 ASLB 0 to FSAR
* Houston Lighting & Power Co 79/05/11 300pp

M Antitrust correspondence

79040290110 Notice of appearance of RD Berger on behalf of DOJ Certificate of Div. encl
BERGER, M. D. Justice Dept of 79/03/19 4pp

79040290317 Answer of TX Util Co & subsidiaries to Central Power & Light's first set of interrogatories & request for production of documents Affidavit & Certificate of Div. encl
WERNER, J. I. Wernham, Forsythe & Samuels 79/03/20 14pp

79040290300 TX Util's Generating Co discovery reply for Mar 1979 responses to interrogatories & document requests from HRC, City of Brownsville & Central Power & Light & submitted response to HRC motion to compel w/Certificate of Div. encl
HODGES, J. B. Debevoise & Lieberman 79/04/03 3pp

79040290300 Supplemental answers by TX Util's Generating Co & subsidiaries to first set of interrogatories & request for production of documents from DOJ Supporting documentation & Certificate of Div. encl
WERNER, J. I. Wernham, Forsythe & Samuels 79/04/11 40pp

7904040417 Request by Houston Lighting & Power for extension, until 790430, to file reply to motions for summary disposition Certificate of Div. encl
BARNETT, E. W. Baker & Botts 79/04/11 3pp

79040290120 Response by DOJ to various motions of Houston Lighting & Power, TX Util's Generating Co & City of Austin Supporting documentation & Certificate of Div. encl
HARRIS, J. L. Justice Dept of 79/04/20 62pp

7904040404 Denies 790403 motion filed by Public Util Board of City of Brownsville, TX to compel further production of documents by South TX Electric Cooperative & Austin Cooperative MILLER, H. E. Atomic Safety and Licensing Board Panel 79/04/23 2pp

79040290140 Motion by Gulf States Util Co for protective order re confidential info Requests production of documents per 790402 subpoena be conditioned on reimbursement of expenses Supporting documentation & Certificate of Div. encl
WELSHMAN, H. J. Cooney, Moore & Corbin 79/04/20 23pp

79040290307 Adds responses by Houston Lighting & Power to DOJ first set of interrogatories & requests for production of documents Certificate of Div. encl
GENDLAND, J. D. Baker & Botts 79/04/27 31pp

79040290304 Forwards second supplemental answer of TX Util's Generating Co to DOJ first interrogatories & requests for production of documents forwarded per 790410 meeting
GLOVER, P. K. Wernham, Forsythe & Samuels 79/04/27 1p

--79040290402 Second supplemental answer by TX Util's Generating Co to E first interrogatories & requests for production of documents Supporting documentation & Certificate of Div. encl
WERNER, J. I. Wernham, Forsythe & Samuels 79/04/27 24pp

79040290400 Forwards reply of Houston Lighting & Power Co in support of motion for summary disposition Certificate of Div. encl
GIBBS, R. F. Baker & Botts 79/04/20 7pp

79040290400 Reply by Houston Lighting & Power Co in support of motion for summary judgment. Urges that request for application of collateral estoppel against Central Power & Light be granted Certificate of Div. encl
BARNETT, E. W. Baker & Botts SCHUBERT, J. A. Louisiana-Journal News-Advertiser & Tall Timber 79/04/30 33pp

79040290119 Response by Public Util Board of City of Brownsville, TX to Central Power & Light Co first set of interrogatories & request for production of documents Certificate of Div. encl
MILLER, H. A. Siegel & McDonald 79/04/30 33pp

79040290400 Answer in opposition to Houston Lighting & Power motion to compel NRC production of privileged documents Certificate of Div. encl
LESTER, R. Anti-Trust Division 79/04/20 10pp

79040290309 Response by Houston Lighting & Power to NRC 790419 motion for reconsideration of ASLB 790416 order Requests that ASLB affirm order re revocation of new documents not maintained in normal course of business Certificate of Div. encl
SCHUBERT, J. A. Louisiana-Journal News-Advertiser & Tall Timber 79/04/30 11pp

79040290300 Reply by TX Util's Generating Co to combined answer of Central Power & Light & Central & Southwest in opposition to former's 790403 motion to disallow Central & Southwest as intervenor Supporting documentation & Certificate of Div. encl
HODGES, J. B. Debevoise & Lieberman 79/04/30 11pp

DOCKETED ITEMS

- 7906060203 Supplemental notice by Gulf States Unit amending protective order & order for setting conditions for compliance with subpoena Certificate of Doc encl
HALLER, H.E. Cameron, Moore & Corbin 7/10/03 3pp
- 7906190504 Discovery progress report for Apr 1979 requested by TX Utility Generating Co. & Houston Lighting & Power Interrogatories Re: w/790514 Certificate of Doc encl
HARRIS, J.L. Justice, Dept of 7/10/03 3pp
- 7906200204 Forward Public Utility Bonds of City of Brownsville, TX responses to Houston Lighting & Power first interrogatories & first request for interrogatories & first request for production of documents Affidavit & Certificate of Doc encl
HARRIS, J.L. Spiegel & McDaniel 7/10/03 3pp
- 7906200304 Public Utility Board of Brownsville responses to Houston Lighting & Power Co. first interrogatories & first request for production of documents
JANLOR, R.A. Spiegel & McDaniel 7/10/03 11pp
- 7906200306 TX Utility Generating Co. answer to Central Power & Light 790620 motion to compel further responses to latter's interrogatories & requests for production of documents complete & fair/adequate demands by Central Power are returned
HARRIS, J.L. Delavolpe & Lieberman 7/10/03 3pp
- 7906270202 Subpoena Apr 1979 discovery progress report for City of San Antonio Certificate of Doc encl
WILSON, H.H. Matthews, Howland, MacFarlane & Gerratt 7/10/03 4pp
- 7906270203 Discovery status report for Apr 1979 H&L Piller answer in opposition to motion of Houston Lighting & Power Co. to compel production of privileged documents
LEWIS, R.P. Anti-Trust Division 7/10/03 3pp
- 7906040202 TX Utility Generating Co. discovery progress report for Apr 1979 responses to Interrogatories from SOJ, not w/790514 H&L & H&L & answered to subordinate remaining discovery activity of Brownsville, TX Certificate of Doc encl
HARRIS, J.L. Delavolpe & Lieberman 7/10/03 3pp
- 7906230101 South TX Electric Cooperative & Medina Electric Cooperative monthly discovery report for Apr 1979 no new discovery requests initiated on received during month
JOHN, B.R. Allen, Geop. Survey & Field 7/10/03 3pp
- 7906190101 Response by Houston Lighting & Power to Central Power & Light 790620 motions to compel answers to interrogatories. Provides late re preparation of previous answers Certificate of Doc encl
BARNETT, E.W. Baker & Burke 7/10/03 10pp
- 7906190405 Rules on discovery in response to H&L 790619 motion for reconsideration of H&L 790619 order. Includes order re production of settlement documents & recording Houston Lighting & Power from producing taxable documents
HALLER, H.E. Atomic Safety and Licensing Board Panel 7/10/03 7pp
- 7906040002 Second request for utility supplemental production of nonprivileged documents
BARNETT, E.W. Anti-Trust Division 7/10/03 3pp
- 7906020107 Answer by Public Utility Board of City of Brownsville, TX to 790625 & 790430 motions by Gulf States Unit re compliance w/790504 subpoena duces tecum from H&L Supporting documentation & Certificate of Doc encl
HARRIS, J.L. Spiegel & McDaniel 7/10/03 10pp
- 7906230203 Answer in opposition to Gulf States Unit 790625 motion for protective order & order setting conditions for compliance w/790504 subpoena for production of documents Certificate of Doc encl
HARRIS, J.L. Justice, Dept of 7/10/03 13pp
- 7906230107 Notice of appearance by SE Ophart & RH Clark on behalf of COJ Certificate of Doc encl
CHIFFERT, D.B. Justice, Dept of 7/10/03 1pp
- 7906230204 Houston Lighting & Power Co. petition for extension until 790629 to compel further responses from Public Utility Board of City of Brownsville, TX. Addl. time required to delineate scope of planned motion Certificate of Doc encl
PARKER, SH. J. Lounsbury, Neuman-Roth-Asford & Bell 7/10/03 1pp
- 7906190407 Answers first set of Interrogatories & request for production of documents submitted by TX Utility Generating Co. Supporting documentation & Certificate of Doc encl
LEWIS, R.P. Anti-Trust Division 7/10/03 10pp
- 7906070212 Notice of 790601 conference in Deland, MD to discuss pending motions & responses re discovery & summary disposition
HALLER, H.E. Atomic Safety and Licensing Board Panel 7/10/03 1p
- 7906200105 Motion by Houston Lighting & Power to include Central Power & Light within H&L 790609 protective order setting terms for production of confidential documents to Public Utility Board of City of Brownsville, TX Certificate of Doc encl
BARNETT, E.W. Baker & Burke 7/10/03 3pp
- 7906070305 Motion by Gulf States Unit Co. to file brief in reply to SOJ & City of Brownsville, TX answers to previous utility motion & supplemental motion for protective order. Goals to clarify third party status
WETTERMAN, W.J. Cameron, Moore & Corbin 7/10/03 1pp
- 7906070315 Grants Houston Lighting & Power Co. 790511 motion. Parties answer of time, until 790629, for filing motion to compel further production from City of Brownsville, TX
HALLER, H.E. Atomic Safety and Licensing Board Panel 7/10/03 1p
- 7906190104 Requests for H&L & H&L Elements be added to sub list
HARRIS, J.L. Cameron, Moore & Corbin 7/10/03 1p
- 7906230204 All Houston Lighting & Power confidential documents, produced for Public Utility Board of City of Brownsville, TX & returned by Central Power & Light, shall be sub. to terms & conditions of 790609 protective order
HALLER, H.E. Atomic Safety and Licensing Board Panel 7/10/03 1p
- 7906130410 Grants Gulf States Unit Co. 790504 motion requesting leave to file brief in reply to answers to SOJ & City of Brownsville, TX answers to utility request for protective order
HALLER, H.E. Atomic Safety and Licensing Board Panel 7/10/03 1p
- 7906230203 Gulf State Unit reply brief to OJA & Public Utility Board of City of Brownsville, TX answers in response to utility motion for protective order & order setting conditions for compliance w/790504 subpoena & Certificate of Doc encl
WETTERMAN, W.J. Cameron, Moore & Corbin 7/10/03 11pp
- 7906230505 TX Utility Generating Co. discovery report for May 1979 still provided supplementary responses to H&L Interrogatories & requests for production of documents Certificate of Doc encl
HARRIS, J.L. Delavolpe & Lieberman 7/10/03 3pp
- Q Inspection reports, IE Bulletins & correspondence
- 7906230014 Forwards IE Insp Repts 50-498/79-04 & 50-499/79-04 on 790620-23 & notice of violation
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 7/10/03 2pp
- 7906250047 Notice of violation from Insp on 790620-23
+ Region 4, Dallas, Office of the Director 7/10/03 1pp
- 7906230203 IE Insp Repts 50-498/79-04 & 50-499/79-04 on 790620-23
Noncompliance noted Failure to follow concrete placement procedures
HARRIS, J.L. Region 4, Dallas, Office of the Director 7/10/03 1pp
- 7906230203 IE Insp Repts 50-498/79-04 & 50-499/79-04 on 790620-23
HARRIS, J.L. Region 4, Dallas, Reactor Construction & Engineering Support Branch 7/10/03 1pp
- 7906190302 Forwards IE Bulletin 79-058, "Nuclear Incident at OJA-S&P" & no written response required
SEIDLE, W.C. Region 4, Dallas, Office of the Director 7/10/03 1pp
- 7906230107 Second interim report of reportable deficiency dimensional error in base slab of mechanical/electrical Unit 2 monitoring slab. Describes progress on redesign of slab
Final report will be available by 790601
TURNER, E.A. Houston Lighting & Power Co. 7/10/03 2pp
- 7906230104 Confirms 790626 & 27 letters re improper storage of reinforcing steel. AEC understands that unit has found no significant departures exist from reinforcing steel requirements of site quality control procedures
SEIDLE, W.C. Region 4, Dallas, Office of the Director 7/10/03 1pp
- 7906190407 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Inspection Support Problem" & no action required.
SEIDLE, W.C. Region 4, Dallas, Office of the Director 7/10/03 1p

DOCKETED ITEMS

209

7906250019 Forwards IE Info Notice 79-12: "Attempted Damage to New Fuel Assembly"
SEYFERT, K V Region 4, Dallas, Office of the Director 79/05/11 1p

7906180138 Ack receipt of 790503 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-466/79-04 & 30-467/79-04
SEIBLER, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/16 1p

--7906120141 Responds to NRC 790411 ltr re violations noted in IE Insp Repts 30-466/79-04 & 30-467/79-04 Corrective actions concrete placement procedure training session held on 790511
TURNER, E A Houston Lighting & Power Co 79/05/03 2pp

7906120047 Forwards IE Bulletin 79-11: "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys - License Action Required"
SEYFERT, K V Region 4, Dallas, Office of the Director 79/05/22 1p

B. Reportable occurrences, LERs & related correspondence

7906180134 Forwards PWD-79-A20H
SEIBLER, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/03 1p

7906180134 Forwards PWD-79-A20H
SEIBLER, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/03 1p

7906180243 Forwards PWD-79-A2AD
SEIBLER, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/22 1p

7906180230 Forwards PWD-79-A2AP
SEIBLER, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/23 1p

7906180290 Forwards Final deficiency rept re concrete valve behind liner plate in reactor bldg exterior wall
TURNER, E A Houston Lighting & Power Co 79/05/03 1p

--7906120372 Final deficiency rept on 791020 1544 lift concrete valve caused by inadequate planning for large gear-long pour time longer than normal silica fumes & concrete pump breakdowns immediate & long-term corrective actions have been effected
Houston Lighting & Power Co 79/06/13 13pp

7906120430 Second interim rept of deficiency re improper anchor bolt used Final rept will not be submitted until 790815 due to complexity of identifying & testing suspect bolts
TURNER, E A Houston Lighting & Power Co 79/06/03 2pp

7906120007 Forwards Final deficiency rept re failure to properly consider application of certain postulated loads in interior structural steel beam deficiency would not have resulted in significant safety hazard
TURNER, E A Houston Lighting & Power Co 79/06/03 2pp

--7906130038 Final deficiency rept on 791028 beam-to-column connections caused by human error & inadequate postseismic training Beams have been reanalyzed, errors corrected & calculations design verified
Houston Lighting & Power Co 79/06/03 6pp

7906120637 Interim deficiency rept on 790816 essential cooling water gentry crane not designed to withstand SET Caused by breakdown in design change program Design & change procedure being corrected
TURNER, E A Houston Lighting & Power Co 79/06/13 6pp

F. Hearing transcripts on non-initiated matters

7906180734 Transcripts of 790601 hearing in Bethesda, MD Re 210-471
MILLER, M E & WILPE, B J Atomic Safety and Licensing Board Panel 79/06/01 200pp

G. Congressional/Executive Correspondence

7906070342 Requests info on Westinghouse reactor design & possibility of facility used in light of TMI incident
FISHER, J J House of Reps. 79/06/28 2pp

7906250071 Responds to 790416 ltr which forwarded J Lowry 790404 ltr requesting info on safety of plant tests & operation
Forwards "Summary of Progress of South TX Plant," providing general info re facility
SEIBLER, L V Office of the Executive Director for Operations 79/05/23 4pp

--7906200085 Forwards J Lowry 790604 ltr requesting info on safety of plant tests & operation
SEIBLER, L V Senate 79/06/16 2pp

DOCKET 30-300 DAVID-BESSIE NUCLEAR POWER STATION, UNIT 2

A. Application/Construction stage documents & correspondence

7904210001 Forwards revision to BOR re design criteria & bases for protection against dynamic effects associated w/postulated rupture of piping outside containment
HARRIS, D H Plant Systems Branch 79/03/29 6pp

F. Security, medical, emergency & fire protection plans

7906250003 Emergency Procedure 1202 24 steam supply stop rupture
SERIN, L & HARRAY, T D Toledo Edison Co 79/06/02 17pp

D. Adjudicatory correspondence

7906180447 Motion for extension until 790601 to prepare response to ALAB-509
SCOTT, J F Hearings Division 79/06/02 2pp

--7906210360 Responds to 790322 request for info re status of reanalyzing proposed to develop value for radon in Table 6-3a Rept & prepared role will be sent to NRC by 790604 Rept does not address health effects of radon releases
CHRISTENSEN, E Hearings Division 79/03/26 13pp

7906120075 NRC motion for summary disposition re radon issue was in error ALAB-540 consolidated only 5 of 16 cases Series NRC motion as to parties in other proceedings Certificate of Dec
GULF, H E Atomic Safety and Licensing Appeal Panel 79/03/28 3pp

J. Insurance & indemnity information

7906250336 Forwards Endorsements 23 & 25 to H&L Policy #9-92
LUDWIG, D Marsh & McLennan, H & H Reinsurer Consultants Inc 79/06/15 2pp

H. Antitrust correspondence

7906250064 Notification that certain documents were removed from ALAB hearings desk by unauthorized person Documents found in another off investigation initiated
GULF, H E Atomic Safety and Licensing Appeal Panel 79/05/02 3pp

DOCKETED ITEMS

--7904200236 Responds to 781107 memo re investigation of document removal info partly withheld due to enforcement proceedings (ref FOIA Exemption 7A) BURLIN, C L Division of Security 78/12/04 2pp

--7904200234 Comments on OIC of Inspector & Auditor report re investigation of document removal info partly withheld due to enforcement proceedings (ref FOIA Exemption 7A & 7E) Forwards Washington Post article, 5/12/83 articles HARRIS, T F Office of Inspector & Auditor 79/02/28 3pp

--7904200264 Comments on OIC of Inspector & Auditor report re investigation of document removal info partly withheld due to enforcement proceedings (ref FOIA Exemption 7E) CUMMINGS, J J Office of Inspector & Auditor 79/02/28 2pp

DOCKET 55-550 HAVEN NUCLEAR POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

7904200203 Forwards revision to NRC re design criteria & bases for protection against dynamic effects associated with calculated rupture of piping outside containment HARRIS, B H Plant Systems Branch 79/03/29 6pp

F Security, medical, emergency & fire protection plans

7904200309 Emergency Procedures 1202 24 steam supply pipe rupture BURLIN, C L HARRIS, T F Telsco Edison Co 79/04/02 2pp

G Adjudicatory correspondence

7904200447 Motion for extension until 790415 to prepare response to ALAD-509 SCINTO, J F Hearings Division 79/04/02 2pp

--7904200505 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table G-2 Rept 6 proposed rule will be sent to NRC by 790408 Rule does not address health effects of radon releases CHRISTENSEN, E Hearings Division 79/03/25 3pp

7904200505 NRC motion for summary disposition re radon issue was in error ALAD-340 consolidated only 5 of 16 counts. Denies NRC motion as to parties in other proceedings Certificate of Gov sent BURLIN, C L Atomic Safety and Licensing Appeal Panel 79/03/28 3pp

J Insurance & indemnity information

7904200524 Forwards Endorsements 22 & 23 to HALL/Poling H-92 LLOYD, R S Harris & McLean H & H Nuclear Consultants, Inc Div 79/04/15 2pp

K Antitrust correspondence

7904200566 Notifies that certain documents were removed from ALAD secretary's desk by unauthorized person Documents found on another site investigation initiated BURLIN, C L Atomic Safety and Licensing Appeal Panel 78/10/08 2pp

--7904200570 Forwards ALAD memo issued in Davis-Besse & Perry proceeding re missing papers in file ROBERTSON, A B Atomic Safety and Licensing Appeal Panel 78/10/03 1p

--7904200330 Comments on OIC of Inspector & Auditor report re investigation of document removal info partly withheld due to enforcement proceedings (ref FOIA Exemption 7A) ROBERTSON, A B Atomic Safety and Licensing Appeal Panel 78/11/03 2pp

--7904200376 Responds to 781107 memo re investigation of document removal info partly withheld due to enforcement proceedings (ref FOIA Exemption 7A) BURLIN, C L Division of Security 78/12/04 2pp

--7904200349 Comments on OIC of Inspector & Auditor report re investigation of document removal info partly withheld due to enforcement proceedings (ref FOIA Exemption 7A & 7E) Forwards Washington Post article, 5/12/83 articles HARRIS, T F Office of Inspector & Auditor 79/02/28 2pp

--7904200348 Comments on OIC of Inspector & Auditor report re investigation of document removal info partly withheld due to enforcement proceedings (ref FOIA Exemption 7E) CUMMINGS, J J Office of Inspector & Auditor 79/02/28 2pp

DOCKET 55W-55-502 HAVEN NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

7904200373 Submits addl info on cost benefit analysis basins & industrial wastewater treatment facilities, in response to 790424 request BURLIN, C L Wisconsin Electric Power Co 79/03/28 2pp

7904200445 Forwards memo re energy release rates & main steam line break rates before withdrawal (ref 10CFR 790) FAY, C W Wisconsin Electric Power Co 79/04/04 2pp

7904200421 Forwards Paper 24, "Toward Universal Electromagnetic Extreme Limit Distribution," by HC Thom Power was requested in J.D.045 790424 Motion re response to NRC Question 332 d12 2 11 FAY, C W Wisconsin Electric Power Co 79/04/03 2pp

7904200117 Forwards response to NRC 790324 & 790415 requests for addl info re alternative site studies FAY, C W Wisconsin Electric Power Co 79/04/20 10pp

B Utility Preliminary Safety Analysis Report, amendments

7904200147 Forwards Amend 18 to PSAR BURLIN, C L Wisconsin Electric Power Co 79/03/31 3pp

--7904200191 Amend 18 to PSAR Wisconsin Electric Power Co 79/04/20 15pp

7904200193 Forwards Amend 23 to PSAR for insertion into site addendum BURLIN, C L Wisconsin Electric Power Co 79/05/31 2p

--7904200200 Amend 23 to PSAR Wisconsin Electric Power Co 79/05/31 11pp

7904200197 Forwards FP Liberator's 790425 Affidavit of Gov affirming distribution of PSAR Amend 18 & PSAR Site Addendum Amend 23 BURLIN, C L Wisconsin Electric Power Co 79/06/12 2pp

C Utility Environmental Report (ER), amendments & correspondence

7904200360 Forwards request for addl info based on review of environ Rept Amends 9-11 & site visits Questions re alternate sites sent sent 790324 BURLIN, C L Environmental Projects Branch 1 79/05/15 14pp

7904200314 Forwards June 1979 "Response to Dept of Natural Resources Specific Comments on Amends 11 & 12 Haven Rept" BURLIN, C L Wisconsin Electric Power Co 79/05/29 20pp

240409 Forwards complete environ Rept, including Amends 10 & 11 errata & Amend 13 BURLIN, C L Wisconsin Electric Power Co 79/04/18 2pp

240411 Forwards complete environ Rept, including Amends 10 & 11 errata & Amend 12 BURLIN, C L Wisconsin Electric Power Co 79/04/18 2pp

240414 Forwards complete environ Rept, including Amends 10 & 11 errata & Amend 13 BURLIN, C L Wisconsin Electric Power Co 79/04/18 2pp

DOCKETED ITEMS

2

G Adjudicatory correspondence

7906010216 Forwards June 1979 "Response to Dept of Natural Resources Specific Comments on Amends 11 & 12 Envrion Rept."
BURSTEIN, S P Wisconsin Electric Power Co 79/03/29 25pp

7906020407 Forwards complete environ repl. including Amends 10 & 11 w/errata & Amend 12
BURSTEIN, S Wisconsin Electric Power Co 79/06/18 2pp

DOCKET STN-50-503 HAVEN NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7906020272 Submits addl info on cost runoff settling basins & industrial wastewater treatment facilities, in response to 790406 request
BURSTEIN, S Wisconsin Electric Power Co 79/03/29 2pp

C Utility Environmental Report (ER), amends & correspondence

7906130216 Forwards June 1979 "Response to Dept of Natural Resources Specific Comments on Amends 11 & 12 Envrion Rept."
BURSTEIN, S P Wisconsin Electric Power Co 79/03/29 25pp

7906020407 Forwards complete environ repl. including Amends 10 & 11 w/errata & Amend 12
BURSTEIN, S Wisconsin Electric Power Co 79/06/18 2pp

7906020411 Forwards complete environ repl. including Amends 10 & 11 w/errata & Amend 12
BURSTEIN, S Wisconsin Electric Power Co 79/06/18 2pp

7906020414 Forwards complete environ repl. including Amends 10 & 11 w/errata & Amend 12
BURSTEIN, S Wisconsin Electric Power Co 79/06/18 2pp

G Adjudicatory correspondence

7906020175 Dismisses intervenor 790300 request for verification & analysis of mathematical computations & computer codes of BSA
LUTON, E Atomic Safety and Licensing Board Panel 79/03/07 2pp

DOCKET STN-50-504 KOSHONGONG NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

7906020272 Submits addl info on cost runoff settling basins & industrial wastewater treatment facilities, in response to 790406 request
BURSTEIN, S Wisconsin Electric Power Co 79/03/29 2pp

C Utility Environmental Report (ER), amends & correspondence

7906130216 Forwards June 1979 "Response to Dept of Natural Resources Specific Comments on Amends 11 & 12 Envrion Rept."
BURSTEIN, S P Wisconsin Electric Power Co 79/03/29 25pp

7906020407 Forwards complete environ repl. including Amends 10 & 11 w/errata & Amend 12
BURSTEIN, S Wisconsin Electric Power Co 79/06/18 2pp

7906020411 Forwards complete environ repl. including Amends 10 & 11 w/errata & Amend 12
BURSTEIN, S Wisconsin Electric Power Co 79/06/18 2pp

7906020414 Forwards complete environ repl. including Amends 10 & 11 w/errata & Amend 12
BURSTEIN, S Wisconsin Electric Power Co 79/06/18 2pp

DOCKET STN-50-505 KOSHONGONG NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7906020272 Submits addl info on cost runoff settling basins & industrial wastewater treatment facilities, in response to 790406 request
BURSTEIN, S Wisconsin Electric Power Co 79/03/29 2pp

C Utility Environmental Report (ER), amends & correspondence

7906130216 Forwards June 1979 "Response to Dept of Natural Resources Specific Comments on Amends 11 & 12 Envrion Rept."
BURSTEIN, S P Wisconsin Electric Power Co 79/03/29 25pp

7906020407 Forwards complete environ repl. including Amends 10 & 11 w/errata & Amend 12
BURSTEIN, S Wisconsin Electric Power Co 79/06/18 2pp

7906020411 Forwards complete environ repl. including Amends 10 & 11 w/errata & Amend 12
BURSTEIN, S Wisconsin Electric Power Co 79/06/18 2pp

7906020414 Forwards complete environ repl. including Amends 10 & 11 w/errata & Amend 12
BURSTEIN, S Wisconsin Electric Power Co 79/06/18 2pp

DOCKET STN-50-506 KOSHONGONG NUCLEAR PLANT, UNIT 3

A Application/construction stage documents & correspondence

7906020272 Submits addl info on cost runoff settling basins & industrial wastewater treatment facilities, in response to 790406 request
BURSTEIN, S Wisconsin Electric Power Co 79/03/29 2pp

C Utility Environmental Report (ER), amends & correspondence

7906130216 Forwards June 1979 "Response to Dept of Natural Resources Specific Comments on Amends 11 & 12 Envrion Rept."
BURSTEIN, S P Wisconsin Electric Power Co 79/03/29 25pp

7906020407 Forwards complete environ repl. including Amends 10 & 11 w/errata & Amend 12
BURSTEIN, S Wisconsin Electric Power Co 79/06/18 2pp

7906020411 Forwards complete environ repl. including Amends 10 & 11 w/errata & Amend 12
BURSTEIN, S Wisconsin Electric Power Co 79/06/18 2pp

7906020414 Forwards complete environ repl. including Amends 10 & 11 w/errata & Amend 12
BURSTEIN, S Wisconsin Electric Power Co 79/06/18 2pp

DOCKET STN-50-507 KOSHONGONG NUCLEAR PLANT, UNIT 4

A Application/construction stage documents & correspondence

7906020272 Submits addl info on cost runoff settling basins & industrial wastewater treatment facilities, in response to 790406 request
BURSTEIN, S Wisconsin Electric Power Co 79/03/29 2pp

C Utility Environmental Report (ER), amends & correspondence

7906130216 Forwards "Response to Dept of Natural Resources Specific Comments on Amends 11 & 12 to Envrion Rept." dtd June 1979
BURSTEIN, S P Wisconsin Electric Power Co 79/03/29 25pp

7906020407 Forwards complete environ repl. including Amends 10 & 11 w/errata & Amend 12
BURSTEIN, S Wisconsin Electric Power Co 79/06/18 2pp

7906020411 Forwards complete environ repl. including Amends 10 & 11 w/errata & Amend 12
BURSTEIN, S Wisconsin Electric Power Co 79/06/18 2pp

7906020414 Forwards complete environ repl. including Amends 10 & 11 w/errata & Amend 12
BURSTEIN, S Wisconsin Electric Power Co 79/06/18 2pp

DOCKET STN-50-508 HPP86 NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

7906020123 Forwards groundwater drainage analysis for 790301 submitted in two versions dated
KOSHONGONG, S L Washington Public Power Supply System 79 2pp

DOCKETED ITEMS

--790270130 Fifth step to design parameters of groundwater drainage system for 790231-0815, contained in two oversized drawings
at Washington Public Power Supply System 79/04/22 2pp

6 Inspection reports, IE Bulletins & correspondence

790200520 Forwards IE Insp Repts 20-208/79-03 & 20-209/79-02 on 79032-15 No noncompliance noted
ENGLAND, R H Region 3, San Francisco, Reactor Construction & Engineering Support Branch 79/04/20 2pp

--790200525 IE Insp Repts 20-208/79-03 & 20-209/79-02 on 79032-15 No noncompliance noted Major areas inspected changes in site
OR organizations & structural concrete QA procedure review
ALBERT, H C - INADVISABLE C Region 3, San Francisco, Reactor Construction & Engineering Support Branch 10/04/15 11pp
S. San Francisco, Office of the Director 79/04/15 11pp

790100907 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Installation Support Problem." No action required
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/07 1p

790100488 Forwards IE Info Notice 79-12, "Accumulated Damage to New Fuel Assembly." No written response necessary
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/10 1p

790100245 Forwards IE Circular 79-05, "Attempted Extortion - Low Enriched U"
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/18 1p

790100204 Forwards IE Bulletin 79-11, "Vocally Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/22 1p

790200061 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Dyeing Creek Reactor"
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/25 1p

8 Reportable occurrences, LERs & related correspondence

790100221 Forwards PNO-79-67AH
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/14 1p

790100230 Forwards PNO-79-67AD
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/21 1p

790100231 Forwards PNO-79-67AF
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/22 1p

790100232 Forwards PNO-79-67AG
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/22 1p

SECRET BBN-30-309 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

790270120 Forwards groundwater drainage analysis for 790331-0815, oversized drawings,
Washington Public Power Supply System 79/04/22

790100207 Forwards IE Info Notice 79-10, "Lower Reactor Vessel Head Installation Support Problem." No action required
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/07 1p

790100448 Forwards IE Info Notice 79-10, "Attempted Damage to New Fuel Assembly." No written response necessary
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/10 1p

790100245 Forwards IE Circular 79-05, "Attempted Extortion - Low Enriched U"
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/18 1p

790100204 Forwards IE Bulletin 79-11, "Vocally Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/22 1p

790200061 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Dyeing Creek Reactor"
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/25 1p

8 Reportable occurrences, LERs & related correspondence

790100221 Forwards PNO-79-67AH
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/14 1p

790100230 Forwards PNO-79-67AD
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/21 1p

790100231 Forwards PNO-79-67AF
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/22 1p

790100232 Forwards PNO-79-67AG
ENGLAND, R H Region 3, San Francisco, Office of the Director 79/03/22 1p

SECRET 30-310 BLUE HILLS STATION, UNIT 1

B RMC Draft/Final Environmental Statements, supply & correspondence

790100204 Forwards errata sheet to RMC for facility (BWR09-0469)
SLATER, R Environmental Projects Branch 1 79/04/20 2pp

8 Adjudicators correspondence

790600132 Forwards info re occupational exposure in commercial nuclear reactors & adequacy of neutron dosimetry now used
WICKHEAD, C P Branch 3 79/04/04 1p

790600068 Forwards re qualifications of applicant witness panel in licensing early site review hearing
METERNA, W H J Conner, Moore & Carver 79/04/17 12pp

790100264 Requests to make limited appearance statement at licensing proceeding conference
MELING, B Affiliation Unknown 79/04/26 1p

790100470 Requests appearance at site hearings near Joseph-TS diesel unit of 790326
METERNA, W H J Stephen F Austin State Univ 79/04/26 1p

790100468 Requests to make limited appearance statement at licensing proceeding conference
LEBLAND, L P Affiliation Unknown 79/04/23 1p

-- 80148 Forwards Applicant Gulf States Utility 790607 proposed findings of fact & conclusions of law in form of partial civil decision
METERNA, W H J Conner, Moore & Carver 79/06/07 1p

8000169 Gulf States Utility proposed findings of fact & conclusions of law in form of partial initial decision re issues of site suitability Certificate of Suitability
METERNA, W H J Conner, Moore & Carver 79/06/07 7pp

DOCKETED ITEMS

H General correspondence

7906150246 Supports cost of nuclear plant
WILLIAMS, C H Affiliation Unknown 79/04/28 1p

DOCKET 30-511 BLUE HILLS STATION, UNIT 2

A NRC Draft/Final Environmental Statements, supply & correspondence

7906120006 Forwards errata sheet to FES for facility (HAREP-0449)
HEATON, M Environmental Projects Branch 1 79/04/20 3pp

G Adjudicatory correspondence

7906050132 Forwards info re occupational exposure in commercial nuclear
reactors & adequacy of neutron dosimetry used
WIGGINS, C Branch 3 79/04/04 1p

7906050600 Forwards grad qualifications of applicant witness panel in
upcoming early site review hearing
METTERMAN, J Conner, Moore & Corber 79/04/17 12pp

7906140844 Requests to make limited appearance statement at licensing
prehearing conference
WRIGHT, D Affiliation Unknown 79/04/06 1p

7906140470 Requests appearance at site hearings near Jasper, TX during
week of 7/20/80
WFFRACZUR, W N Stephen F Austin State Univ 79/04/26 1p

7906140630 Requests to make limited appearance statements at licensing
prehearing conference
LEHMAN, C P Affiliation Unknown 79/04/20 1p

7906050155 Forwards applicant Gulf States Utility 790627 proposed
findings of fact & conclusions of law in form of partial
official decision
METTERMAN, J Conner, Moore & Corber 79/04/07 1p

---7906050109 Gulf States Utility proposed findings of fact & conclusions
of law in form of partial initial decision re issues of site
suitability Certificate of No Objection
METTERMAN, J Conner, Moore & Corber 79/04/07 50pp

H General correspondence

7906150246 Supports cost of nuclear plant
WILLIAMS, C H Affiliation Unknown 79/04/28 1p

DOCKET 30-513 WPPSS NUCLEAR PROJECT, UNIT 4

A Application/Construction stage documents & correspondence

7906040222 Approves proposed date of Aug 1980 for submittal of FEAR &
environmental report
BOYD, R B Division of Project Management 79/05/01 3pp

G Adjudicatory correspondence

7906210547 Motion for extension until 7/20/81 to prepare response to
ALAB-809
BOYD, R B Hearings Division 79/04/02 2pp

---7906210540 Responds to 790502 request for info re status of rulemaking
proceeding to develop value for radon in Table B-2 Repts &
proposed rule will be sent to NRC by 7/20/80 Rule does not
address health effects of radon releases
CHIBBIBUR, E Hearings Division 79/05/06 3pp

7906210505 NRC action for summary disposition re radon issue was in
error (ALAB-840 consolidated only 2 of 16 cases Denies NRC
motion as to parties in other proceedings Certificate of No
Objection
DUNLOP, E Atomic Safety and Licensing Appeal Panel 79/05/20
3pp

G Inspection reports, IE Bulletin & correspondence

7906220120 Forwards IE Insp Repts 30-460/79-05 & 30-513/79-05 on
790327-02 re noncompliance noted
BRYNCH, R G Region 3, San Francisco, Office of the Director
79/04/10 2pp

---7906020137 IE Insp Repts 30-460/79-05 & 30-513/79-05 on 790327-02 re
noncompliance noted Major areas inspected noted activities.
Training programs & miscellaneous open items
ALBERT, W G, HAYKES, B C Region 3, San Francisco, Office of the
Director 79/04/12 4pp

7906050605 Response to NRC 790325 ltr re violations noted in IE Insp
Repts 30-237/79-03, 30-460/79-04 & 30-513/79-04 Corrective
actions audit conducted Feb 1977 Deficiency number RD-858
will be removed & replaced properly
RENNERT, S L Washington Public Power Supply System 79/04/20
3pp

---7906150095 Ack receipt of 790420 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 30-237/79-03,
30-460/79-04 & 30-513/79-04
ENGELMAN, R H Region 3, San Francisco, Reactor Construction &
Engineering Support Branch 79/05/03 1p

---7906150055 Forwards IE Insp Repts 30-237/79-03, 30-460/79-04 &
30-513/79-04 on 790301-02 & 14-15 re notice of violation
BRYNCH, R G Region 3, San Francisco, Reactor Construction &
Engineering Support Branch 79/03/21 2pp

---7906150043 Notice of violation from Insp on 790301-02 & 14-15
re Region 3, San Francisco, Reactor Construction & Engineering
Support Branch 79/03/21 2pp

---7906150079 IE Insp Repts 30-237/79-03, 30-460/79-04 & 30-513/79-04 on
790301-02 & 14-15 Noncompliance noted Failure to respond
effectively to audit finding & failure to implement
effective Insp program
BRYNCH, R G, ENGELMAN, R H, HAYKES, B C Region 3, San
Francisco, Reactor Construction & Engineering Support Branch
79/03/21 7pp

7906120057 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Support Problem - No Action Required"
ENGELMAN, R H Region 3, San Francisco, Office of the Director
79/05/07 1p

7906180488 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assembly - No Action Required"
ENGELMAN, R H Region 3, San Francisco, Office of the Director
79/05/10 1p

7906050245 Forwards IE Circular 79-05, "Attempted Extortion - Low
Surched" in
ENGELMAN, R H Region 3, San Francisco, Office of the Director
79/05/10 1p

7906130054 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device
in Circuit Breakers for Engineering Safety Sys" License
action required
ENGELMAN, R H Region 3, San Francisco, Office of the Director
79/05/02 1p

7906050561 Forwards IE Info Notice 79-13, "Indication of Low Water
Level in Dwyer Graph Reactor"
ENGELMAN, R H Region 3, San Francisco, Office of the Director
79/05/29 1p

E Reportable occurrences, LERs & related correspondence

7906180321 Forwards PHD-79-A74N
ENGELMAN, R H Region 3, San Francisco, Office of the Director,
79/05/14 1p

7906180320 Forwards PHD-79-A74O
ENGELMAN, R H Region 3, San Francisco, Office of the Director
79/05/01 1p

7906180331 Forwards PHD-79-A74P
ENGELMAN, R H Region 3, San Francisco, Office of the Director
79/05/02 1p

7906180371 Forwards PHD-79-A74B
ENGELMAN, R H Region 3, San Francisco, Office of the Director
79/05/03 1p

DOCKET 30-314 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

A Application/Construction stage documents & correspondence

7906190472 Ack receipt of NRC 790318 ltr re PSE-1020 Response schedule
will be confirmed by 790618
JOHNSON, R H Portland General Electric Co 79/05/01 1p

7903200230 Forwards Jan 1979 "Housing & Community Facilities Requirements Update," Vol 2
LINDBLAD, W J Portland General Electric Co 79/06/18 2pp

0 Adjudicatory correspondence

7903201031 Forwards proposed NRC response by RL Doty & R Miller to 790318 memo re ASL's questions Unable to give filing date for NRC revised alternative sites analysis being prepared by ASL
BROOKHICK, S H Branch 4 79/03/07 1p

8 Periodic operating reports & related correspondence

7903203481 Forwards "Belmont Nuclear Annual Rept." Nov 1977-Oct 1978
LINDBLAD, W J Portland General Electric Co 79/06/18 1p

7903203049 "Belmont Nuclear Annual Rept." Nov 1977-Oct 1978. By
TEMA Corp
Portland General Electric Co 79/06/18 38pp

DOCKET 80-318 HEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

790318473 Ack receipt of NRC 790318 ltr re NRC-1920 Response schedule will be confirmed by 790315
JONES, R W Portland General Electric Co 79/06/11 1p

7903200230 Forwards Jan 1979 "Housing & Community Facilities Requirements Update," Vol 2
LINDBLAD, W J Portland General Electric Co 79/06/18 2pp

0 Adjudicatory correspondence

7903201031 Forwards proposed NRC response by RL Doty & R Miller to 790318 memo re ASL's questions Unable to give filing date for NRC revised alternative sites analysis being prepared by ASL
BROOKHICK, S H Branch 4 79/03/07 1p

8 Periodic operating reports & related correspondence

7903203481 Forwards "Belmont Nuclear Annual Rept." Nov 1977-Oct 1978
LINDBLAD, W J Portland General Electric Co 79/06/18 1p

7903203049 "Belmont Nuclear Annual Rept." Nov 1977-Oct 1978. By
TEMA Corp
Portland General Electric Co 79/06/18 38pp

DOCKET 88N-50-016 JAMESPORT NUCLEAR STATION, UNIT 1

0 Adjudicatory correspondence

7903049970 Motion to file supplemental brief Certificate of Service
LIRE, L Suffolk County, NY 79/04/19 7pp

7903200230 Forwards IE Bulletin 79-02, "Pipe Support Base Plate Design Using Concrete Expansion Anchor Bolts"
BROOKHICK, S H Branch 4 79/04/26 1p

points to 790305 ltr re design deficiencies in support NRC still waiting for BAW evaluation of both critical pipe supports Info will be evaluated outstanding safety review
H Branch 4 79/04/12 1p

supplemental
or

r reply to
ll
AD b

of or, in
ght

8 Inspection reports, IE Bulletins & correspondence

7903182974 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Bolts" No written response necessary
GRIER, S H Region 1, Philadelphia, Office of the Director 79/04/16 1p

7903110118 Forwards IE Bulletin 79-028, "Nuclear Incident at TH-0091" No written response required
GRIER, S H Region 1, Philadelphia, Office of the Director 79/04/22 1p

7903180566 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Inspection Support Problem" No action required
GRIER, S H Region 1, Philadelphia, Office of the Director 79/05/07 2pp

7903080115 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" No written response required
GRIER, S H Region 1, Philadelphia, Office of the Director 79/05/11 1p

7903070794 Responds to IE Bulletin 79-03 Station design reviewed & verified pipe is not used in Westinghouse MGS
FLAHERTY, K Long Island Lighting Co 79/05/11 1p

7903050000 Responds to IE Bulletin 79-07 No seismic stress analysis of support-plated piping has been performed Intends to use COMPARE computer program for piping analysis
FLAHERTY, K Long Island Lighting Co 79/05/30 1p

DOCKET 87N-50-517 JAMESPORT NUCLEAR STATION, UNIT 2

0 Adjudicatory correspondence

7903040393 Motion to file supplemental brief Certificate of Service and
LIRE, L Suffolk County, NY 79/04/19 7pp

7903050223 Forwards IE Bulletin 79-02, "Pipe Support Base Plate Design Using Concrete Expansion Anchor Bolts"
BROOKHICK, S H Branch 4 79/04/26 1p

7903050223 Responds to 790305 ltr re design deficiencies in support base plates NRC still waiting for BAW evaluation of both piping & electrical pipe supports Info will be evaluated on part of continuing safety review
BROOKHICK, S H Branch 4 79/05/10 1p

7903050369 Opposes Suffolk County 790419 motion to file supplemental brief Arguments presented are outside scope of evidence of Certificate of Service already admitted into evidence
REVOLTER, M F Newton & Williams 79/05/09 4pp

7903050500 Requests ASL grant extension until 790408 for reply to Suffolk County motion to file supplemental brief NRC will complete evaluation of mail re TH-1 & submit info to ASL & all parties Motion granted by ASL as 790318
BROOKHICK, S H Branch 4 79/03/08 2pp

7903070269 Answers 790419 request to file supplemental brief as in alternative to request request Further relief will be sought after ASL has received NRC response to 790419 order Certificate of Service
LIRE, L Suffolk County, NY 79/05/26 4pp

8 Inspection reports, IE Bulletins & correspondence

7903180974 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Bolts" No written response necessary
GRIER, S H Region 1, Philadelphia, Office of the Director 79/04/16 1p

7903110118 Forwards IE Bulletin 79-028, "Nuclear Incident at TH-0091" No written response required
GRIER, S H Region 1, Philadelphia, Office of the Director 79/04/22 1p

7903180566 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Inspection Support Problem" No action required
GRIER, S H Region 1, Philadelphia, Office of the Director 79/05/07 2pp

7903080115 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" No written response required
GRIER, S H Region 1, Philadelphia, Office of the Director 79/05/11 1p

DOCKETED ITEMS

216

7904270794 Response to IE Bulletin 79-03 Station design reviews & welded pipe is not used in Westinghouse N880
FLADGREN, R E Long Island Lighting Co 79/03/31 1p

7904270938 Response to IE Bulletin 79-07 No seismic stress analyses of safety-related piping have been performed. Intends to use NUREC computer program for piping analysis
FLADGREN, R E Long Island Lighting Co 79/03/30 1p

DOCKET 87N-50-310 HARTSVILLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

7904270173 Confirms JC Killian & CE Murphy 790313 action re discontinuance of production of cathodic splices & placement of concrete for Category I structures
O'DRILL, J P Region 2, Atlanta, Office of the Director 79/03/13 2pp

7904270204 Notification of 790419 meeting w/utl to discuss leak testing, temp & pressure data for piping embedded in concrete
BENEDICT, R A , RODD, H Light Water Reactors Branch 2 79/03/21 4pp

O Adjudicatory correspondence

7904270207 Motion for extension until 790411 to prepare response to ALAB-509
SCHEIDT, J F Hearings Division 79/04/02 2pp

--7904270340 Response to 790328 request for info re status of rulemaking proceeding to develop value for radon in Table B-3 Rept & proposed rule will be sent to NRC by 790406. Rule does not address health effects of radon releases
CHRISTENSEN, E Hearings Division 79/03/26 34pp

7904270395 NRC motion for summary disposition re radon issue was in error. ALAB-540 consolidated only 5 of 16 cases. Denies NRC motion as to parties in other proceedings. Certificate of NRC
DUFFLO, H E Atomic Safety and Licensing Appeal Panel 79/03/25 2pp

O Inspection reports, IE Bulletins & correspondence

7904270332 Forwards IE Insp Repts 80 518/79-03, 80-516/79-03, 80-521/79-03 & 80-521/79-03 as 790320-03 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 2pp

--7904270338 IE Insp Repts 80-518/79-03, 80-516/79-03, 80-521/79-03 & 80-521/79-03 as 790320-03 No noncompliance noted. Major areas inspected review of previous ins findings, spray ponds & containment concrete
SHAW, W B Region 2, Atlanta, Office of the Director 79/04/02 4pp

7904270347 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase." No written response required
O'DRILL, J P Region 2, Atlanta, Office of the Director 79/03/32 1p

7904270398 Response to IE Bulletin 79-03 Investigation shows no piping in use or planned in safety-related areas. Effort in progress to locate any ASME SA-312, Type 304 piping supplied by Youngtown Welding & Engineering
GILLILAND, J E Tennessee Valley Authority 79/03/14 1p

N Reportable occurrences, LERs & related correspondence

7904270411 Submits interim deficiency report breakdown in SC program at industrial engineering work re reactor pressure vessel shield wall. Initial report to W Group on 790417. Final report to be submitted 790520
GILLILAND, J E Tennessee Valley Authority 79/03/17 2pp

7904270412 Forwards deficiency report re const of piping elbows w/unspecified matl
GILLILAND, J E Tennessee Valley Authority 79/03/25 1p

--7904270442 Deficiency report on 790325 piping elbows constructed from unclassified matl. Elbow without spec 163719 was identified, tested & returned to manufacturer
E Tennessee Valley Authority 79/03/25 3pp

DOCKET 87N-50-310 HARTSVILLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7904270173 Confirms JC Killian & CE Murphy 790313 action re discontinuance of production of cathodic splices & placement of concrete for Category I structures
O'DRILL, J P Region 2, Atlanta, Office of the Director 79/03/13 2pp

7904270204 Notification of 790419 meeting w/utl to discuss leak testing, temp & pressure data for piping embedded in concrete
BENEDICT, R A , RODD, H Light Water Reactors Branch 2 79/03/21 4pp

O Adjudicatory correspondence

7904270207 Motion for extension until 790411 to prepare response to ALAB-509
SCHEIDT, J F Hearings Division 79/04/02 2pp

--7904270340 Response to 790328 request for info re status of rulemaking proceeding to develop value for radon in Table B-3 Rept & proposed rule will be sent to NRC by 790406. Rule does not address health effects of radon releases
CHRISTENSEN, E Hearings Division 79/03/26 34pp

7904270395 NRC motion for summary disposition re radon issue was in error. ALAB-540 consolidated only 5 of 16 cases. Denies NRC motion as to parties in other proceedings. Certificate of NRC
DUFFLO, H E Atomic Safety and Licensing Appeal Panel 79/03/25 2pp

O Inspection reports, IE Bulletins & correspondence

7904270332 Forwards IE Insp Repts 80 518/79-03, 80-516/79-03, 80-521/79-03 & 80-521/79-03 as 790320-03 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 2pp

--7904270338 IE Insp Repts 80-518/79-03, 80-516/79-03, 80-521/79-03 & 80-521/79-03 as 790320-03 No noncompliance noted. Major areas inspected review of previous ins findings, spray ponds & containment concrete
SHAW, W B Region 2, Atlanta, Office of the Director 79/04/02 4pp

7904270347 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase." No written response required
O'DRILL, J P Region 2, Atlanta, Office of the Director 79/03/32 1p

7904270398 Response to IE Bulletin 79-03 Investigation shows no piping in use or planned in safety-related areas. Effort in progress to locate any ASME SA-312, Type 304 piping supplied by Youngtown Welding & Engineering
GILLILAND, J E Tennessee Valley Authority 79/03/14 1p

N Reportable occurrences, LERs & related correspondence

7904270411 Forwards deficiency report re const of piping elbows w/unspecified matl
GILLILAND, J E Tennessee Valley Authority 79/03/25 1p

--7904270442 Deficiency report on 790325 piping elbows constructed from unclassified matl. Elbow without spec 163719 was identified, tested & returned to manufacturer
E Tennessee Valley Authority 79/03/25 3pp

DOCKET 87N-50-310 HARTSVILLE NUCLEAR PLANT, UNIT 3

A Application/construction stage documents & correspondence

7904270173 Confirms JC Killian & CE Murphy 790313 action re discontinuance of production of cathodic splices & placement of concrete for Category I structures
O'DRILL, J P Region 2, Atlanta, Office of the Director 79/03/13 2pp

7904270204 Notification of 790419 meeting w/utl to discuss leak testing, temp & pressure data for piping embedded in concrete
BENEDICT, R A , RODD, H Light Water Reactors Branch 2 79/03/21 4pp

8 Adjudicatory correspondence

7903210426 Act receipt of 790322 ltr requesting leave to intervene
informs that 790329 ltr was issued as intervention
informs. Forwards notice of establishment of rules to rule
on petition. W/O encl
02/06/82, S.C. Branch 2 79/03/05 1p

7903210847 Motion for extension until 790411 to prepare response to
ALAB-509
SCINTG, J.F. Hearings Division 79/04/02 3pp

--7903210360 Responds to 790322 request for info re status of rulemaking
proceeding to develop value for radon in Table B-3 Rept &
proposed rule will be sent to NRC by 790406. Rule does not
address health effects of radon releases.
CHRISTENBURY, E. Hearings Division 79/03/26 3pp

7903210975 NRC motion for summary disposition re radon issue was an
error. ALAB-540 consolidated only 3 of 15 cases. Denies NRC
motion as to parties in other proceedings. Certificate of Doc
encl
BUTTS, H.E. Atomic Safety and Licensing Appeal Panel 79/03/25
3pp

9 Inspection reports, IE Bulletins & correspondence

7903210322 Forwards IE Insp Repts 32-518/79-05, 50-519/79-05,
32-520/79-05 & 50-521/79-05 as 790320-22. No noncompliance
noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 79/04/02 2pp

--7903210328 IE Insp Repts 50-518/79-05, 50-519/79-05, 50-520/79-05 &
50-521/79-05 as 790320-22. No noncompliance noted. Major areas
inspected review of previous insp findings, open ponds &
containment concrete.
BANKS, M.B. Region 2, Atlanta, Office of the Director 79/04/02
6pp

7903210347 Forwards IE Circular 79-07, "Unexpected Speed Increase of
Reactor Motor Generator Set Resulted in Reactor Power
Increase." No written response required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/03/02, 1p.

7903210690 Responds to IE Bulletin 79-03. Investigation shows no piping
in use or planned in safety-related area. Effort in progress
to locate any ADRS BA-312, Type 356 piping supplied by
Youngstown Welding & Engineering.
GILLBLAND, J.E. Tennessee Valley Authority 79/03/14 1p

9 Reportable occurrences, LERs & related correspondence

7903210321 Forwards efficiency test re coast of piping elbows
w/inspected metal.
GILLBLAND, J.E. Tennessee Valley Authority 79/03/25 1p

--7903210442 Efficiency test on 790325 piping elbows constructed from
uninspected metal. Elbows without code M6729 were identified,
tested & returned to manufacturer.
Tennessee Valley Authority 79/03/25 3pp

WHYNNY WPP-50-501 WHITEVILLE NUCLEAR PLANT, UNIT 4

/construction stage documents & correspondence

NIS telcom re
lancement

motion

7903210347 Motion for extension until 790411 to prepare response to
ALAB-509
SCINTG, J.F. Hearings Division 79/04/02 3pp

--7903210360 Responds to 790322 request for info re status of rulemaking
proceeding to develop value for radon in Table B-3 Rept &
proposed rule will be sent to NRC by 790406. Rule does not
address health effects of radon releases.
CHRISTENBURY, E. Hearings Division 79/03/26 3pp

7903210975 NRC motion for summary disposition re radon issue was an
error. ALAB-540 consolidated only 3 of 15 cases. Denies NRC
motion as to parties in other proceedings. Certificate of Doc
encl
BUTTS, H.E. Atomic Safety and Licensing Appeal Panel 79/03/25
3pp

9 Inspection reports, IE Bulletins & correspondence

7903210322 Forwards IE Insp Repts 50-518/79-05, 50-519/79-05,
50-520/79-05 & 50-521/79-05 as 790320-22. No noncompliance
noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 79/04/02 2pp

--7903210328 IE Insp Repts 50-518/79-05, 50-519/79-05, 50-520/79-05 &
50-521/79-05 as 790320-22. No noncompliance noted. Major areas
inspected review of previous insp findings, open ponds &
containment concrete.
BANKS, M.B. Region 2, Atlanta, Office of the Director 79/04/02
6pp

7903210347 Forwards IE Circular 79-07, "Unexpected Speed Increase of
Reactor Motor Generator Set Resulted in Reactor Power
Increase." No written response required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/03/02, 1p.

7903210690 Responds to IE Bulletin 79-03. Investigation shows no piping
in use or planned in safety-related area. Effort in progress
to locate any ADRS BA-312, Type 356 piping supplied by
Youngstown Welding & Engineering.
GILLBLAND, J.E. Tennessee Valley Authority 79/03/14 1p

DOCKET 570-50-582 BRANT NUCLEAR POWER PROJECT, UNIT 1

A Application/construction stage documents & correspondence

7903210322 Forwards Reg 1976 "Onion Analysis Rept on Babcock-Shipwreck
Hull Portent." Rept available in Central Files only.
MORRIS, J.R. Agriculture Dept of 79/03/08 1p

7903210325 "Rept of Geologic Investigations in 1978-79."
Pugot Bound Power & Light Co. 79/03/31 200pp

7903210341 Forwards info re costs associated w/operation of alternate
sites as requested in NRC 790301 ltr. Tabulation & summary
explanation sheets encl.
MORRIS, J.R. Pugot Bound Power & Light Co. 79/03/12 4pp

8 Adjudicatory correspondence

7903210314 Response 790319 list of principal issues submitted per ALAB
790308 order. Certificate of Doc encl.
LEER, E.H. - OGDH/57-H.H. Scientists Concerned About Nuclear Plants
79/03/14 2pp

7903210315 Various ltrs objecting to proposed cost of facility
19790308-11. MURPHY, E. - OGDH/72-S. Affiliation Unknown 79/04/02
13pp

7903210327 Request by intervenors Skagitarians Concerned About Nuclear
Plants for action ordering review of NRC petition re
relevance of Class 9 accident issue. Remotely motion to
consider Class 9 accidents. Certificate of Doc encl.
LEER, E.H. Lead, Paper # 79/04/02 3pp

7903210312 Forwards "1979 West Group Forecast."
SCHNEIDER, P.T. Parkins, Cole, Biscoe, Olson & Williams 79/03/04
1p

10254 Forwards amended response to Interrogatory 9 previously
filed on 790324.
IL-R.L. Branch 1 79/03/04 1p

DOCKETED ITEMS

217

7904020062 Requests denial of 790427 motion by Shaghtians Concerned About Nuclear Power re NRC proceeding-REL, not NRC-grants license on basis of record & Board member personal expertise Certificate of Rev encl
BAGGLEY, A. Loomis/In:Heaven/Rel:Asired & Tell 79/05/08 App

7904020017 Requests denial of Shaghtians Concerned About Nuclear Plants 790427 motion re consideration of Class 9 accidents NRC policy provides that Class 9 accidents need not be considered in EIS Certificate of Rev encl
THOMPSON, P. T. Perkins, Cole, Steiner, Olsen & Williams 79/05/11 App

7904020046 Reviews NRC safety review efforts in response to 790409 lit expressing concerns re proposed nuclear facility close to Canadian border & City of Vancouver
BENTON, N. A. Office of Nuclear Reactor Regulation 79/05/14 App

DOCKET 87N-50-303 BRAGIT NUCLEAR POWER PROJECT, UNIT 2

A Application/construction stage documents & correspondence

7904130028 Forwards May 1976 "Onions Analysis Rpt #8 Baker-Benjamin Plant Forest" Rpt available in Central Files only
BENTON, N. A. Application Dept of 79/05/06 App

7904020085 Rpt of Geologic Investigations in 1970-79
* Page Sound Power & Light Co 79/05/31 200pp

7904150041 Forwards info re costs associated w/selection of alternate sites requested in NRC 790513 lit Tabulation & summary explanation sheets encl
NECCA, J. E. Page Sound Power & Light Co 79/06/12 App

C Adjudicatory correspondence

7904010014 Replies 790313 list of principal issues submitted per NRC 790309 order Certificate of Rev encl
LEON, R. H. & BOWEN, R. W. Shaghtians Concerned About Nuclear Plants 79/03/14 22pp

7904050013 Various lit objecting to proposed const of Facility
THOMPSON, P. T. WILSON, R. B. SCHULTZ, G. Affiliation Unknown 79/04/10 13pp

7904060022 Request by intervenors Shaghtians Concerned About Nuclear Plants for motion ordering review of NRC position re elements of Class 9 accident issue Remedy action to consider Class 9 accidents Certificate of Rev encl
LEON, R. H. Lead, Roger H 79/04/27 App

7904020102 Forwards "1979 West Group Forecast"
THOMPSON, P. T. Perkins, Cole, Steiner, Olsen & Williams 79/05/04 80pp

7904020024 Forwards amended response to Interrogatory 5 previously submitted as 790214
BLACK, J. L. Branch 1 79/05/04 App

7904020042 Requests denial of 790427 motion by Shaghtians Concerned About Nuclear Power in NRC proceeding-REL, not NRC-grants license on basis of record & Board member personal expertise Certificate of Rev encl
BAGGLEY, A. Loomis/In:Heaven/Rel:Asired & Tell 79/05/08 App

7904020017 Requests denial of Shaghtians Concerned About Nuclear Plants 790427 motion re consideration of Class 9 accidents NRC policy provides that Class 9 accidents need not be considered in EIS Certificate of Rev encl
THOMPSON, P. T. Perkins, Cole, Steiner, Olsen & Williams 79/05/11 App

7904020046 Reviews NRC safety review efforts in response to 790409 lit expressing concerns re proposed nuclear facility close to Canadian border & City of Vancouver
BENTON, N. A. Office of Nuclear Reactor Regulation 79/05/14 App

DOCKET 87N-50-300 PALO VERDE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

7904020019 Summary of 790428-28 meeting w/Unit 1 in Phoenix AZ re status of const.
LICHTNER, E. Light Water Reactors Branch 3. 79/05/14 App

7904040064 Forwards press release announcing 1-yr delay in Unit 1 commercial operation which is still within CP latest completion date Will file FSNR & OL stage environ rpt in Oct 1979
WAM BURT, E. E. Arizona Public Service Co 79/05/23 App

B Adjudicatory correspondence

7904020034 Objects to proposed facility site
PARKER, S. A. Affiliation Unknown 79/04/07 App

D Inspection reports, IE Bulletin & correspondence

7904130043 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem - No action required"
BOWEN, R. W. Region 5, San Francisco, Office of the Director 79/05/07 App

7904150072 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies - No written response necessary"
BOWEN, R. W. Region 5, San Francisco, Office of the Director 79/05/10 App

7904050040 Forwards IE Circular 79-08, "Attempted Extension - Low Irradiation"
BOWEN, R. W. Region 5, San Francisco, Office of the Director 79/05/10 App

7904130027 Forwards IE Bulletin 79-13, "Weekly Government Trip Device in Circuit Breakers for Engineered Safety Sys" - Licensee action required
BOWEN, R. W. Region 5, San Francisco, Office of the Director 79/05/02 App

7904020048 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Outer Graph Reactor"
BOWEN, R. W. Region 5, San Francisco, Office of the Director 79/05/29 App

E Reportable occurrences, LERs & related correspondence

7904100013 Forwards PNO-79-67AN
BOWEN, R. W. Region 5, San Francisco, Office of the Director 79/05/16 App

7904100014 Forwards PNO-79-67AD
BOWEN, R. W. Region 5, San Francisco, Office of the Director 79/05/21 App

7904100015 Forwards PNO-79-67AP
BOWEN, R. W. Region 5, San Francisco, Office of the Director 79/05/22 App

7904100016 Forwards PNO-79-67AR
BOWEN, R. W. Region 5, San Francisco, Office of the Director 79/05/23 App

DOCKET 87N-50-329 PALO VERDE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7904020019 Summary of 790428-28 meeting w/Unit 2 in Phoenix AZ re status of const.
LICHTNER, E. Light Water Reactors Branch 3. 79/05/14 App

7904040064 Forwards press release announcing 1-yr delay in Unit 1 commercial operation which is still within CP latest completion date Will file FSNR & OL stage environ rpt in Oct 1979
WAM BURT, E. E. Arizona Public Service Co 79/05/23 App

B Adjudicatory correspondence

7904020034 Objects to proposed facility site
PARKER, S. A. Affiliation Unknown 79/04/07 App

D Inspection reports, IE Bulletin & correspondence

7904130043 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem - No action required"
BOWEN, R. W. Region 5, San Francisco, Office of the Director 79/05/07 App

DOCKETED ITEMS

7904180472 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assembly - No Written Response Necessary."
 ENGLISH, R. H. Region 3, San Francisco, Office of the Director
 79/03/10 1p

7904000240 Forwards IE Circular 79-08, "Attempted Expiration - Low
 ENGLISH, R. H. Region 3, San Francisco, Office of the Director
 79/03/10 1p

7904100037 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device
 in Circuit Breakers for Engineered Safety Sys - License
 action required
 ENGLISH, R. H. Region 3, San Francisco, Office of the Director
 79/03/22 1p

7904200349 Forwards IE Info Notice 79-13, "Indication of Low Water
 Level in Baster Creek Reactor"
 ENGLISH, R. H. Region 3, San Francisco, Office of the Director
 79/03/29 1p

5 Reportable occurrences, LERs & related correspondence

7904180213 Forwards FND-79-67AM
 ENGLISH, R. H. Region 3, San Francisco, Office of the Director
 79/03/16 1p

7904180348 Forwards FND-79-67AD
 ENGLISH, R. H. Region 3, San Francisco, Office of the Director
 79/03/21 1p

7904180035 Forwards FND-79-67AF
 ENGLISH, R. H. Region 3, San Francisco, Office of the Director
 79/03/22 1p

7904180345 Forwards FND-79-67AB
 ENGLISH, R. H. Region 3, San Francisco, Office of the Director
 79/03/20 1p

DOCKET 8TH-80-030 PALO VERDE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

7904200319 Summary of 790420-26 meeting w/etel in Phoenix re status
 of cost
 L. C. H. Light Water Reactor Branch 3 79/05/14 4pp

7904260044 Forwards press release announcing 1-yr delay in Unit 1
 commercial operation which is still within CP intent
 completion date still file FEAR & GL stage enviro report in
 Oct 1979
 Van Brunt, E. E. Arizona Public Service Co 79/05/28 4pp

O Adjudicatory correspondence

7904200304 Objects to proposed facility site
 PARKER, R. A. Affiliation Unknown 79/06/07 3p

G Inspection reports, IE Bulletins & correspondence

1 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head
 on Support Problem - No action required"
 R. H. Region 3, San Francisco, Office of the Director
 1p

79-12, "Attempted Damage to New Fuel
 Assembly"
 R. H. Office of the Director

tion - Low

6 Reportable occurrences, LERs & related correspondence

7904180213 Forwards FND-79-67AM
 ENGLISH, R. H. Region 3, San Francisco, Office of the Director
 79/03/16 1p

7904180348 Forwards FND-79-67AD
 ENGLISH, R. H. Region 3, San Francisco, Office of the Director
 79/03/21 1p

7904180035 Forwards FND-79-67AF
 ENGLISH, R. H. Region 3, San Francisco, Office of the Director
 79/03/22 1p

7904180345 Forwards FND-79-67AB
 ENGLISH, R. H. Region 3, San Francisco, Office of the Director
 79/03/20 1p

DOCKET 80-037 CLINCH RIVER RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

7904200288 Forwards responses to NRC request for addl info re physical
 security plan Plan withheld (ref 100F82 7901)
 C. L. Energy Dept of 79/06/01 4pp

DOCKET 80-038 HIGHWAY STATE UNIV RESEARCH REACTOR

8 Inspection reports, IE Bulletins & correspondence

7904200417 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
 Assembly"
 S. H. Region 3, Atlanta, Office of the Director
 79/03/10 1p

7904000155 Ack receipt of 790417 for informing NRC of steps taken to
 correct violations noted in IE Insp Rept 80-038/79-01
 H. H. Region 2, Atlanta, Safeguards Branch 79/05/14 1p

7904000112 Forwards IE Insp Rept 80-038/79-01 on 790306-07 Notice of
 violation withheld (ref 100F82 7901)
 H. H. Region 2, Atlanta, Safeguards Branch 79/03/21 2pp

7904000149 IE Insp Rept 80-038/79-01 on 790306-07 Noncompliance noted
 failure to conduct security program review Details withheld
 (ref 100F82 7901)
 PERRY, C. B. Region 2, Atlanta, Office of the Director
 GILLESPIE, F. P. Region 2, Atlanta, Safeguards Branch 79/03/21 2p

DOCKET 8TH-80-046 MARBLE HILL NUCLEAR STATION, UNIT 1

C Utility Environmental Report (ER), amendments & correspondence

7906000030 Envelope not for GL stage
 R. Public Service Co of Indiana, Inc 79/05/31 000pp

O Adjudicatory correspondence

7904200047 Motion for extension until 790411 to prepare response to
 ALAB-509
 G. H. H. Hearings Division 79/04/02 2pp

7904201060 Responds to 790323 request for info re status of rulemaking
 proceeding to develop value for raton in Table B-3 Rept 5
 proposed rule will be sent to NRC by 790404 Rule does not
 address health effects of radon release
 G. H. H. Hearings Division 79/03/26 34pp

7904201064 Unit responds in support of 2d minimum theory per ALAB-509.
 as modified by ALAB-510 & 790323 order. Recommends
 termination of review of jurisdiction initiated in
 ALAB-490 & continued in ALAB-492 Certificate of Dv sent
 G. H. H. Lebowitz, Lamb, Leiby & MacRae 79/06/09 16pp

7904201065 Ack receipt of 790405 board notification (non discussed
 are outside jurisdiction of board & NRC Requests NRC stop
 restrictions in this docket
 G. H. H. Lebowitz, Lamb, Leiby & MacRae 79/04/23 2pp

DOCKETED ITEMS

7904030075 NRC action for summary disposition re radon issue was in error: ALAB-540 corrected only 3 of 16 cases Series NRC action as to parties in other proceedings Certificate of Govt
DUPLO, M E Atomic Safety and Licensing Appeal Panel 79/05/25 3pp

7904030077 Forwarded CE Cuthall statement to be considered as part of
Bare the Valley motion to reopen safety hearing
DATTILO, T M Battalion, F M 79/05/12 1p

7904030080 Transcript of CE Cuthall statement re hexagram patches in
context at facility supporting Bare the Valley motion to
reopen safety hearings
CUTHALL, C E Affiliation Unknown 79/05/08 82pp

K Utility Final Safety Analysis Report (FSAR) & amendments

7904030025 Forwarded Amend 22 to license application-consisting of FSAR
& answers reft for OL stage
COUHLIN, J Public Service Co of Indiana, Inc 79/05/01 3pp

7904030027 FSAR for facility
Public Service Co of Indiana, Inc 79/05/31 800pp

7904030030 Revision reft for OL stage
Public Service Co of Indiana, Inc 79/05/31 800pp

D Inspection reports, IE Bulletins & correspondence

7904030120 Forwarded IE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Support Problem" - No action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/07 1p

7904030121 Forwarded IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/11 1p

7904030225 Notification of 790515 meeting w/NRC in Plainfield, IN to
discuss open findings
FIORELLI, G Region 3, Chicago, Office of the Director 79/05/14 1p

7904030319 Response to IE Bulletin 79-07 requesting info re seismic
stress safety piping analysis DOWNSPEC & PIPES computer
programs are used for piping sig.
COUHLIN, J Public Service Co of Indiana, Inc 79/05/13 3pp

7904030413 Forwarded IE Bulletin 79-11, "Faulty Overcurrent Trip Device
in Circuit Breaker for Engineered Safety Sys." License
action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/32 1p

7904030524 Forwarded IE Info Notice 79-13, "Indication of Low Water
Level in Outer Creek Reactor"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/29 1p

7904030675 Ack receipt of 790502 interim reft re containment sump &
recirculation piping status will complete review wpm
receipt of final reft
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/05/24 1p

7904030618 Ack receipt of 790509 interim reft re damage to containment
liner
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/05/24 1p

7904030604 Ack receipt of 790514 interim reft re post-tensioning
cracks
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/05/29 1p

7904030248 Provides add info re two potentially reportable incidents
because qualifications of welders utilizing Chromo
Contracting Corp welding procedures for radiographic
examination of welds & qualification repts
COUHLIN, J Public Service Co of Indiana, Inc 79/05/08 3pp

U Congressional/Executive Correspondence

7904030038 Forwarded CE Greenwood 790426 for re emergency planning for
localities near nuclear facilities.
MCDONALD, M P Senate 79/05/21 1p

SECRET 87N-30-547 MARBLE HILL NUCLEAR STATION, UNIT 2

C Utility Environmental Report (ER), amendments & correspondence
COUHLIN, J Public Service Co of Indiana, Inc 79/05/01 3pp

7904030030 Revision reft for OL stage
Public Service Co of Indiana, Inc 79/05/31 800pp

D Adjudicatory correspondence

7904030047 Motion for extension until 790511 to prepare response to
ALAB-540
SCIND, J P Hearings Division 79/04/02 3pp

7904030060 Response to 790302 request for info re status of vulnerabilities
proceeding to develop value for radon in Table B-3 Rept &
proposed rule will be sent to NRC by 790404 Rule does not
address health effects of radon released
CHRISTENSEN, E Hearings Division 79/03/26 34pp

7904030164 Util response in support of 4x minimum theory per ALAB-540,
as modified by ALAB-512 & 790305 order Remands
Termination of reservation of jurisdiction initiated in
ALAB-440 & continued in ALAB-493 Certificate of Govt encl
DUPLO, M E LeBeauf, Lamb, Leiby & MacLean 79/04/09 14pp

7904030055 Ack receipt of 790405 board notification Items discussed
are outside jurisdiction of boards & NRC Requests NRC stop
distribution on this docket
DUPLO, M E LeBeauf, Lamb, Leiby & MacLean 79/04/23 2pp

7904030395 NRC action for summary disposition re radon issue was in
error: ALAB-540 corrected only 3 of 16 cases Dennis NRC
action as to parties in other proceedings Certificate of Govt
DUPLO, M E Atomic Safety and Licensing Appeal Panel 79/05/25 3pp

7904030477 Forwarded CE Cuthall statement to be considered as part of
Bare the Valley motion to reopen safety hearing
DATTILO, T M Battalion, F M 79/05/12 1p

7904030550 Transcript of CE Cuthall statement re hexagram patches in
context at facility supporting Bare the Valley motion to
reopen safety hearings
CUTHALL, C E Affiliation Unknown 79/05/08 82pp

K Utility Final Safety Analysis Report (FSAR) & amendments

7904030025 Forwarded Amend 22 to license application-consisting of FSAR
& answers reft for OL stage
COUHLIN, J Public Service Co of Indiana, Inc 79/05/01 3pp

7904030027 FSAR for facility
Public Service Co of Indiana, Inc 79/05/31 800pp

D Inspection reports, IE Bulletins & correspondence

7904030120 Forwarded IE Info Notice 79-11, "Lower Reactor Vessel Head
Insulation Support Problem" - No action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/07 1p

7904030121 Forwarded IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/11 1p

7904030225 Notification of 790515 meeting w/NRC in Plainfield, IN to
discuss open findings
FIORELLI, G Region 3, Chicago, Office of the Director 79/05/14 1p

7904030319 Response to IE Bulletin 79-07 requesting info re seismic
stress safety piping analysis DOWNSPEC & PIPES computer
programs are used for piping sig.
COUHLIN, J Public Service Co of Indiana, Inc 79/05/13 3pp

7904030413 Forwarded IE Bulletin 79-11, "Faulty Overcurrent Trip Device
in Circuit Breaker for Engineered Safety Sys." License
action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/32 1p

7904030524 Forwarded IE Info Notice 79-13, "Indication of Low Water
Level in Outer Creek Reactor"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/29 1p

B. Reportable occurrences, LIRs & related correspondence

- 790620073 Ack receipt of 790502 interim rept re containment sump recirculation piping sleeve W/31 complete review upon receipt of final rept
FIORELLI, D Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/24 1p
- 790620045 Ack receipt of 790509 interim rept re damage to containment liner
FIORELLI, D Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/24 1p
- 790620064 Ack receipt of 790516 interim rept re post-leakdown inspection
FIORELLI, D Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/29 1p
- 790610240 Provide add'l info re two potentially reportable incidents. Discusses qualifications of welders utilizing Chemtec Contracting Corp welding procedures for radiographic examination of welds & qualification pays
COULDER, J Public Service Co of Indiana, Inc 79/06/08 2pp

C. Congressional/Executive Correspondence

- 790620050 Forwards CE Document 790426 1tr re emergency planning for facilities near nuclear facilities
MCCLELLIN, M 2 Senate 79/05/21 1p

DOCKET 50-549 GREENE COUNTY NUCLEAR POWER PLANT

D. Adjudicatory correspondence

- 790620046 Objects to interagency of Green County, NY, because interagency (NYA, FBI & IIR) require compilation of data, research & add calculations. Certificate of Evt Rec'd
LEWIS, B H Branch 2 79/03/05 2pp
- 790640147 Grants various extensions to discovery schedules
GOSWAMI, A C Atomic Safety and Licensing Board Panel COHEN, E D New York, State of 79/03/13 2pp
- 790610030 Objects to still 790303 second document request Certificate of Evt Rec'd
LEWIS, B H Branch 2 79/03/14 13pp
- 790610106 Forwards JC Mitchell 790302 testimony re land use issues
MCCLELLIN, J A Consumer Civic Association 79/03/14 1p
- 790610101 Testifies on land use issues Supporting documentation sent
MCCLELLIN, J A Consumer Civic Association 79/03/15 21pp
- 790610066 Response by Intervenor Greene County (NY) to NRC & NY State Public Use Commission objections to interagency testimony submitted by county to NRC & state Commission witnesses
BUTLER, A H Butzel & Kass 79/03/14, App
- 790610270 Notice of cancellation of all scheduled hearings at request of still
COLLIER, F Atomic Safety and Licensing Board Panel 79/04/19, 1p
- DOCKET 50-550 PHIPPS BEAD NUCLEAR PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 790610703 Concerns w/anal still rept conclusion component cooling water branch fault is minor crack fault. Based on evidence to date, branch fault is considered to be acceptable
JACKSON, R E Occurrences Branch 79/05/14 2pp
- 790620064 Multiplication of 790619 meeting w/anal to discuss leak testing leak & pressure tests for piping embedded in concrete
MCHUGH, R A Light Water Reactors Branch 2 79/05/21 App
- 790620245 Forwards "Structural Geology of Gower Formation Folds & Faults at Plant Site."
GILLESPIE, J E Tennessee Valley Authority 79/06/19, 1p
- 790620246 "Structural Geology of Gower Formation Folds & Faults at Plant Site."
GILLESPIE, J E Tennessee Valley Authority 79/05/16, 10pp.
- 790620024 Forwards add drawings to still to 790430 1tr re fault in area of cooling water pumping station Two oversized drawings sent
GILLESPIE, J E Tennessee Valley Authority 79/06/19 1p
- D. Adjudicatory correspondence
- 790621047 Repts for extension until 790411 to prepare response to ALAD-509
KENTON, J F Hearings Division 79/04/02 2pp
- 790610040 Responds to 790322 request for info re status of nuclear's proceeding to develop value for radon in Table D-3 Reg 1. proposed rule will be sent to NRC by 790405. Rule does not address health effects of radon releases
CHRISTENSEN, E Hearings Division 79/03/26 34pp
- 790610095 NRC action for summary disposition re radon issue was in error. ALAD-509 dematerialized only 3 of 16 cases. Demates NRC action as to parties in other proceedings. Certificate of Evt Rec'd
BUTLER, A H Atomic Safety and Licensing Board Panel 79/03/26 2pp
- G. Inspection reports, IE Bulletins & correspondence
- 790610046 Forwards IE Circular 79-07, "Uninspected Head Increase of Reactor Water Generator Due Resulted in Reactor Power Increase." No written response required
D'EMILY, J P Region 2, Atlanta, Office of the Director 79/03/02 1p
- 790610120 Ack receipt of 790409 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-553/79-02 & 50-554/79-02
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/04 1p
- 790610120 Responds to NRC 790519 1tr re violations noted in IE Insp Repts 50-553/79-02 & 50-554/79-02 Corrective actions requested of Braun & Co to amend concrete spec
GILLESPIE, J E Tennessee Valley Authority 79/04/09 1p
- 790610120 Responds to IE Repts 50-553/79-02 & 50-554/79-02 on 790503-08
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 2pp
- 790610141 Notice of violation from Insp on 790508-08
MURPHY, C E Region 2, Atlanta, Office of the Director 79/03/13 1p
- 790610143 IE Insp Repts 50-553/79-02 & 50-554/79-02 on 790503-08. Noncompliance noted replacement of 3-inch aggregate w/ 1/2-inch aggregate
MURPHY, C E Region 2, Atlanta, Office of the Director 79/03/13 2pp
- 790620098 Responds to IE Bulletin 79-03 investigation shows no piping in use or planned in safety-related area. Effort in progress to locate any ASME B-21.2, Type 304 piping supplied by Youngman Welding & Engineering
GILLESPIE, J E Tennessee Valley Authority 79/05/14, 1p
- 790620121 Ack receipt of 790508 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-553/79-02 & 50-554/79-02
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/16 2pp
- 790620245 Responds to NRC 790413 1tr re violations noted in IE Insp Repts 50-553/79-02 & 50-554/79-02 Corrective actions site procurement files have been reviewed & site OK until review verified. Documentation review ongoing.
GILLESPIE, J E Tennessee Valley Authority 79/05/08 App
- 7906200129 Forwards IE Insp Repts 50-553/79-02 & 50-554/79-02 on 790503-08
MURPHY, C E Region 2, Atlanta, Office of the Director 79/04/13 2pp
- 790620140 Notice of violation from Insp on 790528-29
MURPHY, C E Region 2, Atlanta, Office of the Director 79/04/13 2pp
- 790620144 IE Insp Repts 50-553/79-02 & 50-554/79-02 on 790503-08. Noncompliance noted failure to follow procedures for prefabricated wall rebar preventive maintenance implementation & inspection w/21.
MURPHY, C E Region 2, Atlanta, Office of the Director 79/04/13 2pp

DOCKETED ITEMS

R Periodic operating reports & related correspondence

7704120337 Requests comments & recommendations re const effects monitoring program, semiannual & sediment-saturate reports
Requests response by 7/26/85
JILLER, H.D. Environmental Protection Agency 7/26/84 1p

--7704120338 Response to REC 770318 ltr re violations noted in IE Insp Repts 50-553/79-02 & 50-554/79-02 Corrective actions requested of Branch & Co to avoid concrete repair
GILLILAND, J.E. Tennessee Valley Authority 7/26/84 3pp

--7704120421 Notice of violation from Insp on 770325-02
Region 2, Atlanta, Office of the Director 7/27/83 1p

S Reportable occurrences, LORs & related correspondence

7704120406 Submits interim deficiency report to advise another capacitor being lower than allowed in design allowable initial report made to H Quags on 7/20/82 Final report expected by 7/20/82
GILLILAND, J.E. Tennessee Valley Authority 7/20/84 3pp

--7704120423 IE Insp Repts 50-553/79-02 & 50-554/79-02 on 770325-02 Noncompliance noted replacement of 3-inch aggregate w/lt 3-inch aggregate
WRIGHT, R. J. HENDRICK, A. Region 2, Atlanta, Office of the Director 7/27/83 3pp

7704120431 Forwarded deficiency report re const of piping elbows w/unspecified wall
GILLILAND, J.E. Tennessee Valley Authority 7/27/83 1p

7704120508 Response to IE Bulletin 79-03 Investigation shows no piping in use or planned in safety-related area Efforts in progress to locate any ASME SA-302 Type 304 piping supplied by Youngblood Welding & Engineering
GILLILAND, J.E. Tennessee Valley Authority 7/27/84 1p

--7704120442 Deficiency report on 770325 piping elbows constructed from unspecified wall Elbows without code N6719 were identified, tested & returned to manufacturer
Tennessee Valley Authority 7/27/83 3pp

7704120513 Ack receipt of 770328 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-553/79-02 & 50-554/79-03
WRIGHT, R. J. HENDRICK, A. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 7/26/84 3pp

7704120586 Forwarded detailed description of fault discovered in Unit 2 turbine blade area
GILLILAND, J.E. Tennessee Valley Authority 7/27/84 1p

--7704120525 Response to REC 770418 ltr re violations noted in IE Insp Repts 50-553/79-02 & 50-554/79-03 Corrective actions site management files have been reviewed & site SA unit review verified Documentation review ongoing
GILLILAND, J.E. Tennessee Valley Authority 7/27/84 3pp

DOCKET BTH-50-554 PHIPPS BEND NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7704120733 Concerns w/when until report conclusion component cooling water trench fault is minor cross fault based on evidence to date.
Trench fault is considered to be non-critical
JACKSON, R.E. Tennessee Valley Authority 7/27/84 3pp

--7704120519 Forwarded IE Insp Repts 50-553/79-02 & 50-554/79-03 on 770328-20 & notice of violation
WRIGHT, R. J. HENDRICK, A. Region 2, Atlanta, Office of the Director 7/27/83 3pp

7704120844 Notification of 770419 meeting w/when to discuss leak testing, leak & pressure tests for piping embedded in concrete
BENNETT, R.A. Light Water Reactors Branch 2 7/27/84 3pp

--7704120440 Notice of violation from Insp on 770326-27
Region 2, Atlanta, Office of the Director 7/27/83 3pp

7704120845 "Structural Geology of Benton Formation Folds & Faults at Plant Site"
GILLILAND, J.E. Tennessee Valley Authority 7/27/84 1p

--7704120344 IE Insp Repts 50-553/79-02 & 50-554/79-03 on 770328-27 Noncompliance noted failure to follow procedures for safety-related work contracts, preventive maintenance & inspection
WRIGHT, R. J. HENDRICK, A. Region 2, Atlanta, Office of the Director 7/27/83 3pp

--7704120846 "Structural Geology of Benton Formation Folds & Faults at Plant Site"
GILLILAND, J.E. Tennessee Valley Authority 7/27/84 10pp

R Periodic operating reports & related correspondence

7704120824 Forwarded add drawings to encl to 770340 ltr re fault in area of cooling water pumping station Two overlaid drawings encl
GILLILAND, J.E. Tennessee Valley Authority 7/27/84 1p

7704120337 Requests comments & recommendations re const effects monitoring program, semiannual & sediment-saturate reports
Requests response by 7/26/85
JILLER, H.D. Environmental Protection Agency 7/26/84 1p

G Adjudicatory correspondence

7704121047 Motion for extension until 770411 to prepare response to ALAB-509
BENNETT, R.A. 7/27/84 3pp

S Reportable occurrences, LORs & related correspondence

--7704120560 Response to 770322 request for info re status of rulemaking proceeding to develop value for radon in Table B-3 Repts & proposed rule will be sent to NRC by 770505. Rule does not address health effects of radon released
GIBBERN, R.E. Hearings Division 7/27/84 3pp

7704120406 Submits interim deficiency report to advise another capacitor being lower than allowed in design allowable initial report made to H Quags on 7/20/82 Final report expected by 7/20/82
GILLILAND, J.E. Tennessee Valley Authority 7/27/84 3pp

7704121005 NRC action for summary disposition re radon issue was in error. ALAB-509 considered only 3 of 14 cases. Denies NRC motion as to parties in safety proceedings Certificate of Rev encl.
GILFLO, H.E. Atomic Safety and Licensing Appeal Panel 7/27/84 3pp

7704120431 Forwarded deficiency report re const of piping elbows w/unspecified wall
GILLILAND, J.E. Tennessee Valley Authority 7/27/83 1p

G Inspection reports, IE Bulletin & correspondence

7704120146 Forwarded IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase" & written response required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 7/27/82 1p

--7704120442 Deficiency report on 770325 piping elbows constructed from unspecified wall Elbows without code N6719 were identified, tested & returned to manufacturer
Tennessee Valley Authority 7/27/83 3pp

7704120123 Ack receipt of 770409 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-553/79-02 & 50-554/79-03
WRIGHT, R. J. HENDRICK, A. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 7/27/84 1p

7704120586 Forwarded detailed description of fault discovered in Unit 2 turbine blade area
GILLILAND, J.E. Tennessee Valley Authority 7/27/84 1p

DOCKET BTH-50-554 BLANCH FEE STATION, UNIT 1

A Application/construction stage documents & correspondence

7704120333 Describes technical advisory committee program to assess TH-2 events. Lists assigned tasks included assessing containment isolation & identifying ways used in transfer of radioactive fluid.
FATE, R.E. Public Service Co. of Oklahoma 7/27/84 10pp

DOCKETED ITEMS

□ *Address correspondence to:*

7903010001 Advices of Filing of Will proposed Findings of Fact re: legal authentication methodology for reasons discussed in 790303A
Findings of Facts, conclusions of Law & proposed order
(Certificate of Doc #001)
SWALL, J. 1999m. Lincoln & Seale 79030200 400

7903010009 Util proposed findings of fact re load combination
 methodology
 GALL, J 148am Lincoln & Beale 79030100 148a

H. General correspondence

9904040805 Grants 790402 mayan for extension, until 780410 for
interviewers to file proposed findings of fact & conclusions
of law
HJL/FE/J #10000 Safety and Licensing Board Panel 79/04/11 10

7966010150 Response to 7964517 ltr discusses release of all portions
of safety hearing transcripts
ENCLOSURE T F Office of the Executive Legal Director 79/09/80
2pg

790403059 Series GE 790328 action requesting return of Read rept &
related substat force rept
6804.F J, 6804.E.S J Atomic Safety and Licensing Board Panel
79/04/12 2pp

--7864010JAB requests release of all portions of transcripts of weekly
hearings
CANNETT, W. Affiliation Unknown 78/04/17 1p

7906010410 Grants 790610 motion for extension until 790620, requested by
to file prepleated findings of fact & conclusions of law-as
requested by HRC
HRC/E/S J Atkail Safets and Licensing Board Panel 29/04/17 30

BUCKET BFN-90-987 BLACK FOX STATION, UNIT 2

A Application/construction stage documents & correspondence

7950070068 Response to JO Davis 790413 Ltr Provides info re ultimate heat sink sys & interconnection of sys between reactors
Certificate of Work 0401
DALEDA A F Baker, A F 790413 Doc

780420030 Describes technical advisory committee program to
THI-2 events & apply lessons learned facts included assessing
containment isolation & identifying ops used in transfer
of Radiogenic Fluid
FATE, H.E. Public Service Co. of Delaware 78/04/15 0000

196040079 Forwards application & complains as attachment to motion
of State of OR for redemptive stay in issuance of initial
decision
ADDRESS C 3 Olatona, State of 79/04/30 09g

③ 艾迪生爱灯，爱得最热烈。

© 2006 The Authors
Journal compilation © 2006 Blackwell Publishing Ltd

7904080500 Notice of Filing by Mail to proposed findings of fact & conclusions of law from HRC & intervenors. Notice of appearance of HE Gibbs on behalf of Mail & Certificate of Doc sent

Finding of facts, conclusions of law & proposed order
 Certificate of Doc and
 GMLD-J Isham, Lincoln & Seale 7/7/2018 4pp

--790600204 Response by utrl to proposed findings of fact & concl
of law from NRC & joint intervenors Citizens Action for
Safe Energy, L Youngblain & L Burrall Limited re findings
where clarification of record is required
GIBBS, M E ; GALLO, J Isha, Lincoln & Seale 29/04/26 37p

methodology
GALLAGHER, J. A., LARSEN, L. & DAVIS, J. 2005. 1000. 1400.

7906060154 Until request that ARS grant extension until 790801, to permit will be file answer to State of OK 790419 motion for indefinite stay in issuance of initial decision Certificate of Div and

041101-0 Public Service Co of Oklahoma 79060300 dkt

7906040089 Denial of 790608 notice requesting return of Road rep4 & related subtrack force main

790404002A Grants will 790804 motion to file replies by 790810 to
Interviewers 790427 responses to State of OK 790427 motion for
indefinite stay to issuance of initial decisions
MOJPE.9 J Atomic Safety and Licensing Board Panel 79/03/04 10

790426D12 Grants 790416 notice for extension until 790426 requested by
to file proposed findings of fact & conclusion of law as
requested by NRC
HOLFE, G J Atomic Safety and Licensing Board Panel 790426/12 G

7905280590 Requests ASLS grant extension until 790519 for Utah to file answer by Inter-viewers 790419 action for indefinite stay of initial decision Helian seeks addl relief; reply is warranted Certificate of Evnt sent
GMALEJ Public Service Co of Oklahoma 79/05/04 See

7906050068 responds to JD 8ev14 T90411 ltr Provides info re ultimate
best sink vs b submersement of sgs between reactors
Certificate of Gov encl
DALTON-A F Dalton, A F 79/04/17 3pg

7706200100 Submits draft of proposed ECG findings which reflect record as of close of Feb 1979 bearing Certificate of Gvc
ecsl
Garcia, L. B. Research, A. 770605000 Gvc

PROBATIONER Forwards application & complaint as app
of State of OK for indefinite stay in lieu of a
decision
EXHIBIT C is Oklahoma, State of 78/04/80 Su

7906280490 Response by applicants to State of OH motion for indefinite stay in instance of initial decision State lacks standing to file motions w/RR&L legal requirements for obtaining stay have not been met w/ supporting ltr & Certificate of Dec
Nashville - JENNIFER M K

TP060000350 Notice of Filing of 4531 re proposed findings of Facts &
conditions of law from NRC & Intervenor's Notice of
Appearance of NE Gibbs on behalf of 4531 & Certificate of
Env and
GALLAGHER, GIBBS & N E Isham Lincoln & Beale 7/9/04/26 3pg

79045700320 Grants applicants 7905221 Motion to file reply by 790522; to
NRC response to State of GA motion for indefinite stay on
issuance of initial decision & to interlocutor 7905218 motion
to reopen record
NOLPER, S J Atomic Safety and Licensing Board Panel 7905218

790602054 Response by still to proposed findings of fact & conclusions
of law from NRC & joint intervenors Citizens Action for
Safe Energy, 1 Yonge St. & L. Burrall Limited to findings
where clarification of record is required
01998.H.K. & GALLAGHER, Susan, Lincoln & Beale 79/06/26 37pg

7906290171 Certifies NRC determination of returning Reed rept & subseq force rept to GE Two requests to return rept were untimely Recommendation rept under protective order, be returned
WOLFE-B Atomic Safety and Licensing Board Panel 79/06/06, Re

7904080114 Will request that ASLB grant extension until 790 permit until to file answer to State of OR 790417 notice for indefinite stay in lieu of initial decision Certificate of Rev entl
DALLIDJ Public Service Co of Oklahoma 7908030 de

DOCKETED ITEMS

7906040004 Grants until 790304 motion to file reply by 790304 to intervenors 790407 response to State of OK 790407 motion for indefinite stay in issuance of initial decision
WJFBE, B J Atomic Safety and Licensing Board Panel 79/03/04 1p

7906030050 Requests ASLB grant extension until 790508 for writ to file answer to intervenors 790419 motion for indefinite stay of initial decision Motion seeks ASLB relief; reply is unopposed Certificate of Vol assent
GALLU, J Public Service Co of Oklahoma 79/03/04 3pp

7906020010 Rehears draft of proposed RCR findings which reflect record as of close of Feb 1978 hearing Certificate of Vol assent
DUFFEL, D Branch 4 79/05/09 3pp

7906020090 Response by applicants to State of OK motion for indefinite stay in issuance of initial decision State lacks standing to file motion w/ASLB; legal requirements for obtaining stay have not been met w/supporting ltr & Certificate of Vol assent
GALLU, J, GIBSON, E Idaho, Lincoln & Beale 79/05/11 24pp

7906040022 Grants applicant 790501 motion to file reply by 790501 to NRC response to State of OK motion for indefinite stay on issuance of initial decision & to intervenor 790508 motion to reopen record
MILFEL, J Atomic Safety and Licensing Board Panel 79/05/02 1p

7906020071 Certifies RCR determination of returning Reactor & subunit force repts to SE Two requests to review repts were unopposed; reprints under protective order, be returned
MILFEL, J Atomic Safety and Licensing Board Panel 79/05/02 3pp

7906020104 Motion by SE to quash ASLB 790508 subpoena to produce Reactor Rept 6 willing to submit repts for use by ASLB to determine need of reprints to proceeding; ASLB appearance to present oral argument in support of motion
GIBSON, E L, GALLU, J R Morgan, Lewis & Bockius 79/10/30 3pp

7906020029 Memo by SE regarding 790503 motion to quash ASLB 790508 subpoena to produce Reactor Rept Requests discovery be denied info material relevant not necessary to decision w/supporting documentation
EDGAR, S L, GALLU, J R Morgan, Lewis & Bockius 79/10/30 4pp

H General correspondence

7906050103 Responds to 790417 for discusses release of all portions of safety hearing transcripts
DUFFEL, D T F Office of the Executive Legal Director 79/05/08 3pp

7906060106 Requests release of all portions of transcripts of safety hearings
GIBSON, E Affiliation Unknown 79/04/17 1p

DOCKET ETH-50-566 B-GNE-203

A Application/construction stage documents & correspondence

7906070109 Discusses and BSW responses to NRC request for info re generic issues identified in answers to BSW-261 First round questions
EDWARDS, R L Assistant Director for Plant Systems 79/04/03 1p

DOCKET ETH-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

7906010005 Notification of 790501 meeting w/uttl in Conith-MB to observe & discuss site geology & soils
8003, H Light Water Reactors Branch 2 79/05/07 2pp

7906020004 Notification of 790609 meeting w/uttl to discuss leak testing temp & pressure tests for piping embedded in concrete
8003, H A Light Water Reactors Branch 2 79/05/03 4pp

7906070007 Summary of 790501 site visit & meeting w/MB Geological Survey, AL Geological Survey, Army Corps of Engineers & TVA at Yellow Creek site to inspect & discuss foundation conditions & verify continuity of exposed geological strata
LEFEBVRE, H E Associates Branch 79/05/04 3pp

G Inspection reports, IN Bulletin & correspondence

7906010010 Forwards IE Insp Repts 90-566/79-03 & 90-567/79-03 on 790510-15 ASB noncompliance noted
HARFV, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 2pp

7906010020 IE Insp Repts 90-566/79-03 & 90-567/79-03 on 790512-15 ASB noncompliance noted Major areas inspected core status; procedures; work performance & associated quality records for site preparation & structural concrete
HARFV, C E Region 2, Atlanta, Office of the Director, BSWAT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 4pp

7906020021 Forwards IE Insp Repts 90-566/79-03 & 90-567/79-03 on 790510-15 ASB noncompliance noted
HARFV, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 2pp

7906020024 IE Insp Repts 90-566/79-03 & 90-567/79-03 on 790510-15 ASB noncompliance noted Major areas inspected const status; licensee action on previous insp findings; QA records; warehouse storage & preventive maint sys
GIBSON, E J, HARFV, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 7pp

7906020008 Response to IE Bulletin 79-03 Investigation shows no piping in use or planned in safety-related pipe effort in progress to locate any ASLB SA-312, Type 304 piping supplied by Trumbull Welding & Engineering
GILBLAND, J E Tennessee Valley Authority 79/05/14 1p

M Reportable occurrences, LERs & related correspondence

7906010021 Forwards deficiency repts in const of piping elbows w/unidentified matl
GILBLAND, J E Tennessee Valley Authority 79/05/22 1p

7906010040 Deficiency repts on 790525 piping elbows constructed from unspecified matl Elbows without code MATN were identified, tested & returned to manufacturer
E Tennessee Valley Authority 79/05/25 2pp

DOCKET ETH-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7906010020 Notification of 790501 meeting w/uttl in Conith-MB to observe & discuss site geology & soils
8003, H Light Water Reactors Branch 2 79/05/07 2pp

7906020004 Notification of 790609 meeting w/uttl to discuss leak testing temp & pressure tests for piping embedded in concrete
8003, H A Light Water Reactors Branch 2 79/05/03 4pp

7906070007 Summary of 790501 site visit & meeting w/MB Geological Survey, AL Geological Survey, Army Corps of Engineers & TVA at Yellow Creek site to inspect & discuss foundation conditions & verify continuity of exposed geological strata
LEFEBVRE, H E

DOCKETED ITEMS

790610098 Response to IE Bulletin 79-03 Investigation shows no piping in use or planned in safety-related system effort in progress to locate any ASME SA-312 Type 304 piping supplied by Thompson Welding & Engineering
MILLARD, J E Tennessee Valley Authority 79/05/14 1p

5 Reportable occurrences, CERs & related correspondence

790610043 Forward deficiency report re cost of piping elbows unspecified metal
MILLARD, J E Tennessee Valley Authority 79/05/28 1p

790610042 Deficiency report re 790329 piping elbows constructed from unspecified metal Elbow without code W6719 were identified, tested & returned to manufacturer
Tennessee Valley Authority 79/05/25 2pp

SECRET BTM-50-540 RDP NUCLEAR UNIT 1

A Application/construction stage documents & correspondence

790608029 Forward "Distribution & Abundance of Lobster Larvae in Block Island Sound, 1978"
HARRINGTON, J New England Power Co 79/05/30 1p

790608020 "Distribution & Abundance of Lobster Larvae in Block Island Sound, 1978"
HERSEY, R MILLARD, J P Raytheon Co 79/05/30 50pp

790610003 Forward preliminary case report & fourth draft of "Historic, Architectural & Archeological Investigation of Former Charleston Naval Air Station & Vicinity"
MILLARD, R L Environmental Projects Branch 1 79/05/31 10pp

790610032 "Historic, Architectural & Archeological Investigation of Former Charleston Naval Air Station & Vicinity," fourth draft
Rhode Island, State of 79/05/28 60pp

790610029 Forward "Population Statistics & Commercial Catch Rate of American Lobster (Homarus Americanus) in Charleston - Narragansett Region of Block Island Sound"
HARRINGTON, J New England Power Co 79/04/28 1p

790610027 "Population Statistics & Commercial Catch Rate of American Lobster (Homarus Americanus) in Charleston - Narragansett Region of Block Island Sound"
MILLARD, R L New England Power Co DAVID, H Yankee Atomic Electric Co YAE-1149 79/04/30 50pp

7906120402 Forward "Currents & Residual Drift in Block Island Sound During Period Feb-Dec 1977"
HARRINGTON, J New England Power Co 79/04/06 1p

7906120402 "Currents & Residual Drift in Block Island Sound During Period Feb-Dec 1977"
SHOXB, J H New England Power Co JACOBS, J P Yankee Atomic Electric Co YAE-1149 79/04/30 170pp

790612029 Forward "Velocity Cap Fish Entrapment Assessment, Phase II, Comparative Study"
HARRINGTON, J New England Power Co 79/04/07 1p

790612023 "Velocity Cap Fish Entrapment Assessment, Phase II, Comparative Study"
Yankee Atomic Electric Co 79/05/03 225pp

790610028 Forward revised pages to PSAR, indicating that ref to Westinghouse RBMCR, Revision 3, includes Amendment 1-0 info will be included in Amend RB3 of PSAR
DAVID, H New England Power Co 79/06/10 2pp

790610088 Confirms action notification re suspension of efforts to locate DR & CP until OSA decision on disposition of Charleston RI site. Forward 790412 press release announcing curtailment of activity
HARRINGTON, J New England Power Co 79/06/13 1p

D NRC Draft/Final Environmental Statements, apply & correspondence

790609034 Forward DES re CP application (INARS-0209) & PM notice of availability Also Forward Request alternate site study (INARS-0201) & Pilgrim FEG/Final app (INARS-0204) for use in review of DES
MILLARD, R L Environmental Projects Branch 1, 79/05/31 5pp

790608018 Notice of availability of DES
MILLARD, R L Environmental Projects Branch 1 79/05/31 2pp

790605048 DES re plant cost
Office of Nuclear Reactor Regulation NRES-0209 79/05/31 20pp

790605076 Final report to PER re plant cost
Office of Nuclear Reactor Regulation NRES-0209 79/05/31 100pp Available at NRES 723

790609014 Forward DES for proposed facilities & notice of availability Requests comments
MILLARD, R L Environmental Projects Branch 1 79/05/31 1p

790612029 Offers re comment on DES
CUTNER, H L Agriculture Dept of 79/06/03 1p

790612010 No comments on DES re plant cost
MCARTHUR, R R Transportation Dept of 79/06/13 1p

G Application correspondence

790608028 Forward 790314 Board notification re recent issue on nonseafarers-grade equipment to mitigate transients
CUTNER, H L Branch 3 79/05/30 2pp

790608024 Board notification retrans nonseafarers-grade equipment to mitigate transients Requests add review to assure adequate thermal margins
CUTNER, H L Assistant Director for Reactor Safety 79/05/31 2pp

I Financial Information

790610018 Apply for order withholding financial info from public disclosure Pursuant Revision 3 in response to 781016 Ltr
Representing affidavit and
CUTNER, H L New England Power Co 79/05/09 17pp

790610003 Advice of public release of financial tables, forecasts & schedules submitted w/790209 Ltr to PDB Third day, have elapsed since NRC 790312 request for justification for withholding data
HARR, G S Light Water Reactors Branch 3 79/05/11 4pp

SECRET BTM-50-540 RDP NUCLEAR UNIT 2

A Application/construction stage documents & correspondence

790608029 Forward "Distribution & Abundance of Lobster Larvae in Block Island Sound, 1978"
HARRINGTON, J New England Power Co 79/05/30 1p

790610030 "Distribution & Abundance of Lobster Larvae in Block Island Sound, 1978"
HERSEY, R MILLARD, J P Raytheon Co 79/05/30 50pp

790610003 Forward preliminary case report & fourth draft of "Historic, Architectural & Archeological Investigation of Former Charleston Naval Air Station & Vicinity"
MILLARD, R L Environmental Projects Branch 1 79/05/31 10pp

790610092 "Historic, Architectural & Archeological Investigation of Former Charleston Naval Air Station & Vicinity," fourth draft
Rhode Island, State of 79/05/28 60pp

790610029 Forward "Population Statistics & Commercial Catch Rate of American Lobster (Homarus Americanus) in Charleston - Narragansett Region of Block Island Sound"
HARRINGTON, J New England Power Co 79/04/28 1p

790610027 "Population Statistics & Commercial Catch Rate of American Lobster (Homarus Americanus) in Charleston - Narragansett Region of Block Island Sound"
MILLARD, R L New England Power Co DAVID, H Yankee Atomic Electric Co YAE-1149 79/04/30 50pp

7906120402 Forward "Currents & Residual Drift in Block Island Sound During Period Feb-Dec 1977"
SHOXB, J H New England Power Co JACOBS, J P Yankee Atomic Electric Co YAE-1149 79/04/30 170pp

7906120402 "Currents & Residual Drift in Block Island Sound During Period Feb-Dec 1977"
SHOXB, J H New England Power Co JACOBS, J P Yankee Atomic Electric Co YAE-1149 79/04/30 170pp

DOCKETED ITEMS

7906100079 Forwarders "Velocity Cap Fish Entrapment Assessment, Phase II, Comparative Study"
HARRINGTON, J. New England Power Co 79/05/07 1p

--7906100080 "Velocity Cap Fish Entrapment Assessment, Phase II, Comparative Study"
a Yankee Atomic Electric Co 79/03/20 200pp

7906100081 Forwarders revised pages to PSAR, indicating that ref to Westinghouse NRCAR, Revision 3 includes Amends 1-4. Info will be included in Amend H12 of PSAR
HARRINGTON, J. New England Power Co 79/06/13 3pp

7906100082 Confirmed action notification re suspension of efforts to obtain O&S CFE until O&S decision on disposition of Charleston, RI site Forwarders 790612 press release announcing curtailment of activity
HARRINGTON, J. New England Power Co 79/06/13 1p

D NRC Draft/Final Environmental Statements, supply & correspondence

7906050154 Forwarders DEC re OP application (NRCG-0089) & PR notice of availability Also Forwarders Westinghouse alternate site study (NRCG-0090) & Program FBS, final supp (NRCG-0091), for use in review of DEC
BALLARD, B. L. Environmental Projects Branch 1 79/05/21 3pp

--7906050155 Notice of availability of DEC
BALLARD, B. L. Environmental Projects Branch 1 79/05/21 3pp

--7906050162 DEC re plant cost
a Office of Nuclear Reactor Regulation NUREG-0029 79/05/21 324pp

--7906050176 Final suppl to PSR re plant cost
a Office of Nuclear Reactor Regulation NUREG-0029 79/05/21 533pp Available at NTIS 7-25

7906100216 Forwarders DEC for proposed facilities & notice of availability Requests comments
BALLARD, B. L. Environmental Projects Branch 1. 79/05/21 1p

7906100376 Offers no comment on DEC
CUTCHER, M. L. Agriculture, Dept of 79/06/03 1p

7906101576 No comments on DEC re plant cost
NRCATIN, J. S. Transportation, Dept of 79/06/13. 1p

D Adjudicatory correspondence

7906100159 Forwarders 790316 Board notification re recent issue on non-safety-grade equipment to mitigate transients
CUTCHER, J. M. Branch 3 79/05/03 3pp

--7906100166 Board notification recent non-safety-grade equipment to mitigate transients Recommends add reviews to ensure adequate thermal margins.
TERRANCE, S. L. Assistant Director for Reactor Safety 79/05/16 3pp.

I Financial information

7906100016 Apply for order withholding financial info from public disclosure Forwarders Revision 3 in response to 790106 1p
Supporting affidavit encl
BRYCE, G. A. New England Power Co. 79/02/09 17pp

7906100003 Advice of public release of financial tables, forecasts & schedules submitted w/790209 1tr to PSRs thirty days have elapsed since NRC 790308 request for justification for withholding data.
PARR, D. D. Light Water Reactors Branch 3 79/05/13 4pp

DOCKET ESH-50-572 ESHAR-414

A Application/construction stage documents & correspondence

7906100057 Comments on ESHAR-414 integrated protection sys. Applicants should provide reliability analysis of protective sys to assess whether sys will perform satisfactorily after installation
LIFKIN, L. H. Q. Argonne National Laboratory 79/04/30. 2pp

DOCKET ESH-50-572 DASHA NUCLEAR POWER PROJECT

A Application/construction stage documents & correspondence

7906100081 Concludes that IAEA investigations of proposed Philippine nuclear reactor application are sufficient NRC should be aware of previous comments re application threshold before decision is made on application merit
DENTON, H. R. Office of Nuclear Reactor Regulation 79/01/22 3pp

7906100019 Responds to 790110 1tr re export requirements for reactor equipment intended for The Philippines Equipment not subject to NRC export licensing authority
RHEA, J. A. Office of International Programs 79/03/08 1p

--7906100032 Responds to 790032 memo re export of reactor equipment The Philippines Components are listed as balance of plant equipment
SUNCH, D. F. Program Support Branch 79/02/07 1p

--7906100038 Forwarders Westinghouse 790119 1tr listing reactor equipment for export to The Philippines Equipment is not considered to be specifically designed or prepared for use in nuclear facility Requests comments
SPLINER, D. C. Assistant Director for Export/Import & International Safeguards 79/02/02 1p

--7906100048 Forwarders 1tr in chronological shipping order of balance plant components intended for shipment to The Philippines Inquires whether mail is subject to NRC export licensing action
RHEA, J. P. Westinghouse Electric Corp 79/01/19 3pp

7906100050 Requests that NRC consider neutron detector positioning device & safety injection sys accumulators for export
RHEA, J. P. Westinghouse Electric Corp 79/05/02 2pp

--7906100034 Ask receipt of 790427 1tr concerning export of reactor components to The Philippines Review of components has been initiated
RHEA, J. A. Office of International Programs 79/05/01 1p

G Adjudicatory correspondence

7906100081 Opens prepared shipment of Westinghouse reactor to The Philippines
RHEA, J. P. Affiliation Unknown 79/04/10 2pp

7906100082 Petition to Intervene & request for hearing per 30CFR110.2 for Development Policy, JN Parties & Philippine Movement for Nuclear Protection Supporting documentation encl
ASHER, T. R.; RODIN, H. B. Asher, T. R. PC 79/04/19 20pp

7906100138 Requests denial of joint interveners 790419 petition to Intervene He objects to consolidation of 35080-1472 & 38-0180 opposes consolidation w/35080-0013 Certificate of BvC encl
BICKER, J. M. Office of the Executive Legal Director 79/05/22 2pp

7906100376 Joint reply of petitioners to NRC & Westinghouse request for denial of intervenor status Petitioners have standing under all applicable tests Consolidation of licenses will add proceedings Certificate of BvC encl
ASHER, T. R.; RODIN, H. B. Asher, T. R. PC 79/06/04 13pp.

DOCI

B

7906100124 Forwarders PSAR Amend 22 re O&S in response to NRC 790403 1tr affidavit encl
HCHREITER, R. J. Ohio Edison Co 79/06/05 3pp

--7906101259 Amend 02 to PSAR
a Ohio Edison Co 79/06/05 14pp.

G Adjudicatory correspondence

7906100083 Responds applicant 790216 motion to dismiss C Stebbins & Coalition for Safe Electric Power as intervenors; ARLS 790400 & 790102 orders disqualify all contentions of these intervenors Certificate of BvC encl.
BARTH, G. A. Branch 2 79/03/07 3pp

7906100376 Forwarders memo re behavior of iodine during postulated steam generator tube rupture
BARTH, G. A. Branch 3 79/04/08 1p

DOCKET STN-90-581 ERIE NUCLEAR PLANT, UNIT 2

B Utility Preliminary Safety Analysis Report: amendments

790400134 Forwards PSAR amend 22 re 9A in response to NRC 7904030
 1TR Affidavit re:1
 NRC/HQ/ED:R J. Chris Edison Co 79/04/05 3pp

--790410120 Amend 22 to PSAR
 * Chris Edison Co 79/04/05 1app

G Adjudicatory correspondence

7903210403 Supports applicant 790284 motion to dismiss E Shokins &
 Coalition for Safe Electric Power as intervenors:ASL
 790400 6 790402 orders dismissed all contentions of three
 intervenors Certificate of Doc encl
 BARTH, C A Branch 2 79/03/07 3pp

7904000374 Forwards memo re behavior of turbine during postulated steam
 generator tube rupture accidents
 BARTH, C A Branch 3 79/04/09 1p

DOCKET STN-90-588 REGUCLA NUCLEAR POWER STATION

G Adjudicatory correspondence

7904000374 Forwards memo which contains info potentially relevant to
 issue of sabotage of spent nuclear fuel
 BARTH, C A Branch 3 79/04/09 3pp

DOCKET STN-90-589 ARCO PISCATAWAY NUCLEAR POWER STATION

G Adjudicatory correspondence

7904000374 Forwards memo which contains info potentially relevant to
 issue of sabotage of spent nuclear fuel
 BARTH, C A Branch 3 79/04/09 3pp

DOCKET STN-90-592 PALO VERDE NUCLEAR STATION, UNIT A

A Application/Construction stage documents & correspondence

7904230128 PR notice of AGRR 790400-07 meeting in Washington:DC
 HOLYE, J L AGRR - Advisory Committee on Reactor Safeguards
 79/03/14 3pp

7903100397 Confirms 790423 meeting in Riverside, CA
 GELBERG, J R Anti-Trust Division 79/04/10 1p

7904070290 Comments on utility owner data statement in response to NRC
 790410 request for conflict of interest plans Requests info re
 plant for use of retained consultant for cooling water
 ARND, N Armg. Dept. of Corps of Engineers 79/04/01 1p

7904100208 Confirms 790400 telcon extending comment review period for
 BEI until 790408
 WAGNER, D Environmental Protection Agency 79/04/08 1p

C Utility Environmental Reports CER: amendments & correspondence

900050080 Forwards Suppl 2 to opinion report for CP stage
 ATLE, E Arizona Public Service Co 79/04/04 3pp

75 Suppl 2 to opinion report for CP stage re alternative
 fossil energy source evaluation
 Arizona Public Service Co 79/04/04 100pp

Iron report for CP stage & "Preliminary
 Archaeological Assessment of Five Alternative Pipeline
 Routes & Four Alternative Wellpaths" by Museum of Northern
 AZ Dept of Anthropology
 AZ Dept of Anthropology
 * Arizona Public Service Co 79/05/31 05pp

--7904100808 Suppl 2 to opinion report for CP stage & preliminary
 Archaeological Assessment of Five Alternative Pipeline
 Routes & Four Alternative Wellpaths" by Museum of Northern
 AZ Dept of Anthropology
 * Arizona Public Service Co 79/05/31 05pp

D NRC Draft/Final Environmental Statements, update & correspondence

7904100270 Confirms 790400 telcon granting extension until 790406 to
 comment on EIS
 WAGNER, D Environmental Protection Agency 79/04/08 1p

7904000339 Supports joint applicant-consent comments on EIS
 VAN BUREN, E E Arizona Public Service Co 79/04/11 30pp

7904000462 Forwards comments on EIS suggests expansion of radiological
 waste disposal section to indicate alternatives Section on
 environmental impact of past accidents should be deleted it
 is outdated
 GUSTAF, C Health, Education & Welfare, Dept of 79/04/21 3pp

G Adjudicatory correspondence

7904040420 Requests funding as intervenor in proceeding Cost &
 available time for preparation with NRC funding necessary
 BARR, L Affiliation Unknown 79/03/27 2pp

7904050048 Responds to 790324 ltr requesting notification of hearing
 date & time No hearing date set at present time
 BISHOP, S M Branch 2 79/04/03 1p

7904010331 Forwards Rules of Practice 100P21 & 781208
 supplemental FR notice of hearing W/o encl
 BISHOP, S M Branch 3 79/04/10 3pp

7904000437 Confirms 790404 meeting in Los Angeles, CA
 GELBERG, J R Anti-Trust Division 79/04/17 1p

7904000330 Joint applicants' response to Palo Verde Nuclear intervenor
 amended petition for ex-intervention Petitioners are not
 entitled to intervene as matter of right or matter of
 discretion Certificate of Doc encl
 BISHOP, S M, GELBERG, J C, Gail & Hilar 79/04/26 12pp

7904000243 Petition to Intervene Notice of appearance of D Hestbaum
 AS one on behalf of intervenor Affidavit of SA Sutter &
 Certificate of Doc encl
 WAGNER, D, SEC, D 3 Environmental Defense Fund 79/05/03 21p

7904000291 Requests opportunity to testify at hearing on CP
 79030708 A. Bissler Anti-Trust Group 79/03/07 1p

7904000357 Denies Palo Verde Nuclear intervenors 790326 amended
 petition to ex-intervene Petitioners failed to justify
 why they are filing of original petition
 LAIRD, N M Atomic Safety and Licensing Board Panel 79/05/10 7p

7904000231 Forwards 790511 petition to intervene by Maranga Band of
 Mission Indians Denies intervention to request for special
 consideration re svc requirements
 GELBERG, J R, V California Indian Legal Services 79/03/14 3pp

--7904000225 Petition to intervene by Maranga Band of Mission Indians
 Proposed transmission lines will adversely affect
 Indians' use of reservation lands Notice of appearance
 & Certificate of Doc encl
 GELBERG, J R, V California Indian Legal Services 79/05/11 11pp

7904070293 State of CA & CA Public Utility Commission motion for
 extension until 790325 for letter to file formal comments re
 DEN DEN not received until 790307/Commission needs add'l time
 for evaluation Certificate of Doc encl
 MCKENNETT, V V California, State of 79/03/16 7pp

7904000462 Responds to 790327 ltr requesting NRC funding for
 participation in proceeding Request has been denied
 Funding policy currently under consideration
 BISHOP, S M Commission 79/03/17 1p

7904100803 Orders inadmissibility of S. Bard 790301 First amended
 contention challenging Section 3 D 2 of 100P21, App B, re
 spent fuel containers DEN DEN & third amended interventions re
 transportation of radioactive waste should remain open
 LAIRD, N M Atomic Safety and Licensing Board Panel 79/03/10 4p

7904000170 Opposes Facility cost Unneeded extra generating capacity
 waste problem remains unresolved
 WAGNER, D A. Affiliation Unknown 79/05/30 3pp

7904000181 Motion to file reply to NRC & joint applicants' response 1
 Intervenor Defense Fund petition to intervene Responses contain
 factual inaccuracies/citation of inappropriate cases &
 inaccurate analyses Certificate of Doc encl
 WAGNER, D, NRC, B 3 Environmental Defense Fund 79/04/24 4pp

DOCKETED ITEMS

22

H General correspondence

7906150020 Comments on DOE suggests acceptance of waste by using separation Solar energy is more appropriate technology
Expresses concern re high level wastes Urges and to nuclear power
* Affiliation Unknown 79/06/11 App

I Financial information

7906200326 Notification of 790623 meeting w/uttl in Bethesda, MD to discuss submission of nonproprietary financial info to complete review
LICITRA, E A Light Water Reactors Branch D 79/05/14 App

DOCKET ITEM-90-090 PAID VERDE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

7906200326 FR notice of ACRS 790405-07 meeting in Washington, DC
HIGLEY, J L ACRS - Advisory Committee on Reactor Safeguards 79/05/16 App

7906150329 Confirms 790623 meeting in Riverside, CA
GILBERT, J H Anti-Fraud Division 79/06/10 App

7906200326 Comments on uttl involves date statement. In response to NRC 790413 request for conflict of interest plans Requests info re plans for use of relicensed wastewater for cooling units
ACRS, H Army Dept of Corps of Engineers 79/06/01 App

7906150326 Confirms 790623 notice attending commission review period for
GEO, J L ACRS - Advisory Committee on Reactor Safeguards 79/05/16 App

C Utility Environmental Report (ER), amendments & correspondence

7906200326 Forwarded Suppl 2 to environ report for CP stage
VAN BRUNT, E E Arizona Public Service Co 79/06/04 App

7906200326 Suppl 2 to environ report for CP stage re alternative supplemental water source evaluation
* Arizona Public Service Co 79/06/04 100pp

7906150432 Forwarded Suppl 2 to environ report for CP stage & Preliminary Archaeological Assessment of Five Alternative Pipeline Routes & Four Alternative Halfpiles by Museum of Northern Arizona Dept of Anthropology
COTTE, P H NRC Corp 79/06/08 App

7906150446 Suppl 2 to environ report for CP stage & preliminary Archaeological Assessment of Five Alternative Pipeline Routes & Four Alternative Halfpiles by Museum of Northern Arizona Dept of Anthropology
* Arizona Public Service Co 79/06/01 99pp

7906200437 Forwarded Affidavit of Sec for Suppl 2 to environ report
VAN BRUNT, E E Arizona Public Service Co 79/06/18 23pp

B NRC Draft/Final Environmental Statements, supplements & correspondence

7906150270 Confirms 790609 notice granting extension until 790626 to comment on DOE
KATZ, R A Environmental Defense Fund 79/06/08 App

7906200326 Submits joint applicant-commentary comments on DOE
VAN BRUNT, E E Arizona Public Service Co 79/06/11 30pp

7906200442 Forwarded comments on DOE suggests acceptance of radioactive waste disposal section to indicate alternative Section re environ impact of postulated accidents should be deleted if it is included
CLINTON, C Health, Education & Welfare, Dept of 79/06/21 App

D Adjudicatory correspondence

7906200442 Requests funding as intervenor in proceeding Cont & available time for preparation make NRC funding necessary
BARD, L Affiliation Unknown 79/05/27 App

7906200442 Responds to 790326 ltr requesting notification of hearing date & time No hearing date set at present time
GILBERT, J H Branch D 79/06/08 App

7906150326 Forwarded Rules of Practice(10CFR29 & 701208 supplemental FR notice of hearing NRC and
GILBERT, J H Branch D 79/06/10 App

7906200327 Confirms 790424 meeting in Los Angeles, CA
GILBERT, J H Anti-Fraud Division 79/06/17 App

7906200326 Joint applicants' response to Palo Verde Nuclear intervenors' amended petition for co-intervention Petitioners are not entitled to intervene as matter of right or matter of discretion Certificate of Sec and
GILBERT, J H Branch D 79/06/26 13pp

7906200326 Petition to Intervene Notice of appearance of B Hestum & DO Ros on behalf of intervenor Affidavit of MR Gutter & Certificate of Sec and
HISTORICAL, D NRC-D Environmental Defense Fund 79/06/08 31pp

7906200326 Requests opportunity to testify at hearing on CP
JORDAN, A Ethics Anti-Nuclear Group 79/05/07 App

7906200326 Denies Palo Verde Nuclear intervenors' 790326 amended petition to co-intervene Petitioners failed to justify untimely filing of original petition
LADD, R H Atomic Safety and Licensing Board Panel 79/05/10 App

7906200326 Forwarded 790611 petition to intervene by Menzies Band of Mission Indians Draw attention to request for special consideration re requirements
GILBERT, J H California Indian Legal Services 79/06/16 App

7906200326 Petition to intervene by Menzies Band of Mission Indians Proposed transmission lines will adversely affect Indians' use of reservation Lands Notice of appearance Certificate of Sec and
GILBERT, J H California Indian Legal Services 79/05/11 11pp

7906200326 State of CA & CA Public Utility Commission notice for extension until 790701 for letter to file formal comments re DOE SEC not received until 790609/Commission needs addl time for evaluation Certificate of Sec and
GILBERT, J H California State of 79/05/16 App

7906200326 Responds to 790327 ltr requesting NRC funding for participation in proceeding Request has been denied Pending policy currently under consideration
HISTORICAL, D Commission 79/06/17 App

7906150326 Orders inadmissibility of L Dard 790301 first amended content challenge Section 3 B 2 of 10CFR71 App 3 re agent fuel containers Section 3 third amended content challenge re transportation of radioactive waste should remain open
LADD, R H Atomic Safety and Licensing Board Panel 79/06/18 App

7906200326 Opposes facility cannot Unneeded extra generating capacity waste problem remains unresolved
GILBERT, J H Affiliation Unknown 79/06/08 App

7906200326 Motion to file reply to NRC 6 point applicants response to Environ Defense Fund petition to intervene Responses contain factual inaccuracies, citation of inaccurate cases & inadequate analyses Certificate of Sec and
HISTORICAL, D NRC-D Environmental Defense Fund 79/06/01 App

H General correspondence

7906150326 Comments on DOE suggests acceptance of waste by using separation Solar energy is more appropriate technology
Expresses concern re high level wastes Urges and to nuclear power
* Affiliation Unknown 79/06/11 App

I Financial information

7906200326 Notification of 790623 meeting w/uttl in Bethesda, MD to discuss submission of nonproprietary financial info to complete review
LICITRA, E A Light Water Reactors Branch D 79/05/14 App

DOCKET ITEM-90-090 NEW HAVEN, UNIT 1

A Application/construction stage documents & correspondence

7906200442 Summary of 790424 meeting w/uttl, SEC & LAR, in Bethesda, MD re reactor safeguards requirements
GILBERT, J H Light Water Reactors Branch D 79/06/08 App

790403070 Notice that refs requested in 790404 ltr have been sent under separate cover to DL Menton at ARL
NAUGHTON, W F Commonwealth Edison Co 79/03/30 1p

790403023 Forward "Thermal Mapping of Steam Discharge" & "Cooling Water Intake & Steam Discharge Study" in response to NRC 790404 ltr
NAUGHTON, W F Commonwealth Edison Co 79/04/06 1p

--790403027 "Thermal Mapping of Steam Discharge" *
* Commonwealth Edison Co 79/03/31 10pp

--790403020 "Cooling Water Intake & Steam Discharge Study" *
* Commonwealth Edison Co 79/03/31 12pp

790403080 Ref: Note that Miles Quadrangle topographical map, referred to in 790301 ltr, is no longer available. Area in vicinity of proposed facility will be included in Green Island Quadrangle 7 5-minute map
NAUGHTON, W F Commonwealth Edison Co 79/04/06 1p

790403030 Submits add info re site suitability, in response to NRC 790404 request
NAUGHTON, W F Commonwealth Edison Co 79/04/10 2p

C Utility Environmental Report (ER), amendments & correspondence

790403032 Forward add info to site suitability/environ rept
Suggested area may contain archaeological sites
KENNEY, D Illinois, State of 79/04/06 2p

790403080 Discusses transmittal of info re site suitability/environ rept. Questions 3d & 3d 1-1, in response to NRC 790404 request
NAUGHTON, W F Commonwealth Edison Co 79/04/10 3p

790403050 Forward Dupl 1 to site suitability - environ rept, constituting amend to application for CP & early site review
RECS-C Commonwealth Edison Co 79/04/22 2p

--790403059 Dupl 1 to site suitability - environ rept, constituting amend to application for CP & early site review
* Commonwealth Edison Co 79/04/22 40pp

G Adjudicatory correspondence

790403041 Requests limited appearance at hearing re plant const
Affiliation Unknown 79/05/22 1p

--790403049 Requests limited appearance at first public hearing re proposed plant
NAUGHTON, W F Affiliation Unknown 79/05/22 1p

790403087 Answer by applicant to 790304 SR notice re hearing for early site review. Repts inclusion of seismology, environ & safety findings, heat dissipation sys & site alternatives. Notice of appearance & Certificate of Soc acct
GTC/MS-C Iowa, Lincoln & Dale 79/05/28 7p

790403040 Notices of limited appearance per 10CFR2 & 790301 hearing notice. Requests right to intervene if interests are adversely affected
HILLER, T J, GOSWAMIL, H. PETERSON, M C Iowa, State of 79/05/20 2pp

790403009 Petition to intervene re CP application. Repts to present evidence re safety issues, geology, hydrology, weather conditions, aesthetics & other considerations. Affidavit & Certificate of Soc acct
COO, J D in Davis County Ad Hoc Committee re Nuclear Energy Information 79/04/01 3pp

790403002 Petition to Intervene Catholic Worker of Dubuque-Dubuque Fellowship of Reconciliation-Division Coordinating Organization & Carroll County-Division Coordinating Organization. Affidavits & Certificate of Soc acct
GOSWAM, J D Iowa Public Interest Research Group 79/04/01 18pp

DOCKET 50-600 CANNON FACILITY II

A Application/Construction stage occurrence & correspondence

790407038 Notification of 790308 site visit for NRC & ARL to inspect prime & alternate sites
BALAB, R L Environmental Projects Branch 1 79/04/26 20pp

790404050 Summary of 790424 orientation meeting w/plant dedicated review team in Richards, ID
CIBOLD, A A Light Water Reactors Branch 2 79/04/27 4pp

790404028 Forward data sources under map per NRC 790404 request. Map will be included in response to Question 3d 1
NAUGHTON, W F Commonwealth Edison Co 79/05/22 2pp

790404024 Responds to request for comments on environ rept & site safety rept. Neither rept received
NAUGHTON, W F Illinois, State of 79/05/23 1p

790405003 Summary of 790509 meeting w/ARL in Bethesda, MD re implementation of Recommendation 3 of envt NRC study group rept. NUREG-0092, "Nuclear Power Plant Licensing Opportunities for Improvement"
DIBOLD, A A Light Water Reactors Branch 2 79/05/24 14pp

--790405004 "Nuclear Power Plant Licensing Opportunities for Improvement"
NAUGHTON, W F Office of Nuclear Reactor Regulation 77/04/28 1pp

790405074 Forward responses to 790404 questions & revised portions of text referenced in responses. Responses & revision of site suitability ER to be distributed by first week of June, 1979
WU, encl
NAUGHTON, W F Commonwealth Edison Co 79/05/25 1p

790405020 Notice that refs requested in 790404 ltr have been sent under separate cover to DL Menton at ARL
NAUGHTON, W F Commonwealth Edison Co 79/05/30 1p

790405023 Forward "Thermal Mapping of Steam Discharge" & "Cooling Water Intake & Steam Discharge Study" in response to NRC 790404 ltr
NAUGHTON, W F Commonwealth Edison Co 79/05/06 1p

--790405027 "Thermal Mapping of Steam Discharge" *
* Commonwealth Edison Co 79/05/31 10pp

--790405020 "Cooling Water Intake & Steam Discharge Study" *
* Commonwealth Edison Co 79/05/31 12pp

790405080 Notice that Miles Quadrangle topographical map, referred to in 790301 ltr, is no longer available. Area in vicinity of proposed facility will be included in Green Island Quadrangle 7 5-minute map
NAUGHTON, W F Commonwealth Edison Co 79/06/06 1p

790405030 Submits add info re site suitability, in response to NRC 790404 request
NAUGHTON, W F Commonwealth Edison Co 79/06/18 2p

C Utility Environmental Report (ER), amendments & correspondence

790405032 Forward add info to site suitability/environ rept
Suggested area may contain archaeological sites
KENNEY, D Illinois, State of 79/06/06 2p

790405080 Discusses transmittal of info re site suitability/environ rept. Questions 3d 1 & 3d 1-1, in response to NRC 790404 request
NAUGHTON, W F Commonwealth Edison Co 79/06/19 2pp

790405050 Forward Dupl 1 to site suitability - environ rept, constituting amend to application for CP & early site review
RECS-C Commonwealth Edison Co 79/06/22 2p

--790405059 Dupl 1 to site suitability - environ rept, constituting amend to application for CP & early site review
* Commonwealth Edison Co 79/06/22 40pp

G Adjudicatory correspondence

790405041 Requests limited appearance at hearing re plant const
Affiliation Unknown 79/05/22 1p

--790405049 Requests limited appearance at first public hearing re proposed plant
NAUGHTON, W F Affiliation Unknown 79/05/22 1p

DOCKETED ITEMS

7904210287 Answer by applicant to 790504 FR notice re hearing for early site review. seeks inclusion of seismology, environ & safety findings, heat dissipation and site alternatives. Notices of appearance & Certificate of Rec. encl.
BETTERD, P. Ithaca, Lincoln & Davis 79/05/24 7pp

7904210420 Petition of limited appearance; re 100FR & 790501 hearing notice. Requests right to intervene if interests are adversely affected.
HILLER, T. J., OGDENBAUGH, C. H., PETERSON, C. E. Iowa: State of 79/05/30 2pp

7904210509 Petition to intervene re CP application. Seeks to present evidence re safety issues: geology, hydrology, weather conditions, aesthetics & other considerations. Affidavit & Certificate of Rec. encl.
CDS, J. W. Jo Davies County Ad Hoc Committee on Nuclear Energy Information 79/06/01 5pp

7904210512 Petition to Intervene Catholic Worker of Dubuque, Dubuque Fellowship of Reconciliation, Christian Coordinating Organization & Carroll County Rivian Coalition join in petition. Affidavits & Certificate of Rec. encl.
SCHMIDT, J. C. Iowa Public Interest Research Group 79/06/01 10pp

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 79-0009 BATTLE COLUMBUS LABORATORIES

7904210170 Forwards supplemental info to "Financial Plan for Reestablishing of Battelle Columbus Labs Contaminated Facilities," Transmitted under 701322 answer ltr.
TOY, H. L. Battelle Memorial Institute, Columbus Laboratories 79/04/25 4pp

7904210230 Responds to 790123 ltr reporting changes to physical protection plan for West Jefferson Nuclear Science Area. Has changes are acceptable. Reel withheld (ref 100FR 7901).
HOGGINS, G. W. Physical Security Licensing Branch 79/04/23 1p

7904210235 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies." No written response necessary.
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/05/11 1p

7904210412 Forwards SE Circular 79-08, "Attempted Extortion - Lew Enriched U."
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/05/18 1p

DOCKET 79-0005 RICHMOND INTERNATIONAL CORP

7904210436 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies." No written response necessary.
ENVELOPE, R. H. Region 5, San Francisco, Office of the Director 79/05/10 1p

7904210520 Forwards IE Circular 79-08, "Attempted Extortion - Lew Enriched U."
ENVELOPE, R. H. Region 5, San Francisco, Office of the Director 79/05/18 1p

7904210508 Ack receipt of 790510 ltr requesting temporary exception to certain requirements of 100FR 701a(9)(1) to permit removal of air enrichment of U fuel plates Sections 2 & 9 of Amend 89F-1 to License SMP-1 are amended.
BARNETT, R. F. Division of Safeguards 79/05/18 3pp

DOCKET 79-0027 SANDOCK & WILSON CO

7904210523 Amends License SMP-23 Condition 11 re nonradioactive gas effluent in accordance w/780522 Submittal & 100FR 7004.
CROW, M. T. Fuel Process & Fab Branch 79/04/04 1p

7904210518 Forwards revised pages to measurement control plan in response to comments contained in 790508 ltr. Pages withheld (ref 100FR 7901).
BARNETT, R. F. Sandock & Wilson Co 79/04/20 2pp

7904210544 Notifies of requirement of amend Fee, based on evaluation of management expenditure required for review of application.
HILLER, M. D. License Fee Management Branch 79/04/27 1p

7904210425 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/05/10 1p

7904210520 Ack receipt of 790507 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 79-0027/79-03.
KEDMAN, B. Region 2, Atlanta, Safeguards Branch 79/05/11 1p

7904210525 Responds to NRC 790410 ltr re violation noted in IE Insp Rept 79-0027/79-03. Corrective actions withheld.
MELIS, J. P. Sandock & Wilson Co 79/05/07 1p

7904210529 Forwards IE Insp Rept 79-0027/79-03. Notice of violation withheld (ref 100FR 7901).
KEDMAN, B. Region 2, Atlanta, Office of the Director 79/04/10 2pp

7904210594 IE Insp Rept 79-0027/79-03 on 790234-20 Noncompliance noted. Lack of full access area physical barrier details withheld.
HOGGINS, G. W. Region 2, Atlanta, Safeguards Branch 79/04/10 1p

7904210612 Forwards IE Insp Rept 79-0027/79-09 on 790507-11. No noncompliance noted.
KEDMAN, B. Region 2, Atlanta, Safeguards Branch 79/05/22 1p

7904210614 IE Insp Rept 79-0027/79-09 on 790507-11. No noncompliance noted. Major areas inspected. Records & reports withheld.
HOGGINS, G. W., GILLESPIE, F. Region 2, Atlanta, Safeguards Branch 79/05/18 1p

DOCKET 79-0023 TEXAS INSTRUMENTS, INC

7904210126 Forwards updates to NRCN Project emergency plan, resulting from NRC review in Oct 1978.
HOPPER, C. M. Texas Instruments, Inc 79/04/03 12pp

7904210439 Forwards IE Insp Rept 79-0023/79-03 on 790303-08. No noncompliance noted.
SHILL, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/04/09 2pp

7904210443 IE Insp Rept 79-0023/79-03 on 790303-08. No noncompliance noted. Major areas inspected. License action on previous ltr findings, organization, operations, safety & procedure control.
HINER, H. M., CROCKER, H. W. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/04/09 12pp

7904210520 Provides summary of determination & application of limits of errors for inventory differences & shipments as result of IE Insp Rept 79-05.
HOPPER, C. M. Texas Instruments, Inc 79/04/20 4pp

7904210510 Amends License SMP-23 Condition 11 re emergency planning in accordance w/780522 Submittal & 100FR 7004.
CROW, M. T. Fuel Process & Fab Branch 79/04/23 1p

7904210514 Discusses review of 780522 emergency plan & 790303 & 0403. Provides Emergency plan made requirements of 100FR 7004 App E & provides basis for acceptable state of emergency preparations.
KEDMAN, B. Fuel Process & Fab Branch 79/04/23 2pp

7904210530 Submits list of replacement pages to "Plan for Protection of Nuclear Facilities & Nuclear Materials" Pages withheld (ref 100FR 7901).
BARNETT, R. F. Texas Instruments, Inc 79/05/02 4pp

7904210507 Requests that BA plan for shipping packages for radioactive salts be withdrawn from application. NRC project is not used as general license for shipment of DOT spec containers.
BARNETT, R. F. Texas Instruments, Inc 79/05/08 1p

7904210503 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies."
O'REILLY, J. P. Region 1, Philadelphia, Office of the Director 79/05/11 1p

7904210525 Ack receipt of 790507 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 79-0023/79-04.
MARTIN, H. O. Region 1, Philadelphia, Safeguards Branch 79/05/14 1p

7904210561 Responds to NRC 790426 ltr re violations noted in IE Insp Rept 79-0023/79-04. Corrective actions plan for protection of facilities & materials has been properly changed.
CROW, M. T., BARNETT, R. F. Texas Instruments, Inc 79/05/02 1p

--790420053 Forwards IE Insp Repts 70-0103/79-04 on 790303-09
MARTIN, M G Region 1, Philadelphia, Safeguards Branch
79/04/26 2pp

--790420056 IE Insp Repts 70-0103/79-04 on 790303-09 Information noted
noncompliance re physical barriers
JONES, E M, MCNEIL, L N, BEAL, R J H Region 1, Philadelphia,
Safeguards Branch 79/04/23 1p

790420067 Summary of 790517 meeting w/ TX Instruments, Inc in Silver
Spring, MD re format & content of license renewal application of
Arlington MA Facility
MELTZER, H Fuel Process & Fab Branch 79/05/17 13pp

790420063 Forwards IE Circular 79-08, "Attempted Extortion - Low
Enriched U"
GIER, S H Region 1, Philadelphia, Office of the Director
79/05/18 1p

DOCKET 70-003a COMBUSTION ENGINEERING, INC

7904170036 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
MPP, J L J D Region 3, Chicago, Office of the Director 79/05/11
1p

790420003 Responds to 790214 ltr Revised measurement control plan
revised & accepted Strengthening of self control &
automation program required Assessment of RUP 31a requested
within two months
MARTIN, M G Material Control Licensing Branch 79/05/16 3pp

--790420001 Amend RFP-3 to License SW-03, superseding all previous
safeguard amendments Addresses conditions re facility
partitioning & operation, measurement procedure & control,
inventory records & metrics & internal control
MARTIN, M G Material Control Licensing Branch 79/05/16
7pp

790420008 Requests add ref matl in order to enhance incident response
ctr Add matl needed include site emergency plan &
implementing procedures & four sets of site maps showing
neutron monitoring locations
MPP, J L J D Region 3, Chicago, Office of the Director 79/05/12
1p

7904090132 Forwards IE Circular 79-08, "Attempted Extortion - Low
Enriched U"
MPP, J L J D Region 3, Chicago, Office of the Director 79/05/18
1p

790420037 Requests info re prospect of flooding to further CIA
CROW, H T Fuel Process & Fab Branch 79/05/22 1p

DOCKET 79-0041 NORTH CAROLINA STATE UNIV

7904210391 Ack receipt of 790419 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 70-0103/79-01
06/29/79-01 & 70-0041/79-01
MORROW, W B Region 2, Atlanta, Safeguards Branch 79/05/03 1p

--790421034 Responds to NRC 790327 ltr re violations noted in IE Insp
Repts 90-111/79-01, 90-297/79-01 & 70-0041/79-01 Corrective
actions Para 760 prepared prospect & copy for period
Oct 1978 - Mar 1979 forwarded to Region 2
ELLISMAN, T S North Carolina State Univ 79/04/19 1p

7904140212 Forwards IE Insp Repts 70-0103/79-05 & 70-0041/79-05 on
790303-09 No noncompliance noted
MARTIN, M G Region 1, Philadelphia, Safeguards Branch 79/04/12
2pp

--790414028 IE Insp Repts 70-0103/79-05 & 70-0041/79-05 on 790303-09
No noncompliance noted Major areas inspected physical
security, health & safety & environ program
BIBERT, P Region 1, Philadelphia, Office of the Director
JONES, J H Region 1, Philadelphia, Safeguards Branch
79/03/22 6pp

790420013 Ack receipt of 790302 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 70-0103/79-07
GIER, S H Region 1, Philadelphia, Office of the Director
79/05/10 1p

--790413043 Responds to violations noted in IE Insp Repts 70-0103/79-07
Corrective actions ship hull re radiation contamination
work permits conducted Ops mch
MARTIN, M A Babcock & Wilcox Co 79/05/01 2pp

--790413049 Forwards IE Insp Repts 70-0103/79-07 on 790213-1a re notice of
violations
GIER, S H Region 1, Philadelphia, Office of the Director
79/04/12 2pp

--790413052 Notice of violation from Insp on 790313-1a
GIER, S H Region 1, Philadelphia, Office of the Director 79/04/12
1p

--790413050 IE Insp Repts 70-0103/79-07 on 790213-1a Noncompliance noted
air sample not representative of breathing zone & failure
to account for RSH
GIER, S H, CROOKER, H H Region 1, Philadelphia, Office of the
Director 79/04/12 10pp

790420003 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
GIER, S H Region 1, Philadelphia, Office of the Director
79/05/11 1p

7904090034 Forwards IE Circular 79-08, "Attempted Extortion - Low
Enriched U"
GIER, S H Region 1, Philadelphia, Office of the Director
79/05/10 1p

7904200177 Requests payment of administrative fee for amend to License
SW-118 & SW-012 to delay physical inventory
WELLS, S License Fee Management Branch 79/05/22 1p

DOCKET 79-0143 NUCLEAR FUEL SERVICES, INC

7904200209 Responses Revision 7 to 790415 mail control plan Revision
withhold (ref 100792, 7001)
WELLS, R D Nuclear Fuel Services, Inc (subs of Getty Oil Co)
79/04/20 1p

7904200203 Notifies that License SW-126 is amended to require NRC
approval prior to introduction of RSH into process via
CONVENSAN, B E Division of Fuel Cycle & Materials Safety
79/04/22 1p

7904200182 Requests 20-day extension to comment on draft documents
forwarded by R Bennett 790306 ltr Delay due to labor
problems
MICHEL, J J Nuclear Fuel Services, Inc (subs of Getty Oil Co)
79/04/22 1p

7904200172 Ack receipt of 790420 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 70-0103/79-04
BUTTERLAND, J T Region 2, Atlanta, Fuel Facility & Materials
Safety Branch 79/04/26 1p

--7904200179 Responds to NRC 790326 ltr re violations noted in IE Insp
Repts 70-0041/79-08 Corrective actions chemical bldg
employees have signed off on revised procedure
MORROW, W B Nuclear Fuel Services, Inc (subs of Getty Oil Co)
79/04/20 2pp

--7904200177 Forwards IE Insp Repts 70-0103/79-04 on 790123-0a &
notice of violation
BUTTERLAND, J T Region 2, Atlanta, Fuel Facility & Materials
Safety Branch 79/03/30 2pp

--7904200180 Notice of violation from Insp on 790123-0a
GIER, S H Region 2, Atlanta, Office of the Director 79/03/30 1p

DOCKETED ITEMS

23

--7906040184 IE Insp Rept 70-0142/79-04 on 790123-26 Noncompliance noted Failure of operators to sign chemical bldg SOP log
CORRELL, G P. Region 2, Atlanta, Office of the Director 79/05/30 2pp

7906040473 Forwards Revision 15 change pages to physical security plan
Revision of chemical (ref 10CFR2 7901)
RECHER, G J. Nuclear Fuel Services, Inc (subs of Getty Oil Co) 79/04/26 2pp

7906050442 Forwards IE Insp Rept 70-0143/79-16 on 790410-16 No noncompliance noted
Region 2, Atlanta, Safeguards Branch 79/04/27 1p

--790605047 IE Insp Rept 70-0143/79-16 on 790410-16 No noncompliance noted Major areas inspected nuclear fuel safeguards program & plans for coping with strikes Details withheld
(ref 10CFR2 7901)
HOSCH, D E. L&L T. Region 2, Atlanta, Safeguards Branch 79/04/27 1p

7906050441 Amends License BSM-124 by accepting Revision 15 to physical protection plan, forwarded in license 790426 ltr Plan withheld (ref 10CFR2 7901)
HOSCH, D E. Physical Security Licensing Branch 79/04/30 1p

7906050509 Requests amend to License BSM-124 Amend withheld (ref 10CFR2 7901)
HEMLEY, A D. Nuclear Fuel Services, Inc (subs of Getty Oil Co) 79/04/30 2pp

7906050527 Accepts site security training plan submitted on 790516 Amends License BSM-124
HOSCH, D E. Physical Security Licensing Branch 79/05/03 2pp

7906060646 Responds to 790425 ltr requesting 30-day extension of 790318 due date for submittal of revised Section 7.10
Fundamental nuclear mat control plan Extension granted
PARTLOW, J C. Material Control Licensing Branch 79/05/04 1p

7906060628 Summary of 790509 meeting w/MPE in Silver Spring, MD re 790423 order & procedures to be followed before operations can resume
SALAMET, C J. Fuel Process & Fab Branch 79/05/09 2pp

7906060400 Forwards IE Info Notice 79-12: "Attempted Damage to New Fuel Assembly"
O'NEILL, J P. Region 2, Atlanta, Office of the Director 79/05/10 1p

7906060449 Ack receipt of 790301 ltr re suspension of stock fluoride monitoring program Request requires payment of \$150
Administrative amend fee
WEISS, D. License Fee Management Branch 79/05/11 1p

7906070623 Notify that time for licensee to request hearing re introduction of add'l BSM into process sgt is extended to 790623
CRON, W T. Fuel Process & Fab Branch 79/05/17 1p

7906070745 Notify that License BSM-124 is amended Amend constitutes written approval to introduce BSM into process sgt &/or emergency operations using mgt personnel
CRON, W T. Fuel Process & Fab Branch 79/05/18 1p

7906070788 Notify that Request to delay scheduled annual audit of inventory tabs is justifiable Audit shall be conducted on or before 790731
PARTLOW, J C. Material Control Licensing Branch 79/05/22 1p

7906070741 Adds license conditions to amend MPP-1 of License BSM-124 Amend makes it unacceptable to keep shipping values for low enriched plant II 790515 physical inventory
PARTLOW, J C. Material Control Licensing Branch 79/05/23 1p

7906070759 Responds to 790420 submission of revised Fundamental nuclear mat control plan Revisions are acceptable Revises License Condition 2.1 of Amend MPP-1 to License BSM-124
PARTLOW, J C. Material Control Licensing Branch 79/05/24 2pp

7906070804 Responds to 791227 ltr. Had scheduled to be completed 60 ds after Oil/Chemical & Atomic Workers Intl Union returns to work
HOSCH, D E. Nuclear Fuel Services, Inc (subs of Getty Oil Co) 79/05/30, 1p

DOCKET 79-0122 PURDUE UNIV

7906080123 Ack receipt of 790419 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept
HOSCH, D E. Region 3, Chicago, Safeguards Branch 79/05/08 1p

--7906080130 Responds to NRC 790324 ltr re violations noted in IE Insp Rept
Corrective actions withheld (ref 10CFR2 7901)
SLEIGHMAN, F H. Purdue Univ 79/04/19 2pp

7906090040 Forwards IE Info Notice 79-13: "Attempted Damage to New Fuel Assembly"
REFLEER, J Q. Region 3, Chicago, Office of the Director 79/05/11 1p

7906090170 Forwards IE Circular 79-26: "Attempted Extension - Low Enriched U"
REFLEER, J Q. Region 3, Chicago, Office of the Director 79/05/10 1p

DOCKET 79-0344 PHASE TWO/SHUP SITE, SARCOS & MILCOS CO

7906090166 Forwards revised Chapter 3 of License BSM-014, Section 11 "Facilities Descriptions" Includes changes to continuous air monitoring & plant ventilation sgt
AUSTIN, R A. Sarcos & Milcor Co 79/04/30 13pp

7906090137 Notification that inventory processing operation will not be completed until 790520 due to metal certification problems
AUSTIN, R A. Sarcos & Milcor Co 79/05/13 1p

7906090217 Requests delay until 790515 for implementing requirements of License Condition 4.7 to License BSM-145 & BSM-414
AUSTIN, R A. Sarcos & Milcor Co, Nuclear Material Div 79/05/14 1p

7906090199 Forwards IE Insp Rept 70-0344/79-07 on 790527-0301 No noncompliance noted
PARTLOW, J C. Region 1, Philadelphia, Safeguards Branch 79/05/26 2pp

--7906090305 IE Insp Rept 70-0344/79-07 on 790527-0301 No noncompliance noted Major areas inspected nuclear mat control & accounting in area of independent measurements of facility holdings
OISEY, A. BGS&TY, P. Region 1, Philadelphia, Office of the Director 79/05/26 2pp

7906090305 IE Insp Rept 70-0344/79-07 on 790527-0301 No noncompliance noted Major areas inspected nuclear mat control & accounting in area of independent measurements of facility holdings
OISEY, A. BGS&TY, P. Region 1, Philadelphia, Office of the Director 79/05/26 2pp

7906090305 IE Insp Rept 70-0344/79-07 on 790527-0301 No noncompliance noted Major areas inspected nuclear mat control & accounting in area of independent measurements of facility holdings
OISEY, A. BGS&TY, P. Region 1, Philadelphia, Office of the Director 79/05/26 2pp

7906090305 IE Insp Rept 70-0344/79-07 on 790527-0301 No noncompliance noted Major areas inspected nuclear mat control & accounting in area of independent measurements of facility holdings
OISEY, A. BGS&TY, P. Region 1, Philadelphia, Office of the Director 79/05/26 2pp

7906090305 IE Insp Rept 70-0344/79-07 on 790527-0301 No noncompliance noted Major areas inspected nuclear mat control & accounting in area of independent measurements of facility holdings
OISEY, A. BGS&TY, P. Region 1, Philadelphia, Office of the Director 79/05/26 2pp

7906090305 IE Insp Rept 70-0344/79-07 on 790527-0301 No noncompliance noted Major areas inspected nuclear mat control & accounting in area of independent measurements of facility holdings
OISEY, A. BGS&TY, P. Region 1, Philadelphia, Office of the Director 79/05/26 2pp

7906090305 IE Insp Rept 70-0344/79-07 on 790527-0301 No noncompliance noted Major areas inspected nuclear mat control & accounting in area of independent measurements of facility holdings
OISEY, A. BGS&TY, P. Region 1, Philadelphia, Office of the Director 79/05/26 2pp

7906090305 IE Insp Rept 70-0344/79-07 on 790527-0301 No noncompliance noted Major areas inspected nuclear mat control & accounting in area of independent measurements of facility holdings
OISEY, A. BGS&TY, P. Region 1, Philadelphia, Office of the Director 79/05/26 2pp

7906090305 IE Insp Rept 70-0344/79-07 on 790527-0301 No noncompliance noted Major areas inspected nuclear mat control & accounting in area of independent measurements of facility holdings
OISEY, A. BGS&TY, P. Region 1, Philadelphia, Office of the Director 79/05/26 2pp

7906090305 IE Insp Rept 70-0344/79-07 on 790527-0301 No noncompliance noted Major areas inspected nuclear mat control & accounting in area of independent measurements of facility holdings
OISEY, A. BGS&TY, P. Region 1, Philadelphia, Office of the Director 79/05/26 2pp

7906090305 IE Insp Rept 70-0344/79-07 on 790527-0301 No noncompliance noted Major areas inspected nuclear mat control & accounting in area of independent measurements of facility holdings
OISEY, A. BGS&TY, P. Region 1, Philadelphia, Office of the Director 79/05/26 2pp

7906090305 IE Insp Rept 70-0344/79-07 on 790527-0301 No noncompliance noted Major areas inspected nuclear mat control & accounting in area of independent measurements of facility holdings
OISEY, A. BGS&TY, P. Region 1, Philadelphia, Office of the Director 79/05/26 2pp

7906090305 IE Insp Rept 70-0344/79-07 on 790527-0301 No noncompliance noted Major areas inspected nuclear mat control & accounting in area of independent measurements of facility holdings
OISEY, A. BGS&TY, P. Region 1, Philadelphia, Office of the Director 79/05/26 2pp

7906090305 IE Insp Rept 70-0344/79-07 on 790527-0301 No noncompliance noted Major areas inspected nuclear mat control & accounting in area of independent measurements of facility holdings
OISEY, A. BGS&TY, P. Region 1, Philadelphia, Office of the Director 79/05/26 2pp

7906090305 IE Insp Rept 70-0344/79-07 on 790527-0301 No noncompliance noted Major areas inspected nuclear mat control & accounting in area of independent measurements of facility holdings
OISEY, A. BGS&TY, P. Region 1, Philadelphia, Office of the Director 79/05/26 2pp

DOCKETED ITEMS

- 790620076 Discusses safety evaluation for BW 790301 license amendment application requesting extension limit for enriched U for Penn Township, PA. Fuel Storage Unit
SUNNYSIDE, W Fuel Reprocess & Recycle Branch 79/05/00 3p
- 790621008 Act receipt of 790620 for informing NRC of info taken to correct violations noted in 79 Inspect 79-036/79-05
CRITERIA Region 1, Philadelphia: Office of the Director 79/05/10 1p
- 790621028 Responds to NRC 790404 for re violations noted in 79 Inspect 79-036/79-05. Corrective actions now being implemented. Specificity addressing OSHA Site Ins prepared & currently being waited for review & approval
AUSTIN, M A Belmont & Mohr Co., Nuclear Material Div 79/04/25 3p
- 790621028 Forwards 79 Inspect 79-036/79-05 on 790620-032 & notice of violation
SUNNYSIDE, W Region 1, Philadelphia: Fuel Facility & Materials Safety Branch 79/04/05 2p
- 790621028 Notice of violation from INS on 790620-032
SUNNYSIDE, W Region 1, Philadelphia: Fuel Facility & Materials Safety Branch 79/04/05 2p
- 790621028 79 Inspect 79-036/79-05 on 790620-032 Noncompliance noted. Failure to have posted nuclear safety sign
not on Pak 4 area signed by authorized individual
NORTH, J Region 1, Philadelphia: Office of the Director 79/04/05 1p
- 790621042 Act receipt of 790621 for re physical inventories. Request payment of \$100 administrative award for
LICENSURE Fee Management Branch 79/05/11 1p
- 790620034 Forwards 79 Info Notice 79-10, "Attempted Damage to New Fuel Assembly"
CRITERIA Region 1, Philadelphia: Office of the Director 79/05/11 1p
- 790620039 Forwards 79 Circular 79-08, "Attempted Extortion - Low Enriched U"
CRITERIA Region 1, Philadelphia: Office of the Director 79/05/11 1p
- 790620047 Requests payment of administrative fee for amendment to License 89F-145 & 89F-434 to delay physical inventory
NRC-5 License Fee Management Branch 79/05/02 3p
- DOCKET 79-0675 UNITED NUCLEAR CORP
- 790621016 Forwards 79 Inspect 79-037/79-05 on 790620-032 No noncompliance noted
PARTLOW, S Region 1, Philadelphia: Safeguards Branch 79/03/28 1p
- 790621014 79 Inspect 79-037/79-05 on 790620-032 No noncompliance noted. Major areas inspected
related major areas inspected nuclear fuel control & accounting & shipper-receiver differences. Details attached (see 790622 7901)
GOMAN, J KATZ, A B Region 1, Philadelphia: Office of the Director 79/03/26 1p
- 790620075 Forwards 0A program
KATZ, A B United Nuclear Corp 79/05/03 1p
- 790620077 0A program for facility
79/03 3p
- Sen from requestor
notified
on 79/05/04 1p
- 790621028 Responds to 790401 for notice request to use hot type seal on burial drums
PARTLOW, S Material Control Licensing Branch 79/03/07 1p
- 790620038 Forwards 79 Info Notice 79-10, "Attempted Damage to New Fuel Assembly"
on 1, Philadelphia: Office of the Director
- 790620038 Act receipt of 79 Inspect 79-037/79-05 on 790620-032
SUNNYSIDE, W United Nuclear Corp 79/03/19 3p
- 790620038 Responds to NRC 790404 for re violations noted in 79 Inspect 79-037/79-05. Corrective actions now being implemented. Specificity addressing OSHA Site Ins prepared & currently being waited for review & approval
AUSTIN, M A Belmont & Mohr Co., Nuclear Material Div 79/04/25 3p
- 790620038 Clarifies elements of 790621. Request re posting of controlled areas
SUNNYSIDE, W United Nuclear Corp 79/04/12 3p
- 790620040 Forwards 79 Inspect 79-037/79-05 on 790620-032 & notice of violation
SUNNYSIDE, W Region 1, Philadelphia: Fuel Facility & Materials Safety Branch 79/03/14 2p
- 790620042 Notice of violation from Inspect on 790620-032
on 1, Philadelphia: Fuel Facility & Materials Safety Branch 79/03/14 2p
- 790620047 79 Inspect 79-037/79-05 on 790620-032 Noncompliance noted. Failure to identify & enforce proper protective clothing for areas into potentially contaminated area
NORTH, J KATZ, A B GOMAN, J K Region 1, Philadelphia: Fuel Facility & Materials Safety Branch 79/03/12 10p
- 790620050 Forwards 79 Circular 79-08, "Attempted Extortion - Low Enriched U"
CRITERIA Region 1, Philadelphia: Office of the Director 79/05/11 1p
- 790620057 Directors proposed agenda for 790605 meeting to discuss shipment & receipt & reg control & accountability of SRM
PARTLOW, S Material Control Licensing Branch 79/04/01 1p
- 800621 79-0610 U S COAST GUARD ACADEMY
- 790621028 Discusses 79 Inspect of License 89-036/01 & 89F-434 on 790621 No noncompliance noted. Major areas inspected
procedures & representative records & measurements re radiation safety
NORTH, J KATZ, A B GOMAN, J K Region 1, Philadelphia: Office of the Director 79/03/08 1p
- 800621 79-0617 CENTRAL MISSISSAUGA LARV
- 790621060 79 Inspect Findings & License 89-036/01 & 89F-434 on 790621 No noncompliance noted. Major areas inspected
21-0142-02 & 89F-434 Inspect Findings 29 (a) (a) Part 1
on 2, License 89-036 & procedures not posted in designated location
DAVLEE, R Region 3, Chicago: Office of the Director 79/01/13 1p
- 800621 79-0617 UNION CARBIDE CORP
- 790620073 Recommends approval of Union Carbide Corp 790117 request to amend license by altering administrative procedures & redefining SRM limits
SUNNYSIDE, W CORNELL, W T Radiological Licensing Branch (P) 79/03/11 79/02/26 3p
- 790620078 Discusses 790620-032 & 1013 requests to amend license to increase waste limit by not call Amend should be granted
SUNNYSIDE, W CORNELL, W T Radiological Licensing Branch (P) 79/03/11 79/03/26 3p
- 800621 79-0618 UNITE HILL DITE, WINTERHOUR ELECTRIC CORP
- 790621028 Amends Item 89 of License 89F-770 to revise personnel limits
CORNELL, W T Fuel Process & Fab Branch 79/03/29 3p
- 790620034 Forwards 7907 decommissioning program for retired Westinghouse Training Reactor Facilities
SUNNYSIDE, W WINTERHOUR ELECTRIC CORP 79/04/27 3p
- 800621 79-0709 ES & S, INC
- 790620004 Act receipt of 790620 for requesting that License 89F-434 not be renewed. License terminated
CORNELL, W T Fuel Process & Fab Branch 79/08/07 1p

DOCKETED ITEMS

235

DOCKET 70-0734 GENERAL ATOMIC CO

7906270546 Forwards IE Insp Rept 70-0734/79-03 on 790605-04 to noncompliance noted
Region 5, San Francisco. Fuel Facility & Materials
Safety Branch 79/04/27 2pp

7906270546 IE Insp Rept 70-0734/79-03 on 790605-04 Noncompliance noted Major areas inspected and 5 changes to facilities & equipment review & audit-safety committee activities & required safety
COSTLEY, M. J. BIEDLINER, S. A. BOCK, H. N. Region 5, San Francisco. Fuel Facility & Materials Safety Branch 79/04/27 2pp

7906270546 Forwards to "Security Guard Training & Qualification Plan" submitted in 790620 ltr Plan withheld
Inef 10CFR2.3901
HOSKINS, E. W. Physical Security Licensing Branch 79/04/26 2pp

7906270546 Responds to 790520 ltr re revision to measurement procedures for ventilation systems & changes involving use of alternate measurement type changes are acceptable & license is revised to reflect changes
PARTLOW, J. G. Material Control Licensing Branch 79/05/02 2pp

7906270546 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
ENGELHORN, E. H. Region 5, San Francisco. Office of the Director 79/05/10 1p

7906270520 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
ENGELHORN, E. H. Region 5, San Francisco. Office of the Director 79/05/10 1p

7906270520 Forwards IE Insp Rept 70-0734/79-03 on 790507-10 No noncompliance noted Major areas inspected activities related to physical protection against industrial sabotage & against theft of RRM
HOSKINS, E. W. Region 5, San Francisco. Safeguards Branch 79/05/24 2pp

7906270794 Forwards revision of Sections 1-8 of Amend HP-1 to License 080-066
PARTLOW, J. G. Material Control Licensing Branch 79/05/24 4pp

DOCKET 70-0704 WALLCREEK NUCLEAR CENTER, GENERAL ELECTRIC CO

7906010209 Forwards "Annual Financial Rept 1978"
CUNNINGHAM, C. E. General Electric Co. Nuclear Energy Products Div 79/05/30 1p

7906010209 "Annual Financial Rept 1978"
JONES, R. H. General Electric Co 79/12/31 46pp

7906010542 Forwards Board notification item re C Johnson epidemiological study of cancer incidence near Rocky Flats plant
CHANCELLER, L. J. Branch 1 79/04/27 24pp

7906190020 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
ENGELHORN, E. H. Region 5, San Francisco. Office of the Director 79/05/10 1p

7906090232 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U"
ENGELHORN, E. H. Region 5, San Francisco. Office of the Director 79/05/10 1p

7906290546 Forwards IE Insp Rept 70-0734/79-03 on 790428-07 notice of violation & notice of violation Rept & notices withheld (Inf 10CFR2.3901)
HOSKINS, E. W. Region 5, San Francisco. Safeguards Branch 79/05/31 2pp

DOCKET 70-0820 UNITED NUCLEAR CORP

7906200145 Forwards OE Reur 790319 ltr containing organization chart for fuel recovery operation w/790601 implementation date Due to delay in expansion program implementation date delayed Updated chart encl
BOSCH, C. E. United Nuclear Corp 79/05/13 2pp

7906200145 Forwards modified organization chart for fuel recovery operation w/790601 implementation date
BOSCH, C. E. United Nuclear Corp 79/05/13 2pp

7906200159 Forwards updated Section 330 of License SM-777 requested by RL Stevenson during 790227 telcon
BOSCH, C. E. United Nuclear Corp 79/02/22 18pp

7906290546 Summary of 790221 meeting w/United Nuclear Corp in Silver Spring, MD re proposed 790203 emergency plan
BOSCH, C. E. Fuel Process & Fab Branch 79/04/06 2pp

7906290558 Forwards IE Insp Rept 70-0820/79-09 on 790122-26 No noncompliance noted
PARTIN, H. O. Region 1, Philadelphia. Safeguards Branch 79/04/19 2pp

7906290558 IE Insp Rept 70-0820/79-09 on 790122-26 No noncompliance noted Major areas inspected implementation of security plan
PARTIN, H. O. Region 1, Philadelphia. Safeguards Branch 79/04/19 2pp

7906290558 IE Insp Rept 70-0820/79-09 on 790122-26 No noncompliance noted Major areas inspected implementation of security plan
PARTIN, H. O. Region 1, Philadelphia. Safeguards Branch 79/04/19 2pp

7906290558 Act receipt of 790626 ltr w/revision pages & drawings for safety demonstration discarding lagged recovery process
Technical changes to not affect safety or security controls
Aspirant conflict w/notice of License Condition 20
CORN, M. T. Fuel Process & Fab Branch 79/04/19 1p

7906290820 Requests 10-day extension for reporting physical inventory
BREG, R. J. United Nuclear Corp 79/04/24 1p

7906290103 Responds to 791517 & 780928 ltrs Accepts revisions re informational nuclear mail central plan Review License
Condition 2 I
PARTLOW, J. G. Material Control Licensing Branch 79/04/30 2pp

7906140875 Act receipt of 790606 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0820/79-04
BOSCH, C. E. Region 1, Philadelphia. Fuel Facility & Materials Safety Branch 79/08/03 1p

7906140875 Responds to NRC 790319 ltr re violation noted in IE Insp Rept 70-0820/79-04 Corrective actions alarm immediately meet to proper subpoint when critical conditions discovered
BOSCH, C. E. United Nuclear Corp 79/04/06 2pp

7906140392 Forwards IE Insp Rept 70-0820/79-04 on 790212-13 & notice of violation
BOSCH, C. E. Region 1, Philadelphia. Fuel Facility & Materials Safety Branch 79/03/19 2pp

7906140392 Notice of violation from Insp on 790212-13
Region 1, Philadelphia. Fuel Facility & Materials Safety Branch 79/03/19 1p

7906140608 IE Insp Rept 70-0820/79-04 on 790212-15 Noncompliance noted License failed to have alarm setpoints for three critically monitors set between 3 & 20 millirem/minute
BOSCH, C. E. Region 1, Philadelphia. Fuel Facility & Materials Safety Branch 79/03/19 12pp

7906190020 Act receipt of 790406 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0820/79-04 & 79-0820
BOSCH, C. E. Region 1, Philadelphia. Fuel Facility & Materials Safety Branch 79/03/19 12pp

DOCKETED ITEMS

790520028 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies" Region 1, Philadelphia, Office of the Director
GRIER, B H
79/05/11 1p

790520028 Forwards IE Circular 79-08. "Attempted Sabotage - Low Enriched U" Region 1, Philadelphia, Office of the Director
GRIER, B H
79/05/10 1p

790529207 Discusses proposed options for 790526 meeting to discuss shipment & receipt & fuel control & accountability of SRM
Material Control Licensing Branch 79/05/01 1p
PARTLOW, J G

DOCKET 70-0324 BACCHIO & WILCOX CO

790520437 Amends License BBN-770-Condition 18 per 790420 application & 10CFR70 to read & mCi (131) not to exceed 250 mCi in any the solvent used
Fuel Process & Fab Branch 79/04/20 1p
CROW, M F

790520033 Responds to ARC 790420 Itr Forwards replacement pages for violations in safeguards centrifuge plant pages withheld
Inf 10CFR2 7901
CLEVER, A F Babcock & Wilcox Co 79/05/02 2pp

790520044 Requests investigation as same of model CHS-1-12C
BACCHIO, A F Babcock & Wilcox Co 79/05/04 1p

790520036 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies" Region 2, Atlanta, Office of the Director
GRIER, B H
79/05/10 1p

790519054 Act receipt of 790416 Itr informing BSC of steps taken to search violations noted in IE Insp Rep 70-024/79-03
Region 2, Atlanta, Safeguards Branch 79/05/14 1p
KELSO, W B

790519054 Responds to ARC 790320 Itr re violations noted in IE Insp Rep 70-024/79-03 Corrective action withheld
Inf 10CFR2 7901
CLEVER, A F Babcock & Wilcox Co 79/04/16 1p

790519057 Forwards IE Insp Rep 79-024/79-03 Notice of violation withheld (Inf 10CFR2 7901)
KELSO, W B Region 2, Atlanta, Office of the Director 79/04/20 2pp

790519254 IE Insp Rep 70-024/79-03 an 790320-15 Measurement noted review of measurement program not conducted by designated person & failure to properly document testing program
Order withheld (Inf 10CFR2 7901)
GRIER, B H Region 2, Atlanta, Office of the Director 79/05/10 1p
GRIER, B H Region 2, Atlanta, Safeguards Branch 79/05/20 1p

790505088 Forwards Integrity Agreement 8-3 in response to 790516 Itr
CLEVER, A F Babcock & Wilcox Co 79/05/23 10pp

DOCKET 70-0885 ARMAH&B, GENIV CO

790500010 Responds to 790420 Itr re use of resident inspection at nuclear plant sites Forwards map describing revised map program which should be implemented in 1979
BACCHIO, J G Office of Inspection & Enforcement 79/04/20 1p

790500010 Reports concept of placing resident inspectors at commercial nuclear power plants Offers use of inspectors at Black Sea Station of AN Power & Light plant in Kazakhstan, AR
GRIER, B H Arkansas, Univ of 79/04/25 2pp

DOCKET 70-2425 CINCINNATI FACILITY, KNS-KOBER CORP

790519028 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies" Region 3, Chicago, Office of the Director 79/05/11 1p
KEFFLER, J G

790500012 Forwards IE Circular 79-08. "Attempted Sabotage - Low Enriched U" Region 3, Chicago, Office of the Director 79/05/10 1p
KEFFLER, J G

DOCKET 70-0877 NUCLEAR FUEL SERVICES, INC. 1970S OF GENIV COIL CO

790520040 Forwards IE Info Notice 79-12. "Attempted Damage to Fuel Assemblies" No written response necessary
Region 1, Philadelphia, Office of the Director 79/05/11 1p
GRIER, B H

DOCKET 70-0887 PACIFIC NORTHWEST LAB

790520038 Forwards IE Info Notice 79-12. "Attempted Damage to Fuel Assemblies" No written response necessary
Region 3, San Francisco, Office of the Director 79/05/10 1p
BACCHIO, J G

790520034 Forwards IE Circular 79-08. "Attempted Sabotage - Low Enriched U" Region 3, San Francisco, Office of the Director 79/05/10 1p
BACCHIO, J G

DOCKET 70-1007 GENERAL ELECTRIC CO

790519028 Forwards IE Info Notice 79-12. "Attempted Damage to Fuel Assemblies" Region 3, San Francisco, Office of the Director 79/05/10 1p
BACCHIO, J G

790500022 Forwards IE Circular 79-08. "Attempted Sabotage - Low Enriched U" Region 3, San Francisco, Office of the Director 79/05/10 1p
BACCHIO, J G

DOCKET 70-1100 COMBUSTION ENGINEERING, INC

790520027 Amends License BBN-1047 to include decommissioning & financial plans in accordance w/790112 submittal & 10CFR70
Fuel Process & Fab Branch 79/04/23 1p
CROW, M F

790520027 Discusses review of 790112 license amend application & 790503 simpl plan for future decommissioning & financial arrangements provide satisfactory assurance of health & safety
KELSO, W B Fuel Process & Fab Branch 79/04/23 2pp

790520028 Requests amend of License BBN-1047 to allow increase of enrichment of enrich U from 3.95 U-235 to 4.14 U-235
Forwards necessary critical safety analysis of each step in fuel fabrication process
LIGHTHOUSE, H Combustion Engineering, Inc 79/04/23 40pp

790520048 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies" Region 1, Philadelphia, Office of the Director 79/05/11 1p
GRIER, B H

790520001 Responds to 790218 Itr Revised measurement control plan reviewed & accepted Strengthening of fuel control & accounting program required Assessment of fuel line requested within two months
PARTLOW, J G Material Control Licensing Branch 79/05/16 50p

790520002 Amends NPP-1 to License BBN-1047, superseding previous safeguard amendments addresses conditions on facility organization & operation, measurement procedure & control, inventory records & parts of internal controls
PARTLOW, J G Material Control Licensing Branch 79/05/16 1pp

790520044 Forwards IE Circular 79-08. "Attempted Sabotage - Low Enriched U" Region 1, Philadelphia, Office of the Director 79/05/10 1p
GRIER, B H

DOCKET 70-1113 GENERAL ELECTRIC CO

790520030 Discusses latest revisions to Chapter 4 & App C of Fundamentals nuclear fuel control plan Revisions withheld
Inf 10CFR2 7901
BACCHIO, J G General Electric Co, Nuclear Energy Products Div 79/04/17 1p

790520038 Discusses latest revisions to Chapter 4 of Fundamentals nuclear fuel control plan for fuel fabrication plant Revisions withheld (Inf 10CFR2 7901)
BACCHIO, J G General Electric Co, Nuclear Energy Products Div 79/05/02 1p

DOCKETED ITEMS

2

7906040075 Requests that soil melt control plan accounting program be improved in order to ensure compliance w/10CFR20 57 Revised measurement control plan reviewed & accepted Plan withheld (ref 10CFR20 7901)
PARTLOW J D Material Control Licensing Branch 79/05/04 3pp

7906050388 Forwards add info to Ref 2 to application Amend B-B re physical inventory of U oxide pellets & BHT containers Info & med withheld (ref 10CFR20 7901)
NAPLAN A L General Electric Co. Nuclear Energy Products Div 79/03/04 3pp

7906050430 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
O'REILLY J P Region 2, Atlanta, Office of the Director 79/05/10 1p

7906050630 Submits corrected version of page 3 of safety evaluation for OF 790630 emergency plan
STEVENSON R L Fuel Processes & Recycle Branch 79/05/14 3pp

DOCKET 79-1143 WESTINGHOUSE ELECTRIC CORP

7906050044 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
ORRER H H Region 1, Philadelphia, Office of the Director 79/05/11 1p

7906080035 Forwards IE Circular 79-06, "Attempted Extortion - Low Enriched U"
SEIBER H H Region 1, Philadelphia, Office of the Director 79/05/08 1p

DOCKET 79-1156 WESTINGHOUSE ELECTRIC CORP

7906050237 Responds to 790507 request to expand U recovery age facility from scrap-by means of solvent extraction Control plan must be reviewed & approved prior to startup
PARTLOW J D Material Control Licensing Branch 79/05/04 1p

7906050300 Submits latest revision of 790604 measurement control plan for approval Review withheld (ref 10CFR20 7901)
VIGOR C E General Electric Co. Nuclear Energy Products Div 79/05/06 1p

7906050167 Forwards revised application for Withholding Privileges Info from Public Disclosure, "to be inserted with request for amend to license BHM-1107 Also forwards revised page 1949 of 790403 ltr Revisions withheld (ref 10CFR20 7901)
SIMPSON R P Westinghouse Electric Corp 79/04/28 1p

7906040115 Revises Amend 88-4 to License BHM-1107 to require that licensee will adhere to fundamental nuclear melt control plan Request for addl time to implement program may not be granted until proper justification License condition smci
PARTLOW J D Material Control Licensing Branch 79/04/20 4pp

7906040044 Responds to 790509 telar & 790424 ltr re LEIS model & requested time extension to use new model New License Condition D 9 to Amend 88-4 allows licensee to calculate LEIS within 60 days using revised model
PARTLOW J D Material Control Licensing Branch 79/05/04 1p

7906020070 Approves revision to License Condition 2 I & addition of new Condition 2 E to Amend 88-4 to License BHM-1107 Requests request for 60-day extension to implement Condition 4 & 8
PARTLOW J D Material Control Licensing Branch 79/05/17 2pp

7906070030 Requests supporting info in order to conduct review of 790400 application for amend to License BHM-1107 authorizing operations w/BNR in plant expansion
WITENBERG R L Fuel Processes & Recycle Branch 79/05/22 3pp

DOCKET 79-1193 CHARRON FACILITY, WERN-HOUSE CORP

7906030182 Discusses license amend application for decontamination & dismantlement of obsolete solvent extraction equipment at Charron Corp
HUGHES C J Fuel Processes & Recycle Branch 79/04/17 2pp

7906110029 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
O'REILLY J D Region 3, Chicago, Office of the Director 79/05/11 1p

7906030142 Forwards IE Circular 79-06, "Attempted Extortion - Low Enriched U"
HOPPER J D Region 3, Chicago, Office of the Director 79/05/10 1p

DOCKET 79-1200 PRINCETON GAMMA-TECH

7906010123 Ack receipt of 790305 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 79-1200/79-01
ROSLINTON R D Region 1, Philadelphia, Office of the Director 79/03/27 1p

7906010129 Responds to NRC 790328 ltr re violations noted in IE Insp Rept 79-1200/79-01 Corrective actions now ongoing in use. reasons have been posted & Pu/Decontamination source use has been restricted
LISTER D S Princeton Gamma-Tech 79/03/03 3pp

7906010130 Discusses IE Insp Rept 79-1200/79-01 on 790303 Forwards notice of violation Noncompliance noted Inspect unused rooms not posted, mail used by unauthorized persons & stored in unauthorized places
ROSLINTON R D Region 1, Philadelphia, Office of the Director 79/01/25 2pp

7906010136 Notice of violation from Insp on 790304
Region 1, Philadelphia, Office of the Director 79/01/25 2pp

DOCKET 79-1201 UP & CONVERSION FACILITY, BAECHCK & HILCOX CO

7906070018 Forwards IE Insp Rept 79-1201/79-10 on 790320-23 No noncompliance noted
SIMPSON R P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/06 2pp

7906070020 IE Insp Rept 79-1201/79-10 on 790320-23 No noncompliance noted Major areas inspected organization, facility changes & waste, internal review & audit, safety committees & operation review
KANE J E, WOODRUFF R L Region 2, Atlanta, Office of the Director 79/04/06 2pp

7906030113 Amends License BHM-1166, Condition 12, re emergency plans in accordance w/790320 submittal & 10CFR20
GOSWAMI T Fuel Processes & Recycle Branch 79/04/23 1p

7906030143 Revises 790726 emergency plan & revisions for BHM
WITENBERG R L Fuel Processes & Recycle Branch 79/05/23 3pp

7906030164 Requests registration as user of BU-7 shipping container under License BHM-1168 All documentation required for container use has been obtained
ZEFF D W Babcock & Wilcox Co 79/04/23 1p

7906040008 Forwards IE Insp Rept 79-1201/79-01 on 790319-23 No noncompliance noted
SIMPSON R P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/26 2pp

7906040098 IE Insp Rept 79-1201/79-01 on 790319-23 No noncompliance noted Major areas inspected coordination w/offsite support agencies, emergency equipment, medical arrangements & fire prevention
PERNOTTE D J, WILSON W H Region 2, Atlanta, Office of the Director 79/04/21 2pp

7906050185 Forwards revised sections of Amend Request 79-4, Contamination action revised for further compliance w/expressed license limits & proposed Reg Guide 0 24
ZEFF D W Babcock & Wilcox Co 79/04/25, 60pp

7906030129 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
O'REILLY J P Region 2, Atlanta, Office of the Director 79/05/10 1p

7906020037 Forwards revised conditions re melt control & accounting program to be added to License BHM-1148 Revised conditions to Sections D 9, 4 & 8 of Amend BHM-2 should be implemented within 30 days
PARTLOW J D Material Control Licensing Branch 79/05/19 3pp

DOCKETED ITEMS

7904290818 Forwards 790309 to Linn request for add info re revised 790430 application
MELTZER, J. S. Fuel Process & Fab Branch 79/05/22 3pp

7904290772 Response to 790704 & 790457 ltr re charges to fundamental nuclear plant control plan Forwards request for add info
MELTZER, J. S. Material Control Licensing Branch 79/05/24 3pp

SECRET 79-1200 GENERAL ELECTRIC CO

7904290503 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies" -
KEPPLER, J. S. Region 3, Chicago, Office of the Director 79/05/11 1p

7904290137 Forwards IE Circular 79-08. "Attempted Extortion - Low Enriched U"
KEPPLER, J. S. Region 3, Chicago, Office of the Director 79/05/18 1p

SECRET 79-1207 MIXED OXIDE FABRICATION PLANT, EXXON NUCLEAR CO., INC

7904290313 Forwards 790401-003 "Security Training & Qualification Plan for Exxon Nuclear Mixed Oxide & Specializing Plant Plans"
Plan withheld re: 100798 7903
MILNER, R. Exxon Nuclear Co. & 1st 1984 or Exxon Corp. 79/05/20 3pp

7904290429 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies" -
KEPPLER, J. S. Region 3, San Francisco, Office of the Director 79/05/10 1p

7904290218 Forwards IE Circular 79-08. "Attempted Extortion - Low Enriched U"
MELTZER, J. S. Region 5, San Francisco, Office of the Director 79/05/18 1p

7904290274 Request replacement of cover sheet for Insp report changes re: 790309 from 79-1207/79-01 to 79-1207/79-04 Also requests corresponding to 790716 ltr which Forwards report
Region 4, Dallas, Office of the Director 79/05/18 2pp

SECRET 79-1208 NORMIE OPERATIONS, GENERAL ELECTRIC CO

7904290306 Submits revision per 790309 application for renewal of License 7903-1205
MELTZER, J. S. General Electric Co 79/05/18 11pp

7904290213 Forwards IE Insp Rept 79-1208/79-03 on 790307 & 0402-03 No noncompliance noted
DAVIS, A. S. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/23 2pp

7904290008 IE Insp Rept 79-1208/79-03 on 790307 & 0402-03 No noncompliance noted Major areas inspected safety committees, training, surveillance testing, fuel storage & handling, airborne effluents & solid wastes
MELTZER, J. S. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/20 2pp

7904290138 Forwards table showing current inventory of fuel stored at facilities
MELTZER, J. S. General Electric Co - Nuclear Energy Products Div 79/04/24 2pp

7904290364 Response to safeguards emergency plan. App. A submitted by 790718 ltr. Form should be revised to reflect recent changes
MELTZER, J. S. Physical Security Licensing Branch 79/05/04 1p

7904290104 Ack receipt of 790404 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 79-1208/79-02
DAVIS, A. S. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/08 1p

7904290130 Response to NRC ltr re violations noted in IE Insp Rept 79-1208/79-02 Corrective actions were being moved to storage location in main bldg & stored away from combustible mat
MELTZER, J. S. General Electric Co 79/04/24 2pp

7904290308 Requests assistance in reviewing application for renewal of License 7903-1205
MELTZER, J. S. Fuel Process & Fab Branch 79/05/08 2pp

7904290356 Forwards corrected attachment to 790404 ltr discussing fuel storage at existing Morris operation space
MELTZER, J. S. General Electric Co - Nuclear Energy Products Div 79/05/08 2pp

7904290303 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies" -
KEPPLER, J. S. Region 3, Chicago, Office of the Director 79/05/11 1p

7904290378 Ack receipt of 790501 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 79-1208/79-01
MELTZER, J. S. Region 3, Chicago, Safeguards Branch 79/05/18 1p

7904290304 Response to NRC ltr re violations noted in IE Insp Rept 79-1208/79-01 Corrective actions withheld (ref 100798 7903)
MELTZER, J. S. General Electric Co - Nuclear Energy Products Div 79/05/08 1p

7904290320 Requests add reference mat in order to enhance incident response ctr add mat needed include site emergency plan & implementing procedures & four sets of site maps showing emission monitoring stations
KEPPLER, J. S. Region 3, Chicago, Office of the Director 79/05/17 1p

7904290327 Forwards IE Circular 79-08. "Attempted Extortion - Low Enriched U"
KEPPLER, J. S. Region 3, Chicago, Office of the Director 79/05/18 1p

7904290373 Notice to intervene as party & as intervenor status Request based on license renewal & NRC preparation of CIB Notice of appearance. Affidavits in support of Certificate of Due
SCOTT, H. J. & MELTZER, J. S. Illinois, State of 79/05/21 10pp

7904290280 Petition to Intervene Confidentially allege applicant has not filed CIB notice petition plan for area cited & major disaster in possible due to concentration of spent fuel in area Certificate of Due
MELTZER, J. S. & MELTZER, J. S. Affiliation Unknown 79/05/27 7pp

7904290402 Notification of appointment of AC Goodhue as NRC chairman & LM Lichte & PJ Welch as NRC members
LISC, R. N. Atomic Safety and Licensing Board Panel 79/05/05 2pp

SECRET 79-1209 NORMIE OPERATIONS, SOURCES & STANDARDS, GENERAL

7904290303 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies" -
KEPPLER, J. S. Region 3, Chicago, Office of the Director 79/05/11 1p

7904290323 Requests add reference mat in order to enhance incident response ctr add mat needed include site emergency plan & implementing procedures & four sets of site maps showing emission monitoring stations
KEPPLER, J. S. Region 3, Chicago, Office of the Director 79/05/17 1p

7904290317 Forwards IE Circular 79-08. "Attempted Extortion - Low Enriched U"
KEPPLER, J. S. Region 3, Chicago, Office of the Director 79/05/18 1p

SECRET 79-1210 U S NUCLEAR, INC

7904290428 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies" -
MELTZER, J. S. Region 2, Atlanta, Office of the Director 79/05/08 1p

SECRET 79-1211 ARMY, DEFENSE

7904290447 Ack receipt of 790403 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 79-1208/79-01
MELTZER, J. S. & MELTZER, J. S. 79-1208/79-01
MELTZER, J. S. Region 3, Philadelphia, Office of the Director 79/05/08 1p

7904290303 Response to NRC 790330 ltr re violations noted in IE Insp Rept 79-1208/79-01, 40-0104/79-01 & 79-1208/79-01
Corrective actions installation of fence enclosing radiation area & storage of licensed mat in locked cabinet
MELTZER, J. S. Army, Dept. of Electronics Research & Development Command 79/04/21 1p

DOCKETED ITEMS

--7906140504 Forwards notice of violation from IE Insp Rept 70-0248/79-01 on 790226
NCLINTECK, R D Region 1, Philadelphia, Office of the Director
79/03/30 Dpp

--7906140616 Notice of violation from Insp on 790306 Noncompliance noted
radiation levels outside reactor facility exceeded limits
+ licensed mail stored in unlicensed container
NCLINTECK, R D Region 1, Philadelphia, Office of the Director
79/03/30 Dpp

DOCKET 70-8759 INT CORP

7906270026 Notices of issuance of Amend 10 to License 89W-1405
extending expiration date to 8/20/80 per 790226 application
CRS&W, T Fuel Process & Fab Branch 79/03/03 Dpp

--7906270026 Discusses 790206 license amend application requesting
extension of expiration date to 8/20/80 Recommendations approved
CRS&W, T Fuel Process & Fab Branch 79/03/03 Dpp

DOCKET 70-1426 TRANSNUCLEAR, INC

7906340706 Notices that safeguards contingency plan for transportation
+ transfer points requires supplemental info + revision Decl
associated copy unoriginal notes withheld (ref 8/20/80 780)
HCCORR, G W Physical Security Licensing Branch 79/03/13 Dpp

DOCKET 70-1432 RECYCLE FUEL PLANT, MERTNSHORE ELECTRIC CORP

7906320497 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
O'HEELY, J P Region 2, Atlanta, Office of the Director
79/03/10 Dpp

DOCKET 70-1469 GOODYEAR AEROSPACE CORP

7906100027 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies"
MEFFLER, J O Region 3, Chicago, Office of the Director 79/03/11
Dpp

7906100140 Forwards IE Circular 79-08, "Attempted Extension - Low
Enriched U"
MEFFLER, J O Region 3, Chicago, Office of the Director 79/03/18
Dpp

DOCKET 70-1510 NUCLEAR ASSURANCE CORP

7906210016 Forwards check for add \$200 to cover fees required for
renewal of License 89W-1473 per 790302 request
VIBROTEC, J R Nuclear Assurance Corp 79/03/10 Dpp

--7906210028 Responds to 790423 re forwarding \$400 fee for renewal of
License 89W-1473 Since application is only to renewal fee of
\$400, requests payment of add \$200
JACKSON, G License Fee Management Branch 79/03/02 Dpp

--7906210304 Applies for renewal of License 89W-1473 to permit delivery
of SHW products mail + source mail to carrier for
transport in Cont NAC-1 Forwards license renewal fee
HOLLINGS, J E Nuclear Assurance Corp 79/04/23 Dpp

DOCKET 70-1621 CONOVER & ASSOCIATES, INC

7906190419 Forwards Endorsements 24 & 25 to NELA Policy 89-226 +
Endorsements 26 & 27 to NELA Policy 89-27
BARNETT, J E Conover & Associates, Inc Insurance 79/06/14 Dpp

DOCKET 70-1710 ST. MARY'S HOSP, WA, CONNECTICUT

7906290145 Ack receipt of 790405 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 70-1710/79-01
on 790216
NCLINTECK, R D Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch 79/05/02 Dpp

--7906290162 Responds to NRC 790216 ltr re violations noted in IE Insp
Rept 70-1710/79-01 on 790216 Corrective actions procedure
established to ensure that mail not in storage will be under
constant surveillance + leak tests performed
HEASLER, L V St Mary's Hosp WA, Connecticut 79/04/09 Dpp

--7906290671 Discusses IE Insp Rept 70-1710/79-01 on 790225
NCLINTECK, R D Region 1, Philadelphia, Fuel Facility &
Materials Safety Branch 79/03/19 Dpp

DOCKET 70-1717 NORMAN, HOSP

7906300184 Ack receipt of 790402 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 70-1717/79-01
NCLINTECK, R D Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch 79/05/02 Dpp

--7906300508 Responds to NRC 790306 ltr re violations noted in IE Insp
Rept 70-1717/79-01 Corrective actions audit of program has
been performed + researcher protocol revised Protocol.mtl
BRADY, A M Norman Hosp 79/04/02 Dpp

--7906300800 "Research Protocol for Clinical Investigation of Nuclear
Reactions"
+ Annual Hosp 79/03/05 Dpp

DOCKET 70-1729 FUEL, NRC & NRC, STA., ALLIED GENERAL NUCLEAR SERVICES

7906300687 Advises that NRC cannot require applicant or licensee to
include parties in NRC proceedings in meetings or other
contacts which are extraneous to proceedings
KROENKE, T F Deputy Executive Legal Director 79/04/17 Dpp

DOCKET 70-1738 PACIFIC GEN & ELECTRIC CO

7906300157 Discusses IE Insp Rept 70-1738/79-01 on 790309-06 Details
withheld (ref 10/09/79)
MOTTERHOUSE, L H Region 3, San Francisco, Safeguards Branch
79/04/26 Dpp

DOCKET 70-2000 MT DIANE HOSP, WA

7906300009 Ack receipt of 790317 ltr informing NRC of steps taken to
correct violation noted in IE Insp Rept 70-2000/79-01 on
790214
NCLINTECK, R D Region 1, Philadelphia, Office of the Director
79/04/04 Dpp

--7906300508 Responds to NRC 790309 ltr re violation noted in IE Insp
Rept 70-2000/79-01 on 790214 Corrective actions employee
re-instructed in disposal of radioactive wastes + but lab
waste basket labeled
BRADY, A + LESHINSKY, V + LAZARUS, M Mount Sinai CT/WA 79/03/19
Dpp

--7906300501 Discusses IE Insp Rept 70-2000/79-01 on 790214 + forward
notice of violation
RECLINTECK, R D Region 1, Philadelphia, Office of the Director
79/03/19 Dpp

--7906300504 Notice of violation from Insp on 790214 Noncompliance re
failure to survey + record procedures for disposal of
licensed waste mail + failure to clearly label licensed
radioactive mail
+ Region 1, Philadelphia, Office of the Director 79/03/19
Dpp

- 7903010331 NRC interrogatories to Carolina Envrion Study Group per ASLR 790303 and/or KETCHEN, E G Branch 4 79/03/04 3pp
- 7903010334 Interrogatories to Carolina Action per ASLR 790303 order KETCHEN, E G Branch 4 79/03/04 3pp
- 7903010337 Interrogatories to Davidson College Chapter of NC PIRG per ASLR 790303 order ASLR 790303 order Certificate of Doc encl KETCHEN, E G Branch 4 79/03/04 3pp
- 7903040141 Second set of interrogatories directed to intervenor Carolina Action Certificate of Doc encl KETCHEN, E G Branch 4 79/03/23 1pp
- 7903040143 Request intervenor Carolina Action to produce documents identified in responses to NRC second set of interrogatories KETCHEN, E G Branch 4 79/03/23 1p
- 7903070170 Applicant's interrogatories to NRC per ASLR 790303 order. 6 requests to produce documents Certificate of Doc encl KETCHEN, E G Branch 4 79/03/28 3pp
- 7903100016 Forward verification of 790307 response to NRC interrogatories to applicant N/A encl W/affidavit PORTER, W L Duke Power Co 79/03/30 2pp
- 7903100333 Forward answers to NRC interrogatories & motion to produce documents Certificate of Doc encl KETCHEN, E G Branch 4 79/04/01 2pp
- 7903100341 Answers to NRC interrogatories Affidavits of AJ Holman, TD Cushman & AM Tonglin encl KETCHEN, E G Branch 4 79/04/01 10pp
- 7903100343 Response to NRC motion to produce documents. 4 Natural Resources Defense Council 79/04/01 3pp
- 7903100312 Forward applicant's motion to dismiss Safe Energy Alliance as party intervenor Includes page 2 omitted when motion was originally filed on 790303 KETCHEN, E G Branch 4 79/04/01 1p
- 7903100313 Motion to dismiss Safe Energy Alliance as party intervenor Includes page 2 omitted when motion was originally filed on 790303 Certificate of Doc encl KETCHEN, E G Branch 4 79/04/01 1pp
- 7903100314 Response to 790308 request for production of documents Lists documents available for inspection agreement re info disclosure encl PORTER, W L Duke Power Co 79/04/01 3pp
- 7903100315 Requests responses to 790314 interrogatories PORTER, W L Duke Power Co 79/04/01 2pp
- 7903100337 Response to NRC 790308 request for admissions Objects to Items 5, 6 & 7 Admits Items 3, 4, 8 & 9 Admits Items 10 & 12 Neither admits nor denies Items 11 & 12 Affidavit Certificate of Doc encl PORTER, W L Duke Power Co 79/04/01 7pp
- 7903100338 Response to NRC 790308 request for admissions by NRC 5 encl Affidavit of RE Hocking & Certificate of Doc encl PORTER, W L Duke Power Co 79/04/01 10pp
- 7903100340 Requests to make limited appearance statement at licensing proceeding conference KETCHEN, E G Branch 4 79/04/01 2pp
- 7903100342 Forward info requested on 790312 re NRC Contention 3 Certificate of Doc encl KETCHEN, E G Branch 4 79/04/02 2pp
- 7903100345 Motion to compel applicant to respond to NRC 790402 requests for admissions or file default Certificate of Doc encl KETCHEN, E G Branch 4 79/04/25 2pp
- 7903100326 Motion for order to compel intervenor Davidson College Chapter of NC PIRG to respond to NRC second set of interrogatories Certificate of Doc encl KETCHEN, E G Branch 4 79/04/25 2pp
- 7903100354 Supports motion for order to compel intervenor Davidson College Chapter of NC PIRG to respond to NRC second set of interrogatories submitted 790303 Proposed form of order encl KETCHEN, E G Branch 4 79/04/25 2pp
- 7903100355 Motion for order to compel intervenor Carolina Action to respond to NRC second set of interrogatories submitted 790303 Proposed form of order encl KETCHEN, E G Branch 4 79/04/25 2pp
- 7903100376 Supports motion for order to compel intervenor Carolina Action to respond to NRC second set of interrogatories submitted 790303 Proposed form of order encl KETCHEN, E G Branch 4 79/04/25 2pp
- 7903100398 Motion by intervenor Carolina Envrion Study Group to permit further removal of info obtained through discovery Supporting documentation & Certificate of Doc encl KETCHEN, E G Branch 4 79/04/27 2pp
- 7903100399 Requests admission of time through 790301, or ten days after applicant responses to request for admissions, for filing of motions for summary disposition re Contention 4 W/affidavit Certificate of Doc encl KETCHEN, E G Branch 4 79/04/27 2pp
- 7903100309 Response to NRC 790427 request for extension of time in which to file motion for summary disposition Does not oppose NRC motion Move for summary disposition until 790331 on own behalf Certificate of Doc encl KETCHEN, E G Branch 4 79/05/01 3pp
- 7903100344 Motion for summary disposition re NRC Contention 4 W/affidavit to issue order for discovery to be completed & discovery to be allowed before completion of further proceedings Affidavit & Certificate of Doc encl KETCHEN, E G Branch 4 79/05/01 13pp
- 7903100362 Interrogatories submitted by NRC re weekly info kept far west ending 790410 KETCHEN, E G Branch 4 79/05/01 2pp
- 7903100367 Requests that board direct NRC to respond to 790304 Interrogatories Certificate of Doc encl KETCHEN, E G Branch 4 79/05/01 2pp
- 7903100368 Motion for extension of time until 790331 to file summary disposition to intervenor NRC 790312 certification based on failure to respond to discovery Certificate of Doc encl KETCHEN, E G Branch 4 79/05/02 2pp
- 7903101014 Motion for protective order denying discovery sought by intervenor Carolina Envrion Study Group Interrogatories and hypotheticals & request order of discovery Certificate of Doc encl PORTER, W L Duke Power Co 79/05/03 4pp
- 7903100312 Requests status of Award to License SW-173 re receipt & storage of spent fuel LAM, R E South Carolina, State of 79/05/03 1p
- 7903100316 Forward NRC-0352, "Summary of Operating Experience w/Recirculating Steam Generators" W/affidavit KETCHEN, E G Branch 4 79/05/03 2pp
- 7903100317 Branch extensions of time in which to file motions for summary disposition until 790331 re NRC 790312 motion for summary disposition until 790331 KETCHEN, E G Branch 4 79/05/04 2pp
- 7903100316 Forward responses to Interrogatories 120, submitted by intervenor Carolina Envrion Study Group KETCHEN, E G Branch 4 79/05/07 1p
- 7903100319 Requests to intervenor Carolina Envrion Study Group Interrogatory 120 Affidavit & Certificate of Doc encl KETCHEN, E G Branch 4 79/05/07 2pp
- 7903100357 Forward supplemental response to Question 1 of NRC 790402 for Applicant's partial support page of probabilistic simulation production testing model used to determine change in production costs caused by operating at half capacity PARKER, H D Duke Power Co 79/05/07 17pp
- 7903100308 Answers to NRC second set of Interrogatories Supporting documentation Affidavits & Certificate of Doc encl PORTER, W L Duke Power Co 79/05/07 34pp

DOCKETED ITEMS

7906010078 Opposes Intervenor Caroline Envinon Study Group 790427 motion for confinement motion is insufficient as matter of law & case not rest on matters necessary for continuance Certificate of Evc encl
KETCHEN, C D Branch 3 79/05/10 3pp

7906010019 Forwards motions for summary disposition intends to file supplemental affidavits attesting accuracy of affidavits which accompany motions Certificate of Evc encl
KOPFLING, H K Branch 4 79/05/11 4pp

7906010025 Motion for summary disposition of Intervenor HRC Contentions 1-5 Affidavits encl
HSEFLING, R K K. KETCHEN, C D Branch 4 79/05/11 10pp

7906010031 Statement of natl facts as to which there is no genuine issue to be heard, submitted in support of AMC motion for summary disposition of HRC Contentions 1-5
HSEFLING, R K Branch 4 79/05/11 10pp

7906010038 Motion for summary disposition of Intervenor Caroline Envinon Study Group & Caroline Action Contentions 1-3 Affidavits encl
HSEFLING, R K K. KETCHEN, C D Branch 4 79/05/11 17pp

7906010039 Statement of natl facts as to which there is no genuine issue to be heard, submitted in support of AMC motion for summary disposition of Intervenor Caroline Envinon Study Group & Caroline Action Contentions 1-3
HSEFLING, R K K. KETCHEN, C D Branch 4 79/05/11 10pp

7906010049 Statement of natl facts as to which there is no genuine issue to be heard, submitted in support of AMC motion summary disposition of Intervenor Caroline Envinon Study Group & Caroline Action Contention 2
HSEFLING, R K K. KETCHEN, C D Branch 4 79/05/11 7pp

7906010042 Motion for summary disposition of Intervenor Caroline Action Contention 4 & contention of Intervenor Davidson Chapter of HRC PBOB Supporting affidavits encl
HSEFLING, R K K. KETCHEN, C D Branch 4 79/05/11 40pp

7906010019 Opposes Intervenor Caroline Envinon Study Group 790427 motion for confinement
MILLER, M E Atomic Safety and Licensing Board Panel 79/05/11 1p

7906020038 Dismisses Caroline Action as intervening party & active participation due to failure to respond to applicant interrogatories
MILLER, M E Atomic Safety and Licensing Board Panel 79/05/23 1p

7906020097 Grants dismissal of HRC Contention 4 & granting of util 790521 motion for summary disposition Contention presents no issue of law or natl fact suitable for resolution
Certificate of Evc encl
MCGARRY, J H Duke Power Co 79/05/29 17pp

DOCKET 79-0484 BRAUER, L. E. INC

7906010057 Ack receipt of 790411 ltr informing HRC of steps taken to correct violations noted in IE Insp of License 20-01412-02
on 790396
HCCLEINTOCK, R D Region 1, Philadelphia, Office of the Director 79/05/10 1p

7906010063 Responds to HRC 790402 ltr re violations noted in IE Insp of License 20-01412-03 on 790396 Corrective actions procedures for receipt of radioactive shipment altered & sign posted near access to radiation storage room
BARNHART, G M, BRADMAN, A, GIFFORD, K C Baystate Medical Center MA/SP 79/05/11 10pp

7906010063 Submits details of unified radiation safety program
GIFFORD, K C Baystate Medical Center MA/SP 79/05/16 3pp

7906010075 Discusses IE Insp of License 20-01412-03 on 790306 & forwards notice of violation
HCCLEINTOCK, R D Region 1, Philadelphia, Office of the Director 79/04/02 2pp

7906010077 Notice of violation from insp on 790306 Noncompliance noted failure to survey for contamination in natl before disposal, lack of surveillance for stored natl & unopened radiation area
* Region 1, Philadelphia, Office of the Director 79/04/02 2pp

7906010077 Notice of violation from insp on 790306 Noncompliance noted failure to survey for contamination in natl before disposal, lack of surveillance for stored natl & unopened radiation area
* Region 1, Philadelphia, Office of the Director 79/04/02 2pp

DOCKET 79-2020 PARSONS AMERICA CORP

7906010031 Forwards IE Insp Rpt 79-2020/79-01 on 790409 Rept withheld (ref IOCFR 7001)
HSEFLING, R K Region 3, San Francisco, Safeguards Branch 79/04/23 2pp

DOCKET 79-2828 CINCINNATI GAS & ELECTRIC CO

7906020042 Forwards revised papers to license application for storage only of unirradiated reactor fuel & associated radioactive natl
FLANNEL, J P Cincinnati Gas & Electric Co 79/04/12 3pp

DOCKET 79-2880 HERY HOSP. SP, MASSACHUSETTS

7906010021 Ack receipt of 790403 ltr informing HRC of steps taken to correct violations noted in IE Insp Rpt 79-2880/79-01 on 790306
HCCLEINTOCK, R D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/02 1p

7906010022 Responds to HRC ltr re violations noted in IE Insp Rpt 79-2880/79-01 on 790306 Corrective actions sealed canister or ref sources shall be tested for leakage & nuclear medicine facility shall be surveyed weekly
HCCLEINTOCK, R D Hery Hosp MA/SP 79/04/03 3pp

7906010023 Discusses IE Insp Rpt 79-2880/79-01 on 790305 Forwards notice of violation
HCCLEINTOCK, R D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/23 2pp

7906010024 Notice of violation from insp on 790305 Noncompliance noted failure to make surveys necessary to determine that individuals handling 1-13 were not overexposed & failure to test coat (60 uCi) sealed canister ref source
* Region 1, Philadelphia, Office of the Director 79/03/23 2pp

DOCKET 79-2884 LONG ISLAND LIGHTING CO

7906010043 Responds to HRC request for analysis re dry storage under option moderator conditions Dry storage under such conditions is feasible & brief will be less than 6 yb for all values of moderator density
WISNIEWSKI, J P Long Island Lighting Co 79/05/09 4pp

DOCKET 71-0018 NUCLEAR ASSURANCE CORP

7906210087 Forwards request for addl info to complete review of QA program
HACEDORALD, C E Transportation Branch 79/05/20 1p

DOCKET 71-0028 BORG-WARNER CORP

7906210044 Responds to 790402 request for addl info re QA program
Furnishes Procedure 03173-02 reflecting code
000TH-J H Borg-Warner Corp 79/04/25 1p

7906210072 QA program for facility
ALBERT, H C Borg-Warner Corp 79/04/15 4pp

DOCKET 71-0034 BARCOCK & WILCOX CO

7906210171 Furnishes Revision 1 of QA program for transportation & receipt of radioactive material
SULZER, H C Barcock & Wilcox Co 79/05/16 1p

79062102174 Revision 1 to QA program for transportation & receipt of radioactive material
S Barcock & Wilcox Co 79/05/16 4pp

DOCKET 71-0036 ITT GRINELL CORP

7906210020 Forwards revised QA program for radioactive material package
Previously deleted Part B on audits and
KOSMINSKI, J D absolute code 79/05/02 1p

79062100204 Revised QA program for radioactive material package
KOSMINSKI, J D absolute code 79/04/20 12pp

DOCKET 71-0037 NAVY, DEPT OF

7906210030 Forwards QA program
SIMPSON, P B Navy/Dept of 79/04/18 1p

7906210001 QA program for receipt, handling, storage & transfer of special forms of radioactive material
Navy/Dept of 79/04/18 12pp

DOCKET 71-0039 SULLIVAN CO

7906210044 Forwards Revision 1 to QA program
STEPHEN, H B Sullivan Co 1000 of 10 International Corp 1
79/05/02 1p

79062100297 Revision 1 to QA program
STEPHEN, H B Sullivan Co 1000 of 10 International Corp 1
79/05/02 3pp

DOCKET 71-0047 CAPETOL INTERNATIONAL, AM/RE, INC

7906210047 Responds to 790412 ltr Forwards current organizational structure
OPARKS, E Capitol International Attorneys, Inc 79/04/17 1p

Forwards request for current organizational chart for use
79/04/13 4pp

7906210001 Informs that activities conducted under applicable criteria of 10CFR50 App B will be executed regardless of transportation packages by 790620
HACEDORALD, C E Transportation Branch 79/05/02 1p

DOCKET 71-0059 GENERAL ELECTRIC CO

7906210074 Responds to MEC 790413 ltr requesting addl info & clarification Radiation protection officer & radiation safety officer in organizational chart are same
JULLY, J General Electric Co 79/05/08 1p

DOCKET 71-0061 NAVY, DEPT OF

7906210020 Submits addl info re QA program covering duties of radiation protection officer & director of Weapons Quality Engineering
Civ
FORSNAP, R Navy/Dept of 79/05/02 2pp

DOCKET 71-0068 YAMKOR ATOMIC ELECTRIC CO

7906210038 Responds to 790413 request re QA program Suggests revision number of 790413-A not be designated
HEDGECOCK, L Yamkor Atomic Electric Co 79/04/24 1p

DOCKET 71-0070 GENERAL MOTORS CORP

7906210021 Forwards QA program for License 12-13028-01
ABRAHAM, C J General Motors Corp 79/05/07 1p

79062100254 QA program for License 12-13028-01
ABRAHAM, C J General Motors Corp 79/05/07 3pp

DOCKET 71-0072 BARCOCK & WILCOX CO

7906210019 Forwards QA program for License 12-002-01
FERTER, C Barcock & Wilcox Co 79/05/04 3pp

7906210021 QA program for License 12-002-01
S Barcock & Wilcox Co 79/05/03 3pp

DOCKET 71-0074 NUCLEAR SELLING, INC

7906210045 Forwards requested QA program
HARRIS, T B Nuclear Selling, Inc 79/05/07 1p

79062100459 QA program for industrial radiography license
Nuclear Selling, Inc 79/05/07 11pp

DOCKET 71-0077 HIGSBY TESTING LAB

7906210051 Responds to 790427 ltr re 790400 application requesting approval of QA program Requests deletion of ref to "radiation control officer"
KEELMAN, T J Higbys Testing Laboratory, Inc 79/05/09 1p

DOCKET 71-0085 NAVY, DEPT OF

7906210026 Notification that addl info re QA program will be provided no later than 79/05/08
SULLIVAN, J Navy/Dept of 79/05/10 1p

DOCKET 71-0087 NAVY, DEPT OF

7906210046 Responds to 790413 ltr re QA program for USS Jensen radiographic film processing Program is contained in COMNAVFLTINST 4255 1A Provisions are made in code for annual issue of paint actions & annual audits
SULLIVAN, J Navy/Dept of 79/05/03 1p

DOCKET 71-0090 COMBINATION ENGINEERING CO, INC

7906210042 Forwards QA program approval for radioactive material package
HACEDORALD, C E Transportation Branch 79/05/02 1p

DOCKETED ITEMS

7906010095 Inform that activities conducted under applicable criteria of 10CFR71 App E will be executed w/regard to transportation packages by 790601
RACDONALD, C E Transportation Branch 79/05/02 1p

DOCKET 71-0046 PAN AMERICAN WORLD AIRWAYS

7906070037 Notifies that proposed QA program does not meet requirements of App E to 10CFR71 Forwards sample 790602 QA program for industrial radiography licenses to assist in application revision Request revision by 790602
RACDONALD, C E Transportation Branch 79/04/27 3pp

DOCKET 71-0099 FOSTER WHEELER ENERGY CORP

7906020024 Forwards Foster Wheeler Energy Corp procedure, "Radiation Safety QA Requirements for Radiography Source Shipments," Revision 1.0.0 790504
WATKINS, P D Foster Wheeler Corp 79/05/04 3pp

DOCKET 71-0103 TWIN CITY TESTING & ENGR LAB

7906020028 Forwards page 4 of QA program per NRC 790613 request 000126, H T Twin City Testing & Engineering Laboratory, Inc 79/05/03 2pp

DOCKET 71-0110 BUCKING STEEL CASTINGS

7906040125 Forwards QA program
KRAUSE, J F Bucking International, Inc Steel Castings Div 79/04/19 1p

7906040132 QA program for industrial radiography
KRAUSE, J F Bucking International, Inc Steel Castings Div 79/04/19 4pp

DOCKET 71-0115 BARBER & WILCOX CO

7906060107 Forwards request for add info to complete review of QA program
RACDONALD, C C Transportation Branch 79/05/02 12pp

DOCKET 71-0119 INGERSOLL-RAND CO

7906020012 Forwards QA program w/requested change Radiation Safety Officer title changed to Radiation Protection Officer
RACDONALD, C C Ingersoll-Rand Co 79/05/11 1p

7906020018 QA program for industrial radiography licenses
Ingersoll-Rand Co 79/05/06 3pp

DOCKET 71-0120 DANIEL INTERNATIONAL CORP

7906020044 Forwards Revision 1 to QA program for License 01-0126-02
FLUOR, W C Daniel International (subs of Fluor Corp) 79/03/09 1p

7906020038 Revision 1 to QA program for License 01-0126-02
Daniel International (subs of Fluor Corp) 79/03/09 2pp

DOCKET 71-0126 BARBER & WILCOX CO

7906020438 Requests correspondence to PA operations site be addressed to PA Austin instead of PA Williams
MARTIN, H A Barber & Wilcox Co 79/05/10 1p

DOCKET 71-0137 METAL TESTING CO, INC

7906020044 Notifies that proposed QA program does not meet requirements of App E to 10CFR71 Forwards sample QA program to aid in making application
RACDONALD, C E Transportation Branch 79/05/18 3pp

DOCKET 71-0145 TRAYNOR INSPECTION SERVICE, INC

7906020046 Submits revised page of Part 71 QA program
TRAYNOR, D M Traynor Inspection Service, Inc 79/05/04 2pp

DOCKET 71-0146 GLEBE 3-RAY SERVICES, INC

7906020157 Forwards copy of Form to be used in compliance w/QA program
38 Gamm unit to be added
GLEBE, R V Glebe 3-Ray Services, Inc 79/05/01 2pp

DOCKET 71-0130 PEEBLY TESTING SERVICES

7906020105 Forwards add paragraph to QA program re audits per NRC 790613 request
BAMFELD, E L Peebly Testing/X-Ray Engineering Co 79/05/03 2pp

DOCKET 71-0154 GENERAL DYNAMICS

7906020019 Forwards QA program w/requested change Radiation Safety Officer title changed to Radiation Officer
GENERAL, V M General Dynamics Corp Quincy Shipbuilding Div 79/05/09 1p

7906020028 QA program license 00-11415-01
GENERAL, V M General Dynamics Corp Quincy Shipbuilding Div 79/05/09 2pp

DOCKET 71-0157 FROHLING & ROBERTSON, INC

7906020011 Forwards revised Section VII of QA program for transportation packaging, allowing add by Amendment
Radiation Safety Coordinator, in response to request for add info
FROHLING, W M Frohling & Robertson, Inc 79/05/10 2pp

DOCKET 71-0162 BARBER SERVICES, INC

7906020070 Forwards add copies of QA program for shipping packages for radioactive materials
BARBER, J W Barber Services, Inc (subs of Research Corp) 79/04/30 1p

7906020075 QA program for License 01-0126-02
BARBER, J W Barber Services, Inc (subs of Research Corp) 79/04/30 2pp

DOCKET 71-0169 FLORIDA POWER & LIGHT CO

7906020019 Responds to 790319 ltr requesting ref to specific QA program used to meet requirements of 10CFR71 D1 Revision 2 as typical QA ref to in effect for Turkey Point & FSNR
QA program is in effect for St Lucie
FLORIDA, R E Florida Power & Light Co 79/04/22 1p

DOCKET 71-0174 SOUTHERN CALIFORNIA Edison CO

7906020109 Forwards QA program approval for radioactive mail packs
SOUTHERN, C E Transportation Branch 79/05/02 1p

7906020134 Activities conducted under applicable criteria of App 790601 to be executed w/regard to transportation packages by 790601
RACDONALD, C E Transportation Branch 79/05/02 1p

DOCKET 71-0180 HYUNDAI STEEL CASTING CO

7906020041 Forwards Revision 1 to QA program for License 48-07086-
FAIRBANK, A Hyundai Steel Casting Co 79/05/09 1p

7906020026 Revision 1 to QA program for License 48-07086-01
Hyundai Steel Casting Co 79/05/09 2pp

7906020050 Requests add info re company organization & statement
audit activities to complete review of QA program
RACDONALD, C E Transportation Branch 79/05/04 2pp

DOCKET 71-0190 TEXAS INSTRUMENTS, INC

770608003 Forwards request for add info to complete review of QA program
 MACDONALD, C E Transportation Branch 79/04/27 13pp

770608007 Requests that QA plan for shipping packages for radioactive waste be withdrawn from application N78E project as not user of general license for shipment of DOT spec containers
 BERNHART, L Texas Instruments, Inc 79/05/08 1p

DOCKET 71-0190 TOLSON, EDWARD C

770608008 Responds to 7706081 request for info re QA program until nuclear QA manual revised 7706081 is used for shipments of Type B quantities
 WELLS, E Toledo Selson Co 79/04/06 1p

770608042 Forwards QA program approval for radioactive mail package
 MACDONALD, C E Transportation Branch 79/05/17 1p

--770608047 QA program approval for radioactive mail package 0375.
 Revision 0
 MACDONALD, C E Transportation Branch 79/04/23 1p

DOCKET 71-0202 PACIFIC GAS & ELECTRIC CO

770608027 Forwards QA program approval for radioactive mail package
 MACDONALD, C E Transportation Branch 79/05/02 1p

--770608029 QA program approval for radioactive mail package 0232.
 Revision 0
 MACDONALD, C E Transportation Branch 79/05/02 1p

DOCKET 71-0207 CONNECTICUT NUCLEAR POWER CO

7706080149 Forwards QA program approval for radioactive mail package
 MACDONALD, C E Transportation Branch 79/05/08 1p

--7706080147 Informs that activities conducted under applicable criteria of 10CFR50 will be executed w/ regard to transportation pkg
 by 770608
 MACDONALD, C E Transportation Branch 79/05/08 1p

DOCKET 71-0208 NORTHEAST NUCLEAR ENERGY CO

7706081090 Forwards QA program approval for radioactive mail package
 MACDONALD, C E Transportation Branch 79/05/30 1p

--7706081092 QA program approval for radioactive mail package 0208.
 Revision 0
 MACDONALD, C E Transportation Branch 79/05/30 1p

DOCKET 71-0212 INTERMOUNTAIN TESTING CO

770619447 Advises that organization table has been changed to read Radiation Safety Officer instead of Radiation Protection Officer
 SCHILL, Y A Intermountain Testing Co 79/04/16 1p

O GENERAL DYNAMICS CORP

DOCKET 71-0222 NAVY, DEPT OF

7706020025 Requests and of QA program submitted on 781220 re duties of radiation safety officer
 HENFMAN, E E Navy Dept of, Naval Research Laboratory 79/04/26 1pp

7706020044 Forwards 1st sent to Naval organizations involved in radioactive mail packages Lists organizations which have submitted acceptable QA programs 1/24 and 1
 MACDONALD, C E Transportation Branch 79/05/04 1p

DOCKET 71-0229 WOOD INDUSTRIES PIPE FABRICATING, INC

7706020027 Submits addl info for QA program re radiation safety officer document control, handling, storage, shipping, insp & test & operating violation responses to NRC 770608 request
 ROSENBERG, R M Wood Industries Pipe Fabricating, Inc 79/05/07 13pp

DOCKET 71-0230 SARGENT & LILCO CO

7706020014 Forwards revised QA program for shipping containers. Revision 1
 NECLAN, HANNA, H H Sargent & Lilo Co 79/05/10 1p

--7706020013 QA program for shipping containers. Revision 1
 Sargent & Lilo Co 79/05/10 13pp

DOCKET 71-0233 O'NEILL TANK CO - INC

7706020148 Forwards QA manual for transportation packaging of radioactive mail
 ASHMAN, R O'Neill Tank Co, Inc 79/04/20 1p

--7706020131 QA manual for transportation packaging of radioactive mail
 O'Neill Tank Co, Inc 79/04/20 1pp

DOCKET 71-0248 POWER AUTHORITY OF STATE OF NEW YORK

7706020027 Forwards listing of deferred info describing QA program
 EARLY, P J Power Authority State of New York 79/04/23 13pp

7706020108 Forwards QA program approval for radioactive mail package
 MACDONALD, C E Transportation Branch 79/05/17 1p

--7706020112 QA program approval for radioactive mail package 240.
 Revision 0
 MACDONALD, C E Transportation Branch 79/05/17 1p

DOCKET 71-0258 NUCLEAR ENGINEERING CO - INC

7706020211 Forwards acceptance criteria used to evaluate QA program
 Addl info is required to satisfy requirements of 10CFR71. App E
 MACDONALD, C E Transportation Branch 79/05/16 13pp

DOCKET 71-0260 ASTROTECH, INC

7706020005 QA program for shipping packages of radioactive waste
 WENTZ, L Astrotech, Inc 79/05/10 13pp

DOCKET 71-0278 BANGOR LIGHT

7706160060 Requests withdrawal of valid radioactive waste packaging QA program submitted 7706081 Approves operational QA program
 LONN, C M Bangor Light Co 79/05/07 1p

7706020213 Forwards QA program approval for radioactive mail package
 MACDONALD, C E Transportation Branch 79/05/17 1p

--7706020215 QA program approval for radioactive mail package 0275.
 Revision 0
 MACDONALD, C E Transportation Branch 79/05/07 1p

DOCKETED ITEMS

24

DOCKET 71-0279 UNIVERSAL TESTING, INC.

7906150413 Forwards SA program does not meet requirements of App. B to 10CFR171. Forwards sample SA program for industrial radiography licenses. dtd 790602, to assist in application reviews. Reports revision by 790528. HANCOCK, D. E. Transportation Branch. 79/06/27 App

DOCKET 71-0284 ULTRASONIC SPECIALISTS, INC.

7906150267 Forwards SA program
GUTHRIER, R. L. Ultrasonic Specialists, Inc. 79/03/13 1p

--7906070007 SA program
* Ultrasonic Specialists, Inc. 79/03/13 App

DOCKET 71-0285 BELL GEOPHYSICS

7906140102 Forwards SA program for License 33-10126-01
BELL, J. A. Bell Geophysics 79/03/16 App

--7906140185 SA Program for License 33-10126-01
* Bell Geophysics 79/03/16 App

DOCKET 71-0287 CARSON NON-DESTRUCTIVE TESTING

7906170118 Forwards SA program for License 33-17880-05
HAWKINS, R. H. Carson Nondestructive Testing 79/03/19 App

--7906070119 SA program for License 33-17880-05
MCVILLOE, R. H. Carson Nondestructive Testing 79/03/19 App

DOCKET 71-0289 TERRADATA GEOPHYSICAL, INC.

7906140271 Forwards SA program for License 09-18217-05
MCBRIDE, G. E. Terradata Geophysical, Inc. 79/03/18 App

--7906140100 SA program for License 09-18217-01
MCBRIDE, G. E. Terradata Geophysical, Inc. 79/03/18 App

DOCKET 71-0291 GJ INSPECTION SERVICES, INC.

7906130427 Forwards SA program for License 3-2067
JOHNSON, R. G. GJ Inspection Services, Inc. 79/03/19 1p

--7906150430 SA program for License 3-2067
JOHNSON, R. G. GJ Inspection Services, Inc. 79/03/19 App

DOCKET 71-0292 INDUSTRIAL SAMPA INSPECTION

7906140078 Forwards SA program for License 33-14760-01
SMITH, R. Industrial Sampa Inspection 79/03/13 1p

--7906140380 SA program for License 33-14760-01
SMITH, R. Industrial Sampa Inspection 79/03/13 App

DOCKET 71-0294 APPLIED ENGINEERING CO.

7906150433 Forwards SA program for License 203
GOSWAMI, J. Applied Engineering Co. 79/03/23 1p

--7906150440 SA program for License 203
GOSWAMI, J. Metropolitan Edison Co. 79/03/23 App

DOCKET 71-0295 ACUREX CORP.

7906150444 Forwards SA program for License 2713-0795
FENDRICK, J. E. Acurex Alcorn, 79/03/26 1p

--7906150449 SA program for License 2713-0795
FENDRICK, J. E. Acurex Alcorn 79/03/26 App

DOCKET 71-0298 STEEL TANK CONSTRUCTION CO.

7906150173 Forwards SA program for License B-0033.
PADGETT, D. Steel Tank Construction Co. 79/03/22 1p.

--7906150195 SA program for License B-0033
KALLOUWY, C. C. Steel Tank Construction Co. 79/03/22 App

DOCKET 71-0301 CTL ENGINEERING, INC.

7906150284 Forwards SA program. Revision 1, for License 34-08331-01
CHAMLEY, J. L. CTL Engineers, Inc. 79/03/19 1p

--7906150288 SA program. Revision 1, for License 34-08331-01
CHAMLEY, J. L. CTL Engineers, Inc. 79/03/19 App

DOCKET 71-0302 JOHNSON CONTROLS

7906150224 Forwards SA program
JOHNSON, R. C. Johnson Controls, Inc. 79/03/23 1p

--7906150224 SA program for License 43-15117-01
JOHNSON, R. C. Johnson Controls, Inc. 79/03/23 App

DOCKET 71-0303 MONPHIS TESTING SERVICES, INC.

7906150048 Forwards SA program for License R-9630-04
REID, R. C. Monphis Testing Services, Inc. 79/03/28 1p

--7906140073 SA program for License R-9630-04
REID, R. C. Monphis Testing Services, Inc. 79/03/28 App

DOCKET 71-0304 SNYDER DRILLING-MAIL SERVICES CO.

7906150403 Forwards SA program for License 12-12194-08
SNYDER, H. L. Snyder Drilling-Mail Services 79/03/26 1p

--7906150404 SA program for License 12-12194-01
SNYDER, H. L. Snyder Drilling-Mail Services 79/03/26 App

DOCKET 71-0308 ALASKA INDUSTRIAL 3-RAY

7906140677 Forwards SA program for License 30-14084-01
MILLER, P. A. Alaska Industrial 3-Ray 79/03/18 1p

--7906140680 SA program for License 30-14084-01
MILLER, P. A. Alaska Industrial 3-Ray 79/03/18 App

DOCKET 71-0310 DUCYPUS-ERIE CO.

7906110423 Forwards SA program for License 48-06370-01
MERTZ, J. H. Ducypus-Erie Co. 79/04/04 1p

--7906110427 SA program for License 48-06370-01
MERTZ, J. H. Ducypus-Erie Co. 79/04/04 App

7906140587 Forwards request for Add info to complete review of SA program
HANCOCK, D. E. Transportation Branch 79/05/06 App

DOCKET 71-0313 PRECISION INSPECTION, LTD.

7906140044 Forwards SA program for License B-003
SING, J. E. Precision Inspection Ltd. 79/04/12 1p

--7906140048 SA program for License B-003
SING, J. E. Precision Inspection Ltd. 79/04/12 App

DOCKET 71-0314 SMITH-EMERY CO.

7906140033 Forwards SA program for License 3070-09.
SMITH-EMERY, C. Smith-Emery Co. 79/04/09 1p.

--7906140037 SA program for License 3070-09
SMITH-EMERY, C. Smith-Emery Co. 79/04/09 App.

DOCKETED ITEMS

247

DOCKET 71-5768 MODEL 88-250-2, CONSTRUCTION ENGINEERING CO., INC

7906200430 Requests correspondence to PA operations site be addressed to PA Austin instead of RA Williams
AUSTIN, R A Babcock & Wilcox Co 79/05/10 1p

DOCKET 71-5790 MODEL AL-101, ENERGY DEPT OF

7906200504 Concludes Packages AL-101 & AL-102 meet current packaging criteria
ROSEN, J R Energy Dept of 79/05/10 1p

DOCKET 71-5791 MODEL AL-101, ENERGY DEPT OF

7906200614 Concludes Packages AL-101 & AL-102 meet current packaging criteria
ROSEN, J R Energy Dept of 79/05/10 1p

DOCKET 71-5809 MODEL A500 WOOD CARR, ATCO, INC

7906200234 Forwards Revision 2 of Certificate of Compliance 5005 for shipping package Model Vandenberg
HACDONALD, C E Transportation Branch 79/05/09 2pp

7906200734 Certificate of Compliance 5005/Revision 3 for radioactive metal shipping package Model Vandenberg
HACDONALD, C E Transportation Branch 79/05/09 2pp

DOCKET 71-5908 MODEL 501-QN TYPE D, BABCOCK & WILCOX CO

7906200438 Requests correspondence to PA operations site be addressed to PA Austin instead of RA Williams
AUSTIN, R A Babcock & Wilcox Co 79/05/10 1p

7906200574 Forwards Certificate of Compliance 5908/Revision 3 for Model 501-QN Type D shipping package Superdome Certificate of Compliance 5008/Revision 4 Constitutes authority to use package for shipment of radioactive metal
HACDONALD, C E Transportation Branch 79/05/17 2pp

7906200574 Certificate of Compliance 5908/Revision 3
HACDONALD, C E Transportation Branch 79/05/17 2pp

DOCKET 71-5926 MODEL 100, GENERAL ELECTRIC CO

7906200632 Forwards Revision 2 of Certificate of Compliance 5926 for shipping package Model GE-100
HACDONALD, C E Transportation Branch 79/05/08 2pp

7906200704 Certificate of Compliance 5926/Revision 2 for radioactive metal shipping package Model GE-100
HACDONALD, C E Transportation Branch 79/05/08 2pp

DOCKET 71-5942 MODEL GE-700, GENERAL ELECTRIC CO

7906201024 Forwards request for add info to complete review of amend to Model GE-700 packaging info should be submitted as revised pages to GOR Requests response schedule within 30 days
HACDONALD, C E Transportation Branch 79/04/18 2pp

7906201062 Forwards revised SAR pages no criticality analysis accounting for reflection by lead & use of some correct U-238 cross-section set Revised structural analysis & mechanical drawings of Model 700 GE shipping cask and
BROOKS, R H Electric Univ of 79/05/02 10pp

DOCKET 71-6018 MODEL ED-1, NUCLEAR ENGINEERING CO

7906105606 Supplement previous report advising that certain shipping casks do not comply with provisions of Certificate of Compliance 6028 Have placed all three casks in out-of-use status until detailed info is made
BAER, T B Nuclear Engineering Co., Inc (subs of Teledyne, Inc.) 79/05/07 2pp

7906200132 Notification that Certificate of Compliance 6028 for Model 62-1 exp-PWR 79023 Requests removal of existing Certificate of Compliance if continued use is desired
HACDONALD, C E Transportation Branch 79/05/16 1p

7906201030 Notifies that Certificate of Compliance 6028 for Model 62-1 expires 791231 Request for continuation as user of certificate must be submitted
MAYLE, V Oak Ridge National Laboratory WILLIAMS, D H Arkansas Power & Light Co OUSON, A F Babcock & Wilcox Co 79/05/16 2pp

DOCKET 71-6244 MODEL 6244, CHEM-NUCLEAR SYSTEMS, INC

7906100785 Requests renewal of Certificate of Compliance 6244, which expires on 790731 Forwards renewal for
REHAG, D L E Chem-Nuclear Systems, Inc 79/05/07 1p

7906200228 Requests registration as user of Model HN-100 Series 1 & 2, HN-100B, HN-200, HN-300, HN-301, Pelic Panther, Half Super Tiger, Super Tiger, HPS-4, HPS-1/2, HS-301, HS-401, HS-401 & HS-402
REHAG, D L E Chem-Nuclear Systems, Inc 79/05/11 1p

DOCKET 71-6272 MODEL POLY PANTHER, TELEPHONE BATTERY SYSTEMS

7906200428 Requests correspondence to PA operations site be addressed to PA Austin instead of RA Williams
AUSTIN, R A Babcock & Wilcox Co 79/05/10 1p

DOCKET 71-6274 MODEL UHC-2701, CONSTRUCTION ENGINEERING, INC

7906200430 Requests correspondence to PA operations site be addressed to PA Austin instead of RA Williams
AUSTIN, R A Babcock & Wilcox Co 79/05/10 1p

DOCKET 71-6379 MODEL PB-1, CHEM-NUCLEAR SYSTEMS, INC

7906100543 Notification that Certificate of Compliance 6375 for Model PB-1 shipping package will expire 790731 Requests submission of consolidated application H/drawings, incorporating all previous submissions so that new certificate can be issued
HACDONALD, C E Transportation Branch 79/05/16 1p

7906200191 modifies Certificate of Compliance 6375 for Model PB-1 expires on 790430 Primary user should submit consolidated application for renewal
HACDONALD, C E Transportation Branch 79/05/17 2pp

7906200507 Requests add info re changes made to Drawing 7103-APB-0001, Revision E in response to 790124 application for amend to Model PB-1 packaging
HACDONALD, C E Transportation Branch 79/05/03 1p

DOCKET 71-6387 MODEL AG, BATELLE MEMORIAL INSTITUTE

7906200438 Requests correspondence to PA operations site be addressed to PA Austin instead of RA Williams
AUSTIN, R A Babcock & Wilcox Co 79/05/16 1p

DOCKETED ITEMS

DOCKET 71-6574 MODEL HM-200, WESTMAN NUCLEAR & DEVELOPMENT CORP

7904103046 Notification of registration as user of Model HM-200, HM-100 Series 2 & HM-100 Series 1 in response to license 790100 request
 MACDONALD, C E Transportation Branch 79/05/14 1p

DOCKET 71-6601 MODEL LL-50-100, CHEM-NUCLEAR SYSTEMS, INC

7904030104 Requests Drawing 1040-B-0001, Revision 5 in order to complete review of request for amendment to Model LL-50-100
 MACDONALD, C E Transportation Branch 79/05/17 1p

DOCKET 71-6639 MODEL HM-1A, ARMY, SEPT OF

7904020100 Notices that amend to Certificate of Compliance 6409, Revision 4 Item 5 (a)(12)(d) not required for proposed change to fuel basket design for shipment of TRIGA fuel assemblies
 MACDONALD, C E Transportation Branch 79/05/17 1p

DOCKET 71-6679 MODEL 1/2 SUPER TIGER, NUCLEAR ENGINEERING CO

7904020100 Requests correspondence to PA operations site be addressed to PA Austin instead of SA Williams
 AUSTIN, M A Babcock & Wilcox Co 79/05/10 1p

DOCKET 71-6690 MODEL MPS-4, NUCLEAR FUEL SERVICES, INC

7904050410 Submits historical info re MAC-1 spent fuel shipment case
 ROLLINS, J B Nuclear Assurance Corp 79/04/12 1p

7904100642 Responds to 790406 show cause order Suspension of license can be lifted for tests for which data has been approved in a timely fashion
 PARKER, M O Duke Power Co 79/04/27 2pp

7904140252 Informs that 790406 LTR was sent on behalf of Duke Power Co
 ROBERTS, J H Delcovalve & Listerland 79/05/02 1p

DOCKET 71-6717 MODEL 6717 B

7904100140 Requests authorization as shipper under same terms & conditions listed in Certificate of Compliance 6717
 ROBERTS, W P Argonne National Laboratory - Argonne West 79/04/10 1p

7904090097 Notification of registration as user of Model 6717-B in response to 790410 request
 MACDONALD, C E Transportation Branch 79/05/14 1p

DOCKET 71-6902 MODEL M-10-CL, BABCOCK & WILCOX CO

7904020430 Requests correspondence to PA operations site be addressed to SA Austin instead of SA Williams
 AUSTIN, M A Babcock & Wilcox Co 79/05/10 1p

DOCKET 71-6909 MODEL PL 40-1, GENERAL ELECTRIC CO

7904020420 Requests correspondence to PA operations site be addressed to SA Austin instead of SA Williams
 AUSTIN, M A Babcock & Wilcox Co 79/05/10 1p

DOCKET 71-6910 MODEL ML-1/2, M. INDUSTRIES, INC

7904050071 Submits info prior to first use of Model ML-1 shipping container
 DIFANZA, M P Hawthorne Electric Corp 79/04/27 1p

7904020041 Forwards Revision 5 of Certificate of Compliance 7010 for shipping package Model ML-1/2
 MACDONALD, C E Transportation Branch 79/05/25 4pp

--7904090009 Certificate of Compliance 7010, Revision 5, for radioactive mail shipping package Model ML-1/2
 MACDONALD, C E Transportation Branch 79/05/25 1p

DOCKET 71-6919 MODEL BU-7, GENERAL ELECTRIC CO

7904060001 Requests registration as user of GE Transportation Package WM 5 & 450
 WREDS, M J United Nuclear Corp 79/04/23 1p

7904100104 Requests registration as user of BU-7 shipping container under license HM-100 All documentation required for container use has been obtained
 ZEPF, E W Babcock & Wilcox Co 79/04/20 1p

DOCKET 71-6920 MODEL CE-250-2, COMBUSTION ENGINEERING CO, INC

7904020420 Requests correspondence to PA operations site be addressed to SA Austin instead of SA Williams
 AUSTIN, M A Babcock & Wilcox Co 79/05/10 1p

DOCKET 71-6933 MODEL 660 & 660C, TECHNICAL OPERATIONS, INC

7904100400 Forwards Certificate of Compliance 9003, Revision 2, for radioactive mail shipping package Model 660 & 660C
 MACDONALD, C E Transportation Branch 79/05/01 4pp

--7904100400 Certificate of Compliance 9003, Revision 2, for radioactive mail shipping package Model 660 & 660C
 MACDONALD, C E Transportation Branch 79/05/01 2pp

DOCKET 71-6944 MODEL GE-1600, GENERAL ELECTRIC CO

7904100470 Notification of registration as user of Model GE-1600 in response to license 790320 request
 MACDONALD, C E Transportation Branch 79/05/14 1p

DOCKET 71-6945 MODEL BU-6, GENERAL ELECTRIC CO

7904020420 Requests correspondence to PA operations site be addressed to SA Austin instead of SA Williams
 AUSTIN, M A Babcock & Wilcox Co 79/05/10 1p

DOCKET 71-6970 MODEL N-55, ENERGY SEPT OF

7904090031 Requests registration as user of Model CHEI 1-5 radioactive mail shipping case
 STRACCA, P P Union Carbide Corp 79/05/16 1p

7904090735 Requests SA program be submitted prior to registration as package user or delivery of licensed mail to carrier for transport
 MACDONALD, C E Transportation Branch 79/05/20 1p

DOCKET 71-6979 MODEL HM-100 SERIES 2, WESTMAN NUCLEAR & DEVELOPMENT

7904020001 Forwards Drawing 0004-9110, Revision 2 & Addendum 1 to SMR, Revision 1, for HM-100 Series 2 Radioactive Shipping Case Six overpacked drawings and
 TRIGLER, A C Westman Nuclear & Development Corp (subs of Hillman Corp) 79/05/09 2pp

--7904020001 Addendum 1 to SMR for HM-100 Series 2 Radioactive Shipping Case Referencing 10CFR71 Type A Packaging Regulations -
 TRIGLER, A C TRIGLER, A C Westman Nuclear & Development Corp (subs of Hillman Corp) 79/05/09 1pp

7904100467 Notification of registration as user of Models HM-200, HM-100 Series 2 & HM-100 Series 1 in response to license 790100 request
 MACDONALD, C E Transportation Branch 79/05/14 1p

DOCKET 71-6980 MODEL HM-100, WESTMAN NUCLEAR & DEVELOPMENT CORP

7904020091 Requests registration as user of Model 36600
 ARNET, R W Ficker Corp 79/05/10 1p

7904100467 Notification of registration as user of Models HM-200, HM-100 Series 2 & HM-100 Series 1 in response to license 790100 request
 MACDONALD, C E Transportation Branch 79/05/14 1p

DOCKETED ITEMS

7904200129 Aile recelak f 790510 ltr re intended use of H9-100 under general license provisions of 10CFR71.12(a) amend to this section requires approved SA program by 790510 Authorization terminated until SA program approved
HACDONALD.C E Transportation Branch 79/05/17 1p

DOCKET 71-7031 MODEL CHS1-1600, CHDH-NUCLEAR SWITCHES, INC

7904240137 Requests registration as user of Model CHS1-1600
GUSTO R Isomedia, Inc tasks of Massfield Enterprises, Inc 1
79/04/14 1p

7904260094 Requests registration as user of Model CHS1-1-12C
CLARK A P Bapost & Wilson Co 79/05/19 1p

DOCKET 71-7004 MODEL H9-100 SERIES 1, HITEMAN NUCLEAR & DEVELOPMENT

7904260497 Notification of registration as user of Models H9-100, H9-100 Series 2 & H9-100 Series 1-12 response to license
790100 request
HACDONALD.C E Transportation Branch 79/05/14 1p

DOCKET 71-9108 MODEL AL-33-90, ATEOR, INC

7904260143 Requests registration as user of CHS1 AL-33-90 radioactive
mail shipping case under License H9-1
MITCHELL B Portland General Electric Co 79/03/29 1p

DOCKET 71-9117 MODEL RC-PR870-1000, ARMY, DEPT OF, DPO, FT BELVOIR

7904260319 Notifies of 790321 expiration of Certificate of Compliance
9117 for Model RC-PR870-1000 Requester submitted of General
Corp "Test Report for One-M Radioisotope Thermoelectric
Generator" & manual for
HACDONALD.C E Transportation Branch 79/04/12 1p

DOCKET 71-9135 MODEL 20, 20A, 30, 30A, GAMMA INDUSTRIES

7904260377 Forwards Revision 1 of Certificate of Compliance 9124 for
shipping package Model 20, 20A, 30 & 30A
* Transportation Branch 79/04/04 1p

--7904260385 Certificate of Compliance 9124, Revision 1, for radioactive
mail shipping package Models 20, 20A, 30 & 30A
HACDONALD.C E Transportation Branch 79/04/04 2pp

--7904260395 Safety evaluation supporting Certificate of Compliance 91
Revisions 1 for radioactive mail shipping package Models
20, 20A, 30 & 30A
HACDONALD.C E Transportation Branch 79/04/04 4pp

DOCKET 71-9129 MODEL C-8, GAMMA INDUSTRIES

7904270014 Forwards Revision 1 of Certificate of Compliance 9128 for
shipping package Model C-8
HACDONALD.C E Transportation Branch 79/04/04 1p

--7904270017 Certificate of Compliance 9128, Revision 1, for radioactive
mail shipping package Model C-8
HACDONALD.C E Transportation Branch 79/04/04 2pp

--7904270020 Safety evaluation supporting Certificate of Compliance 91
Revision 1, for radioactive mail shipping package Model C-8
HACDONALD.C E Transportation Branch 79/04/04 4pp

DOCKET 71-9152 MODEL T-3, NUCLEAR PACKAGING, INC

7904280156 Responds to 790328 ltr re Revision 1 amend to SAR for T-3
Shipping Case Forwards amended pages
SHINDLER, J B Nuclear Packaging, Inc 79/03/18 167pp

DOCKET 71-9156 MODEL H9274A-2, ENERGEX, DEPT OF

7904280307 Responds to 790427 ltr re Model H9 2704-2 shipping package
in Certificate of Compliance 7095 Re plans for add review
of package
REISER, J R Energy Dept of 79/05/07 1p

NONDOCKETED ITEMS

10CFR COMMISSION MEETING RECORDS

7903240121 Expresses concern that concurrent jurisdiction between NRC & State of TX over U mill licensing may adversely affect Chevron U mill Tailings subsidiary Urges adoption of Policy Alternative 1 in NSC-79-08
TURNER, J. S. Chevron Oil Co (subs of Standard Oil Co of California) 79/04/16 2pp

7903240402 Expresses appreciation for 790320 ltr re U Mill Tailings Radiation Control Act of 1970
SIMPSON, H. K. Office of the Executive Legal Director 79/04/17 1p

7903240403 Comments on 790320 memo re timing of certain requirements of U Mill Tailings Radiation Control Act of 1970 Act is subj to interpretation & implementation resulting in 3-yr deferral of mill tailings licensing
LYNCH, S. A. US Steel Corp 79/04/18 3pp

7903250602 Act receipt of 790322 ltr providing views on NRC interpretation & implementation of U Mill Tailings Radiation Control Act of 1970
SIMPSON, H. K. Office of the Executive Legal Director 79/04/17 1p

7903250603 Act receipt of 790327 ltr providing views on NRC interpretation & implementation of U Mill Tailings Radiation Control Act of 1970
SIMPSON, H. K. Office of the Executive Legal Director 79/04/18 1p

7903250601 Act receipt of 790321 ltr providing views on NRC interpretation & implementation of U Mill Tailings Radiation Control Act of 1970
SIMPSON, H. K. Office of the Executive Legal Director 79/04/17 1p

7903250605 Act receipt of 790319 ltr providing views on NRC's interpretation & implementation of U Mill Tailings Radiation Control Act of 1970
SIMPSON, H. K. Office of the Executive Legal Director 79/04/17 1p

7903250608 Act receipt of 790321 ltr providing views on NRC's interpretation & implementation of U Mill Tailings Radiation Control Act of 1970
SIMPSON, H. K. Office of the Executive Legal Director 79/04/17 1p

7904020176 Transcript of 790301 public meeting in Washington, DC re resident isotope program Pg 1-28
HEMERIE, J. M., GILLINRY, V., KENNEDY, R. T. Commission 79/05/01 3pp

7904020225 Transcript of 790311 public meeting & Affirmation Session 79-12 in Washington, DC to discuss NSC-79-11a seeking to amend 10CFR19 & 20 to central radiation exposure to transient workers Pg 1-3
HEMERIE, J. M., GILLINRY, V., KENNEDY, R. T. Commission 79/05/11 4pp

7904020227 NSC-79-11a
Seeks NRC approval to publish amendments to 10CFR19 & 20 re radiation exposure to transient workers Recommends approval Supporting documentation email
HINDOE, R. B. Office of Standards Development 79/01/12 5pp

7904020231 Value/import assessment containing peer justification analysis of amend to regulations to control radiation doses to transient workers Recommends proposed action be taken
S. Office of Standards Development 79/01/12 3pp

7904020234 Recommends paper re amend to 10CFR19 & 20 provide analysis of "no further action" alternative including latest assessment of impact & value
DUNN, S. R. Office of Policy Evaluation 79/11/07 1p

7904040101 Transcript of 790322 public meeting in Washington, DC to discuss NSC-79-08 Pg 1-78
HEMERIE, J. M., GILLINRY, V., KENNEDY, R. T. Commission 79/05/02 7pp

7904070506 Transcript of 790322 public meeting in Washington, DC to discuss NSC-79-08 Pg 1-78
HEMERIE, J. M., GILLINRY, V., KENNEDY, R. T. Commission 79/05/02 7pp

7904070509 Act receipt of 790412 ltr commenting on NRC interpretation & implementation of U Mill Tailings Radiation Control Act of 1970
ENRICH, M. T. Deputy Executive Legal Director 79/04/30 1p

7904070523 Comments on NRC interpretation of U Mill Tailings Radiation Control Act of 1970 State & NRC concurrent licensing jurisdiction is unnecessary
TURNER, J. S. Chevron Industries, Inc., Chevron Resources Co Div 79/04/16 2pp

7904070602 Forwards NRC 790322 determination statement for withholding type of Executive Branch briefing re int'l safety matters ltr encl
GILLIN, S. J. Office of the Secretary of the Commission 79/05/02 2pp

7904070609 Forwards NRC determination statement for withholding transcript of 790322 discussion of personnel matter
GILLIN, S. J. Office of the Secretary of the Commission 79/05/02 2pp

7904100401 Transcript of 790316 public meeting in Washington, DC re hearing on NSC petition for reconsideration Pg 1-67
Affirmation Session 79-12 encl
HEMERIE, J. M., GILLINRY, V., KENNEDY, R. T. Commission 79/05/11 22pp

7904140104 Revision of 790705 petition for rulemaking re decontaminating to require plant operators to post bonds
SCARLETT, W. S., ARDRETT, J. Public Interest Research Group 77/10/07 11pp

7904140107 Transcript of 790322 public meeting in Washington, DC re briefing on interspersed radiological assistance program Pg 1-57 Presentation encl
HEMERIE, J. M., GILLINRY, V., KENNEDY, R. T. Commission 79/05/02 40pp

7904140108 Transcript of 790322 public meeting in Washington, DC re ltr to governors Pg 1-6
HEMERIE, J. M., BRADFORD, P., KENNEDY, R. T. Commission 79/05/02 7pp

7904140109 Transcript of 790327 Affirmation Session 79-11 in Washington, DC Pg 1-6
HEMERIE, J. M., GILLINRY, V., KENNEDY, R. T. Commission 79/05/07 7pp

7904140104 Transcript of 790430 Affirmation Session 79-9 in Washington, DC Pg 1-8
HEMERIE, J. M., GILLINRY, V., KENNEDY, R. T. Commission 79/04/30 8pp

7904140101 Transcript of 790311 public meeting in Washington, DC to discuss & vote on order in NSC rulemaking Pg 1-16
HEMERIE, J. M., GILLINRY, V., BRADFORD, P. Commission 79/05/11 10pp

7904140705 Transcript of 790311 public meeting to discuss NSC regulations NSC-79-05 Pg 1-9
HEMERIE, J. M., GILLINRY, V., KENNEDY, R. T. Commission 79/05/11 10pp

7904140724 Transcript of 790311 public meeting in Washington, DC re briefing on legislative matters (adding to licensing)
Pg 1-32
HEMERIE, J. M., GILLINRY, V., KENNEDY, R. T. Commission 79/05/11 3pp

7904140804 Transcript of 790430 public meeting in Washington, DC to discuss 790329 Dir of General Counsel memo on NSC rulemaking
HEMERIE, J. M., GILLINRY, V., KENNEDY, R. T. Commission 79/04/30 7pp

NONDOCKETED ITEMS

- 790603003 Transcript of 790509 public meeting in Washington, DC re SECY-79-08 & W mill hearings Pt 1-02
HENDERSON, J. H., GILLENKOPF, V., BRADFORD, P. A. Commission 79/05/09
2pp
- 790616005 Transcript of 790517 public meeting re SECY-79-08 & W mill hearings Pt 1-02
HENDERSON, J. H., GILLENKOPF, V., BRADFORD, P. A. Commission 79/05/17
2pp
- 7906200136 Transcript of 790521 public meeting in Washington, DC re licensing schedule & related matters Pt 1-70
GILLENKOPF, V., HENDERSON, J. H., BRADFORD, P. A. Commission 79/05/21
7pp
- 7906260172 Summary of 790528 conference in Washington, DC re presentation of all records relating to THU-2 incident
CHILKOT, S. J. Office of the Secretary of the Commission 79/05/30
1p
- 7906260410 Summary of 790517 meeting w/ACRS in Washington, DC re record retention re THU-2 incident
CHILKOT, S. J. Office of the Secretary of the Commission 79/04/18
1p
- 7906260416 Summary of 790409 briefing in Washington, DC re THU-2 incident sequence of events & current assessment of safety of BN reactors
CHILKOT, S. J. Office of the Secretary of the Commission 79/04/09
1p
- 7906260420 Summary of 790329 meeting in Washington, DC re SECY-79-34A, "Regulation of Federal Radioactive Waste Activities"
CHILKOT, S. J. Office of the Secretary of the Commission 79/04/03
1p
- 7906260428 Summary of 790209 meeting in Washington, DC re SECY-79-134 & SECY-79-144A, "Report to Congress: Means for Improving State Participation in Siting Activities"
CHILKOT, S. J. Office of the Secretary of the Commission 79/04/02
1p
- 7906260434 Summary of 790229 briefing in Washington, DC re THU-2 incident, current plant status & state & federal incident response
CHILKOT, S. J. Office of the Secretary of the Commission 79/03/29
1p
- 7906260447 Summary of 790323 meeting in Washington, DC re application by Edison Int'l Co. for license to export BNW to India
Subsequent value approved license after meeting all relevant requirements
CHILKOT, S. J. Office of the Secretary of the Commission 79/03/23
1p
- 7906260450 Summary of 790322 Affirmation Session 79-7 in Washington, DC re SECY-79-120, SECY-79-121 & SECY-79-140 AEC approved amendment of proposed rulemaking
CHILKOT, S. J. Office of the Secretary of the Commission 79/03/23
2pp
- 7906260454 Summary of 790322 meeting in Washington, DC re SECY-79-36A, "Regulation of Federal Radioactive Waste Activities"
CHILKOT, S. J. Office of the Secretary of the Commission 79/03/23
1p
- 7906260162 Summary of 790527 conference in Washington, DC re State of NE - NRC decision 3744 approved extending S-3 interim rule to 790320
CHILKOT, S. J. Office of the Secretary of the Commission 79/05/28
1p
- 7906260197 Summary of 790524 conference in Washington, DC re 1928 Nix nuclear accident
CHILKOT, S. J. Office of the Secretary of the Commission 79/05/29
1p
- 7906260314 Summary of 790528 discussion in Washington, DC re NRC approval to preserve all THU-2 records Add'l order requested for records prior to 790209 re similar plant events
CHILKOT, S. J. Office of the Secretary of the Commission 79/05/30
1p
- 7906260318 Summary of 790528 discussion in Washington, DC re NRC approval to preserve all THU-2 records Add'l order requested for records prior to 790209 re similar plant events
CHILKOT, S. J. Office of the Secretary of the Commission 79/05/29
1p
- 7906260384 Summary of 790529 discussion in Washington, DC re SECY-79-026 & SECY-79-028A concerning physical protection of irradiated fuel shipments
CHILKOT, S. J. Office of the Secretary of the Commission 79/05/29
2pp
- 7906260397 Summary of 790521 discussion in Washington, DC re formulation of SFC of Nuclear Reactor Regulation interim organization to deal w/THU-2 impacts
CHILKOT, S. J. Office of the Secretary of the Commission 79/05/26
2pp
- 7906260406 Summary of 790517 meeting in Washington, DC re SECY-79-08 & W mill billings Legislation to clarify matter will be requested by NRC
CHILKOT, S. J. Office of the Secretary of the Commission 79/05/23
2pp
- 7906260215 Summary of NRC 790517 briefing in Washington, DC re interim operational sequence of events of THU-2 incident
Order requested Requiring involved parties to keep records
CHILKOT, S. J. Office of the Secretary of the Commission 79/05/25
1p
- 7906260219 Summary of 790517 hearing in Washington, DC re NRC staff petition for reconsideration
CHILKOT, S. J. Office of the Secretary of the Commission 79/05/16
1p
- 7906260223 Summary of 790511 meeting in Washington, DC re S-3 rule & statement of considerations No vote was completed Interim rule extended until 790525
CHILKOT, S. J. Office of the Secretary of the Commission 79/05/11
1p
- 7906260243 Summary of 790511 Affirmation Session 79-12 in Washington, DC re approval of SECY-79-014 amended (SFR) 17 & 20 re central radiation exposure to transient workers
CHILKOT, S. J. Office of the Secretary of the Commission 79/05/14
2pp
- 7906260254 Summary of 790511 briefing in Washington, DC re siting & licensing Requested amendments to be prepared by General Counsel re licensing sections of regulatory reform packages submitted to Congress
CHILKOT, S. J. Office of the Secretary of the Commission 79/05/16
2pp
- 7906260261 Summary of 790511 meeting in Washington, DC re NEPA regulations Approved revision of proposed rule to CEQ re conditions for NRC compliance w/NEPA regulations.
CHILKOT, S. J. Office of the Secretary of the Commission 79/05/14
1p
- 7906260264 Summary of 790520 briefing in Washington, DC re siting & planned NRC actions on THU-2 incident
CHILKOT, S. J. Office of the Secretary of the Commission 79/05/14
1p
- 7906260274 Summary of 790509 briefing in Washington, DC re SECY-79-08 & NRC options on certain provisions of W MHI Tailings Radiation Control Act of 1978.
CHILKOT, S. J. Office of the Secretary of the Commission 79/05/11
1p

NONDOCKETED ITEMS

263

790606277 Summary of 790508 discussion in Washington, DC re letter to Governors Approved proposed site re governance of states
offered nuclear facilities re emergency radiological
planning
CHILM, S. J. Office of the Secretary of the Commission 79/05/18
lp

790606280 Summary of 790508 briefing in Washington, DC re objectives &
management of laboratory radiological assistance program
response to TMI-2 incident
CHILM, S. J. Office of the Secretary of the Commission 79/05/04
lp

790606303 Summary of 790508 meeting in Washington, DC re revisions to
draft PB notice announcing promulgation of final fuel cycle
B-3 rule
CHILM, S. J. Office of the Secretary of the Commission 79/05/04
lp

790606310 Summary of 790508 briefing in Washington, DC re offsite
radiological levels at TMI-2 identification requested of
potential contractors to perform monitoring
CHILM, S. J. Office of the Secretary of the Commission 79/05/07
lp

790606311 Summary of 790508 discussion in Washington, DC re
changes to draft PB notice announcing promulgation of final
fuel cycle B-3 rule
CHILM, S. J. Office of the Secretary of the Commission 79/05/04
lp

790606338 Summary of 790508 briefing in Washington, DC re steam
generator denting & replacement Special attention given to
problems at Burrehead no action taken
CHILM, S. J. Office of the Secretary of the Commission 79/05/09
lp

790606343 Summary of 790508 briefing in Washington, DC re resident
inspector program Performance appraisal & projected FY80
cost analysis requested
CHILM, S. J. Office of the Secretary of the Commission 79/05/08
lp

790606350 Summary of 790430 meeting in Washington, DC re extension of
interim fuel cycle rule MDG voted to extend rule through
790515
CHILM, S. J. Office of the Secretary of the Commission 79/05/05
lp

790606357 Summary of 790430 affirmation session in Washington, DC re
appointment of JH Torr to part-time position on ASLB
Group on full-time position on ASLB
CHILM, S. J. Office of the Secretary of the Commission 79/05/02
lp

790606366 Summary of 790426 continuing briefing in Washington, DC re
state emergency preparedness activities for nuclear plant
accidents
CHILM, S. J. Office of the Secretary of the Commission 79/04/30
lp

790606371 Summary of 790426 briefing in Washington, DC re status of
plants shut down 790515 to permit seismic reanalysis of
piping systems
CHILM, S. J. Office of the Secretary of the Commission 79/05/03
lp

790606374 Summary of 790426 briefing by Study Group on Coast in
Washington, DC re funding of proposal for gathering of views
of participants in ASLB cases
CHILM, S. J. Office of the Secretary of the Commission 79/05/07
lp

790606381 Summary of 790426 briefing by Off of State Programs in
Washington, DC re current emergency preparedness programs
CHILM, S. J. Office of the Secretary of the Commission 79/04/30
lp

790606386 Summary of 790426 briefing w/US, EMB & Duke Power Co in
Washington, DC re status of operating BSW reactors
CHILM, S. J. Office of the Secretary of the Commission 79/04/27
lp

790606397 Summary of 790426 briefing in Washington, DC re current
status of operating BSW reactors
CHILM, S. J. Office of the Secretary of the Commission 79/04/27
lp

790606407 Summary of 790420 briefing in Washington, DC re procedures
for qualifying reactor operators
CHILM, S. J. Office of the Secretary of the Commission 79/04/20
2pp

790606408 Summary of 790419 Affirmation Session 79-B in Washington, DC
re Kansas PDA Appeal 79-A-3 18000-79-007 re appointment of
H. Lewis to ASRB Renshaw appeal denied
CHILM, S. J. Office of the Secretary of the Commission 79/04/28
2pp

790606409 Summary of 790419 briefing in Washington, DC re NRC
activities involving gathering & analyzing data significant
operational safety
CHILM, S. J. Office of the Secretary of the Commission 79/05/04
lp

790606418 Summary of 790418 meeting in Washington, DC re updating
requirements for physical protection systems for fuel cycle
facilities
CHILM, S. J. Office of the Secretary of the Commission 79/05/01
lp

ASRB ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

790606422 Notice of ASRB Subcommittee on Consideration of Class 9
Accidents 790408 meeting w/consultants & NRC in Washington,
DC to discuss role of Class 9 accidents in licensing
process
HYNES, J. C. ASRB - Advisory Committee on Reactor Safeguards 79/03/14
2pp

790606419 Transcript of ASRB Subcommittee on Safeguards & Security
790325 meeting in Washington, DC re 1-87
ETSG-C P. HYNES, J. C. ASRB - Advisory Committee on
Reactor Safeguards 79/05/23 14pp

7906150482 Summaries responses to IE Bulletin 79-06A, "Review of
Operational Errors & Site Misalignments Identified During TMI
Incident"
TAM, F. ASRB - Advisory Committee on Reactor Safeguards 79/05/07
10pp

7906150503 Summaries responses to IE Bulletin 79-06, "Events Relevant
to Belling Water Power Reactors Identified During TMI
Incident"
TAM, F. ASRB - Advisory Committee on Reactor Safeguards 79/05/09
8pp

7906060186 Summaries responses to IE Bulletin 79-06B Operating manuals
are being scrutinized Operational personnel are being
trained Radiactive gases & liquids transfer lines are
interlocked w/containment isolation &/or radiation signals.
TAM, F. Division of Risk Safety & Environmental Analysis 79/05/08
2pp

7906060505 Recommendations given by NRC re establishment of
quantitative safety goals for nuclear power reactors.
CARSON, H. W. ASRB - Advisory Committee on Reactor Safeguards 79/05/16
1p

7906060474 Summary of 790104-08 meeting w/NRC in Washington, DC re NRC
safety research program evaluation of seismic design
requirements by ASLB request for review of LER &
testimony on seismicity App and
CARSON, H. W. FLORES, M. D. EBERHARDT, H. W. ASRB - Advisory Committee
on Reactor Safeguards 79/04/12 25pp

7906060482 Transcript of 790426 ASRB subcommittee meeting in
Washington, DC re reliability & probabilistic assessment
CURRENT, D. HARRIS, C. ASRB - Advisory Committee on Reactor
Safeguards 79/05/02 25pp

7906060547 Summary of 790327 meeting w/ASRB Subcommittee on Reactor
Safety Research in Washington, DC re preparation of 1979 Rept
to Congress on NRC safety research
CURRENT, D. EBERHARDT, H. W. LAMONTAGNE, W. ASRB - Advisory Committee on
Reactor Safeguards 79/04/08 11pp

7906060570 Summary of LER Subcommittee 790307 meeting in Washington, DC
re ASRB review of LERs for 1979-78
& ASRB - Advisory Committee on Reactor Safeguards 79/02/07 2pp

7906060602 Comments on NRC licensing review of structural conditions in
vicinity of plant Site does not seem to have active
faulting
PHILLIPS, E. W. Affiliation Unknown 79/04/29 1p

7906060627 Notices of willingness to assist Reliability Subcommittee
of LER Evaluation Program re SCED valve failure rate
analysis
BETHKE, D. Pennsylvania State Univ 79/04/02 1p.

7904270003 Forwards comments on analysis of adequacy of reactor pressure vessel nozzle safe replacement. Concerns w/NSC decision regarding resumption of operations. Cannot make determination on allegations of falsifying info.
RUBIN, E. H. Battelle Memorial Institute, Pacific Northwest Laboratory
79/04/17 3pp

7904270002 Summary of 790411-12 Denver workshop re recent phenomena.
CATTONE, I. ACRS - Advisory Committee on Reactor Safeguards.
79/05/01 3pp

7904270003 Comments on recent ACRS meeting presentation lacked organization, thoroughness & visual aids.
ALLISON, R. T. Battelle Memorial Institute, Pacific Northwest Laboratory
79/04/05 2pp

7904270005 Forwards suggested review of Upper Bys Code for LIPRES. Much of work is being done in duplicate. Suggests more attention be given to natural convection phenomena in low Prandtl number fluids.
CATTONE, I. California Univ. of Los Angeles
79/03/23 2pp

7904290023 Summary of ACRS Subcommittee on WH Emer Nuclear Power Station, Unit 1 790327 meeting w/USDOE, ERM, Commerce, Reactor & Secher & Am Federal in Washington, DC re WHI application for SL.
ACRS - Advisory Committee on Reactor Safeguards 79/03/28 50pp.

7904290173 Summary of ACRS Subcommittee on Regulatory Activities 790405 meeting in Washington, DC re proposed reg guide-revisions to existing reg guides & other matters pertinent to activities affecting licensing process.
ACRS - Advisory Committee on Reactor Safeguards 79/02/05 20pp

7904290175 Summary of ACRS Subcommittee on ECOS 790316 meeting in Washington, DC re issues related to ECOS.
ACRS - Advisory Committee on Reactor Safeguards 79/03/27 20pp

7904290647 Transcript of ACRS subcommittee meeting on reactor operations - power level increase P-1-255.
STEWARTSON, H. H. ACRS - Advisory Committee on Reactor Safeguards 79/04/13 23pp

7904290643 Transcript of ACRS subcommittee 790412 meeting in Washington, DC re reactor fuel. P-1-255.
STEWARTSON, H. H. ACRS - Advisory Committee on Reactor Safeguards 79/04/12 150pp

7904290653 Transcript of ACRS subcommittee 790411 meeting in Washington, DC re reactor fuel. P-1-255.
STEWARTSON, H. H. ACRS - Advisory Committee on Reactor Safeguards 79/04/11 23pp

7904290727 Summary of 790324 meeting w/NSC, BSC & Secher in Washington, DC re review of proposed reg guides & revisions to existing reg guides.
ACRS - Advisory Committee on Reactor Safeguards 79/04/04 21pp

7904290745 Forwards memo on ACRS ECOS Subcommittee 790319-20 meeting in Los Angeles, CA.
HAY, T. California Institute of Technology
79/04/20 3pp

7904290811 Minutes of 790304 meeting re committee 790417 recommendations, topics arising from TMS accident procedures for handling SL & SD reissues, license for Research & add postulated scenarios.
ACRS - Advisory Committee on Reactor Safeguards 79/03/10 1p

7904290813 Summary of 790328 visit to Sherman site re methods of support for transportation and vents.
CATTONE, I. California Univ. of Los Angeles
79/04/20 1p

COMMISSIONER NRC COMMISSIONERS

7904290865 Forwards reg on number of full-time permanent employees hired & promoted by NRC during first quarter FY79 Sept submitted per Energy Reorganization Act of 1974, Title II.
HEMBRE, J. M. Commission 79/03/19 4pp.

7904290865 Comments on H.R. 2 & H.R. 65 (Sunset Bill).
HEMBRE, J. M. Commission 79/03/19 1p

7904290952 Inform of completion of NRC assessment of progress in support of Congressional directed initiatives. Requests approval of initiatives in NRC FY79 Budget.
HEMBRE, J. M. Commission 79/04/26 18pp.

7904290943 Requests to 790129 ltr of concern re 790328 transportation accident near Hanford. TN Requests NRC investigation under existing regulations, neither NRC nor DOT is responsible for prescribing specific routes w/supporting documentation.
HEMBRE, J. M. Commission 79/03/07 7pp

7904290945 Forwards revised memo of understanding between NRC & DOE re safety regulation in transportation of radioactive materials.
DURBIN, W. J. Office of Nuclear Material Safety & Safeguards
79/03/02 13pp

7904290939 Weekly info report for week ending 790504.
RENN, T. A. Office of the Executive Director for Operations
79/05/09 25pp

7904290944 Comments on recent meeting re China. Will forward comments of speech after careful study.
RENN, T. A. Commission 79/04/04 1p

7904290947 Confirms withdrawal from participation in Hanford, Germany conference due to time demands of TMS incident.
RENN, T. A. Commission 79/04/23 1p

7904290970 Forwards RT Kennedy 790328 speech in Washington, DC re act.
RENN, T. A. Commission 79/05/13 1p

7904290974 Forwards RT Kennedy 790328 speech in Tucson, AZ & 790320 speech in Washington, DC w/ re act.
RENN, T. A. Commission 79/05/13 1p

7904290976 Request of likelihood to attend & participate in seminar on energy & non security.
RENN, T. A. Commission 79/05/14 1p

7904290982 Forwards RT Kennedy 790314 memo re DOE-79-020, technology transfer to Brazil.
RENN, T. A. Commission 79/05/15 1p

7904290984 Comments on DOE-79-020 re technology transfer to Brazil questions statutory & factual basis for NRC statement that transfer is not consistent w/NEPA/NEPA/NEPA policy re West Germany/France joint nuclear plant.
RENN, T. A. Commission 79/05/16 2pp

7904290986 Act receipt of photo of life & test site.
RENN, T. A. Commission 79/03/28 1p

7904290988 Requests 1980 conference be held at Doubletree Inn, Rockville, MD.
RENN, T. A. Commission 79/03/31 1p

7904290992 Act receipt of "Strategic Options for Early EO's." by Van Cleave & Thompson.
RENN, T. A. Commission 79/04/02 1p

7904290993 Requests views on various questions re pending license applications covering reports destined for Taiwan.
RENN, T. A. Commission 79/04/02 1p

7904290995 Act receipt of monograph on non security affairs of Mexico on Spanish Coast, Iran & Comp.
RENN, T. A. Commission 79/04/04 1p

7904290997 Accepts invitation to attend 790427 seminar at Army/Naval Club.
RENN, T. A. Commission 79/04/04 1p

7904291002 Act receipt of update on successful use trials of USB.
RENN, T. A. Commission 79/04/09 1p

7904291004 Regrets inability to meet w/ J Hill during recent visit to US.
RENN, T. A. Commission 79/04/18 1p

7904291007 Act receipt of 790501 info which reviewed records of 790328.
RENN, T. A. Commission 79/05/11 1p

7904291010 Comments on RT Kennedy's remarks of 790328.
RENN, T. A. Commission 79/05/09 1p

7904291027 Comments decision to close several nuclear power plants.
RENN, T. A. Commission 79/05/06 1p

NONDOCKETED ITEMS

256

7904070029 Expresses congratulations for honor received for work on deaggregation
MEMORIE, R. T. Commission 7/6/05/10 1p

7904070030 Receipt of inability to attend Adelphi Univ Conference on Energy & Environment
MEMORIE, R. T. Commission 7/6/04/24 1p

7904070034 Ack receipt of info re Natl Library Info Ctr work on R&D
MEMORIE, R. T. Commission 7/6/05/03 1p

7904070037 Commands action taken re closing of nuclear reactor
MEMORIE, R. T. Commission 7/6/05/10 1p

790410000 Ack receipt of 790413 ltr re radiation exposure of nuclear plant workers
MEMORIE, R. T. Commission 7/6/05/18 3pp

790410009 Forwards R. Hader & R. Hader 790413 ltr re radiation exposure of nuclear plant workers
MEMORIE, R. T. Commission 7/6/05/18 3pp

790410013 RDCY-78-418
NRC 1977 Annual Report on Occupational Radiation Exposure
MEMORIE, R. T. Commission 7/6/05/18 3pp

790410014 Forwards NRC response to GAO report EHS-79-16, "Reporting Unscheduled Events at Commercial Nuclear Facilities
MEMORIE, R. T. Commission 7/6/05/13 1p

790410023 Forwards NRC response to GAO report EHS-79-16, "Reporting Unscheduled Events at Commercial Nuclear Facilities
MEMORIE, R. T. Commission 7/6/05/13 1p

790410032 Forwards NRC response to GAO report EHS-79-16, "Reporting Unscheduled Events at Commercial Nuclear Facilities
MEMORIE, R. T. Commission 7/6/05/13 1p

790410033 Forwards NRC response to GAO report EHS-79-16, "Reporting Unscheduled Events at Commercial Nuclear Facilities
MEMORIE, R. T. Commission 7/6/05/13 1p

790410034 Forwards NRC response to GAO report EHS-79-16, "Reporting Unscheduled Events at Commercial Nuclear Facilities
MEMORIE, R. T. Commission 7/6/05/13 1p

790410035 Forwards NRC response to GAO report EHS-79-16, "Reporting Unscheduled Events at Commercial Nuclear Facilities
MEMORIE, R. T. Commission 7/6/05/13 1p

790410036 Forwards NRC response to GAO report EHS-79-16, "Reporting Unscheduled Events at Commercial Nuclear Facilities
MEMORIE, R. T. Commission 7/6/05/13 1p

790400003 Weekly info report for week ending 7/6/05/11
MEMORIE, R. T. Commission 7/6/05/16 30pp

7904270107 Requests support for legislation re effective date provision of U. S. Nuclear Regulatory Commission Act of 1970
MEMORIE, R. T. Commission 7/6/05/03 8pp

7904270114 Requests support for legislation re effective date provision of U. S. Nuclear Regulatory Commission Act of 1970
MEMORIE, R. T. Commission 7/6/05/03 1p

7904270123 Requests support for legislation re effective date provision of U. S. Nuclear Regulatory Commission Act of 1970
MEMORIE, R. T. Commission 7/6/05/03 1p

7904270124 Requests support for legislation re effective date provision of U. S. Nuclear Regulatory Commission Act of 1970
MEMORIE, R. T. Commission 7/6/05/03 1p

7904270133 Requests support for legislation re effective date provision of U. S. Nuclear Regulatory Commission Act of 1970
MEMORIE, R. T. Commission 7/6/05/03 1p

7904270144 Submits correction to 790509 testimony before Subcommittee on Energy, Nuclear Proliferation & Federal
MEMORIE, R. T. Commission 7/6/05/03 2pp

7904270150 Ack receipt of 790516 request for certain vaccine documents & reporting was used internally by NRC
MEMORIE, R. T. Commission 7/6/05/21 1p

7904270157 Requests regular receipt of certain routine documents & reporting was used internally by NRC
MEMORIE, R. T. Commission 7/6/05/16 1p

7904270163 Ack receipt of 790516 ltr re transportation of waste matter
MEMORIE, R. T. Commission 7/6/05/25 2p

7904270164 Requests detailed report outlining exact requirements of NRC in transportation of nuclear wastes & report outlining
MEMORIE, R. T. Commission 7/6/05/16 3pp

7904270173 MEMO-0170-01
MEMORIE, R. T. Commission 7/6/05/13 150pp

7904270177 MEMO-0170-02
MEMORIE, R. T. Commission 7/6/05/13 220pp

7904270184 Responds to 790320 ltr re physical security & safeguard measures for handling shipments of highly enriched U
MEMORIE, R. T. Commission 7/6/05/23 24pp

7904270189 Responds add'l & updated info re physical security & safeguard measures for handling shipments of highly enriched U
MEMORIE, R. T. Commission 7/6/05/23 24pp

7904270193 Responds to questions in 760910 ltr re applicability of Price-Anderson Act to proposed waste isolation pilot plant
MEMORIE, R. T. Commission 7/6/05/25 7pp

7904270194 Requests NRC opinion on applicability of Price-Anderson Act to proposed waste isolation pilot plant under various operating conditions
MEMORIE, R. T. Commission 7/6/05/25 7pp

7904270207 Responds to 790320 ltr which forwarded J. H. Jones 790321 ltr. Commission on limited appearance statements at public hearing conducted by NRC in Salem County, NJ re licensing of nuclear waste storage facility
MEMORIE, R. T. Commission 7/6/05/23 2pp

7904270208 Forwards J. H. Jones 790321 ltr concerning on manner in which public hearing was conducted by NRC in Salem County, NJ
MEMORIE, R. T. Commission 7/6/05/23 2pp

7904270209 Responds to 790320 ltr re use of synthetic aperture radar in locating potential pump plant sites. NRC has not used such techniques but does use others such as infrared film taken from aircraft platforms & multispectral images
MEMORIE, R. T. Commission 7/6/05/23 1p

NONDOCKETED ITEMS

--7904020084 Requests info re use of synthetic aperture radar in locating potential sites for nuclear power plants
DECONCENT. D Senate 79/03/30 1p

CONTRACT NRC CONTRACTS AND MODIFICATIONS

7904020159 Notification of contract execution, Mod 1, to "Add Logistical Support for Stanislaus Nuclear Project Unit 1, Stanislaus Hearings." Contractor ROL
W05108, H. J. Division of Contracts NRC-10-78-604 79/05/09 1p

--7904020172 Mod 1, including transportation charges for items to be delivered under "Add Logistical Support for Stanislaus Nuclear Project Unit 1, Stanislaus Hearings." Contractor ROL
W05108, H. J. Division of Contracts NRC-10-78-604 79/04/11 1p

7904020201 Notification of contract execution, Mod 2, to "Analysis of Hypothetical Accidents Resulting in Core Meltdown" Contractor Battelle Columbus Labs
W05108, H. J. Division of Contracts NRC-10-78-604 79/04/11 1p

--7904020202 Mod 2, adding funded period of performance to "Analysis of Hypothetical Accidents Resulting in Core Meltdown" Contractor Battelle Columbus Labs
W05108, H. J. Division of Contracts NRC-10-78-604 79/04/17 2pp

7904020349 Notification of contract execution, Mod 2 to "FOR Micrographic Storage & Retrieval Sys." Contractor AGOOD
DECONCENT. D Administrative Contracts Branch NRC-10-78-604 79/05/02 1p

--7904020352 Mod 2, extending term of contract & delaying original installation date by 30 days to "FOR Micrographic Storage & Retrieval Sys." Contractor AGOOD
DECONCENT. D Administrative Contracts Branch NRC-10-78-604 79/04/09 3pp

7904020372 Notification of contract execution, "Sys Maint Programming," awarded to SSA-prime contractor & Rehab Group, Inc. subcontractor
W05108, H. J. Administrative Contracts Branch NRC-10-78-604 79/05/01 1p

--7904020376 Contract "Sys Maint Programming," awarded to SSA-prime contractor & Rehab Group, Inc. subcontractor
W05108, H. J. Administrative Contracts Branch NRC-10-78-604 79/04/02 1app

7904020378 Notification of contract execution, "Transcription of TMS Tapes," awarded to Heel & Gross & Co. Inc.
W05108, H. J. Administrative Contracts Branch NRC-10-78-604 79/03/17 1p

--7904020504 Contract, "Transcription of TMS Tapes," awarded to Heel & Gross & Co. Inc.
W05108, H. J. Administrative Contracts Branch NRC-10-78-604 79/05/18 50pp

7904020586 Notification of contract execution, Mod 6, to "Operation & Maint of Technical Assignment & Control Sys (TACS)" Contractor Defense Corp.
W05108, H. J. Administrative Contracts Branch NRC-10-78-604 79/05/15 1p

--7904020591 Mod 6, increasing estimated hours & calling amount to "Operation & Maint of Technical Assignment & Control Sys (TACS)" Contractor Defense Corp.
W05108, H. J. Administrative Contracts Branch NRC-10-78-604 79/05/15 2pp

7904020136 Notification of contract execution, "Survey Instruments," awarded to Eberline Instrument Corp.
W05108, H. J. Administrative Contracts Branch NRC-10-78-604 79/04/06 1p

--7904020208 Contract "Survey Instruments," awarded to Eberline Instrument Corp.
W05108, H. J. Division of Contracts, FIN 8-1215 NRC-10-78-604 79/04/06 25pp

7904020123 Notification of contract execution, Mod 7, to "Consultant Svc in Connection W/Anthrax Hearing," Contractor CH2M
W05108, H. J. Technical Assistance Contracts Branch, FIN 8-1002, AT149-241-0326, 79/03/29 1p

--7904020123 Mod 7, clearing ext contract for "Consultant Svc in Connection W/Anthrax Hearing," Contractor CH2M
W05108, H. J. Technical Assistance Contracts Branch, FIN 8-1002, AT149-241-0326 79/05/04 1p

7904020132 Notification of contract execution, Mod 1, to "Implementation & Operation of NRC Document Control Sys." Contractor TERA
W05108, H. J. Administrative Contracts Branch NRC-10-78-604 79/04/28 1p

--7904020133 Mod 1, providing add equip & performance requirements & administrative changes to "Implementation & Operation of NRC Document Control Sys." Contractor TERA
W05108, H. J. Administrative Contracts Branch NRC-10-78-604 79/05/29 2pp

7904020132 Notification of contract execution, "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt." awarded to AGA Ltd.
W05108, H. J. Technical Assistance Contracts Branch NRC-10-78-604 79/05/02 1p

--7904020135 Contract "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt." awarded to AGA Ltd.
W05108, H. J. Technical Assistance Contracts Branch NRC-10-78-604 79/05/02 15pp

7904020139 Notification of contract execution, Mod 10, to "Document Distribution - Contractor Computer Data Sys. Inc." Contractor TERA
W05108, H. J. Administrative Contracts Branch NRC-10-78-604 79/04/05 1p

--7904020168 Mod 10, changing contractor name from Electronic Composition, Inc. to Computer Data Sys. Inc. to "Document Distribution" Contractor TERA
W05108, H. J. Administrative Contracts Branch NRC-10-78-604 79/04/09 1p

7904020168 Notification of contract execution, Mod 2, to "Electrostatic Copying Sys." Contractor Literature Research Co.
W05108, H. J. Administrative Contracts Branch NRC-10-78-604 79/05/01 1p

--7904020168 Mod 2, increasing funding to "Electrostatic Copying Sys." Contractor Literature Research Co.
W05108, H. J. Administrative Contracts Branch NRC-10-78-604 79/05/01 1p

7904020171 Notification of contract execution, "Expansion of Reliability Data Manual," awarded to IEEE
W05108, H. J. Research Contracts Branch, FIN 8-6708, NRC-10-78-604 79/05/08 1p

--7904020171 Contract "Expansion of Reliability Data Manual," awarded to IEEE
W05108, H. J. Research Contracts Branch, FIN 8-6708, NRC-10-78-604 79/03/08 1pp

7904020207 Notification of contract execution, "Cataloging Support Svc." awarded to Informatic, Inc.
W05108, H. J. Administrative Contracts Branch NRC-10-78-604 79/05/02 1p

--7904020208 Contract "Cataloging Support Svc." awarded to Informatic, Inc.
W05108, H. J. Division of Contracts, NRC-10-78-604 79/04/24 3pp

7904020232 Notification of contract execution, Mod 4, to "Technical Assistance/Defendants Suppl to GEHRC," awarded to Lulejian & Associates, Inc.
W05108, H. J. Technical Assistance Contracts Branch, FIN 8-1527, AT149-241-0326, 79/03/22 1p

--7904020232 Mod 4, decreasing amount obligated to "Technical Assistance/Defendants Suppl to GEHRC," awarded to Lulejian & Associates, Inc.
W05108, H. J. Division of Contracts, FIN 8-1527, AT149-241-0326, 79/03/22 1p

7904020232 Notification of contract execution, "Verification of Eason Technique for Stability Calculations," awarded to Nuclear Associates, Inc.
W05108, H. J. Technical Assistance Contracts Branch, FIN 8-6005, NRC-10-78-604 79/05/01 1p

NONDOCKETED ITEMS

257

- 7906160040 Contract "Verification of Exxon Technique for Stability Calculation" awarded to Nuclear Associates Inc.
DOUGHERTY, S. J. Division of Contracts NRC-03-79-130 79/05/01 4pp
- 7906180348 Notification of contract execution, Mod 3 to "Haggenbach & Verification" awarded to Nuclear Associates Inc.
WIGGINS, E. Administrative Contracts Branch NRC-10-79-071 NRC-10-79-071 79/05/02 1p
- 7906180349 Mod 3, extending period of performance to "Haggenbach & Verification" awarded to Nuclear Associates Inc.
MATTIA, H. J. Division of Contracts NRC-10-79-071 79/04/26 4pp
- 7906180382 Notification of contract execution, "Implementation of Executive Development Program" awarded to Project Associates, Inc.
PERLMAN, J. Purchasing Section NRC-10-79-348 79/05/07 1p
- 7906180508 Contract "Implementation of Executive Development Program," awarded to Project Associates, Inc.
MORSETT, D. J. Division of Contracts NRC-10-79-348 79/05/09 4pp
- 7906180624 Forward "Electrical & Instrumentation Technology & Codes Training Program" Progress Rept 12 for Mar 1979
WILSON, R. F. General Services, Inc. (subs. of Enersys Corp.) NRC-05-79-361 79/04/26 1p
- 7906180432 "Electrical & Instrumentation Technology & Codes Training Program," Progress Rept 12 for Mar 1979
General Services, Inc. (subs. of Enersys Corp.) NRC-05-79-361 79/06/12 2pp
- 7906180581 Notification of contract execution, Mod 1 to "Sys Maint Programming" Contractor Intl Business Buss. Inc.
MORSETT, D. J. Administrative Contracts Branch NRC-10-79-372 79/04/26 1p
- 7906180890 Mod 1, defining ceiling loaded rates to "Sys Maint Programming" awarded to Intl Business Buss. Inc.
MORSETT, D. J. Division of Contracts NRC-10-79-372 NRC-10-79-372 79/04/20 2pp
- 7906180597 Notification of contract execution, Mod 1 to "Radioactive Heat Transportation" Contractor Univ. of Denver
MORSETT, D. J. Administrative Contracts Branch NRC-06-79-361 NRC-06-79-361 79/04/09 1p
- 7906180666 Mod 1, extending period of performance to "Radioactive Heat Transportation" awarded to Univ. of Denver
MORSETT, D. J. Division of Contracts NRC-06-79-361 NRC-06-79-361 79/04/13 4pp
- 7906180708 Notification of contract execution, "Transfer of Multi-Channel Tapes to 30-Minute Cassette," awarded to Biophase Corp.
MATTIA, H. J. Administrative Contracts Branch NRC-10-79-348 79/05/01 1p
- 7906180744 Contract "Transfer of Multi-Channel Tapes to 30-Minute Cassette," awarded to Biophase Corp.
MATTIA, H. J. Administrative Contracts Branch NRC-10-79-348 79/05/01 10pp
- 7906180791 Corrected notification of contract execution: "Transfer of Multi-Channel Tapes to 30-Minute Cassette," awarded to Biophase Corp.
MATTIA, H. J. Administrative Contracts Branch NRC-10-79-348 79/05/01 1p
- 7906180178 Notification of contract execution, "Basic Ordering Agreement to Develop Regulatory Framework for Nuclear Waste Mgt.," awarded to Southwest Research Inst.
LEBO, C. O. Technical Assistance Contracts Branch NRC-02-77-201-46 NRC-02-77-201-46 79/05/17 1p
- 7906180181 Contract "Basic Ordering Agreement to Develop Regulatory Framework for Nuclear Waste Mgt.," awarded to Southwest Research Inst.
DOUGHERTY, S. J. Division of Contracts NRC-02-77-201-46 79/05/17 10pp
- 7906200325 Notification of contract execution: "Implementation of ATNH Recommendations on Site Plant Design," awarded to H. G. Galey.
PERLMAN, J. Purchasing Section NRC-03-79-144 79/05/17 1p
- 7906200306 Contract "Implementation of ATNH Recommendations on Site Plant Design," awarded to H. G. Galey.
DOUGHERTY, S. J. Division of Contracts NRC-03-79-144 79/05/17 2pp
- 7906200327 Notification of contract execution, "Design of Integrated Financial Mgt Info Sys.," awarded to Shell Business Administration.
HARRIS, T. F. Administrative Contracts Branch NRC-09-79-349 79/05/17 1p
- 7906200340 Contract "Design of Integrated Financial Mgt Info Sys.," awarded to Shell Business Administration.
HARRIS, T. F. Administrative Contracts Branch NRC-09-79-349 79/05/17 1pp
- 7906200123 Notification of contract execution, Mod 1 to "Assessment of Mill Tailings Improvement Diversion Ditches & Flood Protection" Contractor Hahn & Enviro Consultants, Inc.
PERLMAN, J. Purchasing Section NRC-02-79-031 79/05/17 1p
- 7906200120 Mod 1, extending period of performance to "Assessment of Mill Tailings Improvement Diversion Ditches & Flood Protection" awarded to Hahn & Enviro Consultants, Inc.
HARRIS, T. F. Division of Contracts NRC-02-79-031 79/05/02 1p
- 7906200135 Notification of contract execution, "Review of Slip Rate Versus Magnitude Study," awarded to D. Blumenthal.
PERLMAN, J. Purchasing Section NRC-03-79-146 79/05/17 1p
- 7906200140 Contract "Review of Slip Rate Versus Magnitude Study," awarded to D. Blumenthal.
HARRIS, T. F. Division of Contracts NRC-03-79-146 79/05/17 2pp
- 7906200106 Notification of contract execution, Mod 4 to "FWR Vortex Technology" Contractor Univ. of IA.
HARRIS, T. F. Technical Assistance Contracts Branch NRC-03-79-130 79/05/04 1p
- 7906200087 Mod 4, extending contract two months at no add cost & changing reporting requirements to allow for incorporation of new economic info. Final report to "FWR Vortex Technology" awarded to Univ. of IA.
DOUGHERTY, S. J. Division of Contracts NRC-03-79-130 79/05/24 1p
- 7906200192 Notification of contract execution, Mod 7 to "Sys/Project Maint Programming" Contractor Shell Business Administration/Contractor Hahn Group, Inc.
HARRIS, T. F. Administrative Contracts Branch NRC-10-79-348 NRC-10-79-348 79/05/14 1p
- 7906200192 Mod 7, increasing ceiling price & amount obligated for performance of "Sys/Project Maint Programming" awarded to Hahn Group, Inc.
HARRIS, T. F. Division of Contracts NRC-10-79-348 NRC-10-79-348 79/03/30 2pp
- 7906200105 Notification of contract execution, "Course on Preconditioning Interim Operating Mgt Recommendations (INCONE)/Process Computer Software Feasibility Study," awarded to GE.
PERLMAN, J. Purchasing Section NRC-03-79-260 79/07/01 1p

- 790601019 FOIA request by USC for all documents re Test Action Plans 4-A2 & 4-A3 info on seismic issues prepared for systematic evaluation program & snap reports for Beaver Valley units
WEISSER R Skelton, Harman & Reisman 79/03/19 2pp
- 790601018 FOIA request by USC for all documents re Test Action Plans 4-A2 & 4-A3 info on seismic issues prepared for systematic evaluation program & snap reports for Beaver Valley units
WEISSER R Skelton, Harman & Reisman 79/03/19 2pp
- 790601018 FOIA request by USC for all documents re Test Action Plans 4-A2 & 4-A3 info on seismic issues prepared for systematic evaluation program & snap reports for Beaver Valley units
WEISSER R Skelton, Harman & Reisman 79/03/19 2pp
- 790601021 Responds to 790519 FOIA request re seismic issues BECV-79-561 "Systematic Evaluation of Operating Reactors, Phase I & II," is now available in FDR
FELTON J M Division of Rules and Records 79/03/17 1p
- 790601023 BECV-79-561
Advance Phase I of systematic evaluation program to obtain approval to proceed w/Phase II of plant-specific review
Recommends NRC approve continuation of program plan
GAGE E G Office of Nuclear Reactor Regulation 77/03/26 47pp
- 790601027 Provides guidance on systematic evaluation program for operating reactors NRC approves objectives & general approach of program described in BECV-79-561
CHICK K J Office of the Secretary of the Commission 79/01/23 2pp
- 790601019 BECV-79-561
Advance continuation of plans to convert provisional OX to full-term licenses
GAGE E G Office of Nuclear Reactor Regulation 77/05/14 5pp
- 790601024 Responds to FOIA request re equipment mentioned in 790502
1st NRC has no records relevant
FELTON J M Division of Rules and Records 79/03/11 1p
- 790601024 FOIA request for info re equipment TH-1-A212-230-10-5
NRC-DM Model GE 405-A/E E/D
OELILOU J Affiliation Unknown 79/05/02 2p
- 790601023 Responds to 790507 FOIA request Provides final award amounts of Hs Signal & George Washington Univ Contract NRC-01-70-318
NRC-01-70-318
FELTON J M Division of Rules and Records 79/03/18 1p
- 790601029 FOIA request for info re final award amounts of Hs Signal & George Washington Univ Contract NRC-01-70-318 & availability of final reports on these programs
PARAZOSOM L Kinetic Research, Inc 79/03/07 1p
- 790601023 Responds to 790417 FOIA request for copy of winning proposal for Contract NRC-79-037 info partially withheld
Identification of consultants & qualifications (ref FOIA Exemption 4)
FELTON J M Division of Rules and Records 79/03/18 1p
- 790601025 Responds to 791219 FOIA request re E/row Intl expert of USG to India Four documents in FDR info partially withheld:
"Area Control & Sismogram Agency Swift Disposition of Bomb Terrorist Plot/Storage Abroad US-Quoted Vessel"
FELTON J M Division of Rules and Records 79/03/11 2pp
- 790601027 FOIA request for copy of winning technical proposal for Contract NRC-92-79-037, "Study of ALARA for Radiochemical Manufacturing"
RAGAN K N Kinetic Research, Inc 79/04/17 1p
- 790601028 Responds to FOIA request for I Bone 780407 presentation "Hazard to Persons Exposed to Ionizing Radiation (& to Their Children) from Disasters Currently Permitted by NRC."
FELTON J M Division of Rules and Records 79/03/20 2pp
- 790601028 "Hazard to Persons Exposed to Ionizing Radiation (& to Their Children) from Disasters Currently Permitted by NRC."
received for 780407 presentation to NRC
BROOKS D J Russell Park Memorial Inst. 79/04/07 2pp
- 790601028 FOIA request for I Bone (Hansel Memorial Inst) Apr 1980 report on radiation of persons exposed to "Tritium-Helium Survey"
LANNING R Affiliation Unknown 79/04/27 1p
- 790601028 Responds to FOIA request for info on S-1 accident & investigation Forwards & Manager 790510 memo to G Thorne
FELTON J M Division of Rules and Records 79/04/26 1pp
- 790601020 Comments re industrial reactor sabotage internal plant security should be strengthened
JENNINGS D H Atomic Energy Commission (Pne 1975) 71/09/10 1p
- 790601027 Responds to 790712 1st re review of past AC-TOP-6 on seismic analysis of nuclear plant structures & equipment
Submits chronological summary of basic seismic analysis requirements & structural design criteria
HARRIS J H Atomic Energy Commission, Deputy Director for Technical Review (Pne-1975) 73/08/04 22pp
- 790601029 Discusses justification for & implementation of recent regulatory positions on seismic analysis of Category 1 structures & components
SMITH L Atomic Energy Commission, Directorate of Licensing (Pne-1975) 79/03/03 5pp
- 790601029 "Development of Criteria For Seismic Review of Selected Nuclear Power Plants"
KORHONEN H W, HALL W J M H Hume Consulting Engineering Services AT149-241-0116 77/09/20 36pp
- 790601020 Proposes that NRC request opinions of AEGIS as safety problems resulting from incorrect ASR pipe stress calculations
GILMAYER V Commission 79/03/12 1p
- 790601020 Confirms 790313 conversation emphasizing desire to be kept properly informed on matters of regulatory concern
KORHONEN R T Commission 79/03/12 1p
- 790601021 Requests info re plant seismic-induced piping stress code compliance w/NRC safety requirements during OX issuance
KORHONEN R T Commission 79/03/14 1p
- 790601017 Forwards requests for PDR re NRC 790313 discussion of seismic design problems in certain plants
CORRIS E R Public Document Branch 79/03/15 4pp
- 790601020 Forwards responses to 790214 memo from RF Kennedy & BJ Chilly re plant seismic-induced piping stress evaluation
During OX application review MINT Kennedy 790314 memo to L/O District
KORHONEN R T Office of Nuclear Reactor Regulation 79/03/13 2pp
- 790601022 Requests info re NRC consideration of plant-specific piping gaps in terms of past & present NRC safety requirements & NRC decision to apply recent findings on seismic basis
KORHONEN R T Commission 79/03/16 1p
- 790601020 Ack receipt of 790313 memo re understanding that said Commissioner is to be promptly advised of any matter of imminent regulatory concern
GROSSMAN L V Office of the Executive Director for Operations 79/03/20 1p
- 790601024 Expresses gratitude for 790320 briefing re seismic design files compliance of three staffers
GILMAYER V Commission 79/03/20 1p
- 790601026 Discusses 790201 conversations w/congressional staff re past events affected by ASR pipe stress calculations
KORHONEN R T Office of Nuclear Reactor Regulation 79/03/21 1p
- 790601025 Discusses 790900 congressional hearing re ASR calculational error & associated shutdown of five nuclear plants
GILMAYER V Commission 79/03/20 2pp
- 790601028 Forwards proposed statement setting forth NRC guidance on FOIA requests which concern the info partially withheld statement (ref FOIA Exemption 5)
SHEPHERD L Office of the General Counsel 79/04/20 1p
- 790601029 Summary of 790403 press conference held by G McBoevers & US Forwards McBoevers' statements & press release
KORHONEN R T Office of Congressional Affairs 79/04/12 3pp
- 790601023 Provides NRC employee radiation exposure history for 690407-780703 info partially withheld name Social Security number & date of birth (ref FOIA Exemption 4)
JONES E E, George, Dept of, 79/04/09 2pp
- 790601027 Forwards Fleischaker 790420 FOIA request for documents obtained through civil investigative demand re will proposed to construct Medicine project
OELILOU J R Anti-Trust Division 79/05/04 1p

NONDOCKETED ITEMS

259

- 7904070040 Provides LNL employee radiation exposure history for 790402-790328 info partially withheld name Social Security number & date of birth (ref FOIA Exemption 4)
JONES, B. E. Energy Dept. of 79/04/09 App
- 7904070056 Response to FOIA request for all documents re promulgation & possible future revisions of Reg Guide 1.3, Revision 2 & 3 Reg Guide 1.4, Revision 2, both dtd Jun 1974
FELTON, J. H. Division of Rules and Records 79/03/15 App
- 7904070075 Response proposed revision to Reg Guides 1.3 & 1.4 re procedure to use 150-ran thyroid & 20-ran whole body dose during CP review
HINDS, R. B. Atomic Energy Commission (Pfr 1975) 74/02/22 App
- 7904070080 Response proposed revision to Reg Guide 1.3, Revision 2, Reg Guide 1.4, Revision 2 re assumptions used for evaluating potential radiological consequences of LDC for 30rps
BURNH, H. A. Atomic Energy Commission (Pfr 1975) 74/02/27 App
- 7904070100 Comments on proposed revision to Reg Guide 1.3 recommends factor of 1.5 be used for short-term events such as accident analysis
HINDS, R. B. General Electric Co 791-521-74 79/04/02 App
- 7904070108 Comments on proposed revisions to Reg Guides 1.3 & 1.4 to be considered as 30rps Reg Guide Subcommittee 790410 meeting no technical road exists for proposed revisions & no insured benefits will result
W. Duke Power Co 79/04/08 App
- 7904070123 Response drafts of proposed Revision 2 to Reg Guide 1.3 & Revision 2 to Reg Guide 1.4
HINDS, R. B. Atomic Energy Commission (Pfr 1975) 74/04/19 App
- 7904070128 Response issuance of eight new reg guides outlining positions developed by AEC on acceptable solutions to safety issues
HINDS, R. B. Atomic Energy Commission (Pfr 1975) 74/05/01 App
- 7904070130 Discusses status of eight reg guides transmitted to R Mattson from G. A. Roberts in 740501 memo Reg Guide 1.3, Revision 2 & Reg Guide 1.4, Revision 2 re being forwarded for further review
HINDS, R. B. Atomic Energy Commission (Pfr 1975) 74/05/14 App
- 7904070132 Discusses Revision 2 to Reg Guides 1.3 & 1.4 re use of 150-ran thyroid & 20-ran whole body dose during CP review Requests review schedule for proposed reg guide revisions
HINDS, R. B. Atomic Energy Commission (Pfr 1975) 74/05/18 App
- 7904070138 Response proposed Revision 2 to Reg Guides 1.3 & 1.4 re acceptable procedures for using 150-ran thyroid & 20-ran whole body dose during CP review MWR draft public announcement
HINDS, R. B. Atomic Energy Commission (Pfr 1975) 74/06/18 App
- 7904070147 Requests AEC re-evaluation of positions re Reg Guides 1.3 & 1.4 re use of reg guides w/holdals & conditions consistent w/actual physical phenomena
HINDS, R. B. General Electric Co, Nuclear Energy Products Div 74/07/29 App
- 7904070178 Comments on Reg Guide 1.3, Revision 2, "Assumptions Used for Evaluating Potential Radiological Consequences of LDC for 30rps"
HINDS, R. B. Consumers Power Co, HAN-75-74 74/07/03 App
- 7904070188 Requests initiation of change actions to revise Reg Guides 1.3 & 1.4 to more completely reflect recommended practices for LDC radiological analysis Forward draft guide indicating desired changes
HINDS, R. B. Office of Nuclear Reactor Regulation, 79/07/13 App
- 7904070195 Requests review of draft BECH-78-11A, "Accident Evaluation Practices in siting & licensing of Nuclear Power Plants - Major Issues"
HINDS, R. B. Division of Siting, Health & Safeguards Standards 79/09/28 App
- 7904070209 Summarizes major issues & alternative approaches in current accident evaluation practices in siting & licensing of nuclear power plants
HINDS, R. B. Office of Standards Development, 70/09/21 10pp
- 7904070234 Requests delay in completion of draft BECH-78-11A until first draft of proposed revision to "General Public Statement on Nuclear Power Reactor Site Regulation."
HINDS, R. B. has been completed
HINDS, R. B. Division of Site Safety & Environmental Analysis 79/10/27 App
- 7904070340 "Assumptions Used for Evaluating Light Water Cooled Nuclear Power Plant Siting Distances for Purposes of 100rps 1.3 & 1.4" Office of Standards Development 79/03/21 10pp
- 7904070348 "Assumptions Used for Evaluating Potential Radiological Consequences in Public from Design Basis Accidents in Light Water Cooled Nuclear Power Plants for Purposes of 100rps 1.3 & 1.4" Values/Impact Statement and Office of Standards Development 79/03/21 10pp
- 7904070375 FOIA request for all documents re promulgation & possible future revisions of Reg Guide 1.3, Revision 2 & 3 Reg Guide 1.4, Revision 2, both dtd Jun 1974 Requests waiver of all fees
FELTON, J. H. Affiliation Unknown 74/03/28 App
- 7904070385 Response to 790417 FOIA request for nonproprietary portion of Basic Ordering Agreement NSC-03-78-101, awarded to Sage-Barrett & Associates
FELTON, J. H. Division of Rules and Records 79/03/11 App
- 7904070416 Draft of FOIA request for TR Gibson 790314 memo to Commissioner Bradford re oil requirements resulting from shutdown of five nuclear plants & Thompson 790315 memo to Bradford requesting info on TR incident
FELTON, J. H. Division of Rules and Records 79/05/20 App
- 7904070422 FOIA request for all info & records re 790313 decision to shut down five nuclear plants Requests waiver of any production fees associated w/request
FELTON, J. H. New England Regional Energy Project 79/03/23 App
- 7904070428 Response to 790503 FOIA request Forward DWD-77-1371, "Spent Fuel Heatup Following Loss of Water During Storage."
W. Duke Power Co
FELTON, J. H. Division of Rules and Records 79/03/15 App
- 7904070430 FOIA request for DWD-77-1371, "Spent Fuel Heatup Following Loss of Water During Storage" dtd June 1978
W. Duke Power Co & HINDS, R. B. Others Mobilizing for Survival 79/05/03 App
- 7904070432 Response to FOIA request for licensing qualifications Tests, written answers & scores of reactor operators licensed for nuclear facilities are available as PDF
FELTON, J. H. Division of Rules and Records 79/05/22 App
- 7904070433 Response licensing qualifications of all facilities' personnel levels given & results for all plant operators
HINDS, R. B. The Wall Street Journal 79/04/16 App
- 7904070437 FOIA request for copy of Basic Ordering Agreement NSC-03-78-101, "Technical Assistance for Fire Protection Program Review & Evaluation" awarded to Sage-Barrett & Associates
HINDS, R. B. Sage-Barrett & Associates, Inc. 79/04/17 App
- 7904070456 Response 790402 memo on test group for generic implications of reactor transients in BAO-designed reactors
HINDS, R. B. Office of Nuclear Reactor Regulation 79/04/02 App
- 7904070477 "Effects of Weathering on Impregnated Charcoal Performance" UCRL-78-8 Mon. Dept. of Naval Research Laboratory 79/03/31 20pp
- 7904070537 Technical data on SA16P-100 radiolysis cartridge for total iodine (2.5-inch diameter by inch deep)
HINDS, R. B. Science Applications, Inc 79/05/06 App
- 7904070546 Notification of 790505 meeting in Bethesda, MD w/owners of all operating Washington-designed plants to discuss activities of them in IE Bulletin 79-06A & 79-06B, Revision 1
HINDS, R. B. Standardization Branch, 79/05/29 App
- 7904070556 AEC daily staff notes for 790517
HINDS, R. B. Office of the Executive Director for Operations, 79/05/18 App
- 7904070588 Summarizes responses to IE Bulletin 79-06B, Operating manuals are being scrutinized Operational personnel are being trained, Radioactive gases & liquids transfer lines are interlocked w/unattended isolation/hard radiation signals.
HINDS, R. B. Division of Site Safety & Environmental Analysis 79/05/08 App

79030201645 Forwards IE Bulletin 79-01, "Environ Qualification of Class IE Equipment." w/draft transmittal letter for 7903020
depleting M/let of 11 systematic evaluation program
plants for which no action is required
H02LEY, L. N. Office of Inspection & Enforcement 79/02/04 2pp

7903040199 Forwards IE Circular 79-04, "Failure to Use Springs & Bottle
Series in Nuclear Medicine." & list of licensees
* Region 5, San Francisco. Office of the Director 79/04/19
7pp.

790510048 IE Bulletin 79-10, "Regualization Training Program
Qualifies." *
* Office of Inspection & Enforcement 79/05/11 7pp

7906060193 IE Info Notice 79-10, "Nonconforming Pipe Support Struts." *
* Office of Inspection & Enforcement 79/06/16 3pp

7906060198 IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation
Support Problem." *
* Office of Inspection & Enforcement 79/06/07 2pp

7906060161 IE Info Notice 79-12, "Attempted Damage to New Fuel
Accessories." *
* Office of Inspection & Enforcement 79/06/10, 2pp

7906060164 IE Info Notice 79-12, "Indication of Low Water Level in
Copper Creek Reactor." *
* Office of Inspection & Enforcement 79/06/29 11pp

7906060168 IE Bulletin 79-11, "Faulty Overcurrent Trip Device in
Circuit Breakers for Engineered Safety Sys." *
* Office of Inspection & Enforcement, 79/05/22 App

7906060168 IE Bulletin 79-12, "Short Period Scrums at SWR Facilities." *
* IE Circular 79-07 and
* Office of Inspection & Enforcement, 79/06/01 8pp

7906060172 IE Circular 79-06, "Attempted Restoration - Low Enriched U"
Landed Summary of SC Wilmington Incident." *
* Office of Inspection & Enforcement 79/06/18 7pp

7906060214 IE Info Notice 79-14, "Safety Classification of Electrical
Cable Support Sys." *
* E020L020, K. V. Office of Inspection & Enforcement 79/06/11 2pp

7906070030 IE Info Notice 79-17, "Source Holder Assembly Damage From
Misfit Between Assembly & Reactor Upper Grid Plate." *
* D'02ILL, J. P. Office of Inspection & Enforcement 79/06/20 App

7906070032 IE Bulletin 79-03, Revision 1, "Pipe Support Base Plate
Design Using Concrete Expansion Anchor Bolts." *
* SEYFRIE, K. V. Office of Inspection & Enforcement 79/06/21 11pp

7906070037 IE Circular 79-04, "Occurrence of Bell or Punctured
Regulator Diaphragm in Certain Self-Contained Breathing
Apparatus." *
* SEYFRIE, K. V. Office of Inspection & Enforcement 79/06/22, App

NUREC NUREC REPORTS AND RELATED CORRESPONDENCE

79030201496 NUREC-0336
Surf Book 2 Status Summary Rept-Advanced Reactor Safety
Research, date as of 790322
* Office of Nuclear Reactor Regulation 79/02/27, 80pp

7903030202 Notifies that NRC has completed review of environ sketches
as presented in 790303 1st Summary of NRC responsibilities
under various environ statutes and
DEPT/ENR, K. R. Office of Nuclear Reactor Regulation, 79/03/14 10pp.

7903030386 Requests participation in Task Force on Environ Statutes, to
review compliance w/ existing regulations Request for info
& cooperation and
* J02000, C. G. Interier, Dept of 79/11/16 12pp

7903030443 Forwards NUREC-0335, "Environ SWP For Environ Review of
CP Applications for Nuclear Power Plants." *
* Office of Nuclear Reactor Regulation, NUREC-0335, 79/03/21,
39/03/21, 1p.

7903030449 NUREC-0335
NUREC-0335, "Environ SWP For Environ Review of CP
Applications for Nuclear Power Plants." *
* Office of Nuclear Reactor Regulation, NUREC-0335, 79/03/21,
80pp. Available at NTIS.

7903030355 NUREC-0320 V3 V4
Gray Book Operating Units Status Rept, date as of 790320
* Commission 79/04/03 103pp

7906010214 NUREC-0376
White Book Fire Protection Action-Status Summary Rept.
Revision 1
* Commission 79/05/02 26pp

7906010337 Research Info Ltr 29 results of initial series of three
incore experiments on combustibility limits of post-accident
particulate LWR fuel debris in sodium pool Forwards
NUREC/CR-0263 & NUREC/CR-0421
LEVINE, E. Office of Nuclear Reactor Regulation Research 79/05/10 7pp

7906010337 Research Info Ltr 29 results of initial series of three
incore experiments on combustibility limits of post-accident
particulate LWR fuel debris in sodium pool Forwards
NUREC/CR-0263 & NUREC/CR-0421
LEVINE, E. Office of Nuclear Reactor Regulation Research 79/05/10 7pp

7906010344 NUREC/CR-0263
"Debris Bed Studies & Experiments at Sandia Labs." *
* RIVARD, J. B. Sandia Laboratories, P.O. Box 1680 SANDIA-CR-79
79/07/01 35pp Available at NTIS

7906010351 NUREC/CR-0421
"Post-Accident Heat Removal Debris Bed Experiments D-2 &
D-3." *
* RIVARD, J. B. Sandia Laboratories, P.O. Box 1680 SANDIA-CR-79
79/11/02 6pp Available at NTIS

7906030094 NUREC-0482
"Occupational Radiation Exposure at Light Water Cooled Power
Reactors." Annual Rept for 1977.
* RIVARD, J. B. Office of Management and Program Analysis 79/03/31
90pp Available at NTIS

7906030097 NUREC/CR-0230
"Manifestations of Nonlinearity in Fuel Ckr Thermocouple
Steady State & Transient State Implications for Data
Analysis." *
* LARSEN, S. O., & MILLER, R. E. Bettelle Memorial
Institute, Pacific Northwest Laboratory, P.O. Box 2073 PNL-2592
79/01/31 10pp Available at NTIS

7906030102 NUREC/CR-0779
"Superficial Investigation of Aerosol Behavior in
Post-LWR Accident Reactor Containment Atmosphere." *
* USER/ENR, J. B. M. D. T. New York, State Univ. of Buffalo, P.O. Box
2074 79/04/20 45pp Available at NTIS

7906030103 NUREC/CR-0434 V2
"Radiation Dose to Control Workers at Operating Nuclear Power
Plant Sites." Vol 2, App A-F
* USER/ENR, J. B. M. D. T. Bettelle Memorial Institute, Pacific
Northwest Laboratory, P.O. Box 2073 PNL-2773 79/12/31 200pp
Available at NTIS

7906030143 NUREC-0348
"Selection & Training of ASLS Panel Members, Rept to
Congress." *
* Commission 79/04/30 241pp. Available at NTIS

7906030148 NUREC/CR-0638
"Mathematical Simulation of Sediment & Contaminant Transport
in Surface Waters." Annual Rept, Oct 1977-Sept 1978
* USER/ENR, J. B. M. D. T. Bettelle Memorial Institute,
Pacific Northwest Laboratory, P.O. Box 2073 PNL-2932 79/01/31,
32pp Available at NTIS.

7906030149 NUREC/CR-0793
"Building Criteria & Application of Criteria to Design of
Steel Containment Shell." Final Rept, Jan 1978-Mar 1978
* USER/ENR, J. B. M. D. T. Bettelle Memorial Institute,
Pacific Northwest Laboratory, P.O. Box 2073 PNL-2932 79/01/31,
32pp Available at NTIS.

7906030220 NUREC-78/087 13, 1, 2
SWP, Revision 1 to Section 13, 1, 2, "Review of Safety Analysis
Rept for Nuclear Power Plants." *
* Office of Nuclear Reactor Regulation, 79/04/20, 8pp.

7906030244 NUREC/CR-0769
"Analysis of Aerosol Particles Undergoing Gravitationsl
Accretion." Annual Rept, Oct 1977-Sept 1978
* USER/ENR, J. B. M. D. T. Bettelle Memorial Institute,
Pacific Northwest Laboratory, P.O. Box 2073 PNL-2932 79/01/31,
32pp Available at NTIS.

7906050048 Requests for request for NUREG-0465, "Transportation Security Personnel Training Manual." Vols 1-3. Vol 1-2 may be purchased from NTIS
JONES, R J Safeguards Standards Branch 79/04/04 2pp

--7906050049 Requests NUREG-0465, "Transportation Security Personnel Training Manual." Vols 1-3
NELSON, H D Nuclear Vets 79/03/29 1p

7906050056 NUREG/CR-0394
"PSAP-82 Computer Code For Steady State Analysis of Oxide Fuel Rods." model assessment part
COLLEMAN, D R ; LAUTS, E T ; SCOTT, L D R ED & G. Inc FIN A-0046
TREE-1355 79/04/30 70pp Available at NTIS

7906050058 NUREG/CR-0004
"Bed-Baffle Thermal-Hydraulic Analysis Using Boundary-Fitted Coordinate Sys."
CHU, W T ; HEDGECOCK, J F Argonne National Laboratory FIN A-0045
AML-79-1 79/05/31 45pp Available at NTIS

7906050059 NUREG/CR-0739
"Quarterly Technical Progress Report on Water Reactor Safety Program Sponsored by NRC Div of Reactor Safety Research."
Jan-Mar 1979
WARRIOR, D J ED & G. Inc FIN A-0041 TREE-1299 79/04/30 80pp Available at NTIS

7906050134 NUREG/CR-0510
"Surface Heat Flux Perturbations in DHT Fuel Pin Simulators"
OTT, L J ; CHILDS, K H Oak Ridge National Laboratory FIN B-0125
ORNL/NUREG-54 79/04/30 122pp Available at NTIS

7906050141 NUREG/CR-0697
"Leak Rate Tests on PC-1 Pu Product Can Sealed by Welding."
Final rept. Sept 1978-Jan 1979
GILBERT, J D ; PETTIGREW, R E NRC International NRC-DO-70-076
79/05/31 20pp Available at NTIS

7906050200 NUREG/CR-0947
"LAR Safety Research Program." quarterly progress rept.
Jul-Aug 1978
RACHE, R S ; MYERS, J A Argonne National Laboratory FIN A-0014
AML-79-167 79/01/31 8pp Available at NTIS

7906050204 Requests to WA Spradley 790413 ltr to JH Hendrix re safety of nuclear power plants. Forwarded to B. Sullivan 79-03 & 79-054. NRC Annual Rept 1978. NUREG-0094 & NUREG-79/111
NUREG-79/007 will answer other questions. ltr encl
REYNOLDS, R C Division of Site Safety & Environmental Analysis
79/05/01 2pp

--7906050221 Requests info on safety programs for input or criticism of State of OR review of nuclear reactor safety. Relevant info from state of OR encl
REYNOLDS, R A OR, State of. 79/04/13 4pp

7906050284 NUREG/CR-0644
"Neutrotechnical Analysis of Soil Samples From Test Trench at Hanford RF Nuclear Res. Chalk Valley, OR."
FICHTER, R H ; FROST, H. R. New York, State of FIN B-0208
NY02579-2401 79/04/30 27pp Available at NTIS 4 RD

7906050323 NUREG-0036 V3 N3
"Program Summary Rept."
Office of Management and Program Analysis 79/05/18 101pp
Available at NTIS

7906050377 NUREG-071A
on One Critical Reactor Safety Studies" quarterly

7906100710 NUREG/CR-0489
"Handbook for Prediction of Strong Earthquake Ground Motion."
Southern California Univ of FIN D-0677 79/02/31 240pp
Available at NTIS

7906100717 NUREG/CR-0483
"Statistical Methods For Evaluating Sequential Fuel Balance Data."
WILSON, H A ; STEWART, E R ; PIERCE, S F Battelle Memorial Institute,
Pacific Northwest Laboratory FIN B-02149 FW-0920 79/05/30
170pp Available at NTIS

7906100722 NUREG-0525
"Reagents Summary Event List (SSEL)."
SAULSON, J J Division of Safeguards 79/03/31 114pp Available at NTIS

7906100732 NUREG-0246
"Fuel Supply Increased Cost Coal & Nuclear."
United Engineers & Constructors, Inc 1984 of Raytheon Co 1
RSC-26-70-351 CSD-2477-10 79/04/30 300pp Available at NTIS

7906100742 NUREG/CR-0301
"LWR Pressure Vessel Irradiation Surveillance Dosimetry."
quarterly progress rept. Jul-Sept 1978
GUTHRIE, G L ; KELLEY, H H ; LIPKOWITZ, E F Stanford Engineering
Development Laboratory FIN B-0385-7 NTL-ONE 79-8 79/03/31
230pp Available at NTIS

7906100744 NUREG/CR-0710
"SW Steady State Capability of SWAP-CH Sys."
GRIFF, O A Savannah River Ecology Laboratory FIN B-0126-B
GRIFF-NUREG-78-1 79/04/30 78pp Available at NTIS

7906100757 NUREG/CR-0823
"New Universal Harmonics Solutions of Neutron Transport Problems."
BLUMBERG, R M ; LEIDIG, E Northwestern Univ FIN A-0079
79/05/31 10pp Available at NTIS

7906100762 NUREG/CR-0713
"BAR LCCA Analysis Capability of MWAP-CH Sys."
BOYNER, H R ; EICHENBERG, R R ; SHEDDEN, H R Savannah River Ecology
Laboratory FIN B-0126-B GRIFF-NUREG-78-2 79/04/30 44pp
Available at NTIS

7906100765 NUREG-0330
"BER Related to Operation of PWR, Group 2."
Office of Nuclear Reactor Regulation 648 79/03/31 150pp
Available at NTIS

7906100770 NUREG/CR-0114
"User's Guide for BAR LCCA Analysis Capability of MWAP-CH Sys."
EICHENBERG, R R ; GRIFF, H R ; NEED, R L Savannah River Ecology
Laboratory FIN B-0126-B GRIFF-NUREG-78-3 79/04/30 200pp
Available at NTIS

7906100774 NUREG/CR-0728
"Physical Protection of Nuclear Fuel In-Transit." quarterly
progress rept. Jan-Mar 1979
GRIFF, O A ; GRIFF, H R ; GRIFF, H R FIN A-1060 BW079-0651
79/04/30 130pp Available at NTIS

7906100779 NUREG/CR-0820
"Critical Experiments, Measurements and Analyses to Establish
Crack Arrest Methodology for Nuclear Pressure Vessels."
quarterly rept. Jan-Mar 1979
WILSON, H A ; GRIFF, H R ; GRIFF, H R ; GRIFF, H R Battelle Memorial Institute,
Pacific Northwest Laboratory FIN A-0046 BK1-0020 79/05/31 240pp
Available at NTIS

7906100804 NUREG/CR-0750
"Criticality Experiments W/Unsubcritical Clusters of 2 SS WE & 4 SF WE U-235 Enriched U Oxide Rods in Water w/o Leaf Refueling Wells."
COLLEMAN, D R ; BURST, E H ; CLAYTON, E D Battelle Memorial Institute,
Pacific Northwest Laboratory FIN B-0094 FW-0827 79/04/30
80pp Available at NTIS

7906100808 NUREG/CR-0478
"Analysis of Fuel & Heat Transfer Processes of U Oxide
Bubbles in Sodium For Fast Aerosol Simulant Test (FAST)."
TOSLAND, M L Oak Ridge National Laboratory FIN B-0121
ORNL/NUREG/IN-3 79/05/31 49pp Available at NTIS

7906100825 NUREG/CR-0684
"Critical Experiments, Measurements and Analyses to Establish
Crack Arrest Methodology for Nuclear Pressure Vessels."
quarterly rept. Apr-Jun 1978
WILSON, H A ; GRIFF, H R ; GRIFF, H R ; GRIFF, H R Battelle Memorial Institute,
Pacific Northwest Laboratory FIN A-0046 BK1-0020 79/05/31 80pp
Available at NTIS 6.00

790420365 NUREG/CR-0039
"Advanced Reactor Safety Research," quarterly rept. Jan-Mar 1979
GATTS, L. E. WALKER, J. V. Sandia Laboratories, PM
A-1016 SAND79-1421 79/01/31 194pp Available at NTIS

790420376 NUREG/CR-0038
"Review Group Meeting on Two-Phase Flow Instrumentation,"
rept. at 790313-14 meeting at Researcher Polytechnic Inst.
Troy, NY
WALL, V. Office of Nuclear Reactor Regulation 79/04/30 480pp
Available at NTIS

790420311 Forwarded from NUREG/CR-0421, "Post-Accident Heat Removal
Systems - See Experiments 8-2 & 8-3." (SAND79-1339)
SILVER, J. E. Sandia Laboratories 79/04/05 22pp

790420312 Forwarded add comments as NUREG-0396 to be added to notebook
of comments forwarded 790405
COLLINS, H. E. Assistant Director for Emergency Preparedness
79/02/13 1p

790420320 Ack receipt of ltr requesting return of 790330 comments on
NRC/NRA task force rept on emergency planning. All comments
received have been placed in FDR
COLLINS, H. E. Assistant Director for Emergency Preparedness EPA
391-170-01 79/04/27 1p

790420324 Request return of comments as NUREG-0396 as note can be
made in light of TMI developments
MANNING, A. Commonwealth Edison Co 79/04/02 1p

7904203136 Comments on NUREG-0396 question validity of technical data
dealing w/densities, probabilities & distances info
presented & conclusions reached place undue emphasis on
unrealistic worst-case scenarios
BOULETTO, J. A. Southern California Edison Co 79/04/08 2pp

7904203130 Comments on NUREG-0396 guidance predominantly general in
nature & subj to diverse interpretation. Need to develop
consistent federal guidance on emergency planning & uniform
federal policy for emergency plan review
ANDERSON, H. New York, State 79/03/23 3pp

7904203139 Comments on NUREG-0396 endorses concept of emergency
planning using Plant to identify state & local plans in
reflecting NUREG-0396 concepts as soon as final adoption of
repts
MCLELLAND, R. J. Washington, State of 79/05/08 1p

7904203141 Comments on NUREG-0396 considers info provided of value in
emergency planning program. Response need to separate
siting criteria from emergency planning. Prudent to
re-evaluate analyses performed per WASH-1400
REIDEN, H. Michigan, State of 79/04/17 3pp

7904203142 Comments on NUREG-0396 basis for planning recommendations
to incorporate many NUREG-0396 recommendations are beyond
scope of licensing considerations.
WRIGHT, R. E. Florida Power & Light Co L-79-95 79/04/16 2pp

7904203144 Comments on NUREG-0396 agrees w/principles developed in
document. Questions adequacy of 10-mile radius for
emergency planning zone
WOMERSLEY, Kentucky, State of 79/03/09 1p

7904203146 Further comments on NUREG-0396 in light of TMI incident
rept does not consider possibility or consequences of
explosion similar to that transpiring. TMI Recommended
planning distances for molten salt adequate
JONES, O. L. Virginia, State of 79/04/30 2pp

7904203147 Comments on NUREG-0396. TMI incident demonstrates need &
importance of detailed hazard analysis of each plant
nuclear facility. Risk Analysis should be beyond generalized
linear definition of emergency planning zones
HENDERSON, C. K. Pennsylvania, State of 79/03/10 1p

7904203150 Comments on NUREG-0396 contains useful observations & info.
but exhibits inadequacy in moving 1000 toward achieving
effective plans to protect public after severe accident
SANCHEZ, N. Public Citizen Litigation Group 79/05/10 1p

7904203483 NUREG-0254
"Failure-Proof Cycles For Nuclear Power Plants"
#0985, L. Division of Engineering Standards 79/03/31 14pp.

7904203074 "Nuclear Power Plant Fire Protection: Fire Detection
(Subsys Task 21 - Fire Detection) FSN A-1093 SAND79-1373
79/02/05 36pp.

7904203096 NUREG/CR-0486
"Advanced Two-Phase Flow Instrumentation Program," quarterly
progress rept. for Jul-Dec 1978
WAGNER, C. D. DAVIS, E. E. & TOWNS, D. D. Oak Ridge National Laboratory
FIN 8-0401 79/03/31 66pp

7904203095 Research Info Ltr. 84 forwards NUREG/CR-0465, "NETS User's
Manual for Fault Tree Analyst," by Sandia Labs
LEVINE, S. Office of Nuclear Regulatory Research 79/05/15 2pp

7904203660 NUREG/CR-0465
"NETS User's Manual for Fault Tree Analyst"
MORRILL, L. B. & STACEY, S. L. Sandia Laboratories FSN A-1019
SAND77-2051 79/05/15 96pp Available at NTIS

7904203608 NUREG/CR-0781
"Physical Protection of Nuclear Facilities," quarterly
progress rept. for Jan-Mar 1979
CHAPMAN, L. D. Sandia Laboratories FSN A-1060 SAND79-0786
79/04/30 30pp

7904203123 NUREG-0170, Vol. 1
NUREG-0170, Vol. 1, "FDS on Transportation of Radioactive Fuel
by Air & Other Modes"
a Office of Standards Development 77/12/31 130pp

7904203177 NUREG-0170, Vol. 2
NUREG-0170, Vol. 2, "FDS on Transportation of Radioactive Fuel
by Air & Other Modes"
a Office of Standards Development 77/12/31 825pp

7904203011 NUREG/CR-0781
"Analysis of Procedure Calculation of Effects of Structure
Design on Neutron Primary Gamma-Ray & Secondary Gamma-Ray
Scatter in Air"
LAPLEY, C. H. Radiation Research Association NRC-D3-78-175
REV-7745 79/03/31 105pp Available at NTIS

7904203005 NUREG/CR-0422, Vol. 1
"LWR Safety Research Program," quarterly rept. Apr-June 1978
SIMPSON, J. Sandia Laboratories FSN A-1019 SAND79-1951 79/03/31
115pp Available at NTIS

7904203046 NUREG/CR-0448
"Measurement of Phase Selection in Mist Flows Using
Stagnation Probe"
THOMAS, J. S. & SEAMON, W. A. Idaho National Engineering Laboratory FSN
A-6074 TRC-1350 79/03/31 61pp

7904203003 NUREG-0448
"Investigation & Analysis of Mass Hortality of Commercial
Labrador (Chenamus Americanus) in Southwest Harbor, ME During
Oct of 1977"
HODGINS, E. Division of Site Safety & Environmental Analysis
79/07/25 105pp Available at NTIS 96 50

7904203167 NUREG-0540, Vol. 1
"Title List of Documents Made Publicly Available," for Apr
1979
a Technical Information & Document Control 79/04/30 334pp
Available at NTIS

7904203186 NUREG/CR-0492, Vol. 1
"Repts Distributed under NRC Reactor Safety Research
Foreign Technical Exchange Program," Vol. VI, Jul-Dec 1978
SUCKER, D. D. Oak Ridge National Laboratory FSN 8-0126
ORNL/NUREG-586 79/05/31 115pp Available at NTIS

7904203197 NUREG-0561
"Physical Protection of Shipments of Irradiated Reactor
Fuel Interim Schedule"
KAGAN, D. J. Office of Nuclear Material Safety & Safeguards
79/06/30 36pp Available at NTIS

7904203481 NUREG/CR-0429
"Field & Modeling Study of Mirdinon Particles From
U Mill Tailings Plant," interim rept.
SCHNEIDER, L. & HODGETT, T. W. Battelle Memorial Institute
Pacific Northwest Laboratory, FSN 8-2093-9, PNL-2090 79/04/30
102pp Available at NTIS

7904203487 NUREG/CR-0752
"Quarterly Progress Rept on Steadystate Heat Transfer
Separate-Effects Program," Jan-Mar 1979
WHITE, J. D. & HANNA, R. E. & CLARK, D. L. Oak Ridge National Laboratory
FSN 8-0126 ORNL/NUREG-77-3 79/03/31 23pp. Available at NTIS

7904203488 NUREG/CR-0487
"Bibliography of Repts on Research Sponsored by NRC Office of
Nuclear Regulatory Research," Jul-Dec 1978
SCHNEIDER, L. Oak Ridge National Laboratory FSN 8-0126
ORNL/NUREG-7810 79/03/31 130pp.

790629648 NUREG-0320

"Toxic Vapor Concentrations in Control Room Following Postulated Accidental Release"

WONG, J. Division of Risk Safety & Environmental Analysis
79/06/33 32pp Available at NTIS

790629651 NUREG/CR-0307 V3

"Screen Analysis of Cylindrical Pressure Vessels W/Various Stress Corrosion by Fluoride-Cleaned Method/Vessels W/Three Various Internal Pressure & External Loadings."

WU, F. M., MCD, R. A. Oak Ridge National Laboratory FIN 8-0123
ORNL/NUREG-10 79/05/31 32pp Available at NTIS

790629664 NUREG-0320 V3 M6

"Program Summary Rep." Vol 3, Number 6
Office of Management and Program Analysis 79/04/15 70pp
Available at NTIS

790629668 NUREG/CR-0355

"Aerodynamic Considerations on Injection of Canada-Sentinel Missiles From Ground Launch into Toronto Flow Field"

WALLER, T. Navy/Dept. of. FIN 8-1142. 79/06/30 87pp

790629673 NUREG/CR-0710

"Advanced Two-Phase Flow Instrumentation Program." quarterly progress report for DOE-CE 1978

TURNER, R. D., DAVIS, C. R., THOMAS, D. G. Oak Ridge National Laboratory
FIN 8-0401 ORNL/NUREG/CR-3 79/05/31 332p Available at NTIS

790629676 Submits changes to be made in NUREG CR-0421, "Post-Accident Heat Removal/Control-Test Experiments B-2 & B-3."

(SAND76-1230)
RIVERO, J. Sandia Laboratories 79/04/03 3pp

010 CORRESPONDENCE WITH OTHER ORGANIZATIONS

790629682 Responds to 790107 request

Forwarders composite listing of anticipated requests for NRC safety review upgrades both 790201 & 1004 lists

BARBER, R. N. Energy Dept. of. 79/04/09 3pp

790629683 Responds to 790103 ltr

re NRC coordination w/Interagency Working Group on Medical Radiation re diagnostic x-ray; guidance, NRC has no requirements for diagnostic x-ray; gives no specific application of new guidance

OSLAW, K. N. Division of Risk, Health & Safeguards Standards
79/10/30 1p.

790629684 Offers to help NRC

w/program to minimize unproduction exposure of persons to diagnostic x-ray; per C. Davis

790203 recommendations
MARTIN, J. R. Environmental Protection Agency 79/10/13 3pp

790629685 "Radiation Protection

Guidance to Federal Agencies for Diagnostic X-Ray; Approved as Recommendations"

COBLE, D. H. Environmental Protection Agency RICHMOND, J. H.
Health, Education & Welfare, Dept. of. 78-0776 78/02/01 3pp

790629686 Comments on EPA

"Hazardous Waste Guidelines & Regulations;" regulations unclear in role that regulatory agencies play in implementation EPA must incur w/NRC requirements re U.S. facilities w/NRC notices

OSBORN, L. V. Office of the Executive Director for Operations
79/05/16 3pp

790629687 Forwarders outlines & schedules

for ten ltrs proposed for NRC-02 of application review program

OSBORN, L. V. Gen-Contol Reactor Associates GCRA/NRC-0018
79/05/05 32pp

790629688 Summarizes 790402 meeting

w/DOE re NRC-11 submittal & chronology of events involved w/program

NOZAKURA, Y. Engineering Branch 79/04/06 3pp.

790629689 Responds to ltr re C. Johnson

Forwarders NRC comments on C. Johnson manuscript re epidemiological evaluation of cancer incidence rates for 1957-71 in areas w/adequate concentrations of Pu soil contamination near Rocky Flats

MARSHALL, M. A. Radiological Health Standards Branch 79/04/20 3pp.

790629691 Provides guidance & funding

to BNL to support evaluation of Part I containment suppression pool hydrodynamic loads

STELL, G. V. Division of Operating Reactors 79/05/26 3pp

790629692 3rd order for DOE work

"Part I Containment Assessment." increasing funding.

THURLEY, R. P. Office of Nuclear Reactor Regulation. FIN A-0108-9
79/05/02 3pp.

790629693 Forwarders IE Info Notice 79-12.

"Lower Reactor Vessel Head Insulation Support Problem"

PAPPAS, H. Region 3, Chicago, Office of the Director 79/05/08 3pp

790629694 IE Info Notice 79-11.

"Lower Reactor Vessel Head Insulation Support Problem"

Region 3, Chicago, Office of the Director 79/05/07 3pp

790629695 Requests opportunity

to participate in NRC 790510 meeting re UCB petition for emergency & remedial action & petition for reinstatement

REYNOLDS, H. B. Oakville & Lishman 79/03/07 1p

790629696 Requests opportunity

to participate in NRC 790510 meeting re UCB petition for emergency & remedial action & petition for reinstatement

PORTER, W. L. Gals Patent Co. 79/05/04 1p

790629697 Forwarders IE Circular 79-08.

"Attempted Eruption - Low Enriched U" which was sent to States parties on 790518

PAPPAS, H. Region 3, Chicago, Office of the Director 79/05/18 3pp

790629698 Ack receipt of UCB

790327 ltr re UCB petition for emergency & remedial action as adequacy of fire protection criteria

Participation at NRC meeting not deemed necessary to further client interests

EDWARDS, F. B. Conner, Moore & Carter 79/06/04 3pp

790629699 Ack receipt of UCB

790328 petition requesting NRC order for all operating reactors to perform seismic reassessments within 100 days Request will be handled per 10CFR 206.46 notice

SENTER, H. R. Office of Nuclear Reactor Regulation 79/05/05 1p

790629700 Notice of UCB

790328 petition requesting NRC order for reinstatement of seismic capabilities of all operating reactors

OSBORN, L. V. Office of Nuclear Reactor Regulation 79/05/10 1p

790629701 Forwarders UCB

790328 petition requesting seismic reassessment of operating plants Petition will be treated per 10CFR 206.46 Requests program response

CHILKOT, J. Office of the Secretary of the Commission 79/04/25 1p

790629702 Forwarders IE Circular 79-07.

"Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase" Submits list of licenses to whom circular was sent on 790326

PAPPAS, H. Region 3, Chicago, Office of the Director 79/05/03 3pp

790629703 Notifies that IE Bulletin 79-11.

"Safety Government Trip Done in Circuit Breakers for Engineered Safety Sys." has been forwarded to listed state

PAPPAS, H. Region 3, Chicago, Office of the Director 79/05/08 2pp.

790629704 Transcript of 790516

public meeting in Washington, DC re hearing on UCB petition for reinstatement 79-107

OSBORN, L. V. 79-13 encl.

OSBORN, L. V. & OSBORN, L. V. NRC/DOE Commission 79/05/16 3pp

790629705 Responds to 790427 ltr

extending invitation to address NRC re UCB petition for emergency & remedial action re fire protection Unable to attend Committee sits as fire protection efforts

OSBORN, L. V. Oakville Co. 79/05/04. 3pp.

790629706 Forwarders IE Info Notice 79-13.

"Indication of Low Water Level in Dwyer Steam Reactor"

OSBORN, L. V. Region 3, Chicago, Office of the Director 79/05/20 3pp

790629707 Forwarders IE Info Notice 79-12.

"Attempted Damage to New Fuel Assemblies" Lists recipient licenses

PAPPAS, H. Region 3, Chicago, Office of the Director 79/05/04 4pp.

FR PROPOSED RULE

790629708 Responds to 790203 request

Forwarders description of recent NRC successes in improving part of regulatory process

Specific examples encl.

OSBORN, L. V. Office of Standards Development 79/05/06 3pp

790603035 Comments on proposed rules 10CFR19 & 20 lifting limit of 1.25 rads per quarter week result in higher exposures to men, individuals & check in administering radiation control program
MCKLEY, H. H. Tennessee, State of 79/04/17 1p

790603058 Comments on proposed rules 10CFR19 & 20 objects to unclear section re determination of prior dose Questions revised radiation protection rules
MCKESSON, C. R. American Airlines, Inc 79/04/18 8pp

790603058 Comments on proposed rules 10CFR19 & 20 objects to unclear section re determination of prior dose Questions revised radiation protection rules
MCKESSON, C. R. American Airlines, Inc 79/04/18 8pp

790603060 Comments on proposed rule 10CFR20 argues stricter rules for all nuclear plants
MCKESSON, C. R. Affiliation Unknown 79/04/20 1p

790603069 Comments on proposed rules 10CFR19 & 20 basic concept of proposed is good but approach is poor, wording indicates overexposures are deliberate Opposes proposal
MCKESSON, C. R. Affiliation Unknown 79/04/21 3pp

790603069 Comments on proposed rules 10CFR19 & 20 basic concept of proposed is good but approach is poor, wording indicates overexposures are deliberate Opposes proposal
MCKESSON, C. R. Affiliation Unknown 79/04/21 3pp

790603057 Comments on proposed rules 10CFR19 & 20 favors mod of existing dose stds allowing up to 12-mrem/yr whole body dose under certain conditions Requests adoption of 3-mrem/yr std
MCKEL, J. H. AND MCKEL, D. Vanderbilt Univ 79/04/27 2pp

790603057 Comments on proposed rules 10CFR19 & 20 favors mod of existing dose stds allowing up to 12-mrem/yr whole body dose under certain conditions Requests adoption of 3-mrem/yr std
MCKEL, J. H. AND MCKEL, D. Vanderbilt Univ 79/04/27 2pp

790603058 Comments on proposed rules 10CFR19 & 20 proposed elimination of 510-10 rule is unacceptable without major ALARA objections Rule would establish no scientific basis for proposed dose limit changes
MCKESSON, C. R. General Electric Co, Nuclear Energy Products Div 80A-108-79 79/04/20 2pp

790603058 Comments on proposed rules 10CFR19 & 20 proposed elimination of 510-10 rule is unacceptable without major ALARA objections Rule would establish no scientific basis for proposed dose limit changes
MCKESSON, C. R. General Electric Co, Nuclear Energy Products Div 80A-108-79 79/04/20 2pp

790603060 Comments on proposed rules 10CFR19 & 20 requests that 510-10 formula guidelines be retained
MCKESSON, C. R. Todd Shipyards 79/04/16 2pp

790603060 Comments on proposed rules 10CFR19 & 20 requests that 510-10 formula guidelines be retained
MCKESSON, C. R. Todd Shipyards 79/04/16 2pp

790603060 Comments on proposed rules 10CFR19 & 20 recommends that regulations include provisions allowing prescribed dose levels to be exceeded when qualified expert believes circumstances warrant such action
MCKESSON, C. R. Beckman Instruments, Inc 79/04/23 2pp

790603060 Comments on proposed rules 10CFR19 & 20 recommends that regulations include provisions allowing prescribed dose levels to be exceeded when qualified expert believes circumstances warrant such action
MCKESSON, C. R. Beckman Instruments, Inc 79/04/23 2pp

790603070 Comments on proposed rules 10CFR19 & 20 opposes rule because long-term effects of radiation are unknown
MCKESSON, C. R. Affiliation Unknown 79/04/20 3pp

790603070 Comments on proposed rules 10CFR19 & 20 opposes rule because long-term effects of radiation are unknown
MCKESSON, C. R. Affiliation Unknown 79/04/20 3pp

7906030219 Comments on proposed rules 10CFR19 & 20 supplements 790416 comments Objects to elimination of 510-10 formula. Proposed amendments are not supported by scientific data that justify mod of current rules
MCKESSON, C. R. Health Physics Society 79/04/24 1p

7906030219 Comments on proposed rules 10CFR19 & 20 supplements 790416 comments Objects to elimination of 510-10 formula. Proposed amendments are not supported by scientific data that justify mod of current rules
MCKESSON, C. R. Health Physics Society 79/04/24 1p

790603050 Comments on proposed rule 10CFR20 approves proposed ALARA suggests clarification re actual number of recommended committee members
MILTON, R. D. Wilson, R. D. MD 79/04/26 1p

790603040 Responses to 790420 (re re deletion of long-standing 510-10) dose-averaging formula from 10CFR20 Proposed action is part of broader action to strengthen stds & implementation of ALARA concept
MCKESSON, C. R. Office of Standards Development 79/04/22 3pp

790603040 Responses to 790420 (re re deletion of long-standing 510-10) dose-averaging formula from 10CFR20 Proposed action is part of broader action to strengthen stds & implementation of ALARA concept
MCKESSON, C. R. Office of Standards Development 79/04/22 3pp

790603069 Requests explanation of nuclear workers radiation dose stds & list of regulations now in force
MCKESSON, C. R. Affiliation Unknown 79/04/23 1p

790603069 Requests explanation of nuclear workers radiation dose stds & list of regulations now in force
MCKESSON, C. R. Affiliation Unknown 79/04/23 1p

790603048 Comments on proposed rules 10CFR19 & 20 changes would remove flexibility & provide little or no corresponding benefit to workers
MCKESSON, C. R. Wisconsin Electric Power Co 79/04/24 2pp

790603048 Comments on proposed rules 10CFR19 & 20 changes would remove flexibility & provide little or no corresponding benefit to workers
MCKESSON, C. R. Wisconsin Electric Power Co 79/04/24 2pp

790603050 Comments on proposed rules 10CFR19 & 20 finds significant inconsistency in proposed rule
MCKESSON, C. R. Atomic Industrial Forum 79/04/24 2pp

790603050 Comments on proposed rules 10CFR19 & 20 finds significant inconsistency in proposed rule
MCKESSON, C. R. Atomic Industrial Forum 79/04/24 2pp

790603053 Comments on proposed rules 10CFR19 & 20 cannot support changes in present form until issues of employment status after max allowed exposure are sufficiently addressed
MCKESSON, C. R. Louisiana, State of 79/04/25 2pp

790603053 Comments on proposed rules 10CFR19 & 20 cannot support changes in present form until issues of employment status after max allowed exposure are sufficiently addressed
MCKESSON, C. R. Louisiana, State of 79/04/25 2pp

790603040 Comments on proposed rules 10CFR19 & 20 proposal of regulations is premature
MCKESSON, C. R. Consolidated Edison Co of New York 79/04/23 2pp

790603060 Comments on proposed rules 10CFR19 & 20 proposal of regulations is premature
MCKESSON, C. R. Consolidated Edison Co of New York 79/04/23 2pp

7906030219 Comments on proposed rules 10CFR19 & 20 supplements 790416 comments Objects to elimination of 510-10 formula. Proposed amendments are not supported by scientific data that justify mod of current rules
MCKESSON, C. R. Health Physics Society 79/04/24 1p

NONDOCKETED ITEMS

7904030259 Comments on petition for rulemaking 10CFR20-12 Section 20.605 is unnecessary Compliance of health physics staff is gained from education & experience
BENTLEY, R. Public Service Co. of Oklahoma 79/04/24 1p

7904030214 Comments on petition for rulemaking 10CFR20-13 requests denial of Section 20.602 petition. Health physics staffs are operated by highly qualified personnel
JONES, T. A. Pacific Gas & Electric Co. 79/04/27 1p

7904030204 Comments on petition for rulemaking 10CFR20-12 Section 20.605 should apply only to nuclear reactor facilities
WILLIAMS, P. R. Dow Corning Corp. 79/04/23 2pp

7904030406 Comments on petition for rulemaking 10CFR71 requests 180-day attention to field descriptions of QA program
HENDRICK, E. L. Yuba Heat Transfer Corp. 79/04/04 1p

7904040104 Revision of 790305 petition for rulemaking re decommissioning to require plant operators to post bonds
GONZALES, W. S. ARBOTH, J. Public Institute Research Group 79/04/07 1pp

7904140346 Comments on petition for rulemaking 10CFR20-12 opposes rulemaking Doubling importance of academic requirements for health physicists
KATHRIN, R. L. Affiliation Unknown 79/04/17 4pp

7904140530 Comments on petition for rulemaking 10CFR20-13 opposes rulemaking self certification of health physicists is no guarantee of competence or licensing from bad practice
HARRIS, J. R. Affiliation Unknown 79/04/20 3pp

7904140543 Comments on petition for rulemaking 10CFR20-13 opposes rulemaking that should not certify grade or specify min experience requirements
MERTZ, L. F. California Institute of Technology 79/04/10 2pp

7904140546 Comments on petition for rulemaking 10CFR20-12 opposes rulemaking Classifications for certification less specifically current yrs is sufficient
CORTIS, R. H. Pennsylvania Power & Light Co. 79/04/17 3pp

7904140570 Comments on petition for rulemaking 10CFR20-13 opposes rulemaking Existing American Board of Health Physics certification program procedure need for work program
HARRIS, E. R. Yale Univ. 79/04/19 2pp

7904140504 Requests 30-day attention to comment on petition for rulemaking 10CFR20-12
TEMPERLEY, R. B. Affiliation Unknown 79/04/20 1p

7904200215 Comments on petition for rulemaking 10CFR71 questions necessity for users to develop QA program Basic attention for low level radiation sources Requests extension of 790401 deadline for submission of QA program
GARRARD, E. C. Nuclear Energy Service, Inc. 79/04/01 1p

7904200253 Comments on petition for rulemaking 10CFR20-13 approves 20.605 which involves high standards for personnel in field of radiation protection Disapproves of portion denying licenses power to override decisions of certified health physicists
MURPHY, California Univ. of Berkeley 79/04/19 2pp

7904200268 Comments on petition for rulemaking 10CFR20-13; amend will not contribute to current certification process Will only administratively burden NRC
BENNETT, L. L. Navy Dept. 79/04/20 1p

7904200272 Comments on petition for rulemaking 10CFR20-12; supports petition Relieves certification of health physics personnel should be open to public scrutiny
KOROSOFF, M. J. Affiliation Unknown 79/04/27 1p

7904200279 Comments on petition for rulemaking 10CFR20-13 not in best interest of NRC to engage in certification of individual personnel
HARRIS, E. D. Montana State of 79/04/26 3pp

7904200286 Comments on petition for rulemaking 10CFR20-13 should not be adopted Proposal to have NRC certify radiation protection personnel is unnecessary in view of existing license review procedures
N. Army Dept. of 79/04/26 2pp

7904200294 Comments on petition for rulemaking 10CFR20-13; petition implies NRC is not presently evaluating qualifications of health physicists or radiation safety officers; which is not true
N. Affiliation Unknown 79/04/24 3pp

7904200450 Comments on petition for rulemaking 10CFR20-13 proposed amendments have previously been addressed by NRC in reg guide No need for new amendments
LAWRENCE, R. R. Dow Chemical Co. 79/04/25 2pp

7904200416 Comments on petition for rulemaking 10CFR20-7 strongly supports meeting proposed basis
HARRIS, R. Affiliation Unknown 79/04/20 1p

7904200450 Fifteen public interest groups request NRC amend emergency procedures re accidental release of radioactivity Proposed amendments involve regulation, evaluation, monitoring equipment & certification of procedural accuracy
BANCROFT, M. H. Public Citizen Litigation Group POLLOCK, R. Critics Mass Energy Project 79/03/09 13pp

7904200441 Comments on petition for rulemaking 10CFR20-13 proposed action should be considered as only one of several possible responses to problem
WILLIAMS, C. A. Philippines 79/04/10 3pp

7904200498 Requests petition for rulemaking 10CFR20-13 which would require health physics personnel to be certified by NRC
DELAVALLE, A. Army Dept. of White Sands Missile Range STEAD, T. W. H. 79/04/12 1p

7904200503 Comments on petition for rulemaking 10CFR20-13 petitioners has not demonstrated sufficient evidence of pressure on health physics personnel to engage in bad practice
PARKER, H. O. Duke Power Co. 79/04/20 2pp

7904200549 Comments on petition for rulemaking 10CFR20-13 since health physicists are certified by American Board of Health Physics, additional would duplicate procedures Does not approve of federal govt entering judgment of competence
CUMMINGS, J. E. Affiliation Unknown 79/04/10 1p

79042005129 Comments on petition for rulemaking 10CFR20-13 proposed certification program unnecessary in light of present measures for ensuring high level of health physics competence
HARRIS, E. C. Florida Power & Light Co. L-79-180 79/04/27 2pp

79042005129 Comments on petition for rulemaking 10CFR20-13 proposed certification program unnecessary in light of present measures for ensuring high level of health physics competence
HARRIS, E. C. Florida Power & Light Co. L-79-180 79/04/27 2pp

79042005129 Comments on petition for rulemaking 10CFR20-13 proposed certification program unnecessary in light of present measures for ensuring high level of health physics competence
HARRIS, E. C. Florida Power & Light Co. L-79-180 79/04/27 2pp

79042005129 Comments on petition for rulemaking 10CFR20-13 proposed certification program unnecessary in light of present measures for ensuring high level of health physics competence
HARRIS, E. C. Florida Power & Light Co. L-79-180 79/04/27 2pp

79042005129 Comments on petition for rulemaking 10CFR20-13 proposed certification program unnecessary in light of present measures for ensuring high level of health physics competence
HARRIS, E. C. Florida Power & Light Co. L-79-180 79/04/27 2pp

79042005129 Comments on petition for rulemaking 10CFR20-13 proposed certification program unnecessary in light of present measures for ensuring high level of health physics competence
HARRIS, E. C. Florida Power & Light Co. L-79-180 79/04/27 2pp

79042005129 Comments on petition for rulemaking 10CFR20-13 proposed certification program unnecessary in light of present measures for ensuring high level of health physics competence
HARRIS, E. C. Florida Power & Light Co. L-79-180 79/04/27 2pp

79042005129 Comments on petition for rulemaking 10CFR20-13 proposed certification program unnecessary in light of present measures for ensuring high level of health physics competence
HARRIS, E. C. Florida Power & Light Co. L-79-180 79/04/27 2pp

79042005129 Comments on petition for rulemaking 10CFR20-13 proposed certification program unnecessary in light of present measures for ensuring high level of health physics competence
HARRIS, E. C. Florida Power & Light Co. L-79-180 79/04/27 2pp

79042005129 Comments on petition for rulemaking 10CFR20-13 proposed certification program unnecessary in light of present measures for ensuring high level of health physics competence
HARRIS, E. C. Florida Power & Light Co. L-79-180 79/04/27 2pp

79042005129 Comments on petition for rulemaking 10CFR20-13 proposed certification program unnecessary in light of present measures for ensuring high level of health physics competence
HARRIS, E. C. Florida Power & Light Co. L-79-180 79/04/27 2pp

79042005129 Comments on petition for rulemaking 10CFR20-13 proposed certification program unnecessary in light of present measures for ensuring high level of health physics competence
HARRIS, E. C. Florida Power & Light Co. L-79-180 79/04/27 2pp

79042005129 Comments on petition for rulemaking 10CFR20-13 proposed certification program unnecessary in light of present measures for ensuring high level of health physics competence
HARRIS, E. C. Florida Power & Light Co. L-79-180 79/04/27 2pp

79042005129 Comments on petition for rulemaking 10CFR20-13 proposed certification program unnecessary in light of present measures for ensuring high level of health physics competence
HARRIS, E. C. Florida Power & Light Co. L-79-180 79/04/27 2pp

79042005129 Comments on petition for rulemaking 10CFR20-13 proposed certification program unnecessary in light of present measures for ensuring high level of health physics competence
HARRIS, E. C. Florida Power & Light Co. L-79-180 79/04/27 2pp

NONDOCKETED ITEMS

7906020080 "Preconceptual Study of Proliferation-Resistant
Heterogeneous Oxide Fuelled LMFBR Core." final rep. Vol 1
BACH, C. W., CAMPBELL, M. D., COFFIN, R. D. Westinghouse Electric Corp
79/11/93 22pp

7906020082 "Preconceptual Study of Proliferation-Resistant
Heterogeneous Oxide Fuelled LMFBR Core." final rep. Vol 2
Westinghouse Electric Corp 79/11/93 38pp

7906020087 GCR-00392
"Preconceptual Design Study of Proliferation-Resistant
Heterogeneous Oxide Fuelled LMFBR Core." final rep. Vol 3
Westinghouse Electric Corp UC-798 79/11/93 305pp

7906020091 EDS-90C-13244
"Preconceptual Study of L-600 FM Carbide-Fueled LMFBR
Design." summary report
VITTE, J. A., FORTIN, J. D., BRITTON, J. C. Westinghouse International
Corp UC-798 79/09/93 170pp Available at NRC

7906020094 Transcript of 790517 meeting in Bethesda-MD Pg 2.463-2.749
MILLER, M. E., HANSEN, E. Atomic Safety and Licensing Board Panel
79/05/17 104pp

7906020014 Forward 790501-0011, "Draft Generic EIS on U Mining " A
FR notice Repl withheld from (OCPS) 7901
SCARANO, R. A. Uranium Recovery Licensing Branch 79/04/20 2pp

7906020041 Requests will not be required to answer certain
interrogatories from CA Dept of Water Resources Requests
regarding interrogatories be deferred pending response to
all interrogatories (Certificate of the NRC)
DOLBE, R. M., ARMSTRONG, W. H., McQuibban, R. J., Brown, B. Emerson
FUSHER, R. Pacific Gas & Electric Co 79/05/02 14pp

7906020072 Response to 790420 ltr requesting EIS CP application never
filed to EIS issued
BROOKS, W. Environmental Projects Branch 2 79/05/14 1p

7906020016 advice that JF Delaney will present ASLAW record argument
on behalf of NRC re Baskin/CA Action Co appeal from ASL
790129 order
GOLDFELD, J. R. Anti-Trust Division 79/05/04 1p

7906020010 Response to alleged self-serving ltr of 790412 assumes
mischaracterizations are further attempt to influence case
re motion to grant discovery before NRC
MCDONALD, R. C. Spillage & Remediation 79/05/14 1p

7906020010 Defines issues that parties will be expected to address at
790522 oral argument
DOLBE, R. M. Atomic Safety and Licensing Appeal Panel 79/05/04 2pp

7906020014 Transcript of 790517 meeting in Bethesda-MD Pg 2.235-2.435
MILLER, M. E., LITTLE, C., HANSEN, E. Atomic Safety and Licensing Board
Panel 79/05/17 205pp

7906020019 Transcript of 790522 hearing in Bethesda-MD Pg 1-130
ROBERTSON, A., FORTIN, J. D., BRITTON, J. C. Atomic Safety and Licensing
Appeal Panel 79/05/22 123pp

7906020027 Forward 790436 790436 FOIA request for documents
obtained through civil investigative demand re will proposed
to construct Nondocking project
GOLDFELD, J. R. Anti-Trust Division 79/05/04 1p

7906020022 Response by CA Dept of Water Resources in opposition to
FOIA action for protective order re Baskin deposition
Certificate of the NRC
MILLER, C. California, State of 79/04/23 16pp

7906180045 NRC02-0088
"SDR Release on Operation of PFW, Supp 1 -
a Notice of Atomic Reactor Regulation 448 79/02/31 150pp
Available at NRC

7906190007 Notice that ASLAW for antitrust proceedings has three
members RE William McFarley & J. D. Brinkman, Chairman
ROBERTSON, A. Atomic Safety and Licensing Appeal Panel 79/01-01
79/05/17 1p

7906200056 Progress report to State of CA Dept of Water Resources 790425
request for computerized documents forwards 1989-90-1990
deposition of documents & draft stipulation to protective
order Certificate of the NRC
MILLER, M. E., FORTIN, J. D., BRITTON, J. C. Pacific Gas & Electric Co ARMSTRONG, W. H.
McQuibban, R. J., Brown, B. Emerson 79/04/30 74pp

7906200072 Reels denied of will motion for protective order re
790426 fourth set of interrogatories from CA Dept of Water
Resources will compel justify request for additional
documents to questions are inconsistent & unanswerable
GOLDFELD, J. R., DOLBE, R. M., HANSEN, E. California, State of
79/05/02 16pp

7906200079 Directs will to submit all info & notes promised in response
to NRC notice to compel discovery along with info to which
will to NRC agreed during informal discussions Requests
response within 30 days
MILLER, M. E. Atomic Safety and Licensing Board Panel 79/05/16 1p

7906200080 Response to NRC 790503 action to compel discovery Will
supply all info in Questions 2-8 re load dropping
Will supply annual site load, nuclear waste management, waste &
purchase & energy base Certificate of the NRC
MILLER, C. Pacific Gas & Electric Co DOLBE, R. M.
McQuibban, R. J., Brown, B. Emerson 79/05/11 14pp

7906200090 FOIA request for copies of documents obtained by NRC from
DOJ re PDRS proposal to construct Nondocking project
FUSHER, R. C. Center for Law in the Public Interest 79/04/20 1p

7906200092 Response to FOIA request for documents made available to NRC
Forwards index to 148 microfiche rolls
MILLER, J. R. Division of Rules and Records, 79/06/12 1p

--7906200099 Index to 148 microfiche rolls provided by CA Dept of Water
Resources Reel involves PDRS Jan-Mar 1973 memo re proposal
to construct Nondocking project. Enc. available in General
files
California, State of 79/05/12 22pp

7906200094 Requests preparation of proposal re isolation of new
yellowcake calciner & new yellowcake handling operation
from east of bldg & provision of rock emission control
MILLER, J. R. Colorado, State of 79/05/22 2pp

7906200093 Requests that NRC make air dispersion & deposition
evaluations of radiological & chemical exposure to Lincoln
Park area due to protect offsite groundwater contamination
caused by leakage from existing CCHW soil buildings ponds
MILLER, J. R. California, State of 79/05/04 1p

PT21 198905PLANCE REPORTS AND RELATED CORRESPONDENCE

7906200090 Forward ltr re ASLAW program for computing piping
response to various static & transient loads Requests
info be considered as Part 21 ltr
MCDONALD, R. W. Atomic Safety and Licensing Appeal Panel 79/04/17 1p

--7906200097 Forward memo confirming info furnished at 790416 meeting
w/ NRC re ASLAW program for computing piping response to
various static & transient loads Five baseline solutions
will be verified lists ASLAW program
MCDONALD, R. W. Atomic Safety and Licensing Appeal Panel 79/04/19 2pp

00000 QUALITY ASSURANCE INSPECTIONS

7906010105 Act receipt of 790411 ltr informing NRC of steps taken to
correct deviation noted in SA Program Inspect
790505/79-01
FOTAPROG, U. Region 4, Dallas, Vendor Inspection Branch
79/05/06 1p

7906010106 Response to NRC 790318 ltr re deviation noted in SA Program
Inspect 790505/79-01 Corrective actions W-102 weld
procedures has been revised to incorporate backing ring tack
welding
MCDONALD, R. W. Diamond Power Specialty Corp (subs of Deakot &
Hilco) 79/04/11 2pp.

NONDOCKETED ITEMS

- 7906010100 Forwards SA Program Insp Rept 99000074/79-01 on 790227-0302
a notice of deviation
POTAF0905.U Region 4, Dallas, Vendor Inspection Branch
79/03/13 App
- 7906010112 Notice of deviation from Insp on 790227-0302
POTAF0905.U Region 4, Dallas, Vendor Inspection Branch
79/03/13 App
- 7906010114 SA Program Insp Rept 99000074/79-01 on 790227-0302
Noncompliance noted lack labeling procedures not developed & qualified
ELLERB00M.L E. & HUNNITT-D H Region 4, Dallas, Vendor
Inspection Branch 79/03/14 App
- 7906010139 Ack receipt of 790400 ltr informing NRC of steps taken to
correct deviation noted in SA Program Insp Rept
99000074/79-01
POTAF0905.U Region 4, Dallas, Vendor Inspection Branch
79/03/03 App
- 7906010143 Responds to NRC 790400 ltr re deviation noted in SA Program
Insp Rept 99000074/79-01 Corrective actions dead weight
calibr source changed to obtain more timely src
KORBER E J Lucile Co 79/04/20 App
- 7906010148 Forwards SA Program Insp Rept 99000074/79-01 on 790312-16
a notice of deviation
POTAF0905.U Region 4, Dallas, Vendor Inspection Branch
79/04/09 App
- 7906010171 Notice of deviation from Insp on 790312-16
a Region 4, Dallas, Vendor Inspection Branch 79/04/06 App
- 7906010177 SA Program Insp Rept 99000074/79-01 on 790312-16
Noncompliance noted master test pass not calibr as
prescribed & assembly instruction procedure not
reviewed by QA manager.
SUTHERLAND W. & HUNNITT-D H Region 4, Dallas, Vendor Inspection
Branch 79/04/06 App
- 7906010185 Ack receipt of 790400 ltr informing NRC of steps taken to
correct deviation noted in SA Program Insp Rept
99000074/79-01
POTAF0905.U Region 4, Dallas, Vendor Inspection Branch
79/03/03 App
- 7906010170 Responds to NRC 790400 ltr re deviation noted in SA Program
Insp Rept 99000074/79-01 Corrective actions nonconformance
not issued & receiving Insp personnel instructed to create
nonconformance report for all nonconforming condition.
TOMBAULT V M Almond & Merrill Co. Inc. Galva of Foster Wheeler
Corp 79/04/20 App
- 7906010174 Forwards SA Program Insp Rept 99000074/79-01 on 790312-16
a notice of deviation
POTAF0905.U Region 4, Dallas, Vendor Inspection Branch
79/04/06 App
- 7906010179 Notice of deviation from Insp on 790321-22
a Region 4, Dallas, Vendor Inspection Branch 79/04/03 App
- 7906010182 SA Program Insp Rept 99000074/79-01 on 790321-22
Noncompliance noted receiving inspector processed cover as
drawing C-24257, although cover had outside diameter of
29.4375 inches
KORBER E J & HUNNITT-D H Region 4, Dallas, Vendor Inspection
Branch 79/04/03 App
- 7906010188 Ack receipt of 790426 ltr informing NRC of steps taken to
correct deviations noted in SA Program Insp Rept
99000074/79-01
POTAF0905.U Region 4, Dallas, Vendor Inspection Branch
79/03/03 App
- 7906010194 Responds to NRC 790326 ltr re deviations noted in SA Program
Insp Rept 99000074/79-01 Corrective actions change notices
not released unless all changes are clearly noted & new
quality-related analytical chemistry procedures under review
KORBER E J, General Atomic Co. (subs of Gulf Oil Corp) 79/04/26 App
- 7906010198 Forwards SA Program Insp Rept 99000074/79-01 on 790326-0301
a notice of deviation.
POTAF0905.U Region 4, Dallas, Vendor Inspection Branch
79/03/26 App
- 7906010204 Notice of deviation from Insp on 790326-0301.
a Region 4, Dallas, Vendor Inspection Branch 79/03/19 App
- 7906010208 SA Program Insp Rept 99000074/79-01 on 790326-0301
Noncompliance noted certain design activities not properly
implemented & analytical chemistry lab procedures not
reviewed as prescribed
KORBER E J & HUNNITT-D H Region 4, Dallas, Vendor
Inspection Branch 79/03/19 App
- 7906010244 Ack receipt of 790417 ltr informing NRC of steps taken to
correct deviation noted in SA Program Insp Rept
99000074/79-01
POTAF0905.U Region 4, Dallas, Vendor Inspection Branch
79/03/02 App
- 7906010248 Responds to NRC 790330 ltr re deviation noted in SA Program
Insp Rept 99000074/79-01 Corrective actions correct
certifications received from supplier
CARRINGTON Process Equipment Co., Inc 79/04/17 App
- 7906010252 Forwards SA Program Insp Rept 99000074/79-01 on 790312-13
a notice of deviation
POTAF0905.U Region 4, Dallas, Vendor Inspection Branch
79/03/03 App
- 7906010259 Notice of deviation from Insp on 790312-13
a Region 4, Dallas, Vendor Inspection Branch 79/03/03 App
- 7906010259 SA Program Insp Rept 99000074/79-01 on 790312-13
Noncompliance noted certificate for developer test batch
number different from batch number on developer card
ELLERB00M.L E. & HUNNITT-D H Region 4, Dallas, Vendor
Inspection Branch 79/03/03 App
- 7906010270 Ack receipt of 790308 & 0400 ltr informing NRC of steps
taken to correct deviation noted in SA Program Insp Rept
99000074/79-01
POTAF0905.U Region 4, Dallas, Vendor Inspection Branch
79/04/03 App
- 7906010273 Responds to NRC 790330 ltr re deviation noted in SA Program
Insp Rept 99000074/79-01 Corrective actions GC
inspected terminals & marked damaged wires requiring
replacement Power operated screwdrivers banned from area
LEAHMAN H H Fairbro Co 79/04/20 App
- 7906010282 Ack receipt of 790308 ltr informing NRC of steps taken to
correct deviation noted in SA Program Insp Rept
99000074/79-01 Ack ltr info required specific description
of steps necessary to correct defective terminal
POTAF0905.U Region 4, Dallas, Vendor Inspection Branch
79/03/20 App
- 7906010286 Responds to NRC 790326 ltr re deviation noted in SA Program
Insp Rept 99000074/79-01 Corrective actions audit will be
conducted & customers will send test report on wire & cable
used on panel jobs
BENNETT H O Fairbro Co 79/03/06 App
- 7906010294 Forwards SA Program Insp Rept 99000074/79-01 on 790116-19
a notice of deviation
BENNETT H O Region 4, Dallas, Office of the Director
79/03/02 App
- 7906010297 Notice of deviation from Insp on 790116-19
BENNETT H O Region 4, Dallas, Office of the Director
79/03/02 App
- 7906010301 SA Program Insp Rept 99000074/79-01 on 790116-19
Noncompliance noted failure to take committed corrective
action & damaged insulation of re-insulated terminals not
consistent with NRC's V of 102P220 App &
KORBER E J & HUNNITT-D H Region 4, Dallas, Vendor Inspection
Branch 79/01/29 App
- 7906010304 Forwards SA Program Insp Rept 99000074/79-01 on 790312-16
a notice of deviation
POTAF0905.U Region 4, Dallas, Vendor Inspection Branch
79/03/03 App
- 7906010308 Notice of deviation from Insp on 790312-16
a Region 4, Dallas, Vendor Inspection Branch 79/03/29 App
- 7906010318 SA Program Insp Rept 99000074/79-01 on 790312-16
Noncompliance noted fuel rod travelers signed off before
completion of hydrogen testing.
KORBER E J & HUNNITT-D H Region 4, Dallas, Vendor
Inspection Branch 79/03/29 App
- 7906010309 Ack receipt of 790323 ltr informing NRC of steps taken to
correct deviation noted in SA Program Insp Rept
99000074/79-01
POTAF0905.U Region 4, Dallas, Vendor Inspection Branch
79/03/03 App

NONDOCKETED ITEMS

- 790670022 Responds to NRC 790290 ltr re deviations noted in QA Program Insp Rept 99900034/79-01 Corrective actions QA manual revised to include duties & authorities of all personnel performing quality-related activities
DUNN, C P Boring Mfg 79/04/29 3pp
- 790670023 Forwards QA Program Insp Rept 99900034/79-01 on 790121-15 & notice of deviation
POTAPPOV, U Region 4, Dallas, Vendor Inspection Branch 79/03/20 2pp
- 790670025 Notice of deviation from Insp on 790121-15
* Region 4, Dallas, Vendor Inspection Branch 79/03/07 1p
- 790670026 QA Program Insp Rept 99900034/79-01 on 790321-18 Noncompliance noted failure to clearly delineate duties & responsibilities of personnel & failure to include apt policy statement in QA program
GUTBERG, W, WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch 79/03/07 12pp
- 790670028 Forwards QA Program Insp Rept 99900034/79-01 on 790321-001 No noncompliance noted
POTAPPOV, U Region 4, Dallas, Vendor Inspection Branch 79/03/04 2pp
- 790670031 QA Program Insp Rept 99900034/79-01 on 790321-001 Noncompliance noted Major areas inspected implementation of 30CFR50, App E criteria, other NRC requirements & applicable codes & codes
OLLIVER, E E, SMITH, J R Region 4, Dallas, Vendor Inspection Branch 79/03/03 16pp
- 790670032 Forwards QA Program Insp Rept 99900034/79-01 on 790321-06 No noncompliance noted
POTAPPOV, U Region 4, Dallas, Vendor Inspection Branch 79/04/20 3pp
- 790670033 QA Program Insp Rept 99900034/79-01 on 790402-06 No noncompliance noted Region areas inspected implementation of explicit rept & other applicable codes & standards & program controls & audit attributes
MONTELL, W D, WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch 79/03/19 3pp
- 790670044 Ack receipt of 790002 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900034/79-02
POTAPPOV, U Region 4, Dallas, Office of the Director 79/02/06 1p
- 790670048 Responds to NRC 790312 ltr requesting add info re deviation noted in QA Program Insp Rept 99900034/79-02 Corrective actions purchase orders will be forwarded to QA for approval
HEUBLEIN, D A, Simpson-Williams Co 79/03/16 3pp
- 790670054 Requests add info to complete review of response to deviation from QA Program Insp Rept 99900034/79-02
POTAPPOV, U Region 4, Dallas, Office of the Director 79/03/12 1p
- 790670057 Responds to NRC 790319 ltr re deviations noted in QA Program Insp Rept 99900034/79-02 Corrective actions beam welder repair & weld order format being revised
THARP, W E Simpson-Williams Co 79/02/02 3pp
- 790670058 Forwards QA Program Insp Rept 99900034/79-02 on 790321-16 & 4 deviations
- 790670059 Responds to NRC 790297 ltr re deviations noted in QA Program Insp Rept 99900034/79-01 Corrective actions QA manual updated & personnel qualification records revised
GILBERT, M Western Splicing & Engineering Co - Inc 79/04/04 3pp
- 790670061 Forwards QA Program Insp Rept 99900034/79-01 on 790122-24 & notice of deviation
POTAPPOV, U Region 4, Dallas, Vendor Inspection Branch 79/02/27 2pp
- 790670065 Notice of deviation from Insp on 790122-24
* Region 4, Dallas, Office of the Director 79/02/26 3pp
- 790670066 QA Program Insp Rept 99900034/79-01 on 790122-24 Noncompliance noted Failure to take remedial corrective actions Welding procedures spec packages did not contain required qualification of personnel Records
WITTE, W D, WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch 79/02/26 3pp
- 790670068 Ack receipt of 790316 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900034/79-02
POTAPPOV, U Region 4, Dallas, Vendor Inspection Branch 79/03/26 1p
- 790670069 Responds to NRC 790313 ltr re deviations noted in QA Program Insp Rept 99900034/79-01 Corrective actions will assembly & research house vouchers will be maintained in central location
SHELLEY, J F Varney Corp 79/03/16 1p
- 790670063 Forwards QA Program Insp Rept 99900034/79-01 on 790321 & notice of deviation
POTAPPOV, U Region 4, Dallas, Vendor Inspection Branch 79/02/13 2pp
- 790670064 Notice of deviation from Insp on 790122
* Region 4, Dallas, Vendor Inspection Branch 79/02/13 1p
- 790670067 QA Program Insp Rept 99900034/79-01 on 790122 Noncompliance noted assembly & research house vouchers were found
WELLY, W D, WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch 79/02/13 4pp
- 790670070 Ack receipt of 790423 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900034/79-01
POTAPPOV, U Region 4, Dallas, Vendor Inspection Branch 79/03/03 1p
- 790670078 Responds to NRC 790301 ltr re deviation noted in QA Program Insp Rept 99900034/79-01 Changes data of commitment for corrective action agreed to at 790413 meeting
YANUS, B E Electric Services, Inc Invs of Search Corp - 79/04/20 1p
- 790670079 Ack receipt of 790418 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900034/79-01
POTAPPOV, U Region 4, Dallas, Vendor Inspection Branch 79/03/03 1p
- 790670084 Responds to NRC 790406 ltr re deviation noted in QA Program Insp Rept 99900034/79-01 Corrective actions: drawings in question have been revised to show correct dimensions Welds have been repaired
HINTER, W W Anchor/Barling Valve Co of Anchor/Barling Industries, Inc 79/04/18 1p
- 790670082 Forwards QA Program Insp Rept 99900034/79-01 on 790221-22 & notice of deviation
POTAPPOV, U Region 4, Dallas, Vendor Inspection Branch 79/04/08 2pp
- 790670087 Notice of deviation from Insp on 790321-23
POTAPPOV, U Region 4, Dallas, Vendor Inspection Branch 79/04/03 1p
- 790670074 QA Program Insp Rept 99900034/79-01 on 790321-23 Noncompliance noted: Failure to adhere to min size specified weld specified in ASME code & fillet weld less than min size specified
WELLY, W D, WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch 79/04/03 3pp

NONDOCKETED ITEMS

- 790420060 Act receipt of 790420 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept
 9904041/79-04
 POTAF008-U Region 4, Dallas, Vendor Inspection Branch
 79/04/03 1p
- 790420081 Responds to NRC 790322 ltr re deviation noted in QA Program Insp Rept 9904041/79-04
 Corrective actions revision to QA of design manual
 KIRKENDALL R Combustion Engineering, Inc 79/04/20 App
- 790420082 Forwards QA Program Insp Rept 9904047/79-01 on 790312-10
 No noncompliance noted
 POTAF008-U Region 4, Dallas, Office of the Director 79/04/02 App
- 790420099 QA Program Insp Rept 9904057/79-01 on 790312-10 No noncompliance noted
 Major areas inspected implementation of 10CFR50 App 8 criteria, other NRC requirements & applicable codes & actions on previous Insp Findings
 ELDER, R. E., WANNICUTT, S. H Region 4, Dallas, Office of the Director 79/04/30, 10pp
- 790420100 Forwards QA Program Insp Rept 9904049/79-01 on 790308-08
 No noncompliance noted
 POTAF008-U Region 4, Dallas, Office of the Director 79/04/03, 5pp
- 790420104 QA Program Insp Rept 9904040/79-01 on 790308-08 No noncompliance noted
 Major areas inspected implementation of 10CFR50 App 8 criteria & customer requirements, including Insp of QA manual/program design control & contracts
 AGEE, J. R Region 4, Dallas, Office of the Director 79/04/03 App
- 790420107 Act receipt of 790420 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept
 9904043/79-01
 POTAF008-U Region 4, Dallas, Office of the Director 79/05/07 1p
- 790420107 Responds to NRC 790324 ltr re deviation noted in QA Program Insp Rept 9904043/79-01
 Corrective actions in-process
 Revision notice issued & disposed of & responsible foreman retrained re welding machine settings
 BATES, D. J., MILLER, L. C., KIRKENDALL, R. A Combustion Engineering, Inc 79/04/23 App
- 790420100 Forwards QA Program Insp Rept 9904053/79-01 on 790324-0209
 & notice of deviation
 POTAF008-U Region 4, Dallas, Office of the Director 79/03/19 App
- 790420103 Notice of deviation from Insp on 790324-0302
 * Region 4, Dallas, Office of the Director 79/03/14 1p
- 790420108 QA Program Insp Rept 9904056/79-01 on 790308-0302
 Noncompliance noted welder was not welding within specified average range
 HUNTEN, V. H., WHITEHEAD, S. E. Region 4, Dallas, Office of the Director 79/03/15 App
- 790420109 Act receipt of 790420 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept
 9904058/79-01
 POTAF008-U Region 4, Dallas, Office of the Director 79/05/15, 1p
- 790420109 Responds to NRC 790404 ltr re deviation noted in QA Program Insp Rept 9904058/79-01
 Corrective actions project
 Inspection P-8004, Revision 4, will be revised & notification of scheduled revision will be issued by 790430.
 HCFARMAN, J. E. Bargent & Lundy, Inc 79/04/25 App
- 790420103 Forwards QA Program Insp Rept 9904057/79-01 on 790312-14
 & notice of deviation
 POTAF008-U Region 4, Dallas, Vendor Inspection Branch 79/05/30 App
- 790420201 Notice of deviation from Insp on 790312-14
 * Region 4, Dallas, Office of the Director 79/03/26, 1p
- 790420202 QA Program Insp Rept 9904057/79-01 on 790312-14
 Noncompliance noted, project instruction covering project above steps did not meet requirements & some signatures on QA record submitted schedules not dtd.
 CORRELL, J. B., BOWMAN, L., HOLIF, J. J. Region 4, Dallas, Vendor Inspection Branch 79/05/30 10pp.
- 790420207 Act receipt of 790327 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept
 9904047/79-01
 POTAF008-U Region 4, Dallas, Vendor Inspection Branch 79/04/05 1p
- 790420207 Responds to NRC 790320 ltr re deviation noted in QA Program Insp Rept 9904047/79-01
 Corrective actions revised electrode checkout log & 2-3 limit established for evening electrode log ambient temp & humidity
 MILLER, T. D. Westinghouse Electric Corp 04-79-TSH 79/04/27 App
- 790420312 Forwards QA Program Insp Rept 9904047/79-01 on 790308-12
 & notice of deviation
 POTAF008-U Region 4, Dallas, Vendor Inspection Branch 79/05/03 App
- 790420314 Notice of deviation from Insp on 790308-12
 * Region 4, Dallas, Office of the Director 79/05/15 App
- 790420322 QA Program Insp Rept 9904047/79-01 on 790308-12
 Noncompliance noted inspector control of weld electrodes
 HUNTEN, V. H., MILLER, S. E., WHITEHEAD, S. E. Region 4, Dallas, Vendor Inspection Branch 79/05/15 10pp
- 790420326 Act receipt of 790312 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept
 9904038/79-01
 POTAF008-U Region 4, Dallas, Vendor Inspection Branch 79/05/26 1p.
- 790420326 Responds to NRC 790322 ltr re deviation noted in QA Program Insp Rept 9904038/79-01
 Corrective actions revision of main control procedure & procedure specs for welding machines
 AMMHO, R. Imbriusma - Marine Heavy Industries Co., Ltd. 04-79-016 79/05/12 App
- 790420326 Forwards QA Program Insp Rept 9904038/79-01 on 790308-12
 & notice of deviation
 POTAF008-U Region 4, Dallas, Vendor Inspection Branch 79/05/26 App
- 790420320 Notice of deviation from Insp on 790308-12
 * Region 4, Dallas, Office of the Director 79/05/16 1p.
- 790420344 QA Program Insp Rept 9904038/79-01 on 790308-12
 Noncompliance noted nonconsistent callir procedures for welding control
 IARRED, L., KIRKENDALL, D. M. Region 4, Dallas, Vendor Inspection Branch 79/05/26 11pp
- 790420401 Forwards QA Program Insp Rept 9904049/79-01 on 790312-15.
 No noncompliance noted
 POTAF008-U Region 4, Dallas, Vendor Inspection Branch 79/05/09 App
- 790420404 QA Program Insp Rept 9904009/79-01 on 790312-15 No noncompliance noted
 Major areas inspected implementation of 10CFR50 App 8 criteria & applicable codes & rules, including Insps, tests & weld metal control
 HUNTEN, V. H. Region 4, Dallas, Vendor Inspection Branch 79/04/04 App
- 790420502 Act receipt of 790420 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept
 9904057/79-01
 POTAF008-U Region 4, Dallas, Vendor Inspection Branch 79/05/09, 1p
- 790420501 Responds to NRC 790330 ltr re deviation noted in QA Program Insp Rept 9904057/79-01
 Corrective actions project
 Inspection P-8004, Revision 4, will be revised & notification of scheduled revision will be issued by 790430.
 HCFARMAN, J. E. Bargent & Lundy, Inc 79/04/25 App
- 790420503 Forwards QA Program Insp Rept 9904052/79-01 on 790325-01
 & notice of deviation
 POTAF008-U Region 4, Dallas, Office of the Director 79/04/04 App
- 790420507 Notice of deviation from Insp on 790325-01
 * Region 4, Dallas, Office of the Director 79/04/03 1p.
- 790420509 QA Program Insp Rept 9904052/79-01 on 790325-01
 Noncompliance noted: deviations re design verification & audits
 HOLIF, J. B., WHITEHEAD, S. E. Region 4, Dallas, Office of the Director 79/04/03, 10pp.

NONDOCKETED ITEMS

- 7903238025 Act receipt of 790301 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rpt
 99003317/79-01
 Region 4, Dallas, Vendor Inspection Branch
 79/03/10 1p
- 7903238028 Responds to NRC 790409 ltr re deviation noted in QA Program Insp Rpt 99003317/79-01
 Corrective actions noted deviation matter that has been reviewed & reminder items issued for corrective actions requests delayed next 30 days
 99003317/79-01
 Region 4, Dallas, Vendor Inspection Branch
 79/03/01 2p
- 7903238032 Forwarded QA Program Insp Rpt 99003317/79-01 on 790319-83 & notice of deviation
 BEYFRET, K V Region 4, Dallas, Office of the Director
 79/04/09 2p
- 7903238033 Notice of deviation from Insp on 790319-83
 Region 4, Dallas, Office of the Director
 79/04/09 4p
- 7903238035 QA Program Insp Rpt 99003317/79-01 on 790319-83
 Noncompliance noted failure to take preventive measures within established time for deviation identified in Insp Rpt 99003317/79-01 re mfg process control
 PORTER, E C, HARRIS, C J Region 4, Dallas, Vendor Inspection Branch
 79/04/05 12p
- 7903238038 Forwarded QA Program Insp Rpt 99003317/79-01 on 790411 No noncompliance noted
 PORTAFORS, U Region 4, Dallas, Vendor Inspection Branch
 79/04/05 1p
- 7903238039 QA Program Insp Rpt 99003317/79-01 on 790411 No noncompliance noted
 Major areas inspected Implementation of RPT BAREC CDR-9P-1A, including initial mfg meeting
 ANDERSON, B D, PORTAFORS, U, HARRIS, C J Region 4, Dallas, Vendor Inspection Branch
 79/04/05 3p
- 7903238048 Forwarded QA Program Insp Rpt 99003317/79-01 on 790318-15
 No noncompliance noted
 PORTAFORS, U Region 4, Dallas, Vendor Inspection Branch
 79/04/05 2p
- 7903238049 QA Program Insp Rpt 99003317/79-01 on 790318-15 No noncompliance noted
 Major areas inspected followup on 10CFR20 App B & applicable codes & standards
 Fabricated rigid rod structures-Paterson Part 2, 030
 COLLIER, M C, HARRIS, C J Region 4, Dallas, Vendor Inspection Branch
 79/04/05 4p
- 7903238051 Forwarded QA Program Insp Rpt 99003317/79-01 on 790325-07
 No noncompliance noted
 PORTAFORS, U Region 4, Dallas, Vendor Inspection Branch
 79/04/04 2p
- 7903238052 QA Program Insp Rpt 99003317/79-01 on 790325-07 No noncompliance noted
 Major areas inspected Implementation of 10CFR20 App B & applicable codes & standards
 Vendor corrective action re 10CFR21 rpt
 KELLEY, B B, HARRIS, C J Region 4, Dallas, Vendor Inspection Branch
 79/04/05 14p
- 7903238055 Act receipt of 790414, 0411 & 12 ltrs informing NRC of steps taken to correct deviation noted in QA Program Insp Rpt 99003317/79-01
 BEYFRET, K V Region 4, Dallas, Office of the Director
 79/05/10 1p
- 7903238064 Notice of deviation from Insp on 790327-03
 Region 4, Dallas, Office of the Director
 79/03/19 4p
- 7903238066 QA Program Insp Rpt 99003317/79-01 on 790327-03
 Noncompliance noted deviations re action on previous Insp findings, design control, post-weld heat treatment & mfg process control
 HARRIS, C J, HARRIS, H M, HARRIS, C J Region 4, Dallas, Vendor Inspection Branch
 79/03/13 17p
- 7903238068 Forwarded QA Program Insp Rpt 99003317/79-01 on 790328-003
 & notice of deviation
 PORTAFORS, U Region 4, Dallas, Vendor Inspection Branch
 79/04/02 3p
- 7903238071 Notice of deviation from Insp on 790328-003
 Region 4, Dallas, Vendor Inspection Branch
 79/04/02 1p
- 7903238073 QA Program Insp Rpt 99003317/79-01 on 790328-003
 Noncompliance noted calibr documentation for magnetic particle testing equipment not available
 PORTAFORS, U, HARRIS, C J Region 4, Dallas, Vendor Inspection Branch
 79/03/29 10p
- 7903238075 Act receipt of 790413 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rpt 99003317/79-01
 PORTAFORS, U Region 4, Dallas, Vendor Inspection Branch
 79/03/25 1p
- 7903238081 Responds to NRC 790405 ltr requesting add info on Item 5
 Corrective actions engineering change notice log revised to include 5 ltr requested in Item 5
 DEANE, G D Transamerica Global, Inc
 79/05/16 3p
- 7903238082 Act receipt of 790422 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rpt 99003317/79-01
 Add info requested re steps taken to correct & prevent recurrence of Item 5
 PORTAFORS, U Region 4, Dallas, Vendor Inspection Branch
 79/04/26 1p
- 7903238083 Responds to NRC 790502 ltr re deviation noted in QA Program Insp Rpt 99003317/79-01
 Corrective actions QA program & change control practice revised, mfg process investigated, internal audit schedule revised & engineering change notice log revised
 BEARE, E C Transamerica Global, Inc
 79/04/13 4p
- 7903238085 Forwarded QA Program Insp Rpt 99003317/79-01 on 790325-07 & notice of deviation
 PORTAFORS, U Region 4, Dallas, Vendor Inspection Branch
 79/04/25 2p
- 7903238087 Notice of deviation from Insp on 790325-07
 Region 4, Dallas, Office of the Director
 79/03/19 4p
- 7903238089 QA Program Insp Rpt 99003317/79-01 on 790325-07
 Noncompliance noted QA program & change control practice not consistent w/10CFR20 App B & applicable codes & standards
 HARRIS, C J Region 4, Dallas, Office of the Director
 HARRIS, C J, HARRIS, C J Region 4, Dallas, Vendor Inspection Branch
 79/03/19 12p
- 7903238092 Act receipt of 790412 & 0312 ltrs informing NRC of steps taken to correct deviation noted in QA Program Insp Rpt 99003317/79-01
 PORTAFORS, U Region 4, Dallas, Vendor Inspection Branch
 79/03/25 1p
- 7903238093 Submits add info re QA Program Insp Rpt 99003317/79-01
 NRC 790422 request Describes method of documentation used for training & indoctrination
 HERATZ, F Herata Valve Solving Co., Ltd., Kansas City
 79/05/02 1p
- 7903238095 Act receipt of 790422 ltr re steps taken to correct deviation noted in QA Program Insp Rpt 99003317/79-01
 PORTAFORS, U Region 4, Dallas, Vendor Inspection Branch
 79/04/03 1p
- 7903238096 Responds to NRC 790502 ltr re deviation noted in QA Program Insp Rpt 99003317/79-01
 Corrective actions valve machined & reworked, detailed welding procedures revised & applicable welding records examined re interpretation from per JB code
 HERATZ, F Herata Valve Solving Co., Ltd., Kansas City
 79/04/12 3p
- 7903238098 Forwarded QA Program Insp Rpt 99003317/79-01 on 790312 & 0412 & notice of deviation
 PORTAFORS, U Region 4, Dallas, Vendor Inspection Branch
 79/05/02 3p

NONDOCKETED ITEMS

27

- 7902700275 Notice of deviation from Insp on 790112 & 16-18
* Region 4, Dallas, Office of the Director 79/01/31 3pp
- 7902700282 SA Program Insp Rept 99000282/79-01 on 790112 & 16-18
Noncompliance noted qualification of handeling welding
procedure specs not consistent w/requirements
BARNES, D M, HANNCUTT, D M Region 4, Dallas, Vendor Inspection
Branch 79/01/31 11pp
- 7902700283 Act receipt of ltr informing NRC of steps taken to correct
deviation noted in SA Program Insp Rept 99000283/79-01
POTAPPOVE, U Region 4, Dallas, Vendor Inspection Branch.
79/05/02 1p
- 7902700272 Response to NRC 790412 ltr re deviation noted in SA Program
Insp Rept 99000272/79-01 Corrective actions welding
procedure revised & pertinent addenda distributed to weld
shop
HARNEY, D B Brevett Industries, Inc 79/05/10 3pp
- 7902700276 Forward SA Program Insp Rept 99000276/79-01 on 790319-22
& notice of deviation
POTAPPOVE, U Region 4, Dallas, Vendor Inspection Branch
79/04/12 2pp
- 7902700282 Notice of deviation from Insp on 790119-22
* Region 4, Dallas, Office of the Director 79/04/12 3pp
- 7902700291 SA Program Insp Rept 99000291/79-01 on 790319-22
Noncompliance noted mfg process control welding not
consistent w/unid procedure used & distribution of
weld procedure addenda not consistent w/unid criterion
BARNES, D M, HANNCUTT, D M, HANNCUTT, D M Region 4, Dallas,
Vendor Inspection Branch 79/04/04 11pp
- 7902700294 Act receipt of 790202 ltr informing NRC of steps taken to
correct deviation noted in SA Program Insp Rept
99000294/79-01
POTAPPOVE, U Region 4, Dallas, Vendor Inspection Branch
79/05/17 1p
- 7902700290 Response to NRC 790412 ltr re deviation noted in SA Program
Insp Rept 99000290/79-01 Corrective actions revision of
Procedure DC-2 to delete requirement of specifying issue
date of codes & vds for design descriptions
DERIDIO, F P Gibbs & Hill, Etc. Inc. of Onavo Corp 1
79/05/02 3pp
- 7902700291 Forward SA Program Insp Rept 99000291/79-01 on 790326-03
& notice of deviation
POTAPPOVE, U Region 4, Dallas, Vendor Inspection Branch
79/04/13 2pp
- 7902700294 Notice of deviation from Insp on 790326-03
* Region 4, Dallas, Office of the Director 79/04/12 1p
- 7902700294 SA Program Insp Rept 99000294/79-01 on 790326-03
Noncompliance noted design descriptions did not specify
issue date of applicable codes & vds & design checklist
not used on all design reviews
BARNES, D M, HANNCUTT, D M, HANNCUTT, D M Region 4, Dallas, Vendor
Inspection Branch 79/04/12 10pp
- 7902700291 Response to NRC 790202 ltr re deviation noted in SA Program
Insp Rept 99000291/79-01 Corrective actions copies of
acknowledgments of 790202 instructions were signed
by mfg room attendant & QC Inspector
HARRIS, D M Southwest Fabricating & Welding Co (subs of IU
International Corp 1 79/03/15 3pp
- 7902700293 Act receipt of 790202 & 0515 ltr informing NRC of steps
taken to correct deviation noted in SA Program Insp Rept
99000293/79-01
POTAPPOVE, U Region 4, Dallas, Vendor Inspection Branch
79/05/02 1p
- 7902700292 Act receipt of 790202 ltr informing NRC of steps taken to
correct deviation noted in SA Program Insp Rept
99000292/79-01 Response add info re method of documenting
shaded instructions to provide auditable record
POTAPPOVE, U Region 4, Dallas, Vendor Inspection Branch
79/04/26 3pp
- 7902700291 Response to NRC 790202 ltr re deviation noted in SA Program
Insp Rept 99000291/79-01 Corrective actions: temp
modification within design add has been corrected. Hds have
maintained air temp within 350 F to 330 F
HARRIS, D M Southwest Fabricating & Welding Co (subs of IU
International Corp 1 79/03/26 10pp
- 7902700292 Forward SA Program Insp Rept 99000292/79-01 on 790129-3202
& notice of deviation
POTAPPOVE, U Region 4, Dallas, Vendor Inspection Branch
79/02/26 2pp
- 7902700292 Notice of deviation from Insp on 790129-3202
POTAPPOVE, U Region 4, Dallas, Vendor Inspection Branch
79/02/21 1p
- 7902700297 GA Program Insp Rept 99000297/79-01 on 790129-3202
Noncompliance noted storage of coated electrodes not
consistent w/criterion 721 of 10CFR50 App B & temp
requirements of Procedure - NRC-1, Revision 0
BARNES, D M, HANNCUTT, D M, HANNCUTT, D M Region 4, Dallas,
Vendor Inspection Branch 79/02/21 2pp
- 7902700297 Act receipt of 790202 & 0425 ltr informing NRC of steps
taken to correct deviation noted in SA Program Insp Rept
99000297/79-01
POTAPPOVE, U Region 4, Dallas, Vendor Inspection Branch
79/05/02 1p
- 7902700292 Forward response to 790402 request for add info re
deviation noted in SA Program Insp Rept 99000292/79-03
HARRIS, D M Bendix Corp 79/04/25 10pp
- 7902700292 Request add info to 790202 response re steps taken to
correct deviation noted in SA Program Insp Rept
99000292/79-03
SEFRIT, K V Region 4, Dallas, Office of the Director
79/04/02 2pp
- 7902700298 Response to NRC 790104 ltr re deviation noted in SA Program
Insp Rept 99000298/79-03 Corrective actions training &
inspection program will be revised & procedure developed
for handling & storage of items to prevent deterioration
HARRIS, D M Bendix Corp 79/02/09 5pp
- 7902700298 Forward GA Program Insp Rept 99000298/79-03 on 790211-13 &
notice of deviation
SEFRIT, K V Region 4, Dallas, Office of the Director
79/03/04 2pp
- 7902700291 Notice of violation from Insp on 790211-15
* Region 4, Dallas, Office of the Director 79/01/04 3pp
- 7902700291 SA Program Insp Rept 99000291/79-03 on 790211-15
Noncompliance noted training procedure not revised to
include handling & storage not accomplished w/approved
procedures & minutes of training meeting not maintained
BARNES, D M, HANNCUTT, D M, HANNCUTT, D M Region 4, Dallas,
Vendor Inspection Branch 79/12/29 10pp
- REGID REGULATORY GUIDELINE
- 7902700293 Corrects 790412 ltr forwarding draft reg guide - "Lightning
Protection for Nuclear Power Plants"
STANEC, E Bechtel Power Corp (subs of Bechtel Corp 1 79/04/19
1p
- 7902700294 Comments on proposed Revision 2 to Reg Guide 1.0
 wording should be changed as follows: "Included in one year
of experience, should be training & experience sufficient to
qualify individual"
BASTIE, A Public Service Co of Oklahoma 79/04/09 2pp
- 7902700292 Value/Impact statement for proposed Revision 3 to Reg Guide 1.0
135: "Exercise Value of Unsubstantiated Tandom in Pressurized
Containment"
* Office of Standards Development 79/04/30 2pp
- 7902700294 "Assumptions Used for Evaluating Light Heat Cooled Nuclear
Power Plant Basis Distances for Purposes of 10CFR100"
* Office of Standards Development 79/03/31 10pp
- 7902700294 "Assumptions Used for Evaluating Potential Radiological
Consequences to Public from Design Basis Accidents in
Light Heat Cooled Nuclear Power Plants for Purposes of
10CFR100 to 31" Value/Impact Statement end
* Office of Standards Development 79/03/31 10pp
- 7902700297 Comments on proposed Reg Guide 1.144 disagrees w/proposed
position requiring internal audits to be conducted annually
becausde scope of procurement actions not requiring
external audits to be extended to include source verification.
VOLLETTE, J B Bechtel Power Corp (subs of Bechtel Corp 1
79/03/01 3pp

NONDOCKETED ITEMS

- 770407079 Comments on proposed Reg Guide 1.14 recommends endorsement of 116 w/ regard to scheduling of internal audits. Suggests CSB be amended to include acceptable alternative methods for use by customers, rather than auditing. OSMRE, J. M. Atomic Industrial Forum 7/9/04/05 App
- 770407080 Comments on proposed Reg Guide 0.03 guide is sound & strengthens control. Operational considerations re re-keeping & insufficient initiative given to institution of prof health physical. OSMRE, J. M. Atomic Industrial Forum 7/9/03/29 App
- 770407091 Comments on proposed Reg Guide 1.14 recommends no specific revision audit frequency. Endorsement of audit as alternative. EELMAN, H. S. Cleveland Electric Illuminating Co 7/9/03/26 App
- 770407074 Comments on proposed Reg Guide 0.02 usage interval for determining monitoring requirements is unspecified & conflicts w/ Reg Guide 1.0-07 Refs cited are out of date & should be updated. BLANK, W. H. WETTERMAN, W. Vet Admin Hosp LA, California 7/9/04/03 App
- 770407017 Forwards 7704017 for discussing Reg Guide 1.180 requirements for cable penetrations. WOLF, R. L. AORIS - Advisory Committee on Reactor Safeguards 7/9/03/02 App
- 770407012 Discusses 7704018 for re evaluation of cable penetrations. Recent tests of fire barriers above threshold & special system products to withstand 2-4 8-10V furnace fire. ELIASH, A. N. Sergeant & Lundy, Inc 7/9/04/09 App
- 770407017 Proposed Reg Guide 0.25 1. "Determining Presetting Forces for Ints of Presettable Concrete Containments" * Office of Standards Development 7/9/04/03 App
- 770407018 Drafts values/instant statement for proposed Reg Guide 1.12 1. "Determining Presetting Forces for Ints of Presettable Concrete Containments" * Office of Standards Development 7/9/04/02 App
- 770407013 Comments on proposed Reg Guide 0.03 disagree that relationship between radiation dose & biological effects are well suited only for high doses. WILSON, C. Environmental Policy Institute 7/9/04/20 App
- 770407013 Comments on proposed Reg Guide 1.0, education and experience requirements for personnel are needlessly high. PARKER, G. D. Duke Power Co 7/9/04/22 App
- 770407018 Comments on proposed Reg Guide 0.03 objects to survey frequency schedule. Sites radiation-producing equipment not addressed & contamination level tables not provided. WILSON, C. Environmental Policy Institute 7/9/04/20 App
- 770407048 Comments on proposed Revision 2 to Reg Guide 1.8 recommends Paragraphs 2a-2c under Part C be revised to recognize any knowledge gained through best experience as well as formal age training. GALE, L. F. NUCLEARPP Power & Light Co AECN-77041 7/9/04/20 App
- 770407045 Comments on proposed Reg Guide 7.0 fails to specify requirements to ensure that occupational radiation exposures are ALARA. BERGER, C. Environmental Policy Institute 7/9/04/13 App
- 770407009 Comments on proposed Reg Guide 2.0 opposes guide AMS-101 for emergency planning as inadequate. WILSON, C. Environmental Policy Institute 7/9/04/13 App
- 770407009 Comments on proposed Reg Guide 1.8 requirements not consistent w/ extensive testing. Suggests change in additional & experience criteria. GALE, L. F. NUCLEARPP Power & Light Co AECN-77041 7/9/04/20 App
- 770407047 Comments on proposed Revision 4 to Reg Guide 0.03 experience w/ radiation exposure Co data does not warrant reduction of allowable radiation doses for nuclear power plant personnel. GALE, L. F. Affiliation Unknown 7/9/04/10 App
- 770407053 Comments on proposed Reg Guide 1.14. "Adding of QA Programs for Nuclear Power Plants" fails to recognize methods other than audits for QA programs. Mandates audit scheduling may be insufficient. MARTIN, L. L. American Society of Quality Control 7/9/04/10 App
- 770407045 Comments on proposed Reg Guide 1.0 "Guide for Preparation of Applications for Medical Programs" objects to this. Question survey meter & sensitivity requirement for alpha wipe tests. HARTSHORN, E. St. Anthony Hosp. H/ONI 7/9/04/19 App
- 770407048 Comments on proposed Revision 3 to Reg Guide 1.0 "Person Detection & Training" different & add qualifications identified in Regulatory Position 3 add confusion & are not necessary. HALL, E. M. Affiliation Unknown 7/9/04/19 App
- 770407054 Comments on proposed Revision 2 to Reg Guide 1.8 Section 5 should be revised to more accurately agree w/ requirements of ANSI 3.1-1978. JOHNSON, M. P. Yankee Atomic Electric Co WVC 7/9/13 7/9/04/23 App
- 770407062 Comments on proposed draft reg guide, "Lightning Protection for Nuclear Power Plants" authors have confused stage of lightning stroke w/ lightning surge distribution in crucial since difference in magnitude is extremely significant. STADE, R. S. Bechtel Power Corp (subs of Bechtel Corp.) 7/9/04/16 App
- 770407048 Drafts Reg Guide 3.101, "Calculational Models for Estimating Radiation Doses to Man From Airborne Radioactive Materials Resulting From Fuel Handling Operations" * Office of Standards Development 7/9/04/01 App
- 770407070 Comments on proposed Reg Guide 1.144 does not agree w/ Regulatory Position CSB101 internal audit suggests reg guide be modified to state that audits should be scheduled at frequently recommended w/ status & importance of activity. HILBORN, R. E. Eon Nuclear Co - Inc (subs of Eon Corp.) 7/9/04/17 App
- 770407049 Comments on proposed Reg Guide 1.07 problems w/ concern of other reg guides. GARDINER, E. Florida Power & Light Co L-77-104 7/9/04/27 App
- 770407049 Comments on proposed Reg Guide 3.11 suggest editorial correction in Paragraph C (311) relating word "particular" * GILBERT, C. L. Everline Instrument Corp C196200 7/9/04/27 App
- 770407049 Comments on proposed Reg Guide 1.120 Revision 1 for "Personnel Incident" condition to occur, battery would have to be receiving an overcharge w/ instantaneous failure of ventilation system. BOETTCHER, J. T. Power Engineering Society 7/9/04/24 App
- 770407049 Comments on proposed Reg Guide 1.8 Revision 2 EEL health physics test force believes qualifications for radiation protection manager are adequately addressed in existing reg guide. JENSEN, T. A. Pacific Gas & Electric Co 7/9/04/27 App
- 770407052 Comments on proposed Reg Guide 1.9 does not agree w/ resolution of comment on Position C.9. JOHNSON, M. P. Yankee Atomic Electric Co WVC 7/9/04/23 App
- 770407049 Comments on proposed reg guide 1.121 draft guide sets forth Concrete Radiation Shielding for Nuclear Power Plant" draft needs guidelines related to biological shielding design. HUGHES, G. obsolete code WVC-PG-01A 7/9/04/26 App
- 770407052 Comments on proposed Reg Guide 2.6 recommends AMC w/ 1000000 reg guide & formally endorse existing standards/ANSI/ANSI 15.10-1978. CAMERON, R. B. Comments, Dept of National Bureau of Standards 7/9/04/01 App
- 770407055 Comments on proposed Reg Guide 1.8, Revision 2 retirement for 3-month indoctrination/training program for individuals who will be supervising preoperational tests is unduly restrictive. COAN, L. H. Northwest Utilities 7/9/04/23 App
- 770407049 Comments on proposed reg guide 1.121 disagrees w/ any interpretation of AMC regulations that would apply Co occupational law doses. O'DONNELL, P. E. Eon Services, Inc (subs of Eon Corp.) 7/9/04/23 App
- 770407052 Notifies that comment re Reg Guide 1.121 prepared by 180X-202-1974 working group will be forwarded. GARDINER, C. A. Bechtel Power Corp (subs of Bechtel Corp.) 7/9/04/24 App
- 770407058 Comments on proposed Reg Guide 1.81 Section 0.2 each cell connector configuration should not be tested. Requested rewording. GARDINER, C. A. Bechtel Power Systems (subs of Bechtel Corp.) 7/9/04/24 App

NONDOCKETED ITEMS

277

--7906210040 Comments on Reg Guide 1.31, page 1.31-3 Paragraphs 9 & 11: proposals would not provide quoted amount of heat
BURNED, S. Affiliation Unknown 79/06/23 1p

7906210041 Comments on proposed Reg Guide 10 XEE suggests clarification of terms "anti" & "waste disposal"
WELSH, J. D. Allegan General Hosp 79/04/23 App

7906210042 Comments on proposed reg guide 1 XEE NRC quality groups: AMS safety classes & ASME 311 classes are analogous & should be used to define values
BUCKLEY, C. F. American National Standards Institute 79/04/24 1p

7906210043 Comments on proposed reg guide 1 XEE specific concepts need clarification in particular, interpretation of ASME Code Section 31, definition of reg guide terms & implementation of reg guide
CORRECEDA, M. Affiliation Unknown 79/04/19 1p

7906210044 Forwards Draft 1 to proposed Revision 2 of Reg Guide 1.94, preliminary value/impact statement & ASME/ASME HAS 2 3-1979, which relate to QA requirements for installation step 5 testing of structural concrete, steel, soils & foundations
ALBERTO, D. A. Division of Engineering Standards 79/05/16 7pp

--7906210045 Preliminary value/impact statement on QA requirements for installation, step 5 testing of structural concrete, structural steel, soils & foundations during construction of nuclear power plants
* Division of Engineering Standards 79/05/11 App

--7906210046 ASME/ASME HAS 2 3
ASME/ASME HAS 2 3-1979 "Supplementary QA Requirements for Installation Step 5 Testing of Structural Concrete, Structural Steel, Soils & Foundations During Construction of Nuclear Power Plants"
* American Society of Mechanical Engineers 79/05/16 20pp

7906210047 Proposed Revision 2 to Reg Guide 3.44, "Parameter Intrusion Alarm Sys"
* Office of Standards Development 79/05/31 20pp

RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

7906210048 Research Info Ltr 23 results of initial series of three incineration experiments on combustibility limits of post-reactor particulate LWRs Fuel debris in sodium pool Forwards
ALBERTO, D. A. & MARRAS, C. D. Office of Nuclear Regulatory Research 79/05/10 7pp

--7906210049 NUREG/CR-3243
"Debris Bed Studies & Experiments at Sandia Labs"
* RIVARD, J. B. Sandia Laboratories FIN A-1181 GAN79-0299 78/07/31 5pp Available at NTE

--7906210051 NUREG/CR-3481
"Debris Bed Studies & Experiments at Sandia Labs"
* RIVARD, J. B. Sandia Laboratories FIN A-1181 GAN79-0299 78/07/31 5pp Available at NTE

7906210052 "Code Assessment & Applications Program improved RELAP4 Jet Pump Model"
* KODS, E. E. Idaho National Engineering Laboratory FIN A-6009 79/04/30 40pp

7906210054 "Water Reactor Research Directorate" monthly rept for Mar 1979
* KODS, E. E. Idaho National Engineering Laboratory 79/04/30 20pp

7906210055 "REACOR/MODEA Computer Program for Subcomponent Analysis of Nuclear Reactor Containment - User's Manual"
* KODS, E. E. & KODS, E. E. Idaho National Engineering Laboratory FIN A-6042 79/03/31 300pp

7906210056 "Code Development & Analysis Program, Fuel Vapor Pressure"
* KODS, E. E. & KODS, E. E. FIN A-6046 79/04/30 10pp

7906210057 "NRC-Related Waste Mgt Resources BNL Capabilities in Waste Mgt Resource" internal rept
* BNL/NE-2128, D. O. Brookhaven National Laboratory FIN A-3016 79/04/30 12pp

7906210058 "Monthly progress rept/Feb 1979"
* Oak Ridge National Laboratory FIN B-301 OML/ED/CI-8-07 79/02/28 8pp

7906210059 "Forecasting Electricity Demand by States in US an Annual Basis," interim rept for Mar 1979
* CHARN, B. Oak Ridge National Laboratory FIN B-0196-B 79/04/30 8pp

7906210060 "PSP/LCPT Lead Rod Program Tests LIR-3, LIR-4 & LIR-5, Debris Load Rep"
* VARRACELLE, D. J. & GARNER, R. M. ED & G. Inc FIN A-6113 79/04/30 100pp

7906210061 Research Info Ltr 20 summaries & comments on results of research published in NUREG/CR-3095, "Nuclear Safety Guide."
* LEVINE, R. Office of Nuclear Regulatory Research 79/04/30 4pp

7906210062 "Structural Integrity of Water Reactor Pressure Boundary Components," monthly progress rept for Feb 1979
* LOUIS, F. J. Navy Dept. of Naval Research Laboratory 6293-04M-FAL, NA 79/03/16 5pp

7906210063 "Program for Standardized Analysis of Fuel Shipping Containers," quarterly summary-Jan-Mar 1979
* MONTGOMERY, D. E. & MONTGOMERY, D. E. Oak Ridge National Laboratory FIN B-0172 OML/ED/CI-8-79 79/04/30 7pp

7906210064 "Review Assessments of Fuel Cycle Facilities," progress rept for Mar 1979
* ZITTEL, M. E. Oak Ridge National Laboratory FIN B-0279 OML/ED/CI-8-79 79/03/31 4pp

7906210065 Research Info Ltr 44 radiation doses to coast workers at operating nuclear power plant sites. Submits results of completed research Forwards NUREG/CR-3426, Vol 2
* LEVINE, R. Office of Nuclear Regulatory Research 79/05/04 3pp

7906210066 "Review of Critical Experiments Performed for Fuel Cycle Safety," quarterly summary-Jan-Mar 1979
* MONTGOMERY, D. E. & MONTGOMERY, D. E. Oak Ridge National Laboratory FIN B-0409 OML/ED/CI-8-79 79/04/30 11pp

7906210067 "PURE Steam Generator Tube Integrity Program," monthly progress rept for Apr 1979
* CLARK, R. A. Battelle Memorial Institute Pacific Northwest Laboratory FIN B-0297 79/05/31 1p

7906210068 "Application of Internal Friction Nondestructive Evaluation Technique for Detecting Incident Cracking of Supra-Lines & Pipes in SHR Piping Run," progress rept 10 for 790621-27
* Davidson Associates, Inc NRC-04-78-342 79/05/31 10pp

7906210069 "ThreadPin Shed Impingement, Population Response," progress rept/Dec-1978
* COVATANT, C. C. & HOLMAN, R. E. Oak Ridge National Laboratory FIN B-0406 79/04/30 5pp

7906210070 "Time Protection in Operating Nuclear Power Stations: Quad-Cities Stations 1 & 2 BCR Review"
* HOLMAN, R. E. Brookhaven National Laboratory FIN A-0107 79/04/12 4pp

7906210071 "Anisotropic Deformation/Flow Relationships for Inservice Monitoring of Nuclear Pressure Vessels," monthly rept
* COVATANT, C. C. & HOLMAN, R. E. Oak Ridge National Laboratory FIN B-0406 79/04/30 5pp

7906210072 "ThreadPin Shed Impingement, Population Response," quarterly progress rept-Jan-Mar 1979
* COVATANT, C. C. & HOLMAN, R. E. Oak Ridge National Laboratory FIN B-0406 79/04/30 4pp

7906210073 "ThreadPin Shed Impingement, Effect of Cold Stress," progress rept, Jul-Aug 1978
* COVATANT, C. C. & HOLMAN, R. E. Oak Ridge National Laboratory FIN B-0406 79/06/05 2pp

7906210074 "Mar 1979 Monthly Highlights," OML of Nuclear Regulatory Research Programs, Div of Reactor Safety Research at ORNL
* MONTGOMERY, D. E. Oak Ridge National Laboratory OML/NUREG/TH-0 79/04/06 36pp

7906210075 "Geophysical Investigations of Areas, OH Earthquake Zone" covering cities progress rept, Aug 1978-Feb 1979
* MANN, F. J. & MANN, F. J. Michigan Univ. of Michigan-UNIVERSITY-79-0 79/03/31 16pp

7906210076 "Thermal-Hydraulic LWR Safety Experiments," monthly highlight rept for Apr 1979
* JENSEN, C. C. Brookhaven National Laboratory FIN A-3026 79/04/30 4pp

NONDOCKETED ITEMS

- 7904020172 "Div of Reactor Safety Research-DBS, Progress." Apr 1979 monthly highlight report
HWATT, F R Oak Ridge National Laboratory 79/03/09 36pp
- 7904020173 "Lightwater Reactor Thermal Hydraulic Development Program" monthly highlight 1tr for Apr 1979
JONES, G C Brookhaven National Laboratory FIN A-2643 79/04/20 4pp
- 7904020183 "Short Segmented Cost Code Development & Validation Program" monthly highlight 1tr for Apr 1979
WATKINS, A K, CHODURA, K J Brookhaven National Laboratory FIN A-2619-7 79/04/20 4pp
- 7904020183 "NRC Bloodworth/Emergency Control Ctr Program" monthly progress report for Apr 1979
BARNETT, D M General Electric Co./Nuclear Energy Products Div ARC-24-76-213 79/03/09 26pp
- 7904020183 "NRC Safety Program" monthly highlight 1tr for Apr 1979
BARNETT, D M Brookhaven National Laboratory FIN A-2616 79/03/10 3pp
- 790402017 "Advanced Reactor Safety Analysis Technical Assistance Reactor Projects" monthly highlight report for Apr 1979
BARR, R A Brookhaven National Laboratory FIN A-2600 79/03/13 5pp
- 7904020051 "Thermal Fluid Behavior Program/Operational Transient Test Series OPTMAN I-2 Experiment Spec Document"
CHODURA, K J, CHODURA, K J, HOGAN, R A Idaho National Engineering Laboratory FIN A-2601 79/04/20 2pp
- 7904020027 "Stress Corrosion Cracking of PWR Steam Generator Tubing" monthly highlight report for Apr 1979
WATKINS, G C Brookhaven National Laboratory 79/03/09 6pp
- 7904020182 "Thermal Reactor Safety Code Development" monthly highlight 1tr report for Apr 1979
CHODURA, K J, BARR, R A Brookhaven National Laboratory FIN A-2614-9 79/04/20 10pp
- 7904020181 Research Info Ltr 58 forwards NUREG/CR-0465. "RSE User's Manual for Fault Tree Analysis" by Sandra Loh
LEVINE, B Office of Nuclear Regulatory Research 79/05/10 2pp
- 7904020113 "Florida Products in Aquatic Environments" quarterly progress report for Jan-Mar 1979
CHODURA, K J, BARR, R A, CHODURA, K J Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2053-9 79/03/31 36pp
- 7904020116 Interim progress report: "Chemical Effluents in Surface Waters From Nuclear Power Plants"
HARRISON, P Lawrence Livermore Laboratory FIN A-0118 79/04/09 17pp
- 7904020120 Interim progress report: "Chemical Effluents in Surface Waters From Nuclear Power Plants"
HARRISON, P Lawrence Livermore Laboratory FIN A-0119 79/04/10 17pp
- 7904020001 Quarterly progress report for Jan-Mar 1979. "Bibliography of Study on Combustion Risks"
BARKER, L M Purdue Univ, HELLES, D R Texas Univ, LIDIA, E G Pittsburgh Univ of MD-24-76-323 79/04/10 7pp
- 7904020052 "Bibliography of Study on Combustion Risks"
Purdue Univ 79/04/31 6pp
- 7904020170 "LOCA Test Series Test LDC-3 Experiment Predictions"
YACKEL, T R, HELLES, D R, SPORER, T M EG & G, Inc FIN A-0041 79/04/30 160pp
- 7904020034 "Code Development & Analysis Program FRAPCON-4 Uncertainty Analysis Option"
PECK, S G EG & G, Inc FIN A-0030 COMP-TR-033 79/04/30 40pp
- 7904020035 "Summary & Assessment of Return to Normalcy Selling Phenomena During Shutdown Tests Conducted at DEL"
BARTON, A H, TOLMAN, E L EG & G, Inc FIN A-0076 LTR 99-99 79/04/03 6pp
- 7904020038 "Inhalation Dose Determination Resulting From Steam Generator Suppression Tank Failure and From Release Directly to LOST Containment Following LDC-2 Shutdown"
SCHNEIDER, R R EG & G, Inc, FIN A-0048 79/01/16 14pp
- 7904020028 "Best Estimate Prediction for LOFT Nuclear Experiment LDC-3"
KEE, J J, SPORER, T M EG & G, Inc FIN A-0048 79/04/30 96pp
- 7904020021 "Stress Analysis of Modified Rake Assemblies w/Positive Loss Services for Gap Screen"
FIMBLE, G J EG & G, Inc FIN A-0048 79/01/23 36pp
- 7904020031 "Refined Analysis of Effects on LOFT Containment Bleeding Resulting From Main Steam & Feedwater Breaks"
HARRIS, W R EG & G, Inc FIN A-0048 79/01/16 33pp
- 7904020025 "FRAPCON-4 Computer Code for Steady State Analysis of PWR Plant Mode"
LEATO, R T, MOORE, D R, SCHNEIDER, R R Idaho National Engineering Laboratory FIN A-0048 79/05/20 146pp
- 7904020042 "Postirradiation Metallurgical Techniques to Estimate LOFT Peak Cladding Temps"
OLSON, C B Idaho National Engineering Laboratory FIN A-0048 79/02/28 6pp
- REVIEW GROUP NRC RESEARCH REVIEW GROUP
- 7904020183 "Pressure-verified minutes of Risk Assessment Review Group 790402-00 meeting in Berkeley, CA"
AUSTIN, J M Office of Policy Evaluation 79/03/13 13pp
- 7904020027 Notification of 790402-09 meeting w/Project Nucleus
Schnitzer, Fuel Behavior Research Branch of MC & JBSI in Idaho Falls, ID for info exchange on tests & cladding
OLSON, C B Fuel Behavior Branch 79/05/10 3pp
- 7904020039 Forwards draft summary report from Sandra Loh re effect of age on fibre resistant electrical cable
PELT, R Division of Reactor Safety Research 79/03/10 1p
- 7904020037 Draft summary report: "Comparison of Polymer Flammability & Determination of Loss of Fire Resistant Additives W/ing"
OLSON, C B, SCHNEIDER, R R Battelle Laboratory 79/05/10 3pp
- 7904020024 Summary of 790402 meeting of LOFT Review Group in Idaho Falls, ID re presentation of LDC-2 data comparisons, cladding thermocouple accuracy & effect on peak & limitation of LOFT data
BART, J D, MOORE, D R, SCHNEIDER, R R Division of Reactor Safety Research 79/01/23 170pp
- 7904020049 Notification of 790413 meeting w/LOFT Review Group in Idaho Falls, ID re Idaho LDC-3 results
SCHNEIDER, R R Division of Reactor Safety Research 79/04/19 2pp
- 7904020048 Summary of 790107 meeting of LOFT Review Group in Oak Ridge, TN re power ramp testing, experimental safety analysis, long-range experimental plans & test predictions
HARRIS, W R, MOORE, D R, SCHNEIDER, R R Division of Reactor Safety Research 79/01/07 136pp
- RE RESEARCHERS
- 7904020012 Notification that unofficial transcript of NRC 790402 meeting & ASLS report in clearance rule proceeding is available in FORTRAN in web part of formal or informal record of division of authors discussed per OGDW 103.
SCHNEIDER, R R Office of the General Counsel 79/06/07 1p
- GOFF POSITION PAPERS BEFORE THE COMMISSION
- 7904020125 BEEV-77-561
Review Phase I of systematic evaluation program to obtain approval for pressurized water reactor of plant-specific nuclear Reactors NRC approve continuation of program plan
CASE, E C Office of Nuclear Reactor Regulation 79/06/06 4pp
- 7904020148 BEEV-77-297
Inform Commission of receipt of Transacation, Inc 790402 application for license to export highly enriched U to Denmark
BIRDA, J R Office of International Programs 79/04/26 1p

7906001079 SECY-77-839
Advise Commissioners of plans to convert provisional OLE to full-time Licenses
CABE, E. G. Office of Nuclear Reactor Regulation 77/01/16 App

7906000079 SECY-77-839
Request review
BHEA, J. R. Office of International Programs 79/04/04 App

7906000081 SECY-77-839
Request review
BHEA, J. R. Office of International Programs 79/04/04 App

7906000083 SECY-77-839
Request review
BHEA, J. R. Office of International Programs 79/04/04 App

7906000085 SECY-77-839
Request review
BHEA, J. R. Office of International Programs 79/04/04 App

7906000087 SECY-77-839
Request review
BHEA, J. R. Office of International Programs 79/04/04 App

7906000089 SECY-77-839
Request review
BHEA, J. R. Office of International Programs 79/04/04 App

7906000091 SECY-77-839
Request review
BHEA, J. R. Office of International Programs 79/04/04 App

7906000093 SECY-77-839
Request review
BHEA, J. R. Office of International Programs 79/04/04 App

7906000095 SECY-77-839
Request review
BHEA, J. R. Office of International Programs 79/04/04 App

7906000097 SECY-77-839
Request review
BHEA, J. R. Office of International Programs 79/04/04 App

7906000101 SECY-77-839
Request review
BHEA, J. R. Office of International Programs 79/04/04 App

7906000103 SECY-77-839
Request review
BHEA, J. R. Office of International Programs 79/04/04 App

7906000105 SECY-77-839
Request review
BHEA, J. R. Office of International Programs 79/04/04 App

7906000107 SECY-77-839
Request review
BHEA, J. R. Office of International Programs 79/04/04 App

7906000109 SECY-77-839
Request review
BHEA, J. R. Office of International Programs 79/04/04 App

7906000111 SECY-77-839
Request review
BHEA, J. R. Office of International Programs 79/04/04 App

7906000078 SECY-77-005
Request review
BHEA, J. R. Office of International Programs 79/05/01 App

7906000079 SECY-77-005
Request review
BHEA, J. R. Office of International Programs 79/05/01 App

7906000080 SECY-77-005
Request review
BHEA, J. R. Office of International Programs 79/05/01 App

7906000081 SECY-77-005
Request review
BHEA, J. R. Office of International Programs 79/05/01 App

7906000082 SECY-77-005
Request review
BHEA, J. R. Office of International Programs 79/05/01 App

7906000083 SECY-77-005
Request review
BHEA, J. R. Office of International Programs 79/05/01 App

7906000084 SECY-77-005
Request review
BHEA, J. R. Office of International Programs 79/05/01 App

7906000085 SECY-77-005
Request review
BHEA, J. R. Office of International Programs 79/05/01 App

7906000086 SECY-77-005
Request review
BHEA, J. R. Office of International Programs 79/05/01 App

7906000087 SECY-77-005
Request review
BHEA, J. R. Office of International Programs 79/05/01 App

7906000088 SECY-77-005
Request review
BHEA, J. R. Office of International Programs 79/05/01 App

7906000089 SECY-77-005
Request review
BHEA, J. R. Office of International Programs 79/05/01 App

7906000090 SECY-77-005
Request review
BHEA, J. R. Office of International Programs 79/05/01 App

7906000091 SECY-77-005
Request review
BHEA, J. R. Office of International Programs 79/05/01 App

7906000092 SECY-77-005
Request review
BHEA, J. R. Office of International Programs 79/05/01 App

NONDOCKETED ITEMS

- 790406016 DECY-79-305
Inform Commissionnaire of actions required to implement final CNA NPA regulations. Recommend NRC comply w/regulations except w specified conditions regarding documentation and SHARP. H.R. Office of the General Counsel. 79/05/01 40pp
- 790406018 DECY-79-310
Review proposed amend to RMI Co license to export mail to Canada Amend would extend expiration date for 60 gms & increase quantity of depleted U to 105.00g by Amend should be granted
SHEA, J.R. Office of International Programs 79/04/30 4pp
- 790406019 License for RMI Co to export 79.250 g U contained in 105.00g U depleted U to Canada license now referred to as 79-0342
SHEA, J.R. Assistant Director for Export/Import & International Safeguards 79/05/30 2pp
- 790406024 Amend 1 extending expiration date to 001001 & deleting condition 1 from license for RMI Co to export source mail to Canada license now referred to as 79-0342
OPLINGER, G.O. Assistant Director for Export/Import & International Safeguards 79/07/10 1p
- 790406038 Requests extension of export license expiration date to 001001 Also requests increase of mail authorized for export to 105.00g by depleted U
OCHAMPEFF, H.R. RMI Co & RMI Titanium 79/07/07 2pp
- 790406041 Executive Branch position re RMI Co application for amend to export license increasing quantity of depleted U authorized for export to Canada Amend should be issued
NGERARD, L.V. State Dept. of 79/03/14 1p
- 790406052 Amend 2 to RMI Co license 79-0342 increasing quantity of mail authorized for export to 105.00g by depleted U & deleting condition 1
OPLINGER, G.O. Assistant Director for Export/Import & International Safeguards 79/05/02 1p
- 790406073 DECY-79-320
Inform Commissionnaire of receipt of 790216 application from RMI Co for license to export 12.125 kg U to Italy
SHEA, J.R. Office of International Programs 79/04/07 1p
- 790406074 Application by Edlow Intl Co for license to export 25.125 kg U to Italy
SHEA, J.R. Edlow International Co 79/05/16 1p
- 790406074 DECY-79-320
Inform Commissionnaire of receipt of 790406 application for license to export 48.000 kg U-235 to Brazil
SHEA, J.R. Office of International Programs 79/04/23 1p
- 790406075 Application by Edlow Intl Co for license to export 48.000 kg U-235 to Brazil
SHEA, J.R. Edlow International Co 79/04/16 1p
- 790406076 Advise that application to export 50 short tons of U-235 to fulfill requirements of Brazilian Resources Legislation Later US supplies for application.
HARRISON, W. Edlow International Co 79/04/17 1p
- 790406077 DECY-79-320A
Inform Commissionnaire of GE 790410 license application amend requesting rescheduling of first shipment date to 790301
SHEA, J.R. Office of International Programs 79/04/20 1p
- 790406078 Requests application amend to reschedule first shipment date to 790301 Also asks that DOE for requesting assurances be provided to Embassy of Japan to meet new schedule requirements
SHEA, J.R. General Electric Co., Nuclear Energy Products Div. 79/04/13 1p
- 790406082 DECY-79-320
Forward Executive Branch position re Mitsubishi Intl Corp application for license to export 342 kg U-235 to Japan
SHEA, J.R. Office of International Programs 79/04/10 1p
- 790406095 Executive Branch position re Mitsubishi Intl Corp application for license to export 342 kg U-235 enriched to 2.85 to Japan license should be granted
NGERARD, L.V. State Dept. of 79/04/14 1pp
- 790406098 DECY-79-320A
Inform Commissionnaire of receipt of 790409 amend by application by German Siemens to export U hexafluoride to Spain
SHEA, J.R. Office of International Programs 79/04/26 1p
- 790406097 Transcript of 790317 public meeting re DECY-79-08 & U-235 tailings P-124
HARRISON, W. & OPLINGER, G.O. 79/05/17 2pp
- 790406098 DECY-79-320A
Forward Executive Branch position re Edlow Intl Co application for license to export 993 kg U-235 to Italy
SHEA, J.R. Office of International Programs 79/05/02 1p
- 790406097 Executive Branch position re Edlow Intl Co application license to export 993 kg enriched U-235 to Italy License should be granted Forward to list of assurances from Delegation of Commission of European Communities
NGERARD, L.V. State Dept. of Bureau of Ocean & International Affairs & Scientific Affairs 79/04/26 3pp
- 790406097 DECY-79-320A
Forward Executive Branch position re GE application for license to export 301 kg enriched U-235 to Japan
SHEA, J.R. Office of International Programs 79/05/11 1p
- 790406098 Executive Branch position re GE application for license to export 301 kg enriched U-235 to Japan License should be issued Forward 790407 list of assurances
NGERARD, L.V. State Dept. of 79/05/11 2pp
- 790406100 DECY-79-320A
Summarize responses of staff agencies to Administrative Conference Recommendation 77-2 that agencies license w/procedures for grant identification of significant info communicated orally during rulemaking proceedings
MELLEY, L.V. Office of the General Counsel 79/04/12 5pp
- 790406100 DECY-79-320A
Request approval of draft list to Solicitor General recommending DOJ seek Supreme Court review of SC Circuit Court 770325 decision on ex parte contacts in Home Box Office v FCC May 1981
SHEA, J.R. Office of the General Counsel 79/04/27 4pp
- 790406104 DECY-79-320
Inform Commissionnaire of receipt of GE application for license to export reactor replacement parts & components to India
SHEA, J.R. Office of International Programs 79/05/10 1p
- 790406101 Application by GE for license to export reactor reactor replacement parts & components to India
General Electric Co 79/04/25 2pp
- 790406101 DECY-79-320
Inform Commissionnaire of receipt of Hitachi & Co application for license to export U-235 enriched to 2.95 to 100 g U-235 to Japan
SHEA, J.R. Office of International Programs 79/05/11 1p
- 790406102 Forward Hitachi & Co application for license to export U enriched to 2.95 in 100g U-235 to Japan
NGERARD, L.V. Hitachi & Co - Ltd 79/05/01 1p
- 790406107 Inform Commissionnaire of receipt of Edlow Intl Co license application to export 1,000 metric tons of U contained in 105.000 metric tons U-235 to United Kingdom
SHEA, J.R. Office of International Programs 79/05/11 1p
- 790406102 Forward license application to export 1,000 metric tons U contained in 1,100 metric tons of U-235 to United Kingdom license is extension of expired license 50U-7932
OPLINGER, G.O. Edlow International Co 79/05/07 1p
- 790406104 DECY-79-320A
Recommend approval of amend to Aesopet Ordinance & Hfg Co license to export 45,342 kg U contained in 45,342 kg depleted U to Canada
SHEA, J.R. Office of International Programs 79/04/14 4pp
- 790406102 License for Aesopet Ordinance & Hfg Co to export 45,342 kg U contained in 45,342 kg depleted U to Canada
OPLINGER, G.O. Assistant Director for Export/Import & International Safeguards 79/05/15 1pp
- 790406107 Amend 1 to license for Aesopet Ordinance & Hfg Co increase amount of mail authorized for export to 105,000 kg depleted U contained in 103,704 kg depleted U alloy.
OPLINGER, G.O. Assistant Director for Export/Import & International Safeguards 79/05/14 1p
- 790406107 DECY-79-320A
Inform Commissionnaire of Executive Branch response to pending license application for Nishinomiya American Corp to export 3,440 kg U-235 enriched to 45.4% to Japan Forward applicant 790403 list receiving amend to application.
SHEA, J.R. Office of International Programs 79/05/11 1p

NONDOCKETED ITEMS

281

--7906090718 Executive Branch position re Nishino-Tsui American Corp
application for license to export 3 440 kg U-235 contained
in 12 kg U-235 enriched to 48.4% in form of U metal, to
Japan for supporting demonstration
HEDS/ECG, S. V. Defense Dept. of 79/03/01 17pp

VENDOR REPORTS AND RELATED CORRESPONDENCE

790610494 Responds to 790610137 re application of 100PR30 89 to GE
request for 12 revised drawings neither Tech Spec change nor
revised safety question prior NRC approval is not
required
CH2M/H.P. Reactor Safety Branch 79/04/02 1p

7906100191 Forwards comments on HEDS-25470-P-4 Feb 1978, "Multinomial
Hydrodynamic Model for Calculating Peak Boundary Loads Due
to Cladding/Mark 1 Containment"
HEDS/ECG, S. V. Brookhaven National Laboratory 79/03/09 9pp

7906100231 Submits results of transient analysis in response to
commitments made at 790610137 meeting. Analysis conducted to
show that TRAFS (TRAFS-100) computer code will predict trend
of behavior for the parameters
TANDEM, J. H. Babcock & Wilcox Co 79/03/25 2pp

7906100126 Not receipt of 79060517 describing new OR dominant control
sys for handling violations to be met HEDS-110209-044
Comments: Changes Revisions to reports requiring NRC review
are sub. to feed (HEDS-2-2) GE
HEDS/ECG, S. V. Quality Assurance Branch 79/03/08 1p

7906100157 Forwards add requested info supplementing 79060517 submitted
re power operated relief valves & loss of feedwater
commitments
HEDS/ECG, S. V. Westinghouse Electric Corp. NB-TWA-2689 79/03/23
16pp

7906100178 Responds to CP Reas 79051717 re AGND recommendations re
THI incident. Comments & recommendations resulting from THI
meet re late start 13pp to all reactor types & designs
HEDS/ECG, S. V. General Electric Co., Nuclear Energy Products Div
HFN-149/77 79/03/23 17pp

7906100184 Evaluation HEDS-100599, Suppl. 1, "Prototype Vibration
Measurement Results for B&W 177-FX Assembly Supr-Loop
Plant" - Rept acceptable as ref to describe results of
vibration qualification program
HEDS/ECG, S. V. Light Water Reactors Branch 4 79/04/04 1p

7906100417 Forwards evaluation of HEDS-0986, "Perturbation Technique
for Calculating EOCB Cooling Performance."
ETOL, J. F. Light Water Reactors Branch 1 79/04/12 2pp

--7906100422 HEDS-0986
Evaluation of HEDS-0986 Principle of perturbation technique
is acceptable
HEDS/ECG, S. V. Westinghouse Electric Corp. 77/02/28 4pp

7906100541 Forwards HEDS-21471-2, "Analytical Model for Estimating
Three Forces on Rigid Submerged Structures Caused by LSCA &
Safety Relief Valves Nishino-Tsui Air Shocks, Suppl. for Mark 1
T-D Separator Air Shocks from Mark 1 T-D Separator"
HEDS/ECG, S. V. General Electric Co. HFN-136-79 79/05/21 1p

--7906100143 HEDS-21471-2
Analytical Model for Estimating Drag Forces on Rigid
Submerged Structures Caused by LSCA & Safety Relief Valves
Nishino-Tsui Air Shocks, Suppl. for Mark 1 T-D Separator Air
Shocks from Mark 1 T-D Separator
HEDS/ECG, S. V. General Electric Co. 79/04/30 13pp

7906100549 Forwards SE proprietary rept "Analytical Model for
T-D Separator Water Jet Loads on Submerged Structures."
HEDS-210000-000 Rept withheld (ref 100PR2 700)
HEDS/ECG, S. V. General Electric Co., Nuclear Energy Products Div
HFN-156-79 79/03/23 1p

7906100144 Forwards HEDS-26337-P, "Mark 1 Containment Long-Term Program,
Development of Downcomer Lateral Flows From Full Scale Test
Facility Beta-Tax Number 7 & 8" Rept withheld (ref
100PR2 700)
HEDS/ECG, S. V. General Electric Co., Nuclear Energy Products Div
HFN-133-79 79/03/23 1p

7906100217 Clarifies 790610137 response to Question 1 3 re testing of
certain transmitters
HEDS/ECG, S. V. Westinghouse Electric Corp. NB-TWA-2693 79/05/20
1p

--7906100214 Submits items 23, 24 & 28 re post-accident functional
requirements for radiation monitoring system level
instrumentation & cables/wires. H/11st of operating plants
that re HEDS-7744, HEDS-7817, HEDS-7921 and HEDS-7929
HEDS/ECG, S. V. Westinghouse Electric Corp. NB-CF-1132
79/07/27 4pp

7906100160 Forwards HEDS-24460-P, "Off-Centering 1/4-Inch
T-D Separator Test Rept" - H/11st of operating plants
that re 100PR2 700
HEDS/ECG, S. V. General Electric Co., Nuclear Energy Products Div
HFN-133-79 79/03/23 2pp

7906100334 Forwards HEDS-04552, "Mark 1 Containment Program Load
Definition"
HEDS/ECG, S. V. General Electric Co., Nuclear Energy Products Div
HFN-133-79 79/05/23 1p

--7906100114 HEDS-04552
"Mark 1 Containment Program Test Header
Definition Load Definition"
HEDS/ECG, S. V. General Electric Co., Nuclear Energy Products Div
HFN-133-79 79/05/23 1p

7906100035 Notification of 790626 meeting w/EC in Bethesda, MD to
discuss two-loop test apparatus implications for EOCB model &
ECOB model errors
HEDS/ECG, S. V. Analysis Branch 79/03/14 1p

7906100406 Notification of 790626 meeting w/EC in Bethesda, MD to
discuss two-loop test apparatus implications for EOCB model &
ECOB model errors. Time changed to 9:00 AM
HEDS/ECG, S. V. Analysis Branch 79/03/14 1p

7906100230 Comments on AGND recommendations re THI further small
break transient & accident analysis should be performed
HEDS/ECG, S. V. Reactor Safety Branch 1, Inc. Tech. of Steam Corp. 79/03/29 2pp

7906100231 Confirms telcons re schedule for submittal of generic AGND
rept. Rept. completed approach proposed by AGND
HEDS/ECG, S. V. Combustion Engineering, Inc. LD-79-035 79/06/04
1p

7906100259 Notice that responsibility for all matters re June 1978
local reft. COMB-10-79 has been transferred to HEDS/ECG, S. V.
Engineer of PL Power & Light Co.
DAVIDS, E. H. Baltimore Gas & Electric Co. 79/06/07 2pp

7906100337 Responds to NRC request for add info re HEDS-21061, "Mark 1
Containment Dynamic Forcing Functions Info Rept." Revision 3
3 Forwards relevant info
HEDS/ECG, S. V. General Electric Co., Nuclear Energy Products Div
HFN-156-79 79/05/30 1p

--7906100338 HEDS-21061
App. A re responses to NRC 7906130 third round question to be
inserted in App. A of HEDS-21061, "Mark 1 Containment Dynamic
Forcing Functions Info Rept." Revision 3
HEDS/ECG, S. V. General Electric Co., Nuclear Energy Products Div. 79/06/30
23pp

7906100220 Forwards complete set of responses to first round requests
re HEDS-21061, "Mark 1 Containment Dynamic Forcing Functions
Info Rept." Revision 3. Responses to be inserted into App. A
HEDS/ECG, S. V. General Electric Co., Nuclear Energy Products Div
HFN-151-79 79/05/29 2pp

--7906100243 HEDS-21061
App. A re responses to NRC 7906130 third round question to be
inserted in App. A of HEDS-21061, "Mark 1 Containment Dynamic
Forcing Functions Info Rept." Revision 3
HEDS/ECG, S. V. General Electric Co., Nuclear Energy Products Div. 79/06/30
23pp

7906100330 Forwards "Changes to Return Line to Reactor Vessel Control
and Drive Hydraulic Control Sys."
HEDS/ECG, S. V. General Electric Co., Nuclear Energy Products Div. HFN
157-79 79/05/22 1p

--7906100330 "Changes to Return Line to Reactor Vessel Control and
Drive Hydraulic Control Sys."
HEDS/ECG, S. V. General Electric Co., Nuclear Energy Products Div. 79/06/30
2pp

7906100944 Forwards list of plants using analytical techniques for
plant testing analyses described in SE Bulletin 79-67
HEDS/ECG, S. V. Westinghouse Electric Corp. NB-TWA-2694 79/06/01
2pp

NONDOCKETED ITEMS

7906150232 Provides schedule for completion of five NRC benchmark problems using GE proprietary computer program PDSYS
GILDED, R. L. General Electric Co./Nuclear Energy Products Div
7/9/79/35 1p

7906150344 Forwards details of info to be provided re PDSYS analysis of NRC benchmark problems
GILDED, R. L. General Electric Co./Nuclear Energy Products Div
RLD-CM-7 7/9/79/35 2pp

7906160051 Notification of 790589 meeting w/BAW in Bethesda, MD to review successfully-integrated central age & determine interaction w/safety sys on BAW plants
STURMUELLER, J. Electric, Instrumentation & Control Systems
SUN-79/55/32 2pp

7906160422 HURDIS/CM-0719
"First Quarter FY79 Progress Rpt on Refill Effects Program." (pre-qualif. progress rpts-Oct-Oct 1978)
GORDON, C. J. / RORNE, P. H. / DAWY, C. M. General, Inc. FIN-A-4230
GEMAR-TH-292 7/9/79/31 18pp Available at HHL

7906160492 Forwards "Evaluation of Reactor Vessel Brittle Failure Due to Injection of Cold HP1 Water During Small LOCA Events"
TAYLOR, J. H. Babcock & Wilcox Co. 7/9/79/31 1p

7906160491 "Evaluation of Reactor Vessel Brittle Failure Due to Injection of Cold HP1 Water During Small LOCA Events"
Babcock & Wilcox Co. 7/9/79/31 13pp

7906160532 Responds to NRC request for add small break analysis re reactor coolant pump assumptions "Mark 2 case break" & notes given are undeline analysis should demonstrate that all breaks 6 times are covered
TAYLOR, J. H. Babcock & Wilcox Co. 7/9/79/31 1p

7906170038 Forwards BAW-101329, Revision 1, "Mark 2 Fuel Assembly-LOCA-Seismic Analysis" - Withheld (ref 100FR 790)
AFFRIDI, D. J. H. Taylor and
TAYLOR, J. H. Babcock & Wilcox Co. 7/9/79/31 2pp

7906170431 Forwards OF tag tape 31869, comprised of Sargent & Lundy tapes 2675 & 2679, table of contents of OF tape & microfiche softcopy are contained on tape 1/2 tape
GORDON, C. J. General Electric Co./Nuclear Energy Products Div
RSP-1A3-79 7/9/79/31 2pp

7906170495 Forwards list of topical rpts submitted by GE Co to NRC, describing current status of rpts
FISHER, C. R. General Atomic Co. (subs. of Gulf Oil Corp.) 7/9/79/4 4pp

7906200165 Forwards "Mark 1 Containment Activity Review" for Apr 1979
GORDON, C. J. General Electric Co./Nuclear Energy Products Div
RSP-1A4-79 7/9/79/31 1p

7906200166 "Mark 1 Containment Activity Review" for Apr 1979
General Electric Co./Nuclear Energy Products Div 7/9/79/31 3pp

7906200195 Forwards June 1979 "ATWS for Westinghouse Plants" to comply w/requirements of Alternative 3 of NUREG-0546, in response to 790512 request
ANDERSON, T. H. Westinghouse Electric Corp. NS-THA-2096 7/9/79/31 1p

7906200201 "ATWS for Westinghouse Plants"
Westinghouse Electric Corp. 7/9/79/31 16pp

8 Forwards first draft of app to Rpts BAWF-202 & B.NP-203 by performance & safety features of reactor
100 pump

7906200238 Forwards preliminary rpt of joint investigation by Westinghouse-Hitachi Heavy Industries re cracked support pipe & features in guide tubes in operating Japanese plants. Study to be concluded in June 1979
ANDERSON, T. H. Westinghouse Electric Corp. NS-THA-2094 7/9/79/31 9pp

7906200362 Forwards data re "Two-Loop Test Apparatus (TLTA) Results"
ANDERSON, T. H. General Electric Co./Nuclear Energy Products Div
RSP-167-79 7/9/79/31 102pp

7906200364 Notifies that NRC analysis of seismic small break experiments are requested on 790350 is delayed until 790601
TAYLOR, J. H. Babcock & Wilcox Co. 7/9/79/31 1p

7906210028 Forwards slides presented at 790501 meeting w/NRC to discuss GEES evaluation model development status for Westinghouse fuel reloads of C-E NSSS
ANDERSON, T. H. Westinghouse Electric Corp. NS-THA-2091 7/9/79/31 19pp

7906210245 Forwards "GEES Evaluation Model for Westinghouse Fuel Reloads of C-E NSSS," nonproprietary version
ANDERSON, T. H. Westinghouse Electric Corp. NS-THA-2092 7/9/79/31 1p

7906210246 WCAP-V529
"GEES Evaluation Model for Westinghouse Fuel Reloads of C-E NSSS," nonproprietary version
FERGUSON, R. L. / ANDERSON, T. H. Westinghouse Electric Corp. 7/9/79/31 92pp

7906210258 Forwards "GEES Evaluation Model for Westinghouse Fuel Reloads of C-E NSSS," proprietary version Rpt withheld (ref 100FR 790)
ANDERSON, T. H. Westinghouse Electric Corp. NS-THA-2093 7/9/79/31 11pp

7906220126 Requests add info for review of Revision 3 to 80-104-1, submitted 7/9/79
WAMSLEY, P. Quality Assurance Branch 7/9/79/21 4pp

7906230290 Forwards add info on WCAP-8809 & WCAP-0840 (nonproprietary), in response to NRC 780119 request
ANDERSON, T. H. Westinghouse Electric Corp. NS-THA-2090 7/9/79/31 29pp

7906230294 Forwards add info on WCAP-8801, "Franklin Steam Generator Core Description," application for withholding AW-79-19 & affidavit WCAP-0821 (ref 100FR 790)
ANDERSON, T. H. Westinghouse Electric Corp. NS-THA-2090 7/9/79/31 2pp

7906230295 Application for withholding add info re WCAP-8801, "Franklin Steam Generator Core Description," (ref 100FR 790)
WOLFENBARGER, R. A. Westinghouse Electric Corp. AW-79-18 7/9/79/31 1p

7906230301 Application for withholding proprietary info from public disclosure (ref 100FR 790) w/attachment to 80-THA-2090, which is add info re WCAP-8801, "Franklin Steam Generator Core Description."
WOLFENBARGER, R. A. Westinghouse Electric Corp. AW-79-15 7/9/79/31 5pp

7906230309 Forwards 790338 proprietary rpt BW-6469 "Pressurizer Ref Log of Refueling Test" & requests rpt be withheld (ref 100FR 790) WCA and
TAYLOR, J. H. Babcock & Wilcox Co. 7/9/79/31 1p

7906230317 Draft "Becan Heat Removal Problem Associated With Recovery From Very Small Break LOCA" for BAW SCD-Fuel-Assembly PWR
Babcock & Wilcox Co. 7/9/79/31 48pp

7906230340 BAW-103744
"Withholds Analysis of Small Breaks for BAW SCD-Fuel-Assembly Nuclear Plants With Internal Vent Valves"
JONES, R. C. / DUNN, B. H. / PARKS, C. E. Babcock & Wilcox Co. 7/9/79/31 8pp

7906230343 Informs of completion of review of BAW-10042, Revision 1; BAW-10074, Revision 1 & BAW-10075, Revision 1 Forwards topical report evaluation
SCHMIDT, A. Light Water Reactors Branch 2 7/9/79/31 4pp

7906230345 Topical rpt evaluation of BAW-10042, Revision 1; BAW-10074, Revision 1 & BAW-10075, Revision 1 re small break spectrum analyses for BAW 145, 177 & 203-Fuel-Assembly Plants w/interlocks vent valves
Assistant Director for Light Water Reactors 7/9/79/31 9pp

NONDOCKETED ITEMS

283

7906200395 Forwards "Benchmark Analysis For Asymetric Loop Events
157 Fuel Assembly Plants" *
TAYLOR, J. H. Babcock & Wilcox Co 79/06/15 1p

--7906200360 "Benchmark Analysis For Asymetric Loop Events
1177 - Fuel Assembly Plants" *
* Babcock & Wilcox Co 79/06/15 1ppp

7906200418 Response to NRC 790415 request for addl info re central
blade life (BCL) test info will be forwarded on 790702
GRIELER, R. L. General Electric Co -Nuclear Energy Products Div
909-148-79 79/06/15 1p

7906200455 Summarizes 790613 meeting w/NRC in Washington, DC re reactor
vessel brittle fracture during small LOCA events
TAYLOR, J. H. Babcock & Wilcox Co 79/06/14 2pp

7906200777 Forwards revisions to 3N-WF-77-57, "Exxon Nuclear Power
Distribution Control For Phase 51" *
GASLER, D. F. Exxon Nuclear Co., Inc. Incls of Exxon Corp 1
79/04/22 25pp

7906201197 Forwards responses to NRC 790404 request for addl info re
NRC-8977, "Failure Mode & Effects Analysis of ECC"
Westinghouse Type 312-3-Loop PWR *
GOSSEL, T. M. Westinghouse Electric Corp MS-TM-1876 78/07/21
25pp

7906202311 Requests info re review status of 6902-155215, "Containment
Spray Noises for Nuclear Power Plants" *
GRIFFIN, E. D. Spraying Systems Co 79/06/20 1p

7906202313 Refers of change in shell structure changes will be reflected
in update of typical test TP-25A scheduled for Aug 1979
PICHARD, A. E. G. F. Brown & Co 79/06/20 1p

7906202619 Forwards proposed method for calculation of BAW penalty to
allow BAW immediate credit for sound heat beat flux
ICOP test
TAYLOR, J. H. Babcock & Wilcox Co 79/06/22 2pp

7906202699 Forwards three revised organization charts for Power Div &
SA Div of Reacting & Machine Co Reorganization completed to
levels shown in Jul 1979 "QA Program for Nuclear Power
Plants," GAI-TB-10-Revision 1A
GOSSEL, T. M. Oliver Associates, Inc. 79/06/19 1pp

7906202934 Summary of 790335 meeting w/DOE & BNL re resolution of
generic BWR feedwater nozzle cracking problem
GOSSEL, T. M. Systematic Evaluation Program Branch IPV 7906201
79/06/05 3pp

WASTE MGT. NUCLEAR WASTE MANAGEMENT

7904520245 Comments on 781113 EPA-proposed criteria for radioactive
waste. Questions viability of EPA concept of complete
removal of all wastes. Notes questions of certain criteria
misstated comments
GOSSEL, T. M. Office of the Executive Director for Operations
79/03/15 8pp

7904520286 DOE/EIS-0046-V-1
Forwards DOE-Vol 2 App "Mgt of Commercially-Generated
Radioactive Waste."
* Energy Dept of 79/06/30 1p

--7904520366 DOE/EIS-0046-V-2
DOE-Vol 2 App "Mgt of Commercially Generated Radioactive
Waste" *
* Energy Dept of 79/04/30 60ppp

7904110320 Submits schedule for technical info meetings proposed for
790205 briefing on waste mgt program Also submits proposed
agenda for first meeting
MILARD, J. C. Energy Dept of 79/03/30 2pp

7904110350 Forwards notice for fourth meeting in series of NRC/DOE
meetings re radioactive waste repositories Meeting
notice & agenda have been sent to those on distribution
list w/o attach.
MILARD, J. C. High Level Waste Licensing Management Branch.
79/03/07 1p

--7904110393 Notification of 790323 meeting w/DOE in Silver Spring, MD to
discuss radioactive waste repositories
MILARD, J. C. High Level Waste Licensing Management Branch.
79/03/07, 2pp.

7904110034 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
O'NEILL, J. H. Shaw Pittman, Public & Tradebridge. 79/03/26 1p

7904110036 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
BROOKS, H. B. Westinghouse Electric Corp 79/03/27 1p

7904110038 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
BARKER, B. J. Western Nuclear, Inc. (subs of Phelps Dodge Corp) 79/03/27 1p

7904110044 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
KILB, J. L. Gilbert Associates, Inc. 79/03/20 1p

7904110047 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
BENTON, A. J. California, State of 79/03/28 1p

7904110050 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
BROWN, B. H. Wyoming Mineral Corp 79/03/28 1p

7904110051 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
FARRIS, W. A. Consumers Power Co. 79/03/29 1p

7904110054 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
RICHGREN, C. F. Wisconsin, State of 79/03/29 1p

7904110058 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
HARRIS, J. L. South West Nuclear Co 79/03/30 1p

7904110067 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
ORRY, A. E. S. S. G. Inc. 79/04/02 1p

7904110069 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
GOSSEL, T. M. New York, State of. 79/04/02 1p

7904110071 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
GOSSEL, T. M. Affiliation Unknown 79/04/02 1p

7904110074 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
ZIMMERMAN, D. L. General Electric Co -Nuclear Energy Products Div
79/04/03 1p

7904110076 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
WARRREN, B. C. Florida, State of 79/04/04 1p

7904110078 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
MILARD, J. C. Affiliation Unknown. 79/04/05 1p

7904110079 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories.
HARRISON, D. Southwest Research and Information Center. 79/04/05 1p

7904110081 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
BARTY, T. E. Edison Electric Institute 79/04/06 1p

7904110082 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories.
BART, L. Massachusetts, State of. 79/04/06 1p.

7904110083 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
HARRISON, H. B. Tennessee Valley Authority 79/04/10 1p

7904110087 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories
JONES, J. M. G. V. Endosphere Co 79/04/10 1p

7904110089 Requests to be placed on distribution list for notices of
public meetings on radioactive waste repositories.
FARRIS, W. A. Affiliation Unknown. 79/04/12 1p.

NONDOCKETED ITEMS

790410090 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories
BARTLETT-LADRI Affiliation Unknown 79/04/19 1p

790410092 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories
FRANK-T Affiliation Unknown 79/04/21 1p

790410093 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories
WEINER-L J California, State of 79/04/23 1p

790410095 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories
MULLA, R M Tennessee Valley Authority 79/04/24 1p

790410097 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories
SEYDOR-J L Affiliation Unknown 79/04/25 1p

790410099 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories
LOMB-J Affiliation Unknown 79/04/25 1p

790410100 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories
THAMMUN, N. Tennessee: 266 79/04/27 1p

790410102 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories
HINES-L A New England Regional Regulatory Assistance Program 79/04/26 1p

790410109 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories
MCRIE-J A G R Johnson Associates, Inc. 79/04/16 1p

790410107 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories
CLARK-W Citizens for Alternatives to Radioactive Dumping 79/04/14 1p

790410109 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories
LEFEVRE A D Stoller Corp. (subs. of Arthur D. Little, Inc.) 79/03/30 1p

790410520 Summary of 79041 meeting w/OGE in Silver Spring, MD re geological exploration program being implemented by DOE to identify sites for nuclear waste repositories
BOWLE S R High Level Waste Licensing Management Branch 79/04/10 3pp

790420360 Summary of NRC/OGE meeting re geologic exploration for high level waste repository sites. Contains "Program for Identifying Sites for Nuclear Waste Repositories" & "Geologic Investigations Results of Columbia Plateau"
BOWLE S R High Level Waste Licensing Management Branch 79/04/11 107p

SPRINTLICE EXPORT AND IMPORT LICENSES

790420323 NRC conclusion re Transnuclear, Inc. application for license to export 10,500 kg U to Belgium. License should be issued
ROBERT N Office of International Programs 79/04/27 1p

790420097 Executive Branch position re Swiss Co. application for export license to export 4,000 lb of depleted U to Iran in form of plated aircraft counterweights. License should not be granted.
MOSEND, L V State Dept. of Bureau of Ocean & Internal, Environ. & Scientific Affairs 79/04/24 1p

790420099 Forward application for Ramsey Engineering Co. to export 415 kg of Pu-238 to Peru.
HINDRICK-W O Ramsey Engineering Company 79/04/22 1p

790420097 Application by Ramsey Engineering Co. for license to export 415 kg of Pu-238 to Peru.
HINDRICK-W O Ramsey Engineering Company 79/04/23 2pp

790420102 Executive Branch position re Swiss Special Metals Corp. application for license to export 450 lb of strontium-90 to Germany. License should be granted.
MOSEND, L V State Dept. of 79/04/26 3pp

790420104A EECV-79-097
Informs Commission of receipt of Transnuclear, Inc. 790420 application for license to export highly enriched U to Germany
BREN-J R Office of International Programs 79/04/26 1p

790420107 Forward PR notice for filing & publication of application for license to export nuclear facilities or parts
SPLINGER, G O Assistant Director for Export/Import & International Safeguards 79/04/27 3pp

790420107 Forward PR notice for filing & publication of application for license to export nuclear facilities or parts
SPLINGER, G O Assistant Director for Export/Import & International Safeguards 79/04/27 3pp

790420017 Forward proposed license for US Army Materiel & Mechanics Research Ctr. to export source mail to United Kingdom
BREN-J R Office of International Programs 79/04/26 3pp

790420020 Executive Branch position re US Army Materiel & Mechanics Research Ctr. application for license to export 250 kg depleted U alloy to United Kingdom. License should be granted.
MOSEND, L V State Dept. of Bureau of Ocean & Internal, Environ. & Scientific Affairs 79/05/23 3pp

790420023 Application by US Army Materiel & Mechanics Research Ctr. for license to export 250 kg depleted U alloy to United Kingdom
MOSEND, L V State Dept. of Bureau of Ocean & Internal, Environ. & Scientific Affairs 79/05/23 3pp

790420027 License for Army Materiel & Mechanics Research Ctr. to export 250 kg depleted U to United Kingdom
SPLINGER, G O Assistant Director for Export/Import & International Safeguards 79/04/24 3pp

790420101 EECV-79-03A
Provides NRC review of Transnuclear, Inc. 790103 application for license to import low enriched U as U hexafluoride from France
BREN-J R Office of International Programs 79/04/23 3pp

7904202103 Application by Transnuclear, Inc. for license to import 5,500 kg U enriched to 4% of U-235 from France
MATHSON V Transnuclear, Inc. 79/01/03 3pp

7904202106 License for Transnuclear, Inc. to import max of 5,000 kg U enriched to max of 3.0% U-235 from France
SPLINGER, G O Assistant Director for Export/Import & International Safeguards 79/01/03 3pp

7904202106 Requests Executive Branch position re Swiss Int'l Co. application for license to export natural U to United Kingdom for conversion to U hexafluoride & subsequent return to US for enrichment
SPLINGER, G O Assistant Director for Export/Import & International Safeguards 79/03/25 1p

790420209 Requests Executive Branch position re RA Co. application for license to export 500 kg to Philippines
SPLINGER, G O Assistant Director for Export/Import & International Safeguards 79/03/25 1p

7904202102 Requests Executive Branch position re Swiss-Built amended application for license to export 14 kg U increased from 10 kg
SPLINGER, G O Assistant Director for Export/Import & International Safeguards 79/03/26 1p

7904202106 Executive Branch position re Swiss, Inc. application for license to export 1,000 kg thorium in form of thorium oxide powder to Canada. License should be granted.
MOSEND, L V State Dept. of 79/05/17 3pp

7904202106 Requests Executive Branch position re Transnuclear, Inc. application for license to export 25,000 lb U-enriched to 3.0% U-235 to Switzerland
SPLINGER, G O Assistant Director for Export/Import & International Safeguards 79/03/26 1p

790420190 Requests Amend S in GE export license changing ultimate consignee & intermediate consignee.
HINDRICK-W O General Electric Co., Nuclear Energy Products Div 79/04/10 1p

790420197 Requests amend to Swiss-Built export license application changing ultimate consignee, quantity to be shipped & commodity description.
TAMM H Swiss-Int'l American Corp. NACP-0203-NT 79/04/26 3pp

NONDOCKETED ITEMS

285

- 7904000198 Requests Amend 3 to QA Co export license extending expiration date to 8/1/2001
MORRY, W.R. General Atomic Co. (subs. of Gulf Oil Corp.) 79/03/02 1p
- 7904000199 Requests Amend 3 to QA Co export license extending expiration date to 8/1/2001
MORRY, W.R. General Atomic Co. (subs. of Gulf Oil Corp.) 79/03/02 1p
- 7904000200 Requests immediate action on Consolidated Controls Corp. application for license to export 20 radioactive tung detectors to Italy
JLHNSB, L.V. Consolidated Controls Corp. (subs. of GenCorp.) 79/05/09 4pp
- 7904000201 Application by Hoke, Inc. for license to export belt-mounted instrument including valves to Argentina
LHNSB, L.V. Hoke, Inc. 79/04/16 1p
- 7904000202 Requests Executive Branch position re Rauter-Blakes-Inc. application for license to export 80M to India
OPLINER, G.O. Assistant Director for Export/Import & International Safeguards 79/05/08 1p
- 7904000203 Executive Branch position re Hoke Nuclear Co. Inc. application for license to export circulating tubing, spacer parts & spring-loaded insulator distrib. plates & other fuel assembly hardware to Sweden. License should be granted
HNSB, L.V. State/Dept. of, Bureau of Ocean & Internat'l Environ & Scientific Affairs 79/03/17 2pp
- 7904000204 Executive Branch position re Hoke Nuclear Co. Inc. application for license to export circulating tubing, spacer parts & spring-loaded insulator distrib. plates & other fuel assembly hardware to Sweden. License should be granted
HNSB, L.V. State/Dept. of, Bureau of Ocean & Internat'l Environ & Scientific Affairs 79/03/17 1p
- 7904000205 Commission has reviewed & agreed w/rd Chik recommendation re Hoke Nuclear Co. Inc. application to export 80,000 kg U-enriched to 3 1/2 U-235 from Soviet Union. Requests Exon be notified
CHIL, S.J. Office of the Secretary of the Commission 79/04/20 1p
- 7904000206 Notification of Commission approval of license for Transnuclear, Inc. to export 22,701 kg U-enriched to 20 1/2 U-235 from France. Requests Transnuclear, Inc. be notified
CHIL, S.J. Office of the Secretary of the Commission 79/04/20 1p
- 7904000400 Executive Branch position re Cordis Corp. application for license to export 45 g of Pu-238 to Jordan & Saudi Arabia
HNSB, L.V. State/Dept. of 79/04/23 2pp
- 7904000401 Executive Branch position re Cordis Corp. application for license to export 45 g of Pu-238 to Jordan & Saudi Arabia
HNSB, L.V. State/Dept. of 79/04/23 2pp
- 7904000402 Approves Transnuclear, Inc. 790102 application for license to export 12,714 kg U to West Germany based on Executive Branch position & end use statements
HNSB, L.V. Office of International Programs 79/04/27 1p
- 7904000403 Executive Branch position re Rauter-Blakes-Inc. application to export 16 kg U-235 to India. License should be granted if of assurance
HNSB, L.V. State/Dept. of 79/05/01 2pp
- 7904000407 Requests Executive Branch position re Westinghouse application for license to export miscellaneous components & parts to Spain
OPLINER, G.O. Assistant Director for Export/Import & International Safeguards 79/05/08 1p
- 7904000408 Responds to 790102 ltr requesting amend to export license to extend expiration date to 8/1/2001 due to instability of political situation in Iran. Executive Branch is unable to approve request
OPLINER, G.O. Assistant Director for Export/Import & International Safeguards 79/05/03 1p
- 7904000409 Requests expiration date on Licenses 1896-1696 & 1898-1699 be extended from 790501
RATON, V. Transnuclear, Inc. 79/04/04 4pp
- 7904000410 Requests expiration date on Licenses 1896-1696 & 1898-1699 be extended from 790501
RATON, V. Transnuclear, Inc. 79/04/04 4pp
- 7904000500 Requests Executive Branch position re GE 790428 application for license to export replacement parts for use in Turbo-reactor to India
OPLINER, G.O. Assistant Director for Export/Import & International Safeguards 79/05/09 1p
- 7904000501 Requests Executive Branch position re QA Co 790501 application for license to export components for use in PHR research reactor to Philippines. HRA and
OPLINER, G.O. Assistant Director for Export/Import & International Safeguards 79/05/09 1p
- 7904000502 Forwards Application to export 1,000 metric tons U-contained in 1,100 metric tons U-308 concentrate to United Kingdom
ELDM, J. Elcom International Co. 79/05/07 1p
- 7904000503 Application by Elcom Intl Co. for license to export 1,000 metric tons U-contained in 1,100 metric tons U-308 concentrate to United Kingdom
ELDM, J. Elcom International Co. 79/05/07 1p
- 7904000504 Forwards application for license to export startup, intermediate, linear & wide range channels to Philippines
RATON, V. General Atomic Co. (subs. of Gulf Oil Corp.) 79/05/01 1p
- 7904000505 Application by QA Co. for license to export Channel Models M-4-A, M-4-B, M-4-C, M-4-D & M-4-E to Philippines
RATON, V. General Atomic Co. (subs. of Gulf Oil Corp.) 79/05/01 2pp
- 7904000506 Requests new export license for 20,000 kg depleted U parts, due to accelerated scrap accumulation. Requests issuance by 790313
SCHWARTZ, H. Aerogas Dynamics Co. 79/04/26 1p
- 7904000507 Requests amend to export license to change export parties to Rauter-Blakes-Inc. Ltd.
RATON, V. Transnuclear, Inc. 79/05/03 1p
- 7904000508 Application by Sigma Chemical Co. for license to export compounds containing deuterium equivalent to 5 kg deuterium oxide liquid to Mexico
RATON, V. Sigma Chemical Co. (subs. of Sigma Aldrich Corp.) 79/05/03 1p
- 7904000509 Forwards request for extension of license X02H-C02B & amend of dollar value original amount was expressed in Canadian dollars
LHNSB, L.V. Hoke, Inc. 79/04/09 1p
- 7904000510 Application by Hoke, Inc. for license to export control valves to South Korea. Requests provision in value & extension of amt. Dept. of Commerce license A301762
LHNSB, L.V. Hoke, Inc. 79/05/09 2pp
- 7904000511 License for Cordis Corp. to export 45 g Pu-contained in 350 ceramic pellets to Saudi Arabia & Jordan
OPLINER, G.O. Assistant Director for Export/Import & International Safeguards 79/04/27 2pp
- 7904000512 License for QA Co. to export 704 g U-238 contained in 2,940 g U to West Germany
OPLINER, G.O. Assistant Director for Export/Import & International Safeguards 79/04/20 2pp
- 7904000513 License for GE to export signal amplifier, electrical generation modules & valve drive lamps to India
OPLINER, G.O. Assistant Director for Export/Import & International Safeguards 79/04/20 1p
- 7904000514 License for Byron Jackson Pump Div. to export seal cartridge-helical exchange rotating baffles, elements & cooling assemblies to Switzerland
OPLINER, G.O. Assistant Director for Export/Import & International Safeguards 79/04/27 1p
- 7904000515 License for Hoke, Inc. to export 21 control valves & spare parts to Canada
OPLINER, G.O. Assistant Director for Export/Import & International Safeguards 79/07/01 1p
- 7904000516 License for Byron Jackson Pump Div. to export three pump case accessories specially prepared for use in coolant pump to Italy
OPLINER, G.O. Assistant Director for Export/Import & International Safeguards 79/04/27 1p

790609396 License for Kherine Instrument Corp to export BL-6 and P-200 to Indonesia
OF, INGER, O G Assistant Director for Export/Import & International Safeguards 79/04/27 App.

790609402 License for Mitsubishi Travel Div of America to export miscellaneous specially-designed or prepared parts & components to Japan
OF, INGER, O G Assistant Director for Export/Import & International Safeguards 79/04/27 App.

790609404 License for Byron Jackson Pump Div to export seal cartridges ball bushings, bearings, elastomeric coupling assemblies & pump case to Italy
OF, INGER, O G Assistant Director for Export/Import & International Safeguards 79/04/27 App.

790609403 License for GE to export 4 source range & intermediate range monitors to India.
OF, INGER, O G Assistant Director for Export/Import & International Safeguards 79/04/26 App.

790609404 Agrees to proposed license for import of low enriched U hexafluoride from Soviet Union; provided certain conditions are met: addition of 1988 technical review section & recording of NNSB opinion of examination statement
DROGDA, W J Office of Nuclear Material Safety & Safeguards 79/04/10 App.

790609476 SECY-79-023A
Informs Commissioners of preliminary comments on proposed license for Edlow Intl to export low enriched U to India
Recommendations deferred until Executive Branch briefing on pertinent foreign policy developments
SHERA, J R Office of International Programs 79/06/24 App.

790609484 Application by Reuter-Stokes, Inc for license to export B 34 & U-205 to India; Waiver/condition statement
SARAF, A J Reuter-Stokes, Inc 79/04/26 App.

790607610 SECY-79-041
Submits add info re several proposed export licenses
Discusses 790316 meeting of Euratom Supply Agency/Delegation of Commission of European Communities & NSC Ofc of Intl Programs re urgent need for highly enriched U in Europe
SHERA, J R Office of International Programs 79/03/20 App.

790607610 SECY-79-041
Submits add info re several proposed export licenses.
Discusses 790316 meeting of Euratom Supply Agency/Delegation of Commission of European Communities & NSC Ofc of Intl Programs re urgent need for highly enriched U in Europe
SHERA, J R Office of International Programs 79/03/20 App.

790607610 SECY-79-041
Submits add info re several proposed export licenses.
Discusses 790316 meeting of Euratom Supply Agency/Delegation of Commission of European Communities & NSC Ofc of Intl Programs re urgent need for highly enriched U in Europe.
SHERA, J R Office of International Programs 79/03/20 App.

790607610 SECY-79-041
Submits add info re several proposed export licenses.
Discusses 790316 meeting of Euratom Supply Agency/Delegation of Commission of European Communities & NSC Ofc of Intl Programs re urgent need for highly enriched U in Europe.
SHERA, J R Office of International Programs 79/03/20 App.

790607610 SECY-79-041
Submits add info re several proposed export licenses
Discusses 790316 meeting of Euratom Supply Agency/Delegation of Commission of European Communities & NSC Ofc of Intl Programs re urgent need for highly enriched U in Europe
SHERA, J R Office of International Programs 79/03/20 App.

790607610 SECY-79-041
Submits add info re several proposed export licenses
Discusses 790316 meeting of Euratom Supply Agency/Delegation of Commission of European Communities & NSC Ofc of Intl Programs re urgent need for highly enriched U in Europe.
SHERA, J R Office of International Programs 79/03/20 App.

790607612 Response to 790316 meeting request for info re research program & fuel cycle schedule of reactor operators as well as conversion & fabrication planning of NUKEM
GPPFLM, H European Communities: Commission of 79/03/19 App.

790607612 Response to 790316 meeting request for info re research program & fuel cycle schedule of reactor operators as well as conversion & fabrication planning of NUKEM
GPPFLM, H European Communities: Commission of 79/03/19 App.

790607612 Response to 790316 meeting request for info re research program & fuel cycle schedule of reactor operators as well as conversion & fabrication planning of NUKEM
GPPFLM, H European Communities: Commission of 79/03/19 App.

790607612 Response to 790316 meeting request for info re research program & fuel cycle schedule of reactor operators as well as conversion & fabrication planning of NUKEM
GPPFLM, H European Communities: Commission of 79/03/19 App.

790607612 Response to 790316 meeting request for info re research program & fuel cycle schedule of reactor operators as well as conversion & fabrication planning of NUKEM
GPPFLM, H European Communities: Commission of 79/03/19 App.

790607612 Application by Hoke, Inc for license to export needle valves to South Korea
LINDBER, T P Hoke, Inc 79/04/16 App.

790607612 Application by Hoke, Inc for license to export ballcock-valve instrument isolating valves to South Korea
LINDBER, T P Hoke, Inc 79/04/16 App.

790607612 Application by Hoke, Inc for license to export ballcock-valve manually & pneumatically operated valves & three valve manifolds to South Korea
LINDBER, T P Hoke, Inc 79/04/16 App.

790607612 Application by Hoke, Inc for license to export ballcock-valve instrument isolating valves & spools to Canada
LINDBER, T P Hoke, Inc 79/04/16 App.

790607612 Executive Branch position re Mitsubishi Intl Corp application for license to export manipulator crane for clearing & discharging fuel assemblies to Japan; license should be granted
NBSMID, L V State Dept of 79/05/02 App.

790607612 Executive Branch response to Consolidated Controls w/ra customary 25-day waiting period; Applicant was unaware that license was required for export of detectors to Italy
SHERA, J R Office of International Programs 79/03/20 App.

790607612 Executive Branch position re Sandvik Special Metals Corp application for license to export 19 1/2 in 2-2 & 2-4 inch & strip; for testing of physical properties to Israel
License should be granted w/ra of assurance
NBSMID, L V State Dept of 79/05/02 App.

7906120103 Perseus Edlow Intl Co application amend request to remove Reactor Breach/Leakage Unit built as intermediate consequence Request amend be considered w/condition
SHERA, J R Office of International Programs 79/03/20 App.

790612013 Requests license to export fissile counter & accompanying reactor instrumentation replacement to Philippines
NBSMID, L V General Atomic Co 1984 of Gulf Oil Corp 1 18L-1026 79/05/01 App.

7906120227 Application by GA Co for license to export Fission Counter MC-1076 containing U-235 to Philippines
NBSMID, L V General Atomic Co 1984 of Gulf Oil Corp 1 79/05/01 App.

7906120249 Application by Westinghouse for license to export three computerized isolation chambers to France
NBSMID, L V Westinghouse Electric Corp 79/05/15 App.

7906140200 Canada export license applications 3MAT-17, 3MAT-18 & 3MAT-20 per Alrich Chemical Co 790314 request
NBSMID, L V Office of International Programs 79/05/15 App.

7906140550 Canada export license applications 3MAT-17, 3MAT-18 & 3MAT-20 per Alrich Chemical Co 790314 request
NBSMID, L V Office of International Programs 79/05/15 App.

7906140550 Canada export license applications 3MAT-17, 3MAT-18 & 3MAT-20 per Alrich Chemical Co 790314 request
NBSMID, L V Office of International Programs 79/05/15 App.

7906140550 Canada export license applications 3MAT-17, 3MAT-18 & 3MAT-20 per Alrich Chemical Co 790314 request
NBSMID, L V Office of International Programs 79/05/15 App.

7906140550 Canada export license applications 3MAT-17, 3MAT-18 & 3MAT-20 per Alrich Chemical Co 790314 request
NBSMID, L V Office of International Programs 79/05/15 App.

--790140567 Application by Varian Export Corp for license to export 30 mCi nickel for use as ionizing source in x-ray chromatograph electron capture detector during 2-yr license period
HOLBERT, J J Varian Export Corp 79/03/25 2pp

790140575 Forwarded bus applications to export 126-000 kg U & 23-000 kg U to France for use statement encl
HATSOGLU, V Transnuclear, Inc 79/03/03 2pp

790140578 Forwarded bus applications to export 126-000 kg U & 23-000 kg U to France for use statement encl
HATSOGLU, V Transnuclear, Inc 79/03/03 2pp

--790140602 Application by Transnuclear, Inc for license to export 125,500 kg U enriched to 0.35% U-235 & 300 kg U heavy isotopes enriched to 0.35 U-235, to France
HATSOGLU, V Transnuclear, Inc 79/03/03 1p

790140612 Application by Sigma Chemical Co for license to export compounds containing deuterium to India
Sigma Chemical Co Subs of Sigma Aldrich Corp 79/03/20 1p

790140617 Application by Hitachi & Co for license to export enriched U hexafluoride to Japan
Hitachi & Co., Ltd 79/03/01 2pp

790140629 Application by GE for license to export six traversing source probe detector assemblies to India
GE's B D General Electric Co 79/03/07 1p

7901406107 License for Hoke, Inc to export motorized & isolating valves control parts to South Korea
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/03/10 1p

7901406109 License for Spex Industries, Inc to export 0.0005 g U-235 to Japan
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/03/10 2pp

7901406111 License for Mitsubishi Indl Corp to export 345 kg U-235 to Japan
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/03/10 1p

7901406117 Amend D to license for GE & GE Technical Inc Co, Inc to export components & associated R&D equipment to Japan
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/03/14 1p

7901406119 License for Air Products & Chemicals, Inc to export 250 g g deuterium as gas to United Kingdom
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/03/11 2pp

7901406122 License for Westinghouse to export 0.001 g U-235 to Belgium
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/03/11 2pp

7901406286 Executive Branch position re Helwan Div application for license to export to guide U-tube & instrumentation tubes to France. License should be granted
ROSENBLUM, L U.S. State Dept. of 79/03/17 2pp

7901406462 Application by United Kingdom Treasury & Supply Delegation for license to export sodium reactor grade Zircaloy-4 tube to United Kingdom
United Kingdom 79/03/02 1pp

7901406471 Request license to export two pieces of Zircaloy-2 heatlines tubing to South Korea
GILBERT, Y K. Hyundai Bergico Industries, Inc 79/05/11 2pp

7901406474 Application by GE for license to export replacement parts to India
HILSON, G D General Electric Co 80W-79108, 79/04/23 2pp

7901406511 Forwarded application for license to export seven nuclear metal, LTR of insurance required, to encl
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/04/20 1p

7901406512 Executive Branch position re Varian Exports Corp application for license to export 300 mCi nickel to various countries listed in Paragraph 110 of W's encl
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/04/23 1p

7901406518 License for GE to export miscellaneous specially-designed or prepared parts & components, except assembled pressure vessels, to Japan
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/03/03 2pp

7901406518 License for Transnuclear, Inc to export 0.10 kg U-235 to Canada
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/03/03 2pp

7901406525 License for Randvik Special Metals Corp to export 450 lb of Zircaloy-4 tubing to South Korea
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/03/03 1p

7901406526 License for SH Shattuck Chemical Co to export 5 g U to Mexico
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/03/03 2pp

7901406527 License for SH Shattuck Chemical Co to export 4.7 lb U to Mexico
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/03/03 2pp

7901406531 License for Green Precision Engineering & Mfg Corp to export 30,000 diamond springs to India
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/03/02 1p

7901406536 License for Dept of Army to export 250 kg depleted U to United Kingdom
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/03/03 2pp

7901406539 License for Heuter-Stokes, Inc to export 16 mg U-235 to India
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/03/04 2pp

7901406543 Application by Hoke, Inc for license to export hollow-sealed assembly & pneumatically operated valve, bleed & drain valves & three valve manifolds to Korea
LINENDE, T P Hoke, Inc 79/04/16 1p

7901406557 Ratified of export of one lot of metal against license which packaged by Polonium Corp instead of original shipper, United Nuclear Corp
EDLGA, U Follow International Co 79/03/07 1p

7901406558 Application by GE for license to export nozzle fittings to The Netherlands
WILSON, G D General Electric Co 80W-79118 79/03/03 1p

7901406559 License for GE & GE Technical Inc Co to export miscellaneous specially-designed or prepared parts & components to Sweden
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/03/10 1p

7901406561 License for Randvik Special Metals Corp to export 15 lb tubes made from 2r metal Zircaloy-2 rod, Zircaloy-4 rod, Zircaloy-2 strip & Zircaloy-4 strip to Israel
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/03/10 1p

7901406562 Amend D to 1
ROSENBLUM, L U.S. State Dept. of 79/03/17 2pp

7901406563 Executive Branch position re Varian Exports Corp application for license to export 300 mCi nickel to various countries listed in Paragraph 110 of W's encl
OPLINGER, G D Assistant Director for Export/Import & International Safeguards 79/04/23 1p

NONDOCKETED ITEMS

7904180772 Application by Hake, Inc. for license to export bellows-needled
instrument isolating valves to Korea
W Hake, Inc 79/04/16 1p

7904180801 Requests Executive Branch position re GA Co application for
license to export miscellaneous components to Egypt
OPLINDEK, G G Assistant Director for Export/Import & International
Safeguards 79/05/03 1p

7904180820 Requests Executive Branch position re Hakkas Research Corp
application for license to export GME to Turkey
OPLINDEK, G G Assistant Director for Export/Import & International
Safeguards 79/05/04 1p

7904180815 RECE-79-310
Review proposed amend to RMI Co license to export melt to
Canada Amend would extend expiration date for two yrs &
increase quantity of depleted U to 135,000 kg Amend should
be granted
SHEA, J R Office of International Programs 79/04/30 4pp

7904180816 License for RMI Co to export 99-290 U-2-enriched to
100,000 kg depleted U to Canada License now referred to as
EU-8542
SHEA, J R Assistant Director for Export/Import & International
Safeguards 76/12/10 2pp

7904180824 Amend 1, extending expiration date to 05/05/85 & deleting
condition 1 from license for RMI Co to export search melt
to Canada License now referred to as EU-8542
OPLINDEK, G G Assistant Director for Export/Import &
International Safeguards 79/07/10 1p

7904180838 Requests extension of export license expiration date to
05/05/85 Also requests increase of melt authorized for export
to 135,000 kg depleted U
SHEA, J R Office of International Programs 79/07/07 2pp

7904180845 Executive Branch position re OPL Co application for amend to
export license, increasing quantity of depleted U authorized
for export to Canada Amend should be issued
SHEA, J R Office of International Programs 79/03/14 1p

7904180852 Amend 2 to RMI Co license 39-8542, increasing quantity of
melt authorized for export to 135,000 kg depleted U &
deleting condition 1
OPLINDEK, G G Assistant Director for Export/Import &
International Safeguards 79/03/22 1p

7904180729 RECE-79-28C
Inform Commissioners of receipt of 790258 application from
Edlow Intl Co for license to export 13,125 kg U to Italy
SHEA, J R Office of International Programs 79/04/19 1p

7904180747 Application by Edlow Intl Co for license to export 13,125 kg
U to Italy
HARRISON, D W Edlow International Co 79/02/16 1p

7904180754 RECE-79-20V
Inform Commissioners of Edlow Intl Co 790416 application
for license to export 40,000 kg U-308 to Brazil
SHEA, J R Office of International Programs 79/04/23 1p

7904180761 Application by Edlow Intl Co for license to export
40,000 kg U-308 to Brazil
HARRISON, D W Edlow International Co 79/04/16 1p

7904180766 Advise that application to export 50 short tons of U-308 to
is to fulfill requirements of Brazilian Resources Legislation
Lima US suppliers for application
HARRISON, D W Edlow International Co 79/04/17 1p

7904180779 Executive Branch position re Dresser Atlas Export Sales
application for license to export 4 curies Co-57 to China
License should be granted
HARRISON, D W Office of International Programs 79/05/17 1p

7904180771 RECE-79-249A
Inform Commissioners of OE 790412 license application amend
requesting rescheduling of first shipment date to 790321
SHEA, J R Office of International Programs 79/04/23 1p

7904180776 Requests application amend to reschedule first shipment date
to 790321. Also asks that DOE try requesting assurances be
expedited to Embassy of Japan to meet new schedule
requirements.
MILBURN, E D General Electric Co, Nuclear Energy Products Div.
79/04/23 1p

7904180777 Forward application for amend to export license, increasing
amount of SMR for export to Italy
SHEA, J R General Atomic Co 1900s of Gulf Oil Corp 79/05/08
1p

7904180800 Application for amend to GA Co export license, increasing
amount of SMR to 1.04 & restricted to 702 U-235 for export
to Italy
SHEA, J R General Atomic Co 1900s of Gulf Oil Corp 79/05/08
2pp

7904180801 Notify that license for Mitsui Bussan to export
13-day waiting period, due to urgent requirements
OPLINDEK, G G Assistant Director for Export/Import & International
Safeguards 79/05/14 1p

7904180802 RECE-79-28C
Forward Executive Branch position re Mitsubishi Intl Corp
application for license to export 342 kg U-235 to Japan
SHEA, J R Office of International Programs 79/04/19 1p

7904180804 Executive Branch position re Mitsubishi Intl Corp
application for license to export 342 kg U-235 enriched to
2.35 to Japan License should be granted
HARRISON, D W Office of International Programs 79/04/16 1p

7904180805 Forward application for export license
SHEA, J R General Atomic Special Metals Corp 79/05/11 1p

7904180807 Application by Goodrich Special Metals Corp for license to
export 5,100 pieces 131mcp-2 seamless tubing to South
Africa
SHEA, J R Goodrich Special Metals Corp 79/05/11 1p

7904180810 License for Tube Div of Kawasaki Denryo Industries, Inc
to export 2 pieces 131mcp-2 seamless tubing to South
Africa
OPLINDEK, G G Assistant Director for Export/Import & International
Safeguards 79/05/14 1p

7904180822 License for Isotope Products Lab to export 10 mCi Co-244 to
Canada
OPLINDEK, G G Assistant Director for Export/Import & International
Safeguards 79/05/13 2pp

7904180833 License for Sigma Chemical Co to export 5 kg heavy water to
Canada
OPLINDEK, G G Assistant Director for Export/Import & International
Safeguards 79/05/13 2pp

7904180839 Application by Rauter-Stuben, Inc for license to export
3,037 g U-enriched to max of 182 U-235, to West Germany
HARRISON, D W Rauter-Stuben, Inc 79/05/09 2pp

7904180847 Forward Marubeni America Corp application for license to
export 640 g U hexafluoride to Japan
SHEA, J R Marubeni America Corp 1900s of Marubeni Corp 1
79/05/07 1p

7904180850 Application by Marubeni America Corp for license to export
640 g U hexafluoride enriched to max of 12.185 U-235 to
Japan
HARRISON, D W Marubeni America Corp 1900s of Marubeni Corp 1
79/05/07 1p

7904180857 Forward application for export license
CLARK, E L Rhodia, Inc / Rhodia-Pauline, Inc 79/05/08 1p

7904180858 Application by Rhodia Pauline, Inc for license to export
107,302 kg U hexafluoride enriched to max of 0.435 U-235 to
Japan
HARRISON, D W Rhodia, Inc / Rhodia-Pauline, Inc 79/05/07 1p

7904180859 Application by Sigma Chemical Co for license to export
compound containing fluorine to India
HARRISON, D W Sigma Chemical Co, 1900s of Sigma Aldrich Corp 1
79/05/08 1p

7904180860 License for TE Nuclear Div to export 1.415 mg Pu-238 to The
Netherlands
OPLINDEK, G G Assistant Director for Export/Import & International
Safeguards 79/05/16 2pp

7904180861 License for Mitsubishi Intl Corp to export 230 mCi Co-232
to Japan
OPLINDEK, G G Assistant Director for Export/Import & International
Safeguards 79/05/17 2pp

NONDOCKETED ITEMS

285

7904290188 Amend 1 to Caracas Inc license, increasing quantity of metal for export to 36.47 kg thorium & extending expiration date to 03/01/91
OPLINGER, G. G. Assistant Director for Export/Import & International Safeguards 79/05/13 1p

7904290092 RECV-79-0356
Inform Commissioners of receipt of 790409 amend to application by German Dominguez to export U-235 fissile to Spain
SHEA, J.R. Office of International Programs 79/04/24 1p

7904290293 Discusses GA Co application for license to export Plutonium chamber to Italy. Quantity of 880 indicated in 790306 ltr has increased to 1.94 g U-235 & containing 1.72 g U-235
COFFEL, R. European Communities, Commission of 79/05/11 1p

7904290092 Forwards application for export license for minor nuclear metal, Ltr of assurance required
OPLINGER, G. G. Assistant Director for Export/Import & International Safeguards 79/05/26 1p

7904290094 Requests Executive Branch position re Bandvik Special Metals application for license to export Zircaloy-2 assembly tubing to Sweden.
OPLINGER, G. G. Assistant Director for Export/Import & International Safeguards 79/04/23 1p

7904290094 Requests Executive Branch position re Bandvik Special Metals application for license to export Zircaloy-2 assembly tubing to Sweden.
OPLINGER, G. G. Assistant Director for Export/Import & International Safeguards 79/04/23 1p

7904290259 Forwards request for addendum to application for license to export HAN Zircaloy-4 fuel channels to West Germany
HILBORN, S. G. Carpenter Technology Corp 79/05/08 1p

7904290263 Addendum to license application to export HAN Zircaloy-4 fuel channels to West Germany, changing proposed completion of final shipment to Mar 1988 & existing expiration date to 03/01/91
Carpenter Technology Corp 79/05/08 2p

7904290293 Requests amend to GA Co export license, extending expiration date to 01/01/91
HILBORN, S. G. General Electric Co., Nuclear Energy Products Div 80M-79132 79/05/07 1p

7904290293 Requests amend to GA Co export license, extending expiration date to 01/01/91
HILBORN, S. G. General Electric Co., Nuclear Energy Products Div 79/05/07 1p

7904290293 Requests amend to GA Co export license, extending expiration date to 01/01/91
HILBORN, S. G. General Electric Co., Nuclear Energy Products Div 79/05/07 1p

7904290293 Requests amend to GA Co export license, extending expiration date to 01/01/91
HILBORN, S. G. General Electric Co., Nuclear Energy Products Div 80M-79132 79/05/07 1p

7904290411 Application by GE for license to export two offgas filter vessels & associated valves to Italy.
HILBORN, S. G. General Electric Co 79/05/07 1p

7904290411 Application by Reuter-Stratos, Inc for license to export U-235, embedded as UO₂ on an internal surface of radiation detector, to West Germany
Reuter-Stratos, Inc 79/03/29 2p

7904290772 Application by Sighe Chemical Co for license to export components containing deuterium to The Netherlands.
STERM, K. C. Sighe Chemical Co (subs. of Sighe Aldrich Corp) 79/03/08 1p

7904290451 Ask receipt of 790418 ltr re Washington proposed export of power reactor components to Philippines Executive Branch views will be considered at requested hearings.
HENDRICK, J.R. Commission 79/03/02 1p

7904290094 RECV-79-0864
Forwards Executive Branch position re Edlow Intl Co application for license to export 503 kg U-235 to Italy.
SHEA, J.R. Office of International Programs 79/05/02 1p

7904290097 Executive Branch position re Edlow Intl Co application for license to export 503 kg enriched U-235 to Italy. License should be granted. Forwards ltr of assurance from Delegation of Commission of European Communities.
HENDRICK, J. R. State Dept. of Bureau of Oceanic & Internal Environment & Scientific Affairs 79/04/24 2p

7904290091 RECV-79-0274
Forwards Executive Branch position re GE application for license to export 201 kg enriched U-235 to Japan.
SHEA, J.R. Office of International Programs 79/05/11 1p

7904290094 Executive Branch position re GE application for license to export 201 kg enriched U-235 to Japan. License should be issued. Forwards 790427 ltr of assurance.
HENDRICK, J. R. State Dept. of 79/05/11 2p

7904290105 Confirms that HAN will be used in Fukushima Unit 4 in July 1980. HAN will be exported Sept 1979 & Dec 1979
HENDRICK, J. R. State Dept. of 79/05/11 1p

7904290105 Confirms that HAN will be used in Fukushima Unit 4 in July 1980. HAN will be exported Sept 1979 & Dec 1979
HENDRICK, J. R. State Dept. of 79/05/11 1p

7904290092 Amend 1 to license to export metal to West Germany, extending expiration date to 01/01/91
OPLINGER, G. G. Assistant Director for Export/Import & International Safeguards 79/03/18 1p

7904290094 Amend 2 to GE license to export metal to India, extending expiration date to 01/01/91
OPLINGER, G. G. Assistant Director for Export/Import & International Safeguards 79/05/10 1p

7904290094 License for Aldrich Chemical Co. Inc to export 100 g deuterium contained in 225 g compounds to Israel
OPLINGER, G. G. Assistant Director for Export/Import & International Safeguards 79/05/10 2p

7904290092 License for Sighe Chemical Co to export 2 kg heavy water to Argentina.
OPLINGER, G. G. Assistant Director for Export/Import & International Safeguards 79/03/18 2p

7904290092 Amend 1 to GA Co license, increasing export to 1.72 g U-235, contained in 1.94 g U enriched to 93% w/o max in one fusion chamber, to Italy.
OPLINGER, G. G. Assistant Director for Export/Import & International Safeguards 79/05/11 1p

7904290094 License for Aldrich Chemical Co. to export 19 g deuterium, contained in 100 g compounds to Israel
OPLINGER, G. G. Assistant Director for Export/Import & International Safeguards 79/03/18 2p

7904290460 License for Halverson Div to export 8450 lb Zircaloy-4 guide tube tubes & 300 lb Zircaloy-4 instrumentation tubes to France.
OPLINGER, G. G. Assistant Director for Export/Import & International Safeguards 79/03/18 1p

7904290091 Reviews proposed export of reactor components to Philippines
OPLINGER, G. G. Assistant Director for Export/Import & International Safeguards 79/03/02 2p

7904290092 Responds to 790269 memo re review of export of reactor components to Philippines
HENDRICK, J. R. Program Support Branch 79/05/15 1p

7904290092 Ack cooperation in attempt to ease equipment delay on shipment to Philippines.
HENDRICK, J. R. Westinghouse Electric Corp. 79/05/10 2p

7904290092 Requests that review of Philippines export license application be restricted to components covered by 10CFR101.32
HENDRICK, J. R. Westinghouse Electric Corp. 79/04/27 2p

7904290094 Amend 1 to Technical Operations, Inc license, increasing export amount to 5,000 lb depleted U in form of metal.
HENDRICK, J. R. State Dept. of 79/05/11 1p

7904290094 Amend 1 to Technical Operations, Inc license, increasing export amount to 5,000 lb depleted U in form of metal.
HENDRICK, J. R. State Dept. of 79/05/11 1p

NONDOCKETED ITEMS

7706250048 Amend 1 to GC license extending expiration date to 01/07/08 & deleting Condition 3, for mail exported to Austria
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/18 2p

7706250053 License for Sigma Chemical Co to export 10 kg heavy water to Israel
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/18 2p

7706250076 License for Aldrich Chemical Co to export 125 g deuterium contained in compounds to India
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/18 2p

7706250077 Recommendation of draft response to Assistant Secretary of State concerning re-export of nuclear components to Philippines IBC has taken no action to date
BAGG, J. F. Office of International Programs 7/9/04/02 4pp

7706250080 Amend 1 to GC license extending expiration date to 06/07/08 for mail exported to Sudan
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/18 1p

7706250084 License for Aldrich Chemical Co to export 14 g deuterium contained in compounds to Venezuela
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/18 2p

7706250086 License for Sigma Chemical Co to export 10 kg heavy water to Soviet Union
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/18 2p

7706250087 License for TW Nuclear Operations Inc to export 3,000 kg thorium in form of thorium oxide powder to Canada
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/18 1p

7706250093 License for Aldrich Chemical Co to export 150 g deuterium contained in 900 g compounds to Venezuela
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/18 2p

7706250096 License for Greiner Atlas Export Sales to export 4 CI Cr-527 contained in two stainless steel capsules to China
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/18 2p

7706250098 License for Aldrich Chemical Co to export 260 g deuterium contained in compounds to New Zealand
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/18 2p

7706250102 License for RCA Corp to export 60 mCi Pu-239 contained in three metal tubes containing air sent to Poland
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/18 2p

7706250104 License for Sigma Chemical Co to export 1 kg heavy water to Mexico
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/18 2p

7706250117 License for Mueller-Tschack Co to export 0.3 g thorium dioxide to be deposited on filaments of cathode ray tubes to Cambodia, Cuba, North Korea, Zimbabwe-Rhodesia, Uganda & Vietnam
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/18 2p

7706250124 License for Air Products & Chemicals Inc to export 27 g deuterium contained in steel cylinders to United Kingdom
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/18 2p

7706250129 License for Westinghouse to export two compressed ionized chambers, Type M, 22744, to France
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/18 1p

7706250144 License for Varion Export Corp to export 800 mCi Ni-63 coated in aluminum capsules detector to Cambodia, Cuba, North Korea, Zimbabwe-Rhodesia, Uganda & Vietnam
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/18 2p

7706250188 Executive Branch position re Westinghouse application for license to export reactor parts & components to Philippines License should be granted
FICKELING, T. R. State Dept. of 7/9/05/12 2pp

7706250228 Response to 770033 license application to export components for nuclear power plant to Philippines Components not sold to NPC licensing authority
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/22 1p

7706250241 Response to 770037 request for review of Westinghouse application to export components to Philippines Components in Exhibit A may be accepted under general license Components in Exhibit B require special license
BAGG, J. F. Program Support Branch 7/9/05/18 1p

7706250249 Concurrence WMR Peterson 770123 draft staff paper re proposed Westinghouse license to export components to nuclear power plant in Philippines Specifies two deletions to memo to file attachment B
BAGG, J. F. Office of Nuclear Material Safety & Safeguards 7/9/01/16 1p

7706250249 Requests review of Westinghouse list of components to determine which are sold to special license for export to Philippines Action on license will come after final action on related Export License 28-18
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/06/07 1p

7706250251 Forwarded equipment export license application Expedited approval is necessary to assure continued cost of plant in Philippines
MOTTE, J. R. CHINELL, R. J. Westinghouse Electric Corp 7/9/05/18-1834 7/9/05/03 4pp

7706250251 Forwarded equipment export license application Expedited approval is necessary to assure continued cost of plant in Philippines
MOTTE, J. R. CHINELL, R. J. Westinghouse Electric Corp 7/9/05/18-1834 7/9/05/03 4pp

7706250254 Application by Westinghouse for license to export various components to Philippines List of Philippines project shipments for 1978 and 1
MOTTE, J. R. Westinghouse Electric Corp 7/9/06/03 1p

7706250254 Application by Westinghouse for license to export various components to Philippines List of Philippines project shipments for 1978 and 1
MOTTE, J. R. Westinghouse Electric Corp 7/9/06/03 1p

7706250257 Executive Branch position re Allow Intl Co application for license to export 120,243 kg U in form of U-235 to France & United Kingdom License should be granted for assurance
BAGG, J. F. State Dept. of 7/9/05/22 2pp

7706250243 License for Sigma Chemical Co to export 4 kg heavy water to Australia License authorizes export only, not use, receipt or possession
OPLINER, D. G. Assistant Director for Export/Import & International Safeguards 7/9/05/18 2p

7706250212 Executive Branch position re Transnuclear Inc application for license to export 740 Gg of U-235 plus 0.34 kg U-235 as sampling melt to Switzerland via West Germany License should be granted for assurance and 1
BAGG, J. F. State Dept. of 7/9/05/12 2pp

7706250109 Executive Branch position re Unipac Intl application for license to export 700 kg deuterium to North Korea License should be granted
BAGG, J. F. State Dept. of Bureau of Defense & Internal Scientific Affairs 7/9/05/22 2pp

7904290185 Executive Branch position re Edlow Intl Co application for license to export 1,000 metric tons natural U in form of U-308 to United Kingdom license should be granted Ltr of assurance encl.
HSEMD:L.V. State Dept of Bureau of Ocean & International Marine & Scientific Affairs 79/03/23 2pp

7904290239 Application by Rocky Mountain Nuclear Co for license to export shd & remote operated pipe connector to United Kingdom
HSEMD:L.V. Rocky Mountain Nuclear Co 79/03/16 1p

7904290366 Ltr of assurance re Westinghouse license to export U dioxide enriched pellets, encapsulated in sealed fuel rods & assembled into fuel assemblies & four pieces of detector detectors to South Korea
HSEMD:L.V. Korea, Republic of (South Korea) 79/04/17 1p

7904290018 Requests amend to Mitsubishi Intl Corp export license assignments, Nuclear Fuel Industries Ltd.
WATMAN:R.H. Mitsubishi International Corp (subs of Mitsubishi Corp) HSEMD:L.V. 79/03/15 1p

7904290021 Forward application for license to export minor nuclear fuel Ltr of assurance required W/O encl.
OPLIN:R.D. Assistant Director for Export/Import & International Safeguards 79/03/24 1p

7904290280 Application by Westinghouse for license to export encapsulated ionization chambers to France
HSEMD:L.V. Westinghouse Electric Corp 79/03/23 1p

7904290276 Requests NRC action on component export license filed on behalf of Mall Power Corp of Philippines Govt. Coast delays have become critical due to inability to secure authority to export.
HSEMD:L.V. Westinghouse Electric Corp 79/03/22 2pp

7904290309 License for GA Co to export 2,040 kg U-235, contained in 10,380 kg U in fabricated fuel elements to Thailand
OPLIN:R.D. Assistant Director for Export/Import & International Safeguards 79/03/24 1p

7904290194 SECY-79-028
Inform Commission of receipt of GE application for license to export Tanager reactor replacement parts & components to India
HSEMD:L.V. Office of International Programs 79/03/10 1p

7904290011 Application by GE for license to export Tanager reactor replacement parts & components to India
HSEMD:L.V. General Electric Co 79/04/23 2pp

7904290256 License for Blythe Chemical Co to export 2 kg heavy water to the Netherlands
OPLIN:R.D. Assistant Director for Export/Import & International Safeguards 79/03/23 2pp

7904290201 SECY-79-029
Inform Commission of receipt of Mitsui & Co application for license to export U-enriched to 2.95% in 102 kg U-235, to Japan
HSEMD:L.V. Office of International Programs 79/03/11 1p

7904290253 Furnishes Mitsui & Co application for license to export U, enriched to 2.95% in 102 kg U-235 to Japan
HSEMD:L.V. Mitsui & Co Ltd 79/03/01 1p

7904290071 Inform Commission of receipt of Edlow Intl Co license application to export 1,000 metric tons of U contained in 1,100 metric tons U-308 to United Kingdom
HSEMD:L.V. Office of International Programs 79/03/11 1p

7904290285 Forward license application to export 1,000 metric tons U, contained in 1,100 metric tons of U-308 to United Kingdom
License is extension of expired license 508-7932
HSEMD:L.V. Edlow International Co 79/03/07 1p

7904290046 SECY-79-046
Recommend approval of amend to Aerojet Ordnance & Hfg Co license to export 45,040 kg U contained in 45,260 kg depleted U to Canada
HSEMD:L.V. Office of International Programs 79/03/14 2pp

7904290112 License for Aerojet Ordnance & Hfg Co to export 45,040 kg U contained in 45,300 kg depleted U to Canada
OPLIN:R.D. Assistant Director for Export/Import & International Safeguards 79/03/14 2pp

7904290279 Amend 1 to license for Aerojet Ordnance & Hfg Co, increasing amount of mail authorized for export to 100,000 kg depleted U contained in 100,704 kg depleted U alloy
OPLIN:R.D. Assistant Director for Export/Import & International Safeguards 79/03/14 1p

7904290143 Executive Branch position re Radium Chemical Co, Inc application for license to export 150,000 copper telluride to Switzerland
HSEMD:L.V. State Dept of 79/03/23 2pp

7904290214 SECY-79-014
Inform Commissioners of Executive Branch response to pending license application for Minsho-Dual American Corp to export 5,448 kg U-235, enriched to 45.4%, to Japan Forwarders application 790420 ltr requesting amend to application
HSEMD:L.V. Office of International Programs 79/03/11 1p

7904290218 Executive Branch position re Minsho-Dual American Corp application for license to export 5,448 kg U-235, contained in 12 kg U-235 enriched to 45.4% in form of U metal, to Japan, W/supplementing documentation
HSEMD:L.V. Defense Dept of 79/03/01 17pp

7904290244 Requests license for Westinghouse to export reactor pressure tubes & any other component specially designed or prepared for use in nuclear reactor to Canada
HSEMD:L.V. Westinghouse Electric Corp 79/03/18 2pp

7904290253 Executive Branch position re GA Co application for license to export 2,040 kg U-235, fabricated in 10,380 fuel elements to Thailand license should be granted
HSEMD:L.V. State Dept of 79/03/23 2pp

7904290277 Executive Branch position re Mitsui & Co (USA) application for license to export 2,95% U-235 in 102 kg U-235, to Japan
U enriched to 2.95% to Japan License should be granted Ltr of assurance encl.
HSEMD:L.V. State Dept of 79/03/23 2pp

7904290249 Contacts member of France Soc Co export license Contract member should be SP-0403
HSEMD:L.V. Office of International Programs 79/03/30 1p

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
ABERTH, J.	7704142104	103P		ABOGHIN, G. C.	7706290086	95-293	0
ABRAM, H.	7704020240	50-320	F	ABOGHIN, H. S.	7704090108	40-0452	8
ABRAM, C. J.	7704020251	71-70	C	ABOGHIN, H. S.	7704100504	40-0452	C
ABRAM, C. J.	7704020252	71-70	C	ABOGHIN, H. S.	7706290477	40-0452	C
ABSTON, G. G.	7704020203	50-324	H	ABOGHIN, H. S.	7706100547	50-375	0
ACKERMAN, N. J.	7704060028	50-320	P	ABOGHIN, H. S.	7704040205	50-383	0
ADAMS, H. E.	7704040148	71-323	C	ABOGHIN, R. L.	7706290534	50-325	0
ADAMS, J. R.	7704130520	50-320	H	ABOGHIN, R. L.	7706050292	50-320	0
ADAMS, J. R.	7704010049	049P		ABOGHIN, R. L.	7706290586	50-320	F
ADAMS, A. K.	7704050043	813		ADOLG, C. D.	7704020175	50-320	U
ADAMS, J. F.	7704060488	50-320	P	ADOLG, C. D.			
ADAMS, J. F.	7704060503	50-346	F	ADOLG, C. D.			
ADAMS, J. F.	7704060474	50-320	F	ADOLG, C. D.			
ADAMS, J. F.	7704040111	105P		ADOLG, C. D.			
ADAMS, J. F.	7704060488	50-320	P	ADOLG, C. D.			
ADAMS, J. F.	7704060503	50-346	F	ADOLG, C. D.			
ADAMS, J. F.	7704060474	50-320	F	ADOLG, C. D.			
ADAMS, J. F.	7704040111	105P		ADOLG, C. D.			
ADAMS, J. F.	7704060488	50-320	P	ADOLG, C. D.			
ADAMS, J. F.	7704060503	50-346	F	ADOLG, C. D.			
ADAMS, J. F.	7704060474	50-320	F	ADOLG, C. D.			
ADAMS, J. F.	7704040111	105P		ADOLG, C. D.			
ADAMS, J. F.	7704060488	50-320	P	ADOLG, C. D.			
ADAMS, J. F.	7704060503	50-346	F	ADOLG, C. D.			
ADAMS, J. F.	7704060474	50-320	F	ADOLG, C. D.			
ADAMS, J. F.	7704040111	105P		ADOLG, C. D.			
ADAMS, J. F.	7704060488	50-320	P	ADOLG, C. D.			
ADAMS, J. F.	7704060503	50-346	F	ADOLG, C. D.			
ADAMS, J. F.	7704060474	50-320	F	ADOLG, C. D.			
ADAMS, J. F.	7704040111	105P		ADOLG, C. D.			
ADAMS, J. F.	7704060488	50-320	P	ADOLG, C. D.			
ADAMS, J. F.	7704060503	50-346	F	ADOLG, C. D.			
ADAMS, J. F.	7704060474	50-320	F	ADOLG, C. D.			
ADAMS, J. F.	7704040111	105P		ADOLG, C. D.			
ADAMS, J. F.	7704060488	50-320	P	ADOLG, C. D.			
ADAMS, J. F.	7704060503	50-346	F	ADOLG, C. D.			
ADAMS, J. F.	7704060474	50-320	F	ADOLG, C. D.			
ADAMS, J. F.	7704040111	105P		ADOLG, C. D.			
ADAMS, J. F.	7704060488	50-320	P	ADOLG, C. D.			
ADAMS, J. F.	7704060503	50-346	F	ADOLG, C. D.			
ADAMS, J. F.	7704060474	50-320	F	ADOLG, C. D.			
ADAMS, J. F.	7704040111	105P		ADOLG, C. D.			
ADAMS, J. F.	7704060488	50-320	P	ADOLG, C. D.			
ADAMS, J. F.	7704060503	50-346	F	ADOLG, C. D.			
ADAMS, J. F.	7704060474	50-320	F	ADOLG, C. D.			
ADAMS, J. F.	7704040111	105P		ADOLG, C. D.			
ADAMS, J. F.	7704060488	50-320	P	ADOLG, C. D.			
ADAMS, J. F.	7704060503	50-346	F	ADOLG, C. D.			
ADAMS, J. F.	7704060474	50-320	F	ADOLG, C. D.			
ADAMS, J. F.	7704040111	105P		ADOLG, C. D.			
ADAMS, J. F.	7704060488	50-320	P	ADOLG, C. D.			
ADAMS, J. F.	7704060503	50-346	F	ADOLG, C. D.			
ADAMS, J. F.	7704060474	50-320	F	ADOLG, C. D.			
ADAMS, J. F.	7704040111						

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

295

[illegible]

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
CHILK, B. J.	77042402369	SPURTLIC		CHURCHOFF, M. B.	77042500266	93-254	C
CHILK, B. J.	77042402394	10CFR		CHURCHOFF, C. H.	77042445511	93-2	C
CHILK, B. J.	77042402401	10CFR		CHURCHOFF, S.	77042452201	93-837	C
CHILK, B. J.	77042402404	10CFR		CHURCHILL, B. W.	77042510311	93-552	C
CHILK, B. J.	77042402409	10CFR		CHURCHILL, B. W.	77042510364	93-344	C
CHILK, B. J.	77042402434	10CFR					
CHILK, B. J.	77042402471	10CFR		CINA, T.	77041700991	93-295	C
CHILK, B. J.	77042402501	10CFR		CITELLI, R. J.	77042502051	SPURTLIC	
CHILK, B. J.	77042402504	10CFR		CLARK, R. L.	77041101017	NAFTE	
CHILK, B. J.	77042402507	10CFR		CLARK, R. L.	77041101017	SPURTLIC	
CHILK, B. J.	77042402508	10CFR		CLARK, R. H.	77040202129	93-445	H
CHILK, B. J.	77042402544	93-444	C	CLARK, R. H.	77041700324	93-445	H
CHILK, B. J.	77042402548	93-444	C	CLARK, R. H.	77042502187	93-445	H
CHILK, B. J.	77042402549	93-444	C	CLARK, R. A.	77042002029	77042500409	
CHILK, B. J.	77042402557	10CFR		CLARK, R. L.	77042904687	NAFTE	
CHILK, B. J.	77042402559	10CFR		CLARK, A. T.	77042302179	93-201	P
CHILK, B. J.	77042402593	10CFR		CLARK, R. A.	77042903223	93-589	A
CHILK, B. J.	77042402607	93-209	P	CLAYTON, F. L.	77042904683	93-242	P
CHILK, B. J.	77042402614	10CFR		CLAYTON, F. L.	77042502247	93-243	P
CHILK, B. J.	77042402628	93-400	C	CLAYTON, F. L.	77042907061	93-048	P
CHILK, B. J.	77042402699	10CFR		CLAYTON, F. L.	77042907023	93-048	P
CHILK, B. J.	77042402694	93-247	C	CLAYTON, F. L.	77042502280	93-048	P
CHILK, B. J.	77042402718	93-012	C	CLAYTON, F. L.	77042502279	93-048	P
CHILK, B. J.	77042402819	93-240	P	CLAYTON, F. L.	77042510226	93-248	P
CHILK, B. J.	77042402821	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402822	93-240	P	CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402823	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402824	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402825	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402826	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402827	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402828	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402829	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402830	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402831	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402832	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402833	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402834	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402835	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402836	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402837	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402838	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402839	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402840	10CFR		CLAYTON, F. L.	77042510229	93-048	P
CHILK, B. J.	77042402841						

PERSONAL AUTHOR INDEX

307

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
DAVIS, J. S.	7906210027	50-330 P		DENTON, H. R.	7906270076	50-280 H	
DAVIS, J. O.	7906270036	FDIA		DENTON, H. R.	7906270080	50-280 H	
DAVIS, J. O.	7906270014	50-320 P		DENTON, H. R.	7906270087	50-280 H	
DAVIS, J. O.	7906270024	FDIA		DENTON, H. R.	7906270095	50-280 H	
DAVIS, J. O.	7906270070	FDIA		DENTON, H. R.	7906270100	50-280 H	
DAVIS, J. O.	7906270048	FDIA		DENTON, H. R.	7906270119	50-280 H	
DAVIS, J. O.	7906260019	50-346 F		DENTON, H. R.	7906270144	50-280 H	
DAVIS, J. O.	7906260110	70-088 C		DENTON, H. R.	7906270132	50-280 H	
DAVIS, J. O.	7906270003	50-330 F		DENTON, H. R.	7906270143	50-280 H	
DAVIS, J. O.	7906270062	FDIA		DENTON, H. R.	7906270151	50-280 H	
DAVIS, J. O.	7906270012	50-482 A		DENTON, H. R.	7906270063	50-280 H	
DAVIS, J. O.	7906270047	FDIA		DENTON, H. R.	7906270268	50-280 H	
DAVIS, J. O.	7906260171	50-482 B		DENTON, H. R.	7906270367	50-280 H	
DAVIS, J. O.	7906260180	50-315 A		DENTON, H. R.	7906260422	50-320 H	
DAVIS, J. O.	7906260140	50-315 D		DENTON, H. R.	7906260322	50-320 H	
DAVIS, A. B.	7906260074	50-013 G		DENTON, H. R.	7906260330	50-359 F	
DAVIS, A. B.	7906260093	50-013 G		DENTON, H. R.	7906260377	50-359 F	
DAVIS, A. B.	7906260213	70-1330 C		DENTON, H. R.	7906260421	50-360 H	
DAVIS, A. B.	7906260121	50-013 B		DENTON, H. R.	7906260492	50-360 H	
DAVIS, A. B.	7906260117	50-013 D		DENTON, H. R.	7906260522	50-320 H	
DAVIS, A. B.	7906260126	70-1330 C		DENTON, H. R.	7906260528	50-320 H	
DAVIS, A. B.	7906260097	50-013 G		DENTON, H. R.	7906260556	50-320 H	
DAVIS, D. K.	7906260007	50-320 A		DENTON, H. R.	7906260609	50-320 H	
DAVIS, D. H.	7906270004	70-1330 C		DENTON, H. R.	7906260619	50-320 H	
DAVIS, D. M.	7906260158	70-1330 C		DENTON, H. R.	7906260616	50-320 H	
DAVIS, D. R.	7906270086	70-1330 C		DENTON, H. R.	7906260128	50-320 H	
DAV, J.	7906270419	FE		DENTON, H. R.	7906260224	50-320 H	
DEALE, V. B.	7906190616	50-329 F		DENTON, H. R.	7906260278	50-424 G	
DEAN, J. B.	7906210203	50-021 F		DENTON, H. R.	7906260282	50-424 G	
DEANE, E. G.	7906290223	50-019		DENTON, H. R.	7906260297	50-424 G	
DEANE, E. G.	7906290211	50-019		DENTON, H. R.	7906260284	50-424 G	
DEAN, V. A.	7906270046	50-019	NUC89/ER-9648	DEPHILIPP, A. A.	7906230121	40-8884 G	
DEBELL, G. B.	7906260179	50-482 B		DESHIELD, P. F.	7906260360	50-019	
DEBORA, E. R.	7906110049	50-019		DESHIELD, P. F.	7906260373	50-280 B	
DECOMPTRE, B.	7906260246	50-019		DESHIELD, P. F.	7906260373	50-280 B	
DELO, F. H.	7906270224	50-023 J		DESHIELD, P. F.	7906260373	50-280 B	
DELO, J. H.	7906270224	50-023 J		DESHIELD, P. F.	7906260373	50-280 B	
DELL, V. R.	7906260470	FDIA		DESHIELD, P. F.	7906260373	50-280 B	
DELANEY, J. C.	7906260425	70-143 C		DESHIELD, P. F.	7906260373	50-280 B	
DELANEY, J. C.	7906260733	70-487 C		DESHIELD, P. F.	7906260373	50-280 B	
DELANEY, J. C.	7906260733	70-487 C		DESHIELD, P. F.	7906260373	50-280 B	
DELAPEZ, A.	7906260604	50-019		DESHIELD, P. F.	7906260373	50-280 B	
DELAPEZ, A.	7906260609	50-019		DESHIELD, P. F.	7906260373	50-280 B	
DELORE, L. O.	7906110089	50-073 B		DESHIELD, P. F.	7906260373	50-280 B	
DELORE, L. O.	7906260604	50-073 B		DESH			

PERSONAL AUTHOR INDEX

[illegible]

AUTHOR	ACCOUNT NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCOUNT NUMBER	SUBJECT CATEGORY	REPORT NUMBER
ENGELMAN, R. H.	7906180456	50-326	0	ENGELMAN, R. H.	7906180373	50-133	G
ENGELMAN, R. H.	7906180455	50-326	0	ENGELMAN, R. H.	7906180374	50-135	G
ENGELMAN, R. H.	7906180454	50-142	0	ENGELMAN, R. H.	7906180375	50-241	G
ENGELMAN, R. H.	7906180453	50-324	0	ENGELMAN, R. H.	7906180376	50-377	0
ENGELMAN, R. H.	7906180452	50-110	0	ENGELMAN, R. H.	7906180377	50-368	P
ENGELMAN, R. H.	7906180451	50-423	0	ENGELMAN, R. H.	7906180378	50-360	0
ENGELMAN, R. H.	7906180450	50-129	0	ENGELMAN, R. H.	7906180379	50-441	0
ENGELMAN, R. H.	7906180449	50-327	0	ENGELMAN, R. H.	7906180380	50-350	0
ENGELMAN, R. H.	7906180448	50-394	0	ENGELMAN, R. H.	7906180381	50-394	0
ENGELMAN, R. H.	7906180472	50-328	0	ENGELMAN, R. H.	7906180382	50-394	0
ENGELMAN, R. H.	7906180471	50-344	0	ENGELMAN, R. H.	7906180383	50-394	0
ENGELMAN, R. H.	7906180470	50-128	0	ENGELMAN, R. H.	7906180384	50-394	0
ENGELMAN, R. H.	7906180469	50-304	0	ENGELMAN, R. H.	7906180385	50-394	0
ENGELMAN, R. H.	7906180468	50-312	0	ENGELMAN, R. H.	7906180386	50-394	0
ENGELMAN, R. H.	7906180467	50-397	0	ENGELMAN, R. H.	7906180387	50-397	0
ENGELMAN, R. H.	7906180466	50-397	0	ENGELMAN, R. H.	7906180388	50-397	0
ENGELMAN, R. H.	7906180465	50-397	0	ENGELMAN, R. H.	7906180389	50-397	0
ENGELMAN, R. H.	7906180464	50-397	0	ENGELMAN, R. H.	7906180390	50-397	0
ENGELMAN, R. H.	7906180463	50-397	0	ENGELMAN, R. H.	7906180391	50-397	0
ENGELMAN, R. H.	7906180462	50-397	0	ENGELMAN, R. H.	7906180392	50-397	0
ENGELMAN, R. H.	7906180461	50-397	0	ENGELMAN, R. H.	7906180393	50-397	0
ENGELMAN, R. H.	7906180460	50-397	0	ENGELMAN, R. H.	7906180394	50-397	0
ENGELMAN, R. H.	7906180459	50-397	0	ENGELMAN, R. H.	7906180395	50-397	0
ENGELMAN, R. H.	7906180458	50-397	0	ENGELMAN, R. H.	7906180396	50-397	0
ENGELMAN, R. H.	7906180457	50-397	0	ENGELMAN, R. H.	7906180397	50-397	0
ENGELMAN, R. H.	7906180456	50-397	0	ENGELMAN, R. H.	7906180398	50-397	0
ENGELMAN, R. H.	7906180455	50-397	0	ENGELMAN, R. H.	7906180399	50-397	0
ENGELMAN, R. H.	7906180454	50-397	0	ENGELMAN, R. H.	7906180400	50-397	0
ENGELMAN, R. H.	7906180453	50-397	0	ENGELMAN, R. H.	7906180401	50-397	0
ENGELMAN, R. H.	7906180452	50-397	0	ENGELMAN, R. H.	7906180402	50-397	0
ENGELMAN, R. H.	7906180451	50-397	0	ENGELMAN, R. H.	7906180403	50-397	0
ENGELMAN, R. H.	7906180450	50-397	0	ENGELMAN, R. H.	7906180404	50-397	0
ENGELMAN, R. H.	7906180449	50-397	0	ENGELMAN, R. H.	7906180405	50-397	0
ENGELMAN, R. H.	7906180448	50-397	0	ENGELMAN, R. H.	7906180406	50-397	0
ENGELMAN, R. H.	7906180447	50-397	0	ENGELMAN, R. H.	7906180407	50-397	0
ENGELMAN, R. H.	7906180446	50-397	0	ENGELMAN, R. H.	7906180408	50-397	0
ENGELMAN, R. H.	7906180445	50-397	0	ENGELMAN, R. H.	7906180409	50-397	0
ENGELMAN, R. H.	7906180444	50-397	0	ENGELMAN, R. H.	7906180410	50-397	0
ENGELMAN, R. H.	7906180443	50-397	0	ENGELMAN, R. H.	7906180411	50-397	0
ENGELMAN, R. H.	7906180442	50-397	0	ENGELMAN, R. H.	7906180412	50-397	0
ENGELMAN, R. H.	7906180441	50-397	0	ENGELMAN, R. H.	7906180413	50-397	0
ENGELMAN, R. H.	7906180440	50-397	0	ENGELMAN, R. H.	7906180414	50-397	0
ENGELMAN, R. H.	7906180439	50-397	0	ENGELMAN, R. H.	7906180415	50-397	0
ENGELMAN, R. H.	7906180438	50-397	0	ENGELMAN, R. H.	7906180416	50-397	0
ENGELMAN, R. H.	7906180437	50-397	0	ENGELMAN, R. H.	7906180417	50-397	0
ENGELMAN, R. H.	7906180436	50-397	0	ENGELMAN, R. H.	7906180418	50-397	0
ENGELMAN, R. H.	7906180435	50-397	0	ENGELMAN, R. H.	7906180419	50-397	0
ENGELMAN, R. H.	7906180434	50-397	0	ENGELMAN, R. H.	7906180420	50-397	0
ENGELMAN, R. H.	7906180433	50-397	0	ENGELMAN, R. H.	7906180421	50-397	0
ENGELMAN, R. H.	7906180432	50-397	0	ENGELMAN, R. H.	7906180422	50-397	0
ENGELMAN, R. H.	7906180431	50-397	0	ENGELMAN, R. H.	7906180423	50-397	0
ENGELMAN, R. H.	7906180430	50-397	0	ENGELMAN, R. H.	7906180424	50-397	0
ENGELMAN, R. H.	7906180429	50-397	0	ENGELMAN, R. H.	7906180425	50-397	0
ENGELMAN, R. H.	7906180428	50-397	0	ENGELMAN, R. H.	7906180426	50-397	0
ENGELMAN, R. H.	7906180427	50-397	0	ENGELMAN, R. H.	7906180427	50-397	0
ENGELMAN, R. H.	7906180426	50-397	0	ENGELMAN, R. H.	7906180428	50-397	0
ENGELMAN, R. H.	7906180425	50-397	0	ENGELMAN, R. H.	7906180429	50-397	0
ENGELMAN, R. H.	7906180424	50-397	0	ENGELMAN, R. H.	7906180430	50-397	0
ENGELMAN, R. H.	7906180423	50-397	0	ENGELMAN, R. H.	7906180431	50-397	0
ENGELMAN, R. H.	7906180422	50-397	0	ENGELMAN, R. H.	7906180432	50-397	0
ENGELMAN, R. H.	7906180421	50-397	0	ENGELMAN, R. H.	7906180433	50-397	0
ENGELMAN, R. H.	7906180420	50-397	0	ENGELMAN, R. H.	7906180434	50-397	0
ENGELMAN, R. H.	7906180419	50-397	0	ENGELMAN, R. H.	7906180435	50-397	0
ENGELMAN, R. H.	7906180418	50-397	0	ENGELMAN, R. H.	7906180436	50-397	0
ENGELMAN, R. H.	7906180417	50-397	0	ENGELMAN, R. H.	7906180437	50-397	0
ENGELMAN, R. H.	7906180416	50-397	0	ENGELMAN, R. H.	7906180438	50-397	0
ENGELMAN, R. H.	7906180415	50-397	0	ENGELMAN, R. H.	7906180439	50-397	0
ENGELMAN, R. H.	7906180414	50-397	0	ENGELMAN, R. H.	7906180440	50-397	0
ENGELMAN, R. H.	7906180413	50-397	0	ENGELMAN, R. H.	7906180441	50-397	0
ENGELMAN, R. H.	7906180412	50-397	0	ENGELMAN, R. H.	7906180442	50-397	0
ENGELMAN, R. H.	7906180411	50-397	0	ENGELMAN, R. H.	7906180443	50-397	0
ENGELMAN, R. H.	7906180410	50-397	0	ENGELMAN, R. H.	7906180444	50-397	0
ENGELMAN, R. H.	7906180409	50-397	0	ENGELMAN, R. H.	7906180445	50-397	0
ENGELMAN, R. H.	7906180408	50-397	0	ENGELMAN, R. H.	7906180446	50-397	0
ENGELMAN, R. H.	7906180407	50-397	0	ENGELMAN, R. H.	7906180447	50-397	0
ENGELMAN, R. H.	7906180406	50-397	0	ENGELMAN, R. H.	7906180448	50-397	0
ENGELMAN, R. H.	7906180405	50-397	0	ENGELMAN, R. H.	7906180449	50-397	0
ENGELMAN, R. H.	7906180404	50-397	0	ENGELMAN, R. H.	7906180450	50-397	0
ENGELMAN, R. H.	7906180403	50-397	0	ENGELMAN, R. H.	7906180451	50-397	0
ENGELMAN, R. H.	7906180402	50-397	0	ENGELMAN, R. H.	7906180452	50-397	0
ENGELMAN, R. H.	7906180401	50-397	0	ENGELMAN, R. H.	7906180453	50-397	0
ENGELMAN, R. H.	7906180400	50-397	0	ENGELMAN, R. H.	7906180454	50-397	0
ENGELMAN, R. H.	7906180399	50-397	0	ENGELMAN, R. H.	7906180455	50-397	0
ENGELMAN, R. H.	7906180398	50-397	0	ENGELMAN, R. H.	7906180456	50-397	0
ENGELMAN, R. H.	7906180397	50-397	0	ENGELMAN, R. H.	7906180457	50-397	0
ENGELMAN, R. H.	7906180396	50-397	0	ENGELMAN, R. H.	7906180458	50-397	0
ENGELMAN, R. H.	7906180395	50-397	0	ENGELMAN, R. H.	7906180459	50-397	0
ENGELMAN, R. H.	7906180394	50-397	0	ENGELMAN, R. H.	7906180460	50-397	0
ENGELMAN, R. H.	7906180393	50-397	0	ENGELMAN, R. H.	7906180461	50-397	0
ENGELMAN, R. H.	7906180392	50-397	0	ENGELMAN, R. H.	7906180462	50-397	0
ENGELMAN, R. H.	7906180391	50-397	0	ENGELMAN, R. H.	7906180463	50-397	0
ENGELMAN, R. H.	7906180390	50-397	0	ENGELMAN, R. H.	7906180464	50-397	0
ENGELMAN, R. H.	7906180389	50-397	0	ENGELMAN, R. H.	7906180465	50-397	0
ENGELMAN, R. H.	7906180388	50-397	0	ENGELMAN, R. H.	7906180466	50-397	0
ENGELMAN, R. H.	7906180387	50-397	0	ENGELMAN, R. H.	7906180467	50-397	0
ENGELMAN, R. H.	7906180386	50-397	0	ENGELMAN, R. H.	7906180468	50-397	0
ENGELMAN, R. H.	7906180385	50-397	0	ENGELMAN, R. H.	7906180469	50-397	0
ENGELMAN, R. H.	7906180384	50-397	0	ENGELMAN, R. H.	7906180470	50-397	0
ENGELMAN, R. H.	7906180383	50-397	0	ENGELMAN, R. H.	7906180471	50-397	0
ENGELMAN, R. H.	7906180382	50-397	0	ENGELMAN, R. H.	7906180472	50-397	0
ENGELMAN, R. H.	7906180381	50-397	0	ENGELMAN, R. H.	7906180473	50-397	0
ENGELMAN, R. H.	7906180380	50-397	0	ENGELMAN, R. H.	7906180474	50-397	0
ENGELMAN, R. H.	7906180379	50-397	0	ENGELMAN, R. H.	7906180475	50-397	0
ENGELMAN, R. H.	7906180378	50-397	0	ENGELMAN, R. H.	7906180476	50-397	0
ENGELMAN, R. H.	7906180377	50-397	0	ENGELMAN, R. H.	7906180477	50-397	0
ENGELMAN, R. H.	7906180376	50-397	0	ENGELMAN, R. H.	7906180478	50-397	0
ENGELMAN, R. H.	7906180375	50-397	0	ENGELMAN, R. H.	7906180479	50-397	0
ENGELMAN, R. H.	7906180374	50-397	0	ENGELMAN, R. H.	7906180480	50-397	0
ENGELMAN, R. H.	7906180373	50-397	0	ENGELMAN, R. H.	7906180481	50-397	0
ENGELMAN, R. H.	7906180372	50-397	0	ENGELMAN, R. H.	7906180482	50-397	0
ENGELMAN, R. H.	7906180371	50-397	0	ENGELMAN, R. H.	7906180483	50-397	0
ENGELMAN, R. H.	7906180370	50-397	0	ENGELMAN, R. H.	7906180484	50-397	0
ENGELMAN, R. H.	7906180369	50-397	0	ENGELMAN, R. H.	7906180485	50-397	0
ENGELMAN, R. H.	7906180368	50-397	0	ENGELMAN, R. H.	7906180486	50-397	0
ENGELMAN, R. H.	7906180367	50-397	0	ENGELMAN, R. H.	7906180487	50-397	0
ENGELMAN, R. H.	7906180366	50-397	0	ENGELMAN, R. H.	7906180488	50-397	0
ENGELMAN, R. H.	7906180365	50-397	0	ENGELMAN, R. H.	7906180489	50-397	0
ENGELMAN, R. H.	7906180364	50-397	0	ENGELMAN, R. H.	7906180490	50-397	0
ENGELMAN, R. H.	7906180363	50-397	0	ENGELMAN, R. H.	7906180491	50-397	0
ENGELMAN, R. H.	7906180362	50-397	0	ENGELMAN, R. H.	7906180492	50-397	0
ENGELMAN, R. H.	7906180361	50-397	0	ENGELMAN, R. H.	7906180493	50-397	0
ENGELMAN, R. H.	7906180360	50-397	0	ENGELMAN, R. H.	7906180494	50-397	0
ENGELMAN, R. H.	7906180359	50-397	0	ENGELMAN, R. H.	7906180495	50-397	0
ENGELMAN, R. H.	7906180358	50-397	0	ENGELMAN, R. H.	7906180496	50-397	0
ENGELMAN, R. H.	7906180357	50-397	0	ENGELMAN, R. H.	7906180497	50-397	0
ENGELMAN, R. H.	7906180356	50-397	0	ENGELMAN, R. H.	7906180498	50-397	0
ENGELMAN, R. H.	7906180355	50-397	0	ENGELMAN, R. H.	7906180499	50-397	0
ENGELMAN, R. H.	7906180354	50-397	0	ENGELMAN, R. H.	7906180500	50-397	0
ENGELMAN, R. H.	7906180353	50-397	0	ENGELMAN, R. H.	7906180501	50-397	0
ENGELMAN, R. H.	7906180352	50-397	0	ENGELMAN, R. H.	7906180502	50-397	0
ENGELMAN, R. H.	7906180351	50-397	0	ENGELMAN, R. H.	7906180503	50-397	0
ENGELMAN, R. H.	7906180350	50-397	0	ENGELMAN, R. H.	7906180504	50-397	0
ENGELMAN, R. H.	7906180349	50-397	0	ENGELMAN, R. H.	7906180505	50-397	0
ENGELMAN, R. H.	7906180348	50-397	0	ENGELMAN, R. H.	7906180506	50-397	0</

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DISTRICT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DISTRICT CATEGORY	REPORT NUMBER
HECHT, E. J. H.	7706210197	50-300 U		HEND, J. A.	7706220319	50-300 B	
HECHT, E. J. H.	7706110367	50-300 U		HEND, J. A.	7706220310	50-300 B	
HECHT, E. J. H.	7706110376	50-300 U		HEND, J. A.	7706210379	50-294 B	
HECHT, E. J. H.	7706110380	50-300 U		HEND, J. A.	7706140391	50-300 B	
HECHT, E. J. H.	7706110382	50-300 U		HEND, J. A.	7706140393	50-304 B	
HECHT, E. J. H.	7706110386	50-290 U		HEND, J. A.	7706140390	50-264 B	
HECHT, E. J. H.	7706110387	50-300 U		HEND, J. A.	7706140394	50-264 B	
HECHT, E. J. H.	7706110390	50-290 U		HEND, J. A.	7706090325	50-266 B	
HECHT, E. J. H.	7706110394	50-290 U		HEND, J. A.	7706090323	50-182 B	
HECHT, E. J. H.	7706110397	50-290 U		HEND, J. A.	7706110304	50-354 B	
HECHT, E. J. H.	7706110400	50-290 U		HEND, J. A.	7706160303	50-195 B	
HECHT, E. J. H.	7706220627	COMB180104		HEND, J. A.	7706160309	50-234 B	
HECHT, E. J. H.	7706220626	COMB180104		HEND, J. A.	7706060305	50-168 B	
HECHT, E. J. H.	7706270163	COMB180104		HEND, J. A.	7706260312	50-253 B	
HECHT, E. J. H.	7706270164	COMB180104		HEND, J. A.	7706260311	50-439 B	
HECHT, E. J. H.	7706270165	COMB180104		HEND, J. A.	7706260309	50-467 B	
HECHT, E. J. H.	7706270167	COMB180104		HEND, J. A.	7706260307	50-168 B	
HECHT, E. J. H.	7706270168	COMB180104		HEND, J. A.	7706260303	50-167 B	
HECHT, E. J. H.	7706270169	COMB180104		HENDERSON, J. C.	7706090362	50-166 B	
HECHT, E. J. H.	7706270170	COMB180104		HENDERSON, J. C.	7706090363	50-166 B	
HECHT, E. J. H.	7706270171	COMB180104		HENDERSON, J. C.	7706090360	50-166 B	
HECHT, E. J. H.	7706270172	COMB180104		HENDERSON, J. C.	7706090367	50-166 B	
HECHT, E. J. H.	7706270173	COMB180104		HENDERSON, J. C.	7706090368	50-166 B	
HECHT, E. J. H.	7706270174	COMB180104		HENDERSON, J. C.	7706090369	50-166 B	
HECHT, E. J. H.	7706270175	COMB180104		HENDERSON, J. C.	7706090370	50-166 B	
HECHT, E. J. H.	7706270176	COMB180104		HENDERSON, J. C.	7706090371	50-166 B	
HECHT, E. J. H.	7706270177	COMB180104		HENDERSON, J. C.	7706090372	50-166 B	
HECHT, E. J. H.	7706270178	COMB180104		HENDERSON, J. C.	7706090373	50-166 B	
HECHT, E. J. H.	7706270179	COMB180104		HENDERSON, J. C.	7706090374	50-166 B	
HECHT, E. J. H.	7706270180	COMB180104		HENDERSON, J. C.	7706090375	50-166 B	
HECHT, E. J. H.	7706270181	COMB180104		HENDERSON, J. C.	7706090376	50-166 B	
HECHT, E. J. H.	7706270182	COMB180104		HENDERSON, J. C.	7706090377	50-166 B	
HECHT, E. J. H.	7706270183	COMB180104		HENDERSON, J. C.	7706090378	50-166 B	
HECHT, E. J. H.	7706270184	COMB180104		HENDERSON, J. C.	7706090379	50-166 B	
HECHT, E. J. H.	7706270185	COMB180104		HENDERSON, J. C.	7706090380	50-166 B	
HECHT, E. J. H.	7706270186	COMB180104		HENDERSON, J. C.	7706090381	50-166 B	
HECHT, E. J. H.	7706270187	COMB180104		HENDERSON, J. C.	7706090382	50-166 B	
HECHT, E. J. H.	7706270188	COMB180104		HENDERSON, J. C.	7706090383	50-166 B	
HECHT, E. J. H.	7706270189	COMB180104		HENDERSON, J. C.	7706090384	50-166 B	
HECHT, E. J. H.	7706270190	COMB180104		HENDERSON, J. C.	7706090385	50-166 B	
HECHT, E. J. H.	7706270191	COMB180104		HENDERSON, J. C.	7706090386	50-166 B	
HECHT, E. J. H.	7706270192	COMB180104		HENDERSON, J. C.	7706090387	50-166 B	
HECHT, E. J. H.	7706270193	COMB180104		HENDERSON, J. C.	7706090388	50-166 B	

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
KEPPLER, J. S.	7906200126	30-315 S		KOPPEL, J. E.	7906200141	30-424 S	
KEPPLER, J. S.	7906200128	30-317 S		KOPPEL, E. J.	7906200276	30-24 P	
KEPPLER, J. S.	7906200131	30-318 S		KOPPEL, M. R.	7906200340	30-129 P	
KEPPLER, J. S.	7906200132	30-484 S		KOPPEL, R. R.	7906200381	30-127 P	
KEPPLER, J. S.	7906200134	30-484 G		KORCHIN, V. H.	7906200432	30-449 Y	
KEPPLER, J. S.	7906200137	30-246 S		KORNEHL, T. L.	7906200501	30-448 T	
KEPPLER, J. S.	7906200139	30-483 S		KORNEHL, L. S.	7906200501	30-280 S	
KEPPLER, J. S.	7906200142	30-246 S		KORNEHL, L. S.	7906200502	30-250 S	
KEPPLER, J. S.	7906200145	30-325 S		KOSKIN, L. S.	7906200570	30-358 G	
KEPPLER, J. S.	7906200201	30-325 S		KOTMAN, J. J.	7906200504	30-320 P	
KESER, L. W.	7906200242	ACR		KOTMAN, J. J.	7906200499	30-320 P	
KESER, L. W.	7906200671	30-329 P		KOTMAN, J. J.	7906200542	30-320 P	
KESER, M.	7906200648	30-329 P		KOVACH, B. L.	7906200143	30-320 P	NUCEN 610A34701
KERN, H. O.	7906200403	30-320 P		KOVACH, J. L.	7906200457	30-320 P	
KERN, H. O.	7906200521	30-320 P		KOVACH, J. L.	7906200524	30-320 P	
KERN, H. O.	7906200543	30-320 P		KOVACH, B. E.	7906200438	30-320 C	
KERN, H. O.	7906200544	30-320 P		KOVACH, J. L.	7906200504	30-320 C	
KERN, H. O.	7906200545	30-320 P		KOVACH, J. L.	7906200505	30-320 C	
KETCHEM, H. S.	7906200599	70-4823 C		KRAFT, B.	7906200128	30-320 P	
KETCHEM, H. S.	7906201021	70-4823 C		KRAH, D. S.	7906200522	30-320 U	
KETCHEM, H. S.	7906201021	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201024	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201027	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201027	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201028	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201029	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201030	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201031	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201032	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201033	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201034	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201035	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201036	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201037	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201038	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201039	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201040	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201041	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201042	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201043	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201044	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201045	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201046	70-4823 C		KRAMER, J. J.	7906200425	71-110 C	
KETCHEM, H. S.	7906201047	70-4823 C		KRAMER, J. J.	79062		

PERSONAL AUTHOR INDEX

315

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
LEITHE, H. G.	7904290100	50-409 G		HACDONALD, C. E.	7904290429	71-1010 C	
LEU, L.	7904290202	50-301 G		HACDONALD, C. E.	7904180353	71-4949 C	
LEU, L.	7904290204	50-331 G		HACDONALD, C. E.	7904210112	71-5389 C	
				HACDONALD, C. E.	7904290900	71-3 C	
LIU, L.	7904010204	50-331 F					
LIU, L.	7904180470	50-331 F		HACDONALD, C. E.	7904180469	71-6874 G	
LIU, L.	7904180144	50-331 F		HACDONALD, C. E.	7904180476	71-6044 C	
LIVERMORE, H. H.	7904290381	50-409 G		HACDONALD, C. E.	7904180503	71-5504 C	
LIVERMORE, H. H.	7904290424	50-409 G		HACDONALD, C. E.	7904180502	71-8304 G	
				HACDONALD, C. E.	7904180509	71-6717 G	
LODGE, R. B.	7904290306	50-344 J					
LODGE, R. B.	7904290309	50-350 F		HACDONALD, C. E.	7904180343	71-4379 F	
LODGE, R. L.	7904180468	50-302 G		HACDONALD, C. E.	7904200103	71-4493 C	
LODGE, F. J.	7904180230	50-353 G		HACDONALD, C. E.	7904200133	71-5900 C	
LOPATA, J. R.	7904140474	50-374 G		HACDONALD, C. E.	7904200201	71-258 C	
				HACDONALD, C. E.	7904180482	71-105 C	
LOPEZ, J.	7904180772	50-444 G					
LOPEZ, A.	7904101005	HAUTE HOT		HACDONALD, C. E.	7904180793	71-378 C	
LOREN, F. J.	7904140127	EMTE	7904140127	HACDONALD, C. E.	7904200072	71-8908 C	
LOW, R. J.	7904290382	50-444 G		HACDONALD, C. E.	7904200074	71-8908 C	
LOW, R. H.	7904270414	FR		HACDONALD, C. E.	7904200100	71-6429 C	
				HACDONALD, C. E.	7904200104	71-6501 C	
LOYALKA, R. J.	7904290384	HAUTE	HAUTE/CR-6780				
LYNN, M. J. D.	7904210100	50-320 F		HACDONALD, C. E.	7904200108	71-240 C	
LYNN, T. L.	7904200001	50-382 G		HACDONALD, C. E.	7904200112	71-3481 C	
LYNN, T. L.	7904200020	50-382 G		HACDONALD, C. E.	7904200129	71-7080 C	
LYNN, T. L.	7904180314	HAUTE	HAUTE-24412	HACDONALD, C. E.	7904200141	71-6378 C	
LYNN, T. L.	7904180314	HAUTE		HACDONALD, C. E.	7904200004	71-1337 C	
LYNN, T. L.	7904200149	50-317 G					
LYNN, T. L.	7904180083	50-317 G		HACDONALD, C. E.	7904200069	71-4378 C	
LYNN, T. L.	7904200026	FR		HACDONALD, C. E.	7904200124	71-7080 C	
LYNN, T. L.	7904140148	50-317 G		HACDONALD, C. E.	7904200129	71-108 C	
LYNN, T. L.	7904180343	50-317 F		HACDONALD, C. E.	7904200041	71-0010 C	
LYNN, T. L.	7904180343	50-317 F		HACDONALD, C. E.	7904200003	71-0010 C	
LYNN, T. L.	7904200408	50-317 F		HACDONALD, C. E.	7904200723	71-7070 G	
LYNN, T. L.	7904180045	50-317 F		HACDONALD, C. E.	7904200049	71-4381 C	
LYNN, T. L.	7904180044	50-317 G		HACDONALD, C. E.	7904200040	71-4387 C	
LYNN, T. L.	7904180048	50-317 G		HACDONALD, C. E.	7904200040	71-1018 C	
LYNN, T. L.	7904200001	50-317 F		HACDONALD, C. E.	7904200087	71-1018 C	
LYNN, T. L.	7904200001	50-317 G					
LYNN, T. L.	7904200001	50-317 G		HACDONALD, C. E.	7904210090	71-234 C	
LYNN, T. L.	7904200138	50-317 F		HACDONALD, C. E.	7904210092	71-234 C	
LYNN, T. L.	7904200145	50-299 G		HACDONALD, C. E.	7904200224	71-8903 C	
LYNN, T. L.	7904200384	50-123 G		HACDONALD, C. E.	7904200234	71-8908 C	
LYNN, T. L.	7904200178	50-123 G		HACDONALD, C. E.	7904200234	50-257 G	
LYNN, T. L.	7904200178	50-123 G		HACDONALD, C. E.	7904200142	50-257 G	
LYNN, T. L.	7904200145	50-2					

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
HALONEY, P	7706140890	50-315	A	HARTMAN, R	7706060100	50-344	Q
HALONY, P	7706130732	50-320	P	HARTMAN, R	7706060339	50-348	Q
HALONY, P	7706191056	XP857L1C		HARTMAN, R	7706140137	50-348	Q
HALL, J. B.	7706170284	50-310	S	HARTMAN, R	7706060382	50-338	Q
HALL, J. R.	7706140928	PER		HARTMAN, R	7706060191	50-124	Q
HAMBY, H.	7706060221	50-321	S	HARTMAN, R	7706180018	50-324	Q
HAMBY, H.	7706150294	50-346	S	HARTMAN, R	7706060121	50-329	Q
HAMBY, H.	7706057037	50-328	S	HARTMAN, R	7706060496	50-250	Q
HAMBY, H.	7706040204	50-323	P	HARTMAN, R	7706060216	50-384	Q
HAMBY, H.	7706050224	50-316	S	HARTMAN, J.	7706170441	50-320	P
HAMBY, H.	7706040299	50-328	A	HARTMAN, J.	7706050316	50-320	P
HAMBY, H.	7706050230	50-346	S	HARTMAN, J.	7706120396	50-320	P
HAMBY, H.	7706140258	50-323	A	HARTMAN, E.	7706050249	50-329	H
HAMBY, H.	7706140418	50-344	S	HARTMAN, E.	7706060391	50-247	Q
HAMBY, H.	7706060210	50-323	A	HARTMAN, E.	7706050385	71-9126	C
HAMM, H.	7706140255	50-364	S	HASSEL, R. C.	7706020183	PER	7706020103
HAMM, H.	7706140467	50-364	S	HASSEL, R.	7706030115	NAMES	NAMES/PER-0793
HAMM, H.	7706040623	50-364	S	HASSEL, R.	7706050842	50-348	Q
HAMM, H.	7706060243	50-364	S	HASTINGS, P.	7706070818	50-348	Q
HAMM, H.	7706140241	50-364	S	HASTINGS, P.	7706120276	50-372	Q
HAMM, H.	7706140901	50-364	S	HATKIN, S. B.	7706190328	50-241	A
HAMM, H.	7706140517	50-364	S	HATKIN, E. R.	7706180494	50-350	S
HAMM, H.	7706140542	50-364	S	HATKIN, E. R.	7706070116	50-353	Q
HAMM, H.	7706140504	50-364	S	HATKIN, W. R.	7706020487	50-350	S
HAMM, H.	7706140419	50-364	S	HATKIN, W. R.	7706060285	50-350	S
HAMM, H.	7706140255	50-364	S	HATKIN, E. R.	7706090314	50-350	Q
HAMM, H.	7706140467	50-364	S	HATKIN, E. R.	7706050881	50-350	J
HAMM, H.	7706120944	50-364	H	HATKIN, E. R.	7706180820	50-350	J
HAMM, H.	7706120426	50-364	E	HATKIN, E. R.	7706190461	50-350	J
HAMM, H.	7706130623	50-321	R	HATKIN, E. R.	7706080575	50-350	B
HAMMY, R.	7706190304	50-321	R	HATHBARRIER, R. L.	7706080596	50-482	Q
HAMMY, R.	7706190261	50-321	R	HATHBARRIER, R. L.	7706080517	50-482	Q
HAMMY, R.	7706190434	50-364	S	HATHBARRIER, R. L.	7706180285	50-273	B
HAMMY, R.	7706190431	50-321	R	HATHBARRIER, R. L.	7706060189	AC88	
HAMMY, R.	7706190485	50-364	S	HATHBARRIER, R. L.	7706070547	AC88	
HAMMY, R.	7706190389	50-364	S	HATHBARRIER, R. L.	7706070640	50-394	T
HAMMY, R.	7706190494	50-364	S	HATHBARRIER, R. L.	7706070704	50-394	T
HAMMY, R.	7706190509	50-364	S	HATHBARRIER, R. L.	7706060282	50-394	T
HAMMY, R.	7706180467	50-364	S	HATHBARRIER, R. L.	7706060103	KEY	
HAMMY, R.	7706180169	50-321	R	HATHBARRIER, R. L.	7706040443	XP857L1C	
HAMMY, R.	7706200139	50-321	R	HATHBARRIER, R. L.	7706140573	XP857L1C	
HAMMY, R.	7706200297	50-321	R	HATHBARRIER, R. L.	7706060101	XP857L1C	
HAMMY, R. C.	7706200175	70-143	C	HATHBARRIER, R. L.	7706140402	XP857L1C	
HAMMY, R. C.	7706140614	RE509		HATHBARRIER, R. L.	7706080592	50-312	Q
HAMMY, R. C.	7706200616	PER		HATHBARRIER, R. L.	7706060590	50-312	Q
HAMMILL, J. A.	7706120287	50-568	A	YAC0-1175			

PERSONAL AUTHOR INDEX

317

[illegible]

PERSONAL AUTHOR INDEX

321

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
OFLINER, D. G.	7904160015	XFORTLJC		SHARLEY, D. F.	7904270077	TOPEEP	
OFLINER, D. G.	7904160025	XFORTLJC		SHARLEY, D. F.	7904120230	TOPEEP	
OFLINER, D. G.	7904160035	XFORTLJC		SHARLEY, D. F.	7904230127	71-146	C
OFLINER, D. G.	7904200015	XFORTLJC		SHARLEY, D. F.	7904230193	71-290	C
OFLINER, D. G.	7904040030	XFORTLJC		SHARLEY, D. F.	7904190357	71-290	C
OFLINER, D. G.	7904160029	XFORTLJC		PALLADINO, M. J.	7904130688	51-320	G
OFLINER, D. G.	7904160030	XFORTLJC		PALLADINO, M. J.	7904250499	51-311	G
OFLINER, D. G.	7904160031	XFORTLJC		PALLADINO, M. J.	7904120603	010	
OFLINER, D. G.	7904160032	XFORTLJC		PALLADINO, M. J.	7904250111	51-320	G
OFLINER, D. G.	7904160033	XFORTLJC		PALLADINO, M. J.	7904250119	51-320	G
OFLINER, D. G.	7904160034	XFORTLJC		PALLADINO, M. J.	7904250120	010	
OFLINER, D. G.	7904160035	XFORTLJC		PALLADINO, M. J.	7904250121	010	
OFLINER, D. G.	7904160036	XFORTLJC		PALLADINO, M. J.	7904250122	010	
OFLINER, D. G.	7904160037	XFORTLJC		PALLADINO, M. J.	7904250123	010	
OFLINER, D. G.	7904160038	XFORTLJC		PALLADINO, M. J.	7904250124	010	
OFLINER, D. G.	7904160039	XFORTLJC		PALLADINO, M. J.	7904250125	010	
OFLINER, D. G.	7904160040	XFORTLJC		PALLADINO, M. J.	7904250126	010	
OFLINER, D. G.	7904160041	XFORTLJC		PALLADINO, M. J.	7904250127	010	
OFLINER, D. G.	7904160042	XFORTLJC		PALLADINO, M. J.	7904250128	010	
OFLINER, D. G.	7904160043	XFORTLJC		PALLADINO, M. J.	7904250129	010	
OFLINER, D. G.	7904160044	XFORTLJC		PALLADINO, M. J.	7904250130	010	
OFLINER, D. G.	7904160045	XFORTLJC		PALLADINO, M. J.	7904250131	010	
OFLINER, D. G.	7904160046	XFORTLJC		PALLADINO, M. J.	7904250132	010	
OFLINER, D. G.	7904160047	XFORTLJC		PALLADINO, M. J.	7904250133	010	
OFLINER, D. G.	7904160048	XFORTLJC		PALLADINO, M. J.	7904250134	010	
OFLINER, D. G.	7904160049	XFORTLJC		PALLADINO, M. J.	7904250135	010	
OFLINER, D. G.	7904160050	XFORTLJC		PALLADINO, M. J.	7904250136	010	
OFLINER, D. G.	7904160051	XFORTLJC		PALLADINO, M. J.	7904250137	010	
OFLINER, D. G.	7904160052	XFORTLJC		PALLADINO, M. J.	7904250138	010	
OFLINER, D. G.	7904160053	XFORTLJC		PALLADINO, M. J.	7904250139	010	
OFLINER, D. G.	7904160054	XFORTLJC		PALLADINO, M. J.	7904250140	010	
OFLINER, D. G.	7904160055	XFORTLJC		PALLADINO, M. J.	7904250141	010	
OFLINER, D. G.	7904160056	XFORTLJC		PALLADINO, M. J.	7904250142	010	
OFLINER, D. G.	7904160057	XFORTLJC		PALLADINO, M. J.	7904250143	010	
OFLINER, D. G.	7904160058	XFORTLJC		PALLADINO, M. J.	7904250144	010	
OFLINER, D. G.	7904160059	XFORTLJC		PALLADINO, M. J.	7904250145	010	
OFLINER, D. G.	7904160060	XFORTLJC		PALLADINO, M. J.	7904250146	010	
OFLINER, D. G.	7904160061	XFORTLJC		PALLADINO, M. J.	7904250147	010	
OFLINER, D. G.	7904160062	XFORTLJC		PALLADINO, M. J.	7904250148	010	
OFLINER, D. G.	7904160063	XFORTLJC		PALLADINO, M. J.	7904250149	010	
OFLINER, D. G.	7904160064	XFORTLJC		PALLADINO, M. J.	7904250150	010	
OFLINER, D. G.	7904160065	XFORTLJC		PALLADINO, M. J.	7904250151	010	
OFLINER, D. G.	7904160066	XFORTLJC		PALLADINO, M. J.	7904250152	010	
OFLINER, D. G.	7904160067	XFORTLJC		PALLADINO, M. J.	7904250153	010	
OFLINER, D. G.	7904160068	XFORTLJC		PALLADINO, M. J.	7904250154	010	
OFLINER, D. G.	7904160069	XFORTLJC		PALLADINO, M. J.	7904250155	010	
OFLINER, D. G.	7904160070	XFORTLJC		PALLADINO, M. J.	7904250156	01	

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	PROJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	PROJECT CATEGORY	REPORT NUMBER
REF, L. H.	7795210125	93-020 F		ROSEMAN, A. Z.	7795250067	78-2423 E	
				ROSEMAN, A. Z.	7795210337	86-237 D	
REICHERT, J.	7795210291	PH		ROSEMAN, A. Z.	7795202057	58-227 D	
REICHENBERG, W. J.	7795210127	93-280 H		ROLL, IRL, J. D.	7795202415	71-2446 C	
REICHENBERG, W. D.	7795210424	PH		ROSEMAN, A. Z.	7795202066	78-1210 C	
REICHENBERG, J. L.	7795210165	GRS		ROSEMAN, A. Z.	7795210326	85-217 E	
	7795210196	4499V		ROSEMAN, A. Z.	7795202056	58-261 F	
REIDEN, R. B.	7795209526	93-284 O		ROSEMAN, A. Z.	7795202064	58-261 A	
REIDEN, W. B.	7795209527	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209573	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209541	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209579	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209581	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209582	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209583	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209584	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209585	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209586	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209587	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209588	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209589	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209590	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209591	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209592	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209593	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209594	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209595	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209596	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209597	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209598	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209599	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209600	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209601	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209602	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209603	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209604	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209605	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209606	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209607	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209608	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209609	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209610	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209611	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	
REIDEN, W. B.	7795209612	93-284 O		ROSEMAN, A. Z.	7795202066	58-261 A	

[illegible]

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	RECORD NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	RECORD NUMBER
TOLLSON, A. C.	7704070282	50-324	8	TURNAGE, K. D.	7706268996	40-620	40-620/CH-
TOLLSON, A. C.	7704070281	50-324	9	TURNAGE, K. D.	7706269439	40-620	40-620/CH-
TOLLSON, A. C.	7704060250	50-324	8	TURNER, J. S.	7706270221	18-170	
TOLLSON, A. C.	7704120424	50-324	8				
TOLLSON, A. C.	7706110188	50-325	8	TURNER, J. S.	7706280421	14-154	
TOLLSON, A. C.	7706110170	50-325	8	TURNER, E. A.	7706130147	30-448	30-448
TOLLSON, A. C.	7706115529	50-324	8	TURNER, E. A.	7706130141	30-448	30-448
TOLLSON, A. C.	7706120288	50-324	8	TURNER, E. A.	7706130290	30-448	30-448
TOLLSON, A. C.	7706150174	50-325	8	TURNER, E. A.	7706130435	30-448	30-448
TOLLSON, A. C.	7706150183	50-324	8	TURNER, E. A.	7706130507	30-448	30-448
TOLLSON, A. C.	7706150201	50-328	8	TURNER, E. A.	7706130517	30-448	30-448
TOLLSON, A. C.	7706150241	50-328	8	TURNER, E. A.	7706130537	30-331	30-331
TOLLSON, A. C.	7706150250	50-328	8	TURNER, E. A.	7706130547	30-331	30-331
TOLLSON, A. C.	7706150259	50-328	8	TURNER, E. A.	7706130554	30-331	30-331
TOLLSON, A. C.	7706150264	50-328	8	TURNER, E. A.	7706130564	30-331	30-331
TOLLSON, A. C.	7706150279	50-328	8	TURNER, E. A.	7706130574	30-331	30-331
TOLLSON, A. C.	7706150289	50-328	8	TURNER, E. A.	7706130584	30-331	30-331
TOLLSON, A. C.	7706150299	50-328	8	TURNER, E. A.	7706130594	30-331	30-331
TOLLSON, A. C.	7706150309	50-328	8	TURNER, E. A.	7706130604	30-331	30-331
TOLLSON, A. C.	7706150319	50-328	8	TURNER, E. A.	7706130614	30-331	30-331
TOLLSON, A. C.	7706150329	50-328	8	TURNER, E. A.	7706130624	30-331	30-331
TOLLSON, A. C.	7706150339	50-328	8	TURNER, E. A.	7706130634	30-331	30-331
TOLLSON, A. C.	7706150349	50-328	8	TURNER, E. A.	7706130644	30-331	30-331
TOLLSON, A. C.	7706150359	50-328	8	TURNER, E. A.	7706130654	30-331	30-331
TOLLSON, A. C.	7706150369	50-328	8	TURNER, E. A.	7706130664	30-331	30-331
TOLLSON, A. C.	7706150379	50-328	8	TURNER, E. A.	7706130674	30-331	30-331
TOLLSON, A. C.	7706150389	50-328	8	TURNER, E. A.	7706130684	30-331	30-331
TOLLSON, A. C.	7706150399	50-328	8	TURNER, E. A.	7706130694	30-331	30-331
TOLLSON, A. C.	7706150409	50-328	8	TURNER, E. A.	7706130704	30-331	30-331
TOLLSON, A. C.	7706150419	50-328	8	TURNER, E. A.	7706130714	30-331	30-331
TOLLSON, A. C.	7706150429	50-328	8	TURNER, E. A.	7706130724	30-331	30-331
TOLLSON, A. C.	7706150439	50-328	8	TURNER, E. A.	7706130734	30-331	30-331
TOLLSON, A. C.	7706150449	50-328	8	TURNER, E. A.	7706130744	30-331	30-331
TOLLSON, A. C.	7706150459	50-328	8	TURNER, E. A.	7706130754	30-331	30-331
TOLLSON, A. C.	7706150469	50-328	8	TURNER, E. A.	7706130764	30-331	30-331
TOLLSON, A. C.	7706150479	50-328	8	TURNER, E. A.	7706130774	30-331	30-331
TOLLSON, A. C.	7706150489	50-328	8	TURNER, E. A.	7706130784	30-331	30-331
TOLLSON, A. C.	7706150499	50-328	8	TURNER, E. A.	7706130794	30-331	30-331
TOLLSON, A. C.	7706150509	50-328	8	TURNER, E. A.	7706130804	30-331	30-331
TOLLSON, A. C.	7706150519	50-328	8	TURNER, E. A.	7706130814	30-331	30-331
TOLLSON, A. C.	7706150529	50-328	8	TURNER, E. A.	7706130824	30-331	30-331
TOLLSON, A. C.	7706150539	50-328	8	TURNER, E. A.	7706130834	3	

CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
CITIZEN GROUP/INDIVIDUAL/MEDIA		
Baker Anti-Nuclear Group	7904200091	50-092 G
Citizens Against Nuclear Dangers	7904190130	50-397 G
	7904170012	50-397 G
Citizens for Alternatives to Radioactive Dumping	7904101017	NAHTE NST
Citizens Association for Sound Energy	7904070338	50-445 G
CSE News, CSE, Inc.	7904200075	50-320 F
	7904200049	50-320 F
	7904200083	50-320 F
	7904201011	50-249 G
	7904201056	50-249 G
Caution Civic Association		
Concerned Citizens Against Proliferation of Uranium Waste	7904070281	40-6098 G
Concerned Citizens of Lake County, IL	7904190091	50-205 G
Citizens Concerned About Nuclear Power, Inc.	7904090403	50-498 G
	7904070249	50-498 G
	7904090401	50-498 G
Citizens for Energy & Employment	7904200035	50-498 G
Citizens for Fair Utility Regulation	7904200084	50-445 G
Citizens Energy Forum	7904200092	50-334 G
	7904200078	50-334 G
Citizens for Safe Environment	7904290036	50-320 G
Civilian Heat Energy Project	7904040039	50-445 G
Center for Law in the Public Interest	7904070387	50-275 G
	7904200350	FOIA
	7904010341	50-275 G
Center for Law & Social Policy	7904010319	FOIA
Civilian Heat Energy Project	7904201040	PHN
Ecology Action of Shreve	7904201011	50-296 G
Environmental Defense Fund	7904201043	50-292 G
	7904290813	50-292 G
Friends of the Earth	7904200270	50-392 G
	7904200242	50-312 G
Great Lakes Energy Alliance	7904200073	50-312 H
Iowa Public Interest Research Group	7904200405	50-283 G
	7904200512	50-397 G
Jo Daviess County Ad Hoc Committee on Nuclear Energy Information	7904200079	50-399 G
Lake Michigan Preservation	7904090043	50-227 F
League of Women Voters of Rockford, IL	7904200445	50-494 G
	7904080125	50-494 G
Lead Valley Power Project	7904050118	FOIA
Madison & Others Mobilizing for Survival	7904200047	50-275 G
Northern California Ecumenical Council	7904020053	50-275 G
New England Regional Energy Project	7904070262	FOIA
Natural Resources Defense Council	7904070330	50-262 G
	7904070341	50-262 G
	7904070343	50-262 G
	7904040055	50-262 G
	7904060049	50-262 G
	7904200194	50-262 G
	7904200062	50-262 G
	7904090087	50-262 G
	7904210097	50-262 G
	7904210097	50-262 G
Nuclear Vets	7904050049	NAHTE

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Onwego County Farm Bureau	7904270272	50-095 G
Public Citizen Litigation Group	7904140223	PH
	7904201000	PHN
	7904203150	NAHTE
Pennsylvania Illustrated, Inc.	7904101009	50-320 H
People for Energy Progress	7904230016	PH
Public Interest Research Group	7904140104	100FR
Petroleum Alliance	7904200084	50-320 G
Slaghtmen Concerned About Nuclear Plants	7904010016	50-522 G
Texas Public Interest Research Group	7904040383	50-446 G
	7904040390	50-446 G
	7904040394	50-446 G
Trends Publishing, Inc.	7904200209	FOIA
Union of Concerned Scientists	7904200170	50-249 G
	7904200168	50-249 G
	7904200144	50-249 G
The Wall Street Journal	7904070233	FOIA
Half-Century Nuclear Operations, Inc.	7904070214	50-482 A
Women's International League for Peace & Freedom	7904100189	50-682 A
ENGINEERING/CONSTRUCTION/CONSULTANTS/SERVICES		
American Airlines, Inc.	7904160084	PH
Acurex, Alcorn	7904150446	71-293 C
	7904150449	71-293 C
	7904150314	100FR
Alaska Industrial Bldg	7904040077	71-298 C
	7904040090	71-298 C
Applied Engineering Co.	7904100433	71-294 C
Arthur D. Little, Inc.	7904100430	71-294 C
Bachtel Power Corp. (subs. of Bachtel Corp.)	7904100437	71-294 C
	7904070369	REDO
	7904180242	REDO
	7904070213	REDO
	7904150104	REDO
	7904150107	71-293 C
	7904200343	71-293 C
Capital International Airways, Inc.	7904190476	71-47 C
Carson Nondestructive Testing	7904070148	71-297 C
	7904070137	71-297 C
C. F. Green & Co.	7904270013	100FR
Chavron Submarine, Inc., Chavron Resources Co. Div.	7904070221	100FR
Combining Planning Associates	7904200293	50-390 H
Coopers, Inc.	7904180422	100FR
CTL Engineers, Inc.	7904180889	71-291 C
	7904180884	71-291 C
	7904090040	REDO
Daedalus Associates Inc.	7904200284	71-120 C
Daniel International (subs. of Fluor Corp.)	7904090280	71-120 C
	7904180427	71-291 C
	7904180430	71-291 C
DJ Separation Services, Inc.	7904190028	NAHTE
Ethane Services, Inc. (subs. of Research Corp.)	7904200178	71-148 G
	7904200145	REDO

CORPORATE SOURCE INDEX

[illegible]

CORPORATE SOURCE INDEX

[illegible]

CORPORATE SOURCE INDEX

AUTHOR	ACCESSION	SUBJECT	AUTHOR	ACCESSION	SUBJECT
AFFILIATION	NUMBER	CATEGORY	AFFILIATION	NUMBER	CATEGORY
	7904135443	50-408 D		7904130000	50-302 B
	7904135443	50-249 D		7904130224	50-302 F
	7904140413	80-023		7904140255	50-302 B
	7904150040	50-249 D		7904140288	50-302 B
	7904200045	70-0423 C		7904200267	50-302 F
	7904140420	50-408 B		7904200286	50-302 B
	7904220134	50-413 D		7904220201	50-302 D
	7904140428	50-408 B		7904220204	50-302 B
	7904160042	71-4498 C		7904220414	50-302 B
	7904220411	FRH		7904220420	50-302 B
	7904200109	70-0423 C		7904220274	50-302 B
	7904130291	50-249 D		7904220303	50-302 F
	7904140422	50-370 A		7904220324	50-302 F
	7904210126	70-0423 C		7904220329	50-302 F
	7904080391	OWB		7904220343	50-250 B
	7904040421	50-249 D		7904130434	50-250 D
	7904220424	50-249 D		7904130438	50-302 B
	7904140323	50-249 B		7904220442	50-302 B
	7904180741	80-413 B		7904220444	50-250 F
	7904220037	70-0423 C		7904240913	50-302 A
	7904200008	70-0423 C		7904200049	50-250 F
	7904220170	50-249 D		7904200084	50-402 B
	7904190114	50-491 D		7904200481	50-302 D
	7904200045	50-249 D		7904200491	80-030
	7904200037	50-491 D		7904200429	FRH
	7904140334	50-491 B		7904200056	50-309 D
	7904140334	50-249 B		7904130025	50-302 B
	7904200344	50-249 B		7904200370	50-280 D
	7904140181	50-249 D		7904200362	50-280 F
	7904200329	50-280 F		7904200400	50-305 B
	7904200284	50-249 D		7904140384	50-301 B
	7904100444	50-370 B		7904200393	50-302 B
	7904210251	50-370 B		7904200400	50-302 B
	7904220204	50-249 D		7904200423	50-302 B
	7904140333	50-249 B		7904200428	50-309 B
	7904160039	50-280 F		7904200437	50-302 F
	7904200077	70-0423 C		7904130038	50-280 B
	7904200328	50-249 F		7904130344	50-280 B
	7904200329	50-249 F		7904130348	50-280 B
	7904200151	50-249 B		7904130348	50-280 B
	7904200151	50-249 B		7904130348	50-280 B
	7904200327	50-249 B		7904130348	50-280 B
	7904130325	50-249 D		7904200439	50-281 F
	7904130320	50-249 B		7904200439	50-281 F
	7904130324	50-249 B		7904200439	50-281 F
	7904130320	50-249 B		7904200439	50-281 F
	7904200324	50-249 B		7904200439	50-281 F
	7904150200	50-318 J		7904200439	50-302 F
	7904130251	50-249 J		7904200439	50-302 F
	7904130247	50-249 B		7904200439	50-302 F
	7904190241	50-249 F		7904200439	50-302 F
	7904210149	50-249 B		7904200439	50-302 F
	7904210153	50-249 B		7904200439	50-302 F
	7904210149	50-249 B		7904200439	50-302 F
	7904210153	50-249 B		7904200439	50-302 F
	7904210149	50-249 B		7904200439	50-302 F
	7904210153	50-249 B		7904200439	50-302 F
	7904220083	50-249 F		7904200439	50-302 F
	7904220029	50-270 B		7904200439	

EAST - Eastern Utilities Associates
FUEL - Pittsburgh Gas & Electric Light Co.

FPG = Florida Power Corp.

GAP = Georgia Power Co.

CORPORATE SOURCE INDEX

[illegible]

CORPORATE SOURCE INDEX

353

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7906100081	50-272 G		7906100021	50-261 G
	7906020193	50-272 G		7906140022	50-262 PE
	7906070389	50-272 G		7906020138	50-268 H
	7906070256	50-272 G		7906100290	50-261 A
	7906000270	50-272 P			
	7906090274	50-272 G		7906050194	50-256 G
				7906010018	50-204 G
	7906060270	50-272 P		7906040003	50-203 P
				7906060017	50-224 H
	7906050294	50-272 E		7906100238	50-261 A
	7906080283	50-272 G			
	7906040002	50-272 E		7906040017	50-203 A
	7906060061	50-264 G		7906100234	50-261 E
				7906100289	50-268 H
	7906050267	50-211 A		7906100291	50-204 E
	7906050289	50-272 E		7906020203	50-261 A
	7906050291	50-272 G			
	7906050291	50-272 G		7906040072	50-206 F
	7906050291	50-272 G		7906040018	50-206 P
	7906050294	50-272 G		7906100280	50-261 A
				7906050267	50-204 H
	7906050299	50-272 G		7906050314	50-264 D
	7906050340	50-272 G			
	7906070268	50-272 E		7906020202	50-266 B
	7906110226	50-272 E		7906020245	50-204 D
	7906110231	50-272 E		7906020302	50-256 E
				7906020404	50-266 E
	7906060417	50-272 E			
	7906100130	50-272 E		7906050321	50-261 K
	7906100133	50-272 E		7906020324	50-261 E
	7906020410	50-272 E		7906020321	50-261 K
	7906180505	50-272 E		7906020324	50-261 K
				7906020328	50-264 E
	7906100093	50-272 E			
	7906140201	50-272 P		7906100346	50-206 E
	7906140218	50-272 E		7906070239	50-261 E
	7906020361	50-272 P		7906070246	50-261 E
	7906060294	50-272 G		7906070245	50-261 E
				7906070411	50-261 E
	7906050407	50-272 E		7906090341	50-261 E
	7906020414	50-272 E			
	7906020294	50-272 G		7906070239	50-261 E
	7906060294	50-272 E		7906070244	50-261 E
	7906060368	50-272 J		7906070404	50-261 E
				7906070411	50-261 E
	7906030119	50-266 G		7906090338	50-261 K
	7906020027	50-266 K		7906020265	50-265 E
	7906080030	50-266 K		7906040273	50-265 E
	7906080027	50-266 K		7906100132	50-265 E
	7906080030	50-266 K		7906020071	50-269 D
				7906020066	50-265 E
	7906080025	50-266 K		7906070050	50-269 D
	7906100248	50-266 E		7906080070	50-292 J
	7906020081	50-269 J		7906060246	50-287 K
				7906050228	50-298 E
	7906090147	50-263 E		7906020030	50-265 D
	7906050282	50-443 I		7906020093	50-312 G
	7906020136	50-443 G			
	7906020782	50-443 G		7906020095	50-312 G
	7906020657	50-443 G		7906070132	50-320 D
	7906060293	50-443 I		7906100320	50-312 P
	7906020216	50-443 I		7906100318	50-312 P
	7906100299	50-443 I		7906100325	5

CORPORATE SOURCE INDEX

AUTHOR
AFFILIATIONACCESSION
NUMBERSUBJECT
CATEGORYAUTHOR
AFFILIATIONACCESSION
NUMBERSUBJECT
CATEGORY

7906020240 50-344 G
7906140249 50-344 G
7906140252 50-344 G
7906140251 50-344 G
7906201440 50-344 G

7906201110 50-293 G
7906201119 50-344 G
7906201203 50-344 G
7906203037 50-344 G
7906207030 50-344 F

7906206280 50-344 F
7906206287 50-344 G
7906206289 50-344 F
7906206285 50-344 F
7906206242 50-344 G

7906206043 50-344 F
7906206272 50-344 F
7906207008 50-344 G
7906207002 50-344 G
7906207009 50-344 G

7906206033 50-344 F
7906140294 50-344 F
7906140409 50-344 F
7906180244 50-344 G
7906180247 50-344 G

7906180249 50-344 F
7906180251 50-344 F
7906203033 50-344 G
7906203039 50-344 G
7906203036 50-344 F

7906203046 50-344 F
7906203077 50-344 G
7906203403 50-344 F
7906203411 50-344 F
7906203042 50-344 F

7906203046 50-344 F
7906203037 50-344 G
7906203036 50-344 G
7906203175 50-344 G
7906203123 50-344 G

7906203025 50-344 F
7906190239 50-443 F
7906203037 50-443 G
7906203041 50-443 A
7906203042 50-443 G

7906120239 50-443 K
7906120239 50-443 K
7906120235 50-443 K
7906120239 50-443 K
7906120206 50-443 G

7906203020 50-443 A
7906203024 50-443 G
7906130003 50-443 A
7906130029 50-443 K
7906203044 50-443 F

7906203022 70-0443 G
7906203023 50-327 G
7906203029 50-393 G
7906203028 50-393 G
7906130003 50-393 G

7906203022 70-0443 G
7906203023 50-327 G
7906203029 50-393 G
7906203028 50-393 G
7906130003 50-393 G

7906203022 70-0443 G
7906203023 50-327 G
7906203029 50-393 G
7906203028 50-393 G
7906130003 50-393 G

7906203022 70-0443 G
7906203023 50-327 G
7906203029 50-393 G
7906203028 50-393 G
7906130003 50-393 G

7906203022 70-0443 G
7906203023 50-327 G
7906203029 50-393 G
7906203028 50-393 G
7906130003 50-393 G

7906203022 70-0443 G
7906203023 50-327 G
7906203029 50-393 G
7906203028 50-393 G
7906130003 50-393 G

7906203022 70-0443 G
7906203023 50-327 G
7906203029 50-393 G
7906203028 50-393 G
7906130003 50-393 G

7906140387 50-290 G
7906140386 50-290 G
7906140387 50-290 G
7906203046 50-344 G
7906140411 50-318 G

7906060277 50-293 G
7906040204 50-297 A
7906203015 50-293 G
7906040304 50-297 A
7906140414 50-293 G

7906140410 50-293 G
7906040304 50-297 A
7906140410 50-293 G
7906140410 50-293 G
7906010209 50-293 G

7906010210 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G

7906040410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906040410 50-293 G
7906140410 50-293 G

7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G

7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G

7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G

7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G

7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G

7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G

7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G

7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G

7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G

7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G

7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G

7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G

7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G
7906140410 50-293 G

TU = Texas Utilities Co.
TUSC = Texas Utilities Separating Co

TUS = Texas Utilities Services, Inc
TVA = Tennessee Valley Authority

CORPORATE SOURCE INDEX

[illegible]

CORPORATE SOURCE INDEX

357

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Brookhaven National Laboratory	7706260023	50-277 P	Oak Ridge National Laboratory	7706260003	71-029 C
	7706270089	50-277 P		7706260441	REB
	7706280023	50-277 P		7706160230	REB
	7706270085	50-277 P			
	7706260092	50-409 P		7706058680	REB
	7706210018	REB		7706220015	REB
	7706240113	REB		7706180218	REB
	7706230149	REB		7706190349	REB
	7706230173	REB		7706050134	REB
	7706291049	REB		7706260077	REB
	7706260048	REB		7706230178	REB
	7706210191	73-REB		7706220150	71-401B C
	7706260037	REB		7706210018	REB
	7706260013	REB		7706260996	REB
	7706262017	REB		7706240188	REB
	7706270088	50-267 P		7706270087	REB
	7706280136	50-263 P		7706270014	REB
Environmental Policy Institute	7706140695	REB		7706240051	REB
Franklin Institute	7706140610	REB		7706270010	REB
Harvard Engineering Development Laboratory	7706260020	50-230 P		7706270012	REB
	7706160742	REB		7706280182	REB
	7706010042	REB	Wendell Laboratories	7706210044	REB
	7706150087	REB		7706210021	REB
	7706150011	REB		7706210022	REB
	7706290042	REB		7706210023	REB
	7706280113	REB		7706180089	REB
	7706280066	REB		7706260074	REB
	7706280110	REB		7706280111	REB
	7706280114	REB		7706290092	REB
	7706280001	REB		7706100774	REB
	7706290005	REB		7706260005	REB
	7706010070	REB		7706260010	50-220 P
Finite Research, Inc.					
Kent's Atomic Power Laboratory	7706280191	50-220 P		7706210037	REB
Los Alamos Scientific Laboratory	7706280107	REB		7706260008	REB
Lawrence Livermore Laboratory	7706250087	50-201 P	Reventon River Ecology Laboratory	7706180749	REB
	7706260020	REB		7706180762	REB
	7706260014	REB		7706180773	REB
Naval Sup. of Naval Research Laboratory	7706140127	REB	RII International	7706200141	REB
	7706260470	REB	Southwest Research and Information Center	7706180079	REB

U.S. NUCLEAR REGULATORY COMMISSION
ORGANIZATIONAL SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
CHADWICK	7956040403	REC'D
	7956032041	CONFERENCE
	7956030102	FOIA
	7956030120	FOIA
	7956030129	NO-324 F
	7956030132	FOIA
	7956030445	CONFERENCE
	7956030122	FOIA
	7956040058	CONFERENCE
	7956040127	NO-324 F
	7956040134	FOIA
	7956040143	FOIA
	7956070384	CONFERENCE
	7956040173	NO-320 F
	7956040486	NO-320 F
	7956040522	NO-344 F
	7956040488	NO-320 F
	7956260323	NO-344 F
	7956070088	CONFERENCE
	7956070094	CONFERENCE
	7956060176	NO-209 F
	7956070093	CONFERENCE
	7956040248	NO-323 F
	7956060173	NO-209 F
	7956070044	CONFERENCE
	7956070096	CONFERENCE
	7956070097	CONFERENCE
	7956130423	NO-320 F
	7956070102	CONFERENCE
	7956060232	NO-309 F
	7956130201	NO-320 F
	7956060137	NO-320 F
	7956060143	NO-320 F
	7956060167	NO-320 F
	7956070104	CONFERENCE
	7956070547	CONFERENCE
	7956070273	NO-329 F
	7956060332	CONFERENCE
	7956060474	NO-320 F
	7956010609	NUMBER
	7956020143	NUMBER
	7956180234	10CFR
	7956190444	10CFR
	7956020176	10CFR
	7956070219	NUMBER
	7956040017	10CFR
	7956020129	NO-280 F
	7956030431	FOIA 11
	7956070018	10CFR
	7956070294	CONFERENCE
	7956180349	10CFR
	7956140137	10CFR
	7956140111	10CFR
	7956130277	PH
	7956020005	10CFR
	7956070249	CONFERENCE
	7956020228	10CFR
	7956070107	CONFERENCE
	7956180291	10CFR
	7956180708	10CFR
	7956180724	10CFR
	7956070076	CONFERENCE

[illegible]

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7906100282	50-280 U		7906200286	10CFR
	7906100283	50-280 U		7906200289	10CFR
	7906100287	50-280 U		7906200294	10CFR
	7906100290	50-280 U		7906200297	10CFR
	7906100294	50-280 U		7906200298	10CFR
	7906100377	50-280 U		7906200299	10CFR
	7906100400	50-280 U		7906200300	10CFR
	7906200257	COMB REGS		7906200303	10CFR
	7906200264	COMB REGS		7906200308	10CFR
	7906200343	50-280 S		7906200307	10CFR
	7906200487	50-280 P		7906200199	50-320 S
	7906200483	COMB REGS		7906200255	50-400 S
	7906200244	COMB REGS		7906200444	50-44A S
	7906200251	COMB REGS		7906200203	10CFR
	7906200147	50-471 T		7906200216	10CFR
	7906270107	COMB REGS		7906200299	10CFR
	7906270116	COMB REGS		7906200207	50-320 P
	7906270123	COMB REGS		7906200225	50-400 P
	7906270129	COMB REGS		7906200241	FR
	7906270133	COMB REGS		7906200213	10CFR
	7906270150	COMB REGS		7906200276	10CFR
	7906270144	COMB REGS		7906200284	50-341 S
Office of Congressional Affairs	7906200194	50-320 U		7906200193	50-312 S
	7906200194	50-320 U		7906200019	50-320 U
	7906270003	50-320 U		7906270002	10CFR
	7906200199	FOIA		7906270099	10CFR
	7906200903	50-280 U		7906200292	50-341 P
	7906270000	50-375 H		7906200283	10CFR
	7906200242	50-280 U		7906200203	10CFR
	7906200418	50-320 U		7906200299	50-319 P
	7906200470	50-280 U		7906200296	50-320 S
	7906200198	50-320 U		7906200203	10CFR
Office of the General Counsel	7906200237	50-350 U		7906200274	10CFR
	7906200402	SECY		7906200208	10CFR
	7906200234	50-358 S		7906200246	10CFR
	7906200103	SECY		7906200241	10CFR
	7906270016	50-320 P		7906200246	10CFR
	7906270012	50-320 T		7906200270	50-328 P
	7906270027	50-320 T		7906200270	10CFR
	7906200104	FOIA		7906200254	50-300 S
	7906270057	50-320 P		7906200219	10CFR
	7906100116	SECY		7906200284	10CFR
	7906200251	50-320 P		7906200240	50-320 S
	7906100443	SECY		7906200284	50-302 S
	7906200299	50-320 P		7906270145	50-344 S
Office of Inspector and Auditor	7906270012	SH		7906270020	50-302 P
	7906200202	50-440 H		7906100200	50-313 S
	7906200277	50-410 H		7906200210	50-313 S
	7906200289	50-300 H		7906270145	50-320 P
	7906210014	50-300 T		7906270093	50-320 S
Office of Public Affairs	7906200264	50-410 H		7906270093	50-320 S
	7906200267	50-320 P		7906100184	50-389 P
	7906200269	50-320 P		7906200215	10CFR
	7906100281	50-320 P		7906210117	50-444 S
	7906200238	50-320 P		7906200210	50-313 P
	7906200276	50-320 P		7906200142	50-320 O
	7906200236	50-320 O		7906200189	10CFR
Office of Policy Evaluations	7906200238	10CFR		7906200184	10CFR
	7906100110	MMH		7906200226	10CFR
	7906200282	50-320 U		7906210235	50-320 O
Office of the Secretary of the Commission	7906210256	50-249 S		7906200149	10CFR
	7906210107	10CFR		7906200174	10CFR
	7906200452	10CFR		7906200172	10CFR
	7906200449	10CFR		7906200184	10CFR
	7906200427	10CFR		7906200184	10CFR
	7906200430	10CFR		7906200127	50-320 P
	7906200434	10CFR		7906200142	10CFR
	7906200176	50-280 P		7906200138	50-219 P
	7906200426	10CFR		7906200196	50-209 P
	7906200429	50-300 S		7906200147	50-234 P
	7906200422	10CFR		7906200184	27-39 C
	7906200416	10CFR		7906270141	27-39 C
	7906200420	10CFR		7906200277	50-394 O
	7906200413	50-300 P		7906270117	50-320 P
	7906200564	50-300 O		7906200117	FOIA
	7906200503	50-320 S		7906200218	50-320 A
	7906200415	50-300 S		7906200208	FOIA
	7906210077	50-320 P		7906130184	SECY
	7906210072	50-320 P		7906130187	SECY
	7906200410	10CFR		7906200234	50-320 A
	7906200403	2P3R7L1C		7906270071	FOIA
	7906200347	2P3R7L1C		7906270093	FOIA
	7906200376	10CFR		7906270123	FOIA
	7906100405	6W8		7906270130	FOIA

Declassification and Services Branch

Public Document Branch Atomic Energy Commission (Pre 1973)

U.S. NUCLEAR REGULATORY COMMISSION
ORGANIZATIONAL SOURCE INDEX

361

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7956070135	FOIA		7908100276	50-443 S
	7956070152	FOIA		7908100277	50-443 S
	7956070163	FOIA		7908100278	50-443 S
	7956070150	FOIA		7908100279	50-443 S
	7956060009	FOIA		7908100280	50-443 S
Atomic Energy Commission, Directorate of Licensing (Pre-1975)				7908100281	50-443 S
Atomic Energy Commission, Deputy Director for Technical Review (Pre-1975)	7906060087	FOIA		7908100282	50-443 S
				7908100283	50-443 S
W-3 Three Mile Island Task Force	7908290331	50-330 F		7908100284	50-443 S
ACRB - Advisory Committee on Reactor Safety	7908260378	ACRB		7908100285	50-443 S
	7908260173	ACRB		7908100286	50-443 S
	7908260023	ACRB		7908100287	50-443 S
	7908260026	ACRB		7908100288	50-443 S
	7908260128	50-392 A		7908100289	50-443 S
	7908260099	ACRB		7908100290	50-443 S
	7908260061	ACRB		7908100291	50-443 S
	7908130288	50-320 S		7908100292	50-443 S
	7908250038	50-320 S		7908100293	50-443 S
	7908250127	50-320 S		7908100294	50-443 S
	7908250474	ACRB		7908100295	50-443 S
	7908180646	50-320 S		7908100296	50-443 S
	7908010276	50-320 S		7908100297	50-443 S
	7958250161	50-320 T		7908100298	50-443 S
	7958250289	50-320 H		7908100299	50-443 S
	7958130262	50-320 S		7908100300	50-443 S
	7958130270	50-320 S		7908100301	50-443 S
	7958130274	50-320 S		7908100302	50-443 S
	7958130283	50-320 S		7908100303	50-443 S
	7958100600	50-320 S		7908100304	50-443 S
	7958270242	ACRB		7908100305	50-443 S
	7958130213	50-320 S		7908100306	50-443 S
	7958130254	50-320 S		7908100307	50-443 S
	7958120157	89035		7908100308	50-443 S
	7958080292	50-320 S		7908100309	50-443 S
	7958180617	50-320 S		7908100310	50-443 S
	7958180620	50-320 S		7908100311	50-443 S
	7958180623	50-320 S		7908100312	50-443 S
	7958180647	50-320 S		7908100313	50-443 S
	7958180650	50-320 S		7908100314	50-443 S
	7958180653	ACRB		7908100315	50-443 S
	7958180656	ACRB		7908100316	50-443 S
	7958180659	50-320 S		7908100317	50-443 S
	7958180662	50-320 S		7908100318	50-443 S
	7958180665	50-320 S		7908100319	50-443 S
	7958180668	50-320 S		7908100320	50-443 S
	7958180671	50-320 S		7908100321	50-443 S
	7958180674	50-320 S		7908100322	50-443 S
	7958180677	50-320 S		7908100323	50-443 S
	7958180680	50-320 S		7908100324	50-443 S
	7958180683	50-320 S		7908100325	50-443 S
	7958180686	50-320 S		7908100326	50-443 S
	7958180689	50-320 S		7908100327	50-443 S
	7958180692	50-320 S		7908100328	50-443 S
	7958180695	50-320 S		7908100329	50-443 S
	7958180698	50-320 S		7908100330	50-443 S
	7958180701	50-320 S		7908100331	50-443 S
	7958180704	50-320 S		7908100332	50-443 S
	7958180707	50-320 S		7908100333	50-443 S
	7958180710	50-320 S		7908100334	50-443 S
	7958180713	50-320 S		7908100335	50-

U.S. NUCLEAR REGULATORY COMMISSION
ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Office of International Programs	7904200819	50-574 A	7904180122	XPORTLIC	
	7904200701	DECY	7904180117	XPORTLIC	
	7904200577	XPORTLIC			
	7904200517	DECY	7904180601	XPORTLIC	
	7904180739	DECY	7904180078	XPORTLIC	
			7904240779	DECY	
	7904180902	DECY	7904190332	XPORTLIC	
	7904200101	DECY	7904190383	XPORTLIC	
	7904180758	DECY			
	7904180771	DECY	7904190100	XPORTLIC	
	7904200711	DECY	7904190184	XPORTLIC	
			7904190188	XPORTLIC	
	7904200032	DECY	7904250042	XPORTLIC	
	7904201045	DECY	7904250045	XPORTLIC	
	7904203723	XPORTLIC			
	7904240409	XPORTLIC	7904250046	XPORTLIC	
	7904200110	50-529 F	7904250080	XPORTLIC	
			7904250352	XPORTLIC	
	7904200615	DECY	7904200335	XPORTLIC	
	7904240078	DECY	7904200380	XPORTLIC	
	7904200578	DECY			
	7904100020	DECY	7904250084	XPORTLIC	
	7904200338	50-574 A	7904250088	XPORTLIC	
			7904250090	XPORTLIC	
	7904200067	DECY	7904250070	XPORTLIC	
	7904200388	DECY	7904250076	XPORTLIC	
	7904207067	XPORTLIC			
	7904292406	DECY	7904250004	XPORTLIC	
	7904200591	DECY	7904250004	XPORTLIC	
			7904250069	XPORTLIC	
	7904200870	DECY	7904250073	XPORTLIC	
	7904200571	DECY	7904250076	XPORTLIC	
	7904200714	DECY			
7904200604	DECY	7904250098	XPORTLIC		
7904140030	XPORTLIC	7904250102	XPORTLIC		
		7904250104	XPORTLIC		
7904200789	XPORTLIC	7904250117	XPORTLIC		
7904180619	DECY	7904250120	XPORTLIC		
7904180624	DECY	7904250126	XPORTLIC		
7904200249	XPORTLIC	7904250131	XPORTLIC		
7904200612	DECY	7904250138	XPORTLIC		
		7904250139	XPORTLIC		
7904200200	XPORTLIC	7904250144	XPORTLIC		
7904200106	DECY				
7904200300	50-574 A				
7904200327	DECY				
7904120103	XPORTLIC				
		7904200343	XPORTLIC		
7904210094	XPORTLIC				
		7904200455	DECY		
7904200437	XPORTLIC	7904210002	XPORTLIC		
7904200172	XPORTLIC	7904270001	XPORTLIC		
7904250283	XPORTLIC	7904290003	XPORTLIC		
7904250214	XPORTLIC				
		7904290386	XPORTLIC		
7904250067	XPORTLIC	7904290436	10CFR		
7904200296	XPORTLIC	7904290460	10CFR		
7904200402	XPORTLIC	7904290571	10CFR		
7904200404	XPORTLIC	7904290578	10CFR		
7904200212	XPORTLIC				
		7904290587	10CFR		
7904200287	XPORTLIC	7904290608	10CFR		
7904200261	XPORTLIC	7904290641	10CFR		
7904200408	XPORTLIC	7904290641	50-574 F		
7904180011	XPORTLIC	7904290641	50-574 H		
7904180013	XPORTLIC	7904290641	50-574 O		
		7904290641	50-574 Q		
7904180029	XPORTLIC				
7904180031	XPORTLIC				
7904250041	XPORTLIC				
7904204038	XPORTLIC				
7904180029	XPORTLIC				
7904160026	XPORTLIC				
7904180081	XPORTLIC				
7904180029	XPORTLIC				
7904180120	XPORTLIC				
7904180218	XPORTLIC				
79042005010	XPORTLIC				
79042005015	XPORTLIC				
7904200146	XPORTLIC				
7904200149	XPORTLIC				
7904200152	XPORTLIC				
79042020182	XPORTLIC				
7904240026	XPORTLIC				
7904180107	XPORTLIC				
7904180109	XPORTLIC				
7904180113	XPORTLIC				
7904180099	XPORTLIC				
7904180061	XPORTLIC				
7904180062	XPORTLIC				
7904180064	XPORTLIC				
7904180065	XPORTLIC				

U.S. NUCLEAR REGULATORY COMMISSION
ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7903210406	80-849 d		7906010028	70-2623 C
	7903210450	80-850 d		7906010031	70-2623 C
	7906010579	80-249 d		7906010033	70-2623 C
	7906070032	80-263 d		7906010039	70-2623 C
	7906010661	80-308 d			
	7906010359	80-227 d		7906010042	70-2623 C
	7906070011	80-471 d	Operations & Administrative Division	7906010049	70-2623 C
	7906010144	80-471 d	Business & Enforcement Division	7906010052	80-443 H
	79060108807	80-278 d		7906040054	80-443 H
	7906100814	80-272 d		7906020145	80-309 d
			Anti-Traffic Division		
	7906030180	80-261 d		7906011039	80-862 A
	7906010377	80-407 d		7906070047	80-592 d
	7906020124	80-484 d		7906080143	80-443 H
	7906030425	80-456 d		7906070034	80-443 H
	7906020113	80-471 d		7906100676	PROJ
	7906070513	80-278 d		7906070034	80-443 H
	7906040220	80-266 H		7906050118	PROJ
	7906020132	80-510 d		7906040033	80-443 H
	7906020240	80-488 d		7906010017	80-443 H
	7906110069	80-400 d			
			Office of Management and Program Analysis		
	79060703240	80-488 d		7906020445	80-320 P
	7906110009	80-493 d		7906010077	80-320 P
	7906040374	80-493 d		7906010073	80-320 P
	7906070240	80-488 d			
	7906040376	80-580 d		7906070061	80-320 P
				7906020071	80-320 P
	79060402374	80-493 d		7906080073	HABES
	7906030562	80-488 d		7906020094	HABES
	79061100319	80-493 d		7906020616	HABES
	7906010301	80-592 d			
			Office of State Programs		
	7906070368	80-332 H		7906060037	80-320 H
	7906070177	80-400 d		7906020076	80-320 d
	7906020113	80-468 d		7906010020	80-320 P
	79061005493	80-358 d		7906020448	80-320 P
	79060200507	80-468 d		7906050423	80-320 P
	7906060036	80-358 d		7906010660	80-320 P
	7906040114	80-366 d		7906070044	80-320 P
	7906070326	80-366 d		7906080070	80-320 P
	7906100743	80-050 d	Assistant Director for Emergency Preparedness	7906020120	HABES
	7906020178	80-427 d			
	79060200319	80-427 d		7906020214	80-320 P
	7906050237	80-328 d			
	7906030178	80-466 d	Assistant Director for Program Development	7906010067	80-320 P
	7906040188	80-568 d	Assistant Director for State Agreements Programs	7906020021	80-320 P
	7906110558	80-500 d		7906020026	80-320 P
	7906010048	80-358 d			
	7906020021	80-320 P			
	7906020098	70-2623 C			
	7906110564	80-287 d			
	7906110568	80-287 d			
			Office of Inspection & Enforcement		
	7906110572	80-287 d		7906010141	18E
	7906110576	80-287 d		7906010050	18E
	7906110579	80-287 d		7906020127	80-320 P
	7906110580	80-287 d		7906110615	80-320 P
	7906110585	80-287 d		7906040069	80-320 P
	7906110572	80-287 d			
	76	80-267 d		7906110042	80-320 P
	35	80-362 d		7906110427	80-320 P
	38	80-329 d		7906020036	FOIA
	39	70-2623 C		7906	
	4	70-2623 C		7906020014	80-320 P
				7906020070	FOIA
				7906020048	FOIA
				7906110342	80-320 P
				7906020017	80-320 P
				7906020019	80-314 P
				7906060025	80-320 H
				7906070004	80-320 P
				7906020052	FOIA
				7906020003	80-320 P
				7906040110	70-8918 C
				79060700212	80-482 A
				7906090447	FOIA
				7906010023	80-320 P
				7906040171	80-482 d
				7906100180	80-462 A
				7906040336	80-1173
				7906040241	80-320 P
				7906030494	80-320 P
				7906020033	80-320 P
				7906020106	80-320 P
				7906010020	80-320 P
				7906060138	18E
				7906010034	80-320 P
				7906010086	80-320 P
				7906020023	80-320 P

U.S. NUCLEAR REGULATORY COMMISSION
ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	770A060161	1A6		770A140504	40-8194 C
	770A110048	1A6		770A140514	40-8194 C
	770A020501	30-320 P		770A010040	30-311 C
	770A060178	30-320 S		770A140504	40-8194 C
	770A020503	30-320 P		770A140516	40-8194 C
	770A020519	30-320 P		770A010077	70-2484 C
	770A060200	30-320 C		770A010077	70-2484 C
	770A020505	30-320 P		770A010077	70-2484 C
	770A060172	1A6		770A010077	70-2484 C
	770A060207	30-320 C		770A010077	70-2484 C
	770A060181	30-320 S		770A010077	70-2484 C
	770A060183	1A6		770A010077	70-2484 C
	770A060197	30-320 C		770A010077	70-2484 C
	770A060202	30-320 P		770A010077	70-2484 C
	770A020514	30-320 P		770A010077	70-2484 C
	770A060144	1A6		770A010077	70-2484 C
	770A020501	30-320 S		770A010077	70-2484 C
	770A060168	1A6		770A010077	70-2484 C
	770A020543	30-313 C		770A010077	70-2484 C
	770A020553	30-320 C		770A010077	70-2484 C
	770A020587	30-320 P		770A010077	70-2484 C
	770A0205107	30-320 U		770A010077	70-2484 C
	770A020525	1A6		770A010077	70-2484 C
	770A020532	1A6		770A010077	70-2484 C
	770A020537	1A6		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010077	70-2484 C
	770A130534	1A6		770A010077	70-2484 C
	770A020526	30-320 P		770A010077	70-2484 C
	770A130489	30-320 P		770A010077	70-2484 C
	770A130490	30-320 U		770A010	

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7904120015	50-222 G		7904260044	50-24 G
	7904200142	50-219 F		7904260062	50-27 G
	7904220124	50-220 F		7904260070	50-27 G
	7904230040	50-219 G		7904260078	50-27 G
	7904230055	50-219 G		7904260082	50-234 G
	7904230152	50-219 G		7904260075	50-27 G
	7904130153	50-220 G			
	7904130144	50-219 G		7904260082	50-244 G
	7904130177	50-271 G		7904260030	50-170 G
	7904130170	50-277 G		7904260025	50-184 G
				7904260023	50-192 G
	7904130151	50-293 G		7904260030	50-199 G
	7904210217	50-303 F		7904260040	50-201 G
	7904130143	50-302 G		7904260060	50-202 G
	7904130149	50-302 G		7904110119	50-212 G
	7904130172	50-332 G		7904260099	50-213 G
				7904110122	50-219 G
	7904130174	50-354 G			
	7904130173	50-367 G		7904260112	50-219 G
	7904130147	50-410 G		7904110142	50-220 G
	7904120050	50-219 F		7904260120	50-225 G
	7904140143	50-320 F		7904260070	50-222 G
				7904260045	50-233 G
	7904230053	50-305 H			
	7904230091	50-320 F		7904110149	50-244 G
	7904230211	50-320 F		7904260100	50-244 G
	7904230017	50-360 F		7904110120	50-245 G
	7904130243	50-330 F		7904260124	50-245 G
				7904110110	50-3 G
	7904210144	50-320 F			
	7904210232	50-330 F		7904260078	50-3 G
	7904210154	50-3 G		7904110122	50-271 G
	7904120046	50-27 G		7904260103	50-271 G
	7904130154	50-213 G		7904110140	50-272 G
				7904260146	50-272 G
	7904201028	50-219 G			
	7904201077	50-220 G		7904110146	50-277 G
	7904120031	50-244 G		7904260129	50-277 G
	7904130176	50-245 G		7904110144	50-277 G
	7904130132	50-3 G		7904260139	50-277 G
				7904110144	50-286 G
	7904120005	50-271 G			
	7904120197	50-272 G		7904260122	50-286 G
	7904120188	50-277 G		7904110128	50-289 G
	7904120107	50-285 G		7904260119	50-290 G
	7904130149	50-290 G		7904110115	50-292 G
				7904260091	50-293 G
	7904230189	50-320 F			
	7904120149	50-290 G		7904110107	50-309 G
	7904120171	50-299 G		7904260121	50-309 G
	7904120194	50-311 G		7904260121	50-311 G
	7904120193	50-317 G		7904110114	50-317 G
				7904260092	50-317 G
	7904120149	50-320 G			
	7904210145	50-320 F		7904110114	50-317 G
	7904210212	50-320 F			
	7904230189	50-320 F			
				7904260093	50-317 G
	7904260146	50-323 G		7904260057	50-320 G
				7904260121	50-320 H
	7904260052	50-320 G		7904260032	50-320 F
	7904120156	50-324 G			
	7904120176	50-343 G		7904260119	50-320 G
	7904260059	50-352 G		7904260113	50-322 G
				7904110140	50-323 G
	7904260194	50-351 G		7904260126	50-323 G
	7904260143	50-352 G			
	7904120192	50-357 G		7904110120	50-324 G
	7904260132	50-410 G		7904260101	50-324 G
	7904120136	50-412 G		7904110136	50-343 G
				7904260124	50-343 G
	7904260176	50-243 G		7904260181	50-311 G
	7904260196	50-443 G			
	7904120037	50-187 G		7904260112	50-219 G
	7904120146	50-262 G		7904260140	50-287 G
	7904140477	40-0194 C		7904260131	50-210 G
				7904260104	50-412 G
	7904260493	50-219 F		7904260124	50-443 G
	7904140497	40-0194 C			
	7904260192	50-280 F		7904260156	50-443 G
	7904260037	50-2484 C		7904260157	50-492 G
	7904260061	50-248 F		7904260113	50-522 G
				7904260082	70-053 C
	7904260140	50-320 F		7904260104	70-105 C
	7904260172	50-320 F			
	7904260421	50-320 F		7904260078	70-071 C
	7904130042	70-125 C		7904260075	70-072 C
	7904260048	70-344 C		7904260040	50-201 G
				7904260048	70-1100 C
	7904260037	70-344 C		7904260044	70-1143 C
	7904110118	50-3 G			
	7904260048	50-3 G		7904260037	50-320 F
	7904260056	50-5 G		7904260140	50-320 F
	7904260057	50-20 G		7904260102	50-320 F
				7904260036	50-320 F
	7904260051	50-32 G			
	7904110130	50-29 G		7904260035	50-320 F
	7904260144	50-29 G		7904260120	50-320 F
	7904260029	50-47 G			

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

357

AUTHOR
AFFILIATION

ACCESSION
NUMBER

SUBJECT
CATEGORY

AUTHOR
AFFILIATION

ACCESSION
NUMBER

SUBJECT
CATEGORY

77042660232 30-320 Q
77042660241 30-320 Q
77042660248 30-289 F

77042660140 30-320 F

77042660204 30-320 P
77042660247 30-3 Q
77042660227 30-3 Q
77042660224 30-20 Q

77042660253 30-22 Q
77042660112 30-20 Q
77042660212 30-47 Q
77042660145 30-54 Q
77042660315 30-77 Q

77042660221 30-97 Q
77042660297 30-134 Q
77042660221 30-24 Q
77042660234 30-144 Q
77042660211 30-170 Q

77042660214 30-104 Q
77042660222 30-149 Q
77042660218 30-24 Q
77042660271 30-213 Q
77042660244 30-219 Q

77042660296 30-220 Q
77042660201 30-223 Q
77042660208 30-245 Q
77042660105 30-244 Q
77042660291 30-245 Q

77042660347 30-3 Q
77042660111 30-271 Q
77042660104 30-272 Q
77042660102 30-277 Q
77042660297 30-284 Q

77042660287 30-280 Q
77042660299 30-293 Q
77042660308 30-292 Q
77042660264 30-317 Q
77042660287 30-328 Q

77042660499 30-330 F
77042660263 30-348 Q
77042660209 30-349 F
77042660270 30-353 Q
77042660279 30-354 Q
77042660291 30-245 Q

77042660243 30-33 Q
77042660299 30-139 C
77042660280 30-271 C
77042660144 30-288 C

77042660241 30-1150 C
77042660293 30-1143 Q
77042660297 30-320 P
77042660118 30-320 P
77042660202 30-303 Q

77042660436 30-320 F
77042660164 30-320 P
77042660149 30-320 P
77042660174 30-320 P
77042660295 30-320 P

77042660164 30-320 P
77042660283 30-320 P
77042660240 30-320 P
77042660241 30-261 Q
77042660287 30-320 P

77042660293 30-320 P
77042660144 30-320 P
77042660241 30-320 P
77042660270 30-320 P
77042660431 30-320 P

77042660297 30-320 P
77042660240 30-320 Q
77042660211 30-320 Q
77042660223 30-144 H
77042660252 30-320 P

77042660282 30-320 F
77042660212 30-320 F
77042660201 30-320 F
77042660188 30-320 F
77042660182 30-320 F

77042660184 30-320 F
77042660232 30-320 F
77042660212 30-320 F
77042660281 30-272 Q
77042660283 30-272 Q
77042660289 30-272 Q

Region 3, Philadelphia, Fuel Facility
& Nuclear Safety Branch

77042660292 30-363 Q
77042660293 30-363 Q
77042660192 30-363 Q
77042660293 30-363 Q

77042660293 30-363 Q

77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q

77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q

77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q

77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q

77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q

77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q

77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q

77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q

77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q

77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q

77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q

77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q

77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q

77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q

77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q

77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q

77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q
77042660293 30-363 Q

Region 1, Philadelphia, Reactor
Construction & Engineering Support Branch

Region 1, Philadelphia, Reactor
Operations Nuclear Support Branch

p

U.S. NUCLEAR REGULATORY COMMISSION
ORGANIZATIONAL SOURCE INDEX[illegible]

Region 2: Atlanta: Master Construction & Engineering Support Branch

U.S. NUCLEAR REGULATORY COMMISSION
ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7956210209	50-320 F		7956279408	50-329 S
	7956210321	50-320 F		7956270114	50-329 S
	7956240172	70-140 C		7956210321	50-348 C
	7956250088	70-1401 C		7956210322	50-348 C
	7956200454	50-320 F		7956170354	70-044 C
	7956200456	50-320 F		7956270988	50-111 C
	7956200310	50-320 F		7956270987	50-111 C
	7956200273	50-320 F		7956170504	70-027 C
	7956200319	50-320 F		7956270248	50-327 C
	7956200130	50-320 F		7956270390	50-327 C
	7956270326	50-320 F		7956270031	50-111 C
	7956270401	50-320 F		7956170645	70-143 C
	7956200379	50-320 F		7956210064	70-143 C
	7956260513	50-302 C		7956210091	50-111 C
	7956260394	50-280 S		7956180163	50-003 S
	7956200327	50-280 S		7956190015	50-248 C
	7956260271	50-248 S		7956170870	70-027 C
	7956200023	50-291 S		7956200135	50-273 C
	7956200082	50-308 S		7956170542	70-024 C
	7956180032	50-267 S		7956260514	70-277 C
	7956180035	50-269 S		7956260512	70-277 C
	7956200183	50-124 S		7956201128	50-244 S
	7956200191	50-124 S		7956200026	50-209 S
	7956180212	50-202 S		7956210504	70-597 C
	7956180046	50-302 S		7956240411	50-289 S
	7956180016	50-324 S		7956200404	50-244 S
	7956180731	50-327 S		7956200406	50-244 S
	7956200114	50-344 S		7956202646	50-224 S
	7956180013	50-324 S		7956200071	50-244 S
	7956210030	50-327 S		7956200054	50-254 S
	7956180720	50-327 C		7956180036	50-449 S
	7956200376	50-038 S		7956200048	50-284 C
	7956180215	50-038 S		7956200045	50-278 C
	7956170213	50-283 C		7956180040	50-231 C
	7956140035	50-321 S		7956200238	50-124 C
	7956140033	50-321 S		7956194000	50-293 S
	7956140031	50-321 S		7956210139	50-241 S
	7956140013	50-338 S		7956210143	50-241 S
	7956140030	50-321 S		7956200000	50-144 S
	7956140049	50-321 S		7956200181	50-144 S
	7956170190	50-320 C		7956130435	50-320 F
	7956200541	50-324 C		7956200844	50-144 C
	7956200034	50-324 C		7956210013	50-244 S
	7956200121	50-302 C		7956210527	50-144 S
	7956200107	50-302 C		7956200110	50-144 S
	7956210073	50-414 C		7956200073	50-244 C
	7956200460	50-230 C		7956200141	50-244 C
	7956210404	50-327 C		7956200118	50-244 C
	7956200380	50-348 C		7956200441	50-244 C
	7956202442	50-438 C		7956200444	50-244 C
	7956200487	50-230 S		7956210334	50-155 S
	7956200439	50-320 H		7956200460	50-341 C
	7956210499	50-297 S		7956200423	50-244 C
	7956210420	50-249 C		7956210317	50-203 C
	7956260414	50-250 C		7956130130	50-331 C
	7956200370	50-324 S		7956200420	50-244 S
	7956200361	50-270 S		7956210134	50-454 S
	7956200361	50-324 S		7956200141	50-454 C
	7956200363	50-324 S		7956200136	50-454 C</

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

 AUTHOR
AFFILIATION

 ACCESSION
NUMBER

 SUBJECT
CATEGORY

 AUTHOR
AFFILIATION

 ACCESSION
NUMBER

 SUBJECT
CATEGORY

7906020071 50-284 G

7906020080 50-273 G

7906020089 50-409 G

7906010078 50-294 G

7906010079 50-294 G

7906280636 50-244 G

7906280639 50-244 G

7906280191 50-238 G

7906130130 50-243 G

7906120082 089

7906280639 50-237 G

7906120200 50-244 G

7906120077 50-232 G

7906200057 50-414 G

7906090098 50-373 G

79061000147 089

7906120080 50-155 G

7906120090 50-155 G

7906120080 50-155 G

7906120094 50-155 G

7906120121 50-243 G

7906120083 50-155 G

7906120128 50-243 G

7906120121 50-243 G

7906120083 50-155 G

7906120128 50-243 G

7906120114 50-313 G

7906120100 50-329 G

7906120109 50-321 G

7906120106 50-341 G

7906120105 50-341 G

7906120093 50-288 G

7906120118 50-267 G

7906120080 50-10 G

7906120124 50-409 G

7906120077 089

7906120083 50-10 G

7906120111 50-441 G

7906120127 50-453 G

7906120119 50-484 G

7906120127 50-487 G

7906120123 50-946 G

7906020130 50-973 A

7906020148 089

7906103043 50-294 G

7906020128 50-373 G

7906060306 50-243 G

7906110101 50-10 G

7906110070 50-10 G

7906110037 40-2392 C

7906110038 50-2 G

7906110101 50-10 G

7906110078 50-10 G

7906110040 50-87 G

7906110064 50-114 G

7906120097 50-123 G

7906110048 50-180 G

7906110062 50-151 G

7906110066 50-153 G

7906110088 50-180 G

7906110086 50-180 G

7906110081 50-180 G

7906110081 50-180 G

7906110081 50-180 G

7906110081 50-180 G

7906110081 50-180 G

7906110081 50-180 G

7906110081 50-180 G

7906110081 50-180 G

7906110081 50-180 G

7906110081 50-180 G

7906110081 50-180 G

7906110081 50-180 G

7906110081 50-180 G

7906110081 50-180 G

7906110081 50-180 G

7906110081 50-180 G

7906110081 50-180 G

7906110081 50-180 G

7906110070 50-10 G

7906110110 50-244 G

7906110106 50-243 G

7906110101 50-10 G

7906110070 50-10 G

7906110112 50-303 G

7906110103 50-303 G

7906110106 50-303 G

7906110099 50-243 G

7906110094 50-313 G

7906110076 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

7906110074 50-313 G

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
Region 3, Chicago, Safeguards Branch	7906240237	50-213	0	7906050035	50-482	0
	7906240449	50-252	0	7906050073	50-483	0
	7906250109	50-244	0	7906101019	50-490	0
	7906140291	50-2	0	7906130137	50-293	0
	7906010079	50-294	0	7906100075	50-267	0
	7906140305	50-2	0	7906120072	50-283	0
	7906140390	50-264	0	7906120071	50-296	0
	7906140194	50-264	0	7906120043	50-213	0
	7906090123	50-182	0	7906120070	50-282	0
	7906180045	50-254	0	7906120077	50-443	0
	7906050128	50-264	0	7906120048	50-430	0
	7906050123	50-182	0	7906120048	50-402	0
	7906050092	50-183	0	7906120057	50-490	0
	7906180337	50-256	0	7906120074	50-285	0
	7906050395	50-263	0	7906230033	50-499	0
	7906060312	50-263	0	7906250013	50-59	0
	7906200378	70-1300	C	7906250013	50-79	0
	7906220758	50-259	0	7906250014	50-112	0
	7906060209	50-47	0	7906250013	50-59	0
	7906060237	50-165	0	7906250033	50-121	0
	7906200203	50-47	0	7906250077	50-140	0
	7906200221	50-168	0	7906250036	50-180	0
7906160009	50-499	0	7906250013	50-112	0	
Region 4, Dallas, Office of the Director	7906160010	50-499	0	7906250009	50-252	0
	7906160008	50-499	0	7906250030	50-264	0
	7906160003	50-499	0	7906160088	50-267	0
	7906250014	50-499	0	7906250028	50-267	0
	7906250078	50-499	0	7906250054	50-274	0
	7906250071	50-499	0	7906250010	50-284	0
	7906210288	50-499	0	7906110056	50-285	0
	7906060077	50-499	0	7906250054	50-285	0
	7906250076	50-499	0	7906110084	50-290	0
	7906250074	50-499	0	7906250020	50-295	0
	7906210316	50-499	0	7906110080	50-313	0
	7906240160	50-213	0	7906250016	50-313	0
	7906240162	50-213	0	7906110080	50-313	0
	7906240160	50-213	0	7906250020	50-382	0
	7906240162	50-213	0	7906250018	50-72	0
	7906180055	50-499	0	7906250027	50-445	0
	7906210054	50-499	0	7906250018	50-438	0
	7906210083	50-499	0	7906250021	50-452	0
	7906210086	50-499	0	7906250029	50-490	0
	7906210050	50-499	0	7906210088	50-499	0
	7906250059	50-499	0	7906260876	70-1287	C
	7906250076	50-499	0	7906120071	50-082	0
	7906160054	50-499	0	7906130073	50-447	0
	7906250016	50-499	0	7906130048	50-438	0
	7906250059	50-499	0	7906130069	50-482	0
	7906250058	50-499	0	7906130067	50-498	0
	7906250050	50-499	0	7906210030	50-020	F
	7906250051	50-499	0	7906200343	50-047	0
	7906250059	50-499	0	7906200341	50-099	0
	7906250059	50-499	0	7906200329	50-013	0
	7906250059	50-499	0	7906200323	50-092	0
	Region 4, Dallas, Reactor Construction & Engineering Support Branch	7906210099	50-499	0	7906200341	50-082
7906180055		50-213	0	7906200341	50-498	0
7906210052		50-499	0	7906200321	50-498	0
7906180048		50-213	0	7906200344	50-498	0
7906180137		50-267	0	7906200351	50-498	0
7906230030		50-499	0	7906210025	50-482	0
7906230033		50-499	0	7906210032	50-482	0
7906250067		50-213	0	7906210018	50-025	0
7906250034		50-213	0	7906200374	50-447	0
7906250113		50-213	0	7906210022	50-025	0
7906210229		50-320	F	7906180161	50-082	0
7906230028		50-082	0	7906180163	50-498	0
7906250041		50-082	0	7906180159	50-498	0
7906250047		50-498	0	7906180160	50-498	0
7906250051		50-498	0	7906200156	50-490	0
7906250053		50-498	0	7906200143	50-082	0
7906250054		50-498	0	7906180027	50-482	0
7906250055		50-498	0	7906140165	50-482	0
7906250056		50-498	0	7906180162	50-082	0
7906250057		50-498	0	7906180164	50-448	0
7906250058		50-498	0	7906180176	50-420	0
7906250059		50-498	0	7906180247	50-082	0
7906250060		50-498	0	7906180250	50-445	0
7906250061		50-498	0	7906180261	50-418	0

375

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7704180345	50-482 S		7704180374	04999
	7704180348	50-488 S		7704230088	04999
	7704180358	50-502 S		7704230097	04999
	7704180361	50-443 S		7704250051	04999
	7704180368	50-458 S		7704250174	04999
	7704180324	50-462 S		7704250182	04999
	7704180320	50-498 S		7704250297	04999
	7704240389	50-418 S		7704250171	04999
	7704240462	50-313 S		7704251174	04999
Region 4, Dallas, Fuel Facility & Nuclear Safety Branch	7704240456	50-313 S		7704250177	04999
	7704180323	50-313 S		7704180392	04999
	7704180322	50-367 S		7704214004	04999
	7704010280	50-274 S		7704013916	04999
	7704010291	50-274 S		7704011401	04999
	7704210310	50-283 S		7704010591	04999
	7704260186	50-290 S			
	7704260150	50-298 S		7704010514	04999
	7704040349	50-313 S		7704210630	04999
	7704180346	50-367 S		7704293621	04999
	7704180346	50-288 E		7704113628	04999
	7704180348	50-288 E		7704118038	04999
	7704180340	50-313 S		7704120552	04999
	7704270036	50-320 S		7704290231	04999
	7704180398	50-285 S		7704290219	04999
	7704180394	50-292 S		7704291062	04999
	7704180392	50-313 S		7704293006	04999
	7704250041	50-287 S		7704060030	04999
	7704240336	50-313 S		7704293052	04999
	7704270075	50-360 S		7704010106	04999
	7704260570	50-313 S		7704030165	04999
	7704250115	50-298 S		7704030216	04999
	7704180361	50-367 S		7704270519	04999
	7704180297	50-285 S		7704190030	04999
	7704180295	50-288 S		7704190039	04999
Region 4, Dallas, Vendor Inspection Branch	7704180291	50-313 S		7704190560	04999
	7704230050	04999		7704200210	04999
	7704240716	04999		7704200028	04999
	7704210344	04999		7704200563	04999
	7704260151	04999		7704200514	04999
	7704210238	04999		7704290230	04999
	7704270082	04999		7704290633	04999
	7704270360	04999		7704290176	04999
	7704180470	04999		7704290200	04999
	7704180463	04999		7704290225	04999
	7704180464	04999	Region 5, San Francisco, Office of the Director	7704260347	50-312 S
	7704210362	04999		7704130057	50-341 S
	7704210312	04999		7704130059	50-280 P
	7704270040	04999		7704270040	50-312 S
	7704270077	04999		7704290104	50-312 S
	7704180263	04999		7704290091	50-312 S
	7704270352	04999		7704290403	50-312 S
	7704180251	04999		7704290141	50-206 S
	7704270025	04999		7704290144	50-206 S
	7704270036	04999			
	7704270036	04999		7704200149	S
	7704210114	04999			
	7704010110	04999		7704200182	
	7704050112	04999		7704140213	
	7704250204	04999		7	
	7704250208	04999			
	7704270236	04999			
	7704070023	04999			
	7704070031	04999			</

372

[illegible]

U.S. NUCLEAR REGULATORY COMMISSION
ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7904270040	50-285 H		7904270019	50-320 H
	7904270049	50-290 H		790427001A	50-320 H
	790427007A	50-290 H		7904270138	50-325 H
	7904270080	50-290 H		7904210360	50-325 P
	7904270087	50-290 H		7904260224	50-330 H
	7904270093	50-290 H			
	7904270109	50-290 H		7904260376	50-348 D
	7904270119	50-290 H		7904110760	NR029
	7904270124	50-290 H		790426037A	50-350 P
	7904270129	50-290 H		790426037A	50-358 D
	7904270143	50-290 H		7904260182	50-368 D
				7904260376	50-368 D
	7904270151	50-290 H		7904260376	50-368 D
	7904270163	50-290 H		7904260376	50-368 D
	7904270168	50-290 H		7904260376	50-368 D
	7904270173	50-290 H		7904260376	50-368 D
	7904270177	50-290 H		7904260376	50-368 D
	7904270181	50-290 H		7904260376	50-368 D
	7904270185	50-290 H		7904260376	50-368 D
	7904270189	50-290 H		7904260376	50-368 D
	7904270193	50-290 H		7904260376	50-368 D
	7904270197	50-290 H		7904260376	50-368 D
	7904270201	50-290 H		7904260376	50-368 D
	7904270205	50-290 H		7904260376	50-368 D
	7904270209	50-290 H		7904260376	50-368 D
	7904270213	50-290 H		7904260376	50-368 D
	7904270217	50-290 H		7904260376	50-368 D
	7904270221	50-290 H		7904260376	50-368 D
	7904270225	50-290 H		7904260376	50-368 D
	7904270229	50-290 H		7904260376	50-368 D
	7904270233	50-290 H		7904260376	50-368 D
				7904260376	50-368 D
	7904270237	50-290 H		7904260376	50-368 D
	7904270241	50-290 H		7904260376	50-368 D
	7904270245	50-290 H		7904260376	50-368 D
	7904270249	50-290 H		7904260376	50-368 D
	7904270253	50-290 H		7904260376	50-368 D
	7904270257	50-290 H		7904260376	50-368 D
	7904270261	50-290 H		7904260376	50-368 D
	7904270265	50-290 H		7904260376	50-368 D
	7904270269	50-290 H		7904260376	50-368 D
	7904270273	50-290 H		7904260376	50-368 D
	7904270277	50-290 H		7904260376	50-368 D
	7904270281	50-290 H		7904260376	50-368 D
	7904270285	50-290 H		7904260376	50-368 D
	7904270289	50-290 H		7904260376	50-368 D
	7904270293	50-290 H		7904260376	50-368 D
	7904270297	50-290 H		7904260376	50-368 D
	7904270301	50-290 H		7904260376	50-368 D
	7904270305	50-290 H		7904260376	50-368 D
	7904270309	50-290 H		7904260376	50-368 D
	7904270313	50-290 H		7904260376	50-368 D
	7904270317	50-290 H		7904260376	50-368 D
	7904270321	50-290 H		7904260376	50-368 D
	7904270325	50-290 H		7904260376	50-368 D
	7904270329	50-290 H		7904260376	50-368 D
	7904270333	50-290 H		7904260376	50-368 D
	7904270337	50-290 H		7904260376	50-368 D
	7904270341	50-290 H		7904260376	50-368 D
	7904270345	50-290 H		7904260376	5

340

AUTHOR AFFILIATION	ACQUISITION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACQUISITION NUMBER	SUBJECT CATEGORY
Environmental Projects Branch 2	7906280038	50-248 D	7906190340	50-259 P	
	7906200383	50-266 A		7906190334	50-259 P
	7906290316	50-240 D		7906190339	50-259 P
	7906190274	50-296 D		7906190143	50-259 P
	7906180785	50-404 O		7906190160	50-259 P
				7906190094	50-259 P
	7906010009	50-309 A		7906250000	50-259 P
	7906040372	PH03		7906250094	50-259 P
	7906060023	50-471 D		7906250099	50-259 P
	7906060002	50-471 D		7906250103	50-259 P
Licenses Branch	7906090253	50-596 A	7906250090	50-259	
	7906200199	50-308 P	7906250074	7906250099	50-259 P
	7906010001	50-361 A		7906250152	50-259 P
	7906190039	50-500 P		7906250300	50-259 P
	7906140568	50-460 A		7906250301	50-259 P
	7906180733	50-850 A		7906250309	50-259 P
				7906250309	50-259 P
	7906290337	50-366 A		7906250309	50-259 P
	7906290334	50-423 A		7906250309	50-259 P
	7906100349	50-320 P		7906250309	50-259 P
7906290334	50-320 P	7906250309		50-259 P	
Hydrology Waterways Branch Environmental Specialists Branch	7906290334	50-320 P	7906250309	7906250309	50-259 P
	7906290334	50-320 P		7906250309	50-259 P
	7906290334	50-320 P		7906250309	50-259 P
	7906290334	50-320 P		7906250309	50-259 P
	7906290334	50-320 P		7906250309	50-259 P
	7906290334	50-320 P		7906250309	50-259 P
	7906290334	50-320 P		7906250309	50-259 P
	7906290334	50-320 P		7906250309	50-259 P
	7906290334	50-320 P		7906250309	50-259 P
	7906290334	50-320 P		7906250309	50-259 P
Division of Operating Reactors	7903200100	50N 18C 18C	7906250309	7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
Assistant Director for Engineers & Projects (PFA 790625)	7906250309	50-320 P	7906250309	7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
Operating Reactors Branch 4 (PFA 790625)	7906250309	50-320 P	7906250309	7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
Operating Reactors Branch 3 (PFA 790625)	7906250309	50-320 P	7906250309	7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
Reactor Safeguards Licensing Branch Assistant Director for Systems Engineer- ing	7906250309	50-320 P	7906180348	50N 18C 18C	
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P
	7906250309	50-320 P		7906250309	50-259 P

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

382

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	790209040	50-40V F		790209013	50-278 A
Reactor Safety Branch	7901070494	10F8EF		7902090381	50-380 A
Systematic Evaluation Program Branch (Pre 790202)	7902000977	50-500 F	Light Water Reactors Branch 2	7902090160	50-273 A
	790200080	50-320 F		7902090386	50-361 F
Division of Project Management	790207034	10F8EF		7902090270	50-599 A
	7906080008	50-10 U		7902100102	50-38V
	7906120401	50-320 G		7902100131	50-389 A
	7906100427	50-320 G		7902100445	50-366 A
	7906100637	50-360 G		7902110448	50-382 A
	7906100431	50-360 G		7902110124	50-393 A
	7906090401	50-273 H		7902090528	50-320 P
	7906090401	50-273 H		7902100133	50-382 A
	7906070498	50-320 G		7902090319	50-445 A
	7906070498	50-320 G		7902090201	50-361 A
	7906060313	50-460 A		7902090239	50-361 A
	7906070143	50-360 G		7902090078	50-361 A
	7906060216	50-320 G		7902090009	50-361 A
	7906060138	50-275 G		7902090034	50-382 A
	7906110209	50-275 H		7902090323	50-445 A
	7906070084	50-320 G		7902090044	50-318 A
	7906080118	50-275 G		7902090014	50-361 A
	7906100369	50-275 H		7902090163	50-445 A
	7906100148	50-473 A		7902090043	50-427 A
	7906110148	50-473 A		7902090323	50-399 A
	7906070101	50-320 G		7902090322	50-369 A
	7906070137	50-320 G	Light Water Reactors Branch 3	7902070313	50-328 P
	7906050101	50-009 P		7902070321	50-338 P
	7906070028	50-360 G		7902070323	50-338 P
	7906070140	50-320 G		7902070312	50-238 P
	7906070002	50-320 G		7902070321	50-338 P
	7906070140	50-320 G		7902070325	50-328 P
	7906070149	50-320 P		7902070241	50-384 A
	7906060101	50-400 A		7902040030	50-319 A
	7906060107	50-400 A		7902040025	50-311 A
	7906070126	50-320 G		7902070429	50-373 A
	7906070131	50-320 G		7902060133	50-423 A
	7906060153	50-320 P		7902110414	50-408 A
	7906070131	50-320 G		7902100046	50-207 A
	7906060067	50-400 A		7902100003	50-368 I
	7906070154	50-320 P		7902060119	50-522 A
	7906070039	50-320 G		7902060036	50-592 I
	7906100123	50-278 H		7902100131	50-387 A
	7906070170	50-320 P		7902100701	50-405 A
	7906090353	50-320 G		7902100767	50-328 P
	7906100120	50-273 H		7902100781	50-400 A
	7906080001	50-329 P		7902060162	50-307 A
	7906070020	50-320 G		7902060051	50-596 A
	7906070023	50-320 G		7902060115	50-387 A
	7906070086	50-320 G		7902060078	50-498 A
	7906070061	50-320 G		7902060041	50-300 P
	7906060091	50-309 P		7902060190	50-493 A
	7906070130	50-320 G		7902060133	50-387 F
	7906070103	50-320 P	Light Water Reactors Branch 4	7902100423	50-329 A
	7906070160	50-320 G		7902060024	10F8EF
	7906070078	50-320 P		7902060065	50-302 A
	7906070156	50-320 P		7902100001	50-322 A
	7906070062	50-320 G		7902060007	50-390 A
	7906070071	50-320 P		7902060004	50-390 G
	7906110018	50-320 G		7902060156	50-484 A
	7906110028	50-329 G		7902060026	50-329 A
	7906110028	50-329 G		7902060136	50-434 A
	7906110039	50-320 G		7902060002	50-320 G
	7906110056	50-320 G		7902060016	50-393 A
	7906070015	50-329 P		7902070025	50-329 G
Assistant Director for Light Water Reactors	7906050145	10F8EF		7902070021	50-397 A
	7906070019	50-338 P	Assistant Director for Quality Assurance & Operations	7902060007	50-327 G
	7906070039	50-273 G	Operator Licensing Branch	7902060114	50-369 P
	7906050067	50-009 P	Quality Assurance Branch	7902070188	50-325 P
	7906010059	50-273 G		7902100037	50-364 A
	7906020042	50-308 P		7902060139	10F8EF
	7906130040	50-263 G		7902060156	50-369 P
	7906100172	50-273 H		7902060112	50-309 P
Light Water Reactors Branch 1	7906020129	50-366 G		7902060106	10F8EF
	7906040419	10F8EF		7902070102	50-361 A
	7906110056	50-361 A	Assistant Director for Standard & Advanced Reactors	7902070270	50-267 P
	7906060021	50-273 A		7902020430	50-267 P
	7906070104	50-320 G	Advanced Reactors Branch	7902090017	50-367 P
	7906070067	50-320 G		7902070051	50-320 G
	7906060016	50-366 P		7906012071	50-495 A
	7906070097	50-320 G		7902070044	50-320 G
	7906060113	50-275 A		7902070082	50-320 G
	7906070078	50-368 G			

U.S. NUCLEAR REGULATORY COMMISSION
ORGANIZATIONAL SOURCE INDEX

383

AUTHOR	ACCESSION	SUBJECT	AUTHOR	ACCESSION	SUBJECT
AFFILIATION	NUMBER	CATEGORY	AFFILIATION	NUMBER	CATEGORY
Division of System Safety	7704270187	30-320 F		7704300037	FR
	7704270066	FOIA		7704270340	FOIA
	7704270189	30-320 F		7704270348	FOIA
	7704270007	30-320 F		7704270222	NSAS
	7704270240	30-320 H		7704280178	RESPO
	7704280188	30-320 P		7704280180	RESPO
	7704280318	30-326 P		7704280301	FR
	7704280331	30-326 U		7704280748	RESPO
	7704270126	30-320 F		7704280603	RESPO
	7704280043	30-320 H	Division of Engineering Standards	7704280575	FR
Mechanical Engineering Branch	7704281008	30-311 A		7704280108	RESPO
Assistant Director for Plant Systems	7704280507	30-320 F		7704280164	RESPO
	7704280510	30-326 A		7704280463	HAZOP
	7704280314	30-437 A	Reactor Systems Standards Branch	7704280543	30-320 E
	7704280286	30-329 E	Division of Mining, Health & Safeguards Standards	7704270195	FOIA
	7704280347	30-329 A		7704280100	GSD
	7704280318	GEN TEE 1B	Radiological Health Standards Branch	7704280167	30-326 P
	7704280076	30-320 P		7704280202	DRD
Containment Systems Branch (Pw 770101)	7704280248	30-320 F	Defendants Standards Branch	7704280048	NUREG
Electric, Instrumentation & Control Systems Branch	7704280297	30-320 A	Office of Nuclear Regulatory Research +	7704280728	RES
	7704280243	30-327 A		7704280207	RES
	7704280346	30-329 A		7704280401	HAZOP
	7704280274	30-350 A	Administrative and Resource Control Staff	7704280763	30-320 P
				7704280726	30-320 P
Power Systems Branch	7704280091	TOPREF		7704280190	30-320 P
Assistant Director for Reactor Safety	7704280039	30-373 P		7704280139	30-320 P
	7704280177	30-466 D	Program Coordination Branch	7704280003	30-320 P
	7704280144	30-568 G	Probabilistic Analysis Branch	7704280016	30-320 P
	7704280117	30-488 G		7704280012	30-320 P
	7704280070	30-320 F		7704280014	30-320 P
	7704280148	30-320 F		7704280037	30-320 P
	7704280085	30-320 F		7704280037	30-320 P
Analysis Branch	7704270140	30-326 P		7704280037	30-320 P
	7704280405	TOPREF	Division of Safeguards, Fuel Cycle & Environmental Research	7704280000	30-320 P
	7704280438	TOPREF		7704280079	30-320 P
Core Performance Branch	7704280157	30-320 F		7704280021	30-320 P
	7704270088	30-320 F	Environmental Effects Research Branch	7704280018	30-320 P
Reactor Systems Branch	7704280216	30-285 P	Division of Reactor Safety Research	7704280040	REV114 86P
	7704280087	30-326 P		7704280234	REV14 86P
	7704270108	30-326 P		7704280020	REV14 86P
	7704280170	30-326 P		7704280020	REV14 86P
	7704280088	30-320 P		7704280004	30-320 P
	7704280038	30-320 P		7704280473	30-290 R
Division of Reactor Licensing (NSR-1978 only)	7704280033	30-320 A	Assistant Director for Advanced Reactor Safety Research	7704280028	REV14 86P
Office of Standards Development	7704280713	COMPREHENS		7704280121	30-320 P
	7704280177	COMPREHENS		7704280128	30-320 P
	7704280113	COMPREHENS		7704280118	30-320 P
	7704270289	FOIA	Experimental Gas-Cooled Reactor Safety Research Branch	7704280118	30-320 P
	7704280227	105R	Fuel Behavior Branch	7704280027	REV14 86P
	7704280034	105R	Detonations & Meltdown Branch	7704280472	30-320 P

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
WJW02/CR-5674	77061186499	WJW02	04027Y-0378	EECY-77-077A	77061830641	EECY	
WJW02/CR-5675	77061250648	WJW02		EECY-77-118	77061020227	1-6EPR	
WJW02/CR-5676	77061251817	WJW02	LA-7730-58	EECY-77-137B	77061040617	EECY	
WJW02/CR-5677	77061250573	WJW02	09MLN00605/71-3	EECY-77-200A	77061050562	EECY	
WJW02/CR-57-1	77061187498	WJW02	09T-16007-78-1	EECY-77-200A	77061060071	EECY	
WJW02/CR-57-2	77061187562	WJW02	09T-16007-78-2	EECY-77-241	77061791013	EECY	
WJW02/CR-57-4	77061192773	WJW02	09T-16007-78-3	EECY-77-249A	77061180777	EECY	
WJW02/CR-57-5	77061187037	30-2P5	P	EECY-77-260A	77061791014	EECY	
WJW02/CR-57-6	77061192771	WJW02	09MLN00605/71-3	EECY-77-260	77061791015	EECY	
WJW02/CR-57-9	77061193422	TOPREF	09MLN00605/71-3	EECY-77-260A	77061255666	EECY	
WJW02/CR-57-26	77061182774	WJW02	SACV-77-0481	EECY-77-262	77061180808	EECY	
WJW02/CR-57-29	77061005110	WJW02	TRIE-1299	EECY-77-286	77061050575	EECY	
WJW02/CR-57-30	77061260405	WJW02	EECY-77-289	EECY-77-289	77061077854	EECY	
WJW02/CR-57-33	77061270487	WJW02	09MLN00605/71-3	EECY-77-297	77061011046	EECY	
WJW02/CR-57-39	77061200044	WJW02		EECY-77-308	77061102116	EECY	
WJW02/CR-57-61	77061260511	WJW02	FA-17781	EECY-77-356	77061060578	EECY	
WJW02/CR-57-66	77061005094	WJW02	TRIE-1292	EECY-77-357	77061050576	EECY	
WJW02/CR-57-67	77061190793	WJW02	FA-17781	EECY-77-368	77061050579	EECY	
WJW02/CR-57-94	77061100034	WJW02	PK-0827	EECY-77-310	77061184612	EECY	
WJW02/CR-58-0	77061182010	WJW02		EECY-77-320	77061027476	EECY	
WJW02/CR-58-2	77061182017	WJW02		EECY-77-326	77061050580	EECY	
WJW02/CR-58-26	77061193238	WJW02	RP-2026	EECY-77-74	77061284642	EECY	
WJW02/CR-58-25	77061187779	WJW02	BH-15065	EECY-77-750	77061114340	EECY	
09E-01-57F	77061260241	30-2P5	P	EECY-77-781	77061030254	30-206	G
WJW02/CR-59-24	77061260274	30-2P5	P	EECY-77-830	77061230148	EECY	
EECY-77-829	77061011179	FOIA		UTRL-82878	77061295887	30-201	P
EECY-77-565	77061011025	FOIA		WCAP-1962	77061261628	TOPREF	
EECY-77-284A	77061201103	CONY		WCAP-1962	77061212446	TOPREF	
EECY-78-413	77061110313	EECY/BRDM		WCAP-1149	77061124438	30-206	A
EECY-77-104	77061007714	EECY		WCAP-1128	77061124439	30-206	A

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. Application/Construction Stage Documents and Correspondence

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

1. Correspondence and documents relating to unresolved design and construction issues.
2. Meeting announcements and summaries of meeting discussions on issues of item 1.
3. Correspondence regarding Preliminary and Final Safety Analysis Reports.
4. NRC questions, requests for additional information, and applicant responses.
5. Applicant's Quality Assurance Manual.
6. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
7. Federal Register notices that do not apply to other categories.
8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
9. Scheduling of license application submission or review.
10. Reports of site visits.
11. Backup technical documents (i.e., topical reports) submitted in support of the application.
12. Early site review information.
13. Construction Permit, amendments and correspondence relating to construction permit.
14. Environmental review information.
15. Construction permit.

B. Utility Preliminary Safety Analysis Report (PSAR) and Amendments

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by the utility.
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt.
5. Hazards Summary Report submitted by utility (now designated PSAR).

6. Safety Analysis Report submitted by utility (now designated PSAR).
7. Certificates of Service of PSAR.

C. Utility Environmental Report (ER), Amendments and Correspondence

1. Environmental Report (ER) submitted by the utility.
2. Amendments and supplements to the ER.
3. Transmittal letters.
4. Information on scheduling of submittal or review of ER.
5. NRC questions, requests for additional information, and applicant responses.
6. Federal Register notice citing availability of items 1 and 2.
7. Correspondence relating to the review of ER.
8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), Supplements and Correspondence

1. Draft and Final Environmental (Impact) Statements (DES and FES).
2. Supplements to DES and FES.
3. Correspondence relating to the DES or FES.
4. Comments from other federal, state, and local government agencies.
5. Transmittal letters.
6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
7. Backup technical documents submitted in connection with above.
8. Notices of availability of above.
9. Draft of detailed statement.

E. NRC Safety Evaluation Report (SER), Supplements and Correspondence

1. Safety Evaluation Report (SER).
2. Supplements to SER.
3. Correspondence relating to SER.

4. Notices advising of the availability of 1 and 2.
5. Information on scheduling of SER submittals and review.
6. Requests for additional information for use in preparing SER; responses to such requests.
7. Meeting announcements or reports of meetings where the primary subject of discussion is the safety review or safety evaluation.
8. Transmittal letters.
9. Comments from other agencies relative to safety review.
10. NRC-AEC Hazard Analysis Reports (now designated SER).

F. Security, Medical, Emergency, and Fire-Protection Plans

All plans in this category are submitted separately. Information submitted for the PSAR or FSAR is excluded.

1. Correspondence relating to plans.
2. Supplements, changes, and revisions to plans.
3. Fire Hazard Protection Plan and Surveys.

G. Adjudicatory Correspondence

This category contains all documents on hearings, Atomic Safety and Licensing Board (ASLB) review, and opposition except word-for-word transcripts of ASLB hearings (Category T) and anti-trust hearings (Category N).

1. ASLB hearing and review documents.
2. Correspondence to and from intervenors.
3. Correspondence to and from persons writing in opposition to the facility. Those writing for information or in support of the facility are in category H.
4. Board orders and decisions.
5. Requests to make appearances at hearings.
6. Transmittal of supporting documents (i.e., SER, FES) to the board.
7. Federal Register notices regarding hearings.
8. Requests for a hearing.
9. Petitions from participants (including petition for request for extension).
10. Corrections to transcripts.
11. Professional qualifications, if presented at a hearing.

12. Memorandums and orders authorizing issuance of license, changes, and other issuances by the Atomic Safety and Licensing Board.
13. Hearing index.

H. General correspondence

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

1. Qualification statements of new employees.
2. Change of address notifications.
3. Changes in organization.
4. Changes in service lists, "Certificate of Service" documents (without a document attached).
5. NRC requests to applicant for additional copies of documents.
6. Correspondence from the public in support of or requesting information about the facility.
7. Letters of "concern" (NOT "opposition") and response thereto.
8. Correspondence on strictly administrative matters.
9. Correspondence regarding the local Public Document Room.
10. Memoranda to Public Document Room regarding withholding a document (unaccompanied by that document).
11. Press releases from applicant.
12. Any other material that fits the criteria given above.
13. Professional qualifications (resumes).

I. Financial Information

1. Company annual reports.
2. Separately submitted financial information and related correspondence.

J. Insurance and Identity Information

1. All correspondence and documentation regarding indemnity and insurance.
2. Endorsements to insurance policies.
3. NELPIA -- Nuclear Energy Liability Property Insurance information.

K. Utility Final Safety Analysis Report (FSAR) and Amendments

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

1. Final Safety Analysis Report (FSAR).
2. Amendments and changes to the FSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of items.
5. Hazards Final Summary Report (now designated FSAR).
6. Certificates of Service of FSAR.

L. Limited Work Authorization and Related Correspondence

This category is limited to items issued before the construction permit is granted.

1. Limited Work Authorizations.
2. Environmental exemptions.
3. Correspondence relating to 1 and 2.
4. All information concerning site preparation prior to the issuance of a construction permit.

M. Antitrust Correspondence

1. All material concerning antitrust except hearing transcripts (category N)
2. All material marked with an A immediately following the docket number. The A signifies antitrust proceedings.

N. Antitrust Hearing Transcripts

This category contains only word-for-word transcripts of hearings in antitrust matters. In most cases they will be marked with an A following the docket number. Related correspondence falls in category M.

O. Advisory Committee on Reactor Safeguards (ACRS) Reports and Correspondence

1. Correspondence and letter reports relating to ACRS reviews
2. Correspondence from ACRS
3. Announcements of ACRS meetings

4. Transmittal letters to ACRS
5. ACRS reports.

P. Operating License Stage Documents and Correspondence

This file assumes the position of the application file for general technical items dated on or after the issuance of the operating license. It includes:

1. Operating license, amendments, proposed amendments, and changes.
2. Technical specifications and changes.
3. Announcements of issuance of 1 and 2.
4. Transmittal letters.
5. All general technical correspondence relating to technical specifications or operating license.
6. License conditions.
7. Operator licenses or administrative information bearing on the licensing of operators.
8. Meeting announcements or summaries of discussions where the main subject is technical specifications, operating license, or any technical issue arising after the issuance of the operating license.
9. Correspondence regarding codes (ASME), regulations, laws, or changes in policy that may affect plant operation or bear on the operating license.
10. Information on the Standard Review Plan (SRP).
11. Results of surveys or tests conducted in accordance with the technical specifications (NOT periodic reports, which fall in category R).
12. Requests for issuance of operating license.
13. Requests for copies of items 1 and 2 and responses.
14. Correspondence on generic technical issues.
15. Owner's group meeting announcements and reports.
16. Orders for modification of license.
17. Requests for extension date of license or license modification.
18. Quality assurance information.
19. Environmental matters (technical).
20. Emergency core cooling system.
21. Radioactive waste information.

Q. Inspection Reports, IE Bulletins and Correspondence

1. Inspection reports.
2. Bulletins and Circulars of NRC Office of Inspection and Enforcement (IE).
3. Responses by applicant to IE correspondence.
4. Applicant's determination of proprietary nature of inspection reports.
5. Letters concerning areas of noncompliance.
6. Any correspondence relating to inspection and enforcement that does not specifically relate to incidents as defined in category S.
7. In-service inspections.
8. Regulatory Operations (RO) Bulletins.

R. Periodic Operating Reports and Related Correspondence

This category includes periodic reports of a routine nature.

1. Monthly, semiannual, or annual reports (other than financial).
2. Periodic environmental monitoring, effluent testing, or similar reports.
3. Gray Book Information.
4. Operational Logbooks:
 - Logbooks on Environmental Data
 - Logbooks of Radiological Data
 - Operations Log on Plant Systems Core
 - Plant Status Summary Sheets
5. Correspondence or other documents relating to the above listed items.

S. Reportable Occurrences, LERs and Related Correspondence

This category contains all materials relating to abnormal, unusual, reportable, nonroutine, or 10 CFR 50.55e occurrences. This includes:

1. All 24-hour, 10-day, 30-day, interim, final, and followup reports on these events.
2. Other related documents.

NOTE: Also called licensee event reports, incident reports, etc.

T. Hearing Transcripts on Non-Antitrust Matters

This category contains word-for-word transcripts, corrections to the transcript, attachments and Vu-Graphs. Examples of non-antitrust matters include:

1. ASLB hearings.
2. Commission Meetings.
3. Commission Briefings.
4. Telephone conversations.

U. Congressional/Executive Correspondence

1. Testimony before Congress.
2. Preparatory and backup documents for Congressional testimony.
3. Letters to and from Congress and the Executive Branch.
4. Responses to letters from members of Congress and the Executive Branch.
5. Correspondence to and from the NRC Office of Congressional Affairs.

V. Operator Examinations

1. NRC Examination Results.
2. Power Plant Examination Summary Sheet.
3. Related correspondence.

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR — Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

1. Sunshine Act Federal Register notices.
2. Full, written explanation of closed meetings.
3. Certification of General Counsel on closed meetings.
4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS — Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
2. ACRS meeting announcements; description of meeting agendas.
3. ACRS-generated reports, memoranda and correspondence that are publicly available.
4. ACRS consultant reports, comments and related correspondence.
5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

AGREEMENT — State Agreements and Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
3. State Legislative Reports.
4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

COMMISSION – NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.
2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT – NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements. Include:

Request for proposal (RFP) and invitations for bid (IFB).

IFB issued by the NRC.

Contract execution, specifying contract number, project title, contractor funding, and period of performance.

Contract and contract modifications, if any.

Freedom of Information Act Requests and Releases

Requests for agency records and records released in accordance with the Freedom of Information Act (FOIA). Documents in this category include:

1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year—numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS — Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.
3. Meeting notifications and minutes.
4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E — Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

NUREG — NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

1. These reports are normally final work products and are characterized by the following criteria:

- a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG – Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR – Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
2. Text of the Proposed Rule (PR).
3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.

4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM – Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
2. Federal Register cause notices of the filing of the petition.
3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the IOCFR category.

PROJ – Projects–Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

A. Application/Construction Stage

1. Application submitted by the utility.
2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
3. Applicant's Quality Assurance Manual.
4. Early site review information.
5. Backup technical documents submitted in support of the application.
6. Early site visits.

B. Utility PSAR and Amendments

1. PSARs submitted by the utility.
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of the PSAR.

G. Adjudicatory Correspondence

1. Motions, briefs, orders, *et al.* pertaining to pre-hearing conferences, if any.

M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

1. Inspection reports of the applicant's quality assurance program.
2. Notices of deviations.
3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 – Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
3. NRC inspection reports of defects cited.
4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 – Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling

criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
2. Notices of deviations.
3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD – Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
2. Revised or newly issued Regulatory Guides.
3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES – Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

1. Project description documents.
2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
3. Pre-test prediction reports.
4. "Quick look" reports.
5. Informal experimental data reports and post-irradiation examination analyses.
6. Conceptual design descriptions.

7. Letter reports of foreign travel and site visits by contractors.
8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP – NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

1. Agendas for quarterly review group meetings.
2. Summary minutes of review group meetings representing views expressed, including dissenting views.
3. Research plans and predicted results of major experiments; presentations by research contractors.
4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
5. Internal memoranda relating to topics under discussion.

RM – Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

1. Designations of the presiding officer and any special directions for the conduct of the hearing.
2. Notifications of hearing board meetings.
3. Petitions, motions, testimony and statements submitted by parties to the hearings.
4. Hearing board orders and rulings.
5. Technical reports submitted as evidence in the proceeding.
6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY — Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

TOPREP — Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
2. Revisions, modifications and amendments to topical reports.
3. Correspondence between NRC and vendors pertaining to the review of submittals.
4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT — Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.
3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC -- Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
3. Commission letters requesting Executive Branch views.
4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
5. Correspondence from foreign governments, international organizations, and members of the public.
6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
7. Filings pursuant to hearing requests or intervention petitions, if any.
8. Hearing records and decisions.
9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

BIBLIOGRAPHIC DATA SHEET

NUREG-0540 Vol. 1 No. 6

4. TITLE AND SUBTITLE (Add Volume No., if appropriate)		2. (Leave blank)	
Title List of Documents Made Publicly Available		3. RECIPIENT'S ACCESSION NO.	
7. AUTHOR(S)		5. DATE REPORT COMPLETED MONTH YEAR August 1979	
9. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)		DATE REPORT ISSUED MONTH YEAR August 1979	
Division of Technical Information and Document Control U.S. Nuclear Regulatory Commission Washington, D.C. 20555		6. (Leave blank)	
12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)		8. (Leave blank)	
same as #9		10. PROJECT/TASK/WORK UNIT NO.	
		11. CONTRACT NO.	
13. TYPE OF REPORT Monthly		PERIOD COVERED (Inclusive dates) June 1 - 30, 1979	
15. SUPPLEMENTARY NOTES		14. (Leave blank)	
16. ABSTRACT (200 words or less)			
<p>This document is a monthly publication containing descriptions of information received and generated by the U.S. NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The docketed information includes information formerly issued through U.S. DOE's Technical Information Center under the title <u>Power Reactor Docket Information (PRDI)</u>. This document replaces PRDI, which will no longer be prepared. It is indexed by a Personal Author Index, Corporate Source Index and Report Number Index.</p>			
17. KEY WORDS AND DOCUMENT ANALYSIS		17a. DESCRIPTORS	
17b. IDENTIFIERS/OPEN-ENDED TERMS			
18. AVAILABILITY STATEMENT Unlimited		19 20. SECURITY CLASS (This page) 22. PRICE \$	